Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Oracle Unit:

66396

Address: 4248 W 47th St. Region: Mail Room: Asbestos Surveyor: Rivera, Roberto X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/6/2024 Email Address: rbrivera@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type YES SF X NO Drywall 14000 Throughout 2nd Floor No None 0 Miscellaneous 2022 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:

Acero Charter Schools - PFC Omar E. Torres

School:

3345

Building ID:

2	2	Drywall Joint Compound	9000	SF	Throughout 2nd Floor		Miscellaneous	No	None	0		YES	X NO
2	2022 Fall Six	Month Survey: No Ch	ange]							
	Comments:												
2	2023 Fall Six	Month Survey: No Ch	ange										
C	Comments:												
2	2023 Spring S	Six Month Survey: No	Change			}							
C	Comments:												
2	2024 Spring S	Six Month Survey: No	Change										
C	Comments:												
						J							
H	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

0	Floor Tile	23323	OI .	office, Bathrooms
2022 Fall	Six Month Survey:	No Chango		
	•	No Change		
Comment	S:			
2023 Sprii	ng Six Month Surve	ey: No Change		
Comment	S:			
2023 Fall	Six Month Survey:	No Change		
Comment	s:			
				·
2024 Sprii	ng Six Month Surve	ey: No Change		
Comment	S:			

23325

SF

Material

Quantity

Material

Units

Material Location

2nd Floor halls,

Classrooms, Teacher

HA No

8

Material Description

12" X 12" Light Green Mix

Floor Tile

Change in Assessment Category

X NO

YES

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
8M	12" X 12" Light Green Mix Floor Tile Mastic	23325	SF	2nd Floor Halls, Classrooms, Teacher office, Bathrooms		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		<u> </u>								

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Chring Civ Month Curvey No Change
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	12" X 12" Green Mix Floor Tile	1250	SF	2nd Floor Halls , Engineers office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
9M	12" X 12" Green Floor Tile Mastic	1250	SF	2nd Floor Halls, Engineers office		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												
2023 Spring Six Month Survey: No Change												
Comments:	Six Month Carvey. 140	Orlange										

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

2023 Fall Six Month Survey: No Change Comments:

Material

Material

Material Location

2024 Spring Six Month Survey: No Change

Material Description

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12" X 12" Dark Green Mix Floor Tile	50	SF	2nd Floor Halls and Engineers Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

10M	12" X 12" Dark Green Mix Floor Tile Mastic	50	SF	2nd Floor Halls and Engineers Office		Miscellaneous	No	None	0		YES	X NO
2022 Fall S	ix Month Survey: No C	hange			7							
Comments:		larige			+							
Comments.					+							
2023 Fall S	ix Month Survey: No C	hange			†							
Comments:	•	<u> </u>										
2023 Spring	g Six Month Survey: No	Change										
Comments:												
2024 Spring	g Six Month Survey: No	Change			-							
Comments:	•	<u> </u>										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

11	12" X 12" White with Green Specks Floor Tile	15000	SF	2nd Floor Halls, teachers offices, bathrooms, resource room, and multi- purpose room		Miscellaneous	No	None	0	YES
			_		1					
2022 Fal	II Six Month Survey: No Ch	ange								
Commen	nts:									
2023 Spi	ring Six Month Survey: No	Change								
Commen	<u> </u>				1					
					1					
2023 Fal	Il Six Month Survey: No Ch	ange			1					

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11M	12" X 12" White with Green Specks Floor Tile Mastic	15000	SF	2nd Floor halls, teachers offices, bathrooms, resource room, and multi- purpose room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Carpet Adhesive for Green/Yellow Striped Carpet Tile	275	SF	2nd Floor Small Corner Offices		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

											II.
2022 Fall Six	k Month Survey: No Ch										
Comments:											
2023 Spring Six Month Survey: No Change											
Comments:											
2023 Fall Six Month Survey: No Change											
Comments:					_						
2024 Spring Six Month Survey: No Change											
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

10920

Material

Units

LF

LF

Material

Quantity

5520

Material Location

Throughout 2nd Floor

Throughout 2nd Floor

HA No

16

17

Material Description

4" Light Green baseboards

Mastic used for baseboards

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18	2' X 2' White Ceiling Tiles	28000	SF	2nd Floor Halls, Vestibule, Teachers Offices		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall Civ	Month Common No Ch				1							
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange			1							
Comments:	•	-			1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	2' X 4' Drop Face White with Pin Dots Ceiling Tile	21875	SF	2nd Floor Classrooms and Multi- Purpose room		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

2024 Spring Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Sinks	14		2 Classrooms (Art Room & Science Room) in 2nd Floors, and Multi Purpose Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Acero Charter Schools - PFC Omar E. Torres
Date: 8/12/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.