Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Urban Prep Academy for Young Men - Bronzeville 66442 7620 School: **Oracle Unit: Building ID:** Address: 521 35th Region: Mail Room: 39 Asbestos Surveyor: Henderson, Kevin **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 10/23/2024 kmhenderson8@cps. Email Address: k12.il.us A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other Material Description HA No Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Category Quantity Units Type Type 1st Floor Office, Rooms YES X NO 107. 111. and 113. 104. 112, 100C, Lunchroom (119), 217, 216, 215, 1' x 1' Ceiling Tile Miscellaneous 214, 213, 210, 209, 208, 207, 205, 204, 203, 202, 201, 223, 222, 221, 220, 219 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

Oracle Unit: 66442

1A	1' x 1' Ceiling Tile Adhesive	•		1st Floor Office, Rooms 107, 111, and 113		Miscellaneous					YES	X NO
2022 Fall	Six Month Survey: No C	hange			7							
Comment		<u> </u>]							
2023 Fall	Six Month Survey: No C	hange										
Comment	s:				_							
2024 Fall	Six Month Survey: No C	hange										
Comment	S:				_							
2024 Spri	ng Six Month Survey: No	Change										
Comment	S:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
				Throughout School at								

Surface

No

Asbestos

Type

Material

Category

Friable

Damage

Type

None

0

Damage

Quantity

500

SF

HA No

1A

2

Material Description

Plaster

Material

Units

Material

Quantity

Material Location

Classroom Door Entrances- Ceilings

1st Floor Office, Rooms

Change in Assessment Category

YES

YES

X NO

Damage

Units

SF

3	9" x 9" Black Floor Tile - ABATED			Throughout Building, Hallways and Classrooms		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			 							
Comments:	Month Survey. No Cr	iarige										
Comments.					_							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:	•											
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:	4	12" x 12" Off-White Floor Tile w/Gray Streaks	Classrooms -ABATED 1999
2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2022 Fall	Six Month Survey: No Change	
Comments: 2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	Comment	S:	
2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2023 Fall	Six Month Survey: No Change	
Comments: 2024 Spring Six Month Survey: No Change	Comment	S:	
2024 Spring Six Month Survey: No Change	2024 Fall	Six Month Survey: No Change	
	Comment	S:	
Comments:	2024 Sprii	ng Six Month Survey: No Change	
	Comment	S:	

HA No

Material Description

12" x 12" Off-White Floor Tile w/Gray Streaks

Material

Units

Material Quantity Material Location

Library and Various

5	ABATED 1999			Classrooms		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No Ch	ange			7							
Comments	•											
2023 Fall S	Six Month Survey: No Ch	ange										
Comments												
2024 Fall S	Six Month Survey: No Ch	ange										
Comments												
2024 Sprin	g Six Month Survey: No	Change										
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
6	12" x 12" Off-White Floor			Library and Various Classrooms -ABATED		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

9" x 9" Floor Tile Mastic -

Tile w/Gray Streaks Mastic

Material

Units

Material

Quantity

Material Location

Corridors and Various

7	12" x 12" Brown Floor Tile - ABATED 1999			Room 103		Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No Ch	ange										
Comments:	•	•										
2023 Fall Si	x Month Survey: No Ch	ange										
Comments:												
	x Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
8	12" x 12" Brown Floor Tile Mastic - ABATED 1999			Room 103		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Mastic - ABATED 1999

Material

Quantity

Material

Units

9	Brown brick mortar - non ahera			Exterior of Building		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:					=							
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:	,	<u> </u>										
2024 Fall Six	Month Survey: No Ch	ange			_							
Comments:												
2024 Spring	Six Month Survey: No	Change			-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
10	12" x 12" Black Floor Tile - Removed			1st Floor Corridor, 2nd Floor Stairs, Rooms 211, 107, 111, 113, 200, 203,		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

and the Library

11	12" x 12" Black Floor Tile Mastic - Removed		Floor Corridor, 2nd Floor Stairs, Rooms 211, 107, 111, 113, and the Library	Miscellaneous			YES	X NO
2022 Fall Six	Month Survey: No Ch	nange						
Comments:								
2023 Fall Six	Month Survey: No Ch	nange						
Comments:								
2024 Fall Six	Month Survey: No Ch	nange						
Comments:								
2024 Spring	Six Month Survey: No	Change						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Black baseboards			Office, Library, Rooms 107, 111, 113, 105		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

13	Black baseboard adhesive			Offices, Library, Rooms 107, 111, 113, 105,		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No Ch	ange										
Comments												
2023 Fall S	Six Month Survey: No Ch	ange										
Comments	:											
	Six Month Survey: No Ch	ange										
Comments	:											
2024 Sprin	g Six Month Survey: No	Change										
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
14	Roof flashing - Non-AHERA			Exterior		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Quantity

Material

Units

Material Location

15	Exterior window caulk - Non-AHERA			Exterior		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No Ch	nange			7							
Comments:					1							
2023 Fall S	ix Month Survey: No Ch	nange			<u> </u>							
Comments:					-							
	ix Month Survey: No Ch	nange										
Comments:					-							
	g Six Month Survey: No	Change										
Comments:					-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
16	Roof deck - Non-AHERA					Miscellaneous					YES	X NO
	ix Month Survey: No Ch	nange]							
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2023 Fall Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12" x 12" Tan Floor Tile w/Brown Streaks	8000	SF	Stage, 1st Floor Library, Main Library, Rooms 112, 113, 107, 200, and 203, main office closet, 123C, conference room		Miscellaneous	No	Dist	10	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12" x 12" Tan Floor Tile w/ Brown Streaks Mastic	8000	SF	Stage, 1st Floor Library, Main Library, Rooms 112, 113, 107, 200, and 203		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12" x 12" White Floor Tile w/Black Specks	22500	SF	Faculty Dining, Principal, Gym & Lunchroom Entry, Eng. Storage, Rooms 105-106,108-110, 200- 201,204-219		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12" x 12" White Floor Tile w/Black Specks Mastic	22500	SF	Faculty Dining, Principal, Gym & Lunchroom Entry, Eng. Storage, Rooms 105-106, 108-110,200- 201,204-219		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Type	Damage Quantity	Units Units	Change in Asse	essment Category
21	12" x 12" White Floor Tile w/Gray Streaks	5488	SF	1st & 2nd Flr. Corridors and Foyer, Room 112 (patch) - 112 Abated		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		•							•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" White Floor Tile w/Gray Streaks Mastic	5488	SF	1st & 2nd Flr. Corridors and Foyer, Room 112 - Room 112 Abated		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12" x 12" Brown Mix Floor Tile	2800	SF	Rooms 102, 103, 104 and Corridor - Rooms 101, 102, 103 Abated Room 107		Miscellaneous	No	None	0	SF	YES X NO
2022 Fall Six	Month Survey: No Cha										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" Brown Mix Floor Tile Mastic	2800	SF	Rooms 102, 103, 104 and Corridor - Rooms 101, 102, 103 Abated Room 107		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
25	4" Brown vinyl baseboard	10000	LF	Throughout Facility, Rooms		Miscellaneous	No	None	0	LF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
26	4" Brown vinyl baseboard adhesive	1000	SF	Throughout Facility, Rooms		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Quantity Quantity	Units	Change in Asso	essment Category
27	4" Black vinyl baseboard	1000	LF	Rooms 102, 104, 200, 203, 205, 207, 218, 219, Library		Miscellaneous	No	None	0	LF	YES	X NO
2022 Fa	all Six Month Survey: No Ch	nange				•	•		•	•	,	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
28	4" Black vinyl baseboard adhesive	1000	LF	102, 104, 200, 203, 205, 207, 218, 219, Library		Miscellaneous	No	None	0	LF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

29	Brown carpet mastic			Replaced with HA 36		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No C	hange			7							
Comments:												
2023 Fall Six Month Survey: No Change												
Comments:		-										
2024 Fall S	ix Month Survey: No C	hange										
Comments:					_							
2024 Spring	g Six Month Survey: No	Change										
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
30	Gray carpet mastic			Room 119 - Library - Replaced with HA 36		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

 \Box

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Principal's Office -

31	Vibration Absorber on Duct			Southwest Corner Room on 2nd Floor - ABATED		Miscellaneous					YES	X NO
2022 Fall	Six Month Survey: No C	hange]							
Comment	•											
	Six Month Survey: No C	hange			1							
Comment	S:				_							
	Six Month Survey: No C	hange										
Comment	S:											
2024 Spri	ng Six Month Survey: No	Change										
Comment	S:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Type

Damage

Quantity

0

None

Damage

Units

SF

32

SF

Office

HA No

32

Material Description

Vault door liner

Material

Units

Material

Quantity

Material Location

Southwest Corner Room

Change in Assessment Category

YES

YES

X NO

33	12" x 12" Blue Floor Tile	200	SF	Kitchen Office and Kitchen Employee Locker Room	Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange									
2023 Fall Six Comments:	Month Survey: No Ch	ange									
2024 Fall Six Comments:	Month Survey: No Ch	ange									
2024 Spring Comments:	Six Month Survey: No	Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" Blue Floor Tile Mastic	200	SF	Kitchen Office and Kitchen Employee Locker Room		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

35	Boiler gaskets	40	LF	Boiler Room		Miscellaneous	Yes	None	0	LF	YES	X NO
2022 Fall Si	ix Month Survey: No C	hange			7							
Comments:	•	<u> </u>]							
2023 Fall Si	ix Month Survey: No C	hange										
Comments:					-							
2024 Fall Si	ix Month Survey: No C	hange										
Comments:												
2024 Spring	Six Month Survey: No	Change			_							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
36	Red carpet adhesive			Room 119, Office Area,		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Quantity

Material

Units

Material Location

Principal's Office

Change in Assessment Category

VES

37	Brown carpet adhesive - abated					Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No Ch	nange										
Comments:	X Month Carvey. No Ci	larigo										
Comments.												
2023 Fall Si	x Month Survey: No Cl	nange										
Comments:	,											
2024 Fall Si	x Month Survey: No Cl	nange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

2022 Fall Six	Month Survey: No Cha	ange		
Comments:				
2023 Fall Six	Month Survey: No Cha	ange		
Comments:				
2024 Fall Six	Month Survey: No Cha	ange		
Comments:				
2024 Spring S	Six Month Survey: No	Change		
Comments:		•		

Quantity

3

Units

SF

Material

Quantity

Material

Units

Material Location

Room 109, 113, Faculty

lounge, 106

HA No

38

Material Description

Sink undercoating

Change in Assessment Category

Damage

Units

Units

SF

YES

X NO

39	12" x 12" Beige Speckled Floor Tile (Patch)	1st Floor Corridor Outside Room 112	Miscellaneous			YES	X NO
2022 Fall Six	Month Survey: No Change						
Comments:	Civionar Garvey. 110 Gridings		_				
0000 5 11 0	M (1.0 N O)						
2023 Fall Six	Month Survey: No Change						
Comments:							
2024 Fall Six	Month Survey: No Change						
Comments:							
2024 Spring	Six Month Survey: No Chan	nge					
Comments:							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Mastic on 12" x 12" Beige Speckled Floor Tile	12	SF	1st Floor Corridor outside Room 112		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

41	Vibration collar	20	SF	2ndFloor Fan Room	Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange									
2023 Fall Six Comments:	Month Survey: No Ch	ange									
2024 Fall Six Comments:	Month Survey: No Ch	ange									
2024 Spring S Comments:	Six Month Survey: No	Change									

Type

Material

Category

Friable

Damage

Туре

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Boiler gaskets	20	LF	Boiler Room		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Repaired
Comments:New Gaskets
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Change in Assessment Category

Damage

Quantity

Damage

Units

2022 Fall S	Six Month Survey: No C	hange									
Comments		<u> </u>									
2023 Fall S	Six Month Survey: No C	hange									
Comments	:										
2024 Fall S	Six Month Survey: No C	hange									
Comments	:										
2024 Sprin	g Six Month Survey: No	Change									
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

TSI

Friable

No

Miscellaneous

Damage

Туре

Damage

Quantity

0

None

Damage

Units

SF

Material Location

Between Doolittle East

and Doolittle West

Throughout

2022 Fall Six Month Survey: No Change		
Comments:		
2023 Fall Six Month Survey: No Change		
Comments:		
2024 Spring Six Month Survey: No Change		
Comments:		
2024 Fall Six Month Survey: No Change		
Comments:		

57

SF

Material

Quantity

Material

Units

HA No

43

44

Material Description

Buried steam line

Fire doors

Change in Assessment Category

X NO

X NO

YES

YES

45	Chalkboard adhesive	44	SF	behind original chalkboards throughout facility		Miscellaneous	No	None	0	SF	YES	X NO
0000 5-11 0	Marth Oran Na C	N	·	•	7	•				•		
2022 Fall Six	Month Survey: No C	nange										
Comments:												
2023 Fall Six	Month Survey: No C	hange										
Comments:	•											
2024 Spring	Six Month Survey: N	o Change)									
Comments:												
2024 Fall Six	Month Survey: No C	hange										
Comments:	•											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Linoleum wood-patterned floor	5600	SF	Rooms 112, 208, 207, 205, 203, 202, 201		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

47	Linoleum wood-patterned floor Mastic	5600	SF	Rooms 112, 208, 207, 205, 203, 202, 201		Miscellaneous	No	None	0	SF	YES	X NO
					1							
2022 Fall Six	Month Survey: No Cha	ange										
Comments:	-											
2023 Fall Six	Month Survey: No Cha	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:	•											
2024 Fall Siv	Month Survey: No Ch	ange										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Wood floor	4000	SF	Gym (120)		Surface	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

49	2'x2' ceiling tile			100 Main office, Administration throughout		Surface					YES	X NO
2022 Fall	Six Month Survey: No C	hange										
Comments												
2023 Fall	Six Month Survey: No C	hange										
Comments	S:											
2024 Sprii	ng Six Month Survey: No	Change										
Comments	S:											
2024 Fall	Six Month Survey: No C	hange										
Comments	s:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
50	12" x 12" White w/ Blue Fleck Vinyl Floor Tile			Rooms 109, 108, 106, 105, 216, 212A Storage, 2nd FL womens		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

Material

Units

Material

Quantity

Material Location

2nd FL womens bathroom by stair 4 Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" x 12" White w/ Blue Fleck Vinyl Floor Tile Mastic			Rooms 109, 108, 106, 105, 216, 212A Storage, 2nd FL womens bathroom by stair 4		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	White and Gray linoleum	2000	SF	Rooms 104, 103, 102, 101, 101 supply closet, 109		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

53	White and Gray linoleum Mastic	2000	SF	Rooms 104, 103, 102, 101, 101 supply closet, 109		Miscellaneous	No	None	0	SF	YES	X NO
	Month Survey: No Ch	ange]	·						
Comments:												
	Month Survey: No Ch	ange			-							
Comments:					1							
2024 Spring	Six Month Survey: No	Change										
Comments:												
0004 Fall 0: Marth 0 and Na Olassa												
	2024 Fall Six Month Survey: No Change											
Comments:	Comments:											

Type

Material

Category

Friable

Damage

Туре

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	Carpet mastic	2500	SF	Room 120		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Change in Assessment Category

Damage

Quantity

Damage

Units

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
AB	Floor tile tan/ brown specks	7000	SF	Room 101-103, 206, 210, 212, 216, 217		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AB-1	Floor tile mastic	7000	SF	Room 101-103, 206, 210, 212, 216, 217		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

AC	Floor tile Black	900	SF	Room 111		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch											
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
1					1							

Type

Asbestos

Type

Material

Material

Category

Category

Friable

Friable

Damage

Damage

Туре

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

SF

Units

AC-1	Floor tile mastic	900	SF	Room 111	Miscellaneous	No	None	0
2022 Fall 9	Six Month Survey: No	Change						
Comments	3:							
2023 Fall :	Six Month Survey: No	Change						
Comments	3:							
2024 Fall :	Six Month Survey: No	Change						
Comments	S:							

Material Location

HA No

HA No

Material Description

Material Description

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Change in Assessment Category

Change in Assessment Category

YES

X NO

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
AD	Laminate floor	11000	SF	Room 112, 201-205, 207, 208, 221-223		Miscellaneous	No	None	0	SF	YES	X NO
	Month Survey: No Cha											
Comments:												
2023 Fall Six	Month Survey: No Cha	ange										
Comments:												
2024 Spring Six Month Survey: No Change												

Material

Damage

Friable

Damage

Damage

2024 Fall Six Month Survey: No Change
Comments:

Material

Material

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
AD-1	Laminate floor mastic	11000	SF	Room 112, 201-205, 207, 208, 221-223		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

				1 1							
2022 Fall Si	x Month Survey: No Cl	nange									
Comments:		.									
2023 Fall Si	x Month Survey: No Cl	nange									
Comments:											
	x Month Survey: No Cl										
Comments:											
	Six Month Survey: No	Change									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	_		1		_	-	_		-	1	ł

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

LF

290

LF

HA No

ΑE

ΑF

Material Description

Carpet mastic

Base board

Material

Quantity

Material

Units

Material Location

219A, 219B, 220

Lunch Room

Room 113, 211, 213-215,

Change in Assessment Category

X NO

X NO

YES

YES

											II
2022 Fall S	ix Month Survey: No C	hange									
Comments:											
2023 Fall S	ix Month Survey: No C										
Comments:											
2024 Spring Six Month Survey: No Change											
Comments:											
2024 Fall S	ix Month Survey: No C	hange									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

LF

SF

1800

HA No

AG

ΑН

Material Description

Base board mastic

Floor tile brown tan/specks

Material

Units

LF

SF

Material Quantity

290

Material Location

Lunch Room

Lunch Room

Change in Assessment Category

X NO

X NO

YES

YES

Al	Floor tile brown tan/specks mastic	1800	SF	Lunch Room		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ongo			1							
	Nonth Survey. No Ch	ange			4							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	-											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	J 2 3 3 3 1 1 1 1 2 2 2 3 1	
Б	Insulation on Condensate			2nd Floor Boiler Room -								

TSI

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

В

Comments:

Comments:

Comments:

Comments:

Material Description

Water Return Tank

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Floor tile brown tan/specks

Material

Quantity

Material

Units

Material Location

ABATED 1999

YES

X NO

D	Insulation on Water Supply Tank - ABATED			2nd Floor of Boiler Room - ABATED		TSI					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			-							
2023 Fall Six	« Month Survey: No Ch											
Comments:					_							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
F	Mag block duct insulation			Incinerator Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

abated 1999

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

Damage

Units

G	Insulation on Expansion Tanks - ABATED 1999			2nd Floor Boiler Room		TSI					YES	X NO
2022 Fall S	ix Month Survey: No Ch	nange]							
Comments:	•											
2023 Fall S	ix Month Survey: No Ch											
Comments:												
2024 Fall S	ix Month Survey: No Ch	nange										
Comments:												
	g Six Month Survey: No	Change										
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
J	Cementitious joint & fitting insulation	300	LF	Boiler Rooms, Fan Rooms, Plumbing Walls, 2nd Floor Closets and		TSI	Yes	None	0	LF	YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Stairwells

HA No

Material Description

Material

Quantity

Material

Units

Material Location

М	abated 2006			2nd Floor Fan Room		TSI					YES	X NO
2022 Fall S	Six Month Survey: No C	hange										
Comments): :	_										
2023 Fall S	Six Month Survey: No C											
Comments	S:											
	ng Six Month Survey: No	o Change										
Comments	S:											
	Six Month Survey: No C	hange										
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
N	Spray-on fire proofing			Basement Tunnel		Surface					YES	X NO
	· ·					Category	Friable					

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Units

Material

Quantity

Material Location

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Urban Prep Academy for Young Men - Bronzeville
Date: 10/23/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.