Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

66572 Noble - Chicago Bulls College Prep 4040 School: **Oracle Unit: Building ID:** Address: 2040 W Adams Region: Mail Room: Asbestos Surveyor: Marrero, Elizabeth **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 11/14/2024 Email Address: emarrero5@cps.k12.il. A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Other Posted to the CPS W Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar HA No Material Description Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Quantity Units Type X NO 1 Hard coat plaster SF SF YES 30000 Throughout Facility Surface Yes Loc 20 2022 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

2022 Fall S	Six Month Survey: No C	hange			\neg						
Comments		<u> </u>									
2023 Sprin	g Six Month Survey: No	Change									
Comments:											
2024 Fall S	Six Month Survey: No C	hange									
Comments	:										
2024 Sprin	g Six Month Survey: No	Change									
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Yes

Damage

Туре

None

Damage

Quantity

0

Material

Units

SF

Material

Quantity

2000

Material Location

Basement Boy's Locker

Room

Lunch Room

HA No

2

3

Comments:

Comments:

Comments:

Comments:

Material Description

1' x 1' Ceiling Tile (Thick)

2' x 4' Lay In Ceiling Panels - REMOVED

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

Change in Assessment Category

YES

YES

X NO

X NO

Damage

Units

SF

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego
4	1' x 1' Smooth Ceiling Tile (Thin)	300	SF	Room 013A		Miscellaneous	Yes	None	0	SF	YES X NO
2022 Fall Siv	Month Survey: No Ch	2000			1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5.1	12" x 12" Light Brown Floor Tile w/White Speckles	1100	SF	Classrooms 203, 211		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

5.2	12" x 12" White/Yellow Floor Tile w/Brown Speckles	315	SF	Room 101A (Gym Office), Gym, Adjacent Hall and Coaches Office		Miscellaneous	No	Loc	5	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	nange		·]				·		·	
Comments:					<u> </u>							
2023 Spring	Six Month Survey: No	Change										
Comments:					-							
2024 Fall Six	Month Survey: No Ch	nange										
Comments:												
2024 Spring	Six Month Survey: No	Change			-							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5.3	12" x 12" Brown/Yellow Floor Tile w/ White-Brown Specks		SF	Teacher's Lunch Room		Miscellaneous				SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

5.4	12" x 12" Brown Floor Tile	40	SF	Engineer's Storage	Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange									
2023 Spring S Comments:	Six Month Survey: No	Change									
2024 Fall Six Comments:	Month Survey: No Ch	ange									
2024 Spring Comments:	Six Month Survey: No	Change									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5.5	12" x 12" Beige Mix Floor Tile	20000	SF	Library, Storage Room Basement, Rooms 008, 010, 011,013, 016, 106, 111, 112, 116, 203, 207, 209, 210, 213, 214, 300, 301, 304-307, 313, 318, 006, 007, 114, 113		Miscellaneous	No	Dist	60	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

06	Speckled Floor Tile		washroom #202	Miscellaneous			YES	X NO
2022 Fall Six	Month Survey: No	Change		7				
Comments:	t monar Garray. Ha	Gridinge						
2022 Caring	Civ. Month Cumrour	la Changa						
Comments:	Six Month Survey: N	No Change		-				
Comments.				1				
2024 Spring	Six Month Survey: N	lo Change						
Comments:				_				
2024 Fall Six	Month Survey: No	Change		1				
Comments:	•							
				_				

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06A	12" x 12" Off-White Speckled Floor Tile Adhesive	27000	SF	1890 Building: 1st, 2nd, & 3rd Floor Corridors, Women's Bathroom, Third Floor Teacher's Lounge and Classrooms; 006, 006B, 008, 013A, 103, 107, 110, 111, 112, 201, 207, 209, 210, 212, 213, 214, 307, 309, 311, 312, 313, and 314		Miscellaneous	No	Loc	10	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:flooring & ceiling in room 111
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

6.1	9" x 9" Brown Floor Tile			Room 109		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No C	hange										
Comments	:	•										
2023 Sprin	g Six Month Survey: No	Change										
Comments	:											
2024 Sprin	g Six Month Survey: No	Change										
Comments	:											
2024 Fall S	Six Month Survey: No C	hange										
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	0" × 0"	+		 			1	1		1		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

SF

Material

Quantity

Material

Units

SF

Material Location

Rooms 004A & 004B

HA No

6.2

Material Description

Brown/Black/Red/Green

Mix Floor Tile

YES

X NO

6.3	9" x 9" Yellow & Green Floor Tile in a Checkerboard		Lunch Room		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No Cha	ange	•]	•	•	•	•	•	•	
Comments]									
2023 Sprin	g Six Month Survey: No (-									
Comments	Comments:										
2024 Fall S	ix Month Survey: No Cha	 ange		-							
Comments											
	g Six Month Survey: No (
Comments											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
7.1	Yellow linoleum	2000	SF	Gym		Miscellaneous	No	Loc	5	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
	Circ Maneth Common Na	Ob an an										

2023 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change

HA No

Comments:

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
7.2	Linoleum	1000	SF	Basement NW, NE Stairway		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Month Survey: No Change												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8.1	12" x 12"Light Brown Floor Tile w/White Specks Mastic	500	SF	Classrooms 203, 211		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

8.2	12" x 12" White/Yellow Floor Tile w/Brown Specks Mastic	426	SF	Room 101A Gym Office, Adjacent Hall and Coach Office		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Si	x Month Survey: No Ch	ange	<u> </u>	·]							
Comments:												
	Six Month Survey: No	Change			-							
Comments:					-							
2024 Spring	Six Month Survey: No	Change										
Comments:					_							
2024 Fall Si	x Month Survey: No Ch	ange			-							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8.3	12" x 12" Brown Floor Tile Mastic		SF	014		Miscellaneous				SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

8.4	12" x 12" Brown Floor Tile Mastic	40	SF	Engineer's Storage Hallway		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall	Six Month Survey: No Ch	ange]							
Comments:												
	ng Six Month Survey: No	Change]							
Comment	S:				-							
	Six Month Survey: No Ch	ange										
Comments	S:				1							
	ng Six Month Survey: No	Change]							
Comment	S:				_							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Engineer's Storage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8.5	12" x 12" Beige Mix Floor Tile Mastic	20000	SF	Bsmt. ClsRooms,Found. Library,102-104, 109, 111, 112, 115, 116, 203- 207, 209-215, 218, 301, 302, 304, 307, 308, 312- 314, 317, Hallway outside 306		Miscellaneous	No	Loc	1	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

12" x 12" Brown Floor Tile

Material

Quantity

Material

Units

2022 Fall Siz	x Month Survey: No C	hange									
Comments:	•										
2023 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Siz	x Month Survey: No C	hange									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

SF

SF

HA No

9.1

9.2

Material Description

9" x 9" Brown Floor Tile

Mastic

9" x 9"

Brown/Black/Red/Green

Mix Floor Tile Mastic

Material

Units

SF

SF

Material

Quantity

Material Location

Rooms 004A & 004B

109

Change in Assessment Category

X NO

X NO

YES

YES

9.3	9" x 9" Yellow & Green Floor Tile Mastic		SF	Lunch Room & Kitchen		Miscellaneous				SF	YES	X NO
2022 Fall	Six Month Survey: No C	hange			7							
Commen	-											
2023 Spr	ing Six Month Survey: No	o Change										
Commen	ts:											
2024 Fall	Six Month Survey: No C											
Commen	ts:				4							
	ing Six Month Survey: No	Change										
Commen	ts:				-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
10	Canvas wall covering	8000	SF	Hallway by Rooms 210, 104, 105, Men's WR by 210, Teacher's WR by 206, 214-216		Miscellaneous	No	None	0	SF	YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

		200, 214-210	
2022 Fall Six Month Survey: No Cha	nge		
Comments:	90		
2023 Spring Six Month Survey: No C	Change		
Comments:			
2024 Spring Six Month Survey: No C	Change		
Comments:			
2024 Fall Six Month Survey: No Cha	nge		
Comments:	<u>'</u>		

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2022 Fall S	Six Month Survey: No C	hange									
Comments											
2023 Sprin	g Six Month Survey: No	Change									
Comments	:										
2024 Fall Six Month Survey: No Change											
Comments	:										
2024 Sprin	g Six Month Survey: No	Change									
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

HA No

11.1

11.2

Comments:

Comments:

Comments:

Comments:

Material Description

Exterior window glaze -

Interior window glaze

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

Non-AHERA

Material

Units

LF

50

Material

Quantity

Material Location

Throughout Facility

Throughout Facility

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

LF

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Ceramic tile mortar	100	SF	Gym, 1st Floor S. Central, 2nd Floor N. Central, 2nd Floor W. Central, 3rd Floor Boy's Bathroom		Miscellaneous	No	Loc	1	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 A	Blue/maroon mix carpet mastic	400	SF	Rooms 013,107,201,202,208,210 ,214,216,300A, 302,303,308-311		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:flooring & ceiling in room 111

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
13 B	Green mix carpet mastic	800	SF	Foundation Library, 111, 112, 114, 123A, 013, 214, 311. 319		Miscellaneous	No	None	0	SF	YES	X NO
				-	1		-					

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:flooring & ceiling in room 111
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 C	Dark blue carpet mastic	400	SF	Rooms 103, 104, 105, 204 B		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
13 D	Blue carpet mastic		SF	114		Miscellaneous				SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring S Comments:	Six Month Survey: No	Change										
2024 Fall Six	Month Survey: No Ch	ange										

Comments:

2024 Spring Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 E	Blue/purple mix carpet mastic	1000	SF	109		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

14.1	Common brick mortar	20000	SF	Throughout Facility		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall	Six Month Survey: No Ch	nange			7							
Comment	S:]							
2023 Sprii	ng Six Month Survey: No	Change										
Comment	S:				_							
	Six Month Survey: No Ch	nange										
Comment	S:				4							
	ng Six Month Survey: No	Change										
Comment	S:				4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
44.0	Brown Brick Mortar - Non-			E								

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Units

Material Quantity Material Location

Exterior of Building

HA No

14.2

Comments:

Comments:

Comments:

Comments:

Material Description

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Change in Assessment Category

VES

YES

X NO

2022 Fall Si	x Month Survey: No C	hange									
Comments:											
2023 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Si	x Month Survey: No C	hange									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

200000

Material

Units

SF

Material

Quantity

Material Location

Exterior of Building

Throughout Facility

HA No

14.3

15.1

Material Description

Non-AHERA

Common brick

New Brown Brick Mortar -

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

SF

15.2	Original Brown Brick - Non- AHERA			Exterior of Building		Miscellaneous					YES	X NO
2022 Fall	Six Month Survey: No C	nange			\neg							
Comments	,	<u> </u>										
2023 Sprii	ng Six Month Survey: No	Change										
Comments	3:											
2024 Fall	Six Month Survey: No C	nange										
Comments	3:											
2024 Sprii	ng Six Month Survey: No	Change										
Comments	3:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15.3	New Brown Brick - Non-			Exterior of Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

AHERA

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

Damage

Units

HAN	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16		Insulation beneath boiler shells	100	SF	Boiler Room		TSI	Yes	None	0	SF	YES	X NO
2022	2 Fall Six	Month Survey: No Ch	ange]							

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:All boilers abated
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Boiler gaskets - front door	25	LF	Boiler #1		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:All boilers abated
2024 Fall Six Month Survey: No Change
Comments:

18	Boiler gaskets	25	LF	Boiler #2	Miscellaneous	Yes	None	0	LF	YES	X NO
2022 Fall Six	x Month Survey: N	o Change									
Comments:	k Month Garvey. 14	o onange									
2023 Spring	Six Month Survey	: No Change									
Comments:	_	-									
2024 Spring	Six Month Survey	: Abated									
Comments:	All boilers abated										
2024 Fall Six	x Month Survey: N	o Change									
Comments:											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Fire brick	100	SF	Incinerator		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

20	Drywall & compound	5000	SF	Rooms 004, 204 and 203	Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	nange									
Comments:											
	Six Month Survey: No	Change									
Comments:											
2024 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Ch	nange									
Comments:											

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Insulation Inside of Vault Door	28	SF	Near room 314		TSI	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Floor Tile Beneath 12" x 12" Floor Tile	800	SF	Room 112		Miscellaneous	No	None	0	SF	YES X NO
		•	•					•		•	_

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
23	Mastic Beneath 1st Layer of Floor Tile	800	SF	Room 112		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

24	Lab counter tops, sinks & tables	500	SF	Rooms 214, 215, 313B, 313C, 315, Basement Lab	Miscellaneous	No	None	0	SF	YES	X NO
0000 F-II 0:	Marth Orac Na Ob		•	•	•	•		•	•		
2022 Fall Six	Month Survey: No Cha	ange									
Comments:											
2023 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Spring S	Six Month Survey: No	Change									
Comments:	•										

Type

Material

Category

Damage

Quantity

Damage

Units

Damage

Type

Friable

2024 Fall Six Month Survey: No Change	
Comments:	
	I

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
25	2' x 4' Lay In Ceiling Panels	800	SF	315, 318		Miscellaneous	Yes	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
26	Material Beneath 12" x 12" Floor Tile	1000	SF	Rooms 313B & 314		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							

2022 Fall Six Month Survey: No Change
2022 Fall Six World Survey. No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
27	Mastic for Material Beneath 12" x 12" Floor Tile	1000	SF	Rooms 314 & 313B		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	4" Gray vinyl baseboard	190	LF	Room 315, 311, 310		Miscellaneous	No	None	0	LF	YES X NO
2022 Fall Six	Month Survey: No Ch	ango]						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
29	4" Gray vinyl baseboard mastic	190	LF	Room 315, 311, 310		Miscellaneous	No	None	0	LF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

30	Gray linoleum			Room 315		Miscellaneous					YES	X NO
2022 Fall Siz	x Month Survey: No C	hange										
Comments:		•										
2023 Spring	Six Month Survey: No	Change										
Comments:												
	Six Month Survey: No	Change										
Comments:												
2024 Fall Siz	x Month Survey: No C	hange										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
31	Gray linoleum mastic			Room 315		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32	2' x 4' Lay in Ceiling Tile	1050	SF	Rooms 102, 115, and Engineer's Office		Miscellaneous	Yes	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
33	Drywall	320	SF	Tank Room		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	Drywall tape/compound	268	LF	Tank Room		Miscellaneous	No	None	0	LF	YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
35	Sink undercoating	32	SF	Room 115, 202, 203, 306		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

36	White w/Gold Countertop Laminate	30	SF	Room 203		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall S	Six Month Survey: No Ch	nange										
Comments		g-										
2023 Sprin	g Six Month Survey: No	Change										
Comments	:											
2024 Sprin	g Six Month Survey: No	Change										
Comments	:											
2024 Fall S	Six Month Survey: No Ch	nange										
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
———		+	+	+		+	!	 	 	 	-	

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

2nd floor above Gym

HA No

37

Material Description

White w/Gold Countertop

Vinyl running track surface

YES

X NO

38	Vinyl running track surface adhesive	2nd floor above Gym	Miscellaneous		YES	X NO
2022 Fal	I Six Month Survey: No Change		7			
Commen						
2023 Spi	ring Six Month Survey: No Cha	nge	-			
Commen	ts:					
2024 Spi	ring Six Month Survey: No Cha	nge				
Commen	its:					
2024 Fal	Six Month Survey: No Change	9				
Commen	its:					
			_			

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Drywall	34000	SF	Electric Vault, Girl's Basement Bathroom, Basement Store Room, Teachers Lounge, 207, 3rd Fl Hall, 302, 303, 307, 310, 311, 313A		Miscellaneous	No	Loc	10	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Drywall joint compound	3400	SF	Electric Vault, Girl's Basement Bathroom, Teachers Lounge, 207, 3rd Fl Hall, 302, 303, 307, 310, 311, 313A		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Fire doors	224	SF	Boiler Room, Kitchen, Gym and Exterior Doors		TSI	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:Boiler room
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	4" Black vinyl baseboard	722	LF	Basement Hall, 1st Floor Boys Bathroom, 2nd Floor Girls Bathroom, 3rd Floor Hall, 3rd Floor Boys Washroom,Rooms216, 201,202,203,204,300A, 300T,302,303,313A.		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	4" Black vinyl baseboard adhesive	722	LF	Basement Hall, 1st Floor Boys Bathroom, 2nd Floor Girls Bathroom, 3rd Floor Hall, 3rd Floor Boys Washroom,Rooms216, 201,202,203,204,300A, 300T,302,303,313A.		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Gray w/White and Gray Floor Tile	3072	SF	Rooms 300A, 305, 310, 311, 216,215,211,208, 205, 206, 201, 111		Miscellaneous	No	Loc	25	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Gray w/White and Gray Floor Tile Mastic	3072	SF	Rooms 300A, 305, 310, 311, 216, 215, 211, 208, 205, 206, 201, and 111		Miscellaneous	No	Loc	25	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12" x 12" Gray w/Black and White Floor tile	624	SF	102		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" x 12" Gray w/Black and White Floor tile Mastic	624	SF	102		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
Johnnents.
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
48	12" x 12" Beige w/ Light Brown Floor Tile	616	SF	Lunchroom		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
, ,
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12" x 12" Beige w/ Light Brown Floor Tile Mastic	616	SF	Lunchroom		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
50	Peg board	33	SF	Girl's Basement Bathroom and Library		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:	•	•			1							
2023 Spring	Six Month Survey: No	Change			_							
Comments:												
2024 Spring	Six Month Survey: No	Change			_							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange			-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Peg board adhesive	33	SF	Girl's Basement Bathroom and Library		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

Page 38

	· ·	Quantity	Units		Type	Category		Type	Quantity	Units	, and the second	0 ,
52	Chalk boards	4720	SF	Basement Lab, Industrial Arts, Rooms: 103- 106,111-113,A&B,205- 211,214-216,300- 305,307,312-315 Library, 307,313A		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall	Six Month Survey: No (Change]							
Comment	S:	-]							
2023 Spri	ng Six Month Survey: N	lo Change										
Comment	S:											
2024 Spri	ng Six Month Survey: N	lo Change			-							
Comment	S:											
2024 Fall	Six Month Survey: No (Change			-							

Material

Friable

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
53	Marker board adhesive	240	SF	Library, 307, 313A		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Damage Change in Assessment Category

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Asses	ssment Category
54	Duct vibration absorber	4	LF	Room 011		Miscellaneous	No	None	0	LF	YES	X NO
2022 Fall Comment	Six Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Gray carpet adhesive	800	SF	Teachers Lounge on 1st and 209		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

2022 Fall Six Month Survey: No Change											
Comments:											
2023 Spring S	Six Month Survey: No	Change									
Comments:					_						
	Six Month Survey: No	Change									
Comments:											
	Month Survey: No Ch	nange									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

SF

384

SF

Material

Quantity

Material

Units

Material Location

Office

Room 109

Room 108 and Principal's

HA No

56

57

Material Description

Purple carpet adhesive

adhesive.

Green/orange/yellow carpet

Change in Assessment Category

X NO

X NO

YES

YES

58	Gray and Blue Carpet Adhesive	SF	Rooms 112, 210, 212, 214	Miscellaneous		SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange						
2023 Spring Comments:	Six Month Survey: No	Change		- -				
	Circ Month Common No.	Change		<u>-</u> -				
Comments:	Six Month Survey: No	Change		_				
2024 Fall Six Comments:	Month Survey: No Cha	ange		-				

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Blue w/White Carpet Adhesive		SF	Rooms 104, 204		Miscellaneous				SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
60	Vault door insulation	28	SF	Main Office (109)		TSI	Yes	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12" x 12" tan Floor Tile w/ Light Brown	2000	SF	Rooms 006, 006B and 008		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
62	Mastic for 12" x 12" tan Floor Tile w/ Light Brown	2000	SF	Rooms 006, 006B, and 008		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2000 Carrier Cir. Marsh Common No Characa
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
63	Green terrazzo	4000	SF	Stairwells and washroom adjacent to 315		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
64	12" x 12" Dark Brown w/ Gray Floor Tile	4420	SF	Lunch Room		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:					1							
2023 Spring	Six Month Survey: No	Change										
Comments:					 							
2024 Spring	Six Month Survey: No	Change										
Comments:					 							
2024 Fall Six	Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Mastic Associated w/ 12" x 12" Dark Brown w/ Gray Floor Tile	4420	SF	Lunch Room		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
66	12" x 12" Gray w/ Beige and Dark Gray Floor Tile	1900	SF	2nd Floor Above Gym		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Month Survey: No Change												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Mastic Associated w/ 12" x 12" Gray w/ Beige and Dark Gray Floor Tile	1900	SF	2nd Floor Above Gym		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

68	Adhesive Associated w/ Gray Carpet Square	SF	Rooms 107 and 315		Miscellaneous		SF	YES	X NO
2022 Fol	I Six Month Survey: No Cha	2020		1					
		ange							
Commer	nts:								
2023 Sp	ring Six Month Survey: No (Change							
Commer	nts:								
2004.0	· 0: M // 0 N/	01		4					
2024 Sp	ring Six Month Survey: No (Change							
Commer	nts:								
2024 Fal	I Six Month Survey: No Cha	ange							
Commer	nts:	·	·						
	·		·	1					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Adhesive Associated w/ Blue Carpet	30	SF	Room 110		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
70	Adhesive Associated w/ Gray and Green Carpet		SF	Rooms 309, 310, and 312		Miscellaneous				SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12" x 12" Dark Tan w/ Beige and Brown Floor Tile	500	SF	Room 217		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

72	Mastic Associated w/ 12" x 12" Dark Tan w/ Beige and Brown Floor Tile	500	SF	Room 217		Miscellaneous	No	None	0	SF	YES	X NO
0000 F II 0:	M (1.0 N 0)	•	•	•	1	•		•	•	•		
2022 Fall Six	Month Survey: No Cha	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12" x 12" Yellow Floor Tile	200	SF	Room 212		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

2024 Fall Six Month Survey: No Change

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
74	Mastic Associated w/ 12" x 12" Yellow Floor Tile	200	SF	Room 212		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	12" x 12" Light Brown Floor Tile		SF	Room 212		Miscellaneous				SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

76	Mastic Associated w/ 12" x 12" Light Brown Floor Tile		SF	Room 212		Miscellaneous				SF	YES	X NO
2022 Fall S	Six Month Survey: No Ch	ange										
Comments		ango										
Comments	··											
2023 Sprin	g Six Month Survey: No	Change										
Comments):											
_												
	g Six Month Survey: No	Change										
Comments	:											
2024 Fall 9	Six Month Survey: No Ch	ange			_							
Comments	,	arige										
Comments) .											
					_							
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

		Qualitity	Offits		Туре	Calegory		туре	Quantity	Office		
80	12" x 12" Beige Floor Tile w/ Specks	2260	SF	Room 206, 205, 204, 218, 215, 213, 211, 208, 103, 104, 300, 304, 307, 313, 317 hall outside Room 306		Miscellaneous	No	Dist	99	SF	YES	X NO
2022 Fall Six	Month Survey: No Cha	ango										
ZUZZ I ali Six	Month Survey. No Cha	ange										
Comments:												
2222 2 : 6		<u> </u>			1							
2023 Spring S	Six Month Survey: No (Change										
Commonto	-											

Comments:

2024 Spring Six Month Survey: No Change

Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
81	6" Black vinyl baseboard	24	LF	Room 310, Room 216		Miscellaneous	No	None	0	LF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			7							
Comments:					<u> </u>							
2023 Spring	Six Month Survey: No	Change			1							
Comments:	•	•										

2024 Spring Six Month Survey: No Change Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	6" Black vinyl baseboard adhesive	24	LF	Room 310, Room 216		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

83	Gray ceramic floor tile	400	SF	3rd Girls Toilet Room, 3rd Floor Boys Bathroom, Basement Girls Bathroom	Miscellaneous	No	Loc	3	SF	YES	X NO
2022 Fall Six	Month Survey: No C	hange	<u> </u>								
Comments:		90									
	Six Month Survey: No	Change									
Comments:											
	Six Month Survey: No	Change									
Comments:											
2024 Fall Six Comments:	Month Survey: No C	hange									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

3rd Girls Toilet Room, 3rd

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	Gray ceramic floor tile mastic	400	SF	3rd Girls Toilet Room, 3rd Floor Boys Bathroom, Basement Girls Bathroom		Miscellaneous	No	Loc	3	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA NO	Material Description	Quantity	Units	iviaterial Location	Type	Category	Filable	Type	Quantity	Units	Change in Asses	ssment Category
85	White floor (2nd layer)	625	SF	Room 313		Miscellaneous	No	Loc	10	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	Fire stop caulk	2	SF	Room 316		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Gray tarrazzo	400	SF	North 3rd Floor Boys Toilet Room, North 2nd fFloor Boys Toilet Room, North 2nd floor Girls Toilet Room, 1st Floor North Boys Toilet Room, 1st Floor North Girls Toilet Room		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	Vinyl sheet flooring tile pattern	500	SF	1st Floor Teachers Lounge		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 55

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
89	1' x 1' Pinhole Ceiling Tile	500	SF	Room 011		Miscellaneous	Yes	None	0	SF	YES	X NO
2022 Fall Six Month Survey: No Change												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	1' x 1' Ceiling Tile w/ Pinholes Adhesive	500	SF	Room 011		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
91	12" x 24" Gray Floor Tile	3000	SF	Basement Lunchroom		Miscellaneous	No	None	0	SF	YES	X NO
	Month Survey: No Ch	nange										
Comments:												
2023 Spring	Six Month Survey: No	Change			_							
Comments:					-							
2024 Spring	Six Month Survey: No	Change			-							
Comments:												
2024 Fall Six	Month Survey: No Ch	nange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	12" x 24" Gray Floor Tile Mastic	3000	SF	Basement Lunchroom		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

2022 Fall Si	x Month Survey: No Cl	hange									
Comments:											
2023 Spring	Six Month Survey: No	Change									
Comments:											
2024 Spring Six Month Survey: Abated											
Comments:	All boilers abated										
	x Month Survey: No Cl	hange									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
		_	1		_	-	_	†	-	+	

Type

Material

TSI

Category

Miscellaneous

Friable

Damage

Type

Loc

Yes

25

Damage

Quantity

Damage

Units

SF

100

Material

Units

SF

Material Quantity

Material Location

Boiler Room

Boiler Room

HA No

Α

В

Material Description

Water tank insulation

Fiberglass boiler insulation

Change in Assessment Category

X NO

X NO

YES

YES

2022 Fall Six	Month Survey: No Ch	nange									
Comments:	•										
2023 Spring	Six Month Survey: No	Change									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Ch	nange									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

TSI

Category

Miscellaneous

Friable

Yes

Damage

Туре

Loc

Damage

Quantity

5

Damage

Units

SF

HA No

С

D

Comments:

Comments:

Comments:

Comments:

Material Description

Water meter packing

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

Tank insulation

Material

Quantity

125

Material

Units

SF

Material Location

Sprinkler Room - Abated

Tank Room

Change in Assessment Category

X NO

X NO

YES

YES

HA No M	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E Pr	Preformed pipe insulation	550	LF	Basement, Boiler Room, Lunchroom, Air Chamber, Elect. Room, Room 4A		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:Boiler room
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Preformed pipe joint insulation	56	SF	Basement, Boiler Room, Lunchroom, Air Chamber, Elect. Room, Room 4A		TSI	Yes	Loc	3	SF	X YES NO

2022 Fall Six Month Survey: Abated
Comments:abatement to repair leaking pipe in boiler room
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:Boiler room
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Cardboard pipe insulation	1830	LF	Engineer's's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out, 015		TSI	Yes	Loc	3	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Hard joint cmpd. On cardboard pipe insulation	250	SF	Engineer's's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out		TSI	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J.1	Hard joint cmpd orig. Fiberglass pipe insulation	270	SF	Engineer's's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out		TSI	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J.2	Hard joint cmpd new fiberglass pipe insulation	100	LF	Throughout Facility		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Assess	sment Category
К	Aircell pipe insulation	300	LF	Basement, 2nd Floor, 1st fl washroom, Attic		TSI	Yes	Loc	1	LF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Hard Joint Compound on Aircell Pipe Insulation	70	SF	Basement & Second Floor, 1st fl washroom, Attic		TSI	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
M	Duct insulation	50	SF	Kitchen		TSI	Yes	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Noble - Chicago Bulls College Prep
Date:	8/1/2024
the Asbest	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of tos Management Plan is available at each school during school hours by appointment. to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last in	se be advised that CPS conducts asbestos inspections of all Schools every three years. espection was completed in 2022. surveillances are conducted every six months.
CHECK OF	<u>NE</u>
Ac	copy of this notice was sent home in each child's backpack.
A c	copy of this notice was printed in the school's newsletter and sent home with each child
A c	copy of this notice was printed in the school's calendar and sent home with each child
X Oth	ner. Posted to the CPS Website
A COP	Y OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.