Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Noble - Muchin College Prep 66573 **Building ID:** 1137 School: **Oracle Unit:**

Address: 1 N State Street Region: Mail Room: Asbestos Surveyor: Marrero, Elizabeth

> Survey Date: 11/14/2024 emarrero5@cps.k12.il. Email Address:

						us								
	A copy of the2022/202	3 notice to p	parents and	I staff regarding the asb	estos manag	stos management plan notifications was distributed via:								
	Each child's backpa	printed in school's news	Notice printed in school's calendar X Other Pested to the CPS We											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category		
9GFT+M	9" x 9" Green Floor Tile w/ Streaks and Associated Black Mastic			West portion of seventh floor		Miscellaneous					YES X	NO		
2022 Fall Si Comments:	x Month Survey: No Ch	nange												
2023 Fall Si	x Month Survey: No Ch	nange			-									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

X CHECK HERE IF NO CHANGE TO ASBESTOS

9TFT+M	9" x 9" Tan Floor Tile w/ Streaks and Associated Black Mastic		West portion of seventh floor		Miscellaneous					YES	X NO
			<u> </u>	•		•	•	•	•	•	
2022 Fall Six	Month Survey: No Ch	ange									
Comments:	-										
2023 Spring S	Six Month Survey: No	Change									
Comments:	•			1							
2023 Fall Six	Month Survey: No Ch	ange									
Comments:	•										
2024 Spring S	Six Month Survey: No	Change									
Comments:		g-									
2024 Fall Six	Month Survey: No Ch	ange									
	Month Survey. No Ch	ange		1							
Comments:]							
]							

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB3B	3" Brown vinyl baseboard			U09, U10, 701, 702							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Type	Category	Type	Quantity	Units		
BB3BM	Tan mastic behind 3" brown vinyl baseboard			U09, U10, 701, 702						YES	X NO
2022 Fall Six	Month Survey: No Cha	ange									
Comments:											
2023 Fall Six	Month Survey: No Cha	ange									
Comments:											
2023 Spring	Six Month Survey: No (Change									
Comments:											
	Six Month Survey: No (Change									
Comments:											
	Month Survey: No Cha	ange									
Comments:											

Material

Damage

Damage

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB4B	4" Brown vinyl baseboard	44	SF	Vestibule 744, U35, U36		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

BB4BM	Brown mastic behind 4" brown vinyl baseboard	44	SF	Vestibule 744, U35, U36		Miscellaneous	No	None	0	SF	YES	X NO
					1							
2022 Fall Six	Month Survey: No Cha	ange										
Comments:												
2023 Fall Six	Month Survey: No Cha	ange										
Comments:	-											
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Cha	ange										
Comments:	•											
2024 Spring S	Six Month Survey: No	Change										
Comments:	· ·											
					1							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB4G	4" Gray vinyl baseboard			Classrooms, offices, hallways throughout							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
BB4GM	Yellow mastic behind 4' gray vinyl baseboard			Classrooms, offices, hallways throughout							YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			7							
Comments:	,	<u> </u>										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:					_							
	Month Survey: No Ch	ange										
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB6G	6" Gray vinyl baseboard			Center area of east upper hallway at lockers							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
BB6GM	Yellow mastic behind 6" gray vinyl baseboard			Center area of east upper hallway at lockers							YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:	,	.										
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	•	Ŭ										
_					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CFT1G	Blue Grout for 1" x 1" Black Ceramic Floor Tile			Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Page 6

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CFT3G	Gray Grout for 3" x 3" Brown Ceramic Floor Tile	25	SF	L65		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CG	Clear carpet glue			Classrooms and offices on both levels of 7th floor (Rooms 703, 704, 705, 706, 707, 708, 716, 720, 721, 722, 723, 724, U00, U01, U02, U03, U04, U06, U07, U08, U20, U21, Lower 7th north hallway, L00, L01, L02, L04, L50, L51, L52, L53, L54, L55, L56, L57, L58, L59, L60, L61)							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
CL-1	Duct caulk	50	LF	Mechanical Room		Miscellaneous	No	None	0	LF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CT1	1' x 1' White Fissured Ceiling Tile	25	SF	L33		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CT2	2' x 2' White Fissured Ceiling Tile (Replacement)			Vestibule L37							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
СТЗ	2' x 2' White Ceiling Tile w/ Fiberglass Backing			Lower 7th floor ceilings (except south hall, toilets, mech. Spaces); Upper 7th floor ceilings (except halls, toilets, kitchen, mech. Spaces, reception)							YES X NO
2022 Fall Siz	x Month Survey: No Ch	ange		medi. opaecs, receptiony							

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
CT4	2' x 4' White Smooth Ceiling Tile			West hallways							YES	X NO
2022 Fall Six	k Month Survey: No C	hange										
Comments:	•	V										
2023 Fall Six	Month Survey: No C	hange										
Comments:	-	-										
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No C	hange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CWT1G	Blue Grout for 1" x 1" Blue Ceramic Accent Wall Tile			Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

	·	Quantity	Units		Type	Category		Type	Quantity	Units		
CWT4G	Blue Grout for 4" x 4" Gray Ceramic Wall Tile			Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733							YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			7							
Comments:	t monar ourroy. Ho on	arigo										
	Six Month Survey: No	Change			_							
Comments:					_							
2023 Fall Six	Month Survey: No Ch	ange			_							
Comments:	Civional Carvey. 140 On	arige			-							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change			-							
Comments:	Six Moritin Survey. NO	Change			-							
Comments.					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
DC	Gray caulk			At seams of new ductwork above ceilings throughout renovated spaces							YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			7							
Comments:					1							
2023 Spring	Six Month Survey: No	Change			-							
Comments:	Olk Month Odivoy. NO	Silarigo			1							
					() ()							

Material

Friable

Damage

Damage

Damage

Material

Material

Material Location

HA No

Material Description

2023 Fall Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Comments:

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
DWEO	Drywall	1600	SF	East Portion - U34, U35, U36L32, L33, L34		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Month Survey: No Change Comments:												
	Month Survey: No Ch	ange			- -							
Comments:					_							
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange			1							
Comments:	,											
2024 Spring	Six Month Survey: No	Change			1							
Comments:	,]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DWJCEO	Drywall joint compound	1600	SF	East Portion - U34, U35, U36L32, L33, L34		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

DWJCN	Drywall joint compound		Interior classrooms, offices, corridors, washrooms				YES	X NO
0000 F II O'			·	¬				
2022 Fall Six	Month Survey: No Cha	ange						
Comments:								
2023 Fall Six	Month Survey: No Cha	ange						
Comments:								
2023 Spring S	Six Month Survey: No	Change						
Comments:								
2024 Fall Siv	Month Curvoya No Ch	0000		_				
	Month Survey: No Cha	ange						
Comments:								
2024 Spring S	Six Month Survey: No	Change						
Comments:								

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DWJCWO	Drywall joint compound	50000	SF	Throughout building		Miscellaneous	No	Loc	10	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
DWN	Drywall			Interior classrooms, offices, corridors, washrooms							YES	X NO
2022 Fall S	ix Month Survey: No C	hange	•			•	•	•	•			
Comments:		-										
2023 Fall S	ix Month Survey: No C	hange										
Comments:												
2023 Spring	g Six Month Survey: No	Change										
Comments:	:											
2024 Fall S	ix Month Survey: No C	hange										
Comments:												
2024 Spring	g Six Month Survey: No	Change										
Commonte	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DWWO	Drywall	1415	SF	West Portion - Vestibule 744, 742, 743, 738 (Closet)		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FD1	Solid flush wood fire door insulation			700, 703-708, 715, 716, 720-724, 738, L00-L04, L35, L36, L62, L63, L66- L72, U01-U04, U30-U32, U41, U42							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FD2	Metal fire door insulation			731-733, 735-737, 742- 744, L7L, L7W, L7U, L30- L34, L40, L64, L65, L74, LE29, LE30, U33-U38, U40, UE29, UE30							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FD3	Glazed metal fire door insulation			701, 702, 709-715, L04, L50, L52-L61, U05-U10, U20, U21							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FP	Sprayed-on fireproofing	1930	SF	Mechanical room, hall 7E, U34, U35, Kitchen, L32, L33		Surface	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
OOOA Fall Ois Marth Osmass No Ohanga
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-1	12" x 12" Gray w/ Dark Gray Floor Tile	70	SF	Mop room by boys washroom		Miscellaneous	No	Loc	10	SF	YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-2	12" x 12" Gray w/ Dark Gray Floor Tile Mastic	70	SF	Mop room by boys washroom		Miscellaneous	No	None	0	SF	YES X NO
•											

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-3	12" x 12" Gray w/ Dark Gray Spots Floor Tile	500	SF	Room L-04		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
FT-4	12" x 12" Gray w/ Dark Gray Spots Floor Tile Mastic	500	SF	Room L-04		Miscellaneous	No	None	0	SF	YES	X NO
		*	•	•	1	•	•	•	•	•	•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
LT	Lab table top			709, 713, 714, 715							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
MJP	Mudded joint packings	50	LF	Perimeter columns and shafts		TSI	Yes	None	0	LF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	•	J										
2023 Fall Six	Month Survey: No Ch	ange			<u> </u>							
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six Month Survey: No Change												
Comments:	•											
2024 Spring S	Six Month Survey: No	Change										

Material

Friable

Damage

Damage

Asbestos

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
MM	Mirror mastic			U09, Bathroom rooms (L35, L36, L67, L68, U30, U31, U37, U38, 732, 733)							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Material Material Location

Page 22

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
OCFTG	Gray Grout for Octagon- shaped Ceramic Floor Tile	604	SF	Northeast stairwell landing, stairwell landing by U39		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		•		•		•	•	•		

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2004 Caria a Cir. Manth Comor No Changa
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
, ,
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PLE	Plaster walls/ceilings	65000	SF	Original perimeter walls & original ceilings in east portion		Surface	No	Loc	20	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
PLW	Plaster walls/ceilings	27800	SF	Original perimeter walls & original ceilings in west portion		Surface	No	Loc	10	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		•		•	•	•	•	•		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
RFM	Raised floor stand black mastic pods			West portion of seventh floor		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
SST	Slate stair treads	262	SF	Northeast stairwell landing, stairwell landing by U39		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Si	x Month Survey: No C	hange]							
Comments:	•	Ŭ										
2023 Spring	Six Month Survey: No	Change			1							
Comments:	•]							
2023 Fall Si	x Month Survey: No C	hange			1							
Comments:	•]							
2024 Fall Siz	x Month Survey: No C	hange			1							
Comments:	•											
2024 Spring	Six Month Survey: No	Change			1							
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
STG	Gray vinyl stair treads			Center stairways in north and south hallways							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
STGM	Clear mastic below gray vinyl stair tread			Center stairways in north and south hallways							YES	X NO
2022 Fall Six	Month Survey: No Ch	nange			1							
Comments:	•											
2023 Fall Six	Month Survey: No Ch	nange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VJC	Vibration joint cloths	50	SF	Mechanical Room 741		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 26

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VSF2B	Blue 2' x 2' Vinyl Sheet Floor Squares			West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)							YES X NO
2022 Fall Si	ix Month Survey: No Cl	hange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VSF2DG	Dark Gray 2' x 2' Vinyl Sheet Floor Squares			West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)							YES X NO
2022 Fall Six	Month Survey: No C	hange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
VSF2G	Gray 2' x 2" Vinyl Sheet Floor Squares	20000	SF	West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)		Miscellaneous	No	Loc	1	SF	YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Oracle Unit: 66573

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VSF2M	Clear mastic			Below Multi-Colored 2' x 2' Vinyl Sheet Floor Squares							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VSF2T	Tan 2' x 2' Vinyl Sheet Floor Squares			West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)							YES X NO
2022 Fall Si	ix Month Survey: No C	hange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Di Ui
VSFB	Blue vinyl sheet flooring			East upper corridors, lower south corridor, U05, U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)						
2022 Fall S	Six Month Survey: No Cl	nange]					
Comments	•									
2023 Sprin	ng Six Month Survey: No	Change								
Comments	•	Onlange								
2023 Fall S	Six Month Survey: No Cl	nange								
Comments	•	gc								
2024 Fall S	Six Month Survey: No Cl	nange								
Comments		J -								
2024 Sprin	ng Six Month Survey: No	Change								
Comments	· · · · · · · · · · · · · · · · · · ·	Chango								

Damage

Units

Change in Assessment Category

YES

X NO

Oracle Unit: 66573

VSFC Gray Caulk at Seams of U32, U39, L03, L62, L69, L70, L71 (this material is	YES X NO
Flooring part of a four (4) color pattern)	
2022 Fall Six Month Survey: No Change Comments:	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VSFDG	Dark gray vinyl sheet flooring			East upper corridors, lower south corridor, U05, U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)							YES X NO
2022 Fall Size	x Month Survey: No C	hange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units
VSFG	Gray vinyl sheet flooring			East upper corridors, lower south corridor, U05, U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)						
2022 Fall \$	Six Month Survey: No Ch	nange]					
Comments										
2023 Fall 9	Six Month Survey: No Ch	nange								
Comments		larigo								
2023 Sprir	ng Six Month Survey: No	Change								
Comments	7									
2024 Sprin	ng Six Month Survey: No	Change								
Comments	· · · · · · · · · · · · · · · · · · ·	<u> </u>								
2024 Fall \$	Six Month Survey: No Ch	nange								
Comments					1					

Change in Assessment Category

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
VSFM	Yellow mastic			Below Multi-colored Vinyl Sheet Flooring							YES	X NO
2022 Fall Six	Month Survey: No C	hange]							
Comments:	•	<u> </u>										
2023 Spring	Six Month Survey: No	Change			-							
Comments:		<u> </u>										
2023 Fall Six	Month Survey: No C	hange										
Comments:												
2024 Fall Six	Month Survey: No C	hange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:	-											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VSFP	Pink vinyl sheet safety flooring			Kitchen (U33), L30, L31							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
VSFPC	Pink caulk			Seams of Pink Vinyl Sheet Safety Flooring							YES	X NO
2022 Fall Six	Month Survey: No C	hange			1							
Comments:	-											
2023 Fall Six	Month Survey: No C	hange			-							
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No C	hange										
Comments:					_							
	Six Month Survey: No	Change										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VSFPL	Lip at Edge of Pink Vinyl Sheet Safety Flooring			Kitchen (U33), L30, L31							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Page 37

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
VSFPM	White mastic			Below Pink Vinyl Sheet Safety Flooring							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

VSFT	Tan vinyl sheet flooring		East upper corridors, lower south corridor, U05, U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)			
2022 Fall 9	Six Month Survey: No Char	nae				
Comments	•	190				
2023 Fall \$	Six Month Survey: No Char	nge				
Comments						
2023 Sprir	ng Six Month Survey: No Cl	hange				
Comments	S:					
2024 Sprin	ng Six Month Survey: No Cl	hange				
Comments	S:					
2024 Fall \$	Six Month Survey: No Char	nge				
Comments	S:	·				

Material Location

Asbestos

Type

Material

Category

HA No

Material Description

Material

Quantity

Material

Units

Damage Quantity Damage

Units

Change in Assessment Category

YES

X NO

Damage

Type

Friable

Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	WCE	Interior window caulk			East Portion		Miscellaneous					YES	X NO
2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2022 Fall Six	Month Survey: No C	hange										
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:	•											
2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Fall Six	Month Survey: No C	hange										
Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:		•										
2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Spring	Six Month Survey: No	Change										
Comments: 2024 Fall Six Month Survey: No Change	Comments:												
2024 Fall Six Month Survey: No Change	2024 Spring	Six Month Survey: No	Change										
, ,	Comments:												
Comments:	2024 Fall Six	Month Survey: No C	hange										
	Comments:	•	_										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
WCW	Interior window caulk			West Portion		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

WFG	Yellow glue			Below maple Flooring and Athletic Flooring Systems							YES	X NO
2022 Fall (Civ Month Cumrour No C	`hongo			7							
	Six Month Survey: No C	nange										
Comments	S:											
0000 F II I	3: M (I 0 N 0				4							
2023 Fall S	Six Month Survey: No C	nange										
Comments	S:											
2023 Sprir	ng Six Month Survey: No	o Change										
Comments	S:											
0004 On six	a Circ Mandle Common N	- Ob										
	ng Six Month Survey: No	o Change										
Comments); -											
2221 = 111					4							
2024 Fall S	Six Month Survey: No C	hange										
Comments	s:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

2022 Fall Six	Month Survey: No Cha	ange	
Comments:			
2023 Fall Six	Month Survey: No Cha	ange	
Comments:			
2023 Spring	Six Month Survey: No	Change	
Comments:			
2024 Fall Six	Month Survey: No Cha	ange	
Comments:			

HA No

WGE

Material Description

Interior window glazing

Material

Quantity

Material

Units

Material Location

West Portion

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
WGW	Interior window glazing			West Portion		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Noble - Muchin College Prep
Date: 8/1/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. Pested to the CPS Website
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 66573