

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Sor Juana Ines de la Cruz ES  
**Address:** 4034 W. 56th St.

**Oracle Unit:** 23521  
**Region:** 04

**Building ID:** 1200  
**Mail Room:** 44

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Rydell, Michael  
**Survey Date:** 12/11/2025  
**Email Address:** mcrydell@cps.edu

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other | CPS website

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 001   | 1' x 1' Ceiling Tile |                   |                | MATERIAL REMOVED  |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 002   | 9" x 9" Brown w/ White & Red Streaks Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 003   | 1' x 1' Solid Act Ceiling Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description       | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 004   | 1' x 1' Holed Ceiling Tile | 5000              | SF             | Original Building 1st, 2nd, 3rd, 4th Floor & Corridor (Above New Tile) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description   | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 005   | 1' x 1' Metal Pan Act. |                   |                | Faculty Lounge, Faculty Lounge |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description              | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 006   | 1' x 1' Ceiling Tile: Pocked Act. |                   |                | Original Building: Ground Floor Lobby, South Entrance. |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 007   | 2' x 4' Ceiling Tile | 3000              | SF             | 2nd Floor Workout Room Above Gym Offices, Library, 302, 304 (Classroom), Library Bookstore (200B), Library Workroom (200C), Library Office |               | Miscellaneous     | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 008   | 9" x 9" Gray w/ White Streaks Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description              | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 009   | 9" x 9" Green w/ White Floor Tile | 1000              | SF             | Annex: Stairwells, 1st, 2nd, 3rd, 4th Floor Corridors, Auditorium Stairwells & Balcony, Dressing Room, Stairwell C1-3, Stairwell C1-5 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 010   | 12" x 12" Gray Vinyl Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 011   | 9" x 9" Gray Floor Tile | 3000              | SF             | Rooms: 113, 202 (MDF Room), Dressing Room, Auditorium Lobby West Exit Stairwell, |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 012   | 12x 12 Tan Vinyl Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 013   | 9" x 9" Green Vinyl Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description               | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 014   | Cottage Cheese Sprayed on Material | 1000              | SF             | Annex: 2nd Floor Library |               | Surface           | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 015   | Cove Base Molding    |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 016   | Exposed Aicell Pipe Insulation |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 017   | Trowled on Plaster Mateial | 1000              | SF             | Annex: Lobby      |               | Surface           | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|
| 018   | Plaster              | 110000            | SF             | 1st Floor Hallway, 2nd Floor Hallway, 3rd Floor Hallway, 4th Floor Hallway, 412, 401, 402, 403, 407, 405, 409, 411, 413, 414, 416, 415, 417, 419, 421, 423, 424, 425, 426, 429, 431, 432, 433, 325, 323, 324 Office, 322 Office, 321, 320, 319, 317, 310, Room 418, South Hall East Stairwell by 409, South Hall Stairwell by 412, South Hall West Stairwell by 421, Janitor's Closet Next to 418, 3rd Floor South Hall, South Hall East Stairwell by 319, 3rd Floor South Hall Boy's Bathroom, 313, 308, 311, South Hall Stairwell by 306, 306, 309, 3rd Floor South Hall Girl's Bathroom, 307, 304, 305, 303, 304, 301, 302, Library Bookstore (200B), Library Workroom (200C), Library Office, 202 (MDF Room), 203A (School Store), 201, 203, 204, 207, Gymnasium, 209, 211, 210, Corridor 240, Corridor 241 (Elevator Lobby), Vestibule 242 (Elevator Lobby), 212 Office, 213, 214 Office, 215, 246 Janitor's Closet, Lunchroom (116), 162, 162A, 121, 119, 107D, 105C, 105, 107B, Main Office (107), 107A, 105 (Office), 103, 102, 101, 42 (Multi-Purpose Room), Dressing Room, Auditorium |               | Surface           | Yes     | None        |                 |              |                               | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change

Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | Hard Plaster         | 3900              | SF             | Annex: 1st, 3rd, 4th Floor Classrooms and Corridors; 303, 301 |               | Surface           | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 019   | Plaster              |                   |                | Original Building: Classrooms and Crrdrs |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | Plaster              |                   |                | Original Building: Classrooms and Crrdrs; Room 109; Room 100 |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description    | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 020   | Transite Ceiling Panels | 500               | SF             | Original Building: Gym Storage Room |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 022   | Pipe Joint Compound  | 1000              | LF             | Annex: Pipe Tunnel, Basement Above Ceilings |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 023   | Mag Block Insulation |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 024   | Aircell Pipe Insulation |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 025   | Exposed Aircell      |                   |                | Original Building: Pipe Tunnels |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 026   | Pipe Joint Compound  |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 027   | Mag Block Insulation |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 029   | Mag Block Insulation |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 030   | Boiler Breeching Material |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 031   | Mag Block Insulation |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 032   | Gasket Material      |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 033   | Chiller Pump Piping  |                   |                | Annex: Basement Pump Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33    | Chiller Pump Piping  |                   |                | Annex: Basement Pump Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 034   | Heat Pump Insulation |                   |                | Annex: Basement Pump Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34    | Heat Pump Insulation |                   |                | Annex: Basement Pump Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 035   | Pipe Joint Compound  |                   |                | Annex: Basement Pump Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35    | Pipe Joint Compound  |                   |                | Annex: Basement Pump Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 036   | Aircell Pipe Insulation |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                 | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 037   | Cold Water Reservoir Tank Insulation |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 038   | Insulation on Cold Water Circulation Pumps |                   |                | ABATED            |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 039   | Plaster              |                   |                | ABATED            |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 040   | Cottage Cheese Sprayed on Material, Acoustical Ceiling, Concrete Ceiling |                   |                | ABATED            |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 041   | 9" x 9" Red Vfloor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 042   | Cove Base Molding    |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 043   | Exposed Aircell      |                   |                | Convent: Student Activity Room Basement. |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 044   | Chemical Flow Hood   |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 045   | Fire Curtain, Baby Blue | 3500              | SF             | Annex: Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 046   | Asbestos Oven        |                   |                | Original Building: Science Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 047   | Fire Brick           |                   |                | Original Building: Art Room Kiln |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 048   | 9" x 9" White w/ Green Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 050   | 9" x 9" Tan w/ Red & White: Floor Tile |                   |                | Annex: Library, Room 200 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description             | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 051   | 9" x 9" Brown w/ Tan: Floor Tile |                   |                | Annex: Library and Adjacent Rooms, 200 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 053   | 9" x 9" Green, Tan, Black & Orange: Floor |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 054   | 9" x 9" Light Green: Floor |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 055   | 12" x 12" Tan w/ Black & White: Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 056   | 12" x 12" Brown Tan w/ Dark & White Streaks Vinyl Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                 | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 057   | 5"x5" Swirl Pattern Floor Tile: Blue |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 058   | 5"x5" Gold & Brown Tile:<br>Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 060   | Lab Table Tops       | 150               | SF             | Original Building: Science<br>Room 312 (New Room<br>308) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 062   | 9" x 9" Green Swirl Vfloor<br>Tile. |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 063   | 9" x 9" Tan Swirl Vinyl Floor<br>Tile. |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                 | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 064   | 12" x 12" Gray and White Vfloor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 065   | HA #8 Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 066   | 9" x 9" Green w/ White Vinyl Floor Tile Mastic | 1000              | SF             | Annex: Stairwells, 1st, 2nd, 3rd, 4th Floor Corridors, Auditorium Stairwells & Balcony, Dressing Room, Stairwell C1-3, Stairwell C1-5 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 067   | HA #13 Mastic        |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 068   | HA #10 Mastic        |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 069   | HA #11 Mastic        |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 070   | HA #12 Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 071   | 9" x 9" Red Vinyl Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 072   | 9" x 9" Type D Floor Tile Mastic |                   |                | Annex: Storage Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 073   | Type E Floor Tile Mastic |                   |                | Annex: Natural Gas Main |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 074   | Type F Floor Tile Mastic |                   |                | Annex: Student Library |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 075   | Type G Floor Tile Mastic |                   |                | Annex: Student Library |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 076   | Type H Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 077   | Type M Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 078   | Type N Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 079   | Mortar For Terrazzo  | 4000              | SF             | Original Building: Corridor |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 080   | Type P Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 081   | 5x5 Blue Swirl Pattern Vinyl Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 082   | 5x5 Gold/Brown Vinyl Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 083   | Type S Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 084   | Green Swirl Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 085   | Tan Swirl Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 086   | 12x 12 Gray & White Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 087   | Type A Cove Base Molding Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 089   | 12" x 12" Brown Tan w/ Dark & White Streaks Vinyl Floor Tile-Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 090   | 12" x 12" Tan Speckled Vfloor Tile. |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 091   | 12" x 12" Tan Speckled Vfloor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 093   | 9" x 9" Brown w/ White & Red Streaks Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                              | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 094   | 12" x 12" Black w/ White Streaks Vinyl Floor Tile | 300               | SF             | Room 106b (New Room 142) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                     | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 095   | 12" x 12" Black w/ White Streaks Vinyl Floor Tile-Mastic | 300               | SF             | Room 106b (New Room 142) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 096   | 12" x 12" Grayish Green Vinyl Floor Tile | 2500              | SF             | Annex: Basement, Dressing Room, CI07, Rooms 210 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 097   | 12" x 12" Grayish Green Vinyl Floor Tile-Mastic | 2500              | SF             | Annex: Basement, Dressing Room, CI07, Rooms 210 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 098   | 12" x 12" Blue Vinyl Floor Tile | 2500              | SF             | Annex: Basement Under Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 099   | 12" x 12" Blue Vinyl Floor Tile-Mastic | 2500              | SF             | Annex: Basement Under Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description  | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 100   | Plaster Ceiling Patch | 50                | SF             | Convent Basement, Student Activity Room |               | Surface           | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 101   | Pipe Joint Compound  |                   |                | Convent Basement  |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 102   | 12" x 12" Red Vinyl Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 103   | 12" x 12" Red Vinyl Floor Tile-Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                 | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 104   | 12" x 12" Off-White Vinyl Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 104-M | 12" x 12" Off-White Vinyl Floor Tile-Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 105   | 9" x 9" Green & Gray Checkerboard w/ Black Border Vinyl Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 105-M | HA #105 Mastic       |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 107   | Purple Carpet Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 108   | Gray Carpet Mastic   |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 109   | Tan Carpet Mastic    |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 110   | 12" x 12" White & Black Checkerboard Vinyl Floor Tile |                   |                | Room 119          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 111   | 12" x 12" White & Black Checkerboard Vinyl Floor Tile-Mastic |                   |                | Room 119          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                          | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 112   | 12" x 12" Marble Looking Tan Vinyl Floor Tile | 1200              | SF             | Lobby of Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 113   | 12" x 12" Marble Looking Black Vinyl Floor Tile | 1200              | SF             | Lobby of Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 114   | 12" x 12" Marble Looking Black & Tan Vinyl Floor Tile Mastic (for HA #112 & 113) | 2400              | SF             | Lobby of Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 115   | 9" x 9" Dark Green Vinyl Floor Tile |                   |                | Auditorium Floor & Walls & Balcony |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 116   | 9" x 9" Red Vinyl Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 117   | HA #115 & 116 Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 118   | 9" x 9" Brown & Tan Checkerboard Vinyl Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 119   | 9" x 9" Brown & Tan Checkerboard Vinyl Floor Tile-Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 120   | Gray Carpet Mastic   |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                            | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 121   | 12" x 12" White w/ Red & Blue Specks Floor Tile | 800               | SF             | Convent Basement, 42 (Multi-Purpose Room) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 122   | 12" x 12" White w/ Red & Blue Specks Floor Tile Mastic | 800               | SF             | Convent Basement, 42 (Multi-Purpose Room) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 123   | 12" x 12" Purple Mottled Floor Tile | 400               | SF             | Convent Basement, 42 (Multi-Purpose Room) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 124   | 12" x 12" Purple Mottled Floor Tile Mastic | 400               | SF             | Convent Basement, 42 (Multi-Purpose Room) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 125   | 12" x 12" Light Gray w/ White Floor Tile |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 126   | 12" x 12" Light Gray w/ White Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 127   | Gray Mix Terrazzo    | 45000             | SF             | 1st Floor Hallway, 2nd Floor Hallway, 3rd Floor Hallways, 418, Janitor's Closet Next to 418, 3rd Floor South Hall, South Hall East Stairwell by 319, 3rd Floor South Hall Boy's Bathroom, 3rd Floor South Hall Girl's Bathroom, 2nd Floor South Hall Girl's Bathroom, South Hall Stairwell by 204, 1st Floor South Hall Boy's Bathroom, Main Office (107), 105 (Office) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 128   | Green Carpet Adhesive |                   |                | Room 310          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 129   | Peach Linoleum       |                   |                | Room 302, 308, 313, 315 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description    | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 130   | Peach Linoleum Adhesive |                   |                | Rooms 302, 308, 313, 315 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description  | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 131   | Brown Carpet Adhesive |                   |                | Main Office (101a) Closet |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 132   | 24" x 24" Light Blue w/ Blue & White Streaks Floor Tile | 100000            | SF             | 4th Floor Hallway, 306, 213, 217 and Associated Offices, Cafeteria, 412, 401, 402, 403, 409, 411, 413, 414, 416, 415, 417, 419, Corridor 426A, 420 Office, 422 Office, 429, 431, 432, 433, 324, 320, 319, 306, 3rd Floor East Hallway, Corridor 239, 210, Corridor 240, 212 Office, 214 Office 2nd Floor West Hallway, 246 Janitor's Closet, 217, Lunchroom (116), 148 Office |               | Miscellaneous     | No      | Dist        | 36              | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 133   | 24" x 24" Light Blue w/ Blue & White Streaks Floor Tile Mastic | 100000            | SF             | 4th Floor Hallway, 306, 213, 217 and Associated Offices, Cafeteria, 412, 401, 402, 403, 409, 411, 413, 414, 416, 415, 417, 419, Corridor 426A, 420 Office, 422 Office, 429, 431, 432, 433, 324, 320, 319, 306, 3rd Floor East Hallway, Corridor 239, 210, Corridor 240, 212 Office, 214 Office 2nd Floor West Hallway, 246 Janitor's Closet, 217, Lunchroom (116), 148 Office |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 134   | Stairwell Flooring   | 6000              | SF             | Throughout 1st, 2nd, 3rd, & 4th Floors |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change

Comments:

| HA No | Material Description      | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 135   | Stairwell Flooring Mastic | 6000              | SF             | Throughout 1st, 2nd, 3rd, & 4th Floors |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change

Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 136   | 4" Gray Vinyl Baseboard | 100000            | LF             | 1st Floor Hallway, 2nd Floor Hallway, 3rd Floor Hallway, 4th Floor Hallway, Room 303, Room 301, 401, 402, 403, 407, 409, 411, 412, 413, 414, 416, 415, 417, 419, 421, 423, 424, 425, 426, 420 Office, 422 Office, Corridor 441 Elevator Lobby, 429, 428, 430, 431, 446 Janitor's Closet, 432, 433, 325, 326, 323, 346 Janitor's Closet, 324 Office, 322 Office, 321, 320, 319, 317, 310, 313, 311, 304, 301, 302, Library Bookstore (200B), Library Workroom (200C), Library Office, 203, 207, 210, Corridor 240, Corridor 241 (Elevator Lobby), Vestibule 242 (Elevator Lobby), 212 Office, 213, 214 Office, 246 Janitor's Closet, 217, 223, 221, 220, 218, 218B, 219, 162, 148 Office, 114, 121, 119, 103, 102, 101, 014, 42 (Multi-Purpose Room), Dressing Room Ramps, Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change

Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 137   | 4" Gray Vinyl Baseboard Mastic | 100000            | LF             | 1st Floor Hallway, 2nd Floor Hallway, 3rd Floor Hallway, 4th Floor Hallway, Room 303, Room 301, 401, 402, 403, 407, 409, 411, 412, 413, 414, 416, 415, 417, 419, 421, 423, 424, 425, 426, 420 Office, 422 Office, Corridor 441 Elevator Lobby, 429, 428, 430, 431, 446 Janitor's Closet, 432, 433, 325, 326, 323, 346 Janitor's Closet, 324 Office, 322 Office, 321, 320, 319, 317, 310, 313, 311, 304, 301, 302, Library Bookstore (200B), Library Workroom (200C), Library Office, 203, 207, 210, Corridor 240, Corridor 241 (Elevator Lobby), Vestibule 242 (Elevator Lobby), 212 Office, 213, 214 Office, 246 Janitor's Closet, 217, 223, 221, 220, 218, 218B, 219, 162, 148 Office, 114, 121, 119, 103, 102, 101, 014, 42 (Multi-Purpose Room), Dressing Room Ramps, Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description              | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 138   | 2' x 4' White Smooth Ceiling Tile | 50000             | SF             | Room 317, 313, 308, 311, 203, 207, Gymnasium, 209, 119 |               | Miscellaneous     | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location                                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 139   | 2' x 2' White Smooth Ceiling Tile | 35000             | SF             | 4th Floor Hallway, 3rd Floor Hallway, 2nd Floor Hallway |               | Miscellaneous     | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 140   | Drywall              | 60000             | SF             | Throughout Building - 422 Office, Corridor 441 Elevator Lobby, 428, 429, 430, 431, 446 Janitor's Closet, 432, 433, 325, 326, 323, 346 Janitor's Closet, 324 Office, 322 Office, 321, 320, 310, 303, 304, 301, 302, Library Bookstore (200B), Library Workroom (200C), Library Office, 201, 204, 207, 209, 211, 210, Corridor 240, Corridor 241 (Elevator Lobby), Vestibule 242 (Elevator Lobby), 212 Office, 213, 214 Office, 215, 217, 223, 222, 221, 220, 218, 218B, 219, 162, 162A, 114, 121, 119, 110 (Elevator Machine Room), 103, 102, 101, 014, Lobby of Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 141   | Drywall Joint Compound | 60000             | SF             | Throughout Building - 422 Office, Corridor 441 Elevator Lobby, 428, 429, 430, 431, 446 Janitor's Closet, 432, 433, 325, 326, 323, 346 Janitor's Closet, 324 Office, 322 Office, 321, 320, 310, 303, 304, 301, 302, Library Bookstore (200B), Library Workroom (200C), Library Office, 201, 204, 207, 209, 211, 210, Corridor 240, Corridor 241 (Elevator Lobby), Vestibule 242 (Elevator Lobby), 212 Office, 213, 214 Office, 215, 217, 223, 222, 221, 220, 218, 218B, 219, 162, 162A, 114, 121, 119, 110 (Elevator Machine Room), 103, 102, 101, 014, Lobby of Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 142   | 12" x 12" Gray w/ Black and White Specks Floor Tile | 20000             | SF             | Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304 (Classroom), 301, 302, 321, 322, 323, 326, 325, 201, 203, 204, 207, 209, 208, 211, 215, 162, 121, 119, 103, 102, 101, 3rd Floor Hallway, 317, Library Bookstore (200B), Library Workroom (200C), Library Office, 014, Dressing Room Ramps |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 143   | 12" x 12" Light Blue w/ Black and White Specks Floor Tile | 20000             | SF             | Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304, 301, 302 (Classroom), 321, 322, 323, 326, 325, 201, 203, 204, 207, 209, 208, 211, 215, Lunchroom (116), 162, 121, 119, 103, 102, 101, 326, 3rd Floor Hallway, 317, Library Bookstore (200B), Library Workroom (200C), Library Office, 014, Dressing Room Ramps |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 144   | 12" x 12" Light Blue w/ Black and White Specks Floor Tile Mastic | 20000             | SF             | Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304 (Classroom), 301, 302, 321, 322, 323, 326, 325, 201, 203, 204, 207, 209, 208, 211, 215, Lunchroom (116), 162, 121, 119, 103, 102, 101, 3rd Floor Hallway, 317, Library Bookstore (200B), Library Workroom (200C), Library Office, 1st Floor Hallway Library, 014, Dressing Room Ramps |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 145   | Blue Carpet Mastic   | 2500              | SF             | Library, 013      |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change

Comments:

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 146   | 24" x 24" Dark Gray w/ Gray & White Streaks Floor Tile | 10000             | SF             | 2nd Floor East Hallway, 4th Floor Hallway, 306, 213, 217 and Associated Offices, Cafeteria, 412, 401, 402, 403, 409, 411, 413, 414, 416, 415, 417, 419, Corridor 441 Elevator Lobby, 429, 431, 432, 433, 319, 306, 3rd Floor East Hallway, Corridor 239, Corridor 240, Corridor 241 (Elevator Lobby), Vestibule 242 (Elevator Lobby), 217, 223, 222, 221, 220, 218, 218B, 219, Lunchroom (116), Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change

Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 147   | 24" x 24" Dark Gray w/ Black & White Streaks Floor Tile Mastic | 10000             | SF             | 2nd Floor East Hallway, 4th Floor Hallway, 306, 213, 217 and Associated Offices, Cafeteria, 412, 401, 402, 403, 409, 411, 413, 414, 416, 415, 417, 419, Corridor 441 Elevator Lobby, 429, 431, 432, 433, 319, 306, 3rd Floor East Hallway, Corridor 239, Corridor 240, Corridor 241 (Elevator Lobby), Vestibule 242 (Elevator Lobby), 217, 223, 222, 221, 220, 218, 218B, 219, Lunchroom (116), Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 148   | 24" x 24" Light Gray w/ Gray & White Streaks Floor Tile | 10000             | SF             | 4th Floor Hallway, 306, 213, 217 and Associated Offices, Cafeteria, 412, 401, 402, 403, 407, 405, 409, 411, 413, 414, 416, 415, 417, 419, 421 423, 424, 425, 426, Corridor 426A, 429, 428, 430, 431, 446 Janitor's Closet, 432, 433, 346 Janitor's Closet, 306, 304 (Lockers), 3rd Floor East Hallway, 210, 2nd Floor East Hallway, 107D, 105C, 105, 107B |               | Miscellaneous     | No      | Loc         | 8               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 149   | 24" x 24" Light Gray w/ Gray & White Streaks Floor Tile Mastic | 10000             | SF             | 4th Floor Hallway, 306, 213, 217 and Associated Offices, Cafeteria, 412, 401, 402, 403, 407, 405, 409, 411, 413, 414, 416, 415, 417, 419, 421, 423, 424, 425, 426, 429, 428, 430, 431, 446 Janitor's Closet, 432, 433, 346 Janitor's Closet, 306, 304 (Lockers), 3rd Floor East Hallway, 210, 2nd Floor East Hallway, 107D, 105C, 105, 107B |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 150   | Sink Undercoating    | 5                 | SF             | 401               |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                              | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 151   | 12" x 12" Tan w/ Brown & White Streaks Floor Tile | 30                | SF             | Room 406 (Storage) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                     | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 152   | 12" x 12" Tan w/ Brown & White Streaks Floor Tile Mastic | 30                | SF             | Room 406 (Storage) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 153   | White Terrazzo w/ Brown & Yellow Specks | 2500              | SF             | Room 418, South Hall East Stairwell by 409, South Hall Stairwell by 412, South Hall West Stairwell by 421, Janitor's Closet Next to 418, 3rd Floor South Hall, South Hall East Stairwell by 319, 3rd Floor South Hall Boy's Bathroom, South Hall Stairwell by 306, 3rd Floor South Hall Girl's Bathroom, South Hall East Stairwell by 307, 2nd Floor South Hallway, 2nd Floor South Hall Girl's Bathroom, 1st Floor South Hall Boy's Bathroom, 1st Floor Stairwell 2, Main Office (107), 105 (Office) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description             | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 154   | 9" x 9" Greenish Gray Floor Tile | 25                | SF             | Room 203A (School Store) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 155   | 9" x 9" Greenish Gray Floor Tile Mastic | 25                | SF             | Room 203A (School Store) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description            | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 156   | Tongue and Groove Wood Flooring | 3000              | SF             | Gymnasium, Gym Balcony, Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 157   | 9" x 9" Tan w/ Brown Swirls Floor Tile | 100               | SF             | Room 162A         |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 158   | 9" x 9" Tan w/ Brown Swirls Floor Tile Mastic | 100               | SF             | Room 162A         |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 159   | Green Swirl Vinyl Flooring (Border) | 25                | SF             | 162A              |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 160   | Green Swirl Vinyl Flooring (Border) Mastic | 25                | SF             | 162A              |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 161   | 6" Green Vinyl Baseboard | 30                | LF             | Room 110 (Elevator Machine Room) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description            | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 162   | 6" Green Vinyl Baseboard Mastic | 30                | LF             | Room 110 (Elevator Machine Room) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 163   | 12" x 12" Light Gray Mottled Floor Tile | 120               | SF             | Room 111          |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 164   | 12" x 12" Light Gray Mottled Floor Tile Mastic | 120               | SF             | Room 111          |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 165   | 12" x 12" Off-White w/ Blue & Gray Specks | 150               | SF             | Room 109, Main Office (107), 101A |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                             | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 166   | 12" x 12" Off-White w/ Blue & Gray Specks Mastic | 150               | SF             | Room 109, Main Office (107), 101A |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 167   | Boiler Gasket        | 30                | LF             | Boiler Room       |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description               | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 168   | Textured Plaster Ceiling (Popcorn) | 1000              | SF             | 42 (Multi-Purpose Room) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description        | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 169   | 2.5" Purple Vinyl Baseboard | 50                | LF             | Room 42 (Multi-Purpose Room) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description               | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 170   | 2.5" Purple Vinyl Baseboard Mastic | 50                | LF             | Room 42 (Multi-Purpose Room) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 171   | 12" x 12" Blueish Gray w/ White Speckled Floor | 850               | SF             | Dressing Room     |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 172   | 12" x 12" Blueish Gray w/ White Speckled Floor Mastic | 850               | SF             | Dressing Room     |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description           | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 173   | 9" x 9" Gray Floor Tile Mastic | 3000              | SF             | Rooms 113, 202 (MDF Room), Dressing Room, Auditorium Lobby West Exit Stairwell, |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                       | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 174   | 12" x 12" Gray w/ Black and White Specks Floor Tile Mastic | 20000             | SF             | Rooms 315, 313, 308, 311, 310, 309, 307, 305, 303, 304 (Classroom), 301, 302, 321, 322, 323, 326, 325, 201, 203, 204, 207, 209, 208, 211, 215, 162, 121, 119, 103, 102, 101, 3rd Floor Hallway, 317, Library Bookstore (200B), Library Workroom (200C), Library Office, 014, Dressing Room Ramps |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                 | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 175   | 12" x 12" Marble Looking Tan Vinyl Floor Tile Mastic | 1200              | SF             | Lobby of Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 176   | 12" x 12" Marble Looking Black Vinyl Floor Tile Mastic | 1200              | SF             | Lobby of Auditorium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2     | 1' x 1' Acoustical Wall Tiles | 400               | SF             | Annex: Corridors, Lobby Womens Auditorium, C117, C118, C120, C121, C107, C110 |               | Miscellaneous     | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Sor Juana Ines de la Cruz ES  
Date: 8/1/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. CPS website
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.