

Chicago Public Schools

6 Month Asbestos Surveillance

2025 Fall Six Month Survey

School: Phoebe Apperson Hearst Elementary School
Address: 4640 S Lamon Ave

Oracle Unit: 23671
Region: 04

Building ID: 3890
Mail Room: 44

Asbestos Surveyor: Tado, Anthony
Survey Date: 12/4/2025
Email Address: ahtado@cps.edu

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 1 | Boiler Gaskets on Boiler #1 | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2 | Refractory Cement in Boiler #1 Doors | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 3 | Boiler Gaskets on Boiler #2 | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 4 | Refractory Cement in Boiler #2 Doors | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5 | Fire Brick in Boiler #1 | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6 | Fire Brick in Boiler #2 | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7 | Fire Brick in Incinerator | | | Elementary School | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8 | Interior Brick | | | 1951 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9 | Interior Brick Mortar - Non-AHERA | | | 1951 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 | Terrazzo Wall Panels | | | 1st Floor Boys and Girls Bathrooms, Custodian's Lounge | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11 | Spray-on Ceiling Material | | | Elementary School - Boiler Room | | Surface | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14 | Multi-Brown Ceramic Tile Grout | | | Elementary School - Entrances and Bathrooms of 1951 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15 | Marble Stone Mortar | | | Elementary School - Gym Foyer and Auditorium | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16 | 9" x 9" Light Brown w/ Brown & White Streaks Floor Tile | 1250 | SF | Elementary School - Auditorium, 115, 117, 119 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17 | 9" x 9" Light Brown w/ Brown & White Streaks Floor Tile Mastic | 1250 | SF | Elementary School - Auditorium, 115, 117, 119 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18 | 9" x 9" Olive Floor Tile | 5250 | SF | Elementary School - Rooms 113, 118-121, 214-221, 2nd Floor Hallways and Janitor's Closets, Room 115 | | Miscellaneous | No | Loc | 20 | SF | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19 | 9" x 9" Olive Floor Tile Mastic | 5250 | SF | Elementary School - Rooms 118-121, 214-221, 2nd Floor Hallways and Janitor's Closets, Room 115 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20 | 9" x 9" Light Brown Floor Tile | 5250 | SF | Elementary School - Rooms 118-121, 214-221, 2nd Floor Hallways and Janitor's Closets, Room 204 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 | 9" x 9" Light Brown Floor Tile Mastic | 5250 | SF | Elementary School - Rooms 113, 118-121, 214-221, 2nd Floor Hallways and Janitor's Closets, Room 204 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22 | 12" x 12" Brown w/ White Streaks Floor Tile | 10 | SF | Elementary School - Room 121 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23 | 12" x 12" Brown w/ White Streaks Floor Tile Mastic | 10 | SF | Elementary School - Room 121 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 | 9" x 9" Gray w/ White Streaks Floor Tile | | | Elementary School - Room 102 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25 | 9" x 9" Gray w/ White Streaks Floor Tile Mastic | | | Elementary School - Room 102 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26 | 9" x 9" Peach Floor Tile | | | Elementary School - Room 102 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27 | 9" x 9" Peach Floor Tile Mastic | | | Elementary School - Room 102 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28 | 12" x 12" Beige w/ Brown & White Specks Floor Tile | 250 | SF | Elementary School - Room Behind Stage, Room 221 Cut Into 9" x 9" Patches | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29 | 12" x 12" Beige w/ Brown & White Specks Floor Tile Mastic | 250 | SF | Elementary School - Room Behind Stage, Room 221 Cut Into 9" x 9" Patches | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30 | 12" x 12" Blue Swirled Floor Tile | 6250 | SF | Elementary School - Main Office, 102, 105, 106, 108, 110, 112, 113, Teachers' Lounge, 205-213, 1st & 2nd Floor Halls, Room 221 Cut Into 9" x 9" Patches, 203, MDF | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31 | 12" x 12" Blue Swirled Floor Tile Mastic | 6250 | SF | Elementary School - Main Office, 102, 105, 106, 108, 110, 112, 113, Teachers' Lounge, 205-213, 1st & 2nd Floor Halls, Room 221 Cut Into 9" x 9" Patches, 203, MDF | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32 | 12" x 12" Light Brown Swirled Floor Tile | 6250 | SF | Elementary School - Main Office, 102,105, 106, 108, 110, 112, 113, Teachers' Lounge, 205-213, 1st & 2nd Floor Halls, 227 Staff Bathroom, 203, 100, MDF | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33 | 12" x 12" Light Brown Swirled Floor Tile Mastic | 6250 | SF | Elementary School - Main Office, 102,105, 106, 108, 110, 112, 113, Teachers' Lounge, 205-213, 1st & 2nd Floor Halls, 227 Staff Bathroom, 203, 100, MDF | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34 | 12" x 12" Gray Floor Tile | 350 | SF | Elementary School - Room 104 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35 | 12" x 12" Gray Floor Tile Mastic | 350 | SF | Elementary School - Room 104 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36 | 12" x 12" Blue Floor Tile | 350 | SF | Elementary School - Room 104 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37 | 12" x 12" Blue Floor Tile Mastic | 350 | SF | Elementary School - Room 104 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38 | 12" x 12" Brown w/ Brown & White Specks Floor Tile | 700 | SF | Elementary School - 2nd Floor Hall & Room 109 Bathroom | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 | 12" x 12" Brown w/ Brown & White Specks Floor Tile Mastic | 1300 | SF | Elementary School - 2nd Floor Hall & Room 109 Bathroom | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40 | 12" x 12" Dark Brown Floor Tile | 85 | SF | Elementary School - Language Arts, Room 215, and as Patches in 2nd Floor Hall & Hall Across From Room 120 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41 | 12" x 12" Dark Brown Floor Tile Mastic | 85 | SF | Elementary School - Language Arts, Room 215, and as Patches in 2nd Floor Hall & Hall Across From Room 120 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42 | 12" x 12" Gray Floor Tile | 1600 | SF | Elementary School - Language Arts, as Patches in 2nd Floor Hall & Hall Across From 120, 120 Patches | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43 | 12" x 12" Gray Floor Tile Mastic | 1600 | SF | Elementary School - Language Arts, as Patches in 2nd Floor Hall & Hall Across From 120, 120 Patches | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 | 12" x 12" Beige w/ Brown Specks Floor Tile | 100 | SF | Elementary School - Teachers' Bathrooms and Hall in Front of 114 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45 | 12" x 12" Beige w/ Brown Specks Floor Tile Mastic | 100 | SF | Elementary School - Teachers' Bathrooms and Hall in Front of 114 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46 | 12" x 12" Multi-Brown Floor Tile | | | Elementary School - Room 114 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47 | 12" x 12" Multi-Brown Floor Tile Mastic | | | Elementary School - Room 114 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48 | 12" x 12" Light Green Floor Tile | | | ABATED | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49 | 12" x 12" Light Green Floor Tile Mastic | | | ABATED | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50 | 12" x 12" Brown Floor Tile | | | ABATED | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51 | 12" x 12" Brown Floor Tile Mastic | | | ABATED | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52 | 12" x 12" White Floor Tile | | | ABATED | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53 | 12" x 12" White Floor Tile Mastic | | | ABATED | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54 | 12" x 12" Multi-Brown Floor Tile | | | Elementary School - Kitchen | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55 | 12" x 12" Multi-Brown Floor Tile Mastic | | | Elementary School - Kitchen | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56 | Terrazzo Flooring and Stairs | | | Stairways of 1951 Construction (Elementary School) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57 | Terrazzo Flooring and Stairs | | | Stairways of 1958 Construction (Elementary School) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58 | Glazed Brick Mortar | | | Throughout 1951 Construction (Elementary) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59 | Glazed (Finished) Brick Mortar | | | Throughout 1958 Construction (Elementary School) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60 | (Wall) Caulk | | | Elementary School - 2nd Floor Wall Where 1951 and 1958 Buildings Meet | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61 | Plaster | | | Throughout 1951 Construction (Elementary) | | Surface | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62 | Plaster | | | Throughout 1958 Construction (Elementary School) | | Surface | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63 | Cinder Block Mortar | | | Throughout 1958 Construction (Elementary School) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64 | 4" Black Vinyl Baseboard | | | Throughout 1958 Construction (Elementary School) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65 | 4" Black Vinyl Baseboard Mastic | | | Throughout 1958 Construction (Elementary School) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66 | Interior Window Caulk | | | Throughout 1958 Construction (Elementary School) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 67 | Window Caulk | | | Throughout 1951 Construction (Elementary) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 68 | Non-Skid Strips | | | Elementary School - Stairs WomensBasement | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 69 | Window Caulk | | | Elementary School - Cafeteria | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 70 | Ceiling Panels | 3500 | SF | Elementary School - Gym | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 71 | 1' x 1' Ceiling Tile | | | Elementary School - Kitchen | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 72 | 1' x 1' Ceiling Tile Adhesive | | | Elementary School - Kitchen | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 73 | Brown/White Ceramic Tile Grout | 50 | SF | Elementary School - as Patches in 1951 Construction Bathrooms (Boys) | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 74 | Multi-Brown Ceramic Tile Grout | 200 | SF | Entrances and Bathrooms in 1958 Construction (Elementary School) | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 75 | Blue Carpet Mastic | 2000 | SF | Elementary School - Office, 103, 118, Storage Room 122 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 76 | Exterior Brick - Non-AHERA | | | 1951 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 77 | Exterior Brick Mortar - Non-AHERA | | | 1951 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 78 | Exterior Brick - Non-AHERA | | | 1958 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 79 | Exterior Brick Mortar - Non-AHERA | | | 1958 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 80 | Exterior Door Caulk - Non-AHERA | | | 1951 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 81 | Exterior Door Caulk - Non-AHERA | | | 1958 Construction - Door Entrances | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 82 | Exterior Window Caulk - Non-AHERA | | | 1951 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 83 | Exterior Window Caulk - Non-AHERA | | | 1958 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 84 | Roofing Material - Non-AHERA | | | 1951 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 85 | Roofing Material - Non-AHERA | | | 1958 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 86 | Roof Flashing - Non-AHERA | | | 1951 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 87 | Roof Flashing - Non-AHERA | | | 1958 Construction | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 88 | 2' x 4' Ceiling Panels | | | Throughout Primary Annex | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 89 | 1' x 1' Fissured Ceiling Tile | | | Primary Annex - Gym & Gym Foyer | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 90 | 1' x 1' Fissured Ceiling Tile Adhesive | | | Primary Annex - Gym Foyer | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 91 | 1' x 1' Fissured Ceiling Tile (Replacement Tile) | | | Primary Annex - Gym Foyer | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 92 | 1' x 1' Fissured Replacement Ceiling Tile Adhesive | | | Primary Annex - Gym Foyer | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 93 | 12" x 12" Gray Floor Tile | 5000 | SF | Throughout Primary Annex | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 94 | 12" x 12" Gray Floor Tile Mastic | 5000 | SF | Throughout Primary Annex | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 95 | 12" x 12" Black Floor Tile | 5000 | SF | Throughout Primary Annex | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 96 | 12" x 12" Black Floor Tile Mastic | 5000 | SF | Throughout Primary Annex | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 97 | 12" x 12" White Floor Tile | 5000 | SF | Primary Annex - Hallways | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 98 | 12" x 12" White Floor Tile Mastic | 5000 | SF | Primary Annex - Hallways | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 99 | Multi-Brown Ceramic Tile Grout | 600 | SF | Primary Annex - Bathrooms and Entrances | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 100 | Cinder Block Mortar | | | Throughout Primary Annex | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 101 | Glazed Brick Mortar | | | Primary Annex - 402, Various Bathrooms | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 102 | Plaster | | | Primary Annex - Throughout Facility | | Surface | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 103 | Linoleum | | | Primary Annex - Ledges Above Ah Units in Classrooms | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 104 | Vibration Collars | | | Primary Annex - Fan Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 105 | Interior Brick | | | Primary Annex - Fan Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 106 | Interior Brick Mortar | | | Primary Annex - Fan Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 107 | Window Caulk | | | Primary Annex - Throughout Annex | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 108 | White/Rust/Brown Terrazzo | | | Primary Annex - Gym Foyer, Stairways and Landings | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 109 | Yellow Terrazzo | | | Primary Annex - Gym Foyer | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 110 | Interior Door Caulk | | | Throughout Primary Annex | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 111 | Hard (Old Type) Boiler Gasket - Boiler #1 | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 112 | Fluffy (New Type) Boiler Gasket on Boiler #1 | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 113 | Refractory Cement in Boiler #1 Doors | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 114 | Fire Brick in Boiler #1 | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 115 | Boiler Gasket - Boiler #2 | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 116 | Refractory Cement in Doors on Boiler #2 | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 117 | Fire Brick in Boiler #2 | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 118 | 9" x 9" Tan Floor Tile | | | ABATED | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 119 | 9" x 9" Tan Floor Tile Mastic | | | ABATED | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 120 | Material in Fire Block - Boiler #2 | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 121 | Material in Vault Door | 36 | SF | Primary Annex - Stairway Vault | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 122 | Insulation in Firedoors | 30 | SF | Primary Annex - Entrances and Exits, Boiler Room Door | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 123 | Exterior Brick - Non-AHERA | | | Primary Annex | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 124 | Exterior Brick Mortar - Non-AHERA | | | Primary Annex | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 125 | Exterior Window Caulk - Non-AHERA | | | Primary Annex | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 126 | Exterior Door Caulk - Non-AHERA | | | Primary Annex | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 127 | Roof Material - Non-AHERA | | | Primary Annex | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 128 | Roof Flashing - Non-AHERA | | | Primary Annex - Roof | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 129 | Insulation Inside Fire Doors | 336 | SF | Elementary School - Entrances and Exits | | TSI | Yes | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 130 | Block Mortar | | | Elementary School - Gym | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 131 | 12" x 12" Brown w/ White & Brown Streaks Floor Tile | | | Elementary School - Room 107 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 132 | 12" x 12" Brown w/ White & Brown Streaks Floor Tile Mastic | | | Elementary School - Room 107 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 133 | 12" x 12" Gray w/ Brown Streaks Floor Tile | 350 | SF | Elementary School - Room 107 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 134 | 12" x 12" Gray w/ Brown Streaks Floor Tile Mastic | 350 | SF | Elementary School - Room 107 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 135 | Countertop Laminate | 250 | SF | Elementary School - Rooms 113, 114, 115, 117, 119, 121, 214, 215, 217, 219, 221, 220 | | Miscellaneous | No | Loc | 5 | SF | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 136 | Countertop Laminate Mastic | 250 | SF | Elementary School - Rooms 114, 115, 117, 119, 121, 214, 215, 217, and 219 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 137 | 12" x 12" Beige w/ White Specks Floor Tile | 700 | SF | Elementary School - Room 109 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 138 | 12" x 12" Beige w/ White Specks Floor Tile Mastic | 700 | SF | Elementary School - Room 109 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 139 | Sink Undercoating | 20 | SF | Primary Annex - Rooms 115, 109, 117, 119, 120 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 140 | Blackboards | 1100 | SF | Primary Annex: | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 141 | 12" x 12" White w/ Black Floor Tile | 1000 | SF | 1st Floor Hall by Rooms 114-117, Patches by Fountain Next to Room 114 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 142 | 12" x 12" White w/ Black Floor Tile Mastic | 1000 | SF | 1st Floor Hall by Rooms 114-117, Patches by Fountain Next to Room 114 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 143 | 12" x 12" Purple Brown Mix Floor Tile | | | 1st Floor Hall by Rooms -117, Kitchen/Cafe | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 144 | 12" x 12" Purple Brown Mix Floor Tile Mastic | | | 1st Floor Hall by Rooms 117, Kitchen/Cafe | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 145 | 12" x 12" Taupe Mix Floor Tile | | | 2nd Floor Hall, Rooms 203, 205, 206, | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 146 | 12" x 12" Taupe Mix Floor Tile Mastic | | | 2nd Floor Hall, Rooms 203, 205, 206, and 207 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 147 | 12" x 12"Hazel Mix Floor Tile | | | 2nd Floor Drinking Fountain Area by 217 (Patch) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 148 | 12" x 12" Hazel Mix Floor Tile Mastic | | | 2nd Floor Drinking Fountain Area by 217 (Patch) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 149 | 12" x 12" Brown Mix Floor Tile | 5000 | SF | 1st Floor Hallway, Rooms 115-121, 2nd Floor Drinking Fountain Area by 217, Cafeteria (Patch), Room 115 Patches | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 150 | 12" x 12" Brown Mix Floor Tile Mastic | 80 | SF | 1st Floor Hallway, Rooms 115-121, 2nd Floor Drinking Fountain Area by 217, Cafeteria (Patch), Room 115 Patches | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 151 | 12" x 12" White w/ Brown Floor Tile | 180 | SF | 1st Floor Drinking Fountains, 2nd Floor Teachers' Bathroom Across From Room 219, Room 214 Patches | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 152 | 12" x 12" White w/ Brown Floor Tile Mastic | 60 | SF | 1st Floor Drinking Fountains, 2nd Floor Teachers' Bathroom Across From Room 219, Room 214 Patches | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 153 | Purple Carpet Adhesive | | | Main Office | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 154 | 12" x 12" Gray w/ Brown Floor Tile | | | Hallway From Room 117 Womens Stairs | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 155 | 12" x 12" Gray w/ Brown Floor Tile Mastic | | | Hallway From Room 117 Womens Stairs | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 156 | Gray Mix Terrazzo | 6000 | SF | Stairwells | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 157 | 9" x 9" Tan w/ Brown & White Floor Tile | 600 | SF | Room 204 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 158 | 9" x 9" Tan w/ Brown & White Floor Tile Mastic | 600 | SF | Room 204 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 159 | 12" x 12" Bluish Gray Floor Tile | | | Room 107 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 160 | 12" x 12" Bluish Gray Floor Tile Mastic | | | Room 107 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 161 | 12" x 12" Light Bluish Gray Floor Tile | | | Room 107 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 162 | 12" x 12" Light Bluish Gray Floor Tile Mastic | | | Room 107 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 163 | Green Carpet Adhesive | | | Office | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 164 | Blue Carpet Adhesive | 300 | SF | Room 122 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 165 | 12" x 12" Light Gray w/ White Floor Tile | 40000 | SF | Annex Hallways, Classrooms, and Auditorium | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 166 | 12" x 12" Light Gray w/ White Floor Tile Mastic | 40000 | SF | Annex Hallways, Classrooms, and Auditorium | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 167 | 12" x 12" Black w/ White Floor Tile | 5000 | SF | Annex Hallway & Classrooms, 1st and 2nd Floor Elevator | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 168 | 12" x 12" Black w/ White Floor Tile Mastic | 5000 | SF | Annex Hallway & Classrooms, 1st and 2nd Floor Elevator | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 169 | 12" x 12" White w/ Gray Floor Tile | 5000 | SF | Annex Hallways & Classrooms | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 170 | 12" x 12" White w/ Gray Floor Tile Mastic | 5000 | SF | Annex Hallways & Classrooms | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 171 | 2' x 4' Ceiling Tile - White | | | Annex - Throughout | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 172 | 1' x 1' Ceiling Tile - White | | | Annex Entrance and Auditorium | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 173 | 12" x 12" Green Floor Tile | 120 | SF | Annex Engineer's Office | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 174 | 12" x 12" Green Floor Tile Mastic | 120 | SF | Annex Engineer's Office | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 175 | 12" x 12" Dark Gray w/ Dark Spots Floor Tile | 350 | SF | Bathrooms 105, 107, 114 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 176 | 12" x 12" Dark Gray w/ Dark Spots Floor Tile Mastic | 350 | SF | Bathrooms 105, 107, 114 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 177 | 12" x 12" Black w/ White Spots Floor Tile | 3000 | SF | Kitchen, Lunchroom, Elevator Lobby, Basement, 1st-2nd Floor | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 178 | 12" x 12" Black w/ White Spots Floor Tile Mastic | 3000 | SF | Kitchen, Lunchroom, Elevator Lobby, Basement, 1st-2nd Floor | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 179 | 12" x 12" Blue w/ White Streaks Floor Tile | 200 | SF | Lobby 136 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 180 | 12" x 12" Blue w/ White Streaks Floor Tile Mastic | 200 | SF | Lobby 136 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 181 | Black Baseboard Glue | 500 | LF | Kitchen, Lunchroom, Elevator, Lobby, Basement 1st 2nd Floor | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 182 | 12" x 12" Beige w/ Dark Spots Floor Tile | 200 | SF | Lobby 136 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 183 | 12" x 12" Beige w/ Dark Spots Floor Tile Mastic | 200 | SF | Lobby 136 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 184 | 2' x 4' Ceiling Tile | | | Basement, Elevator Lobby, Reception | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 185 | Glue Under Blue w/ Beige Carpet | 400 | SF | Main Office | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 186 | Glue Under Gray w/ White Marks, Carpet | 700 | SF | Library 200 - 202 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 187 | Drywall/Drywall Tile | 1000 | SF | Elevator Lobby Annex 1st, 2nd Floor, Elevator Lobby On Basement, 1st, and 2nd Floor | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 188 | 12" x 12" Yellow w/ Red Spots Floor Tile | | | Lobby 136 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 189 | 12" x 12" Yellow w/ Red Spots Floor Tile Mastic | | | Lobby 136 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 190 | 12" x 12" Blue w/ White Streaks Floor Tile | 200 | SF | Lobby 136 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 191 | 12" x 12" Blue w/ White Streaks Floor Tile Mastic | 200 | SF | Lobby 136 | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 192 | 6" Black Baseboard | 100 | SF | Library | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 193 | 6" Black Baseboard Adhesive | 100 | SF | Library | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 194 | Tongue and Groove | 4500 | SF | Gymnasium , Auditorium Stage | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 195 | Stage Curtain | 1000 | SF | Auditorium | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 196 | 12" x 12" Blue Mottled Floor Tile | 3000 | SF | 1st Floor Hallway | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 197 | 12" x 12" Blue Mottled Floor Tile Mastic | 3000 | SF | 1st Floor Hallway | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 198 | 12" x 12" Light Blue w/ White and Blue Streaks Floor Tile | 26 | SF | Passage 002 By Lunchroom H Design Tile | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 199 | 12" x 12" Light Blue w/ White and Blue Streaks Floor Tile Mastic | 26 | SF | Passage 002 By Lunchroom H Design Tile | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 200 | 12" x 12" Yellow w/ Brown Streaks Floor Tile | 50 | SF | Passage 002 Outside Lunchroom | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 201 | 12" x 12" Yellow w/ Brown Streaks Floor Tile Mastic | 50 | SF | Passage 002 Outside Lunchroom | | Miscellaneous | No | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A | Insulation on Boiler #1 | | | ABATED | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B | Insulation on Boiler #2 | | | ABATED | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C | Fiberglass Pipe Insulation | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D | Insulation on Top Tank | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E | Insulation on Bottom Tank | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F | Insulation Under Metal Jacket Of Incinerator | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G | Aircell Pipe Insulation | 6100 | LF | Elementary School - Basement, Room Behind Stage, Library Mech, Cafeteria, Fan Room | | TSI | Yes | Dist | 5 | LF | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H | Cementitious Joint Insulation Off Aircell Lines | 550 | LF | Elementary School - Basement, Room Behind Stage, Library Mech | | TSI | Yes | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I | Mag-Block Insulation | | | ABATED | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J | Boiler Flue Insulation on Small Boiler | | | ABATED | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K | Fiberglass Pipe Insulation | | | Primary Annex - Boiler Room, 2nd Floor Fan Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L | Cementitious Pipe Joint Insulation | 63 | LF | Primary Annex - 2nd Floor Fan Room | | TSI | Yes | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| M | Cementitious Pipe Joint Insulation | | | Primary Annex - Crawlspace | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| N | Duct Insulation | | | Primary Annex - 2nd Floor Fan Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change
 Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| O | Wrap Around Duct Insulation | | | Primary Annex - 2nd Floor Fan Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| P | Insulation Under Steel Jacket on Boiler #1 | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| Q | Insulation Under Steel Jacket on Boiler #2 | | | Primary Annex - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| R | Tank Insulation | | | Elementary School - Boiler Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

Richard J. Schleyer

Richard J.Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Phoebe Apperson Hearst Elementary School

Date: 12/4/2025

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.