

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Friedrich L. Jahn Elementary of the Fine Arts  
**Address:** 3149 N. Wolcott Avenue

**Oracle Unit:** 23921  
**Region:** 01

**Building ID:** 4170  
**Mail Room:** 33

**Asbestos Surveyor:** Heiting, Brian  
**Survey Date:** 12/5/2025  
**Email Address:** \_\_\_\_\_

**CHECK HERE IF NO CHANGE TO ASBESTOS**

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other |

| HA No | Material Description               | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 01    | 12"x12" White w/ Brown Streaks VFT | 1300              | SF             | (3rd Fl. Teacher's Toilet & Lounge - under carpet), Copy Rm 004, 108 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description               | Material Quantity | Material Units | Material Location                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02    | 12"x12" Beige w/ White Streaks VFT | 800               | SF             | Room 301 & Wardrobe (under existing flooring) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                           | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03    | 12"x12" Brown w/ Tan Streaks VFT - ABATED 2013 |                   |                | Room 205 & Library Wardrobe |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description            | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04    | 9"x9" Gray w/ Black Streaks VFT | 460               | SF             | Principal's Office & Vestibule (Under Wood Floor) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description             | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05    | 9"x9" Beige w/ Brown Streaks VFT | 700               | SF             | Auditorium Stage and Stage Stairs, Room 003 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06    | Battleship Green Linoleum - ABATED |                   |                | Room 107          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07    | 12"x12" Light Green w/ Brown Streaks VFT - ABATED |                   |                | Room 001          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08    | 9"x9" Red VFT - ABATED |                   |                | Room 003          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description           | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11    | 2'x4' White Wormy Ceiling Tile | 33000             | SF             | Throughout 1st, 2nd, & 3rd FL. Corridors, 3rd FL: Rooms 301,304,303,305,307,306 ,308,309, Teacher's Lounge Toilet, Corridor, 2nd FL: Rooms 202,201,203,204,205,207 ,209,208, 1st FL: Rooms 102,101,104,103,108,109 , Asst. Principal Office, Main Office, Principal Office/Toilet, Adjustment Office, Corridor Basement: Copy Room 004 |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12    | 12"x12" White w/ Brown Streaks VFT Mastic | 1300              | SF             | (3rd Fl. Teacher's Toilet & Lounge - under carpet), Copy Rm 004, 108 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                   | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13    | 9"x9" Gray w/ Black Streaks VFT Mastic | 420               | SF             | Principal's Office & Vestibule (under wood floor) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14    | Battleship Green Linoleum Mastic - ABATED |                   |                | Room 107          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15    | Transite Wall Panel  | 640               | SF             | Kitchen Storage, Tank Room (Behind Drywall) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | 2"x18" Border Black VFT - ABATED |                   |                | Room 003          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | 9"x9" Brown w/ Red Streaks VFT - ABATED |                   |                | Room 002          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                           | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | 9"x9" Green w/ White Streaks VFT - ABATED 2013 |                   |                | Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26) |               | Miscellaneous     | No      |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                      | Material Quantity | Material Units | Material Location                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | 12"x12" Beige w/ White Streaks VFT Mastic | 800               | SF             | Room 301 & Wardrobe (under existing flooring) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | 9"x9" Green w/ White Streaks VFT Mastic ABATED (2013) |                   |                | Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26) ABATED (2013) |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                 | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | 12"x12" Brown w/Tan Streaks VFT Mastic ABATED (2013) |                   |                | Room 205 & Library Wardrobe ABATED (2013) |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22    | 9"x9" Beige w/ Brown Streaks VFT Mastic | 700               | SF             | Auditorium Stage and Stage Stairs, Room 003 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23    | 2" x 18" Border Black VFT Mastic - ABATED |                   |                | Room 003          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | 9"x9" Red VFT Mastic - ABATED |                   |                | Room 003          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | 9"x9" Brown w/ Red Streaks VFT Mastic - ABATED |                   |                | Room 002          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26    | 12"x12" Light Green w/ Brown Streaks VFT Mastic - ABATED |                   |                | Room 002, 001     |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27    | 12"x12" Blue VFT - ABATED |                   |                | Staff Toilet      |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28    | 12"x12" Blue VFT Mastic - ABATED |                   |                | Staff Toilet      |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29    | 12"x12" Peach VFT - ABATED Summer 2023 |                   |                | Lunchroom         |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30    | 12"x12" Peach VFT Mastic - ABATED summer 2023 |                   |                | Lunchroom         |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31    | 12"x12" Light Blue w/White Specks VFT | 650               | SF             | Room 002 (Duplicate of HA 45, 46) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                         | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31A   | 12"x12" Light Blue w/White Specks VFT Mastic | 650               | SF             | Room 002 (Duplicate HA 45, 46) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32    | Carpet Mastic        | 1000              | SF             | Rooms 005, Library 205, 3rd FL Teacher's Lounge (over HA 01) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33    | 12"x12" Tan Floor Tile - | 750               | SF             | Room 108 (under existing flooring) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description          | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34    | 12"x12" Tan Floor Tile Mastic | 750               | SF             | Room 108 (under existing flooring) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35    | 12"x12" Grey Floor Tile | 2804              | SF             | Main Office, 1st and 2nd Floor Corridors, 301, 3rd FL Corridor, 3rd FL Stair Landings |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36    | 12"x12" Grey Speckled Floor Tile Mastic | 600               | SF             | 301, 3rd FL Stair Landings, Staff Restroom across from 107 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37    | 12"x12" White w/ Brown Specks Floor Tile | 2500              | SF             | 1st and 2nd Floor Corridors, 1st Boys and Girls Washrooms, 2nd FL Stair Landings, Basement Lunchroom & Corridor, Main Office-Closet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38    | 12"x12" White w/ Brown Specks Floor Tile Mastic | 2500              | SF             | 1st and 2nd Floor Corridors, 1st Boys and Girls Washrooms, 2nd FL Stair Landings, Basement Lunchroom & Corridor, Main Office-Closet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39    | 12"x12" Yellow Floor Tile | 24                | SF             | 1st and 2nd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description             | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40    | 12"x12" Yellow Floor Tile Mastic | 24                | SF             | 1st and 2nd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description    | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41    | 12"x12" Blue Floor Tile | 150               | SF             | 1st, 2nd & 3rd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description           | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42    | 12"x12" Blue Floor Tile Mastic | 150               | SF             | 1st, 2nd & 3rd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43    | 12"x12" Green Floor Tile | 350               | SF             | Teacher's Toilets across Room 107, 1st FL Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description            | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44    | 12"x12" Green Floor Tile Mastic | 350               | SF             | Teacher's Toilets across Room 107, 1st FL Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                 | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45    | 12"x12" Light Blue Floor Tile (Duplicate HA 31, 31A) | 2500              | SF             | Room 002, 301, 3rd FL Corridor, 3rd FL Stair Landing |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46    | 12"x12" Light Floor Tile Mastic (Duplicate HA 31, 31A) | 2500              | SF             | Room 002, 301, 3rd FL Corridor, 3rd FL Stair Landing |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47    | 12"x12" Royal Blue Floor Tile | 1720              | SF             | 301, 3rd & 2nd FL Corridors, 3rd FL Stair Landing |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                 | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48    | 12"x12" Royal Blue Floor Tile Mastic | 1720              | SF             | 301, 3rd & 2nd FL Corridors, 3rd FL Stair Landing |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49    | 12"x12" Off White w/ Black Specks Floor Tile | 900               | SF             | Room 001          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50    | 12"x12" Off White w/ Black Specks Floor Tile MASTIC | 900               | SF             | Room 001          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51    | Terrazzo             | 1800              | SF             | Room 005 (under the carpet), vestibules, 1st Floor Toilet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52    | Ceramic Tile Grout   | 2140              | SF             | 2nd Floor Restroom (206) and Basement Restroom, 3rd FL Teacher's Toilet, Rm 103-Toilet, 101-Toilet, 1st FL Boy's + Girl's Toilet, Main Office Toilet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53    | Ceramic Tile Adhesive | 2140              | SF             | 2nd Floor Restroom (206) and Basement Restroom, 3rd FL Teacher's Toilet, Rm 103-Toilet, 101-Toilet, 1st FL Boy's + Girl's Toilet, Main Office Toilet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54    | Fire Door            | 11                | EA             | 3rd FL Gym, 2nd FL Balcony of Assembly Hall, 1st FL Assembly Hall |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55    | Drywall System (Drywall, Tape, Compound) | 5000              | SF             | 3rd FL: Teacher's Lounge-Toilet, 305, 303<br>2nd FL: 206, Boy's + Girl's Toilet, Teacher's Toilet<br>1st FL: Main Office Toilet, 103-Toilet, 101-Toilet<br>Basement: Kitchen Storage, Girl's + Boy's Toilet, Teacher Lunchroom, BE Office, 001-Toilet |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56    | Vinyl Baseboard Mastic | 2000              | SF             | 2nd FL - Boy's and Girl's Toilet<br>1st FL - Teacher Toilet<br>Basement - Kitchen Storage, Lunchroom, Teacher's Lunchroom |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                  | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57    | Hard Coat Plaster (walls and ceiling) | 80000             | SF             | Throughout Building |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58    | 12"x12" Orange Floor Tile | 20                | SF             | 1st FL Corridor   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58M   | 12"x12" Orange Floor Tile Mastic | 20                | SF             | 1st FL Corridor   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                    | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59    | 12"x12" White w/ Olive Green Specks VFT | 1500              | SF             | Basement Lunchroom/Kitchen |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                             | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59A   | 12" x 12" White w/ Olive Green Specks VFT MASTIC | 1500              | SF             | Basement Lunchroom/ Kitchen |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60    | 12" x 12" Off White w/ Tan Speckles VFT | 350               | SF             | Basement Parents Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60A   | 12" x 12" Off White w/ Tan Speckles VFT MASTIC | 350               | SF             | Basement Parents Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61    | 12" x 12" Gray w/ White Specks VFT | 300               | SF             | Basement Room 003 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61A   | 12" x 12" Gray w/ White Specks VFT MASTIC | 300               | SF             | Basement Room 003 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62    | 2' x 4' Pinhole Ceiling Tile | 350               | PERCENT        | Basement Parents Room |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63    | 2' x 2' Ceiling Tile | 200               | SF             | Basement Kitchen Storage Room |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description              | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D     | Mag Block Breaching ABATED (2016) |                   |                | Boiler Room ABATED (2016) |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E     | Aircell Pipe Insulation | 150               | LF             | Passage by Rm. 003, Tank Room, Lunchroom/Kitchen, Main Office |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                 | Material Quantity | Material Units | Material Location                                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F     | MJP E/F/V on Aircell Pipe Insulation | 120               | FITTING        | Passage by Rm. 003, Tank Room, Lunchroom/Kitchen |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description       | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G     | Mag Block Ppipe Insulation | 150               | LF             | Tank Room, Kitchen/Lunchroom, Engine Room, Boiler Room |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                   | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H     | MJP E/F/V on Mag Block Pipe Insulation | 65                | FITTING        | Tank Room, Kitchen/Lunchroom, Engine Room, Boiler Room |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I     | Cardboard Pipe Insulation | 160               | LF             | Passage by Room 003, Girls Playroom, Tank Room, Engine Room, Boiler Room Toilets |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J     | MJP E/F/V on Cardboard Pipe Insulation | 65                | FITTING        | Passage by Room 003, Girls Play Room, Tank Room, Boiler Room Toilets |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K     | MJP E/F/V on Fiberglass Pipe Insulation | 68                | FITTING        | Throughout (See Hatching) |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L     | Aircell Duct Insulation | 1200              | SF             | Lunchroom/Kitchen |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| M     | Mag Block Duct Insulation (boiler flue) | 1070              | SF             | Boiler Room       |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Friedrich L. Jahn Elementary of the Fine Arts

Date: 12/5/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**