

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Amos Alonzo Stagg Elementary School  
**Address:** 7424 S. Morgan

**Oracle Unit:** 26521  
**Region:** 05

**Building ID:** 7760  
**Mail Room:** 45

**Asbestos Surveyor:** Baggett, Derry  
**Survey Date:** 2/11/2026  
**Email Address:** dbaggett4@cps.edu

**CHECK HERE IF NO CHANGE TO ASBESTOS**

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack     Notice printed in school's newsletter     Notice printed in school's calendar     Other

| HA No | Material Description      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 001-A | White Finish Coat Plaster | 1200              | SF             | 1st Floor Classrooms (with the exception of the Kindergarten Classrooms) and Washrooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                  | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 001-B | Hard Coat Plaster (White Finish Coat) | 12000             | SF             | 2nd Floor Classrooms, Washrooms and 1st Floor Fan Room |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 001-C | Plaster              | 500               | SF             | Second Floor Fan Rooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description      | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 001-D | White Finish Coat Plaster | 12000             | SF             | 3rd Floor Classrooms and Washrooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 001-E | Plaster              | 500               | SF             | 1st Floor Fan Room, 2nd Floor, and 3rd Floor |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description  | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 002   | Cementitious Sprayed On Surfacing Material - On Structural Beams NOT OBSERVED | 21000             | SF             | Above 3rd Floor Ceiling |               | Surface           | Yes     | Unknown     | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 003   | Fireproofing NOT OBSERVED | 25000             | SF             | Structural Beams  |               | Surface           | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 004   | Acoustical Plaster   | 17000             | SF             | Corridors, Lunchroom, Rooms 106 and 108 |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description       | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 005A  | 9"X9" Off-White Floor Tile | 60                | SF             | Engineer's Office 205 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 005B  | 9"X9" Green Floor Tile | 120               | SF             | Kitchen Storeroom |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 005C  | 9"x9" Tan Floor Tile | 28000             | SF             | 1st, 2nd & 3rd Floor Clorridors and Classrooms |               | Miscellaneous     | No      | Loc         | 10              |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description   | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 005D  | 9"x9" Brown Floor Tile | 4500              | SF             | 1st, 2nd & 3rd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description           | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 006A  | 12"x12" Olive Green Floor Tile | 100               | SF             | Classrooms, Corridor, Custodian's Closets |               | Miscellaneous     | No      | Loc         | 15              |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 006B  | 12"x12" Brown Speckled Floor Tile ABATED |                   |                | Lunchroom         |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 007   | Vinyl Baseboard      | 500               | LF             | Throughout school |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description            | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 008   | Vinyl Baseboard Mastic- No ACBM |                   |                | Throughout Classrooms |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 009   | Firedoors            | 5                 | EA             | Boiler Room       |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 010   | Incinerator Door- REMOVED |                   |                | Boiler Room       |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 011   | Fire Brick- No ACBM  |                   |                | Boiler Boom Incinerator |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description          | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 012A  | 9"x9" Brown Floor Tile Mastic | 4500              | SF             | Throughout School Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description        | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 012B  | 9"x9" Tan Floor Tile Mastic | 28000             | SF             | Corridors and Classrooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 012C  | 9"x9" Tan Floor Tile Mastic | 60                | SF             | Engineer's Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 012D  | 9"x9" Green Floor Tile Mastic | 30                | SF             | Engineer's Bathroom |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 013   | 9"x9" Gray Floor Tile (as Patches) ABATED |                   |                | Gym/Stage Access  |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 013A  | 12"x12" Olive Green Floor Tile Mastic | 100               | SF             | Custodian Closets |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 013B  | 12"x12" Brown Speckled Floor Tile Mastic ABATED |                   |                | Lunchroom         |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 014   | Window Glazing       | 7500              | LF             | Interior Windows Throughout school |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                 | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 015   | Brown Coat Plaster, Under Acoustical | 17000             | SF             | Throughout Corridors and Gym |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 016   | Plaster              | 2000              | SF             | Boiler Room       |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 017-A | Brown Coat Plaster   | 12000             | SF             | 1st Floor Classrooms (with the exception of the Kindergarten Classrooms) and Washrooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 017-B | Brown Coat Plaster   | 12000             | SF             | 2nd Floor Classrooms and Washrooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 017-C | Brown Coat Plaster   | 12000             | SF             | 3rd Floor Classrooms and Washrooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61    | 12"x12" White Floor Tile | 3410              | SF             | Rooms 304, 306, 307, 311, 205, 206, 209, 211, 214, 105, 106, 108, 112, 113 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61A   | 12"x12" White Floor Tile Mastic | 3410              | SF             | Room 304, 306, 307, 311, 205, 206, 209, 211, 214, 105, 106, 108, 112, 113 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62    | 12"x12" Yellow Floor Tile | 2910              | SF             | Room 304, 306, 307, 311, 206, 205, 209, 211, 214, 105, 106, 108, 112, 113 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description             | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62A   | 12"x12" Yellow Floor Tile Mastic | 2910              | SF             | Rooms 304, 306, 307, 311, 206, 205, 209, 211, 214, 105, 106, 108, 112, 113 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63    | 12"x12" Blue Floor Tile | 2910              | SF             | Room 304, 306, 307, 311, 205, 206, 209, 211, 214, 105, 106, 108, 112, 1st, 2nd, and 3rd floor corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description           | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63A   | 12"x12" Blue Floor Tile Mastic | 2410              | SF             | Room 304, 306, 307, 311, 205, 206, 209, 211, 214, 105, 106, 108, 112, 1st, 2nd, and 3rd floor corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64    | 12"x12" Off-White w/Gray Streaks Floor Tile | 270               | SF             | Gym/Stage Access  |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65    | 12"x12" Off-White w/Gray Streaks Floor Tile Mastic | 270               | SF             | Gym/Stage Access  |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66    | 12"x12" White w/Gray Streaks Floor Tile | 2700              | SF             | Lunchroom         |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 67    | 12"x12" White w/Gray Streaks Floor Tile Mastic | 2700              | SF             | Lunchroom         |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 68    | 9"x9" Brown Floor Tile | 270               | SF             | Kitchen Storage   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 69    | 9"x9" Brown Floor Tile Mastic | 270               | SF             | Kitchen Storage   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 70    | 12"x12" Blue Mottled Vinyl Floor Tile | 116               | SF             | Room 109          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 71    | 12"x12" Blue Mottled Vinyl Floor Tile Mastic | 116               | SF             | Room 109          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 72    | 12"x12" Gray Mottled Vinyl Floor Tile | 485               | SF             | Room 109          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 73    | 12"x12" Gray Mottled Vinyl Floor Tile Mastic | 485               | SF             | Room 109          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                 | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 74    | 12"x12" Tan Mottled Vinyl Floor Tile | 165               | SF             | Room 109          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 75    | 12"x12" Tan Mottled Vinyl Floor Tile Mastic | 165               | SF             | Room 109          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 76    | Blue Carpet Mastic   | 1200              | SF             | Room 201 (Library) |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 77    | Linoleum Countertops | 1500              | SF             | Throughout Classrooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 78    | Sink Undercoating    | 3                 | EA             | Rooms 106, 108 & 209 |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                                | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 79    | 2"x2" White, Light Blue and Blue Ceramic Tile Grout | 600               | SF             | 2nd Floor Washrooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                 | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 80    | 2"x2" Light Brown Ceramic Tile Grout | 600               | SF             | 1st Floor Washrooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 81    | 1"x1" Multicolor Ceramic Tile Grout | 600               | SF             | 3rd Floor Washrooms |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 82    | 6"x6" Brown Ceramic Tile Grout | 1000              | SF             | Kitchen           |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description   | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 83    | Beige & Brown Terrazzo | 3500              | SF             | All Staircases & Landings, and Entry Door 1 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A     | Hard Elbows          | 550               | LF             | Fan Rooms and Above Ceilings |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B     | Tank Insulation ABATED |                   |                | Boiler Room       |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C     | Boiler Insulation ABATED |                   |                | Boiler Room       |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D     | Boiler Gasket ABATED |                   |                | Boiler Room       |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E     | Blue Carpet Mastic   | 800               | SF             | Room 201          |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F     | Cementitious Pipe Joint Fitting Insulation ABATED |                   |                | Water Inlet Line  |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G     | Pipe Insulation      | 300               | LF             | Pipe Chases - Hidden |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description        | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| NEW   | Newly Installed Suspect ACM |                   |                | Installed After Implementation of Management Plan and After Renovations |               | Miscellaneous     |         | Unknown     |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Amos Alonzo Stagg Elementary School  
Date: 2/11/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.