

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Mark Sheridan Math & Science Academy  
**Address:** 533 W. 27th St.

**Oracle Unit:** 29201  
**Region:** 04

**Building ID:** 4920  
**Mail Room:** 39

**Asbestos Surveyor:** Rivera, Ramona  
**Survey Date:** 2/11/2026  
**Email Address:** rrrivera7@cps.edu

**CHECK HERE IF NO CHANGE TO ASBESTOS**

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 1A    | Plaster              |                   |                | SHERIDAN - MAIN Throughout |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                        | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 2A    | 2' x 4' Acoustical Ceiling Tile- Perforated |                   |                | SHERIDAN - MAIN Room 105 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                              | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 2B    | 2' x 4' Acoustical Ceiling Tile- Lightly Fissured |                   |                | SHERIDAN - MAIN Room 105 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                       | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 2C    | 2' x 4' Fissured & Perforated Ceiling Tile |                   |                | SHERIDAN - MAIN Room 008 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description        | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------|-------------------|----------------|----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 2D    | 2' x 4' Gypsum Ceiling Tile |                   |                | SHERIDAN - MAIN 2nd Floor (Men's Room) |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description              | Material Quantity | Material Units | Material Location                                                                                                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|--------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 3A    | 12" x 12" Speckled Tan Floor Tile | 4500              | SF             | SHERIDAN - MAIN 1st Floor - Bathroom, 2nd Floor - Janitor's Closet, Room 311, 008, 3rd Floor Hallway, 108, 3rd Floor Gym |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 3B    | 12" x 12" Red Speckled Floor Tile | 3000              | SF             | SHERIDAN - MAIN Rooms 206, 203, 103 |               | Miscellaneous     | No      | Loc         | 3               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description            | Material Quantity | Material Units | Material Location                                                                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------|-------------------|----------------|------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 3C    | 12" x 12" Dark Beige Floor Tile | 300               | SF             | SHERIDAN - MAIN 2nd Floor - Janitor's Closets (Right & Left), 3rd Floor Janitor's Closet |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description               | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 3D    | 12" x 12" Beige Marbled Floor Tile |                   |                | SHERIDAN - MAIN Boy's Playroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description       | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 3E    | 12" x 12" Cream Floor Tile |                   |                | SHERIDAN - MAIN Girl's Playroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 3F    | 12" x 12" Tan Floor Tile | 800               | SF             | SHERIDAN - MAIN Room 008 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description           | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------|-------------------|----------------|---------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 3G    | 12" x 12" Light Tan Floor Tile | 2000              | SF             | SHERIDAN - MAIN Room 101, 3rd Floor Hallway |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                             | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------------|-------------------|----------------|---------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 3H    | 12" x 12" Gray w/ White & Gray Specks Floor Tile | 1080              | SF             | SHERIDAN - MAIN Engineer Office and Adjacent Room |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                                                                                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------|-------------------|----------------|-------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 4A    | 12" x 12" Speckled Tan Floor Tile Mastic | 11000             | SF             | SHERIDAN - MAIN Room 008, Basement LR, See HA 3A Locations, 108, 311, 3rd Floor Hallway, First Floor Toilet |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 4B    | 12" x 12" Red Speckled Floor Tile Mastic | 3000              | SF             | SHERIDAN - MAIN Rooms 203, 206, 103 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------|-------------------|----------------|-----------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 4C    | 12" x 12" Dark Beige Floor Tile Mastic |                   |                | SHERIDAN - MAIN 2nd and 3rd Floor Janitor's Closets |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 4D    | 12" x 12" Beige Marbled Floor Tile Mastic |                   |                | SHERIDAN - MAIN Boy's Playroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description              | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 4E    | 12" x 12" Cream Floor Tile Mastic |                   |                | SHERIDAN - MAIN Girl's Playroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 4F    | 12" x 12" Tan Floor Tile Mastic |                   |                | SHERIDAN - MAIN Room 008 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------|-------------------|----------------|---------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 4G    | 12" x 12" Light Tan Floor Tile Mastic | 2000              | SF             | SHERIDAN - MAIN Room 101, 3rd Floor Hallway |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------------------------|-------------------|----------------|---------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 4H    | 12" x 12" Gray w/ White & Gray Specks Floor Tile Mastic | 1080              | SF             | SHERIDAN - MAIN Engineer Office and Adjacent Room |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description             | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 5     | Plaster Walls : 1902 Contruction |                   |                | SHERIDAN - MAIN Throughout |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 6     | Black Vinyl Cove Base |                   |                | SHERIDAN - MAIN Basement, 1st, 2nd |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description               | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 6A/7  | Adhesive For Black Vinyl Cove Base |                   |                | SHERIDAN - MAIN Basement, 1st, 2nd |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 8     | Plaster on Sheetrock |                   |                | SHERIDAN - MAIN Basement |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 9     | Sheetrock            |                   |                | SHERIDAN - MAIN Scattered |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 9A    | Joint Compound on Sheetrock |                   |                | SHERIDAN - MAIN Scattered |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 11    | Caulk                |                   |                | SHERIDAN - MAIN 2nd Floor Urinals |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 12    | 4"x4" White Ceramic Tile |                   |                | SHERIDAN - MAIN 2nd Floor Walls |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description               | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 12A   | Grout For 4"x4" White Ceramic Tile |                   |                | SHERIDAN - MAIN 2nd Floor Walls |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 12B   | 4" x 4" White Ceramic Tile Mastic |                   |                | SHERIDAN - MAIN 2nd Floor Walls |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description        | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------|-------------------|----------------|-------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 13    | 1" x 1" Pastel Ceramic Tile |                   |                | SHERIDAN - MAIN 2nd Floor Bathroom Floors |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------|-------------------|----------------|-------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 13A   | Grout For 1" x 1" Pastel Ceramic Tile |                   |                | SHERIDAN - MAIN 2nd Floor Bathroom Floors |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description               | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------|-------------------|----------------|-------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 13B   | 1" x 1" Pastel Ceramic Tile Mastic |                   |                | SHERIDAN - MAIN 2nd Floor Bathroom Floors |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location                                                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------------|-------------------|----------------|--------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 14    | 1" x 1" Dark Multi-Colored Ceramic Tile |                   |                | SHERIDAN - MAIN Basement Bathrooms and Entry to 1st Floor Boy's Restroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                              | Material Quantity | Material Units | Material Location                                                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------------------|-------------------|----------------|--------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 14A   | Grout For 1" x 1" Dark Multi-Colored Ceramic Tile |                   |                | SHERIDAN - MAIN Basement Bathrooms and Entry to 1st Floor Boy's Restroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                 | Material Quantity | Material Units | Material Location                                                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------------------|-------------------|----------------|--------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 14B   | Adhesive For 1" x 1" Dark Multi-Colored Ceramic Tile |                   |                | SHERIDAN - MAIN Basement Bathrooms and Entry to 1st Floor Boy's Restroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 15    | Wood Window Glaze    |                   |                | SHERIDAN - MAIN Interior Hallways |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                  | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 15A   | Wood Window Glaze : 1902 Construction |                   |                | SHERIDAN - MAIN Interior Hallways |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 16    | Metal Window Glaze : 1976 Construction |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description           | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 17    | Metal Window Caulk - Non-AHERA |                   |                | SHERIDAN - MAIN Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 18    | New 2"x8" Brick      |                   |                | SHERIDAN - MAIN Interior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 18A   | Mortar For 2"x8" Brick |                   |                | SHERIDAN - MAIN Interior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|---------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 19    | 2"x8" Glazed Brick   |                   |                | SHERIDAN - MAIN Interior Basement Bathrooms |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description          | Material Quantity | Material Units | Material Location                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------|-------------------|----------------|---------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 19A   | Mortar For 2"x8" Glazed Brick |                   |                | SHERIDAN - MAIN Interior Basement Bathrooms |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 20    | Interior Brick       |                   |                | SHERIDAN - MAIN Basement |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 20A   | Mortar For Interior Brick |                   |                | SHERIDAN - MAIN Basement |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description               | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 21    | Interior Brick : 1902 Construction |                   |                | SHERIDAN - MAIN Basement |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                          | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 21A   | Mortar For Interior Brick : 1902 Construction |                   |                | SHERIDAN - MAIN Basement |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 22    | 8"x16" Glazed Block  |                   |                | SHERIDAN - MAIN Basement Bathrooms |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 22A   | Mortar For 8"x16" Glazed Block |                   |                | SHERIDAN - MAIN Basement Bathrooms |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 23    | 8"x16" Cinderblock   |                   |                | SHERIDAN - MAIN Scattered |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description          | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 23A   | Mortar For 8"x16" Cinderblock |                   |                | SHERIDAN - MAIN Scattered |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description      | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 24    | Exterior Brick- Non-AHERA |                   |                | SHERIDAN - MAIN Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 24A   | Mortar For Exterior Brick-Non-AHERA |                   |                | SHERIDAN - MAIN Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description      | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 25    | Exterior Brick- Non-AHERA |                   |                | SHERIDAN - MAIN Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 25A   | Mortar For Exterior Brick-Non-AHERA |                   |                | SHERIDAN - MAIN Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 26    | Ceramic Caulk        |                   |                | SHERIDAN - MAIN 2nd Floor Bathrooms |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------|-------------------|----------------|----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 27    | Sink Insulation, Sink Under Coating | 100               | SF             | SHERIDAN - MAIN Rooms 102 and 202, 007 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------------------|-------------------|----------------|----------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 28    | 9" x 9" Vinyl Floor Tile, Beneath 12" x 12" Floor Tile | 1200              | SF             | SHERIDAN - MAIN Lunchroom, Beneath 12x12 VFT |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                                | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------------------------------------|-------------------|----------------|----------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 28A   | 9" x 9" Vinyl Floor Tile, Beneath 12" x 12" Vinyl Floor Tile Mastic | 1200              | SF             | SHERIDAN - MAIN Lunchroom, Beneath 12x12 VFT |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 29    | Window Frame Caulk   |                   |                | SHERIDAN - MAIN Throughout Interior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                   | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 30    | Window Frame Caulk : 1902 Construction |                   |                | SHERIDAN - MAIN Throughout Interior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                                                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 31    | 1' x 1' Ceiling Tile |                   |                | SHERIDAN - MAIN 3rd Floor Hallway, 1st floor teacher's rest room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                    | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 32    | Cloth Window Blinds : 1976 Construction |                   |                | SHERIDAN - MAIN Throughout |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                       | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 33    | Window Caulk Non-AHERA (1998 Construction) |                   |                | SHERIDAN - MAIN Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------|-------------------|----------------|--------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 34    | 4" Gray Vinyl Baseboard | 180               | LF             | SHERIDAN - MAIN Engineer's Office and Teachers' Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description             | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------|-------------------|----------------|--------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 35    | 4" Gray Vinyl Baseboard Adhesive | 180               | LF             | SHERIDAN - MAIN Engineer's Office and Teachers' Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description          | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 36    | Blue Ceramic Floor Tile Grout |                   |                | SHERIDAN - MAIN Engineer's Office Bathroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description          | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 37    | 4" Light Gray Vinyl Baseboard |                   |                | SHERIDAN - MAIN Engineer's Office Bathroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                   | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 38    | 4" Light Gray Vinyl Baseboard Adhesive |                   |                | SHERIDAN - MAIN Engineer's Office Bathroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description          | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 39    | White Ceramic Wall Tile Grout |                   |                | SHERIDAN - MAIN Engineer's Office Bathroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description             | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 40    | White Ceramic Wall Tile Adhesive |                   |                | SHERIDAN - MAIN Engineer's Office Bathroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description         | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 41    | 18" x 18" White Ceramic Tile |                   |                | SHERIDAN - MAIN Engineer's Office Bathroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                  | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------------------------|-------------------|----------------|-------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 42    | Blue, Red, Yellow, Purple Multi-Color Carpet Adhesive | 1600              | SF             | SHERIDAN - MAIN Computer Lab and Room 007 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description          | Material Quantity | Material Units | Material Location                                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------|-------------------|----------------|-----------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 43    | 4" Gray/Black Vinyl Baseboard | 300               | SF             | SHERIDAN - MAIN Computer Lab, Room 007 and Lunchroom area |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                   | Material Quantity | Material Units | Material Location                                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------|-------------------|----------------|-----------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 44    | 4" Gray/Black Vinyl Baseboard Adhesive | 300               | LF             | SHERIDAN - MAIN Computer Lab, Room 007 and Lunchroom area |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 45    | Blue Carpet Mastic   | 1600              | SF             | SHERIDAN - MAIN Library, 2nd Floor Counselor's Office(210), 109.5, 009 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 46    | Black Vinyl Baseboard | 40                | LF             | SHERIDAN - MAIN Room 008 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description           | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 47    | Black Vinyl Baseboard Adhesive | 40                | LF             | SHERIDAN - MAIN Room 008 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description             | Material Quantity | Material Units | Material Location                                                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------|-------------------|----------------|-------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 48    | 12" x 12" Light Beige Floor Tile | 4000              | SF             | SHERIDAN - MAIN Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location                                                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------------|-------------------|----------------|-------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 49    | 12" x 12" Light Beige Floor Tile Mastic | 4000              | SF             | SHERIDAN - MAIN Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|--------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 50    | Green Carpet Mastic  | 1200              | SF             | SHERIDAN - MAIN<br>Main Office and Assistant<br>Principal's Office |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 51    | 12" x 12" Orange/Rust<br>Floor Tile | 3100              | SF             | SHERIDAN - MAIN<br>Rooms 202,207,106 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 52    | 12" x 12" Orange/Rust<br>Floor Tile Mastic | 3100              | SF             | SHERIDAN - MAIN<br>Rooms 202,207,106 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 53    | Lab Tables           | 300               | SF             | SHERIDAN - MAIN<br>Lab Rooms 309 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                               | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 54    | 12" x 12" Gray Floor Tile w/ White and Black Spots | 50                | SF             | SHERIDAN - MAIN Boiler Room Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------------------------|-------------------|----------------|--------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 55    | 12" x 12" Gray Floor Tile w/ White & Black Spots Mastic | 50                | SF             | SHERIDAN - MAIN Boiler Room Stair Landing and Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 56    | Kiln Brick           | 20                | SF             | SHERIDAN - MAIN Boiler Room |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description         | Material Quantity | Material Units | Material Location                                                                                                                                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------|-------------------|----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 57    | Tongue and Groove Wood Floor | 1500              | SF             | SHERIDAN - MAIN 1st and 2nd Floor Hallways, 107, 105, 102, 104, 204, 201, 209, 208, 307, 308, 310, 306, 305, 309, 301, Auditorium/Gym , 304, Social Worker Office |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 58    | White Ceramic Tile   | 25                | SF             | SHERIDAN - MAIN<br>Main Office Toilet Room |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                             | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------------|-------------------|----------------|----------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 59    | 12" x 12" Light Gray Floor Tile w/ Black Streaks | 300               | SF             | SHERIDAN - MAIN<br>Basement Teacher's Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------------------|-------------------|----------------|----------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 60    | 12" x 12" Dark Gray Floor Tile w/ White Streaks | 300               | SF             | SHERIDAN - MAIN<br>Basement Teacher's Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                                  | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------------------------------------------|-------------------|----------------|----------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 61    | 12" x 12" Light Gray and Dark Gray w/ Black Streaks Floor Tile Mastic | 600               | SF             | SHERIDAN - MAIN<br>Basement Teacher's Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 62    | 12" x 12" Blue Floor Tile w/ White Streaks |                   |                | EAST BUILDING - ADDITION Hallway, Room 120 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 63    | 12" x 12" Gold Floor Tile w/ White Streaks |                   |                | EAST BUILDING - ADDITION Hallway, Room 120 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 64    | 12" x 12" Gray Floor Tile w/ White Streaks |                   |                | EAST BUILDING - ADDITION Hallway, Room 120 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                                              | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------------------------------------|-------------------|----------------|--------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 65    | 12" x 12" Blue, Gold, and Gray w/ White Streaks Floor Tile Mastic |                   |                | EAST BUILDING - ADDITION Hallway, Room 120 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                                                                                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|---------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 66    | 2' x 2' Ceiling Tile | 2100              | SF             | SHERIDAN - MAIN<br>307,207, and 107 Closet<br>(Elevator hallway), Main<br>Office Bathroom,<br>Teachers Lounge |               | Miscellaneous     | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 67    | Gray Ceramic Tile    |                   |                | EAST BUILDING -<br>ADDITION<br>Bathrooms |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 68    | Stage Blue Curtain   | 1000              | SF             | SHERIDAN - MAIN<br>3rd Floor Gymnasium |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description       | Material Quantity | Material Units | Material Location                                                                                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-------------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 69    | 2" x 2" Ceramic Floor Tile | 600               | SF             | SHERIDAN - MAIN<br>2nd Floor Women's<br>Bathroom Across 204,<br>107 Bathroom, Main<br>Office Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location                                                                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------|-------------------|----------------|-------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 70    | 2" x 2" Ceramic Floor Tile Grout | 600               | SF             | SHERIDAN - MAIN<br>2nd Floor Women's Bathroom Across 204,<br>107 Bathroom, Main Office Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                | Material Quantity | Material Units | Material Location                                                                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------|-------------------|----------------|-------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 71    | 2" x 2" Ceramic Floor Tile Adhesive | 600               | SF             | SHERIDAN - MAIN<br>2nd Floor Women's Bathroom Across 204,<br>107 Bathroom, Main Office Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description   | Material Quantity | Material Units | Material Location                                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------|-------------------|----------------|--------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 72    | Drywall/Joint Compound | 1000              | SF             | SHERIDAN - MAIN<br>Room 107 Bathroom,<br>Throughout Basement |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description              | Material Quantity | Material Units | Material Location                                                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|--------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 73    | 12" x 12" Blue Mottled Floor Tile | 125               | SF             | SHERIDAN - MAIN<br>1st Floor Staff Bathroom<br>by 103, Lunchroom Patches |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                                                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------|-------------------|----------------|-----------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 74    | 12" x 12" Blue Mottled Floor Tile Mastic | 75                | SF             | SHERIDAN - MAIN<br>1st Floor Staff Bathroom<br>by 103, Lunchroom<br>Patches |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 75    | 3" White Baseboard   | 50                | LF             | SHERIDAN - MAIN<br>Main Office Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description        | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------|-------------------|----------------|-----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 76    | 3" White Baseboard Adhesive | 50                | LF             | SHERIDAN - MAIN<br>Main Office Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description       | Material Quantity | Material Units | Material Location                                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-----------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 77    | 8" x 8" Ceramic Floor Tile | 150               | SF             | SHERIDAN - MAIN<br>Teachers Lounge<br>Bathroom (Basement) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------|-------------------|----------------|-----------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 78    | 8" x 8" Ceramic Floor Tile Grout | 150               | SF             | SHERIDAN - MAIN Teachers Lounge Bathroom (Basement) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------|-------------------|----------------|-----------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 79    | 8" x 8" Ceramic Floor Tile Adhesive | 150               | SF             | SHERIDAN - MAIN Teachers Lounge Bathroom (Basement) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 80    | 6" x 6 Ceramic Wall Tile | 100               | SF             | SHERIDAN - MAIN Teachers Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description           | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 81    | 6" x 6 Ceramic Wall Tile Grout | 100               | SF             | SHERIDAN - MAIN Teachers Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 82    | 6" x 6 Ceramic Wall Tile Adhesive | 100               | SF             | SHERIDAN - MAIN Teachers Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description               | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------|-------------------|----------------|------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 83    | Adhesive For Plastic Wall Covering | 40                | SF             | SHERIDAN - MAIN Teachers Lounge Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description       | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| A     | Fiberglass Pipe Insulation | 5000              | LF             | SHERIDAN - MAIN Throughout |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description        | Material Quantity | Material Units | Material Location                                                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------|-------------------|----------------|-----------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| B     | Fiberglass Joint Insulation | 200               | LF             | SHERIDAN - MAIN Throughout Building Boiler Room, Mechanical Room and Chases |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                          | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| C     | Cardboard Pipe Insulation : 1902 Construction | 2000              | LF             | SHERIDAN - MAIN Basement, 102, 202 |               | TSI               | Yes     | Loc         | 1               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                           | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| D     | Cardboard Joint Insulation : 1902 Construction | 250               | LF             | SHERIDAN - MAIN Basement, 102, 202 |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description    | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------|-------------------|----------------|----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| E     | Aircell Pipe Insulation | 680               | LF             | SHERIDAN - MAIN Basement and Fan Rooms |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------|-------------------|----------------|----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| F     | Aircell Joint Insulation | 81                | LF             | SHERIDAN - MAIN Basement and Fan Rooms |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| G     | Boiler Gaskets       | 40                | LF             | SHERIDAN - MAIN Inspection Doors |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| H     | Boiler Rope Gaskets  | 30                | LF             | SHERIDAN - MAIN Clean-Out Doors |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| I     | Interior Fire Brick  | 100               | SF             | SHERIDAN - MAIN Boilers |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description              | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| J     | Hot Water Make-Up Tank Insulation |                   |                | SHERIDAN - MAIN Boiler Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| K     | Breeching (Brick Lining) |                   |                | SHERIDAN - MAIN Incinerator |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| L     | Breeching Liner      | 150               | SF             | SHERIDAN - MAIN Boilers |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| M     | Refractory Brick     | 10                | SF             | SHERIDAN - MAIN Boilers |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| N     | Fire Brick           |                   |                | SHERIDAN - MAIN Incinerator |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| O     | Chimney Brick        |                   |                | SHERIDAN - MAIN Boiler Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| O1    | Chimney Brick Mortar |                   |                | SHERIDAN - MAIN Boiler Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| P     | Chimney Liner Brick  |                   |                | SHERIDAN - MAIN Boiler Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description       | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| P1    | Chimney Liner Brick Mortar |                   |                | SHERIDAN - MAIN Boiler Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| Q     | Chimney Soot         |                   |                | SHERIDAN - MAIN Boiler Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No    | Material Description   | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|----------|------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| R- Field | Roof Field - Non-AHERA |                   |                | SHERIDAN - MAIN Roof- Section E |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No    | Material Description       | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|----------|----------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| R- Flash | Roof Flashings - Non-AHERA |                   |                | SHERIDAN - MAIN Roof- Section E |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No      | Material Description | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|------------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| R- X Joint | Expansion Joint      |                   |                | SHERIDAN - MAIN Roof- Section E |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| S     | Block Pipe Insulation | 30                | LF             | SHERIDAN - MAIN Throughout |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Mark Sheridan Math & Science Academy  
Date: 2/11/2026

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.