

Chicago Public Schools

6 Month Asbestos Surveillance

2025 Fall Six Month Survey

School: Hyman G Rickover Naval Academy High School
Address: 5700 Berteau

Oracle Unit: 45221
Region: 01

Building ID: 50122-1
Mail Room:

Asbestos Surveyor: Degante, Joaquin
Survey Date: 2/11/2026
Email Address: jdegante9@cps.edu

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M01	Baseboard Mastic	9500	LF	Throughout Building - 1953 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M02	Insulation Panels (Behind Radiators)	3500	LF	Faculty Lounge 212-P, 210, Rooms: 209, 208, 207, 205, MDF Rm. 205A, Student Support Office 206-P, Offices 203-PA, 203-PB, 203-PC, 203-PD, Media Center 201, Art Studio LL09, Lab LL07, Room LL06, Science Lecture Hall LL05, Storage LL05-ST, Lab LL03, Storage LL03A, Bio Lab 100, Prep Room 100A, Office 112-PA, Storage 112-ST, Offices 121-PA & 121-PB, Multi-Purpose RM 110, Rooms: 119, 117, 115, Women's Locker Room, Men's Locker Room - 1953 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M03	12"x12" Off White VFT	5500	SF	Faculty Lounge 212-P, Rooms: 208, 207, 205, Media center 201, 2nd Fl. JC, 2nd Fl. Elevator Lobby, Art Studio LL09, Lab LL07, Science Lecture Hall LL05, Storage LL05-ST, Lab LL03, Storage LL03A, Bio Lab 100, Prep Room 100A, 1st Fl. Corridor/ Elevator Lobby, Lobby/ Corridor 01, Main Office 121, Offices 121-PA & 121-PB, Multi-Purpose Rm. 110 & Foyer, Rooms: 119, 117, 115, Corridor 05, Theater 105, Main Entrance/ Foyer 31, Corridor 04, Women's Toilet 9B, Accessible Shower, Men's Toilet 08C - 1953 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M04	12" x 12" Dark Gray Floor Tile	3500	SF	Faculty Lounge 212-P, Rooms: 208, 207, 205, 2nd Fl. JC, Art Studio LL09, Lab LL07, Science Lecture Hall LL05, Storage LL05-ST, Lab LL03, Bio Lab 100, Prep Room 100A, 1st Fl. Corridor/ Elevator Lobby, Lobby/ Corridor 01, Main Office 121, Offices 121-PA & 121-PB, Multi-Purpose Rm. 110 & Foyer, Rooms: 119, 117, 115, Corridor 05		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M04A	Mastic for 12" x 12" Dark Gray Floor tile	3500	SF	Faculty Lounge 212-P, Rooms: 208, 207, 205, 2nd Fl. JC, Art Studio LL09, Lab LL07, Science Lecture Hall LL05, Storage LL05-ST, Lab LL03, Bio Lab 100, Prep Room 100A, 1st Fl. Corridor/ Elevator Lobby, Lobby/ Corridor 01, Main Office 121, Offices 121-PA & 121-PB, Multi-Purpose Rm. 110 & Foyer, Rooms: 119, 117, 115, Corridor 05		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M07	9 x 9 Red w/ off white streaks VFT - Abated 2021			Corridor 222 Corridor 107 - 1953 building		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M07A	9 x 9 Red w/ off white streaks VFT Mastic - Abated 2021			Corridor 222 Corridor 107 - 1953 building		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M08	9x9 Green with Streaks VFT (Removed 2021)			Corridor #222 Corridor #107 - 1953 building		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M08A	Mastic for 9" x 9" Green w/ White Streaks Floor Tile (Removed in 2021)			Corridor 222, Corridor 107		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M09	2' x 2' Ceiling Tile w/ Pinholes	8500	SF	Faculty Lounge 212-P, Corridor 222, 2nd Fl. Elevator Lobby, Art Studio LL09, Lab LL07, Storage LL05-ST, Storage LL03A, Lab LL03, Bio Lab 100, Prep Room 100A, Corridor 107, 1st Fl. Elevator Lobby, Lobby/ Corridor 01, Office 112-P, Office 112-PA, Storage 112-ST, Corridor 05, Office 108-P, Kitchenette 106-K, Main Entrance/ Foyer 31, Corridor 04, Women's Toilet 9B, Men's Toilet 08C, Toilet 109-WC		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M10	Terrazzo Flooring	2000	SF	Stairwells		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M11	1' x 1' Ceiling Tile w/ Large Grooves	4500	SF	Rooms: 209, 207, 210, Student Support Office 206-P, Offices 203-PA, 203-PB, 203-PC, 203-PD, Media Center 201, Women's Toilet 202-WC, Men's Toilet 204-WC, Science Lecture Hall LL05, Lobby/ Corridor 01, Main Office 121, Offices 121-PA & 121-PB, Rooms: 119, 117, 115		Miscellaneous	No	Loc	6		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M11A	Mastic Pucks for 1' x 1' Ceiling Tile w/ Large Grooves	4500	SF	Rooms: 209, 207, 210, Student Support Office 206-P, Offices 203-PA, 203-PB, 203-PC, 203-PD, Media Center 201, Women's Toilet 202-WC, Men's Toilet 204-WC, Science Lecture Hall, Lobby/ Corridor 01, Main Office 121, Offices 121-PA & 121-PB, Rooms: 119, 117, 115		Miscellaneous	No	Loc	6		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M12	9" x 9" Dark Tan w/ Maroon & White Streaks Floor Tile	600	SF	Room 209		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M12A	Mastic 9" x 9" Dark Tan w/ Maroon & White Streaks Floor Tile	600	SF	Room 209		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M13	Ceramic Tile Grout	650	SF	Unisex Toilet by Faculty Lounge 212-P, 2nd Fl. Women's Toilet 202-WC, Men's Toilet 204-WC, 1st Fl. Women's Toilet LL02-WC, Men's Toilet LL04-WC, Restroom 112-PA-WC, Women's Locker Room 113-L, Women's Toilet 9B, Women's Toilet Room 113-WC, Accessible Shower, Storage 109-ST (111-P Office), Men's Locker Room 109-L, Men's Toilet 08C, Toilet 109-WC		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M14	9" x 9" Beige w/ White & Maroon Streaks Floor Tile (1000SF Removed)	800	SF	Corridor 222, Room 210, Student Support Office 206-P, Office 206-PA & Office 206-PB (under existing laminated wood flooring), Storage 203-PST, Corridor 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M14A	Mastic for 9" x 9" Beige w/ White & Maroon Streaks Floor Tile (1000SF Removed)	800	SF	Corridor 222, Room 210, Student Support Office 206-P, Office 206-PA & Office 206-PB (under existing laminated wood flooring), Storage 203-PST, Corridor 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M15	1' x 1' Ceiling Tile Solid White	100	SF	Room 210		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M15A	Mastic Pucks for 1' x 1' Ceiling Tile Solid White	100	LF	Room 210		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M16	2' x 4' Ceiling Tile w/ Pinholes	1900	SF	Computer Lab 205, Room 208, Office 206-PA, Office 206-PB, Consulting 203-P, Office 203-PB, Office 203-PE & Hall between offices, Men's Toilet LL04-WC, Women's Toilet LL02-WC		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M17	2' x 2' Gray Floor Tile	600	SF	MDF Room 205A, IT/MDF 107-ST		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M17A	Mastic for 2' x 2' Gray Floor Tile	600	SF	MDF Room 205A, IT/MDF 107-ST		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M18	12"x 12" Light Blue w/ Streaks Floor Tile	1600	SF	Men's Toilet 204-WC, Women's Toilet 202-WC, Restroom 112-PA-WC, Men's Toilet 109-WC, Kitchenette 106-K, Office 108-P		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M18A	Mastic for 12"x 12" Light Blue w/ Streaks Floor Tile	1600	SF	Men's Toilet 204-WC, Women's Toilet 202-WC, Restroom 112-PA-WC, Men's Toilet 109-WC, Kitchenette 106-K, Office 108-P		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M19	1' x 1' Textured Ceiling Tile	300	SF	Women's Toilet 202-WC		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M19A	Mastic Pucks for 1' x 1' Textured Ceiling Tile	300	SF	Women's Toilet 202-WC		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M20	Carpet Tiles Mastic	1900	SF	Offices 203-PA, 203-PB, 203-PC, 203-PD, 203-PE & Hall in between, Office 112-P, Office 112-PA, Storage 112-ST		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M21	9" x 9" Maroon w/ White & Red Streaks Floor Tile (180SF Removed)	20	SF	Corridor 222, Corridor 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M21A	Mastic for 9" x 9" Maroon w/ White & Red Streaks Floor Tile	20	SF	Corridor 222, Corridor 107		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M22	2' x 4' Ceiling Tile w/ Grooves (180SF Removed)	2800	SF	Balcony Room for Lower GYM 104-G, Lower GYM 104-G East and West Vestibules/stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M27	2' x 2' Ceiling Tile w/ Large Grooves and Pinholes	100	SF	Women's Toilet Room 113-WC		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M29	1' x 1' Ceiling Tile w/ Wide Grooves and Pinholes	18000	SF	Rooms: 220, 218, 217, 216, 215, 214, 213, 211, LL15, LL14P, LL13, LL12, LL11, Office 123-P, Office 123-PA, Faculty Lunchroom 125-M, Multi-Purpose Room 120-M, Offices 123-P, 124-P, 125-P, 133-P & Hall in between, Band Room 128, Cafeteria 127-M, Hall between band room & cafeteria		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M29A	Mastic Pucks for 1' x 1' Ceiling Tile w/ Wide Grooves and Pinholes	18000	SF	Rooms: 220, 218, 217, 216, 215, 214, 213, 211, LL15, LL14P, LL13, LL12, LL11, Office 123-P, Office 123-PA, Faculty Lunchroom 125-M, Multi-Purpose Room 120-M, Offices 123-P, 124-P, 125-P, 133-P & Hall in between, Band Room 128, Cafeteria 127-M, Hall between band room & cafeteria		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M30	9" x 9" Tan w/ Maroon & Off-White Streaks Floor Tile	7500	SF	Rooms: 220, 218, 217, 216, 214, 213, 2nd Floor Corridor, LL15, LL13 (10SF of Damage) , Office 123-P, Office 123-PA & Closet (Under Carpet), Cafeteria 127-M, Storage 120-MSTA, Stage's Stairs, Offices, 124-P, 125-P & Hall, Storage 120-MSTB		Miscellaneous	No	Loc	10		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M30A	Mastic for 9" x 9" Tan w/ Maroon & Off-White Streaks Floor Tile	7500	SF	Rooms: 220, 218, 217, 216, 214, 213, 2nd Floor Corridor, LL15, LL13 (10SF of damage), Office 123-P, Office 123-PA & Closet (Under Carpet), Cafeteria 127-M, Storage 120-MSTA, Stage's Stairs, Offices, 124-P, 125-P & Hall, Storage 120-MSTB		Miscellaneous	No	Loc	10		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M31	Baseboard Mastic	2500	SF	Throughout 1960 Addition		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M32	Insulation Panels (behind radiators)	1500	SF	Rooms: 220, 218, 217, 216, 215, 214, 213, 211, LL15, LL13, LL12, LL11, Offices 123-P, 123-PA, Multi-Purpose 120-M, Offices 124-P, 125-P		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M33	12" x 12" Off White VFT	2350	SF	Rooms: 215, LL12, LL11, Cafeteria 127-M, 211		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M33A	Mastic for 12" x12" Off White Floor Tile	2350	SF	Rooms: 215, LL12, LL11, Cafeteria 127-M, 211		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M34	12" x 12" Dark Gray Floor Tile	2350	SF	Rooms: 215, LL12, LL11, Cafeteria 127-M, 211		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M34A	Mastic for 12" x 12" Dark Gray Floor Tile	2350	SF	Rooms: 215, LL12, LL11, Cafeteria 127-M, 211		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M35	12" x 12" Light Gray w/ White & Gray Streaks Floor Tile	2350	SF	Rooms: 215, LL12, LL11, Cafeteria 127-M		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M35A	Mastic for 12"x 12" Light Gray w/ White & Gray Streaks Floor Tile	2350	SF	Rooms: 215, LL12, LL11, Cafeteria 217-M, 211		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M36	Drywall System	3300	SF	Rooms: 220, 218, 217, 216, 215, 214, 213, 211, LL15, LL13, LL12, LL11, Men's Toilet 116-WC, Women's Toilet 118-WC, Ramp Area, Kitchen 129-K, Office 128, Toilet RM 128B, Multi-Purpose 120-M, Cafeteria 127-M		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M37	9" x 9" Solid Brown Floor Tile	60	SF	2nd Floor Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M37A	Mastic for 9" x 9" Solid Brown Floor Tile	60	SF	2nd Floor Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M38	9" x 9" Red w/ Off White Streaks Floor Tile	100	SF	2nd & 1st Floor Corridors		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M38A	Mastic for 9" x 9" Red w/ Off White Streaks Floor Tile	100	SF	2nd & 1st Floor Corridors		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M39	9" x 9" Green w/ White Streaks Floor Tile	1200	SF	2nd & 1st Floor Corridors, Not observed in #127M Cafeteria. Still exists under HA#M33, M34, M35, & associated mastic		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M39A	Mastic for 9" x 9" Green w/ White Streaks Floor Tile	1200	SF	2nd & 1st Floor Corridors, Not observed in #127M Cafeteria. Still exists under HA#M33, M34, M35, & associated mastic		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M40	2' x 2' Ceiling Tile w/ Pinholes	9500	SF	2nd & 1st Floor Corridors, Rooms: 221A, 221B, 221C, 221D, 221E, Hall 221, Music Room Corridor 220, Band Room 128		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M41	Terrazzo Flooring	1800	SF	Stairs 1ST & 2nd Floor, Band Room 128, Hall connecting the Band room and Cafeteria		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M42	Ceramic Tile Grout	500	LF	Men's Toilet 116-WC, Women's Toilet 118-WC, Toilet Room 128B		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M43	9" x 9" Beige w/ White & Maroon Streaks Floor Tile	4500	SF	1st Floor Corridors, Room LL15, Cafeteria 127-M, Storage 127-STA, Office 133-P		Miscellaneous	No	Loc	1		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M43A	Mastic for 9" x 9" Beige w/ White & Maroon Streaks Floor Tile	4500	SF	1st Floor Corridors, Room LL15, Storage 127-STA, Office 133-P		Miscellaneous	No	Loc	1		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M44	2' x 2' Gray Floor Tile	200	SF	IDF Room LL16-STA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M44A	Mastic for 2' x 2' Gray Floor Tile	200	SF	IDF Room LL16-STA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M45	12"x 12" Light Blue w/ Streaks Floor Tile	600	SF	Faculty Lunchroom 125-M		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M45A	Mastic for 12"x 12" Light Blue w/ Streaks Floor Tile	600	SF	Faculty Lunchroom 125-M		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M46	Carpet Tiles Mastic	1100	SF	Offices 123-P, 123-PA, Conference Room LL14-P		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M47	9" x 9" Maroon w/ White & Red Streaks Floor Tile	1100	SF	Storage 127-STB		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M47A	Mastic for 9" x 9" Maroon w/ White & Red Streaks Floor Tile	1100	SF	Storage 127-STB		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M48	2' x 4' Ceiling Tile w/ Grooves	200	SF	Storage 127-STA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M49	12" x 12" Off White Stone Pattern Floor Tile	100	SF	Storage/Mezzanine 120-MSTA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M49A	Mastic for 12" x 12" Off White Stone Pattern Floor Tile	100	SF	Storage/Mezzanine 120-MSTA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M50	9" x 9" Yellow Floor Tile	100	SF	Rooms: 215. LL12. LL11, 211 Cafeteria 127-M,		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M50A	Mastic for 9" x 9" Yellow Floor Tile	100	SF	Rooms: 215. LL12. LL11, 211 Cafeteria 127-M,		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M51	9" x 9" Gray w/ White Streaks Floor Tile	1400	SF	Rooms LL15, LL13		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M51A	Mastic for 9" x 9" Gray w/ White Streaks Floor Tile	1400	SF	Rooms LL15, LL13		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M56	Baseboard Mastic	150	LF	2nd Floor Rooms 221-P, 223, Office 103-P, Stairs 15, Upper GYM 100-G, Weight Room S04		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M57	Insulation Panels (behind radiators)	250	SF	Rooms 221-P, 223		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M58	2' x 2' Ceiling Tile w/ Pinholes	400	SF	Bridge/ Breeze Way		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M59	Terrazzo Flooring	1900	SF	Bridge/ Breeze Way, 2nd Fl. Hall, Stairs, Upper GYM 100-G West Stairs, Basement Main Corridor, Locker Room S07-L Toilet, Locker Room S06-L Toilet, Restroom S11-WC, Storage S12-ST		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M60	1' x 1' Ceiling Tile w/ Large Grooves	400	SF	Storage 100-ST		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M60A	Mastic Pucks for 1' x 1' Ceiling Tile w/ Large Grooves	400	SF	Storage 100-ST		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M61	12" x 12" Off White Floor Tile	40	SF	Stairs 15 Landings		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M61A	Mastic for 12" x12" Off White Floor Tile	40	SF	Stairs 15 Landings		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M62	12" x 12" Dark Gray Floor Tile	40	SF	Stairs 15 Landings		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M62A	Mastic for 12" x 12" Dark Gray Floor Tile	40	SF	Stairs 15 Landings		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M63	12"x 12" Light Gray w/ White & Gray Streaks Floor Tile	40	SF	Stairs 15 Landings		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M63A	Mastic for 12"x 12" Light Gray w/ White & Gray Streaks Floor Tile	40	SF	Stairs 15 Landings		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M64	Drywall System	60	SF	Storage S10-ST, Weight Room S04		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M65	2' x 4' Ceiling Tile w/ Pinholes	350	SF	2nd Floor Hall, Room 223		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M66	2' x 4' Ceiling Tile w/ Grooves	550	SF	2nd Fl. Room 221-P, Hall & Stairs, Upper GYM 100-G West Stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M67	12" x 12" Off White w/ Speckles Floor tile	350	SF	2nd Fl. Room 221-P		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M67A	Mastic for 12" x 12" Off White w/ Speckles Floor tile	350	SF	2nd Fl. Room 221-P		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M70	Gray-Wood grained plank flooring	1100	SF	storage 125M Faculty bathroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M70A	Gray-Wood grained plank flooring - Adhesive	1100	SF	Storage 125M Faculty lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M71A	Black Mastic Underwrestling Mats	2000	SF	Upper Gym 100-G		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
MA03A	12"x12" Off White VFT Mastic	5500	SF	Faculty Lounge 212-P, Rooms: 208, 207, 205, Media center 201, 2nd Fl. JC, 2nd Fl. Elevator Lobby, Art Studio LL09, Lab LL07, Science Lecture Hall LL05, Storage LL05-ST, Lab LL03, Storage LL03A, Bio Lab 100, Prep Room 100A, 1st Fl. Corridor/ Elevator Lobby, Lobby/ Corridor 01, Main Office 121, Offices 121-PA & 121-PB, Multi-Purpose Rm. 110 & Foyer, Rooms: 119, 117, 115, Corridor 05, Theater 105, Main Entrance/ Foyer 31, Corridor 04, Women's Toilet 9B, Accessible Shower, Men's Toilet 08C		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S28	Hard Plaster	1800	SF	2nd & 1st Floor Corridors, Stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S55	Hard Plaster	500	SF	Basement Stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
SP1	Hard Coat Plaster	10000	SF	1st and 2nd Floor Corridors, Stairwells, Women's Locker Room & Showers, Kitchenette 106-K, Storage 109 ST (111-P Office), Men's Locker Room & Showers, Office 108-P - 1953 Building		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T23	Mudded Joint Packing on Fiberglass Pipe Insulation	120	LF	Lower GYM 104-G, Pipe Tunnels, Pipe Chases		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T24	Aircell Pipe Insulation	1075	LF	Lower GYM 104-G, Pipe Tunnels		TSI	Yes	Loc	3		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T24A	Mudded Joint Packing for Aircell Pipe Insulation	290	LF	Lower GYM 104-G, Pipe Tunnels - (LL06B Storage Room, LL02 WC - Girls toilets, LL04 WC Boys Toilets) - 1953 building.		TSI	Yes	Loc	1		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T25	Paper-wrap Pipe Insulation	238	LF	Pipe Tunnels - (LL06B Storage Room, LL02 WC - Girls toilets, LL04 WC Boys Toilets)		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T25A	Mudded Joint Packing for Paper-wrap Pipe Insulation	47	LF	Pipe Tunnels - (LL06B Storage Room, LL02 WC - Girls toilets, LL04 WC Boys Toilets)		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T26	Mudded Joint Packing for Roof Drains	12	LF	Lower GYM 104-G		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T52	Mudded Joint Packing (MJP) on Fiberglass Pipe Insulation	10	LF	Stage's Mezzanine		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T53	Aircell Pipe Insulation	60	LF	Rooms: LL15, LL13, LL13 Closet, LL11, LL12		TSI	No	Loc	1		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T53A	Mudded Joint Packing for Aircell Pipe Insulation	6	LF	Rooms: LL15, LL13, LL11		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T54	Paper-wrap Pipe Insulation	100	LF	Storage/Mezzanine 120-MSTA		TSI	No	Loc	27		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T54A	Mudded Joint Packing for Paper-wrap Pipe Insulation	10	LF	Storage/Mezzanine 120-MSTA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T68	Mudded Joint Packing on Fiberglass Pipe Insulation	22	LF	Room S03, Office S14-STP, Locker Room S07-L & Toilet		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T69	Mudded Joint Packing for Roof Drains	16	LF	Upper GYM 100-G -1968 building		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change

Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

Richard J. Schleyer

Richard J.Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Hyman G Rickover Naval Academy High School
Date: 2/11/2026

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
 - A copy of this notice was printed in the school's newsletter and sent home with each child
 - A copy of this notice was printed in the school's calendar and sent home with each child
 - Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.