

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2215  
SCHOOL NAME: Gary School  
ADDRESS OF SCHOOL: 3740 W. 31st St.  
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/4/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 4/28/2016 ENROLLMENT 1114  
IDPH INSPECTOR LICENSE NUMBER: 100-02865  
IDPH LICENSED INSPECTOR NAME (Please Print): Steven Doran  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



4/28/2016

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Gary School**

3740 W. 31st St.  
Chicago, IL, 60623

Unit: 23311  
Building ID: 3520

IDPH ID Number: 14-016-2990-2215

**REPORT DATE:**

Thursday, April 28, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL**  
**REQUIRED BY FEDERAL LAW**

Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 04, 2016

RE: Gary School, Unit 23311  
3740 W. 31st St.  
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Gary School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Gary School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School:	Gary School	Unit:	23311	Region:	04
Address:	3740 W. 31st St.		Chicago, IL, 60623		
IDPH ID:	14-016-2990-2215		Building ID:	3520	
Contact:	Strain, Louis		Phone:	312-966-9737	

### 2. Description of Facility

Original Construction:	1972	Additional Construction:	1911,1980
Total Square Footage:		No of Floors:	
Current Occupancy:	1114		

### 3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	125 South Clark Street, 17th Floor		
	Chicago, IL 60603		


### 4. Managing Environmental Consultant

MEC:	Carnow, Conibear and Associates		
Contact:	Dan Juneau		
Address	600 West Van Buren St., Ste 500		
Phone:	(312) 762-2900	Fax:	(312) 782-5145

### 5. Inspector

Inspector Name: Steven Doran

Inspector IDPH license # 100-02865

Signature:   
Date: 4/4/2016

### 6. Management Planner

Management Planner Name: Evan Christian


Management Planner IDPH license # 100-19466

Signature:  
Date: 04/28/2016

### 7. Review Date: 04/28/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/28/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Gary School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3520:

1	Plaster
11	Tan Linoleum
26	2'x2' Ceiling Panels
3D	12"x12" White Floor Tile
47	Boiler Wrap #1
48	Boiler Wrap #2
49	Insulation Over Fiberglass
51	Duct Insulation
52	Refractory Cement in Doors of #1 Boiler

53	Refractory Cement in Doors of #2 Boiler
54	Firebrick in Boiler #1
55	Firebrick in Boiler #2
86	12" x 12" Beige Floor Tile
87	Mastic Associated w/ 12" x 12" Beige Floor Tile
88	Vinyl Sheeting Glued on Plywood
89	2' x 4' Ceiling Tile



B. The following new homogenous areas have been identified for Building 3520:

86	12" x 12" Beige Floor Tile
87	Mastic Associated w/ 12" x 12" Beige Floor Tile
88	Vinyl Sheeting Glued on Plywood
89	2' x 4' Ceiling Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	Plaster
11	Tan Linoleum
13	Beige Linoleum
15A	4" Black Vinyl Baseboards
15B	6" Black Vinyl Baseboard
16A	4" Black Vinyl Baseboard Mastic
16B	6" Black Vinyl Baseboard Mastic
19	Exterior Brick - Not AHERA
20	Exterior Brick Mortar
21	Exterior Door Caulk
22	Drywall
23	Black Cementitious Flooring
24	Green Terrazzo
25	Brown Terrazzo Wall Panels
26	2'x2' Ceiling Panels
27	Terrazzo Basin
28	Yellow Baseboard
29	Yellow Baseboard Mastic
30	Blue Baseboard
31	Blue Baseboard Mastic
32	Interior Brick
33	Interior Brick Mortar
34	Terrazzo Baseboard
35	Ceramic Tile Grout
36	Glazed Brick Mortar
37	Interior Door Caulk
38	Block Mortar
39	Blue/Green/Gray/White Ceramic Tile Grout
3A	12"x12" Beige Floor Tile w/Brown Streaks
3C	12"x12" Beige Floor Tile w/Brown and White Streaks
4	12"x12" Ceiling Tile
40	Gray Carpet Mastic
41	Cinder Block Mortar
43	Black Border Tile Mastic
44	2'x4' Ceiling Panels
45	Terrazzo
46	12"x12" Terrazzo
49	Insulation Over Fiberglass
51	Duct Insulation
52	Refractory Cement in Doors of #1 Boiler
53	Refractory Cement in Doors of #2 Boiler

54	Firebrick in Boiler #1
55	Firebrick in Boiler #2
56	4" Black Vinyl Baseboard
57	4" Black Vinyl Baseboard Mastic
5A	12"x12" Multi-Gray Floor Tile
6	Brown Linoleum
60	Green Ceramic Tile Grout
61	Gray Carpet Mastic
65	Exterior Door Caulk
66	12"x12" Multi-Gray Floor Tile Mastic
68	Cementitious Pipe Joint Insulation
71	Vault Door Liner
72	12" x 12" Tan w/ Lt. Brown floor tile
73	Mastic w/ 12" x 12" tan w/ Lt. brown floor tile
74	12 x 12 Grey w/ Dk. Grey & White Floor Tile
75	mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile
76	purple carpet adhesive
77	12 x 12 Tan Floor Tile
78	Mastic w/ 12 x 12 Tan Floor Tile
79	12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile
80	Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile
81	12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile
82	Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile
83	Tan Linoleum
84	Adhesive w/ Tan Linoleum
85	Brown Carpet Adhesive
86	12" x 12" Beige Floor Tile
87	Mastic Associated w/ 12" x 12" Beige Floor Tile
88	Vinyl Sheeting Glued on Plywood
89	2' x 4' Ceiling Tile
9A	12" x 12" Beige Floor Tile w/ Brown Streaks Mastic
9C	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic
A2	Cementitious Insulation on Joints off Fiberglass
B2	Cementitious Insulation off Paper Wrap Pipe Runs

The following areas were deemed to be inaccessible:

16A	4" Black Vinyl Baseboard Mastic
16B	6" Black Vinyl Baseboard Mastic
29	Yellow Baseboard Mastic
31	Blue Baseboard Mastic
40	Gray Carpet Mastic

43	Black Border Tile Mastic
61	Gray Carpet Mastic
66	12"x12" Multi-Gray Floor Tile Mastic
67	12"x12" Gray Floor Tile w/White Streaks Mastic
87	Mastic Associated w/ 12" x 12" Beige Floor Tile
8A	9"x9" Tan w/Ye, Blue, and White Floor Tile Mastic
8B	9"x9" Tan Floor Tile w/Brown and White Mastic
8C	9"x9" Brown Floor Tile w/White and Red Mastic
8D	9" x 9" Beige Floor Tile Mastic
8E	9" x 9" Black Floor Tile Mastic
8F	9" x 9" Maroon Floor Tile Mastic
8G	9" x 9" Brown Floor Tile Mastic
8H	9" x 9" Green Floor Tile Mastic
8I	9" x 9" Aqua Floor Tile Mastic
8J	9" x 9" Aqua Floor Tile Mastic
8K	9" x 9" Yellow Floor Tile Mastic
9A	12" x 12" Beige Floor Tile w/ Brown Streaks Mastic
9B	12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic
9C	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic
9D	12" x 12" White Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Steven Doran, IDPH License # 100-02865. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Gary School Building 3520 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Plaster	60,000	SF	Throughout 1909 Building	ASSUMED	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
10	Number Skipped				UNDEFINE D									
11	Tan Linoleum	576	SF	Kitchen of 1909 Building	ASSUMED	MISC	N	DIST	25		Yes	ACBM with the potential for damage	3	LOW
13	Beige Linoleum	720	SF	Lunchroom, 008, and 009 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	4" Black Vinyl Baseboards	1,800	LF	Classrooms in 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15B	6" Black Vinyl Baseboard	480	LF	Hallways of 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16A	4" Black Vinyl Baseboard Mastic	1,800	LF	Classrooms of 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16B	6" Black Vinyl Baseboard Mastic	480	LF	Hallways of 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Exterior Brick - Not AHERA			1909 Building	ASSUMED	MISC								
2 D	9" x 9" Beige Floor Tile			104	CHR	MISC								
20	Exterior Brick Mortar	14,000	SF	1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Exterior Door Caulk	120	LF	1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Drywall	1,440	SF	Teacher's Room, Lunchroom, 008, 009 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Black Cementitious Flooring	1,760	SF	First Floor Corridor and Stair Landings of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Green Terrazzo	40	SF	Women's Washroom of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Brown Terrazzo Wall Panels	40	SF	Men's and Women's Washrooms of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2'x2' Ceiling Panels	800	SF	Lunchroom of 1909 Building	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
27	Terrazzo Basin	20	SF	Kitchen and Sink Closet of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Yellow Baseboard	200	SF	Lunchroom of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
29	Yellow Baseboard Mastic	200	SF	Lunchroom of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2A	9"x9" Tan w/Yellow, Blue, and White Floor Tile	800	SF	100 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2B	9"x9" Tan Floor Tile w/Brown and White	800	SF	100 and Room 208 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2C	9"x9" Brown Floor Tile w/White and Red	800	SF	208 and Faculty Washroom of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2E	9" x 9" Black Floor Tile	50	SF	Faculty Washroom of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2F	9" x 9" Maroon Floor Tile	20	SF	Faculty Washroom of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2G	9" x 9" Brown Floor Tile	750	SF	208 of 1909 Building	CHR	MISC	N	LOC	5		No	ACBM with potential for significant damage	5	LOW
2H	9"x9" Green Floor Tile w/White Streaks	400	SF	204 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2I	9"x9" Aqua Floor Tiles w/White Streaks	415	SF	Room 204 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2J	9"x9" Aqua Floor Tile w/Black and White Specks	40	SF	301 of 1909 Building	CHR	MISC	N	LOC	8		No	ACBM with the potential for damage	3	LOW
2K	9"x9" Yellow Floor Tile w/White Streaks	50	SF	301 of 1909 Building	CHR	MISC	N	LOC	8		No	ACBM with the potential for damage	5	LOW
2L	9"x9" Gray Floor Tile w/White Streaks			Gym of 1909 Building	CHR	MISC								
2M	9"x9" Light Brown Floor Tile w/White Swirls			Gym of 1909 Building	CHR	MISC								
30	Blue Baseboard	108	SF	1st Room West of E Entrance of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Blue Baseboard Mastic	100	SF	1st Room West of E Entrance of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Interior Brick	80,000	SF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Interior Brick Mortar	80,000	SF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Terrazzo Baseboard	300	SF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Ceramic Tile Grout	70	SF	Throughout Entrances of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Glazed Brick Mortar	400	SF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
37	Interior Door Caulk	200	LF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Block Mortar	10	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Blue/Green/Gray/White Ceramic Tile Grout	500	SF	Throughout Boy's and Girl's Washrooms of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3A	12"x12" Beige Floor Tile w/Brown Streaks	700	SF	005 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3B	12"x12" Beige Floor Tile w/Brown and White Specks	750	SF	101 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3C	12"x12" Beige Floor Tile w/Brown and White Streaks	750	SF	206 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3D	12"x12" White Floor Tile	700	SF	301 of 1909 Building	CHR	MISC	N	LOC	7		Yes	ACBM with the potential for damage	3	LOW
4	12"x12" Ceiling Tile			Throughout Annex	ASSUMED	MISC								
40	Gray Carpet Mastic	1,500	SF	Office, 105, and 106 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Cinder Block Mortar	1,300	SF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Black Border Tile	200	SF	204 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Black Border Tile Mastic	50	SF	204 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	2'x4' Ceiling Panels	200	SF	Kitchen of 1909 Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
45	Terrazzo	150	SF	Washroom in Room D of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12"x12" Terrazzo	150	SF	D Room of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Boiler Wrap #1	500	SF	Boiler Room of 1909 Building	CHR	MISC	Y	LOC	50		Yes	Damaged or significantly damaged friable misc. ACBM	1	MODERATE
48	Boiler Wrap #2	500	SF	Boiler Room of 1909 Building	CHR	MISC	Y	LOC	50		Yes	Damaged or significantly damaged friable misc. ACBM	1	MODERATE
49	Insulation Over Fiberglass	140	LF	Maintenance Room of 1909 Building	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
50	Mag Block Insulation	100	LF	Boiler Room of 1909 Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

**School** Gary School **Unit** 23311 **Building ID** 3520  
**Address** 3740 W. 31st St. **Region** 04

### Inspector's Reinspection Findings Table 1

600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

[illegible]

# Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				1972 Annex	ED									
71	Vault Door Liner	15	SF	2nd Floor Landing N/E Stairwell	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	12" x 12" Tan w/ lt. Brown floor tile			Engineer's Office	ASSUMED	MISC								
73	Mastic w/ 12" x 12" tan w/ lt. brown floor tile			Engineer's Office	ASSUMED	MISC								
74	12 x 12 Grey w/ Dk. Grey & White Floor Tile	60	SF	Engineer's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile	60	SF	Engineer's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	purple carpet adhesive			Principal's Office	ASSUMED	MISC								
77	12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	Mastic w/ 12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile	2,300	SF	Café	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile	2,300	SF	Café	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile	100	SF	Café	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile	100	SF	Café	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	Tan Linoleum	600	SF	Basement Art Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	Adhesive w/ Tan Linoleum	600	SF	Basement Art Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	Brown Carpet Adhesive	3,000	SF	1972 Annex Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12" x 12" Beige Floor Tile	700	SF	Room 104	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
87	Mastic Associated w/ 12" x 12" Beige Floor Tile	700	SF	Room 104	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
88	Vinyl Sheeting Glued on Plywood	3,000	SF	Gym	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
89	2' x 4' Ceiling Tile	7,500	SF	N, S, E, W Corridor Entrances, Rooms 401-412	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
8A	9"x9" Tan w/Ye, Blue, and White Floor Tile Mastic	800	SF	Room 100 in 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8B	9"x9" Tan Floor Tile w/Brown and White Mastic	800	SF	Faculty Washroom by Room 100 and Room 208 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
8C	9"x9" Brown Floor Tile w/White and Red Mastic	800	SF	Faculty Washroom and Room 208 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8D	9" x 9" Beige Floor Tile Mastic	250	SF	Room 104 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8E	9" x 9" Black Floor Tile Mastic	50	SF	Faculty Washroom of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8F	9" x 9" Maroon Floor Tile Mastic	20	SF	Faculty Washroom of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8G	9" x 9" Brown Floor Tile Mastic	750	SF	Room 208 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8H	9" x 9" Green Floor Tile Mastic	400	SF	Room 204 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8I	9" x 9" Aqua Floor Tile Mastic	415	SF	Room 301 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8J	9" x 9" Aqua Floor Tile Mastic	40	SF	Room 301 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8K	9" x 9" Yellow Floor Tile Mastic	40	SF	Room 301 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8L	9" x 9" Gray Floor Tile Mastic			Gym of 1909 Building	CHR	MISC								
8M	9" x 9" Light Brown Floor Tile Mastic			Gym of 1909 Building	CHR	MISC								
9A	12" x 12" Beige Floor Tile w/ Brown Streaks Mastic	750	SF	Room 005 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9B	12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic	750	SF	101	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9C	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic	700	SF	206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9D	12" x 12" White Floor Tile Mastic	700	SF	301	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A2	Cementitious Insulation on Joints off Fiberglass	350	LF	Throughout 1909 Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B1	Cardboard Pipe Insulation	1,300	LF	Throughout 1909 Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B2	Cementitious Insulation off Paper Wrap Pipe Runs	100	LF	Throughout 1909 Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D1	Aircell Pipe Insulation	300	LF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date **4/4/2016**

Inspector Name **Steven Doran**

**100-02865**

**5/15/2016**

Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	Damage is located in the kitchen office and kitchen office bathroom
13	Not observed in Rooms 008 and 009
15A	
15B	
16A	
16B	
19	
2 D	Not observed 2016
20	
21	
22	Not observed in Rooms 008 and 009
23	
24	
25	
26	
27	
28	
29	
2A	
2B	Not observed in Room 008 and 009
2C	
2E	

# Chicago Public Schools

**School** Gary School **Unit** 23311 **Building ID** 3520

**Address** 3740 W. 31st St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
2F	
2G	Damage is located in Room 204
2H	
2I	
2J	Damage is located in Room 301
2K	Damage is located in Room 301
2L	Not observed - Now wood patterned linoleum
2M	Not observed - Now wood patterned linoleum
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3A	
3B	
3C	
3D	Damage is located in Room 301
4	Not observed 2016
40	
41	
42	
43	
44	
45	

# Chicago Public Schools

**School** Gary School **Unit** 23311 **Building ID** 3520

**Address** 3740 W. 31st St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	Not observed 2016
57	Not observed 2016
5A	
5B	
6	
60	
61	
65	
66	
67	
68	
7	
70	
71	
72	Not observed - Now a wood floor
73	Not observed - Now a wood floor
74	
75	
76	Not observed - Now a wood floor

# Chicago Public Schools

**School** Gary School **Unit** 23311 **Building ID** 3520

**Address** 3740 W. 31st St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
8A	
8B	
8C	
8D	
8E	
8F	
8G	
8H	
8I	
8J	
8K	
8L	Not observed 2016
8M	Not observed 2016
9A	
9B	
9C	



# Chicago Public Schools

**School** Gary School **Unit** 23311 **Building ID** 3520

**Address** 3740 W. 31st St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
9D	
A2	
B1	
B2	
D1	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Plaster	60,000	SF	Throughout 1909 Building	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
10	Number Skipped				Undefined						
11	Tan Linoleum	576	SF	Kitchen of 1909 Building	Assumed	MISC	No	25	SF	6 ACBM with the potential for damage	Repair
13	Beige Linoleum	720	SF	Lunchroom, 008, and 009 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	4" Black Vinyl Baseboards	1,800	LF	Classrooms in 1972 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
15B	6" Black Vinyl Baseboard	480	LF	Hallways of 1972 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
16A	4" Black Vinyl Baseboard Mastic	1,800	LF	Classrooms of 1972 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
16B	6" Black Vinyl Baseboard Mastic	480	LF	Hallways of 1972 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
19	Exterior Brick - Not AHERA			1909 Building	Assumed	MISC					
2 D	9" x 9" Beige Floor Tile			104	Chrysotile	MISC					Follow O&M Plan
20	Exterior Brick Mortar	14,000	SF	1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
21	Exterior Door Caulk	120	LF	1909 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
22	Drywall	1,440	SF	Teacher's Room, Lunchroom, 008, 009 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Black Cementitious Flooring	1,760	SF	First Floor Corridor and Stair Landings of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Green Terrazzo	40	SF	Women's Washroom of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Brown Terrazzo Wall Panels	40	SF	Men's and Women's Washrooms of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	2'x2' Ceiling Panels	800	SF	Lunchroom of 1909 Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
27	Terrazzo Basin	20	SF	Kitchen and Sink Closet of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Yellow Baseboard	200	SF	Lunchroom of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Yellow Baseboard Mastic	200	SF	Lunchroom of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2A	9"x9" Tan w/Yellow, Blue, and White Floor Tile	800	SF	100 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2B	9"x9" Tan Floor Tile w/Brown and White	800	SF	100 and Room 208 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2C	9"x9" Brown Floor Tile w/White and Red	800	SF	208 and Faculty Washroom of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2E	9" x 9" Black Floor Tile	50	SF	Faculty Washroom of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2F	9" x 9" Maroon Floor Tile	20	SF	Faculty Washroom of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2G	9" x 9" Brown Floor Tile	750	SF	208 of 1909 Building	Chrysotile	MISC	No	5	SF	5 ACBM with potential for significant damage	Repair

# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
2H	9"x9" Green Floor Tile w/White Streaks	400	SF	204 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2I	9"x9" Aqua Floor Tiles w/White Streaks	415	SF	Room 204 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2J	9"x9" Aqua Floor Tile w/Black and White Specks	40	SF	301 of 1909 Building	Chrysotile	MISC	No	8	SF	6 ACBM with the potential for damage	Repair
2K	9"x9" Yellow Floor Tile w/White Streaks	50	SF	301 of 1909 Building	Chrysotile	MISC	No	8	SF	6 ACBM with the potential for damage	Repair
2L	9"x9" Gray Floor Tile w/White Streaks			Gym of 1909 Building	Chrysotile	MISC					Follow O&M Plan
2M	9"x9" Light Brown Floor Tile w/White Swirls			Gym of 1909 Building	Chrysotile	MISC					Follow O&M Plan
30	Blue Baseboard	108	SF	1st Room West of E Entrance of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Blue Baseboard Mastic	100	SF	1st Room West of E Entrance of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Interior Brick	80,000	SF	Throughout 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Interior Brick Mortar	80,000	SF	Throughout 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Terrazzo Baseboard	300	SF	Throughout 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Ceramic Tile Grout	70	SF	Throughout Entrances of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Glazed Brick Mortar	400	SF	Throughout 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Interior Door Caulk	200	LF	Throughout 1909 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
38	Block Mortar	10	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Blue/Green/Gray/White Ceramic Tile Grout	500	SF	Throughout Boy's and Girl's Washrooms of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3A	12"x12" Beige Floor Tile w/Brown Streaks	700	SF	005 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3B	12"x12" Beige Floor Tile w/Brown and White Specks	750	SF	101 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3C	12"x12" Beige Floor Tile w/Brown and White Streaks	750	SF	206 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3D	12"x12" White Floor Tile	700	SF	301 of 1909 Building	Chrysotile	MISC	No	7	SF	6 ACBM with the potential for damage	Repair
4	12"x12" Ceiling Tile			Throughout Annex	Assumed	MISC					Follow O&M Plan
40	Gray Carpet Mastic	1,500	SF	Office, 105, and 106 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Cinder Block Mortar	1,300	SF	Throughout 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Black Border Tile	200	SF	204 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Black Border Tile Mastic	50	SF	204 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	2'x4' Ceiling Panels	200	SF	Kitchen of 1909 Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
45	Terrazzo	150	SF	Washroom in Room D of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12"x12" Terrazzo	150	SF	D Room of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Boiler Wrap #1	500	SF	Boiler Room of 1909 Building	Chrysotile	MISC	Yes	50	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair

# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
48	Boiler Wrap #2	500	SF	Boiler Room of 1909 Building	Chrysotile	MISC	Yes	50	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
49	Insulation Over Fiberglass	140	LF	Maintenance Room of 1909 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
50	Mag Block Insulation	100	LF	Boiler Room of 1909 Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
51	Duct Insulation	300	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
52	Refractory Cement in Doors of #1 Boiler	20	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
53	Refractory Cement in Doors of #2 Boiler	20	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
54	Firebrick in Boiler #1	200	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
55	Firebrick in Boiler #2	200	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
56	4" Black Vinyl Baseboard			004 of 1909 Building	Assumed	MISC					Follow O&M Plan
57	4" Black Vinyl Baseboard Mastic			004 of 1909 Building	Assumed	MISC					Follow O&M Plan
5A	12"x12" Multi-Gray Floor Tile	1,900	SF	Hallways of 1972 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5B	12"x12" Gray Floor Tile w/White Streaks	600	SF	Book Room and Storage in 1972 Annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Brown Linoleum	400	SF	Basement Room D of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Green Ceramic Tile Grout	10	SF	Entrances of 1972 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Gray Carpet Mastic	600	SF	Classrooms, Teacher's Lounge and Office of 1972 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Exterior Door Caulk	84	LF	Throughout 1972 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
66	12"x12" Multi-Gray Floor Tile Mastic	1,900	SF	Hallways of 1972 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12"x12" Gray Floor Tile w/White Streaks Mastic	600	SF	Book Room and Storage in 1972 Annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Cementitious Pipe Joint Insulation	4	LF	Electric Room (Behind Wall) in 1972 Annex	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
7	Transite Panels			Basement (Abated)	Abated						
70	Fiberglass Insulation			Electric Room of 1972 Annex	Not Tested						
71	Vault Door Liner	15	SF	2nd Floor Landing N/E Stairwell	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12" x 12" Tan w/ lt. Brown floor tile			Engineer's Office	Assumed	MISC					Follow O&M Plan
73	Mastic w/ 12" x 12" tan w/ lt. brown floor tile			Engineer's Office	Assumed	MISC					Follow O&M Plan
74	12 x 12 Grey w/ Dk. Grey & White Floor Tile	60	SF	Engineer's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
75	mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile	60	SF	Engineer's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	purple carpet adhesive			Principal's Office	Assumed	MISC					Follow O&M Plan
77	12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	Mastic w/ 12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile	2,300	SF	Café	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile	2,300	SF	Café	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile	100	SF	Café	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile	100	SF	Café	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	Tan Linoleum	600	SF	Basement Art Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Adhesive w/ Tan Linoleum	600	SF	Basement Art Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Brown Carpet Adhesive	3,000	SF	1972 Annex Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Beige Floor Tile	700	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Mastic Associated w/ 12" x 12" Beige Floor Tile	700	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Vinyl Sheeting Glued on Plywood	3,000	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	2' x 4' Ceiling Tile	7,500	SF	N, S, E, W Corridor Entrances, Rooms 401-412	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
8A	9"x9" Tan w/Ye, Blue, and White Floor Tile Mastic	800	SF	Room 100 in 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8B	9"x9" Tan Floor Tile w/Brown and White Mastic	800	SF	Faculty Washroom by Room 100 and Room 208 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8C	9"x9" Brown Floor Tile w/White and Red Mastic	800	SF	Faculty Washroom and Room 208 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8D	9" x 9" Beige Floor Tile Mastic	250	SF	Room 104 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8E	9" x 9" Black Floor Tile Mastic	50	SF	Faculty Washroom of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8F	9" x 9" Maroon Floor Tile Mastic	20	SF	Faculty Washroom of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8G	9" x 9" Brown Floor Tile Mastic	750	SF	Room 208 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8H	9" x 9" Green Floor Tile Mastic	400	SF	Room 204 Of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8I	9" x 9" Aqua Floor Tile Mastic	415	SF	Room 301 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8J	9" x 9" Aqua Floor Tile Mastic	40	SF	Room 301 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8K	9" x 9" Yellow Floor Tile Mastic	40	SF	Room 301 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8L	9" x 9" Gray Floor Tile Mastic			Gym of 1909 Building	Chrysotile	MISC					Follow O&M Plan
8M	9" x 9" Light Brown Floor Tile Mastic			Gym of 1909 Building	Chrysotile	MISC					Follow O&M Plan
9A	12" x 12" Beige Floor Tile w/ Brown Streaks Mastic	750	SF	Room 005 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
9B	12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic	750	SF	101	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9C	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic	700	SF	206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9D	12" x 12" White Floor Tile Mastic	700	SF	301	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A2	Cementitious Insulation on Joints off Fiberglass	350	LF	Throughout 1909 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B1	Cardboard Pipe Insulation	1,300	LF	Throughout 1909 Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B2	Cementitious Insulation off Paper Wrap Pipe Runs	100	LF	Throughout 1909 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D1	Aircell Pipe Insulation	300	LF	Boiler Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	4/28/2016
Manager Planner Name	Evan Christian
100-19466	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	Repair as needed then follow O&M procedure.
13	If identified follow O&M procedure.
15A	
15B	
16A	
16B	
19	
2 D	If identified follow O&M procedure.
20	
21	
22	If identified follow O&M procedure.
23	
24	
25	
26	
27	
28	
29	
2A	
2B	If identified follow O&M procedure.
2C	
2E	



# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
2F	
2G	Repair as needed then follow O&M procedure.
2H	
2I	
2J	Repair as needed then follow O&M procedure.
2K	Repair as needed then follow O&M procedure.
2L	If identified follow O&M procedure.
2M	If identified follow O&M procedure.
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3A	
3B	
3C	
3D	Repair as needed then follow O&M procedure.
4	If identified follow O&M procedure.
40	
41	
42	
43	

# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
44	
45	
46	
47	Patch and repair as needed then follow O&M procedure.
48	Patch and repair as needed then follow O&M procedure.
49	
50	
51	
52	
53	
54	
55	
56	If identified follow O&M procedure.
57	If identified follow O&M procedure.
5A	
5B	
6	
60	
61	
65	
66	
67	
68	
7	If identified follow O&M procedure.
70	
71	
72	If identified follow O&M procedure.

# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
73	If identified follow O&M procedure.
74	
75	
76	If identified follow O&M procedure.
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
8A	
8B	
8C	
8D	
8E	
8F	
8G	
8H	
8I	
8J	

# Chicago Public Schools

**School** Gary School  
**Address** 3740 W. 31st St.

**Unit** 23311  
Chicago, IL, 60623

**Building ID** 3520  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
8K	
8L	If identified follow O&M procedure.
8M	If identified follow O&M procedure.
9A	
9B	
9C	
9D	
A2	
B1	
B2	
D1	

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1909 Building		
MATERIAL QUANTITY:	60000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **60000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10	
MATERIAL DESCRIPTION:	Number Skipped	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Number Skipped**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Tan Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen of 1909 Building		
MATERIAL QUANTITY:	576	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage is located in the kitchen office and kitchen office bathroom		

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Tan Linoleum**

MATERIAL LOCATION: **Kitchen of 1909 Building**

MATERIAL QUANTITY:	<b>576</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>25</b>	DAMAGE UNITS:	<b>SF</b>
------------------	-----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair as needed then follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Gary School** INSPECTION DATE: **4/4/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Beige Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom, 008, and 009 of 1909 Building**

MATERIAL QUANTITY: **720**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 008 and 009**

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Beige Linoleum**

MATERIAL LOCATION: **Lunchroom, 008, and 009 of 1909 Building**

MATERIAL QUANTITY:	<b>720</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15A		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboards		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms in 1972 Annex		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA:	<b>15A</b>		
MATERIAL DESCRIPTION:	<b>4" Black Vinyl Baseboards</b>		
MATERIAL LOCATION:	<b>Classrooms in 1972 Annex</b>		
MATERIAL QUANTITY:	<b>1800</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15B		
MATERIAL DESCRIPTION:	6" Black Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallways of 1972 Annex**

MATERIAL QUANTITY: **480**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **15B**

MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard**

MATERIAL LOCATION: **Hallways of 1972 Annex**

MATERIAL QUANTITY: **480**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16A		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms of 1972 Annex		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **16A**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Classrooms of 1972 Annex**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16B		
MATERIAL DESCRIPTION:	6" Black Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallways of 1972 Annex**

MATERIAL QUANTITY: **480**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **16B**

MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Hallways of 1972 Annex**

MATERIAL QUANTITY: **480**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19	
MATERIAL DESCRIPTION:	Exterior Brick - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2 D	
MATERIAL DESCRIPTION:	9" x 9" Beige Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with potential for significant damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 104

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2 D**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**

MATERIAL LOCATION: **104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Exterior Brick Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1909 Building		
MATERIAL QUANTITY:	14000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Exterior Brick Mortar**

MATERIAL LOCATION: **1909 Building**

MATERIAL QUANTITY: **14000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Exterior Door Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1909 Building		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Exterior Door Caulk**

MATERIAL LOCATION: **1909 Building**

MATERIAL QUANTITY:	<b>120</b>	MATERIAL UNITS:	<b>LF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teacher's Room, Lunchroom, 008, 009 of 1909 Building**

MATERIAL QUANTITY: **1440**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 008 and 009**

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Teacher's Room, Lunchroom, 008, 009 of 1909 Building**

MATERIAL QUANTITY: **1440**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Black Cementitious Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	First Floor Corridor and Stair Landings of 1909 Building		
MATERIAL QUANTITY:	1760	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Gary School	REVIEW DATE:	4/28/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

HOMOGENEOUS AREA: 23

MATERIAL DESCRIPTION: Black Cementitious Flooring

MATERIAL LOCATION: First Floor Corridor and Stair Landings of 1909 Building

MATERIAL QUANTITY:	1760	MATERIAL UNITS:	SF
--------------------	------	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	Green Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Women's Washroom of 1909 Building		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Green Terrazzo**

MATERIAL LOCATION: **Women's Washroom of 1909 Building**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Brown Terrazzo Wall Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Men's and Women's Washrooms of 1909 Building		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Brown Terrazzo Wall Panels**

MATERIAL LOCATION: **Men's and Women's Washrooms of 1909 Building**

MATERIAL QUANTITY:	<b>40</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	-----------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	2'x2' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom of 1909 Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **2'x2' Ceiling Panels**

MATERIAL LOCATION: **Lunchroom of 1909 Building**

MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Terrazzo Basin		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen and Sink Closet of 1909 Building**

MATERIAL QUANTITY: **20**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Terrazzo Basin**

MATERIAL LOCATION: **Kitchen and Sink Closet of 1909 Building**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	Yellow Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom of 1909 Building**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Yellow Baseboard**

MATERIAL LOCATION: **Lunchroom of 1909 Building**

MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	Yellow Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom of 1909 Building**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Yellow Baseboard Mastic**

MATERIAL LOCATION: **Lunchroom of 1909 Building**

MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2A		
MATERIAL DESCRIPTION:	9"x9" Tan w/Yellow, Blue, and White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	100 of 1909 Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **9"x9" Tan w/Yellow, Blue, and White Floor Tile**

MATERIAL LOCATION: **100 of 1909 Building**

MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2B		
MATERIAL DESCRIPTION:	9"x9" Tan Floor Tile w/Brown and White		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **100 and Room 208 of 1909 Building**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 008 and 009**

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2B**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile w/Brown and White**

MATERIAL LOCATION: **100 and Room 208 of 1909 Building**

MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2C		
MATERIAL DESCRIPTION:	9"x9" Brown Floor Tile w/White and Red		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **208 and Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2C**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile w/White and Red**

MATERIAL LOCATION: **208 and Faculty Washroom of 1909 Building**

MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2E		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **50**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2E**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2F		
MATERIAL DESCRIPTION:	9" x 9" Maroon Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **20**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2F**

MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2G		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	208 of 1909 Building		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage is located in Room 204		

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2G**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **208 of 1909 Building**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair as needed then follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2H		
MATERIAL DESCRIPTION:	9"x9" Green Floor Tile w/White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **204 of 1909 Building**

MATERIAL QUANTITY: **400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2H**

MATERIAL DESCRIPTION: **9"x9" Green Floor Tile w/White Streaks**

MATERIAL LOCATION: **204 of 1909 Building**

MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2I		
MATERIAL DESCRIPTION:	9"x9" Aqua Floor Tiles w/White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 204 of 1909 Building**

MATERIAL QUANTITY: **415**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2I**

MATERIAL DESCRIPTION: **9"x9" Aqua Floor Tiles w/White Streaks**

MATERIAL LOCATION: **Room 204 of 1909 Building**

MATERIAL QUANTITY:	<b>415</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2J		
MATERIAL DESCRIPTION:	9"x9" Aqua Floor Tile w/Black and White Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	301 of 1909 Building		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage is located in Room 301		

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2J**

MATERIAL DESCRIPTION: **9"x9" Aqua Floor Tile w/Black and White Specks**

MATERIAL LOCATION: **301 of 1909 Building**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair as needed then follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2K		
MATERIAL DESCRIPTION:	9"x9" Yellow Floor Tile w/White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	301 of 1909 Building		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage is located in Room 301		

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2K**

MATERIAL DESCRIPTION: **9"x9" Yellow Floor Tile w/White Streaks**

MATERIAL LOCATION: **301 of 1909 Building**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair as needed then follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2L	
MATERIAL DESCRIPTION:	9"x9" Gray Floor Tile w/White Streaks	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Gym of 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed - Now wood patterned linoleum

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Gary School	REVIEW DATE:	4/28/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

HOMOGENEOUS AREA: 2L

MATERIAL DESCRIPTION: 9"x9" Gray Floor Tile w/White Streaks

MATERIAL LOCATION: Gym of 1909 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2M	
MATERIAL DESCRIPTION:	9"x9" Light Brown Floor Tile w/White Swirls	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Gym of 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed - Now wood patterned linoleum

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **2M**

MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile w/White Swirls**

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	Blue Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Room West of E Entrance of 1909 Building		
MATERIAL QUANTITY:	108	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Blue Baseboard**

MATERIAL LOCATION: **1st Room West of E Entrance of 1909 Building**

MATERIAL QUANTITY:	<b>108</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	Blue Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Room West of E Entrance of 1909 Building		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Blue Baseboard Mastic**

MATERIAL LOCATION: **1st Room West of E Entrance of 1909 Building**

MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	Interior Brick		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1909 Building		
MATERIAL QUANTITY:	80000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **80000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Gary School** INSPECTION DATE: **4/4/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **80000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **80000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Terrazzo Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Terrazzo Baseboard**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Entrances of 1909 Building		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **Throughout Entrances of 1909 Building**

MATERIAL QUANTITY: **70**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	Glazed Brick Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Glazed Brick Mortar**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Interior Door Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Interior Door Caulk**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>LF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Block Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Block Mortar**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Blue/Green/Gray/White Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Throughout Boy's and Girl's Washrooms of 1909 Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Blue/Green/Gray/White Ceramic Tile Grout**

MATERIAL LOCATION: **Throughout Boy's and Girl's Washrooms of 1909 Building**

MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3A		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile w/Brown Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	005 of 1909 Building		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **3A**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/Brown Streaks**

MATERIAL LOCATION: **005 of 1909 Building**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3B		
MATERIAL DESCRIPTION:	12"x12"Beige Floor Tile w/Brown and White Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **101 of 1909 Building**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **3B**

MATERIAL DESCRIPTION: **12"x12"Beige Floor Tile w/Brown and White Specks**

MATERIAL LOCATION: **101 of 1909 Building**

MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3C		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile w/Brown and White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **206 of 1909 Building**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **3C**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/Brown and White Streaks**

MATERIAL LOCATION: **206 of 1909 Building**

MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3D		
MATERIAL DESCRIPTION:	12"x12" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	301 of 1909 Building		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage is located in Room 301		

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA:	<b>3D</b>		
MATERIAL DESCRIPTION:	<b>12"x12" White Floor Tile</b>		
MATERIAL LOCATION:	<b>301 of 1909 Building</b>		
MATERIAL QUANTITY:	<b>700</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>7</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair as needed then follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4	
MATERIAL DESCRIPTION:	12"x12" Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Throughout Annex

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Gary School	REVIEW DATE:	4/28/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

HOMOGENEOUS AREA: 4

MATERIAL DESCRIPTION: 12"x12" Ceiling Tile

MATERIAL LOCATION: Throughout Annex

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Gray Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office, 105, and 106 of 1909 Building		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Office, 105, and 106 of 1909 Building**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	Cinder Block Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **1300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Black Border Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	204 of 1909 Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Black Border Tile**

MATERIAL LOCATION: **204 of 1909 Building**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Black Border Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	204 of 1909 Building		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Black Border Tile Mastic**

MATERIAL LOCATION: **204 of 1909 Building**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	2'x4' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen of 1909 Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Gary School	REVIEW DATE:	4/28/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

HOMOGENEOUS AREA: 44

MATERIAL DESCRIPTION: 2'x4' Ceiling Panels

MATERIAL LOCATION: Kitchen of 1909 Building

MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
--------------------	-----	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Washroom in Room D of 1909 Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Washroom in Room D of 1909 Building**

MATERIAL QUANTITY:	<b>150</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12"x12" Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	D Room of 1909 Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12"x12" Terrazzo**

MATERIAL LOCATION: **D Room of 1909 Building**

MATERIAL QUANTITY:	<b>150</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Boiler Wrap #1		
HISTORICAL AHERA DAMAGE CATEGORY	4 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON:	Air Erosion/Flow Delamination Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Boiler Room of 1909 Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Boiler Wrap #1**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>50</b>	DAMAGE UNITS:	<b>SF</b>
------------------	-----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Patch and repair as needed then follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Boiler Wrap #2		
HISTORICAL AHERA DAMAGE CATEGORY	4 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON:	Air Erosion/Flow Delamination Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Boiler Room of 1909 Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Boiler Wrap #2**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>50</b>	DAMAGE UNITS:	<b>SF</b>
------------------	-----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Patch and repair as needed then follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	Insulation Over Fiberglass		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Maintenance Room of 1909 Building		
MATERIAL QUANTITY:	140	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Insulation Over Fiberglass**

MATERIAL LOCATION: **Maintenance Room of 1909 Building**

MATERIAL QUANTITY:	<b>140</b>	MATERIAL UNITS:	<b>LF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Gary School** INSPECTION DATE: **4/4/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Mag Block Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room of 1909 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Mag Block Insulation**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>LF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room of 1909 Building		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Duct Insulation**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	Refractory Cement in Doors of #1 Boiler		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room of 1909 Building		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Refractory Cement in Doors of #1 Boiler**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Refractory Cement in Doors of #2 Boiler		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room of 1909 Building		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Refractory Cement in Doors of #2 Boiler**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Firebrick in Boiler #1		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room of 1909 Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Firebrick in Boiler #1**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	Firebrick in Boiler #2		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room of 1909 Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Firebrick in Boiler #2**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56	
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 004 of 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **004 of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57	
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 004 of 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **004 of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5A		
MATERIAL DESCRIPTION:	12"x12" Multi-Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways of 1972 Annex		
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **5A**

MATERIAL DESCRIPTION: **12"x12" Multi-Gray Floor Tile**

MATERIAL LOCATION: **Hallways of 1972 Annex**

MATERIAL QUANTITY: **1900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5B		
MATERIAL DESCRIPTION:	12"x12" Gray Floor Tile w/White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Book Room and Storage in 1972 Annex		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA:	<b>5B</b>				
MATERIAL DESCRIPTION:	<b>12"x12" Gray Floor Tile w/White Streaks</b>				
MATERIAL LOCATION:	<b>Book Room and Storage in 1972 Annex</b>				
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6		
MATERIAL DESCRIPTION:	Brown Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Room D of 1909 Building**

MATERIAL QUANTITY: **400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Brown Linoleum**

MATERIAL LOCATION: **Basement Room D of 1909 Building**

MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	Green Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Entrances of 1972 Annex		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Green Ceramic Tile Grout**

MATERIAL LOCATION: **Entrances of 1972 Annex**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	Gray Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms, Teacher's Lounge and Office of 1972 Annex**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Classrooms, Teacher's Lounge and Office of 1972 Annex**

MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	Exterior Door Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1972 Annex**

MATERIAL QUANTITY: **84**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Exterior Door Caulk**

MATERIAL LOCATION: **Throughout 1972 Annex**

MATERIAL QUANTITY: **84**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12"x12" Multi-Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways of 1972 Annex		
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12"x12" Multi-Gray Floor Tile Mastic**

MATERIAL LOCATION: **Hallways of 1972 Annex**

MATERIAL QUANTITY: **1900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12"x12" Gray Floor Tile w/White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Book Room and Storage in 1972 Annex		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/White Streaks Mastic**

MATERIAL LOCATION: **Book Room and Storage in 1972 Annex**

MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	Cementitious Pipe Joint Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Electric Room (Behind Wall) in 1972 Annex		
MATERIAL QUANTITY:	4	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation**

MATERIAL LOCATION: **Electric Room (Behind Wall) in 1972 Annex**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Gary School** INSPECTION DATE: **4/4/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **Transite Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement (Abated)**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Transite Panels**

MATERIAL LOCATION: **Basement (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Gary School** INSPECTION DATE: **4/4/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **Fiberglass Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Electric Room of 1972 Annex**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Fiberglass Insulation**

MATERIAL LOCATION: **Electric Room of 1972 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	Vault Door Liner		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Landing N/E Stairwell		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Vault Door Liner**

MATERIAL LOCATION: **2nd Floor Landing N/E Stairwell**

MATERIAL QUANTITY: **15**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72	
MATERIAL DESCRIPTION:	12" x 12" Tan w/ lt. Brown floor tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Engineer's Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed - Now a wood floor

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ lt. Brown floor tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	Mastic w/ 12" x 12" tan w/ lt. brown floor tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed - Now a wood floor

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Mastic w/ 12" x 12" tan w/ lt. brown floor tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	12 x 12 Grey w/ Dk. Grey & White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **60**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12 x 12 Grey w/ Dk. Grey & White Floor Tile**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **60**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76	
MATERIAL DESCRIPTION:	purple carpet adhesive	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Principal's Office

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed - Now a wood floor

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **purple carpet adhesive**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	12 x 12 Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Principal's Office Room 104**

MATERIAL QUANTITY: **400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Gary School	REVIEW DATE:	4/28/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

HOMOGENEOUS AREA: 77

MATERIAL DESCRIPTION: 12 x 12 Tan Floor Tile

MATERIAL LOCATION: Principal's Office Room 104

MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
--------------------	-----	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	Mastic w/ 12 x 12 Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Principal's Office Room 104**

MATERIAL QUANTITY: **400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **Mastic w/ 12 x 12 Tan Floor Tile**

MATERIAL LOCATION: **Principal's Office Room 104**

MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Café		
MATERIAL QUANTITY:	2300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile**

MATERIAL LOCATION: **Café**

MATERIAL QUANTITY: **2300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Café**

MATERIAL QUANTITY: **2300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile**

MATERIAL LOCATION: **Café**

MATERIAL QUANTITY: **2300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Café		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile**

MATERIAL LOCATION: **Café**

MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Café**

MATERIAL QUANTITY: **100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile**

MATERIAL LOCATION: **Café**

MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	Tan Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Art Room**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Tan Linoleum**

MATERIAL LOCATION: **Basement Art Room**

MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Gary School** INSPECTION DATE: **4/4/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **Adhesive w/ Tan Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Art Room**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Adhesive w/ Tan Linoleum**

MATERIAL LOCATION: **Basement Art Room**

MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	Brown Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1972 Annex Classrooms		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **Brown Carpet Adhesive**

MATERIAL LOCATION: **1972 Annex Classrooms**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8A		
MATERIAL DESCRIPTION:	9"x9" Tan w/Ye, Blue, and White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 100 in 1909 Building**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8A**

MATERIAL DESCRIPTION: **9"x9" Tan w/Ye, Blue, and White Floor Tile Mastic**

MATERIAL LOCATION: **Room 100 in 1909 Building**

MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8B		
MATERIAL DESCRIPTION:	9"x9" Tan Floor Tile w/Brown and White Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Faculty Washroom by Room 100 and Room 208 of 1909 Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8B**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile w/Brown and White Mastic**

MATERIAL LOCATION: **Faculty Washroom by Room 100 and Room 208 of 1909 Building**

MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8C		
MATERIAL DESCRIPTION:	9"x9" Brown Floor Tile w/White and Red Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Faculty Washroom and Room 208 of 1909 Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8C**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile w/White and Red Mastic**

MATERIAL LOCATION: **Faculty Washroom and Room 208 of 1909 Building**

MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8D		
MATERIAL DESCRIPTION:	9" x 9" Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 104 of 1909 Building**

MATERIAL QUANTITY: **250**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8D**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 104 of 1909 Building**

MATERIAL QUANTITY:	<b>250</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8E		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **50**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Gary School	REVIEW DATE:	4/28/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

HOMOGENEOUS AREA: 8E

MATERIAL DESCRIPTION: 9" x 9" Black Floor Tile Mastic

MATERIAL LOCATION: Faculty Washroom of 1909 Building

MATERIAL QUANTITY: 50

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8F		
MATERIAL DESCRIPTION:	9" x 9" Maroon Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **20**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8F**

MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile Mastic**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8G		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 208 of 1909 Building**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8G**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Room 208 of 1909 Building**

MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8H		
MATERIAL DESCRIPTION:	9" x 9" Green Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 204 Of 1909 Building**

MATERIAL QUANTITY: **400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8H**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**

MATERIAL LOCATION: **Room 204 of 1909 Building**

MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8I		
MATERIAL DESCRIPTION:	9" x 9" Aqua Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 301 of 1909 Building**

MATERIAL QUANTITY: **415**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8I**

MATERIAL DESCRIPTION: **9" x 9" Aqua Floor Tile Mastic**

MATERIAL LOCATION: **Room 301 of 1909 Building**

MATERIAL QUANTITY:	<b>415</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8J		
MATERIAL DESCRIPTION:	9" x 9" Aqua Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 301 of 1909 Building**

MATERIAL QUANTITY: **40**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8J**

MATERIAL DESCRIPTION: **9" x 9" Aqua Floor Tile Mastic**

MATERIAL LOCATION: **Room 301 of 1909 Building**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8K		
MATERIAL DESCRIPTION:	9" x 9" Yellow Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 301 of 1909 Building**

MATERIAL QUANTITY: **40**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8K**

MATERIAL DESCRIPTION: **9" x 9" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **Room 301 of 1909 Building**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8L	
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Gym of 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8L**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8M	
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Gym of 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **8M**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9A		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/ Brown Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 005 of 1909 Building**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **9A**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brown Streaks Mastic**

MATERIAL LOCATION: **Room 005 of 1909 Building**

MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9B		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **101**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **9B**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic**

MATERIAL LOCATION: **101**

MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9C		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **206**

MATERIAL QUANTITY: **700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **9C**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic**

MATERIAL LOCATION: **206**

MATERIAL QUANTITY:	<b>700</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9D		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **301**

MATERIAL QUANTITY: **700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **9D**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **301**

MATERIAL QUANTITY:	<b>700</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Gary School** INSPECTION DATE: **4/4/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A2**  
MATERIAL DESCRIPTION: **Cementitious Insulation on Joints off Fiberglass**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **350**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **A2**

MATERIAL DESCRIPTION: **Cementitious Insulation on Joints off Fiberglass**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY:	<b>350</b>	MATERIAL UNITS:	<b>LF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B1		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1909 Building		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **B1**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Gary School** INSPECTION DATE: **4/4/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B2**  
MATERIAL DESCRIPTION: **Cementitious Insulation off Paper Wrap Pipe Runs**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1909 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **B2**

MATERIAL DESCRIPTION: **Cementitious Insulation off Paper Wrap Pipe Runs**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>LF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Gary School** INSPECTION DATE: **4/4/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D1**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:



Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

---

HOMOGENEOUS AREA: **D1**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>LF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)


LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile		
MATERIAL LOCATION:	N, S, E, W Corridor Entrances, Rooms 401-412		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

HOMOGENEOUS AREA:	<b>89</b>				
MATERIAL DESCRIPTION:	<b>2' x 4' Ceiling Tile</b>				
MATERIAL LOCATION:	<b>N, S, E, W Corridor Entrances, Rooms 401-412</b>				
MATERIAL QUANTITY:	<b>7500</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	87				
MATERIAL DESCRIPTION:	Mastic Associated w/ 12" x 12" Beige Floor Tile				
MATERIAL LOCATION:	Room 104				
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Gary School** REVIEW DATE: **4/28/2016**  
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)


LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	Vinyl Sheeting Glued on Plywood		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Vinyl Sheeting Glued on Plywood**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)


LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Steven Doran		
SCHOOL NAME:	Gary School	INSPECTION DATE:	4/4/2016		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-02865		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile		
MATERIAL LOCATION:	Room 104		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2016

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23311</b>	BUILDING ID:	<b>3520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Gary School</b>	REVIEW DATE:	<b>4/28/2016</b>		
ADDRESS:	<b>3740 W. 31st St.</b>	IDPH LICENSE NO:	<b>100-02865</b>		

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **04/28/2016**

# APPENDIX B

## Inspector and Management Planner Licenses

---

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Abatement Supervisor Refresher

Occupational Training & Supply, Inc. certifies that

**Steven Doran**


has successfully completed the Asbestos Abatement Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/13/2015

Exam Date: 4/13/2015

Expiration Date: 4/13/2016

Certificate Number: ASR1504131973

  
Kathy DeSalvo, Director



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
100 - 02865

ISSUED  
5/4/2015

EXPIRES  
05/15/2016

**STEVEN DORAN**  
3340 MAPLE ST.  
EVERGREEN PARK, IL 60805

Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

2/14/2016

MANAGEMENT PLANNER

5/1/2015

PROJECT MANAGER

3/31/2015

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action.**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that STEVEN DORAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/14/2015 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools.  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/14/2015

Course Dates:

02/14/2016

Expires:

1502BIR12

Certificate Number:



*Handwritten signature*

Phone: 312-491-0081

Director of Training

Nicholas J. Penoff



Doctor of Public Health

FORM # A-010B



## Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW  
CONIBEAR**

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed