

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2254
SCHOOL NAME: Healy School
ADDRESS OF SCHOOL: 3010 S. Parnell
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/13/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/8/2016 ENROLLMENT 1492
IDPH INSPECTOR LICENSE NUMBER: 100-09969
IDPH LICENSED INSPECTOR NAME (Please Print): Dionne Carey
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/8/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Healy School

3010 S. Parnell
Chicago, IL, 60616

Unit: 23651
Building ID: 3880

IDPH ID Number: 14-016-2990-2254

REPORT DATE:

Wednesday, June 08, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 10, 2016

RE: Healy School, Unit 23651
3010 S. Parnell
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Healy School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Healy School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Healy School
Address: 3010 S. Parnell
IDPH ID: 14-016-2990-2254
Contact: Molina, Angel

Unit: 23651
Chicago, IL, 60616
Building ID: 3880
Phone: 708-507-1310

Region: 04

2. Description of Facility

Original Construction: 1993
Total Square Footage:
Current Occupancy: 1492

Additional Construction: 1962
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Dionne Carey

Inspector IDPH license # 100-09969

Signature:

Date: 5/10/2016



6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:

Date: 06/08/2016

7. Review Date: 06/08/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/8/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Healy School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3880:

81	Vibration Damper
82	Duct Cornering
H	Pipe Insulation

B. The following new homogenous areas have been identified for Building 3880:

- | | |
|----|------------------|
| 81 | Vibration Damper |
| 82 | Duct Cornering |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

035	Mastic Associated With Carpeting
036	Brown Mop Board
036 A	Brown Mop Board Mastic
037	Black Mop Board
037 A	Black Mop Board Mastic
038	Exterior Window Caulk - Non AHERA
039	Exterior Expansion Joint - Non AHERA
040	Dark Brown Exterior Brick - Not AHERA
041	Brown Exterior Brick - Not AHERA
042	Tan Exterior Brick - Not AHERA
043	Cream Brick w/Black Speckles - Not AHERA
044	Brick Mortar - Not AHERA
045	Chimney Flashing - Not AHERA
046	Exterior Window Glaze - Not AHERA
049	12" x 12" White w/Gray Specks Floor Tile
050	12" x 12" White w/Gray Specks Floor Tile Mastic
051	12" x 12" Burnt Orange Floor Tile
052	12" x 12" Burnt Orange Floor Tile Mastic
053	Dark Gray Carpet Adhesive
054	12" x 12" Blue Floor Tile
055	12" x 12" Blue Floor Tile Mastic
056	12" x 12" Yellow Floor Tile
057	12" x 12" Yellow Floor Tile Mastic
059	12"x12" Gray Mablign Mix Floor Tile
060	12"x12" Gray Mablign Mix Floor Tile Mastic
061	12"x12" Peach Floor Tile
062	12"x12" Peach Floor Tile Mastic
063	12"x12" White w/Gray Floor Tile
064	12"x12" White w/Gray Floor Tile Mastic
065	12"x12" Grey w/Grey Speckles Floor Tile
066	12"x12" Grey w/Grey Speckles Floor Tile Mastic
067	12"x12" Brown w/White Floor Tile
068	12"x12" Brown w/White Floor Tile Mastic
069	Grey Baseboard
070	Grey Baseboard Adhesive
071	Brown Baseboard
072	Brown Baseboard Adhesive
073	9"x9" White w/Brown Floor Tile
074	9"x9" White w/Brown Floor Tile Mastic
58	Insulation inside of Vault Door
75	12"x12" Light Brown VFT
76	12"x12" Light Brown VFT Mastic

77	12"x12" White w/Multicolored Speckle VFT
78	12"x12" White w/Multicolored Speckle VFT Mastic
79	12"x12" White w/Blue Speckles VFT
80	12"x12" White w/Blue Speckles VFT Mastic
81	Vibration Damper
82	Duct Cornering

The following areas were deemed to be inaccessible:

001 A	12"x12" Brown VFT w/Brown & White Streaks Mastic
002 A	9"x9" Gray Floor Tile w/ White Streaks Mastic
003 A	9"x9" Beige Floor Tile w/White & Blue Strks Mastic
004 A	9"x9" Tan Floor Tile w/White & Brn Streaks Mastic
005 A	9"x9" Green Floor Tile w/White & Blk Strks Mastic
006A	12"x12" Lt. Brn VFT w/Dk Brn & Wht. Marble Mastic
007 A	12"x12" Cream VFT w/Tan & Brown Marbling Mastic
008 A	9"x9" White VFT w/Black & Gray Streaks Mastic
009 A	9"x9" Red Floor Tile w/White Streaks Mastic
010 A	12"x12" White VFT w/Black & Gray Streaks Mastic
012 A	9"x9" Cream Floor Tile w/Red & Black Strks Mastic
036 A	Brown Mop Board Mastic
037 A	Black Mop Board Mastic
050	12" x 12" White w/Gray Specks Floor Tile Mastic
052	12" x 12" Burnt Orange Floor Tile Mastic
055	12" x 12" Blue Floor Tile Mastic
057	12" x 12" Yellow Floor Tile Mastic
060	12"x12" Gray Marbling Mix Floor Tile Mastic
062	12"x12" Peach Floor Tile Mastic
064	12"x12" White w/Gray Floor Tile Mastic
066	12"x12" Grey w/Grey Speckles Floor Tile Mastic
068	12"x12" Brown w/White Floor Tile Mastic
070	Grey Baseboard Adhesive
072	Brown Baseboard Adhesive
074	9"x9" White w/Brown Floor Tile Mastic
58	Insulation inside of Vault Door
76	12"x12" Light Brown VFT Mastic
78	12"x12" White w/Multicolored Speckle VFT Mastic
80	12"x12" White w/Blue Speckles VFT Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey, IDPH License # 100-09969. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Healy School Building 3880 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	12"x12" Brown VFT w/Brown & White Streaks	1,475	SF	Engineer's Office, Room 101,209B	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
001 A	12"x12" Brown VFT w/Brown & White Streaks Mastic	1,475	SF	Engineer's Office, Room 101, 209B	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
002	9"x9" Gray Flilor Tile w/ White Streaks	445	SF	Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
002 A	9"x9" Gray Flilor Tile w/ White Streaks Mastic	445	SF	Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003	9"x9" Beige Floor Tile w/White & Blue Streaks	200	SF	Security Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003 A	9"x9" Beige Floor Tile w/White & Blue Strks Mastic	200	SF	Security Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
004	9"x9" Tan Floor Tile w/White & Brown Streaks	9,000	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
004 A	9"x9" Tan Floor Tile w/White & Brn Streaks Mastic	9,000	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
005	9"X9" Green Floor Tile w/White & Black Streaks	300	SF	1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
005 A	9"X9" Green Floor Tile w/White & Blk Strks Mastic	300	SF	1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006	12"x12" Lt. Brown VFT w/ Dk Brown & White Marbling	4,100	SF	Kitchen and Rooms 101, 204, and 218	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006A	12"x12" Lt. Brn VFT w/Dk Brn & Wht. Marble Mastic	4,100	SF	Kitchen and Rooms 101,204, and 218	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007	12"x12" Cream Floor Tile w/Tan & Brown	4,100	SF	Kitchen, Teacher's	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Marbling			Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor								potential for damage		
007 A	12"x12" Cream VFT w/Tan & Brown Marbling Mastic	4,100	SF	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008	9"x9" White Floor Tile w/Black & Gray Streaks	2,500	SF	North Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008 A	9"x9" White VFT w/Black & Gray Streaks Mastic	2,500	SF	North Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
009	9"x9" Red Floor Tile w/White Streaks	200	SF	North & South Gym Storage Areas and South Gym Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
009 A	9"x9" Red Floor Tile w/White Streaks Mastic	200	SF	North & South Gym Storage Areas and South Gym Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
010	12"x12" White VFT w/Black & Gray Streaks	2,500	SF	South Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
010 A	12"x12" White VFT w/Black & Gray Streaks Mastic	2,500	SF	South Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
011	9"x9" Blue VFT w/White & Black Streaks			Auditorium	CHR	MISC								
011 A	9"x9" Blue VFT w/White & Black Streaks Mastic			Auditorium	CHR	MISC								
012	9"x9" Cream Floor Tile w/Red & Black Streaks	4,000	SF	Rooms 103, 105, 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
012 A	9"x9" Cream Floor Tile w/Red & Black Strks Mastic	4,000	SF	Rooms 103, 105, 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
035	Mastic Associated With Carpeting			Engineer's Office, Main Office, Teachers Lounge,& Various areas Throughout	ASSUMED	MISC								
036	Brown Mop Board	100	SF	Throughout Bldg, Rms 001, 003, 005, 116 & 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
036 A	Brown Mop Board Mastic	100	SF	Throughout Bldg, Rms 001, 003, 005, 116 & 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
037	Black Mop Board	100	SF	Rms 007 through 102 Auditorium & rm. 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
037 A	Black Mop Board Mastic	100	SF	Rms 007 through 102 Auditorium & rm. 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
038	Exterior Window Caulk - Not AHERA			Exterior of Bldg.	ASSUMED	MISC								
039	Exterior Expansion Joint - Not AHERA			Exterior of Bldg.	ASSUMED	MISC								
040	Dark Brown Exterior Brick - Not AHERA			Exterior of Bldg.	ASSUMED	MISC								
041	Brown Exterior Brick - Not AHERA			Exterior of Bldg.	ASSUMED	MISC								
042	Tan Exterior Brick - Not AHERA			Exterior of Bldg.	ASSUMED	MISC								
043	Cream Brick w/Black Speckles - Not AHERA			Exterior of Bldg.	ASSUMED	MISC								
044	Brick Mortar - Not AHERA			Exterior of Bldg.	ASSUMED	MISC								
045	Chimney Flashing - Not AHERA			Exterior of Bldg.	ASSUMED	MISC								
046	Exterior Window Glaze - Not AHERA			Exterior of Bldg.	ASSUMED	MISC								
047	Plaster	3,000	SF	Gym and Auditorium	CHR	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
048	Transite Ceiling Panels			North Doors, West Doors by Main Office, Engineer's Corridor Door	CHR	MISC								
049	12" x 12" White w/Gray Specks Floor Tile	1,850	SF	Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107A,107B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
050	12" x 12" White w/Gray Specks Floor Tile Mastic	1,300	SF	Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107A,107B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
051	12" x 12" Burnt Orange Floor Tile	2,500	SF	North Stairwell	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
052	12" x 12" Burnt Orange Floor Tile Mastic	2,500	SF	North Stairwell	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
053	Dark Gray Carpet Adhesive			Engineer's Office	ASSUMED	MISC								
054	12" x 12" Blue Floor Tile	5,600	SF	109 A and 1st Floor Hallway	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
055	12" x 12" Blue Floor Tile Mastic	5,600	SF	109 A and 1st Floor Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
056	12" x 12" Yellow Floor Tile	5,000	SF	2nd Floor Hallway and Janitor's Utility Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
057	12" x 12" Yellow Floor Tile Mastic	5,000	SF	2nd Floor Hallway and Janitor's Utility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room										
059	12"x12" Gray Mablign Mix Floor Tile	1,150	SF	Room 107 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
060	12"x12" Gray Mablign Mix Floor Tile Mastic	1,150	SF	Room 107 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
061	12"x12" Peach Floor Tile	300	SF	As Patches in Rooms 101, 103, 105 Washroom, 110 & 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
062	12"x12" Peach Floor Tile Mastic	300	SF	As Patches in Rooms 101, 103, 105 Washroom, 110 & 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
063	12"x12" White w/Gray Floor Tile	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
064	12"x12" White w/Gray Floor Tile Mastic	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
065	12"x12" Grey w/Grey Speckles Floor Tile	1,100	SF	First Floor Men's Room, Washroom and Room 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
066	12"x12" Grey w/Grey Speckles Floor Tile Mastic	1,100	SF	First Floor Men's Room,Washroom and Room 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
067	12"x12" Brown w/White Floor Tile	270	SF	Family Room and Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
068	12"x12" Brown w/White Floor Tile Mastic	270	SF	Family Room and Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
069	Grey Baseboard	1,500	LF	First Floor Hall and Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
070	Grey Baseboard Adhesive	1,500	LF	First Floor Hall and Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
071	Brown Baseboard	6,500	LF	First & Second Floor Classrooms and Second Floor Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
072	Brown Baseboard Adhesive	6,500	LF	First & Second Floor Classrooms and Second Floor Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
073	9"x9" White w/Brown Floor Tile	8	SF	Room 203 (Patch)	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
074	9"x9" White w/Brown Floor Tile Mastic	8	SF	Room 203 (Patch)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Insulation inside of Vault Door	32	SF	Main Office	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
75	12"x12" Light Brown VFT	7,200	SF	Room 200,201,202,206,208,214,216	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	12"x12" Light Brown VFT Mastic	7,200	SF	Room 200,201,202,206,208,214,216	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	12"x12" White w/Multicolored Speckle VFT	1,000	SF	Auditorium Rows	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12"x12" White w/Multicolored Speckle VFT Mastic	1,000	SF	Auditorium Rows	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12"x12" White w/Blue Speckles VFT	900	SF	Room 212	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	12"x12" White w/Blue Speckles VFT Mastic	900	SF	Room 212	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	Vibration Damper	10	SF	2nd Floor Fan Room Above Auditorium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
82	Duct Cornering	25	SF	2nd Floor Fan Room Above Auditorium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
H	Pipe Insulation	1,120	LF	101 and Washroom, Crawl Space - Heating System	CHR	TSI	Y	DIST	560		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	10	HIGH
I	Pipe Insulation Assoc. Elbows			Crawl Space	CHR	TSI								

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date **5/10/2016**

Inspector Name **Dionne Carey**

100-09969

5/15/2017

Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	Not observed in Engineer's Office
001 A	
002	
002 A	
003	
003 A	
004	Not observed in Rooms 210, 212, 215, 218, Kitchen, and Engineer's Office. Could be under 12" floor tile
004 A	Not observed in Rooms 210, 212, 215, 218, Kitchen, and Engineer's Office. Could be under 12" floor tile
005	Not observed in 103/106 and Kitchen
005 A	
006	Not observed in Kitchen
006A	Not observed in kitchen
007	
007 A	
008	
008 A	
009	
009 A	
010	
010 A	
011	Not observed 2016
011 A	Not observed 2016

Chicago Public Schools

School Healy School **Unit** 23651 **Building ID** 3880

Address 3010 S. Parnell **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
012	
012 A	
035	Not observed 2016
036	
036 A	
037	
037 A	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	Not observed 2016
049	
050	
051	
052	
053	Not observed 2016
054	
055	
056	
057	
059	
060	

Chicago Public Schools

School Healy School **Unit** 23651 **Building ID** 3880

Address 3010 S. Parnell **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
061	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	
073	
074	
58	
75	
76	
77	
78	
79	
80	
81	
82	
H	Not observed 2016 - Inaccessible, cannot assess HA
I	Not observed 2016

Chicago Public Schools

School Healy School **Unit** 23651 **Building ID** 3880

Address 3010 S. Parnell **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Healy School

Unit 23651

Building ID 3880

Address 3010 S. Parnell

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	12"x12" Brown VFT w/Brown & White Streaks	1,475	SF	Engineer's Office, Room 101,209B	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
001 A	12"x12" Brown VFT w/Brown & White Streaks Mastic	1,475	SF	Engineer's Office, Room 101, 209B	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
002	9"x9" Gray Flilor Tile w/ White Streaks	445	SF	Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
002 A	9"x9" Gray Flilor Tile w/ White Streaks Mastic	445	SF	Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003	9"x9" Beige Floor Tile w/White & Blue Streaks	200	SF	Security Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003 A	9"x9" Beige Floor Tile w/White & Blue Strks Mastic	200	SF	Security Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
004	9"x9" Tan Floor Tile w/White & Brown Streaks	9,000	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
004 A	9"x9" Tan Floor Tile w/White & Brn Streaks Mastic	9,000	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
005	9"X9" Green Floor Tile w/White & Black Streaks	300	SF	1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
005 A	9"X9" Green Floor Tile w/White & Blk Strks Mastic	300	SF	1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006	12"x12" Lt. Brown VFT w/ Dk Brown & White Marbling	4,100	SF	Kitchen and Rooms 101, 204, and 218	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006A	12"x12" Lt. Brn VFT w/Dk Brn & Wht. Marble Mastic	4,100	SF	Kitchen and Rooms 101,204, and 218	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007	12"x12" Cream Floor Tile w/Tan & Brown Marbling	4,100	SF	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 A	12"x12" Cream VFT w/Tan & Brown Marbling Mastic	4,100	SF	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008	9"x9" White Floor Tile w/Black & Gray Streaks	2,500	SF	North Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008 A	9"x9" White VFT w/Black & Gray Streaks Mastic	2,500	SF	North Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
009	9"x9" Red Floor Tile w/White Streaks	200	SF	North & South Gym Storage Areas and South Gym Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
009 A	9"x9" Red Floor Tile w/White Streaks Mastic	200	SF	North & South Gym Storage Areas and	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Healy School

Unit 23651

Building ID 3880

Address 3010 S. Parnell

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				South Gym Office							
010	12"x12" White VFT w/Black & Gray Streaks	2,500	SF	South Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
010 A	12"x12" White VFT w/Black & Gray Streaks Mastic	2,500	SF	South Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
011	9"x9" Blue VFT w/White & Black Streaks			Auditorium	Chrysotile	MISC					Follow O&M Plan
011 A	9"x9" Blue VFT w/White & Black Streaks Mastic			Auditorium	Chrysotile	MISC					Follow O&M Plan
012	9"x9" Cream Floor Tile w/Red & Black Streaks	4,000	SF	Rooms 103, 105, 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
012 A	9"x9" Cream Floor Tile w/Red & Black Strks Mastic	4,000	SF	Rooms 103, 105, 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
035	Mastic Associated With Carpeting			Engineer's Office, Main Office, Teachers Lounge,& Various areas Throughout	Assumed	MISC					Follow O&M Plan
036	Brown Mop Board	100	SF	Throughout Bldg, Rms 001, 003, 005, 116 & 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
036 A	Brown Mop Board Mastic	100	SF	Throughout Bldg, Rms 001, 003, 005, 116 & 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
037	Black Mop Board	100	SF	Rms 007 through 102 Auditorium & rm. 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
037 A	Black Mop Board Mastic	100	SF	Rms 007 through 102 Auditorium & rm. 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
038	Exterior Window Caulk - Non AHERA			Exterior of Bldg.	Assumed	MISC					
039	Exterior Expansion Joint - Non AHERA			Exterior of Bldg.	Assumed	MISC					
040	Dark Brown Exterior Brick - Not AHERA			Exterior of Bldg.	Assumed	MISC					
041	Brown Exterior Brick - Not AHERA			Exterior of Bldg.	Assumed	MISC					
042	Tan Exterior Brick - Not AHERA			Exterior of Bldg.	Assumed	MISC					
043	Cream Brick w/Black Speckles - Not AHERA			Exterior of Bldg.	Assumed	MISC					
044	Brick Mortar - Not AHERA			Exterior of Bldg.	Assumed	MISC					
045	Chimney Flashing - Not AHERA			Exterior of Bldg.	Assumed	MISC					
046	Exterior Window Glaze - Not AHERA			Exterior of Bldg.	Assumed	MISC					
047	Plaster	3,000	SF	Gym and Auditorium	Chrysotile	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
048	Transite Ceiling Panels			North Doors, West Doors by Main Office, Engineer's Corridor Door	Chrysotile	MISC					Follow O&M Plan
049	12" x 12" White w/Gray Specks Floor Tile	1,850	SF	Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107A,107B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
050	12" x 12" White w/Gray Specks Floor Tile Mastic	1,300	SF	Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107A,107B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Healy School

Unit 23651

Building ID 3880

Address 3010 S. Parnell

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
051	12" x 12" Burnt Orange Floor Tile	2,500	SF	North Stairwell	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
052	12" x 12" Burnt Orange Floor Tile Mastic	2,500	SF	North Stairwell	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
053	Dark Gray Carpet Adhesive			Engineer's Office	Assumed	MISC					Follow O&M Plan
054	12" x 12" Blue Floor Tile	5,600	SF	109 A and 1st Floor Hallway	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
055	12" x 12" Blue Floor Tile Mastic	5,600	SF	109 A and 1st Floor Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
056	12" x 12" Yellow Floor Tile	5,000	SF	2nd Floor Hallway and Janitor's Utility Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
057	12" x 12" Yellow Floor Tile Mastic	5,000	SF	2nd Floor Hallway and Janitor's Utility Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
059	12"x12" Gray Mablmg Mix Floor Tile	1,150	SF	Room 107 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
060	12"x12" Gray Mablmg Mix Floor Tile Mastic	1,150	SF	Room 107 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
061	12"x12" Peach Floor Tile	300	SF	As Patches in Rooms 101, 103, 105 Washroom, 110 & 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
062	12"x12" Peach Floor Tile Mastic	300	SF	As Patches in Rooms 101, 103, 105 Washroom, 110 & 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
063	12"x12" White w/Gray Floor Tile	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
064	12"x12" White w/Gray Floor Tile Mastic	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
065	12"x12" Grey w/Grey Speckles Floor Tile	1,100	SF	First Floor Men's Room, Washroom and Room 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
066	12"x12" Grey w/Grey Speckles Floor Tile Mastic	1,100	SF	First Floor Men's Room,Washroom and Room 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
067	12"x12" Brown w/White Floor Tile	270	SF	Family Room and Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
068	12"x12" Brown w/White Floor Tile Mastic	270	SF	Family Room and Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
069	Grey Baseboard	1,500	LF	First Floor Hall and Main Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
070	Grey Baseboard Adhesive	1,500	LF	First Floor Hall and Main Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
071	Brown Baseboard	6,500	LF	First & Second Floor Classrooms and Second Floor Hall	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
072	Brown Baseboard Adhesive	6,500	LF	First & Second Floor Classrooms and Second Floor Hall	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
073	9"x9" White w/Brown Floor Tile	8	SF	Room 203 (Patch)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
074	9"x9" White w/Brown Floor Tile Mastic	8	SF	Room 203 (Patch)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Insulation inside of Vault Door	32	SF	Main Office	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
75	12"x12" Light Brown VFT	7,200	SF	Room 200,201,202,206,208,214,216	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Healy School

Unit 23651

Building ID 3880

Address 3010 S. Parnell

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
76	12"x12" Light Brown VFT Mastic	7,200	SF	Room 200,201,202,206,208,214,216	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	12"x12" White w/Multicolored Speckle VFT	1,000	SF	Auditorium Rows	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12"x12" White w/Multicolored Speckle VFT Mastic	1,000	SF	Auditorium Rows	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12"x12" White w/Blue Speckles VFT	900	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12"x12" White w/Blue Speckles VFT Mastic	900	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Vibration Damper	10	SF	2nd Floor Fan Room Above Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	Duct Cornering	25	SF	2nd Floor Fan Room Above Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Pipe Insulation	1,120	LF	101 and Washroom, Crawl Space - Heating System	Chrysotile	TSI	Yes	560	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
I	Pipe Insulation Assoc. Elbows			Crawl Space	Chrysotile	TSI					Follow O&M Plan

Chicago Public Schools

School Healy School

Unit 23651

Building ID 3880

Address 3010 S. Parnell

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	6/8/2016
Manager Planner Name	Evan Christian
100-19466	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	If identified follow O&M plan.
001 A	
002	
002 A	
003	
003 A	
004	If identified follow O&M plan.
004 A	If identified follow O&M plan.
005	If identified follow O&M plan.
005 A	
006	If identified follow O&M plan.
006A	If identified follow O&M plan.
007	
007 A	
008	
008 A	
009	
009 A	
010	
010 A	
011	If identified follow O&M plan.
011 A	If identified follow O&M plan.
012	
012 A	
035	If identified follow O&M plan.
036	

Chicago Public Schools

School Healy School

Unit 23651

Building ID 3880

Address 3010 S. Parnell

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
036 A	
037	
037 A	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	If identified follow O&M plan.
049	
050	
051	
052	
053	If identified follow O&M plan.
054	
055	
056	
057	
059	
060	
061	
062	

Chicago Public Schools

School Healy School

Unit 23651

Building ID 3880

Address 3010 S. Parnell

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	
073	
074	
58	
75	
76	
77	
78	
79	
80	
81	
82	
H	If identified follow O&M plan.
I	If identified follow O&M plan.

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	001		
MATERIAL DESCRIPTION:	12"x12" Brown VFT w/Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Room 101,209B**

MATERIAL QUANTITY: **1475**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Engineer's Office**

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	001		
MATERIAL DESCRIPTION:	12"x12" Brown VFT w/Brown & White Streaks		
MATERIAL LOCATION:	Engineer's Office, Room 101,209B		
MATERIAL QUANTITY:	1475	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001 A**
MATERIAL DESCRIPTION: **12"x12" Brown VFT w/Brown & White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Room 101, 209B**

MATERIAL QUANTITY: **1475**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	001 A		
MATERIAL DESCRIPTION:	12"x12" Brown VFT w/Brown & White Streaks Mastic		
MATERIAL LOCATION:	Engineer's Office, Room 101, 209B		
MATERIAL QUANTITY:	1475	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	002		
MATERIAL DESCRIPTION:	9"x9" Gray Floor Tile w/ White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm**

MATERIAL QUANTITY: **445**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	002				
MATERIAL DESCRIPTION:	9"x9" Gray Floor Tile w/ White Streaks				
MATERIAL LOCATION:	Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm				
MATERIAL QUANTITY:	445	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	002 A		
MATERIAL DESCRIPTION:	9"x9" Gray Floor Tile w/ White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm**

MATERIAL QUANTITY: **445**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	002 A				
MATERIAL DESCRIPTION:	9"x9" Gray Floor Tile w/ White Streaks Mastic				
MATERIAL LOCATION:	Room 103, Engineers Corridor, 1st & 2nd Flr Teacher's Washrooms, 1st Floor Men's Room & Computer Rm				
MATERIAL QUANTITY:	445	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	003		
MATERIAL DESCRIPTION:	9"x9" Beige Floor Tile w/White & Blue Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Security Office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	003				
MATERIAL DESCRIPTION:	9"x9" Beige Floor Tile w/White & Blue Streaks				
MATERIAL LOCATION:	Security Office				
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	003 A		
MATERIAL DESCRIPTION:	9"x9" Beige Floor Tile w/White & Blue Strks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Security Office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **003 A**

MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile w/White & Blue Strks Mastic**

MATERIAL LOCATION: **Security Office**

MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	004		
MATERIAL DESCRIPTION:	9"x9" Tan Floor Tile w/White & Brown Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.**

MATERIAL QUANTITY: **9000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 210, 212, 215, 218, Kitchen, and Engineer's Office. Could be under 12" floor tile**

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	004				
MATERIAL DESCRIPTION:	9"x9" Tan Floor Tile w/White & Brown Streaks				
MATERIAL LOCATION:	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.				
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004 A**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile w/White & Brn Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.**

MATERIAL QUANTITY: **9000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rooms 210, 212, 215, 218, Kitchen, and Engineer's Office. Could be under 12" floor tile**

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	004 A				
MATERIAL DESCRIPTION:	9"x9" Tan Floor Tile w/White & Brn Streaks Mastic				
MATERIAL LOCATION:	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.				
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	005		
MATERIAL DESCRIPTION:	9"X9" Green Floor Tile w/White & Black Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in 103/106 and Kitchen		

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	005		
MATERIAL DESCRIPTION:	9"X9" Green Floor Tile w/White & Black Streaks		
MATERIAL LOCATION:	1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	005 A		
MATERIAL DESCRIPTION:	9"X9" Green Floor Tile w/White & Blk Strks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **005 A**

MATERIAL DESCRIPTION: **9"X9" Green Floor Tile w/White & Blk Strks Mastic**

MATERIAL LOCATION: **1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall**

MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **12"x12" Lt. Brown VFT w/ Dk Brown & White Marbling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen and Rooms 101, 204, and 218**

MATERIAL QUANTITY: **4100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Kitchen**

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	006		
MATERIAL DESCRIPTION:	12"x12" Lt. Brown VFT w/ Dk Brown & White Marbling		
MATERIAL LOCATION:	Kitchen and Rooms 101, 204, and 218		
MATERIAL QUANTITY:	4100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006A		
MATERIAL DESCRIPTION:	12"x12" Lt. Brn VFT w/Dk Brn & Wht. Marble Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen and Rooms 101,204, and 218**

MATERIAL QUANTITY: **4100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in kitchen**

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **006A**

MATERIAL DESCRIPTION: **12"x12" Lt. Brn VFT w/Dk Brn & Wht. Marble Mastic**

MATERIAL LOCATION: **Kitchen and Rooms 101,204, and 218**

MATERIAL QUANTITY: **4100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007		
MATERIAL DESCRIPTION:	12"x12" Cream Floor Tile w/Tan & Brown Marbling		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor**

MATERIAL QUANTITY: **4100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	007				
MATERIAL DESCRIPTION:	12"x12" Cream Floor Tile w/Tan & Brown Marbling				
MATERIAL LOCATION:	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor				
MATERIAL QUANTITY:	4100	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 A**
MATERIAL DESCRIPTION: **12"x12" Cream VFT w/Tan & Brown Marbling Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor**

MATERIAL QUANTITY: **4100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	007 A				
MATERIAL DESCRIPTION:	12"x12" Cream VFT w/Tan & Brown Marbling Mastic				
MATERIAL LOCATION:	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor				
MATERIAL QUANTITY:	4100	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	008		
MATERIAL DESCRIPTION:	9"x9" White Floor Tile w/Black & Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	008		
MATERIAL DESCRIPTION:	9"x9" White Floor Tile w/Black & Gray Streaks		
MATERIAL LOCATION:	North Gym		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	008 A		
MATERIAL DESCRIPTION:	9"x9" White VFT w/Black & Gray Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **008 A**

MATERIAL DESCRIPTION: **9"x9" White VFT w/Black & Gray Streaks Mastic**

MATERIAL LOCATION: **North Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	009		
MATERIAL DESCRIPTION:	9"x9" Red Floor Tile w/White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	North & South Gym Storage Areas and South Gym Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	009		
MATERIAL DESCRIPTION:	9"x9" Red Floor Tile w/White Streaks		
MATERIAL LOCATION:	North & South Gym Storage Areas and South Gym Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009 A**
MATERIAL DESCRIPTION: **9"x9" Red Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North & South Gym Storage Areas and South Gym Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	009 A		
MATERIAL DESCRIPTION:	9"x9" Red Floor Tile w/White Streaks Mastic		
MATERIAL LOCATION:	North & South Gym Storage Areas and South Gym Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	010		
MATERIAL DESCRIPTION:	12"x12" White VFT w/Black & Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	010		
MATERIAL DESCRIPTION:	12"x12" White VFT w/Black & Gray Streaks		
MATERIAL LOCATION:	South Gym		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	010 A		
MATERIAL DESCRIPTION:	12"x12" White VFT w/Black & Gray Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **010 A**

MATERIAL DESCRIPTION: **12"x12" White VFT w/Black & Gray Streaks Mastic**

MATERIAL LOCATION: **South Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	011	
MATERIAL DESCRIPTION:	9"x9" Blue VFT w/White & Black Streaks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **011**

MATERIAL DESCRIPTION: **9"x9" Blue VFT w/White & Black Streaks**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011 A**
MATERIAL DESCRIPTION: **9"x9" Blue VFT w/White & Black Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **011 A**

MATERIAL DESCRIPTION: **9"x9" Blue VFT w/White & Black Streaks Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	012		
MATERIAL DESCRIPTION:	9"x9" Cream Floor Tile w/Red & Black Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103, 105, 106		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	012				
MATERIAL DESCRIPTION:	9"x9" Cream Floor Tile w/Red & Black Streaks				
MATERIAL LOCATION:	Rooms 103, 105, 106				
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012 A**
MATERIAL DESCRIPTION: **9"x9" Cream Floor Tile w/Red & Black Strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 103, 105, 106**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **012 A**

MATERIAL DESCRIPTION: **9"x9" Cream Floor Tile w/Red & Black Strks Mastic**

MATERIAL LOCATION: **Rooms 103, 105, 106**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **Mastic Associated With Carpeting**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office, Main Office, Teachers Lounge, & Various areas Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	035
MATERIAL DESCRIPTION:	Mastic Associated With Carpeting
MATERIAL LOCATION:	Engineer's Office, Main Office, Teachers Lounge,& Various areas Throughout
MATERIAL QUANTITY:	MATERIAL UNITS:
DAMAGE QUANTITY:	DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	036		
MATERIAL DESCRIPTION:	Brown Mop Board		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Bldg, Rms 001, 003, 005, 116 & 208**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	036		
MATERIAL DESCRIPTION:	Brown Mop Board		
MATERIAL LOCATION:	Throughout Bldg, Rms 001, 003, 005, 116 & 208		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036 A**
MATERIAL DESCRIPTION: **Brown Mop Board Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Bldg, Rms 001, 003, 005, 116 & 208**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **036 A**

MATERIAL DESCRIPTION: **Brown Mop Board Mastic**

MATERIAL LOCATION: **Throughout Bldg, Rms 001, 003, 005, 116 & 208**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	037		
MATERIAL DESCRIPTION:	Black Mop Board		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rms 007 through 102 Auditorium & rm. 100		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	037		
MATERIAL DESCRIPTION:	Black Mop Board		
MATERIAL LOCATION:	Rms 007 through 102 Auditorium & rm. 100		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	037 A		
MATERIAL DESCRIPTION:	Black Mop Board Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rms 007 through 102 Auditorium & rm. 100		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **037 A**

MATERIAL DESCRIPTION: **Black Mop Board Mastic**

MATERIAL LOCATION: **Rms 007 through 102 Auditorium & rm. 100**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **Exterior Window Caulk - Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **038**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Non AHERA**

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **Exterior Expansion Joint - Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **039**

MATERIAL DESCRIPTION: **Exterior Expansion Joint - Non AHERA**

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **Dark Brown Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **040**

MATERIAL DESCRIPTION: **Dark Brown Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **Brown Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **041**

MATERIAL DESCRIPTION: **Brown Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **Tan Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **042**

MATERIAL DESCRIPTION: **Tan Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **Cream Brick w/Black Speckles - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **043**

MATERIAL DESCRIPTION: **Cream Brick w/Black Speckles - Not AHERA**

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **044**

MATERIAL DESCRIPTION: **Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Chimney Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **045**

MATERIAL DESCRIPTION: **Chimney Flashing - Not AHERA**

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Exterior Window Glaze - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **046**

MATERIAL DESCRIPTION: **Exterior Window Glaze - Not AHERA**

MATERIAL LOCATION: **Exterior of Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym and Auditorium**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	047		
MATERIAL DESCRIPTION:	Plaster		
MATERIAL LOCATION:	Gym and Auditorium		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **Transite Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Doors, West Doors by Main Office, Engineer's Corridor Door**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	048	
MATERIAL DESCRIPTION:	Transite Ceiling Panels	
MATERIAL LOCATION:	North Doors, West Doors by Main Office, Engineer's Corridor Door	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	049		
MATERIAL DESCRIPTION:	12" x 12" White w/Gray Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107A,107B		
MATERIAL QUANTITY:	1850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	049		
MATERIAL DESCRIPTION:	12" x 12" White w/Gray Specks Floor Tile		
MATERIAL LOCATION:	Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107A,107B		
MATERIAL QUANTITY:	1850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	050		
MATERIAL DESCRIPTION:	12" x 12" White w/Gray Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107A,107B		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	050		
MATERIAL DESCRIPTION:	12" x 12" White w/Gray Specks Floor Tile Mastic		
MATERIAL LOCATION:	Teacher's Lounge, Lunchroom, Main Office, Rooms 207,210,213,107A,107B		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	051		
MATERIAL DESCRIPTION:	12" x 12" Burnt Orange Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	North Stairwell		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	051		
MATERIAL DESCRIPTION:	12" x 12" Burnt Orange Floor Tile		
MATERIAL LOCATION:	North Stairwell		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **12" x 12" Burnt Orange Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Stairwell**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	052		
MATERIAL DESCRIPTION:	12" x 12" Burnt Orange Floor Tile Mastic		
MATERIAL LOCATION:	North Stairwell		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Dark Gray Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **053**

MATERIAL DESCRIPTION: **Dark Gray Carpet Adhesive**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	054		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	109 A and 1st Floor Hallway		
MATERIAL QUANTITY:	5600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	054		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
MATERIAL LOCATION:	109 A and 1st Floor Hallway		
MATERIAL QUANTITY:	5600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	055		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **109 A and 1st Floor Hallway**

MATERIAL QUANTITY: **5600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	055		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic		
MATERIAL LOCATION:	109 A and 1st Floor Hallway		
MATERIAL QUANTITY:	5600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	056		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Hallway and Janitor's Utility Room**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	056		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile		
MATERIAL LOCATION:	2nd Floor Hallway and Janitor's Utility Room		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	057		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Hallway and Janitor's Utility Room		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	057		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile Mastic		
MATERIAL LOCATION:	2nd Floor Hallway and Janitor's Utility Room		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **12"x12" Gray Mablign Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 107 (Library)**

MATERIAL QUANTITY: **1150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	059		
MATERIAL DESCRIPTION:	12"x12" Gray Mablign Mix Floor Tile		
MATERIAL LOCATION:	Room 107 (Library)		
MATERIAL QUANTITY:	1150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	060		
MATERIAL DESCRIPTION:	12"x12" Gray Mablign Mix Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 107 (Library)		
MATERIAL QUANTITY:	1150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	060		
MATERIAL DESCRIPTION:	12"x12" Gray Mablign Mix Floor Tile Mastic		
MATERIAL LOCATION:	Room 107 (Library)		
MATERIAL QUANTITY:	1150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **12"x12" Peach Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **As Patches in Rooms 101, 103, 105 Washroom, 110 & 112**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	061		
MATERIAL DESCRIPTION:	12"x12" Peach Floor Tile		
MATERIAL LOCATION:	As Patches in Rooms 101, 103, 105 Washroom, 110 & 112		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	062		
MATERIAL DESCRIPTION:	12"x12" Peach Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	As Patches in Rooms 101, 103, 105 Washroom, 110 & 112		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	062		
MATERIAL DESCRIPTION:	12"x12" Peach Floor Tile Mastic		
MATERIAL LOCATION:	As Patches in Rooms 101, 103, 105 Washroom, 110 & 112		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	063		
MATERIAL DESCRIPTION:	12"x12" White w/Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B		
MATERIAL QUANTITY:	3050	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	063		
MATERIAL DESCRIPTION:	12"x12" White w/Gray Floor Tile		
MATERIAL LOCATION:	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B		
MATERIAL QUANTITY:	3050	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	064		
MATERIAL DESCRIPTION:	12"x12" White w/Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B		
MATERIAL QUANTITY:	3050	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	064		
MATERIAL DESCRIPTION:	12"x12" White w/Gray Floor Tile Mastic		
MATERIAL LOCATION:	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B		
MATERIAL QUANTITY:	3050	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	065		
MATERIAL DESCRIPTION:	12"x12" Grey w/Grey Speckles Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First Floor Men's Room, Washroom and Room 211**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	065		
MATERIAL DESCRIPTION:	12"x12" Grey w/Grey Speckles Floor Tile		
MATERIAL LOCATION:	First Floor Men's Room, Washroom and Room 211		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	066		
MATERIAL DESCRIPTION:	12"x12" Grey w/Grey Speckles Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First Floor Men's Room, Washroom and Room 211**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	066		
MATERIAL DESCRIPTION:	12"x12" Grey w/Grey Speckles Floor Tile Mastic		
MATERIAL LOCATION:	First Floor Men's Room, Washroom and Room 211		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	067		
MATERIAL DESCRIPTION:	12"x12" Brown w/White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Family Room and Restroom**

MATERIAL QUANTITY: **270**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	067		
MATERIAL DESCRIPTION:	12"x12" Brown w/White Floor Tile		
MATERIAL LOCATION:	Family Room and Restroom		
MATERIAL QUANTITY:	270	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	068		
MATERIAL DESCRIPTION:	12"x12" Brown w/White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Family Room and Restroom**

MATERIAL QUANTITY: **270**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	068		
MATERIAL DESCRIPTION:	12"x12" Brown w/White Floor Tile Mastic		
MATERIAL LOCATION:	Family Room and Restroom		
MATERIAL QUANTITY:	270	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	069		
MATERIAL DESCRIPTION:	Grey Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First Floor Hall and Main Office**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	069		
MATERIAL DESCRIPTION:	Grey Baseboard		
MATERIAL LOCATION:	First Floor Hall and Main Office		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	070		
MATERIAL DESCRIPTION:	Grey Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First Floor Hall and Main Office**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	070		
MATERIAL DESCRIPTION:	Grey Baseboard Adhesive		
MATERIAL LOCATION:	First Floor Hall and Main Office		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	071		
MATERIAL DESCRIPTION:	Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	First & Second Floor Classrooms and Second Floor Hall		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	071		
MATERIAL DESCRIPTION:	Brown Baseboard		
MATERIAL LOCATION:	First & Second Floor Classrooms and Second Floor Hall		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **Brown Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First & Second Floor Classrooms and Second Floor Hall**

MATERIAL QUANTITY: **6500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	072		
MATERIAL DESCRIPTION:	Brown Baseboard Adhesive		
MATERIAL LOCATION:	First & Second Floor Classrooms and Second Floor Hall		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	073		
MATERIAL DESCRIPTION:	9"x9" White w/Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 203 (Patch)		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	073		
MATERIAL DESCRIPTION:	9"x9" White w/Brown Floor Tile		
MATERIAL LOCATION:	Room 203 (Patch)		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **074**
MATERIAL DESCRIPTION: **9"x9" White w/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 203 (Patch)**

MATERIAL QUANTITY: **8**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	074		
MATERIAL DESCRIPTION:	9"x9" White w/Brown Floor Tile Mastic		
MATERIAL LOCATION:	Room 203 (Patch)		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	Insulation inside of Vault Door		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	32	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Insulation inside of Vault Door**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **32**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Healy School** INSPECTION DATE: **5/10/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12"x12" Light Brown VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 200,201,202,206,208,214,216**

MATERIAL QUANTITY: **7200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12"x12" Light Brown VFT**

MATERIAL LOCATION: **Room 200,201,202,206,208,214,216**

MATERIAL QUANTITY: **7200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	12"x12" Light Brown VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 200,201,202,206,208,214,216**

MATERIAL QUANTITY: **7200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12"x12" Light Brown VFT Mastic**

MATERIAL LOCATION: **Room 200,201,202,206,208,214,216**

MATERIAL QUANTITY: **7200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	12"x12" White w/Multicolored Speckle VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Rows		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12"x12" White w/Multicolored Speckle VFT**

MATERIAL LOCATION: **Auditorium Rows**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	12"x12" White w/Multicolored Speckle VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Rows		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12"x12" White w/Multicolored Speckle VFT Mastic**

MATERIAL LOCATION: **Auditorium Rows**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12"x12" White w/Blue Speckles VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 212		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12"x12" White w/Blue Speckles VFT**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	12"x12" White w/Blue Speckles VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12"x12" White w/Blue Speckles VFT Mastic**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:	Water Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:	Water Physical Damage		
DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	101 and Washroom, Crawl Space - Heating System		
MATERIAL QUANTITY:	1120	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	Not observed 2016 - Inaccessible, cannot assess HA		

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Pipe Insulation**

MATERIAL LOCATION: **101 and Washroom, Crawl Space - Heating System**

MATERIAL QUANTITY:	1120	MATERIAL UNITS:	LF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	560	DAMAGE UNITS:	LF
------------------	------------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I	
MATERIAL DESCRIPTION:	Pipe Insulation Assoc. Elbows	
HISTORICAL AHERA DAMAGE CATEGORY	Damaged or significantly damaged friable thermal system insulating ACBM	
HISTORICAL DAMAGE REASON:	Water Physical Damage	
HISTORICAL RESPONSE ACTION:	Remove	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Crawl Space

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Pipe Insulation Assoc. Elbows**

MATERIAL LOCATION: **Crawl Space**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

If identified follow O&M plan.

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	Vibration Damper		
MATERIAL LOCATION:	2nd Floor Fan Room Above Auditorium		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Healy School	REVIEW DATE:	6/8/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Vibration Damper**

MATERIAL LOCATION: **2nd Floor Fan Room Above Auditorium**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **06/08/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23651	BUILDING ID:	3880
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey		
SCHOOL NAME:	Healy School	INSPECTION DATE:	5/10/2016		
ADDRESS:	3010 S. Parnell	IDPH LICENSE NO:	100-09969		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	Duct Cornering		
MATERIAL LOCATION:	2nd Floor Fan Room Above Auditorium		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/10/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE: **6/8/2016**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **Duct Cornering**
MATERIAL LOCATION: **2nd Floor Fan Room Above Auditorium**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **06/08/2016**

APPENDIX B

Inspector and Management Planner Licenses

JAINA ASSOCIATES

THIS IS TO CERTIFY

THAT

DIONNE L. CAREY

HAS SUCCESSFULLY COMPLETED THE SAMPLING AND EVALUATING ASBESTOS AIRBORNE
DUST - NIOSH 582 EQUIVALENT TRAINING COURSE, AND PASSED THE EXAMINATION WITH
A SCORE OF 70% OR ABOVE FOR THE PURPOSE OF CERTIFICATION.

COURSE DATE: May 14 to 17, 2005

EXAM DATE: May 17, 2005

LOCATION: GSG Environmental, Inc.
855 West Adams Street, Suite 200
Chicago, Illinois 60607

DIRECTOR
OF TRAINING:


SANJIV JAIN

CERTIFICATE No.: 05JA-051405
IDPH COURSE PROVIDER No.: 038



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

DIONNE L CAREY WALKER

211 Somerset Drive
Streamwood, IL 60107

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09969

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 09969	ISSUED 4/18/2016	EXPIRES 05/15/2017	INSPECTOR	3/11/2017
DIONNE L CAREY WALKER 211 Somerset Drive Streamwood, IL 60107 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/12/2017
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.



Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES

Nationally Accredited by PHAB

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW
CONIBEAR**

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed