

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2083
SCHOOL NAME: Bennett School
ADDRESS OF SCHOOL: 10115 S. Prairie Avenue
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 3/2/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 310
IDPH INSPECTOR LICENSE NUMBER: 100-19717
IDPH LICENSED INSPECTOR NAME(Please Print): Shaquille Crews
IDPH MP LICENSE NUMBER: 100-00746
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Bennett School

10115 S. Prairie Avenue
Chicago, IL, 60628

Unit: 22241
Building ID: 2280

IDPH ID Number: 14-016-2990-2083

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

Chicago Public Schools
42 West Madison Street
Chicago, IL 60602

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW

August 9, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22241 Region: 06 IDPH ID:14-016-2990-2083

School: Bennett School Building ID: 2280

Address: 10115 S. Prairie Avenue

Chicago, IL, 60628

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/11/2019

Inspector: Shaquille Crews

Inspector IDPH License: 100-19717

Management Planner: Amy Williams

Management Planner IDPH License: 100-00746

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Amy Williams
100-00746

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 09, 2019

RE: Bennett School, Unit 22241
10115 S. Prairie Avenue
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Bennett School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Bennett School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Bennett School	Unit:	22241	Region:	06
Address:	10115 S. Prairie Avenue		Chicago, IL, 60628		
IDPH ID:	14-016-2990-2083	Building ID:	2280		
Contact:		Phone:			

2. Description of Facility

Original Construction:	1928	Additional Construction:	
Total Square Footage:	67595	No of Floors:	3
Current Occupancy:	310		

3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	42 West Madison Street		
	Chicago, IL 60602		

4. Managing Environmental Consultant

MEC:	TEM Environmental, Inc.		
Contact:	Steven Geneser		
Address	174 N. Brandon Drive		
	Glendale Heights, IL, 60139		
Phone:	630-790-0880	Fax:	630-790-0882

5. Inspector

Inspector Name: Shaquille Crews

Inspector IDPH license # 100-19717

Signature:
Date: 8/9/2019

6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license # 100-00746

Signature:
Date: 09/11/2019

7. Review Date:09/11/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bennett School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2280:

15	Blue-Green Carpet Mastic-NOT OBSERVED
E	Aircell Pipe Insulation
G	MJP E/F/V on Fiberglass Pipe Insulation

B. The following new homogenous areas have been identified for Building 2280:

68	12" X 12" Tan w/White Specks Floor Tile
68A	12" X 12" Tan w/White Specks Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05H	12x12 Green w/Cream Streaks Floor Tile
06	Insulation in 6 Steel Fire Rated Doors
07	Boiler Gaskets
08	Incinerator Fire Brick
08A	12x12 Cream w/Tan Floor Tile Mastic
09	12x12 Dark Brown Floor Tile
11	12x12 Tan w/Orange Streaks Floor Tile - NOT OBSERVED
13	12x12 Green w/White Streaks Floor Tile
13A	12x12 Green w/White Streaks Floor Tile Mastic
14	9x9 Cream w/Brown Specks Floor Tile
14A	9x9 Cream w/Brown Specks Floor Tile Mastic
16	Mauve Carpet Mastic
22	Terrazzo Flooring
23	Ceramic Tile Grout
27	Exterior Window Caulk
28	Exterior Window Glazing
46	12x12 Gray w/White Streaks Floor Tile
47	12x12 Gray w/White Streaks Floor Tile Mastic
48	12x12 Cream w/Tan Floor Tile
49	12x12 Cream w/Tan Floor Tile Mastic
50	12x12 Brown w/White Floor Tile
51	12x12 Brown w/White Floor Tile Mastic
52	12 x 12 Tan w/Brown Floor Tile
53	12 x 12 Tan w/Brown Floor Tile Mastic
54	9x9 Peach Floor Tile
55	9x9 Peach Floor Tile Mastic
56	Plaster Walls and Ceilings
57	Green Carpet Mastic
58	Blue Carpet Mastic
59	12" x 12" Yellow Floor Tile
60	12" x 12" Yellow Floor Tile Mastic
61	12" x 12" Blue Floor Tile
62	12" x 12" Blue Floor Tile Mastic
63	Blown in Insulation
64	12x12 White w/Cream Specks Vinyl Floor Tile
65	12x12 White w/Cream Specks Mastic
66	12x12 Tan w/Beige Specks Vinyl Floor Tile
67	12x12 Tan w/Beige specks Mastic
68	12" X 12" Tan w/White Specks Floor Tile
68A	12" X 12" Tan w/White Specks Floor Tile Mastic
C	Cardboard Pipe Insulation

D	MJP E/F/V on Cardboard Pipe Insulation
G	MJP E/F/V on Fiberglass Pipe Insulation
H	Cardboard Pipe Insulation
I	MJP E/F/V on Cardboard Pipe Insulation
J	MJP E/F/V on Aircell Pipe Insulation
K	Aircell Pipe Insulation
L	Rope Pipe Insulation

The following areas were deemed to be inaccessible:

04	9x9 Brown w/White Floor Tile Mastic
05	12x12 Beige w/Brown Speckled Floor Tile Mastic
06	Insulation in 6 Steel Fire Rated Doors
08	Incinerator Fire Brick
08C	12x12 Cream w/Brown & Maroon Specks Floor Tile Mastic
08H	12x12 Green w/Cream Streaks Floor Tile Mastic
10	12x12 Dark Brown Floor Tile Mastic
13A	12x12 Green w/White Streaks Floor Tile Mastic
14	9x9 Cream w/Brown Specks Floor Tile
14A	9x9 Cream w/Brown Specks Floor Tile Mastic
16	Mauve Carpet Mastic
24	Aircell Duct Covers
25A	9x9 Red w/White Streaks Floor Tile Mastic
26A	9x9 Black w/White Streaks Floor Tile Mastic
29	Mag Block Pipe Insulation
47	12x12 Gray w/White Streaks Floor Tile Mastic
49	12x12 Cream w/Tan Floor Tile Mastic
51	12x12 Brown w/White Floor Tile Mastic
53	12 x 12 Tan w/Brown Floor Tile Mastic
55	9x9 Peach Floor Tile Mastic
57	Green Carpet Mastic
58	Blue Carpet Mastic
60	12" x 12" Yellow Floor Tile Mastic
62	12" x 12" Blue Floor Tile Mastic
63	Blown in Insulation
65	12x12 White w/Cream Specks Mastic
67	12x12 Tan w/Beige specks Mastic
68A	12" X 12" Tan w/White Specks Floor Tile Mastic
C	Cardboard Pipe Insulation
D	MJP E/F/V on Cardboard Pipe Insulation
G	MJP E/F/V on Fiberglass Pipe Insulation
I	MJP E/F/V on Cardboard Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Shaquille Crews, IDPH License # 100-19717. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Bennett School Building 2280 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Bennett School Unit 22241 Building ID 2280

Address 10115 S. Prairie Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	12x12 Beige w/Brown Speckled Floor Tile	9,000	SF	1st, 2nd, & 3rd Floor Hallways and Room 102	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
03	9x9 Brown Floor Tile	500	SF	Room 208	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04	9x9 Brown w/White Floor Tile Mastic	500	SF	Room 208	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	12x12 Beige w/Brown Speckled Floor Tile Mastic	9,000	SF	1st, 2nd, & 3rd Floor Hallways and Room 102	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05H	12x12 Green w/Cream Streaks Floor Tile			NOT OBSERVED	ASSUMED	MISC								
06	Insulation in 6 Steel Fire Rated Doors	168	SF	Boiler Room, Assembly Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
07	Boiler Gaskets	100	LF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Incinerator Fire Brick	75	SF	Incinerator in Boiler House	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	12x12 Cream w/Tan Floor Tile Mastic			Remove All - NOT OBSERVED	ASSUMED	MISC								
08C	12x12 Cream w/Brown & Maroon Specks Floor Tile Mastic	1,000	SF	Room 103 and 3rd Floor NE Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08H	12x12 Green w/Cream Streaks Floor Tile Mastic	400	SF	Engineer's Office and Lunch Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12x12 Dark Brown Floor Tile	430	SF	Room 206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
10	12x12 Dark Brown Floor Tile Mastic	430	SF	Room 206	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	12x12 Tan w/Orange Streaks Floor Tile - NOT OBSERVED			Main Office, Store Room, Copy Room & Reception	ASSUMED	MISC								
11A	12x12 Tan w/White Streaks Floor Tile Mastic- NOT OBSERVED			Main Office, Store Room, Copy Room & Reception	CHR	MISC								
12	12x18 Black w/White Streaks Floor Tile- NOT OBSERVED			Room 106/Lunchroom		MISC								
12A	12x18 Black w/White Streaks Floor Tile Mastic-NOT OBSERVED			Room 106/Lunchroom	CHR	MISC								
13	12x12 Green w/White Streaks Floor Tile	3,100	SF	Rooms 111, 112 & Workroom, 211, 212, 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13A	12x12 Green w/White Streaks Floor Tile Mastic	3,100	SF	Rooms 111, 112 & Workroom, 211, 212, 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	9x9 Cream w/Brown Specks Floor Tile	1,800	SF	Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the		MODERATE

Chicago Public Schools

School Bennett School Unit 22241 Building ID 2280

Address 10115 S. Prairie Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				106/Lunchroom and Library (Under Carpet)								potential for damage		
14A	9x9 Cream w/Brown Specks Floor Tile Mastic	1,800	SF	Room 106/Lunchroom and Library (under carpet)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Blue-Green Carpet Mastic-NOT OBSERVED			Assembly Room		MISC					Yes			
16	Mauve Carpet Mastic	600	SF	Principal's Office, Administrative Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Rust Carpet Mastic-NOT OBSERVED			Library (Room 107, Room 109)		MISC								
18	Interior Window Caulk			Basement Windows East & West sides of Boiler Room	NO_ACBM	MISC								
20	Interior Window Glazing			Basement Only	NO_ACBM	MISC								
22	Terrazzo Flooring	2,200	SF	1st, 2nd & 3rd Floor Corridors, Stairs, Landings, and Entryways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
23	Ceramic Tile Grout	2,500	SF	All Restrooms Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Aircell Duct Covers	230	SF	East-West Crawlspace Under Auditorium	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
25	9x9 Red w/White Streaks Floor Tile	700	SF	Engineer's Office West Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
25A	9x9 Red w/White Streaks Floor Tile Mastic	700	SF	Engineer's Office West Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	9x9 Black w/White Streaks Floor Tile	160	SF	Engineer's Office and Restroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
26A	9x9 Black w/White Streaks Floor Tile Mastic	160	SF	Engineer's Office and Restroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Exterior Window Caulk			Field House - Demolished in 2009	ASSUMED	MISC								
28	Exterior Window Glazing			Fieldhouse - Demolished in 2009	ASSUMED	MISC								
29	Mag Block Pipe Insulation	6	LF	Hall Behind Fans 3 and 4	AMO	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
46	12x12 Gray w/White Streaks Floor Tile	1,600	SF	Rooms 104 and 210, Boiler Room,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Bennett School Unit 22241 Building ID 2280

Address 10115 S. Prairie Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Storage Room										
47	12x12 Gray w/White Streaks Floor Tile Mastic	1,600	SF	Rooms 104 and 210, Boiler Room, Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12x12 Cream w/Tan Floor Tile	1,200	SF	Room 101 and Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
49	12x12 Cream w/Tan Floor Tile Mastic	1,200	SF	Room 101 and Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12x12 Brown w/White Floor Tile	540	SF	Room 101	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51	12x12 Brown w/White Floor Tile Mastic	540	SF	Room 101	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12 x 12 Tan w/Brown Floor Tile	2,200	SF	Rooms 111, 112, 206, 211, 212, and 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53	12 x 12 Tan w/Brown Floor Tile Mastic	2,200	SF	Rooms 111, 112, 206, 211, 212, and 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	9x9 Peach Floor Tile	45	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
55	9x9 Peach Floor Tile Mastic	45	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Plaster Walls and Ceilings	100,000	SF	Throughout Facility	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
57	Green Carpet Mastic	500	SF	Room 302	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Blue Carpet Mastic	2,500	SF	Room 202 - Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	12" x 12" Yellow Floor Tile	320	SF	Assembly Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
60	12" x 12" Yellow Floor Tile Mastic	320	SF	Assembly Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	12" x 12" Blue Floor Tile	2,000	SF	Assembly Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
62	12" x 12" Blue Floor Tile Mastic	2,000	SF	Assembly Rom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Blown in Insulation	6,000	SF	Attic	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
64	12x12 White w/Cream Specks Vinyl Floor Tile	2,300	SF	Room 103 (Kitchen), 106 (Lunchroom), 111, 112, 113, 206, Lunch Manager's	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Bennett School Unit 22241 Building ID 2280

Address 10115 S. Prairie Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Office, Asst. Engineer's Off.										
65	12x12 White w/Cream Specks Mastic	2,300	SF	Room 103 (Kitchen), 106 (Lunchroom), 111, 112, 113, 206, Lunch Room Manager Office, Asst. Engineer's Off.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	12x12 Tan w/Beige Specks Vinyl Floor Tile	150	SF	Main Office Waiting Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
67	12x12 Tan w/Beige specks Mastic	150	SF	Main Office Waiting Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12" X 12" Tan w/White Specks Floor Tile	900	SF	Main Office, Storeroom, Copy Room, Reception	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68A	12" X 12" Tan w/White Specks Floor Tile Mastic	900	SF	Main Office, Store Room, Copy Room, Reception Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	Cardboard Pipe Insulation	800	LF	Boiler Room, Pump Room, Fan Rooms, Pipe Chases, Air Tunnels	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	MJP E/F/V on Cardboard Pipe Insulation	28	FITTING	Pump Room, Fan Rooms, Pipe Chases, Air Tunnels	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Aircell Pipe Insulation	3,294	LF	Boiler Rm., Pump Room, Air Tunnel, Valve Room, Pipe Chases, Fan Rooms	CHR	TSI	Y	LOC	3		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
F	MJP E/F/V on Aircell Pipe Insulation	180	FITTING	Boiler Room, Pump Room, Air Tunnel, Pipe Chases, Crawl Space, Fan Rooms	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	MJP E/F/V on Fiberglass Pipe Insulation	90	FITTING	Boiler Room, Pump Room and Tunnel	ASSUMED	TSI	Y	LOC	10		Yes	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
H	Cardboard Pipe Insulation	200	LF	Crawlspace	ASSUMED	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	MJP E/F/V on Cardboard Pipe Insulation	16	LF	Crawlspace	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Bennett School **Unit** 22241 **Building ID** 2280

Address 10115 S. Prairie Avenue **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
J	MJP E/F/V on Aircell Pipe Insulation	14	LF	Crawlspaces Throughout 1951 & 1927 Buildings	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		LOW
K	Aircell Pipe Insulation	250	LF	Crawlspaces Throughout 1957 & 1927 Buildings	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		LOW
L	Rope Pipe Insulation	40	LF	Fan Rooms	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		MODERATE

Chicago Public Schools

School Bennett School Unit 22241 Building ID 2280

Address 10115 S. Prairie Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	8/9/2019
Inspector Name	<u>Shaquille Crews</u>
<u>100-19717</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
02	
03	
04	
05	
05H	Not Observed 2019
06	
07	
08	
08A	Not Observed 2019
08C	
08H	
09	
10	
11	Not Observed Multiple Years
11A	Not Observed Multiple Years
12	Not Observed - Area is HA 64 & 65
12A	Not Observed - Area is HA 64 & 65
13	
13A	
14	Not Observed 2019
14A	Not Observed 2019
15	Not Observed 2019
16	

Chicago Public Schools

School Bennett School **Unit** 22241 **Building ID** 2280

Address 10115 S. Prairie Avenue **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
17	Not Observed Multiple Years
18	
20	
22	
23	
24	
25	
25A	
26	
26A	
27	Field House Demolished in 2009
28	Field House Demolished in 2009
29	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	

Chicago Public Schools

School Bennett School **Unit** 22241 **Building ID** 2280

Address 10115 S. Prairie Avenue **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
62	
63	
64	
65	
66	
67	
68	
68A	
C	
D	
E	
F	
G	Damage in Tank Rm
H	
I	
J	
K	
L	

Table II

Management Planner's Review

Chicago Public Schools

School Bennett School
Address 10115 S. Prairie Avenue

Unit 22241
Chicago, IL, 60628

Building ID 2280
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	12x12 Beige w/Brown Speckled Floor Tile	9,000	SF	1st, 2nd, & 3rd Floor Hallways and Room 102	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	9x9 Brown Floor Tile	500	SF	Room 208	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9x9 Brown w/White Floor Tile Mastic	500	SF	Room 208	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12x12 Beige w/Brown Speckled Floor Tile Mastic	9,000	SF	1st, 2nd, & 3rd Floor Hallways and Room 102	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05H	12x12 Green w/Cream Streaks Floor Tile			NOT OBSERVED	Assumed	MISC					
06	Insulation in 6 Steel Fire Rated Doors	168	SF	Boiler Room, Assembly Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	Boiler Gaskets	100	LF	Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
08	Incinerator Fire Brick	75	SF	Incinerator in Boiler House	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	12x12 Cream w/Tan Floor Tile Mastic			Remove All - NOT OBSERVED	Assumed	MISC					
08C	12x12 Cream w/Brown & Maroon Specks Floor Tile Mastic	1,000	SF	Room 103 and 3rd Floor NE Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08H	12x12 Green w/Cream Streaks Floor Tile Mastic	400	SF	Engineer's Office and Lunch Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12x12 Dark Brown Floor Tile	430	SF	Room 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12x12 Dark Brown Floor Tile Mastic	430	SF	Room 206	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12x12 Tan w/Orange Streaks Floor Tile - NOT OBSERVED			Main Office, Store Room, Copy Room & Reception	Assumed	MISC					
11A	12x12 Tan w/White Streaks Floor Tile Mastic- NOT OBSERVED			Main Office, Store Room, Copy Room & Reception	Chrysotile	MISC					
12	12x18 Black w/White Streaks Floor Tile-NOT OBSERVED			Room 106/Lunchroom		MISC					
12A	12x18 Black w/White Streaks Floor Tile Mastic- NOT OBSERVED			Room 106/Lunchroom	Chrysotile	MISC					
13	12x12 Green w/White Streaks Floor Tile	3,100	SF	Rooms 111, 112 & Workroom, 211, 212, 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13A	12x12 Green w/White Streaks Floor Tile Mastic	3,100	SF	Rooms 111, 112 & Workroom, 211, 212, 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9x9 Cream w/Brown Specks Floor Tile	1,800	SF	Room 106/Lunchroom and Library (Under Carpet)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	9x9 Cream w/Brown Specks Floor Tile Mastic	1,800	SF	Room 106/Lunchroom and Library (under carpet)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Blue-Green Carpet Mastic-NOT OBSERVED			Assembly Room		MISC					
16	Mauve Carpet Mastic	600	SF	Principal's Office, Administrative Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bennett School
Address 10115 S. Prairie Avenue

Unit 22241
Chicago, IL, 60628

Building ID 2280
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
17	Rust Carpet Mastic-NOT OBSERVED			Library (Room 107, Room 109)		MISC					
18	Interior Window Caulk			Basement Windows East & West sides of Boiler Room	No ACBM	MISC					
20	Interior Window Glazing			Basement Only	No ACBM	MISC					
22	Terrazzo Flooring	2,200	SF	1st, 2nd & 3rd Floor Corridors, Stairs, Landings, and Entryways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Ceramic Tile Grout	2,500	SF	All Restrooms Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Aircell Duct Covers	230	SF	East-West Crawlspace Under Auditorium	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
25	9x9 Red w/White Streaks Floor Tile	700	SF	Engineer's Office West Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	9x9 Red w/White Streaks Floor Tile Mastic	700	SF	Engineer's Office West Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	9x9 Black w/White Streaks Floor Tile	160	SF	Engineer's Office and Restroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26A	9x9 Black w/White Streaks Floor Tile Mastic	160	SF	Engineer's Office and Restroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Exterior Window Caulk			Field House - Demolished in 2009	Assumed	MISC					
28	Exterior Window Glazing			Fieldhouse - Demolished in 2009	Assumed	MISC					
29	Mag Block Pipe Insulation	6	LF	Hall Behind Fans 3 and 4	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
46	12x12 Gray w/White Streaks Floor Tile	1,600	SF	Rooms 104 and 210, Boiler Room, Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12x12 Gray w/White Streaks Floor Tile Mastic	1,600	SF	Rooms 104 and 210, Boiler Room, Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12x12 Cream w/Tan Floor Tile	1,200	SF	Room 101 and Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12x12 Cream w/Tan Floor Tile Mastic	1,200	SF	Room 101 and Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12x12 Brown w/White Floor Tile	540	SF	Room 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12x12 Brown w/White Floor Tile Mastic	540	SF	Room 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12 x 12 Tan w/Brown Floor Tile	2,200	SF	Rooms 111, 112, 206, 211, 212, and 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12 x 12 Tan w/Brown Floor Tile Mastic	2,200	SF	Rooms 111, 112, 206, 211, 212, and 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	9x9 Peach Floor Tile	45	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	9x9 Peach Floor Tile Mastic	45	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Plaster Walls and Ceilings	100,000	SF	Throughout Facility	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Green Carpet Mastic	500	SF	Room 302	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Blue Carpet Mastic	2,500	SF	Room 202 - Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bennett School
Address 10115 S. Prairie Avenue

Unit 22241
Chicago, IL, 60628

Building ID 2280
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
59	12" x 12" Yellow Floor Tile	320	SF	Assembly Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12" x 12" Yellow Floor Tile Mastic	320	SF	Assembly Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12" x 12" Blue Floor Tile	2,000	SF	Assembly Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12" x 12" Blue Floor Tile Mastic	2,000	SF	Assembly Rom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Blown in Insulation	6,000	SF	Attic	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
64	12x12 White w/Cream Specks Vinyl Floor Tile	2,300	SF	Room 103 (Kitchen), 106 (Lunchroom), 111, 112, 113, 206, Lunch Manager's Office, Asst. Engineer's Off.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12x12 White w/Cream Specks Mastic	2,300	SF	Room 103 (Kitchen), 106 (Lunchroom), 111, 112, 113, 206, Lunch Room Manager Office, Asst. Engineer's Off.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12x12 Tan w/Beige Specks Vinyl Floor Tile	150	SF	Main Office Waiting Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12x12 Tan w/Beige specks Mastic	150	SF	Main Office Waiting Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" X 12" Tan w/White Specks Floor Tile	900	SF	Main Office, Storeroom, Copy Room, Reception	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68A	12" X 12" Tan w/White Specks Floor Tile Mastic	900	SF	Main Office, Store Room, Copy Room, Reception Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Cardboard Pipe Insulation	800	LF	Boiler Room, Pump Room, Fan Rooms, Pipe Chases, Air Tunnels	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	MJP E/F/V on Cardboard Pipe Insulation	28	FITTING	Pump Room, Fan Rooms, Pipe Chases, Air Tunnels	Assumed	TSI	Yes	0	FITTING	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Aircell Pipe Insulation	3,294	LF	Boiler Rm., Pump Room, Air Tunnel, Valve Room, Pipe Chases, Fan Rooms	Chrysotile	TSI	Yes	3	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
F	MJP E/F/V on Aircell Pipe Insulation	180	FITTING	Boiler Room, Pump Room, Air Tunnel, Pipe Chases, Crawl Space, Fan Rooms	Chrysotile	TSI	Yes	0	FITTING	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	MJP E/F/V on Fiberglass Pipe Insulation	90	FITTING	Boiler Room, Pump Room and Tunnel	Assumed	TSI	Yes	10	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
H	Cardboard Pipe Insulation	200	LF	Crawlspace	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	MJP E/F/V on Cardboard Pipe Insulation	16	LF	Crawlspace	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	MJP E/F/V on Aircell Pipe Insulation	14	LF	Crawlspaces Throughout 1951 & 1927 Buildings	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Aircell Pipe Insulation	250	LF	Crawlspaces Throughout 1957 & 1927	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable	Follow O&M Plan

Chicago Public Schools

School Bennett School

Unit 22241

Building ID 2280

Address 10115 S. Prairie Avenue

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Buildings						suspect ACBM	
L	Rope Pipe Insulation	40	LF	Fan Rooms	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Review Date	09/11/2019	HA Number	Management Comments
-------------	------------	-----------	---------------------

Chicago Public Schools

School Bennett School
Address 10115 S. Prairie Avenue

Unit 22241
Chicago, IL, 60628

Building ID 2280
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Manager Planner Name	Amy Williams
100-00746	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
03	
04	
05	
05H	
06	
07	
08	
08A	
08C	
08H	
09	
10	
11	
11A	
12	
12A	
13	
13A	
14	
14A	
15	
16	
17	
18	
20	

Chicago Public Schools

School Bennett School
Address 10115 S. Prairie Avenue

Unit 22241
Chicago, IL, 60628

Building ID 2280
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
22	
23	
24	
25	
25A	
26	
26A	
27	
28	
29	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	

Chicago Public Schools

School Bennett School
Address 10115 S. Prairie Avenue

Unit 22241
Chicago, IL, 60628

Building ID 2280
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
62	
63	
64	
65	
66	
67	
68	
68A	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	12x12 Beige w/Brown Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st, 2nd, & 3rd Floor Hallways and Room 102		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	12x12 Beige w/Brown Speckled Floor Tile		
MATERIAL LOCATION:	1st, 2nd, & 3rd Floor Hallways and Room 102		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	9x9 Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 208		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	9x9 Brown Floor Tile		
MATERIAL LOCATION:	Room 208		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	9x9 Brown w/White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 208		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	9x9 Brown w/White Floor Tile Mastic		
MATERIAL LOCATION:	Room 208		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	12x12 Beige w/Brown Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd, & 3rd Floor Hallways and Room 102		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	12x12 Beige w/Brown Speckled Floor Tile Mastic		
MATERIAL LOCATION:	1st, 2nd, & 3rd Floor Hallways and Room 102		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05H	
MATERIAL DESCRIPTION:	12x12 Green w/Cream Streaks Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	05H	
MATERIAL DESCRIPTION:	12x12 Green w/Cream Streaks Floor Tile	
MATERIAL LOCATION:	NOT OBSERVED	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	Insulation in 6 Steel Fire Rated Doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room, Assembly Room		
MATERIAL QUANTITY:	168	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	Insulation in 6 Steel Fire Rated Doors		
MATERIAL LOCATION:	Boiler Room, Assembly Room		
MATERIAL QUANTITY:	168	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	Boiler Gaskets		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	Boiler Gaskets		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Incinerator Fire Brick		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Incinerator in Boiler House		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Incinerator Fire Brick		
MATERIAL LOCATION:	Incinerator in Boiler House		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08A	
MATERIAL DESCRIPTION:	12x12 Cream w/Tan Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Remove All - NOT OBSERVED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2019

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	08A	
MATERIAL DESCRIPTION:	12x12 Cream w/Tan Floor Tile Mastic	
MATERIAL LOCATION:	Remove All - NOT OBSERVED	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08C		
MATERIAL DESCRIPTION:	12x12 Cream w/Brown & Maroon Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103 and 3rd Floor NE Office		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	08C				
MATERIAL DESCRIPTION:	12x12 Cream w/Brown & Maroon Specks Floor Tile Mastic				
MATERIAL LOCATION:	Room 103 and 3rd Floor NE Office				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08H		
MATERIAL DESCRIPTION:	12x12 Green w/Cream Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office and Lunch Lounge		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	08H				
MATERIAL DESCRIPTION:	12x12 Green w/Cream Streaks Floor Tile Mastic				
MATERIAL LOCATION:	Engineer's Office and Lunch Lounge				
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12x12 Dark Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 206		
MATERIAL QUANTITY:	430	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12x12 Dark Brown Floor Tile		
MATERIAL LOCATION:	Room 206		
MATERIAL QUANTITY:	430	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12x12 Dark Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 206		
MATERIAL QUANTITY:	430	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12x12 Dark Brown Floor Tile Mastic		
MATERIAL LOCATION:	Room 206		
MATERIAL QUANTITY:	430	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11	
MATERIAL DESCRIPTION:	12x12 Tan w/Orange Streaks Floor Tile - NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office, Store Room, Copy Room & Reception

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: 12x12 Tan w/Orange Streaks Floor Tile - NOT OBSERVED

MATERIAL LOCATION: Main Office, Store Room, Copy Room & Reception

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22241** BUILDING ID: **2280**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Bennett School** INSPECTION DATE: **8/9/2019**
ADDRESS: **10115 S. Prairie Avenue** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **12x12 Tan w/White Streaks Floor Tile Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, Store Room, Copy Room & Reception**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/09/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	11A				
MATERIAL DESCRIPTION:	12x12 Tan w/White Streaks Floor Tile Mastic- NOT OBSERVED				
MATERIAL LOCATION:	Main Office, Store Room, Copy Room & Reception				
MATERIAL QUANTITY:		MATERIAL UNITS:			
DAMAGE QUANTITY:		DAMAGE UNITS:			

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12
MATERIAL DESCRIPTION:	12x18 Black w/White Streaks Floor Tile-NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 106/Lunchroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed - Area is HA 64 & 65

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	12	
MATERIAL DESCRIPTION:	12x18 Black w/White Streaks Floor Tile-NOT OBSERVED	
MATERIAL LOCATION:	Room 106/Lunchroom	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12A	
MATERIAL DESCRIPTION:	12x18 Black w/White Streaks Floor Tile Mastic-NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 106/Lunchroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed - Area is HA 64 & 65

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	12A	
MATERIAL DESCRIPTION:	12x18 Black w/White Streaks Floor Tile Mastic-NOT OBSERVED	
MATERIAL LOCATION:	Room 106/Lunchroom	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12x12 Green w/White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 111, 112 & Workroom, 211, 212, 213		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12x12 Green w/White Streaks Floor Tile		
MATERIAL LOCATION:	Rooms 111, 112 & Workroom, 211, 212, 213		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13A		
MATERIAL DESCRIPTION:	12x12 Green w/White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 111, 112 & Workroom, 211, 212, 213		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	13A		
MATERIAL DESCRIPTION:	12x12 Green w/White Streaks Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 111, 112 & Workroom, 211, 212, 213		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	9x9 Cream w/Brown Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 106/Lunchroom and Library (Under Carpet)		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2019		

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	9x9 Cream w/Brown Specks Floor Tile		
MATERIAL LOCATION:	Room 106/Lunchroom and Library (Under Carpet)		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14A		
MATERIAL DESCRIPTION:	9x9 Cream w/Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 106/Lunchroom and Library (under carpet)		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2019		

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	14A				
MATERIAL DESCRIPTION:	9x9 Cream w/Brown Specks Floor Tile Mastic				
MATERIAL LOCATION:	Room 106/Lunchroom and Library (under carpet)				
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22241** BUILDING ID: **2280**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Bennett School** INSPECTION DATE: **8/9/2019**
ADDRESS: **10115 S. Prairie Avenue** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Blue-Green Carpet Mastic-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: _____ Date: **08/09/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	15	
MATERIAL DESCRIPTION:	Blue-Green Carpet Mastic-NOT OBSERVED	
MATERIAL LOCATION:	Assembly Room	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Mauve Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office, Administrative Office		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Mauve Carpet Mastic		
MATERIAL LOCATION:	Principal's Office, Administrative Office		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22241** BUILDING ID: **2280**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Bennett School** INSPECTION DATE: **8/9/2019**
ADDRESS: **10115 S. Prairie Avenue** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Rust Carpet Mastic-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library (Room 107, Room 109)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/09/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	17	
MATERIAL DESCRIPTION:	Rust Carpet Mastic-NOT OBSERVED	
MATERIAL LOCATION:	Library (Room 107, Room 109)	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18	
MATERIAL DESCRIPTION:	Interior Window Caulk	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement Windows East & West sides of Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	18	
MATERIAL DESCRIPTION:	Interior Window Caulk	
MATERIAL LOCATION:	Basement Windows East & West sides of Boiler Room	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20	
MATERIAL DESCRIPTION:	Interior Window Glazing	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement Only

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	20	
MATERIAL DESCRIPTION:	Interior Window Glazing	
MATERIAL LOCATION:	Basement Only	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Terrazzo Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Corridors, Stairs, Landings, and Entryways		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Terrazzo Flooring		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Corridors, Stairs, Landings, and Entryways		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Restrooms Throughout School		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Ceramic Tile Grout		
MATERIAL LOCATION:	All Restrooms Throughout School		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	Aircell Duct Covers		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East-West Crawlspace Under Auditorium		
MATERIAL QUANTITY:	230	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	Aircell Duct Covers		
MATERIAL LOCATION:	East-West Crawlspace Under Auditorium		
MATERIAL QUANTITY:	230	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	9x9 Red w/White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Engineer's Office West Room		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	9x9 Red w/White Streaks Floor Tile		
MATERIAL LOCATION:	Engineer's Office West Room		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25A		
MATERIAL DESCRIPTION:	9x9 Red w/White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office West Room		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	25A				
MATERIAL DESCRIPTION:	9x9 Red w/White Streaks Floor Tile Mastic				
MATERIAL LOCATION:	Engineer's Office West Room				
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	9x9 Black w/White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Engineer's Office and Restroom		
MATERIAL QUANTITY:	160	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	9x9 Black w/White Streaks Floor Tile		
MATERIAL LOCATION:	Engineer's Office and Restroom		
MATERIAL QUANTITY:	160	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26A		
MATERIAL DESCRIPTION:	9x9 Black w/White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office and Restroom		
MATERIAL QUANTITY:	160	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	26A				
MATERIAL DESCRIPTION:	9x9 Black w/White Streaks Floor Tile Mastic				
MATERIAL LOCATION:	Engineer's Office and Restroom				
MATERIAL QUANTITY:	160	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27	
MATERIAL DESCRIPTION:	Exterior Window Caulk	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Field House - Demolished in 2009

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Field House Demolished in 2009

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	27	
MATERIAL DESCRIPTION:	Exterior Window Caulk	
MATERIAL LOCATION:	Field House - Demolished in 2009	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28	
MATERIAL DESCRIPTION:	Exterior Window Glazing	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Fieldhouse - Demolished in 2009

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Field House Demolished in 2009

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	28	
MATERIAL DESCRIPTION:	Exterior Window Glazing	
MATERIAL LOCATION:	Fieldhouse - Demolished in 2009	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Amosite	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hall Behind Fans 3 and 4		
MATERIAL QUANTITY:	6	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation		
MATERIAL LOCATION:	Hall Behind Fans 3 and 4		
MATERIAL QUANTITY:	6	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12x12 Gray w/White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 104 and 210, Boiler Room, Storage Room		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12x12 Gray w/White Streaks Floor Tile		
MATERIAL LOCATION:	Rooms 104 and 210, Boiler Room, Storage Room		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	12x12 Gray w/White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 104 and 210, Boiler Room, Storage Room		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	12x12 Gray w/White Streaks Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 104 and 210, Boiler Room, Storage Room		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	12x12 Cream w/Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 101 and Teachers' Lounge		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	12x12 Cream w/Tan Floor Tile		
MATERIAL LOCATION:	Room 101 and Teachers' Lounge		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12x12 Cream w/Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101 and Teachers' Lounge		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12x12 Cream w/Tan Floor Tile Mastic		
MATERIAL LOCATION:	Room 101 and Teachers' Lounge		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12x12 Brown w/White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 101		
MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12x12 Brown w/White Floor Tile		
MATERIAL LOCATION:	Room 101		
MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12x12 Brown w/White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101		
MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12x12 Brown w/White Floor Tile Mastic		
MATERIAL LOCATION:	Room 101		
MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12 x 12 Tan w/Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 111, 112, 206, 211, 212, and 213		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12 x 12 Tan w/Brown Floor Tile		
MATERIAL LOCATION:	Rooms 111, 112, 206, 211, 212, and 213		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12 x 12 Tan w/Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 111, 112, 206, 211, 212, and 213		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12 x 12 Tan w/Brown Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 111, 112, 206, 211, 212, and 213		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	9x9 Peach Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 208		
MATERIAL QUANTITY:	45	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	9x9 Peach Floor Tile		
MATERIAL LOCATION:	Room 208		
MATERIAL QUANTITY:	45	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	9x9 Peach Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 208		
MATERIAL QUANTITY:	45	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22241** BUILDING ID: **2280**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Bennett School** REVIEW DATE: **9/11/2019**
ADDRESS: **10115 S. Prairie Avenue** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **9x9 Peach Floor Tile Mastic**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Plaster Walls and Ceilings		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	100000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Plaster Walls and Ceilings		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	100000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	Green Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 302		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	Green Carpet Mastic		
MATERIAL LOCATION:	Room 302		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 202 - Library		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
MATERIAL LOCATION:	Room 202 - Library		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Assembly Room		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile		
MATERIAL LOCATION:	Assembly Room		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Room		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile Mastic		
MATERIAL LOCATION:	Assembly Room		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Assembly Room		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
MATERIAL LOCATION:	Assembly Room		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Rom		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic		
MATERIAL LOCATION:	Assembly Rom		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	Blown in Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Attic		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	Blown in Insulation		
MATERIAL LOCATION:	Attic		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12x12 White w/Cream Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 103 (Kitchen), 106 (Lunchroom), 111, 112, 113, 206, Lunch Manager's Office, Asst. Engineer's Off.**

MATERIAL QUANTITY: **2300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12x12 White w/Cream Specks Vinyl Floor Tile		
MATERIAL LOCATION:	Room 103 (Kitchen), 106 (Lunchroom), 111, 112, 113, 206, Lunch Manager's Office, Asst. Engineer's Off.		
MATERIAL QUANTITY:	2300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	12x12 White w/Cream Specks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 103 (Kitchen), 106 (Lunchroom), 111, 112, 113, 206, Lunch Room Manager Office, Asst. Engineer's Off.**

MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	12x12 White w/Cream Specks Mastic		
MATERIAL LOCATION:	Room 103 (Kitchen), 106 (Lunchroom), 111, 112, 113, 206, Lunch Room Manager Office, Asst. Engineer's Off.		
MATERIAL QUANTITY:	2300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12x12 Tan w/Beige Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Main Office Waiting Area		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12x12 Tan w/Beige Specks Vinyl Floor Tile		
MATERIAL LOCATION:	Main Office Waiting Area		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12x12 Tan w/Beige specks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office Waiting Area		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12x12 Tan w/Beige specks Mastic		
MATERIAL LOCATION:	Main Office Waiting Area		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room, Pump Room, Fan Rooms, Pipe Chases, Air Tunnels		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
MATERIAL LOCATION:	Boiler Room, Pump Room, Fan Rooms, Pipe Chases, Air Tunnels		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pump Room, Fan Rooms, Pipe Chases, Air Tunnels		
MATERIAL QUANTITY:	28	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING

COMMENTS:

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	D				
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation				
MATERIAL LOCATION:	Pump Room, Fan Rooms, Pipe Chases, Air Tunnels				
MATERIAL QUANTITY:	28	MATERIAL UNITS:	FITTING		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Boiler Rm., Pump Room, Air Tunnel, Valve Room, Pipe Chases, Fan Rooms		
MATERIAL QUANTITY:	3294	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	3	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	E				
MATERIAL DESCRIPTION:	Aircell Pipe Insulation				
MATERIAL LOCATION:	Boiler Rm., Pump Room, Air Tunnel, Valve Room, Pipe Chases, Fan Rooms				
MATERIAL QUANTITY:	3294	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	3	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room, Pump Room, Air Tunnel, Pipe Chases, Crawl Space, Fan Rooms		
MATERIAL QUANTITY:	180	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING

COMMENTS:

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	F				
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation				
MATERIAL LOCATION:	Boiler Room, Pump Room, Air Tunnel, Pipe Chases, Crawl Space, Fan Rooms				
MATERIAL QUANTITY:	180	MATERIAL UNITS:	FITTING		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room, Pump Room and Tunnel**

MATERIAL QUANTITY: **90**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **10**

DAMAGE UNITS: **FITTING**

COMMENTS: **Damage in Tank Rm**

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	G				
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation				
MATERIAL LOCATION:	Boiler Room, Pump Room and Tunnel				
MATERIAL QUANTITY:	90	MATERIAL UNITS:	FITTING		
DAMAGE QUANTITY:	10	DAMAGE UNITS:	FITTING		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Crawlspace		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
MATERIAL LOCATION:	Crawlspace		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22241** BUILDING ID: **2280**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Bennett School** INSPECTION DATE: **8/9/2019**
ADDRESS: **10115 S. Prairie Avenue** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Crawlspace**
MATERIAL QUANTITY: **16** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/09/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	I				
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation				
MATERIAL LOCATION:	Crawlspace				
MATERIAL QUANTITY:	16	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Crawlspaces Throughout 1951 & 1927 Buildings		
MATERIAL QUANTITY:	14	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	J				
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation				
MATERIAL LOCATION:	Crawlspaces Throughout 1951 & 1927 Buildings				
MATERIAL QUANTITY:	14	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Crawlspaces Throughout 1957 & 1927 Buildings		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
MATERIAL LOCATION:	Crawlspaces Throughout 1957 & 1927 Buildings		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Rope Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Fan Rooms		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Bennett School	REVIEW DATE:	9/11/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

HOMOGENEOUS AREA: L

MATERIAL DESCRIPTION: Rope Pipe Insulation

MATERIAL LOCATION: Fan Rooms

MATERIAL QUANTITY: 40

MATERIAL UNITS: LF

DAMAGE QUANTITY: 0

DAMAGE UNITS: LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/11/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	68				
MATERIAL DESCRIPTION:	12" X 12" Tan w/White Specks Floor Tile				
MATERIAL LOCATION:	Main Office, Storeroom, Copy Room, Reception				
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 08/09/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22241** BUILDING ID: **2280**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Bennett School** REVIEW DATE: **9/11/2019**
ADDRESS: **10115 S. Prairie Avenue** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" X 12" Tan w/White Specks Floor Tile**
MATERIAL LOCATION: **Main Office, Storeroom, Copy Room, Reception**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/11/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22241	BUILDING ID:	2280
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Shaquille Crews		
SCHOOL NAME:	Bennett School	INSPECTION DATE:	8/9/2019		
ADDRESS:	10115 S. Prairie Avenue	IDPH LICENSE NO:	100-19717		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	68A		
MATERIAL DESCRIPTION:	12" X 12" Tan w/White Specks Floor Tile Mastic		
MATERIAL LOCATION:	Main Office, Store Room, Copy Room, Reception Room		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **08/09/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22241** BUILDING ID: **2280**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Bennett School** REVIEW DATE: **9/11/2019**
ADDRESS: **10115 S. Prairie Avenue** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **68A**
MATERIAL DESCRIPTION: **12" X 12" Tan w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Main Office, Store Room, Copy Room, Reception Room**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/11/2019**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAQUILLE CREWS
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the
examination on 01/30/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/28/2019-01/30/2019

Course Dates:

01/30/2020

Expires:

1901BI01

Certificate Number:



PUBLIC HEALTH & SAFETY Inc.

Environmental and Occupational Services
37 E. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office 312-491-0081
Fax 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health


Phone: 312-491-0081

FORM # A-010

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

1/30/2020

ID NUMBER

100 - 19717

ISSUED

4/16/2019

EXPIRES

05/15/2020

SHAQUILLE CREWS

12823 S GREEN

CHICAGO, IL 60643

Environmental Health



PROJECT MANAGER

3/29/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Building Inspector Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

COURSE LENGTH: 4 HOURS

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

Certificate Number: BIR/0808

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com



2539 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

William Williams

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least
70% for re-accreditation under AHERA (Title II)*

Asbestos Management Planner Refresher


Class Date: 02/15/2019
Examination Date: 02/15/2019
STC Certificate Number: STC-20190215-000527AMPR
Certification Expiration: 02/15/2020

David M. Mendoza – President/Training Director
Certified Environmental Specialist
OSHA Authorized Instructor

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

4/21/2019

ID NUMBER

ISSUED

EXPIRES

100 - 00746

4/11/2019

05/15/2020

MANAGEMENT PLANNER

4/21/2019

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

AMY J WILLIAMS

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed