

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2440
SCHOOL NAME: Skinner North
ADDRESS OF SCHOOL: 640 W. Scott Street
CITY: Chicago, IL, 60610

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/4/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 537
IDPH INSPECTOR LICENSE NUMBER: 100-11089
IDPH LICENSED INSPECTOR NAME(Please Print): Panfilo Carrazco
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Skinner North

640 W. Scott Street
Chicago, IL, 60610

Unit: 22591
Building ID: 5760

IDPH ID Number: 14-016-2990-2440

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

Chicago Public Schools
42 West Madison Street
Chicago, IL 60602

Prepared by:

GSG-Probe Consulting, Inc.

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW

Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 12, 2019

RE: Skinner North, Unit 22591
640 W. Scott Street
Chicago, IL, 60610

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Skinner North, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Skinner North, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Skinner North	Unit:	25271	Region:	02
Address:	640 W. Scott Street		Chicago, IL, 60610		
IDPH ID:	14-016-2990-2440		Building ID:	5760	
Contact:	Rosas, Manuel		Phone:	773 852 7654	

2. Description of Facility

Original Construction:	1961	Additional Construction:	
Total Square Footage:	68922	No of Floors:	3
Current Occupancy:	537		

3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	42 West Madison Street		
	Chicago, IL 60602		

4. Managing Environmental Consultant

MEC:	GSG-Probe Consulting, Inc.		
Contact:	Jigar Shah		
Address	2942 W. Van Buren		
	Chicago, IL, 60612		
Phone:	3123197575	Fax:	

5. Inspector

Inspector Name: Panfilo Carrazco

Inspector IDPH license # 100-11089

Signature:
Date: 9/12/2019

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature:
Date: 09/16/2019

7. Review Date:09/16/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Skinner North. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5760:

- | | |
|---|-----------------------------------|
| C | MJP on Fiberglass Pipe Insulation |
| D | Mag block pipe insulation |

B. The following new homogenous areas have been identified for Building 5760:

44	12" x 12" Off White w/ Multicolor specks floor tile
44A	12" x 12" Off White w/ Multicolor specks floor tile Mastic
45	Red Fire stop

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Hardcoat Plaster
02	1'x1' Ceiling Tile
26	9"x9" Green w/ White & Green Specks VFT Mastic
31	1' x 1' Ceiling Tile Glue (Mastic)
32	Exterior Window Caulk
33	Sink Coating
34	12 x 12 inch Beige w/Streaks VFT
34 A	12 x 12 inch Beige w/Streaks VFT Mastic
35	12"X 12" Beige w/white spots floor tile
36	12"X 12" Beige w/white spots Fl. Tile MASTIC
37	12 x 12 Grey with Grey Streaks Floor Tile
37M	12 x 12 Grey with Grey Streaks Floor Tile Adhesive
38	12 x 12 Green with Streaks Floor Tile
38M	12 x 12 Green with Streaks Floor Tile Mastic
39	12 x 12 Light Blue with Streaks Floor Tile
39M	12 x 12 Light Blue with Streaks Floor Tile Mastic
40M	12 x 12 White with Blue Streaks Floor Tile Adhesive
41	12 x 12 Brown with White Streaks Floor Tile
41M	12 x 12 Brown with White Streaks Floor Tile Mastic
42	12 x 12 Turquoise with Straks Floor Tile
42M	12 x 12 Turquoise with Straks Floor Tile Adhesive
43	Burgandy with Colored Streaks Carpet Adhesive
44	12" x 12" Off White w/ Multicolor specks floor tile
44A	12" x 12" Off White w/ Multicolor specks floor tile Mastic
45	Red Fire stop
F	Storage Tank Insulation
G	Boiler Gasket
K	HVAC Duct Jacket over Fiberglass Duct Insulation
L	Burgundy with Colored Specks Carpet Mastic
M	Red Carpet Mastic

The following areas were deemed to be inaccessible:

03	Acoustic Ceiling
04	Fireproofing
12	9"x9" Green w/ White Streaks VFT Mastic
26	9"x9" Green w/ White & Green Specks VFT Mastic
30	12"x12" Coffee w/ Brown & White Streaks VFT

	Mastic
31	1' x 1' Ceiling Tile Glue (Mastic)
36	12"X 12" Beige w/white spots Fl. Tile MASTIC
37	12 x 12 Grey with Grey Streaks Floor Tile
37M	12 x 12 Grey with Grey Streaks Floor Tile Adhesive
38M	12 x 12 Green with Streaks Floor Tile Mastic
39M	12 x 12 Light Blue with Streaks Floor Tile Mastic
40M	12 x 12 White with Blue Streaks Floor Tile Adhesive
41M	12 x 12 Brown with White Streaks Floor Tile Mastic
42M	12 x 12 Turquoise with Straks Floor Tile Adhesive
43	Burgandy with Colored Streaks Carpet Adhesive
D	Mag block pipe insulation
L	Burgundy with Colored Specks Carpet Mastic
M	Red Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Panfilo Carrazco, IDPH License # 100-11089. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Skinner North Building 5760 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

School Skinner North **Unit** 25271 **Building ID** 5760
Address 640 W. Scott Street **Region** 02

Inspector's Reinspection Findings Table 1

2942 W. Van Buren Chicago, IL, 60612

Inspector's Comments are Summarized at the End of the Report

[illegible]

Chicago Public Schools

School Skinner North Unit 25271 Building ID 5760

Address 640 W. Scott Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
14	12"x12" Grey w/ Grey & White Specks VFT Mastic (ABATED)			Rm 302, 204	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
17	9"x9" Light Brown w/ Brown & Cream Streaks VFT (ABATED 2009)			Throughout (See Hatching)	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
18	9"x9" Light Brown w/ Brwn & Cream Strks VFT Mastic (ABATED 2009)			Throughout (See Hatching)	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
19	12"x12" Green w/ White & Green Specks VFT (ABATED 2009)			Room 206, 303	ABATED									
20	12"x12" Green w/ White & Green Specks VFT Mastic (ABATED 2009)			Room 206, 303	ABATED									
21	9"x9" Blue w/ White Streaks VFT (ABATED 2009)			1st, 2nd, 3rd Fl	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
22	9"x9" Blue w/ White Streaks VFT Mastic (ABATED 2009)			1st, 2nd, 3rd Fl	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
23	9"x9" Tan w/ White & Dark Brown Streaks VFT (ABATED 2009)			East, West & Central Stairwells	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
24	9"x9" Tan w/ White & Dark Brown Streaks VFT Mastic (ABATED 2009)			East, West & Central Stairwells	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
25	9"x9" Green w/ White & Green Specks VFT	250	SF	Engineers Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
26	9"x9" Green w/ White & Green Specks VFT Mastic	250	SF	Engineers Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12"x12" White w/ Grey Specks VFT (ABATED 2009)			Principals Office	ABATED									
28	12"x12" White w/ Grey Specks VFT Mastic (ABATED 2009)			Principals Office	ABATED									
29	12"x12" Coffee w/ Brown & White Streaks VFT	70	SF	Lunchroom Offices	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
30	12"x12" Coffee w/ Brown & White Streaks VFT Mastic	70	SF	Lunchroom Offices	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	1' x 1' Ceiling Tile Glue (Mastic)	10,000	SF	Throughout (See Hatching)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Exterior Window Caulk	20,000	LF	Exterior Windows	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Sink Coating	32	SF	Room 101, 103, 106, 108, 201, 203, 301, Clinic (110)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Skinner North Unit 25271 Building ID 5760

Address 640 W. Scott Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
34	12 x 12 inch Beige w/Streaks VFT	600	SF	Food Storage Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
34 A	12 x 12 inch Beige w/Streaks VFT Mastix	600	SF	Food Storage Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12"X 12" Beige w/white spots floor tile	1,400	SF	Lunchroom faculty dining	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
36	12"X 12" Beige w/white spots Fl. Tile MASTIC	1,400	SF	Lunchroom, faculty dining	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12 x 12 Grey with Grey Streaks Floor Tile	30,000	SF	1st, 2nd and 3rd Floor Corridors, 3rd Floor Storage and Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37M	12 x 12 Grey with Grey Streaks Floor Tile Adhesive	30,000	SF	1st, 2nd and 3rd Floor Corridors, 3rd Floor Storage and Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12 x 12 Green with Streaks Floor Tile	4,800	SF	Classrooms 206, 210, 303, 304, 310, 106, 2nd lvl storage room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
38M	12 x 12 Green with Streaks Floor Tile Mastix	4,800	SF	Classrooms 206, 210, 303, 304, 310, 106, 2nd fl storage room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12 x 12 Light Blue with Streaks Floor Tile	6,600	SF	Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
39M	12 x 12 Light Blue with Streaks Floor Tile Mastix	6,600	SF	Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12 x 12 White with Blue Streaks Floor Tile	12,000	SF	Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Skinner North Unit 25271 Building ID 5760

Address 640 W. Scott Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				3rd Floor Corridors, 2nd fl faculty room										
40M	12 x 12 White with Blue Streaks Floor Tile Adhesive	12,000	SF	Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	12 x 12 Brown with White Streaks Floor Tile	5,200	SF	Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
41M	12 x 12 Brown with White Streaks Floor Tile Mastic	5,200	SF	Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12 x 12 Turquoise with Straks Floor Tile	569	SF	1st, 2nd and 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
42M	12 x 12 Turquoise with Straks Floor Tile Adhesive	569	SF	1st, 2nd and 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Burgandy with Colored Streaks Carpet Adhesive	3,200	SF	Rooms 101, 103, 108, and 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	12" x 12" Off White w/ Multicolor specks floor tile	4,000	SF	Rooms 110, 108, 103, 101 and the nurse station	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44A	12" x 12" Off White w/ Multicolor specks floor tile Mastic	4,000	SF	Rooms 110, 108, 103, 101 and the nurse station	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Red Fire stop	30	LF	Electrical switch gear room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
C	MJP on Fiberglass Pipe Insulation	28	LF	piping tunnel below the school, auditorium stage, boiler room	CHR	TSI	Y	DIST	25		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
D	Mag block pipe insulation	495	LF	Boiler Room	CHR	TSI	Y	LOC	16		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
E	Aircell Pipe Insulation	150	LF	Lunchroom Store Rm	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Skinner North Unit 25271 Building ID 5760

Address 640 W. Scott Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
F	Storage Tank Insulation	300	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Boiler Gasket	30	LF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
J	Table Top	16	SF	Boiler Rm	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
K	HVAC Duct Jacket over Fiberglass Duct Insulation	1,000	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
L	Burgundy with Colored Specks Carpet Mastic	2,400	SF	Room 108(abated), Library (101 and 103 both abated)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M	Red Carpet Mastic	500	SF	Room 309	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Skinner North Unit 25271 Building ID 5760

Address 640 W. Scott Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>9/12/2019</u>
Inspector Name	<u>Panfilo Carrazco</u>
<u>100-11089</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
17	
18	
19	
20	
21	
22	
23	
24	
25	

Chicago Public Schools

School Skinner North **Unit** 25271 **Building ID** 5760

Address 640 W. Scott Street **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
26	
27	
28	
29	
30	
31	
32	
33	
34	
34 A	
35	
36	
37	
37M	
38	
38M	
39	
39M	
40	
40M	
41	
41M	
42	
42M	
43	
44	
44A	
45	
C	

Chicago Public Schools

School Skinner North **Unit** 25271 **Building ID** 5760

Address 640 W. Scott Street **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
D	Repair
E	
F	
G	
J	
K	
L	
M	

Table II

Management Planner's Review

Chicago Public Schools

School Skinner North
Address 640 W. Scott Street

Unit 25271
Chicago, IL, 60610

Building ID 5760
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Hardcoat Plaster	5,000	SF	Auditorium, Boys and Girls Toilets, Janitors Closets	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	1'x1' Ceiling Tile	10,000	SF	Throughout (See Hatching)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	Acoustic Ceiling	3,500	SF	Gymnasium	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	Fireproofing	2,500	SF	Boiler Room	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	9"x9" Grey w/ White & Dark Streaks VFT	2,050	SF	MDF Room 2nd flr Storage Room next to 202, 1st Staffroom , 1st flr Storage room, RM 1A, Youth Guidance Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	12"x12" Beige w/ Brown & White Specks VFT (ABATED 2009)			Rm 306, 107, 101, 103, 102, 105, 106	Abated						Follow O&M Plan
07	9"x9" Grey w/ White & Dark Specks VFT Mastic	2,050	SF	MDF Room 2nd flr Storage Room next to 202, 1st Staffroom , 1st flr Storage room, RM 1A, Youth Guidance Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Beige w/ Brown & White Specks VFT Mastic (ABATED 2009)			Rm 306, 107, 101, 103, 102, 105, 106	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
09	9"x9" Sand w/ White & Black Streaks VFT (ABATED 2009)			Throughout (See Hatching)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
10	9"x9" Sand w/ White & Black Streaks VFT Mastic (ABATED 2009)			Throughout (See Hatching)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
11	9"x9" Green w/ White Streaks VFT	600	SF	Rm 106 and Gymnasium North Office & storage room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9"x9" Green w/ White Streaks VFT Mastic	600	SF	Rm 106 and Gymnasium North Office & storage room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" Grey w/ Grey & White Specks VFT (ABATED)			Rm 302, 204	Abated						Follow O&M Plan
14	12"x12" Grey w/ Grey & White Specks VFT Mastic (ABATED)			Rm 302, 204	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
17	9"x9" Light Brown w/ Brown & Cream Streaks VFT (ABATED 2009)			Throughout (See Hatching)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
18	9"x9" Light Brown w/ Brwn & Cream Strks VFT Mastic (ABATED 2009)			Throughout (See Hatching)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
19	12"x12" Green w/ White & Green Specks VFT (ABATED 2009)			Room 206, 303	Abated						Follow O&M Plan
20	12"x12" Green w/ White & Green Specks VFT Mastic (ABATED 2009)			Room 206, 303	Abated						

Chicago Public Schools

School Skinner North
Address 640 W. Scott Street

Unit 25271
Chicago, IL, 60610

Building ID 5760
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
21	9"x9" Blue w/ White Streaks VFT (ABATED 2009)			1st, 2nd, 3rd Fl	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
22	9"x9" Blue w/ White Streaks VFT Mastic (ABATED 2009)			1st, 2nd, 3rd Fl	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
23	9"x9" Tan w/ White & Dark Brown Streaks VFT (ABATED 2009)			East, West & Central Stairwells	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
24	9"x9" Tan w/ White & Dark Brown Streaks VFT Mastic (ABATED 2009)			East, West & Central Stairwells	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
25	9"x9" Green w/ White & Green Specks VFT	250	SF	Engineers Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	9"x9" Green w/ White & Green Specks VFT Mastic	250	SF	Engineers Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12"x12" White w/ Grey Specks VFT (ABATED 2009)			Principals Office	Abated						Follow O&M Plan
28	12"x12" White w/ Grey Specks VFT Mastic (ABATED 2009)			Principals Office	Abated						Follow O&M Plan
29	12"x12" Coffee w/ Brown & White Streaks VFT	70	SF	Lunchroom Offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12"x12" Coffee w/ Brown & White Streaks VFT Mastic	70	SF	Lunchroom Offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	1' x 1' Ceiling Tile Glue (Mastic)	10,000	SF	Throughout (See Hatching)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Exterior Window Caulk	20,000	LF	Exterior Windows	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
33	Sink Coating	32	SF	Room 101, 103, 106, 108, 201, 203, 301, Clinic (110)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12 x 12 inch Beige w/Streaks VFT	600	SF	Food Storage Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34 A	12 x 12 inch Beige w/Streaks VFT Mastic	600	SF	Food Storage Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12"X 12" Beige w/white spots floor tile	1,400	SF	Lunchroom faculty dining	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"X 12" Beige w/white spots Fl. Tile MASTIC	1,400	SF	Lunchroom, faculty dining	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12 x 12 Grey with Grey Streaks Floor Tile	30,000	SF	1st, 2nd and 3rd Floor Corridors, 3rd Floor Storage and Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37M	12 x 12 Grey with Grey Streaks Floor Tile Adhesive	30,000	SF	1st, 2nd and 3rd Floor Corridors, 3rd Floor Storage and Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12 x 12 Green with Streaks Floor Tile	4,800	SF	Classrooms 206, 210, 303, 304, 310, 106, 2nd lvl storage room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38M	12 x 12 Green with Streaks Floor Tile Mastic	4,800	SF	Classrooms 206, 210, 303, 304, 310, 106, 2nd fl storage room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Skinner North
Address 640 W. Scott Street

Unit 25271
Chicago, IL, 60610

Building ID 5760
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
39	12 x 12 Light Blue with Streaks Floor Tile	6,600	SF	Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39M	12 x 12 Light Blue with Streaks Floor Tile Mastic	6,600	SF	Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12 x 12 White with Blue Streaks Floor Tile	12,000	SF	Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and 3rd Floor Corridors, 2nd fl faculty room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40M	12 x 12 White with Blue Streaks Floor Tile Adhesive	12,000	SF	Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12 x 12 Brown with White Streaks Floor Tile	5,200	SF	Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41M	12 x 12 Brown with White Streaks Floor Tile Mastic	5,200	SF	Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12 x 12 Turquoise with Straks Floor Tile	569	SF	1st, 2nd and 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42M	12 x 12 Turquoise with Straks Floor Tile Adhesive	569	SF	1st, 2nd and 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Burgandy with Colored Streaks Carpet Adhesive	3,200	SF	Rooms 101, 103, 108, and 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12" x 12" Off White w/ Multicolor specks floor tile	4,000	SF	Rooms 110, 108, 103, 101 and the nurse station	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44A	12" x 12" Off White w/ Multicolor specks floor tile Mastic	4,000	SF	Rooms 110, 108, 103, 101 and the nurse station	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Red Fire stop	30	LF	Electrical switch gear room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
C	MJP on Fiberglass Pipe Insulation	28	LF	pipng tunnel below the school, auditorium stage, boiler room	Chrysotile	TSI	Yes	25	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
D	Mag block pipe insulation	495	LF	Boiler Room	Chrysotile	TSI	Yes	16	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
E	Aircell Pipe Insulation	150	LF	Lunchroom Store Rm	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	Storage Tank Insulation	300	SF	Boiler Room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Boiler Gasket	30	LF	Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Skinner North
Address 640 W. Scott Street

Unit 25271
Chicago, IL, 60610

Building ID 5760
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
J	Table Top	16	SF	Boiler Rm	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	HVAC Duct Jacket over Fiberglass Duct Insulation	1,000	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	Burgundy with Colored Specks Carpet Mastic	2,400	SF	Room 108(abated), Library (101 and 103 both abated)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	Red Carpet Mastic	500	SF	Room 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Skinner North
Address 640 W. Scott Street

Unit 25271
Chicago, IL, 60610

Building ID 5760
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	09/16/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	

Chicago Public Schools

School Skinner North
Address 640 W. Scott Street

Unit 25271
Chicago, IL, 60610

Building ID 5760
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
28	
29	
30	
31	
32	
33	
34	
34 A	
35	
36	
37	
37M	
38	
38M	
39	
39M	
40	
40M	
41	
41M	
42	
42M	
43	
44	
44A	
45	

Chicago Public Schools

School Skinner North
Address 640 W. Scott Street

Unit 25271
Chicago, IL, 60610

Building ID 5760
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
C	Repair ASAP
D	Repair ASAP
E	
F	
G	
J	
K	
L	
M	

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	Hardcoat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Auditorium, Boys and Girls Toilets, Janitors Closets		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Hardcoat Plaster**

MATERIAL LOCATION: **Auditorium, Boys and Girls Toilets, Janitors Closets**

MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout (See Hatching)		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**

MATERIAL LOCATION: **Throughout (See Hatching)**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	Acoustic Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gymnasium		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Acoustic Ceiling**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **3500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	Fireproofing		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Fireproofing**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	9"x9" Grey w/ White & Dark Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **MDF Room 2nd flr Storage Room next to 202, 1st Staffroom , 1st flr Storage room, RM 1A, Youth Guidance Office**

MATERIAL QUANTITY: **2050**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **9"x9" Grey w/ White & Dark Streaks VFT**

MATERIAL LOCATION: **MDF Room 2nd flr Storage Room next to 202, 1st Staffroom , 1st flr Storage room, RM 1A, Youth Guidance Office**

MATERIAL QUANTITY:	2050	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06	
MATERIAL DESCRIPTION:	12"x12" Beige w/ Brown & White Specks VFT (ABATED 2009)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rm 306, 107, 101, 103, 102, 105, 106

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Specks VFT (ABATED 2009)**

MATERIAL LOCATION: **Rm 306, 107, 101, 103, 102, 105, 106**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	9"x9" Grey w/ White & Dark Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **MDF Room 2nd flr Storage Room next to 202, 1st Staffroom , 1st flr Storage room, RM 1A, Youth Guidance Office**

MATERIAL QUANTITY: **2050**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **9"x9" Grey w/ White & Dark Specks VFT Mastic**

MATERIAL LOCATION: **MDF Room 2nd flr Storage Room next to 202, 1st Staffroom , 1st flr Storage room, RM 1A, Youth Guidance Office**

MATERIAL QUANTITY:	2050	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08	
MATERIAL DESCRIPTION:	12"x12" Beige w/ Brown & White Specks VFT Mastic (ABATED 2009)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rm 306, 107, 101, 103, 102, 105, 106

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Specks VFT Mastic (ABATED 2009)**

MATERIAL LOCATION: **Rm 306, 107, 101, 103, 102, 105, 106**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09	
MATERIAL DESCRIPTION:	9"x9" Sand w/ White & Black Streaks VFT (ABATED 2009)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout (See Hatching)

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **9"x9" Sand w/ White & Black Streaks VFT (ABATED 2009)**

MATERIAL LOCATION: **Throughout (See Hatching)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10	
MATERIAL DESCRIPTION:	9"x9" Sand w/ White & Black Streaks VFT Mastic (ABATED 2009)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout (See Hatching)

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9"x9" Sand w/ White & Black Streaks VFT Mastic (ABATED 2009)**

MATERIAL LOCATION: **Throughout (See Hatching)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	9"x9" Green w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rm 106 and Gymnasium North Office & storage room		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**

MATERIAL LOCATION: **Rm 106 and Gymnasium North Office & storage room**

MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	9"x9" Green w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rm 106 and Gymnasium North Office & storage room		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Rm 106 and Gymnasium North Office & storage room**

MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12"x12" Grey w/ Grey & White Specks VFT (ABATED)		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rm 302, 204

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12"x12" Grey w/ Grey & White Specks VFT (ABATED)**

MATERIAL LOCATION: **Rm 302, 204**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14	
MATERIAL DESCRIPTION:	12"x12" Grey w/ Grey & White Specks VFT Mastic (ABATED)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rm 302, 204

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12"x12" Grey w/ Grey & White Specks VFT Mastic (ABATED)**

MATERIAL LOCATION: **Rm 302, 204**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17	
MATERIAL DESCRIPTION:	9"x9" Light Brown w/ Brown & Cream Streaks VFT (ABATED 2009)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout (See Hatching)

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Brown & Cream Streaks VFT (ABATED 2009)**

MATERIAL LOCATION: **Throughout (See Hatching)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18	
MATERIAL DESCRIPTION:	9"x9" Light Brown w/ Brwn & Cream Strks VFT Mastic (ABATED 2009)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout (See Hatching)

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Brwn & Cream Strks VFT Mastic (ABATED 2009)**

MATERIAL LOCATION: **Throughout (See Hatching)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12"x12" Green w/ White & Green Specks VFT (ABATED 2009)		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 206, 303

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12"x12" Green w/ White & Green Specks VFT (ABATED 2009)**

MATERIAL LOCATION: **Room 206, 303**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12"x12" Green w/ White & Green Specks VFT Mastic (ABATED 2009)		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 206, 303

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12"x12" Green w/ White & Green Specks VFT Mastic (ABATED 2009)**

MATERIAL LOCATION: **Room 206, 303**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21	
MATERIAL DESCRIPTION:	9"x9" Blue w/ White Streaks VFT (ABATED 2009)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st, 2nd, 3rd Fl

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9"x9" Blue w/ White Streaks VFT (ABATED 2009)**

MATERIAL LOCATION: **1st, 2nd, 3rd Fl**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22	
MATERIAL DESCRIPTION:	9"x9" Blue w/ White Streaks VFT Mastic (ABATED 2009)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st, 2nd, 3rd Fl

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **9"x9" Blue w/ White Streaks VFT Mastic (ABATED 2009)**

MATERIAL LOCATION: **1st, 2nd, 3rd Fl**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23	
MATERIAL DESCRIPTION:	9"x9" Tan w/ White & Dark Brown Streaks VFT (ABATED 2009)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East, West & Central Stairwells**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **9"x9" Tan w/ White & Dark Brown Streaks VFT (ABATED 2009)**

MATERIAL LOCATION: **East, West & Central Stairwells**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	9"x9" Tan w/ White & Dark Brown Streaks VFT Mastic (ABATED 2009)		
HISTORICAL AHERA DAMAGE CATEGORY	7		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: East, West & Central Stairwells

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9"x9" Tan w/ White & Dark Brown Streaks VFT Mastic (ABATED 2009)**

MATERIAL LOCATION: **East, West & Central Stairwells**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	9"x9" Green w/ White & Green Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Engineers Office		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **9"x9" Green w/ White & Green Specks VFT**

MATERIAL LOCATION: **Engineers Office**

MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	9"x9" Green w/ White & Green Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineers Office		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9"x9" Green w/ White & Green Specks VFT Mastic**

MATERIAL LOCATION: **Engineers Office**

MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12"x12" White w/ Grey Specks VFT (ABATED 2009)		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Principals Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12"x12" White w/ Grey Specks VFT (ABATED 2009)**

MATERIAL LOCATION: **Principals Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12"x12" White w/ Grey Specks VFT Mastic (ABATED 2009)		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Principals Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" White w/ Grey Specks VFT Mastic (ABATED 2009)**

MATERIAL LOCATION: **Principals Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12"x12" Coffee w/ Brown & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Lunchroom Offices		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12"x12" Coffee w/ Brown & White Streaks VFT**

MATERIAL LOCATION: **Lunchroom Offices**

MATERIAL QUANTITY: **70**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilio Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12"x12" Coffee w/ Brown & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom Offices		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12"x12" Coffee w/ Brown & White Streaks VFT Mastic**

MATERIAL LOCATION: **Lunchroom Offices**

MATERIAL QUANTITY: **70**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile Glue (Mastic)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching)		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Glue (Mastic)**

MATERIAL LOCATION: **Throughout (See Hatching)**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	Exterior Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Exterior Windows		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Exterior Window Caulk**

MATERIAL LOCATION: **Exterior Windows**

MATERIAL QUANTITY: **20000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Sink Coating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101, 103, 106, 108, 201, 203, 301, Clinic (110)		
MATERIAL QUANTITY:	32	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Sink Coating**

MATERIAL LOCATION: **Room 101, 103, 106, 108, 201, 203, 301, Clinic (110)**

MATERIAL QUANTITY:	32	MATERIAL UNITS:	SF
--------------------	-----------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12 x 12 inch Beige w/Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Food Storage Area		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12 x 12 inch Beige w/Streaks VFT**

MATERIAL LOCATION: **Food Storage Area**

MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34 A		
MATERIAL DESCRIPTION:	12 x 12 inch Beige w/Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Food Storage Area		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **34 A**

MATERIAL DESCRIPTION: **12 x 12 inch Beige w/Streaks VFT Mastic**

MATERIAL LOCATION: **Food Storage Area**

MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12"X 12" Beige w/white spots floor tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE
MATERIAL LOCATION:	Lunchroom faculty dining

MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12"X 12" Beige w/white spots floor tile**

MATERIAL LOCATION: **Lunchroom
faculty dining**

MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12"X 12" Beige w/white spots Fl. Tile MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, faculty dining		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12"X 12" Beige w/white spots Fl. Tile MASTIC**

MATERIAL LOCATION: **Lunchroom, faculty dining**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12 x 12 Grey with Grey Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors, 3rd Floor Storage and Auditorium		
MATERIAL QUANTITY:	30000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12 x 12 Grey with Grey Streaks Floor Tile**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, 3rd Floor Storage and Auditorium**

MATERIAL QUANTITY: **30000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37M		
MATERIAL DESCRIPTION:	12 x 12 Grey with Grey Streaks Floor Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors, 3rd Floor Storage and Auditorium		
MATERIAL QUANTITY:	30000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA:	37M		
MATERIAL DESCRIPTION:	12 x 12 Grey with Grey Streaks Floor Tile Adhesive		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors, 3rd Floor Storage and Auditorium		
MATERIAL QUANTITY:	30000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	12 x 12 Green with Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Classrooms 206, 210, 303, 304, 310, 106, 2nd lvl storage room		
MATERIAL QUANTITY:	4800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12 x 12 Green with Streaks Floor Tile**

MATERIAL LOCATION: **Classrooms 206, 210, 303, 304, 310, 106, 2nd lvl storage room**

MATERIAL QUANTITY:	4800	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38M		
MATERIAL DESCRIPTION:	12 x 12 Green with Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms 206, 210, 303, 304, 310, 106, 2nd fl storage room		
MATERIAL QUANTITY:	4800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **38M**

MATERIAL DESCRIPTION: **12 x 12 Green with Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms 206, 210, 303, 304, 310, 106, 2nd fl storage room**

MATERIAL QUANTITY: **4800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	12 x 12 Light Blue with Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room**

MATERIAL QUANTITY: **6600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12 x 12 Light Blue with Streaks Floor Tile**

MATERIAL LOCATION: **Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room**

MATERIAL QUANTITY:	6600	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39M		
MATERIAL DESCRIPTION:	12 x 12 Light Blue with Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room**

MATERIAL QUANTITY: **6600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **39M**

MATERIAL DESCRIPTION: **12 x 12 Light Blue with Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room**

MATERIAL QUANTITY:	6600	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12 x 12 White with Blue Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and 3rd Floor Corridors, 2nd fl faculty room**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12 x 12 White with Blue Streaks Floor Tile**

MATERIAL LOCATION: **Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and 3rd Floor Corridors, 2nd fl faculty room**

MATERIAL QUANTITY:	12000	MATERIAL UNITS:	SF
--------------------	--------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40M		
MATERIAL DESCRIPTION:	12 x 12 White with Blue Streaks Floor Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: **12000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **40M**

MATERIAL DESCRIPTION: **12 x 12 White with Blue Streaks Floor Tile Adhesive**

MATERIAL LOCATION: **Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:	12000	MATERIAL UNITS:	SF
--------------------	--------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	12 x 12 Brown with White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors		
MATERIAL QUANTITY:	5200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12 x 12 Brown with White Streaks Floor Tile**

MATERIAL LOCATION: **Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors**

MATERIAL QUANTITY:	5200	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41M		
MATERIAL DESCRIPTION:	12 x 12 Brown with White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors		
MATERIAL QUANTITY:	5200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **41M**

MATERIAL DESCRIPTION: **12 x 12 Brown with White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors**

MATERIAL QUANTITY:	5200	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	12 x 12 Turquoise with Straks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors		
MATERIAL QUANTITY:	569	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12 x 12 Turquoise with Straks Floor Tile**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:	569	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42M		
MATERIAL DESCRIPTION:	12 x 12 Turquoise with Straks Floor Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors		
MATERIAL QUANTITY:	569	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **42M**

MATERIAL DESCRIPTION: **12 x 12 Turquoise with Straks Floor Tile Adhesive**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:	569	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Burgandy with Colored Streaks Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101, 103, 108, and 110		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Burgandy with Colored Streaks Carpet Adhesive**

MATERIAL LOCATION: **Rooms 101, 103, 108, and 110**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	MJP on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 1. **Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	piping tunnel below the school, auditorium stage, boiler room		
MATERIAL QUANTITY:	28	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	25	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **piping tunnel below the school, auditorium stage, boiler room**

MATERIAL QUANTITY:	28	MATERIAL UNITS:	LF
--------------------	-----------	-----------------	-----------

DAMAGE QUANTITY:	25	DAMAGE UNITS:	LF
------------------	-----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair ASAP

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Mag block pipe insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 1. **Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	495	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	16	DAMAGE UNITS:	LF
COMMENTS:	Repair		

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Mag block pipe insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:	495	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	16	DAMAGE UNITS:	LF
------------------	-----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair ASAP

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom Store Rm		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Lunchroom Store Rm**

MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Storage Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Storage Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Boiler Gasket		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Boiler Gasket**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilio Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Table Top		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Rm		
MATERIAL QUANTITY:	16	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Table Top**

MATERIAL LOCATION: **Boiler Rm**

MATERIAL QUANTITY: **16**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	HVAC Duct Jacket over Fiberglass Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **HVAC Duct Jacket over Fiberglass Duct Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Burgundy with Colored Specks Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 108(abated), Library (101 and 103 both abated)		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Burgundy with Colored Specks Carpet Mastic**

MATERIAL LOCATION: **Room 108(abated), Library (101 and 103 both abated)**

MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Red Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 309		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Red Carpet Mastic**

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	44A		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Multicolor specks floor tile Mastic		
MATERIAL LOCATION:	Rooms 110, 108, 103, 101 and the nurse station		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25271** BUILDING ID: **5760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Skinner North** REVIEW DATE: **9/16/2019**
ADDRESS: **640 W. Scott Street** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **44A**
MATERIAL DESCRIPTION: **12" x 12" Off White w/ Multicolor specks floor tile Mastic**
MATERIAL LOCATION: **Rooms 110, 108, 103, 101 and the nurse station**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Red Fire stop		
MATERIAL LOCATION:	Electrical switch gear room		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Skinner North	REVIEW DATE:	9/16/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Red Fire stop		
MATERIAL LOCATION:	Electrical switch gear room		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25271	BUILDING ID:	5760
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	Skinner North	INSPECTION DATE:	9/12/2019		
ADDRESS:	640 W. Scott Street	IDPH LICENSE NO:	100-11089		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	44				
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Multicolor specks floor tile				
MATERIAL LOCATION:	Rooms 110, 108, 103, 101 and the nurse station				
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/12/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25271** BUILDING ID: **5760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Skinner North** REVIEW DATE: **9/16/2019**
ADDRESS: **640 W. Scott Street** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12" x 12" Off White w/ Multicolor specks floor tile**
MATERIAL LOCATION: **Rooms 110, 108, 103, 101 and the nurse station**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/16/2019**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

PANFILO CARRAZCO

This is to certify that _____
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR10

Certificate Number:



N. Penneff

Director of Training

Nicholas J. Penneff

Director of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

PANFILO CARRAZCO
855 W ADAMS STREET, SUITE 200
CHICAGO, IL 60607

4/28/2017

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	2/11/2018
100 - 11089	4/28/2017	05/15/2018		
PANFILO CARRAZCO			PROJECT MANAGER	2/4/2018
855 W ADAMS STREET, SUITE			AIR SAMPLING PROFESSIONAL	
CHICAGO, IL 60607			Alteration of this license shall result in legal action	
Environmental Health:			This license issued under authority of the State of Illinois	
			Department of Public Health	
			This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PANFILO CARRAZCO
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



PUBLIC HEALTH & SAFETY inc.
Environmental and Occupational Services
312 S. Ashland Ave., Chicago, IL 60607
www.public-health-safety.com
Office: 312-491-0081
Fax: 312-421-2501

02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR08

Certificate Number:

Phone: 312-491-0081

Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

PANFILO CARRAZCO
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11089	ISSUED 4/19/2019	EXPIRES 05/15/2020	INSPECTOR	2/9/2020
PANFILO CARRAZCO 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/2/2020
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

PANFILO CARRAZCO
855 W ADAMS STREET, SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License			Back of License	
 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11089	ISSUED 4/18/2016	EXPIRES 05/15/2017	INSPECTOR	2/13/2017
PANFILO CARRAZCO 855 W ADAMS STREET, SUITE CHICAGO, IL 60607 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/6/2017
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES
Nationally Accredited by PHAB

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	2/28/2020
100 - 07342	4/19/2019	05/15/2020	PROJECT DESIGNER	3/15/2020
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	2/28/2020
			PROJECT MANAGER	2/22/2020
			AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos

EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed