

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2842
SCHOOL NAME: Cooper Branch
ADDRESS OF SCHOOL: 1645 W. 18th Place
CITY: Chicago, IL, 60608

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 443
IDPH INSPECTOR LICENSE NUMBER: 100-03175
IDPH LICENSED INSPECTOR NAME(Please Print): Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Cooper Branch

1645 W. 18th Place
Chicago, IL, 60608

Unit: 22831
Building ID: 2891

IDPH ID Number: 14-016-2990-2842

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

November 6, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22832 Region: 00 IDPH ID:14-016-2990-2842

School: Cooper Branch Building ID: 2891

Address: 1645 W. 18th Place

Chicago, IL, 60608

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 12/06/2019

Inspector: Marcos Iwankiw

Inspector IDPH License: 100-03175

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 06, 2019

RE: Cooper Branch, Unit 22831
1645 W. 18th Place
Chicago, IL, 60608

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Cooper Branch, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Cooper Branch, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

| | | | | | |
|----------|--------------------|-------|--------------------|---------|----|
| School: | Cooper Branch | Unit: | 22832 | Region: | 00 |
| Address: | 1645 W. 18th Place | | Chicago, IL, 60608 | | |
| IDPH ID: | 14-016-2990-2842 | | Building ID: | 2891 | |
| Contact: | | | Phone: | | |

2. Description of Facility

| | |
|------------------------|--------------------------|
| Original Construction: | Additional Construction: |
| Total Square Footage: | No of Floors: |
| Current Occupancy: 443 | |

3. LEA Designated Person

| | | | |
|----------|------------------------|--------|----------------|
| Contact: | Robert Christlieb | Phone: | (773) 553-3197 |
| Address: | 42 West Madison Street | | |
| | Chicago, IL 60602 | | |

4. Managing Environmental Consultant

| | | | |
|----------|---------------------------------|------|----------------|
| MEC: | Carnow, Conibear and Associates | | |
| Contact: | Doug McCormick | | |
| Address | 600 West Van Buren St., Ste 500 | | |
| | Chicago, IL, 60607 | | |
| Phone: | (312) 762-2900 | Fax: | (312) 782-5145 |

5. Inspector

Inspector Name: Marcos Iwankiw

| | |
|------------------------------------|-----------------|
| Inspector IDPH license # 100-03175 | Signature: |
| | Date: 11/6/2019 |

6. Management Planner

Management Planner Name: Evan Christian

| | |
|---|------------------|
| Management Planner IDPH license # 100-19466 | Signature: |
| | Date: 12/06/2019 |

7. Review Date:12/06/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

| | | | |
|------------|---|-------|-----------|
| Signature: |  | Date: | 10/1/2019 |
| Name: | Robert Christlieb | | |

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Cooper Branch. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2891:

| | |
|----|---|
| 1 | 9x9 Tan w/white streaks floor tile |
| 13 | 12x12 Tan & White Floor Tile |
| 18 | Roof Chimney & Felt Edge Caulk - Non AHERA |
| 2 | 9x9 Tan w/white streaks floor tile Mastic |
| 22 | 2x4 Replacement, Fissure & Many Dot, Ceiling Tile |
| 24 | Incinerator Brick |
| 3 | 12x12 White Floor Tile |
| 30 | Baseboard |
| 31 | Baseboard Mastic |

- 4 12x12 White Floor Tile Mastic
- 5 12x12 Tan Floor Tile
- 7 2x4 Original Fissure 8 Dot Ceiling Tile
- 8 Hard Plaster
- 9 12x12 Brown Floor Tile

B. The following new homogenous areas have been identified for Building 2891:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|----|---|
| 13 | 12x12 Tan & White Floor Tile |
| 18 | Roof Chimney & Felt Edge Caulk - Non AHERA |
| 19 | Boiler Gasket (Rear) |
| 22 | 2x4 Replacement, Fissure & Many Dot, Ceiling Tile |
| 23 | Kiln Brick |
| 24 | Incinerator Brick |
| 25 | Exterior Brick - Non AHERA |
| 26 | Exterior Brick - Non AHERA |
| 28 | Old Style Black Lab Table Tops |
| 29 | Fire Doors |
| 3 | 12x12 White Floor Tile |
| 30 | Baseboard |
| 31 | Baseboard Mastic |
| 32 | 12" x 12" Lt. Gray w/Gray Specks VFT |
| 33 | 12" x 12" Lt. Gray w/Gray Specks VFT Mastic |
| 34 | 12" x 12" Green Floor Tile |
| 35 | 12" x 12" Green Floor Tile Mastic |
| 36 | 12" x 12" Blue Floor Tile |
| 37 | 12" x 12" Blue Floor Tile Mastic |
| 38 | 12" x 12" Red Floor Tile |
| 39 | 12" x 12" Red Floor Tile Mastic |
| 40 | Sink Under Coating |
| 41 | 12" x 12" Lime Green Floor Tile |
| 42 | 12" x 12" Lime Green Floor Tile Mastic |
| 43 | 12" x 12" Dark Brown W/ Streaks Floor Tile |
| 44 | 12" x 12" Dark Brown W/ Streaks Floor Tile Mastic |
| 45 | 12" x 12" Beige Floor Tile |
| 46 | 12" x 12" Beige Floor Tile Mastic |
| 5 | 12x12 Tan Floor Tile |
| 7 | 2x4 Original Fissure 8 Dot Ceiling Tile |
| 8 | Hard Plaster |
| 9 | 12x12 Brown Floor Tile |

The following areas were deemed to be inaccessible:

| | |
|----|---|
| 10 | 12x12 Brown Floor Tile Mastic |
| 14 | 12x12 Tan & White Floor Tile Mastic |
| 2 | 9x9 Tan w/white streaks floor tile Mastic |
| 31 | Baseboard Mastic |
| 33 | 12" x 12" Lt. Gray w/Gray Specks VFT Mastic |

| | |
|----|---|
| 35 | 12" x 12" Green Floor Tile Mastic |
| 37 | 12" x 12" Blue Floor Tile Mastic |
| 39 | 12" x 12" Red Floor Tile Mastic |
| 4 | 12x12 White Floor Tile Mastic |
| 42 | 12" x 12" Lime Green Floor Tile Mastic |
| 44 | 12" x 12" Dark Brown W/ Streaks Floor Tile Mastic |
| 46 | 12" x 12" Beige Floor Tile Mastic |
| 6 | 12x12 Tan Floor Tile Mastic |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Cooper Branch Building 2891 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Cooper Branch Unit 22832 Building ID 2891

Address 1645 W. 18th Place Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 1 | 9x9 Tan w/white streaks floor tile | 62,000 | SF | Auditorium Room 200, 213, Gym Teacher's Office & Bathroom (109), 128,117, 118, 119, 122, 113, 115, 124, 119A, 119B, 121, 225, 223, 234, 232, 221, 230, 219, 228, 210, 212, 214, 216, 218, 220, 211, 213, 217, 226, 215, 224, 222, 209 | CHR | MISC | N | DIST | 123 | | Yes | ACBM with the potential for damage | 5 | MODERATE |
| 10 | 12x12 Brown Floor Tile Mastic | 900 | SF | Rooms 120 and 118 (Previously listed as Room 114, Room 108, Room 108 Storage) | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 11 | Roof Felt - Non AHERA | | | Roof | CHR | MISC | | | | | No | | | |
| 12 | Roof Tar - Non AHERA | | | Roof | CHR | MISC | | | | | No | | | |
| 13 | 12x12 Tan & White Floor Tile | 125 | SF | Room 109A | ASSUMED | MISC | N | NONE | 0 | | Yes | ACBM with the potential for damage | | MODERATE |
| 14 | 12x12 Tan & White Floor Tile Mastic | 125 | SF | Room 109A | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 15 | Elbows on Fiberglass Pipe Insulation | 3,000 | LF | Groundskeeping Room, Art Room, 2nd Fl Men's Restrm, 1st flr Hall by stairwell, Hall by trophy case | CHR | TSI | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 16 | Boiler Breeching | 50 | LF | Boiler Room | AMO_CHR | TSI | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 17 | Boiler Gasket | 30 | LF | Boiler Room | CHR | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 18 | Roof Chimney & Felt Edge Caulk - Non AHERA | | | Roof | ASSUMED | MISC | | | | | Yes | | | |
| 19 | Boiler Gasket (Rear) | 30 | LF | Boiler Room | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 2 | 9x9 Tan w/white streaks floor tile Mastic | 62,000 | SF | Auditorium Room 200, 213, Gym Teacher's Office & Bathroom (109), | CHR | MISC | N | DIST | 25 | | Yes | ACBM with the potential for damage | 5 | LOW |

Chicago Public Schools

School Cooper Branch Unit 22832 Building ID 2891

Address 1645 W. 18th Place Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| | | | | 128,117, 118, 119, 122, 113, 115, 124, 119A, 119B, 121, 225, 223, 234, 232, 221, 230, 219, 228, 210, 212, 214, 216, 218, 220, 211, 213, 217, 226, 215, 224, 222, 209 | | | | | | | | | | |
| 20 | Boiler Rope Gasket (Front) | 6 | LF | Boiler Room | CHR | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 21 | Water Tank Insulation | 120 | SF | Boiler Room | CHR | TSI | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 22 | 2x4 Replacement, Fissure & Many Dot, Ceiling Tile | 1,600 | SF | Hall by Cafeteria, Hall by locker 1180, Hall by Room 224 | ASSUMED | MISC | Y | NONE | 0 | | Yes | ACBM with the potential for damage | | LOW |
| 23 | Kiln Brick | 60 | SF | Art Room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 24 | Incinerator Brick | 250 | SF | Boiler Room | ASSUMED | MISC | N | NONE | 0 | | Yes | ACBM with the potential for damage | | LOW |
| 25 | Exterior Brick - Non AHERA | | | Gym, Auditorium | ASSUMED | MISC | | | | | | | | |
| 26 | Exterior Brick - Non AHERA | | | Gym, Auditorium | ASSUMED | MISC | | | | | | | | |
| 27 | Exterior Door & Structural Caulk | 250 | LF | South Exit Door, North Main Entrance Door, East Gym Wall at South Classroom wall | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 28 | Old Style Black Lab Table Tops | 180 | SF | 200, 201 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 29 | Fire Doors | 400 | SF | Main Entrance, Stage, Gym, Northwest Entrance, Southwest Entrance | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 3 | 12x12 White Floor Tile | 8,700 | SF | North Entrance, Grounds Room Entrance, Art Room Entrance, Corridors, Cafeteria | ASSUMED | MISC | N | LOC | 8 | | Yes | ACBM with the potential for damage | 4 | HIGH |
| 30 | Baseboard | 220 | LF | Room 200, 201, 205 | ASSUMED | MISC | N | NONE | 0 | | Yes | ACBM with the potential for damage | | LOW |
| 31 | Baseboard Mastic | 220 | LF | Room 201, 200, 205 | ASSUMED | MISC | N | NONE | 0 | | Yes | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Cooper Branch Unit 22832 Building ID 2891

Address 1645 W. 18th Place Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 32 | 12" x 12" Lt. Gray w/Gray Specks VFT | 800 | SF | Main Office | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 33 | 12" x 12" Lt. Gray w/Gray Specks VFT Mastic | 800 | SF | Main Office | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 34 | 12" x 12" Green Floor Tile | 100 | SF | Room 100 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 35 | 12" x 12" Green Floor Tile Mastic | 100 | SF | Room 100 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 36 | 12" x 12" Blue Floor Tile | 100 | SF | Room 100 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 37 | 12" x 12" Blue Floor Tile Mastic | 100 | SF | Room 100 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 38 | 12" x 12" Red Floor Tile | 100 | SF | Room 100 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 39 | 12" x 12" Red Floor Tile Mastic | 100 | SF | Room 100 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 4 | 12x12 White Floor Tile Mastic | 8,700 | SF | North Entrance, Grounds Room Entrance, Art Room Entrance, Cafeteria | CHR | MISC | N | LOC | 8 | | Yes | ACBM with potential for significant damage | 5 | HIGH |
| 40 | Sink Under Coating | 8 | SF | Room 224 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 41 | 12" x 12" Lime Green Floor Tile | 180 | SF | Rm. 111 | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | MODERATE |
| 42 | 12" x 12" Lime Green Floor Tile Mastic | 180 | SF | Rm. 111 | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 43 | 12" x 12" Dark Brown W/ Streaks Floor Tile | 600 | SF | Rm. 128 | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | MODERATE |
| 44 | 12" x 12" Dark Brown W/ Streaks Floor Tile Mastic | 600 | SF | Rm. 128 | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 45 | 12" x 12" Beige Floor Tile | 200 | SF | Rm. 120 | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | MODERATE |
| 46 | 12" x 12" Beige Floor Tile Mastic | 200 | SF | Rm. 120 | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 5 | 12x12 Tan Floor Tile | 1,840 | SF | North Entrance, West Cafeteria Entrance, Art Room Entrance | ASSUMED | MISC | N | LOC | 10 | | Yes | ACBM with the potential for damage | 5 | MODERATE |
| 6 | 12x12 Tan Floor Tile Mastic | 1,840 | SF | North Entrance, West Cafeteria Entrance, Art Room Entrance | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 7 | 2x4 Original Fissure 8 Dot Ceiling Tile | 62,000 | SF | Throughout | ASSUMED | MISC | Y | NONE | 0 | | Yes | Any remaining friable ACBM or friable | | LOW |

Chicago Public Schools

School Cooper Branch **Unit** 22832 **Building ID** 2891

Address 1645 W. 18th Place **Region** 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| | | | | | | | | | | | | suspect ACBM | | |
| 8 | Hard Plaster | 11,000 | SF | Throughout | ASSUMED | SURFACE | Y | NONE | 0 | | Yes | Any remaining friable ACBM or friable suspect ACBM | | MODERATE |
| 9 | 12x12 Brown Floor Tile | 900 | SF | Rooms 120 and 118 (Previously listed as Room 114, Room 108, Room 108 Storage) | ASSUMED | MISC | N | NONE | 0 | | Yes | ACBM with the potential for damage | | MODERATE |

Chicago Public Schools

School Cooper Branch Unit 22832 Building ID 2891

Address 1645 W. 18th Place Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| | |
|---|-----------------------|
| Reinspection Date | <u>11/6/2019</u> |
| Inspector Name | <u>Marcos Iwankiw</u> |
| <u>100-03175</u> | <u>5/15/2020</u> |
| Inspector's IDPH License Number / Expiration Date | |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 1 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 2 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |
| 29 | |
| 3 | |

Chicago Public Schools

School Cooper Branch **Unit** 22832 **Building ID** 2891

Address 1645 W. 18th Place **Region** 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 30 | |
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 4 | |
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |
| 5 | |
| 6 | |
| 7 | |
| 8 | |
| 9 | |

Chicago Public Schools

School Cooper Branch **Unit** 22832 **Building ID** 2891

Address 1645 W. 18th Place **Region** 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Cooper Branch
Address 1645 W. 18th Place

Unit 22832
Chicago, IL, 60608

Building ID 2891
Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|-----------|--|-------------------|----------------|---|---------------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 1 | 9x9 Tan w/white streaks floor tile | 62,000 | SF | Auditorium Room 200, 213, Gym Teacher's Office & Bathroom (109), 128,117, 118, 119, 122, 113, 115, 124, 119A, 119B, 121, 225, 223, 234, 232, 221, 230, 219, 228, 210, 212, 214, 216, 218, 220, 211, 213, 217, 226, 215, 224, 222, 209 | Chrysotile | MISC | No | 123 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 10 | 12x12 Brown Floor Tile Mastic | 900 | SF | Rooms 120 and 118 (Previously listed as Room 114, Room 108, Room 108 Storage) | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 11 | Roof Felt - Non AHERA | | | Roof | Chrysotile | MISC | | | | | |
| 12 | Roof Tar - Non AHERA | | | Roof | Chrysotile | MISC | | | | | |
| 13 | 12x12 Tan & White Floor Tile | 125 | SF | Room 109A | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 14 | 12x12 Tan & White Floor Tile Mastic | 125 | SF | Room 109A | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 15 | Elbows on Fiberglass Pipe Insulation | 3,000 | LF | Groundskeeping Room, Art Room, 2nd Fl Men's Restrm, 1st flr Hall by stairwell, Hall by trophy case | Chrysotile | TSI | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 16 | Boiler Breeching | 50 | LF | Boiler Room | Amosite, Chrysotile | TSI | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 17 | Boiler Gasket | 30 | LF | Boiler Room | Chrysotile | MISC | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 18 | Roof Chimney & Felt Edge Caulk - Non AHERA | | | Roof | Assumed | MISC | | | | | |
| 19 | Boiler Gasket (Rear) | 30 | LF | Boiler Room | Assumed | MISC | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 2 | 9x9 Tan w/white streaks floor tile Mastic | 62,000 | SF | Auditorium Room 200, 213, Gym Teacher's Office & Bathroom (109), 128,117, 118, 119, 122, 113, 115, 124, 119A, 119B, 121, 225, 223, 234, 232, 221, 230, 219, 228, 210, 212, 214, 216, 218, 220, 211, 213, 217, 226, 215, 224, 222, 209 | Chrysotile | MISC | No | 25 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 20 | Boiler Rope Gasket (Front) | 6 | LF | Boiler Room | Chrysotile | MISC | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 21 | Water Tank Insulation | 120 | SF | Boiler Room | Chrysotile | TSI | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |

Chicago Public Schools

School Cooper Branch
Address 1645 W. 18th Place

Unit 22832
Chicago, IL, 60608

Building ID 2891
Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|-----------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 22 | 2x4 Replacement, Fissure & Many Dot, Ceiling Tile | 1,600 | SF | Hall by Cafeteria, Hall by locker 1180, Hall by Room 224 | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 23 | Kiln Brick | 60 | SF | Art Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 24 | Incinerator Brick | 250 | SF | Boiler Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 25 | Exterior Brick - Non AHERA | | | Gym, Auditorium | Assumed | MISC | | | | | |
| 26 | Exterior Brick - Non AHERA | | | Gym, Auditorium | Assumed | MISC | | | | | |
| 27 | Exterior Door & Structural Caulk | 250 | LF | South Exit Door, North Main Entrance Door, East Gym Wall at South Classroom wall | Chrysotile | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 28 | Old Style Black Lab Table Tops | 180 | SF | 200, 201 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 29 | Fire Doors | 400 | SF | Main Entrance, Stage, Gym, Northwest Entrance, Southwest Entrance | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 3 | 12x12 White Floor Tile | 8,700 | SF | North Entrance, Grounds Room Entrance, Art Room Entrance, Corridors, Cafeteria | Assumed | MISC | No | 8 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 30 | Baseboard | 220 | LF | Room 200, 201, 205 | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 31 | Baseboard Mastic | 220 | LF | Room 201, 200, 205 | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 32 | 12" x 12" Lt. Gray w/Gray Specks VFT | 800 | SF | Main Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 33 | 12" x 12" Lt. Gray w/Gray Specks VFT Mastic | 800 | SF | Main Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 34 | 12" x 12" Green Floor Tile | 100 | SF | Room 100 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 35 | 12" x 12" Green Floor Tile Mastic | 100 | SF | Room 100 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 36 | 12" x 12" Blue Floor Tile | 100 | SF | Room 100 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 37 | 12" x 12" Blue Floor Tile Mastic | 100 | SF | Room 100 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 38 | 12" x 12" Red Floor Tile | 100 | SF | Room 100 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 39 | 12" x 12" Red Floor Tile Mastic | 100 | SF | Room 100 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 4 | 12x12 White Floor Tile Mastic | 8,700 | SF | North Entrance, Grounds Room Entrance, Art Room Entrance, Cafeteria | Chrysotile | MISC | No | 8 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 40 | Sink Under Coating | 8 | SF | Room 224 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 41 | 12" x 12" Lime Green Floor Tile | 180 | SF | Rm. 111 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 42 | 12" x 12" Lime Green Floor Tile Mastic | 180 | SF | Rm. 111 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 43 | 12" x 12" Dark Brown W/ Streaks Floor Tile | 600 | SF | Rm. 128 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 44 | 12" x 12" Dark Brown W/ Streaks Floor Tile Mastic | 600 | SF | Rm. 128 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Cooper Branch
Address 1645 W. 18th Place

Unit 22832
Chicago, IL, 60608

Building ID 2891
Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|-----------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 45 | 12" x 12" Beige Floor Tile | 200 | SF | Rm. 120 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 46 | 12" x 12" Beige Floor Tile Mastic | 200 | SF | Rm. 120 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 5 | 12x12 Tan Floor Tile | 1,840 | SF | North Entrance, West Cafeteria Entrance, Art Room Entrance | Assumed | MISC | No | 10 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 6 | 12x12 Tan Floor Tile Mastic | 1,840 | SF | North Entrance, West Cafeteria Entrance, Art Room Entrance | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7 | 2x4 Original Fissure 8 Dot Ceiling Tile | 62,000 | SF | Throughout | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 8 | Hard Plaster | 11,000 | SF | Throughout | Assumed | SURFACE | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 9 | 12x12 Brown Floor Tile | 900 | SF | Rooms 120 and 118 (Previously listed as Room 114, Room 108, Room 108 Storage) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Cooper Branch
Address 1645 W. 18th Place

Unit 22832
Chicago, IL, 60608

Building ID 2891
Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|----------------|
| Review Date | 12/06/2019 |
| Manager Planner Name | Evan Christian |
| 100-19466 | 5/15/2020 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|--------------------------|
| 1 | Remove damaged materials |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 2 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |

Chicago Public Schools

School Cooper Branch
Address 1645 W. 18th Place

Unit 22832
Chicago, IL, 60608

Building ID 2891
Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 29 | |
| 3 | |
| 30 | |
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 4 | |
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |
| 5 | |
| 6 | |
| 7 | |
| 8 | |
| 9 | |

Chicago Public Schools

| | | | | | |
|----------------|--------------------|-------------|--------------------|--------------------|------|
| School | Cooper Branch | Unit | 22832 | Building ID | 2891 |
| Address | 1645 W. 18th Place | | Chicago, IL, 60608 | Region | 00 |

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

| | |
|--|--|
| Managing Environmental Consultant (MEC) | Carnow, Conibear and Associates |
| | 600 West Van Buren St., Ste 500 Chicago, Il, 60607 |
| | Phone: (312) 762-2900 |
| | Fax: (312) 782-5145 |

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 1 | | |
| MATERIAL DESCRIPTION: | 9x9 Tan w/white streaks floor tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | Physical Damage | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

| | | | |
|------------------------|---|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Auditorium Room 200, 213, Gym Teacher's Office & Bathroom (109), 128,117, 118, 119, 122, 113, 115, 124, 119A, 119B, 121, 225, 223, 234, 232, 221, 230, 219, 228, 210, 212, 214, 216, 218, 220, 211, 213, 217, 226, 215, 224, 222, 209 | | |
| MATERIAL QUANTITY: | 62000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 123 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9x9 Tan w/white streaks floor tile**

MATERIAL LOCATION: **Auditorium Room 200, 213, Gym Teacher's Office & Bathroom (109), 128, 117, 118, 119, 122, 113, 115, 124, 119A, 119B, 121, 225, 223, 234, 232, 221, 230, 219, 228, 210, 212, 214, 216, 218, 220, 211, 213, 217, 226, 215, 224, 222, 209**

MATERIAL QUANTITY: **62000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **123**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Remove damaged materials

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 10 | | |
| MATERIAL DESCRIPTION: | 12x12 Brown Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 120 and 118 (Previously listed as Room 114, Room 108, Room 108 Storage) | | |
| MATERIAL QUANTITY: | 900 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | | | |
|-----------------------|--|-----------------|-----------|--|--|
| HOMOGENEOUS AREA: | 10 | | | | |
| MATERIAL DESCRIPTION: | 12x12 Brown Floor Tile Mastic | | | | |
| MATERIAL LOCATION: | Rooms 120 and 118 (Previously listed as Room 114, Room 108, Room 108 Storage) | | | | |
| MATERIAL QUANTITY: | 900 | MATERIAL UNITS: | SF | | |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF | | |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------|----------|
| HOMOGENEOUS AREA: | 11 | |
| MATERIAL DESCRIPTION: | Roof Felt - Non AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Roof Felt - Non AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------------|----------|
| HOMOGENEOUS AREA: | 12 | |
| MATERIAL DESCRIPTION: | Roof Tar - Non AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Roof Tar - Non AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 13 | | |
| MATERIAL DESCRIPTION: | 12x12 Tan & White Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 109A | | |
| MATERIAL QUANTITY: | 125 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12x12 Tan & White Floor Tile**

MATERIAL LOCATION: **Room 109A**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 125 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 14 | | |
| MATERIAL DESCRIPTION: | 12x12 Tan & White Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 109A | | |
| MATERIAL QUANTITY: | 125 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12x12 Tan & White Floor Tile Mastic**

MATERIAL LOCATION: **Room 109A**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 125 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 15 | | |
| MATERIAL DESCRIPTION: | Elbows on Fiberglass Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Groundskeeping Room, Art Room, 2nd Fl Men's Restrm, 1st flr Hall by stairwell, Hall by trophy case | | |
| MATERIAL QUANTITY: | 3000 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | | | |
|-----------------------|---|-----------------|-----------|--|--|
| HOMOGENEOUS AREA: | 15 | | | | |
| MATERIAL DESCRIPTION: | Elbows on Fiberglass Pipe Insulation | | | | |
| MATERIAL LOCATION: | Groundskeeping Room, Art Room, 2nd Fl Men's Restrm, 1st flr Hall by stairwell, Hall by trophy case | | | | |
| MATERIAL QUANTITY: | 3000 | MATERIAL UNITS: | LF | | |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF | | |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 16 | | |
| MATERIAL DESCRIPTION: | Boiler Breeching | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Amosite, Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room | | |
| MATERIAL QUANTITY: | 50 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Boiler Breeching**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 17 | | |
| MATERIAL DESCRIPTION: | Boiler Gasket | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room | | |
| MATERIAL QUANTITY: | 30 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Boiler Gasket**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--|----------|
| HOMOGENEOUS AREA: | 18 | |
| MATERIAL DESCRIPTION: | Roof Chimney & Felt Edge Caulk - Non AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Roof Chimney & Felt Edge Caulk - Non AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 19 | | |
| MATERIAL DESCRIPTION: | Boiler Gasket (Rear) | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room | | |
| MATERIAL QUANTITY: | 30 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Boiler Gasket (Rear)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 2 | | |
| MATERIAL DESCRIPTION: | 9x9 Tan w/white streaks floor tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | Physical Damage | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

| | | | |
|------------------------|---|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Auditorium Room 200, 213, Gym Teacher's Office & Bathroom (109), 128,117, 118, 119, 122, 113, 115, 124, 119A, 119B, 121, 225, 223, 234, 232, 221, 230, 219, 228, 210, 212, 214, 216, 218, 220, 211, 213, 217, 226, 215, 224, 222, 209 | | |
| MATERIAL QUANTITY: | 62000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 25 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

| | | | |
|------------------------|-------|-------|------------|
| Inspector's Signature: | _____ | Date: | 11/06/2019 |
|------------------------|-------|-------|------------|

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **9x9 Tan w/white streaks floor tile Mastic**

MATERIAL LOCATION: **Auditorium Room 200, 213, Gym Teacher's Office & Bathroom (109), 128, 117, 118, 119, 122, 113, 115, 124, 119A, 119B, 121, 225, 223, 234, 232, 221, 230, 219, 228, 210, 212, 214, 216, 218, 220, 211, 213, 217, 226, 215, 224, 222, 209**

MATERIAL QUANTITY: **62000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **25**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 20 | | |
| MATERIAL DESCRIPTION: | Boiler Rope Gasket (Front) | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room | | |
| MATERIAL QUANTITY: | 6 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Boiler Rope Gasket (Front)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **6**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 21 | | |
| MATERIAL DESCRIPTION: | Water Tank Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room | | |
| MATERIAL QUANTITY: | 120 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Water Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 120 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----|
| HOMOGENEOUS AREA: | 22 | | |
| MATERIAL DESCRIPTION: | 2x4 Replacement, Fissure & Many Dot, Ceiling Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Hall by Cafeteria, Hall by locker 1180, Hall by Room 224 | | |
| MATERIAL QUANTITY: | 1600 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|---|-----------------|-----------|
| HOMOGENEOUS AREA: | 22 | | |
| MATERIAL DESCRIPTION: | 2x4 Replacement, Fissure & Many Dot, Ceiling Tile | | |
| MATERIAL LOCATION: | Hall by Cafeteria, Hall by locker 1180, Hall by Room 224 | | |
| MATERIAL QUANTITY: | 1600 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 23 | | |
| MATERIAL DESCRIPTION: | Kiln Brick | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Art Room | | |
| MATERIAL QUANTITY: | 60 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|-------------------|-----------------|-----------|
| HOMOGENEOUS AREA: | 23 | | |
| MATERIAL DESCRIPTION: | Kiln Brick | | |
| MATERIAL LOCATION: | Art Room | | |
| MATERIAL QUANTITY: | 60 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 24 | | |
| MATERIAL DESCRIPTION: | Incinerator Brick | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room | | |
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Incinerator Brick**

MATERIAL LOCATION: **Boiler Room**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------------------|----------|
| HOMOGENEOUS AREA: | 25 | |
| MATERIAL DESCRIPTION: | Exterior Brick - Non AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym, Auditorium

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Exterior Brick - Non AHERA**

MATERIAL LOCATION: **Gym, Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------------------|----------|
| HOMOGENEOUS AREA: | 26 | |
| MATERIAL DESCRIPTION: | Exterior Brick - Non AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym, Auditorium

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Exterior Brick - Non AHERA**

MATERIAL LOCATION: **Gym, Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 27 | | |
| MATERIAL DESCRIPTION: | Exterior Door & Structural Caulk | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | South Exit Door, North Main Entrance Door, East Gym Wall at South Classroom wall | | |
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Exterior Door & Structural Caulk**

MATERIAL LOCATION: **South Exit Door, North Main Entrance Door, East Gym Wall at South Classroom wall**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | LF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 28 | | |
| MATERIAL DESCRIPTION: | Old Style Black Lab Table Tops | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | 200, 201 | | |
| MATERIAL QUANTITY: | 180 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Old Style Black Lab Table Tops**

MATERIAL LOCATION: **200, 201**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 180 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 29 | | |
| MATERIAL DESCRIPTION: | Fire Doors | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Main Entrance, Stage, Gym, Northwest Entrance, Southwest Entrance | | |
| MATERIAL QUANTITY: | 400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **Main Entrance, Stage, Gym, Northwest Entrance, Southwest Entrance**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 400 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 3 | | |
| MATERIAL DESCRIPTION: | 12x12 White Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with potential for significant damage | | |
| HISTORICAL DAMAGE REASON: | Other | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

| | | | |
|------------------------|--|-----------------|----|
| DAMAGE REASON: | Other | | |
| DISTURBANCE POTENTIAL: | HIGH | | |
| MATERIAL LOCATION: | North Entrance, Grounds Room Entrance, Art Room Entrance, Corridors, Cafeteria | | |
| MATERIAL QUANTITY: | 8700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 8 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | | | |
|-----------------------|---|-----------------|-----------|--|--|
| HOMOGENEOUS AREA: | 3 | | | | |
| MATERIAL DESCRIPTION: | 12x12 White Floor Tile | | | | |
| MATERIAL LOCATION: | North Entrance, Grounds Room Entrance, Art Room Entrance, Corridors, Cafeteria | | | | |
| MATERIAL QUANTITY: | 8700 | MATERIAL UNITS: | SF | | |
| DAMAGE QUANTITY: | 8 | DAMAGE UNITS: | SF | | |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 30 | | |
| MATERIAL DESCRIPTION: | Baseboard | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 200, 201, 205 | | |
| MATERIAL QUANTITY: | 220 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|---------------------------|-----------------|-----------|
| HOMOGENEOUS AREA: | 30 | | |
| MATERIAL DESCRIPTION: | Baseboard | | |
| MATERIAL LOCATION: | Room 200, 201, 205 | | |
| MATERIAL QUANTITY: | 220 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 31 | | |
| MATERIAL DESCRIPTION: | Baseboard Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 201, 200, 205 | | |
| MATERIAL QUANTITY: | 220 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Room 201, 200, 205**

MATERIAL QUANTITY: **220**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 32 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Lt. Gray w/Gray Specks VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Main Office | | |
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Lt. Gray w/Gray Specks VFT**

MATERIAL LOCATION: **Main Office**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 33 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Lt. Gray w/Gray Specks VFT Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Main Office | | |
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" Lt. Gray w/Gray Specks VFT Mastic**

MATERIAL LOCATION: **Main Office**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 34 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Green Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 100 | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**

MATERIAL LOCATION: **Room 100**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 35 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Green Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 100 | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**

MATERIAL LOCATION: **Room 100**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 36 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Blue Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 100 | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Room 100**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 37 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Blue Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 100 | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 100**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 38 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Red Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 100 | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **Room 100**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 39 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Red Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 100 | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **Room 100**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 4 | | |
| MATERIAL DESCRIPTION: | 12x12 White Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with potential for significant damage | | |
| HISTORICAL DAMAGE REASON: | Physical Damage | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

| | | | |
|------------------------|---|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | HIGH | | |
| MATERIAL LOCATION: | North Entrance, Grounds Room Entrance, Art Room Entrance, Cafeteria | | |
| MATERIAL QUANTITY: | 8700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 8 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|--|-----------------|-----------|
| HOMOGENEOUS AREA: | 4 | | |
| MATERIAL DESCRIPTION: | 12x12 White Floor Tile Mastic | | |
| MATERIAL LOCATION: | North Entrance, Grounds Room Entrance, Art Room Entrance, Cafeteria | | |
| MATERIAL QUANTITY: | 8700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 8 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 40 | | |
| MATERIAL DESCRIPTION: | Sink Under Coating | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 224 | | |
| MATERIAL QUANTITY: | 8 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Sink Under Coating**

MATERIAL LOCATION: **Room 224**

MATERIAL QUANTITY: **8**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 41 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Lime Green Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Rm. 111 | | |
| MATERIAL QUANTITY: | 180 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" x 12" Lime Green Floor Tile**

MATERIAL LOCATION: **Rm. 111**

MATERIAL QUANTITY: **180**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 42 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Lime Green Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rm. 111 | | |
| MATERIAL QUANTITY: | 180 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" x 12" Lime Green Floor Tile Mastic**

MATERIAL LOCATION: **Rm. 111**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 180 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 43 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Dark Brown W/ Streaks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Rm. 128 | | |
| MATERIAL QUANTITY: | 600 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown W/ Streaks Floor Tile**

MATERIAL LOCATION: **Rm. 128**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 600 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 44 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Dark Brown W/ Streaks Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rm. 128 | | |
| MATERIAL QUANTITY: | 600 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown W/ Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rm. 128**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 600 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 45 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Beige Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Rm. 120 | | |
| MATERIAL QUANTITY: | 200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|-----------------------------------|-----------------|-----------|
| HOMOGENEOUS AREA: | 45 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Beige Floor Tile | | |
| MATERIAL LOCATION: | Rm. 120 | | |
| MATERIAL QUANTITY: | 200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 46 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Beige Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rm. 120 | | |
| MATERIAL QUANTITY: | 200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Rm. 120**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 200 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 5 | | |
| MATERIAL DESCRIPTION: | 12x12 Tan Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

| | | | |
|------------------------|--|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | North Entrance, West Cafeteria Entrance, Art Room Entrance | | |
| MATERIAL QUANTITY: | 1840 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 10 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|---|-----------------|-----------|
| HOMOGENEOUS AREA: | 5 | | |
| MATERIAL DESCRIPTION: | 12x12 Tan Floor Tile | | |
| MATERIAL LOCATION: | North Entrance, West Cafeteria Entrance, Art Room Entrance | | |
| MATERIAL QUANTITY: | 1840 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 10 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 6 | | |
| MATERIAL DESCRIPTION: | 12x12 Tan Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | North Entrance, West Cafeteria Entrance, Art Room Entrance | | |
| MATERIAL QUANTITY: | 1840 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|---|-----------------|-----------|
| HOMOGENEOUS AREA: | 6 | | |
| MATERIAL DESCRIPTION: | 12x12 Tan Floor Tile Mastic | | |
| MATERIAL LOCATION: | North Entrance, West Cafeteria Entrance, Art Room Entrance | | |
| MATERIAL QUANTITY: | 1840 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 7 | | |
| MATERIAL DESCRIPTION: | 2x4 Original Fissure 8 Dot Ceiling Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout | | |
| MATERIAL QUANTITY: | 62000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **2x4 Original Fissure 8 Dot Ceiling Tile**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **62000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 8 | | |
| MATERIAL DESCRIPTION: | Hard Plaster | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|------------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Throughout | | |
| MATERIAL QUANTITY: | 11000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Hard Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **11000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Cooper Branch | INSPECTION DATE: | 11/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 9 | | |
| MATERIAL DESCRIPTION: | 12x12 Brown Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Rooms 120 and 118 (Previously listed as Room 114, Room 108, Room 108 Storage) | | |
| MATERIAL QUANTITY: | 900 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 11/06/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22832 | BUILDING ID: | 2891 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Cooper Branch | REVIEW DATE: | 12/6/2019 | | |
| ADDRESS: | 1645 W. 18th Place | IDPH LICENSE NO: | 100-03175 | | |

| | | | | | |
|-----------------------|--|-----------------|-----------|--|--|
| HOMOGENEOUS AREA: | 9 | | | | |
| MATERIAL DESCRIPTION: | 12x12 Brown Floor Tile | | | | |
| MATERIAL LOCATION: | Rooms 120 and 118 (Previously listed as Room 114, Room 108, Room 108 Storage) | | | | |
| MATERIAL QUANTITY: | 900 | MATERIAL UNITS: | SF | | |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF | | |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/06/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019



Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|------|--|
| MATERIAL | | |
| | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | | |
| | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | | |
| | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | | |
| | Loc | Localized |
| | Dist | Distributed |