

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2256
SCHOOL NAME: Hedges School
ADDRESS OF SCHOOL: 4735 S. Winchester
CITY: Chicago, IL, 60609

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/6/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 568
IDPH INSPECTOR LICENSE NUMBER: 100-03175
IDPH LICENSED INSPECTOR NAME(Please Print): Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Hedges School

4735 S. Winchester
Chicago, IL, 60609

Unit: 23681
Building ID: 3900

IDPH ID Number: 14-016-2990-2256

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 25, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23681 Region: 04 IDPH ID:14-016-2990-2256

School: Hedges School Building ID: 3900

Address: 4735 S. Winchester

Chicago, IL, 60609

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 05/09/2019

Inspector: Marcos Iwankiw

Inspector IDPH License: 100-03175

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 25, 2019

RE: Hedges School, Unit 23681
4735 S. Winchester
Chicago, IL, 60609

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Hedges School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Hedges School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

| | | | | | |
|----------|--------------------|--------------|-------|---------|----|
| School: | Hedges School | Unit: | 23681 | Region: | 04 |
| Address: | 4735 S. Winchester | Chicago, IL, | 60609 | | |
| IDPH ID: | 14-016-2990-2256 | Building ID: | 3900 | | |
| Contact: | | Phone: | | | |

2. Description of Facility

| | | | |
|------------------------|-------|--------------------------|------|
| Original Construction: | 1906 | Additional Construction: | 1997 |
| Total Square Footage: | 50925 | No of Floors: | 3 |
| Current Occupancy: | 568 | | |

3. LEA Designated Person

| | | | |
|----------|------------------------|--------|----------------|
| Contact: | Robert Christlieb | Phone: | (773) 553-3197 |
| Address: | 42 West Madison Street | | |
| | Chicago, IL 60602 | | |

4. Managing Environmental Consultant

| | | | |
|----------|---------------------------------|------|----------------|
| MEC: | Carnow, Conibear and Associates | | |
| Contact: | Doug McCormick | | |
| Address | 600 West Van Buren St., Ste 500 | | |
| | Chicago, IL, 60607 | | |
| Phone: | (312) 762-2900 | Fax: | (312) 782-5145 |

5. Inspector

Inspector Name: Marcos Iwankiw

Inspector IDPH license # 100-03175

Signature:
Date: 4/25/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 05/09/2019

7. Review Date:05/09/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hedges School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3900:

| | |
|----|--|
| 30 | 12" x 12" Multi-Brown Floor Tile |
| 3C | 9" x 9" Brown Floor Tile w/White Streaks |
| 3E | 9" x 9" Beige Floor Tile w/Blue Streaks |

B. The following new homogenous areas have been identified for Building 3900:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|----|---|
| 1 | Plaster |
| 2 | 2' x 4' Ceiling Panels |
| 26 | 2' x 4' White Ceiling Panels |
| 28 | 12" x 12" Multi-Blue Floor Tile |
| 30 | 12" x 12" Multi-Brown Floor Tile |
| 34 | 12" x 12" Off-White Floor Tile w/Gray Streaks |
| 3E | 9" x 9" Beige Floor Tile w/Blue Streaks |
| 3F | 9" x 9" Tan Floor Tile w/ Brown Streaks |
| 42 | Roofing Material - Not AHERA |
| 43 | Roof Flashing - Not AHERA |
| 44 | Insulation Inside of Vault Door |
| 45 | Gray Carpet Mastic |
| 46 | Drywall and Associated Joint Compound |
| 47 | 12" x 12" Beige Floor Tile |
| 48 | 12" x 12" Beige Floor Tile Mastic |
| 5 | Ceramic Tile Grout |
| 55 | 12" x 12" Blue Floor Tile |
| 6 | Red and Tan Ceramic Tile Grout |
| 60 | Blue/Orange Carpet Adhesive |
| 61 | Duct Caulk |
| 62 | Marker Board/Poster Board Adhesive |
| 63 | Spray-on Insulation |
| 64 | Duct Caulk |
| 65 | Tar Paper |
| 66 | Black Sealant |
| 67 | Green Stage Curtains |
| 68 | Gold/Brown Mix Carpet Adhesive |
| 69 | Asbestos Insulated Wire |
| 70 | 12"x12" Grey Speckled VFT |
| 71 | 12" x 12" Gray Speckled Floor Tile Mastic |
| 8 | Insulation in Fire Doors |
| E | Cardboard Pipe Insulation |
| F | Cardboard Pipe Insulation Joints |
| H | Aircell Pipe Insulation |
| I | Aircell Pipe Insulation Joints |
| K | Fiberglass Insulation Joints |

The following areas were deemed to be inaccessible:

| | |
|----|--------------------------------|
| 13 | Cementitious Material on Seams |
|----|--------------------------------|

| | |
|----|--|
| 44 | Insulation Inside of Vault Door |
| 45 | Gray Carpet Mastic |
| 46 | Drywall and Associated Joint Compound |
| 48 | 12" x 12" Beige Floor Tile Mastic |
| 4A | 9" x 9" Beige w/Brown Streaks Floor Tile Mastic |
| 4B | 9" x 9" Tan Floor Tile w/Brn & Wh Streaks Mastic |
| 4C | 9" x 9" Brown Floor Tile w/White Streaks Mastic |
| 4D | 9" x 9" Rusty Brown Speckled Floor Tile Mastic |
| 4E | 9" x 9" Beige Floor Tile w/Blue Streaks Mastic |
| 4F | 9" x 9" Tan Floor Tile w/Brown Streaks Mastic |
| 71 | 12" x 12" Gray Speckled Floor Tile Mastic |
| 8 | Insulation in Fire Doors |
| H | Aircell Pipe Insulation |
| I | Aircell Pipe Insulation Joints |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Hedges School Building 3900 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Hedges School Unit 23681 Building ID 3900

Address 4735 S. Winchester Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 1 | Plaster | 100,607 | SF | Throughout Facility | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 10 | Firebrick | | | Boiler by Outside Wall | NO_ACBM | MISC | | | | | | | | |
| 11 | Refractory Cement on Boiler Doors | | | Boiler by Inside Wall | NO_ACBM | MISC | | | | | | | | |
| 12 | Refractory Cement on Boiler Doors | | | Boiler by Outside Wall | NO_ACBM | MISC | | | | | | | | |
| 13 | Cementitious Material on Seams | 30 | LF | Boiler by Inside Wall | CHR | TSI | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 14 | Cementitious Material on Side of Boiler | | | Boiler by Outside Wall | NO_ACBM | MISC | | | | | | | | |
| 15 | Cementitious Material on Side of Boiler | | | Boiler by Inside Wall | NO_ACBM | MISC | | | | | | | | |
| 16 | Cementitious Material on Seams | | | Boiler by Outside Wall | NO_ACBM | MISC | | | | | | | | |
| 17 | Interior Brick | | | Basement | NO_ACBM | MISC | | | | | | | | |
| 18 | Interior Brick Mortar | | | Throughout Basement | NO_ACBM | MISC | | | | | | | | |
| 19 | Cinder Block | | | Throughout Facility | NO_ACBM | MISC | | | | | | | | |
| 2 | 2' x 4' Ceiling Panels | 11,096 | SF | Throughout Facility | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 20 | Cinder Block Mortar | | | Basement | NO_ACBM | | | | | | | | | |
| 21 | Block | | | Boiler Room | NO_ACBM | | | | | | | | | |
| 22 | Block Mortar | | | Boiler Room | NO_ACBM | | | | | | | | | |
| 23 | Glazed (Finished) Brick Mortar | | | Boy's and Girl's Washrooms | NO_ACBM | | | | | | | | | |
| 24 | Glazed (Finished) Block Mortar | | | Boy's and Girl's Washrooms | NO_ACBM | MISC | | | | | | | | |
| 25 | Terrazzo Flooring | | | Tank Room, Engineer's Office | NO_ACBM | MISC | | | | | | | | |
| 26 | 2' x 4' White Ceiling Panels | 6,000 | SF | Throughout the 1996 Building | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 27 | Material Beneath Floor Tile | | | Room 111 | NO_ACBM | MISC | | | | | | | | |
| 28 | 12" x 12" Multi-Blue Floor Tile | | | Room 110 | ASSUMED | MISC | | | | | | | | |
| 29 | 12" x 12" Multi-Blue Floor Tile Mastic | | | Room 110 | NO_ACBM | MISC | | | | | | | | |
| 30 | 12" x 12" Multi-Brown Floor Tile | 1,400 | SF | Room 112 | ASSUMED | MISC | N | LOC | 30 | | Yes | ACBM with potential for significant damage | 3 | LOW |
| 31 | 12" x 12" Multi-Brown Floor Tile Mastic | | | Room 112 | NO_ACBM | MISC | | | | | | | | |

Chicago Public Schools

School Hedges School Unit 23681 Building ID 3900

Address 4735 S. Winchester Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 32 | 2' x 4' Ceiling Panels | | | Room 110 & 112 | NO_ACBM | MISC | | | | | | | | |
| 33 | Carpet Mastic | | | Auditorium | NO_ACBM | MISC | | | | | | | | |
| 34 | 12" x 12" Off-White Floor Tile w/Gray Streaks | | | Rooms 212 & 216 | ASSUMED | MISC | | | | | | | | |
| 35 | 12"x12" Off-White Floor Tile w/Gray Streaks Mastic | | | Rooms 212 & 216 | NO_ACBM | MISC | | | | | | | | |
| 36 | Interior Window Glazing | | | Rooms 110, 215, 312 | NO_ACBM | MISC | | | | | | | | |
| 37 | Exterior Brick - Non AHERA | | | Exterior of Building | NO_ACBM | MISC | | | | | | | | |
| 38 | Exterior Brick Mortar - Not AHERA | | | Exterior of Building | NO_ACBM | MISC | | | | | | | | |
| 39 | Exterior Door Caulk - Not AHERA | | | | CHR | MISC | | | | | | | | |
| 3A | 9" x 9" Beige Floor Tile w/Brown Streaks | 300 | SF | Corridors on 1st, 2nd, & 3rd Floors | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 3B | 9" x 9" Tan Floor Tile w/Brown & White Streaks | 700 | SF | Room 111 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 3C | 9" x 9" Brown Floor Tile w/White Streaks | 700 | SF | Corridors on 1st, 2nd Floors, 3rd floors | CHR | MISC | N | LOC | 40 | | Yes | ACBM with potential for significant damage | 3 | LOW |
| 3D | 9" x 9" Rusty Brown Speckled Floor Tile | 1,400 | SF | Room 215 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 3E | 9" x 9" Beige Floor Tile w/Blue Streaks | 1,352 | SF | Rooms 210 and 312 | ASSUMED | MISC | N | LOC | 30 | | Yes | ACBM with potential for significant damage | 3 | LOW |
| 3F | 9" x 9" Tan Floor Tile w/ Brown Streaks | 5,500 | SF | 3rd Floor Corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 40 | Exterior Window Caulk - Not AHERA | | | | NO_ACBM | MISC | | | | | | | | |
| 41 | Exterior Block Mortar - Not AHERA | | | | NO_ACBM | MISC | | | | | | | | |
| 42 | Roofing Material - Not AHERA | | | Main Building | ASSUMED | MISC | | | | | | | | |
| 43 | Roof Flashing - Not AHERA | | | | ASSUMED | MISC | | | | | | | | |
| 44 | Insulation Inside of Vault Door | 32 | SF | Office | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 45 | Gray Carpet Mastic | 8,430 | SF | Office Complex | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 46 | Drywall and Associated Joint Compound | 1,500 | SF | 100, 101, 105, Washrooms, 200, Btwn 202 & 204, Btwn 203 & 205, 206, Btwn 300 & 301, Btwn 303 & 305 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 47 | 12" x 12" Beige Floor Tile | 800 | SF | Room 306 - 1911 Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 48 | 12" x 12" Beige Floor Tile Mastic | 800 | SF | Room 306 - 1911 Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Hedges School Unit 23681 Building ID 3900

Address 4735 S. Winchester Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 49 | 2' x 4' Fissured Ceiling Panels | | | Throughout South Building | NO_ACBM | MISC | | | | | | | | |
| 4A | 9" x 9" Beige w/Brown Streaks Floor Tile Mastic | 300 | SF | Corridors on 1st and 2nd Floors | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 4B | 9" x 9" Tan Floor Tile w/Brn & Wh Streaks Mastic | 700 | SF | Room 111 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 4C | 9" x 9" Brown Floor Tile w/White Streaks Mastic | 700 | SF | Corridors on 1st and 2nd Floors | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 4D | 9" x 9" Rusty Brown Speckled Floor Tile Mastic | 1,400 | SF | Room 215 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 4E | 9" x 9" Beige Floor Tile w/Blue Streaks Mastic | 2,000 | SF | Rooms 210, 212, 312 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 4F | 9" x 9" Tan Floor Tile w/Brown Streaks Mastic | 300 | SF | 3rd Floor Corridor | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 5 | Ceramic Tile Grout | 50 | SF | Entrances | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 50 | 4" Dark Blue Vinyl Baseboard | | | Throughout South Building | NO_ACBM | | | | | | | | | |
| 51 | 4" Dark Blue Vinyl Baseboard Mastic | | | Throughout South Building | NO_ACBM | MISC | | | | | | | | |
| 52 | Soundproofing Material on Bottoms of Sinks | | | Rooms 100, 101, 103, 105 | NO_ACBM | MISC | | | | | | | | |
| 53 | Cinder Block | | | Throughout South Building | NO_ACBM | MISC | | | | | | | | |
| 54 | Cinder Block Mortar | | | Throughout South Building | NO_ACBM | MISC | | | | | | | | |
| 55 | 12" x 12" Blue Floor Tile | 180 | SF | Washroom Across From 105 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 56 | 12" x 12" Blue Floor Tile Mastic | | | Washroom Across From 105 | NO_ACBM | MISC | | | | | | | | |
| 57 | 2' x 4' Smooth Ceiling Panels | | | Kitchen and lunch Room | NO_ACBM | MISC | | | | | | | | |
| 58 | Interior Window Caulk | | | Throughout South Building | NO_ACBM | MISC | | | | | | | | |
| 59 | Stored Gaskets | | | Engineers Storage | CHR | MISC | | None | | | | | | Low |
| 6 | Red and Tan Ceramic Tile Grout | 150 | SF | Washrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 60 | Blue/Orange Carpet Adhesive | 3,020 | SF | Room 306, Main Office | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 61 | Duct Caulk | 500 | LF | Mechanical Room/South Building, Gym | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 62 | Marker Board/Poster Board Adhesive | 3,584 | SF | All Classrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Hedges School Unit 23681 Building ID 3900

Address 4735 S. Winchester Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 63 | Spray-on Insulation | 15,000 | SF | South Building 1st & 2nd Floor | ASSUMED | SURFACE | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 64 | Duct Caulk | 500 | LF | Attic in North Building, Throughout Basement | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 65 | Tar Paper | 200 | SF | Attic in North Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 66 | Black Sealant | 900 | SF | At Links Between North & South Building Construction | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 67 | Green Stage Curtains | 1,000 | SF | Assembly Hall | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 68 | Gold/Brown Mix Carpet Adhesive | | | Room 010 | ASSUMED | MISC | | None | | | | | | Low |
| 69 | Asbestos Insulated Wire | 100 | LF | Engineers Storage room in cabinet | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 7 | Multi-Brown Rubber Tile Grout | | | Boy's and Girl's Washrooms | NO_ACBM | MISC | | | | | | | | |
| 70 | 12"x12" Grey Speckled VFT | 44,068 | SF | South Building Elevator, All Classrooms, South Building Corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 71 | 12" x 12" Gray Speckled Floor Tile Mastic | 44,068 | SF | South Building Elevator, All Classrooms, South Building Corridors | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 8 | Insulation in Fire Doors | 30 | SF | Entrances, Exits, Boiler Room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 9 | Firebrick | | | Boiler By Inside Wall | NO_ACBM | MISC | | | | | | | | |
| A1 | Boiler Insulation - ABATED | | | Boiler By Inside Wall | ABATED | TSI | | | | | | | | |
| A2 | Boiler Insulation - ABATED | | | Boiler By Outside Wall | ABATED | TSI | | | | | | | | |
| B-01 | Boiler Gaskets - ABATED | | | Boiler By Inside Wall | ABATED | MISC | | | | | | | | |
| B-02 | Boiler Gaskets ABATED | | | Boiler By Outside Wall | ABATED | MISC | | | | | | | | |
| C | Mag Block Pipe Insulation ABATED | | | Boiler Room | ABATED | TSI | | | | | | | | |
| E | Cardboard Pipe Insulation | 100 | LF | Basement | ASSUMED | TSI | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |

Chicago Public Schools

School Hedges School **Unit** 23681 **Building ID** 3900

Address 4735 S. Winchester **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| F | Cardboard Pipe Insulation Joints | 10 | LF | Basement | ASSUMED | TSI | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| G | Tank Insulation | | | Tank Room | NO_ACBM | TSI | | | | | | | | |
| H | Aircell Pipe Insulation | 200 | LF | In Inaccessible Areas Throughout Facility | ASSUMED | TSI | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| I | Aircell Pipe Insulation Joints | 15 | LF | In Inaccessible Areas Throughout Facility | ASSUMED | TSI | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| J | Fiberglass Pipe Insulation | | | Basement | NOT_TESTED | TSI | | | | | | | | |
| K | Fiberglass Insulation Joints | 30 | LF | Basement | ASSUMED | TSI | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |

Chicago Public Schools

School Hedges School Unit 23681 Building ID 3900

Address 4735 S. Winchester Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| | |
|---|-----------------------|
| Reinspection Date | <u>4/25/2019</u> |
| Inspector Name | <u>Marcos Iwankiw</u> |
| <u>100-03175</u> | <u>5/15/2020</u> |
| Inspector's IDPH License Number / Expiration Date | |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 1 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 2 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | Not observed 2019 |
| 29 | |
| 30 | |

Chicago Public Schools

School Hedges School **Unit** 23681 **Building ID** 3900

Address 4735 S. Winchester **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 31 | |
| 32 | |
| 33 | |
| 34 | Not observed 2019 |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 3A | |
| 3B | |
| 3C | |
| 3D | |
| 3E | |
| 3F | |
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |
| 47 | |
| 48 | |
| 49 | |
| 4A | |
| 4B | |
| 4C | |
| 4D | |

Chicago Public Schools

School Hedges School **Unit** 23681 **Building ID** 3900

Address 4735 S. Winchester **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 4E | |
| 4F | |
| 5 | |
| 50 | |
| 51 | |
| 52 | |
| 53 | |
| 54 | |
| 55 | |
| 56 | |
| 57 | |
| 58 | |
| 59 | Not observed 2019 |
| 6 | |
| 60 | |
| 61 | |
| 62 | |
| 63 | |
| 64 | |
| 65 | |
| 66 | |
| 67 | |
| 68 | Not observed 2019 |
| 69 | |
| 7 | |
| 70 | |
| 71 | |
| 8 | |
| 9 | |

Chicago Public Schools

School Hedges School **Unit** 23681 **Building ID** 3900

Address 4735 S. Winchester **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| A1 | |
| A2 | |
| B-01 | |
| B-02 | |
| C | |
| E | |
| F | |
| G | |
| H | |
| I | |
| J | |
| K | |

Table II

Management Planner's Review

Chicago Public Schools

School Hedges School
Address 4735 S. Winchester

Unit 23681
Chicago, IL, 60609

Building ID 3900
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|-----------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 1 | Plaster | 100,607 | SF | Throughout Facility | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 10 | Firebrick | | | Boiler by Outside Wall | No ACBM | MISC | | | | | |
| 11 | Refractory Cement on Boiler Doors | | | Boiler by Inside Wall | No ACBM | MISC | | | | | |
| 12 | Refractory Cement on Boiler Doors | | | Boiler by Outside Wall | No ACBM | MISC | | | | | |
| 13 | Cementitious Material on Seams | 30 | LF | Boiler by Inside Wall | Chrysotile | TSI | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 14 | Cementitious Material on Side of Boiler | | | Boiler by Outside Wall | No ACBM | MISC | | | | | |
| 15 | Cementitious Material on Side of Boiler | | | Boiler by Inside Wall | No ACBM | MISC | | | | | |
| 16 | Cementitious Material on Seams | | | Boiler by Outside Wall | No ACBM | MISC | | | | | |
| 17 | Interior Brick | | | Basement | No ACBM | MISC | | | | | |
| 18 | Interior Brick Mortar | | | Throughout Basement | No ACBM | MISC | | | | | |
| 19 | Cinder Block | | | Throughout Facility | No ACBM | MISC | | | | | |
| 2 | 2' x 4' Ceiling Panels | 11,096 | SF | Throughout Facility | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 20 | Cinder Block Mortar | | | Basement | No ACBM | | | | | | |
| 21 | Block | | | Boiler Room | No ACBM | | | | | | |
| 22 | Block Mortar | | | Boiler Room | No ACBM | | | | | | |
| 23 | Glazed (Finished) Brick Mortar | | | Boy's and Girl's Washrooms | No ACBM | | | | | | |
| 24 | Glazed (Finished) Block Mortar | | | Boy's and Girl's Washrooms | No ACBM | MISC | | | | | |
| 25 | Terrazzo Flooring | | | Tank Room, Engineer's Office | No ACBM | MISC | | | | | |
| 26 | 2' x 4' White Ceiling Panels | 6,000 | SF | Throughout the 1996 Building | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 27 | Material Beneath Floor Tile | | | Room 111 | No ACBM | MISC | | | | | |
| 28 | 12" x 12" Multi-Blue Floor Tile | | | Room 110 | Assumed | MISC | | | | | Follow O&M Plan |
| 29 | 12" x 12" Multi-Blue Floor Tile Mastic | | | Room 110 | No ACBM | MISC | | | | | |
| 30 | 12" x 12" Multi-Brown Floor Tile | 1,400 | SF | Room 112 | Assumed | MISC | No | 30 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 31 | 12" x 12" Multi-Brown Floor Tile Mastic | | | Room 112 | No ACBM | MISC | | | | | |
| 32 | 2' x 4' Ceiling Panels | | | Room 110 & 112 | No ACBM | MISC | | | | | |
| 33 | Carpet Mastic | | | Auditorium | No ACBM | MISC | | | | | |
| 34 | 12" x 12" Off-White Floor Tile w/Gray Streaks | | | Rooms 212 & 216 | Assumed | MISC | | | | | |
| 35 | 12"x12" Off-White Floor Tile w/Gray Streaks Mastic | | | Rooms 212 & 216 | No ACBM | MISC | | | | | |

Chicago Public Schools

School Hedges School
Address 4735 S. Winchester

Unit 23681
Chicago, IL, 60609

Building ID 3900
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|-----------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 36 | Interior Window Glazing | | | Rooms 110, 215, 312 | No ACBM | MISC | | | | | |
| 37 | Exterior Brick - Non AHERA | | | Exterior of Building | No ACBM | MISC | | | | | |
| 38 | Exterior Brick Mortar - Not AHERA | | | Exterior of Building | No ACBM | MISC | | | | | |
| 39 | Exterior Door Caulk - Not AHERA | | | | Chrysotile | MISC | | | | | |
| 3A | 9" x 9" Beige Floor Tile w/Brown Streaks | 300 | SF | Corridors on 1st, 2nd, & 3rd Floors | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 3B | 9" x 9" Tan Floor Tile w/Brown & White Streaks | 700 | SF | Room 111 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 3C | 9" x 9" Brown Floor Tile w/White Streaks | 700 | SF | Corridors on 1st, 2nd Floors, 3rd floors | Chrysotile | MISC | No | 40 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 3D | 9" x 9" Rusty Brown Speckled Floor Tile | 1,400 | SF | Room 215 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 3E | 9" x 9" Beige Floor Tile w/Blue Streaks | 1,352 | SF | Rooms 210 and 312 | Assumed | MISC | No | 30 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 3F | 9" x 9" Tan Floor Tile w/ Brown Streaks | 5,500 | SF | 3rd Floor Corridor | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 40 | Exterior Window Caulk - Not AHERA | | | | No ACBM | MISC | | | | | |
| 41 | Exterior Block Mortar - Not AHERA | | | | No ACBM | MISC | | | | | |
| 42 | Roofing Material - Not AHERA | | | Main Building | Assumed | MISC | | | | | |
| 43 | Roof Flashing - Not AHERA | | | | Assumed | MISC | | | | | |
| 44 | Insulation Inside of Vault Door | 32 | SF | Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 45 | Gray Carpet Mastic | 8,430 | SF | Office Complex | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 46 | Drywall and Associated Joint Compound | 1,500 | SF | 100, 101, 105, Washrooms, 200, Btwn 202 & 204, Btwn 203 & 205, 206, Btwn 300 & 301, Btwn 303 & 305 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 47 | 12" x 12" Beige Floor Tile | 800 | SF | Room 306 - 1911 Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 48 | 12" x 12" Beige Floor Tile Mastic | 800 | SF | Room 306 - 1911 Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 49 | 2' x 4' Fissured Ceiling Panels | | | Throughout South Building | No ACBM | MISC | | | | | |
| 4A | 9" x 9" Beige w/Brown Streaks Floor Tile Mastic | 300 | SF | Corridors on 1st and 2nd Floors | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 4B | 9" x 9" Tan Floor Tile w/Brn & Wh Streaks Mastic | 700 | SF | Room 111 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 4C | 9" x 9" Brown Floor Tile w/White Streaks Mastic | 700 | SF | Corridors on 1st and 2nd Floors | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 4D | 9" x 9" Rusty Brown Speckled Floor Tile Mastic | 1,400 | SF | Room 215 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 4E | 9" x 9" Beige Floor Tile w/Blue Streaks Mastic | 2,000 | SF | Rooms 210, 212, 312 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 4F | 9" x 9" Tan Floor Tile w/Brown Streaks Mastic | 300 | SF | 3rd Floor Corridor | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 5 | Ceramic Tile Grout | 50 | SF | Entrances | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 50 | 4" Dark Blue Vinyl Baseboard | | | Throughout South Building | No ACBM | | | | | | |
| 51 | 4" Dark Blue Vinyl Baseboard Mastic | | | Throughout South Building | No ACBM | MISC | | | | | |
| 52 | Soundproofing Material on Bottoms of Sinks | | | Rooms 100, 101, 103, 105 | No ACBM | MISC | | | | | |

Chicago Public Schools

School Hedges School
Address 4735 S. Winchester

Unit 23681
Chicago, IL, 60609

Building ID 3900
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|-----------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 53 | Cinder Block | | | Throughout South Building | No ACBM | MISC | | | | | |
| 54 | Cinder Block Mortar | | | Throughout South Building | No ACBM | MISC | | | | | |
| 55 | 12" x 12" Blue Floor Tile | 180 | SF | Washroom Across From 105 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 56 | 12" x 12" Blue Floor Tile Mastic | | | Washroom Across From 105 | No ACBM | MISC | | | | | |
| 57 | 2' x 4' Smooth Ceiling Panels | | | Kitchen and lunch Room | No ACBM | MISC | | | | | |
| 58 | Interior Window Caulk | | | Throughout South Building | No ACBM | MISC | | | | | |
| 59 | Stored Gaskets | | | Engineers Storage | Chrysotile | MISC | | | | | |
| 6 | Red and Tan Ceramic Tile Grout | 150 | SF | Washrooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 60 | Blue/Orange Carpet Adhesive | 3,020 | SF | Room 306, Main Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 61 | Duct Caulk | 500 | LF | Mechanical Room/South Building, Gym | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 62 | Marker Board/Poster Board Adhesive | 3,584 | SF | All Classrooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 63 | Spray-on Insulation | 15,000 | SF | South Building 1st & 2nd Floor | Assumed | SURFACE | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 64 | Duct Caulk | 500 | LF | Attic in North Building, Throughout Basement | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 65 | Tar Paper | 200 | SF | Attic in North Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 66 | Black Sealant | 900 | SF | At Links Between North & South Building Construction | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 67 | Green Stage Curtains | 1,000 | SF | Assembly Hall | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 68 | Gold/Brown Mix Carpet Adhesive | | | Room 010 | Assumed | MISC | | | | | |
| 69 | Asbestos Insulated Wire | 100 | LF | Engineers Storage room in cabinet | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7 | Multi-Brown Rubber Tile Grout | | | Boy's and Girl's Washrooms | No ACBM | MISC | | | | | |
| 70 | 12"x12" Grey Speckled VFT | 44,068 | SF | South Building Elevator, All Classrooms, South Building Corridor | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 71 | 12" x 12" Gray Speckled Floor Tile Mastic | 44,068 | SF | South Building Elevator, All Classrooms, South Building Corridors | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 8 | Insulation in Fire Doors | 30 | SF | Entrances, Exits, Boiler Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 9 | Firebrick | | | Boiler By Inside Wall | No ACBM | MISC | | | | | |
| A1 | Boiler Insulation - ABATED | | | Boiler By Inside Wall | Abated | TSI | | | | | |
| A2 | Boiler Insulation - ABATED | | | Boiler By Outside Wall | Abated | TSI | | | | | |
| B-01 | Boiler Gaskets - ABATED | | | Boiler By Inside Wall | Abated | MISC | | | | | |
| B-02 | Boiler Gaskets ABATED | | | Boiler By Outside Wall | Abated | MISC | | | | | |
| C | Mag Block Pipe Insulation ABATED | | | Boiler Room | Abated | TSI | | | | | |
| E | Cardboard Pipe Insulation | 100 | LF | Basement | Assumed | TSI | Yes | 0 | LF | 7 Any remaining friable ACBM or friable | Follow O&M Plan |

Chicago Public Schools

School Hedges School
Address 4735 S. Winchester

Unit 23681
Chicago, IL, 60609

Building ID 3900
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|-----------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| | | | | | | | | | | suspect ACBM | |
| F | Cardboard Pipe Insulation Joints | 10 | LF | Basement | Assumed | TSI | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| G | Tank Insulation | | | Tank Room | No ACBM | TSI | | | | | |
| H | Aircell Pipe Insulation | 200 | LF | In Inaccessible Areas Throughout Facility | Assumed | TSI | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| I | Aircell Pipe Insulation Joints | 15 | LF | In Inaccessible Areas Throughout Facility | Assumed | TSI | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| J | Fiberglass Pipe Insulation | | | Basement | Not Tested | TSI | | | | | |
| K | Fiberglass Insulation Joints | 30 | LF | Basement | Assumed | TSI | Yes | 0 | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |

Chicago Public Schools

School Hedges School
Address 4735 S. Winchester

Unit 23681
Chicago, IL, 60609

Building ID 3900
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500 Chicago, Il, 60607
Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|----------------|
| Review Date | 05/09/2019 |
| Manager Planner Name | Evan Christian |
| 100-19466 | 5/15/2020 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---------------------|
| 1 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 2 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |
| 29 | |
| 30 | |

Chicago Public Schools

School Hedges School
Address 4735 S. Winchester

Unit 23681
Chicago, IL, 60609

Building ID 3900
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 3A | |
| 3B | |
| 3C | |
| 3D | |
| 3E | |
| 3F | |
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |
| 47 | |
| 48 | |
| 49 | |
| 4A | |

Chicago Public Schools

School Hedges School
Address 4735 S. Winchester

Unit 23681
Chicago, IL, 60609

Building ID 3900
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 4B | |
| 4C | |
| 4D | |
| 4E | |
| 4F | |
| 5 | |
| 50 | |
| 51 | |
| 52 | |
| 53 | |
| 54 | |
| 55 | |
| 56 | |
| 57 | |
| 58 | |
| 59 | |
| 6 | |
| 60 | |
| 61 | |
| 62 | |
| 63 | |
| 64 | |
| 65 | |
| 66 | |
| 67 | |
| 68 | |

Chicago Public Schools

School Hedges School
Address 4735 S. Winchester

Unit 23681
Chicago, IL, 60609

Building ID 3900
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 69 | |
| 7 | |
| 70 | |
| 71 | |
| 8 | |
| 9 | |
| A1 | |
| A2 | |
| B-01 | |
| B-02 | |
| C | |
| E | |
| F | |
| G | |
| H | |
| I | |
| J | |
| K | |

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 1 | | |
| MATERIAL DESCRIPTION: | Plaster | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|---------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout Facility | | |
| MATERIAL QUANTITY: | 100607 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|----------------------------|-----------------|-----------|
| HOMOGENEOUS AREA: | 1 | | |
| MATERIAL DESCRIPTION: | Plaster | | |
| MATERIAL LOCATION: | Throughout Facility | | |
| MATERIAL QUANTITY: | 100607 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------|----------|
| HOMOGENEOUS AREA: | 10 | |
| MATERIAL DESCRIPTION: | Firebrick | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler by Outside Wall

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Firebrick**

MATERIAL LOCATION: **Boiler by Outside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------------------|----------|
| HOMOGENEOUS AREA: | 11 | |
| MATERIAL DESCRIPTION: | Refractory Cement on Boiler Doors | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler by Inside Wall

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Refractory Cement on Boiler Doors**

MATERIAL LOCATION: **Boiler by Inside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------------------|----------|
| HOMOGENEOUS AREA: | 12 | |
| MATERIAL DESCRIPTION: | Refractory Cement on Boiler Doors | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler by Outside Wall

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Refractory Cement on Boiler Doors**

MATERIAL LOCATION: **Boiler by Outside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 13 | | |
| MATERIAL DESCRIPTION: | Cementitious Material on Seams | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler by Inside Wall | | |
| MATERIAL QUANTITY: | 30 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Cementitious Material on Seams**

MATERIAL LOCATION: **Boiler by Inside Wall**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---|----------|
| HOMOGENEOUS AREA: | 14 | |
| MATERIAL DESCRIPTION: | Cementitious Material on Side of Boiler | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler by Outside Wall

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Cementitious Material on Side of Boiler**

MATERIAL LOCATION: **Boiler by Outside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---|----------|
| HOMOGENEOUS AREA: | 15 | |
| MATERIAL DESCRIPTION: | Cementitious Material on Side of Boiler | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler by Inside Wall

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Cementitious Material on Side of Boiler**

MATERIAL LOCATION: **Boiler by Inside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--------------------------------|----------|
| HOMOGENEOUS AREA: | 16 | |
| MATERIAL DESCRIPTION: | Cementitious Material on Seams | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler by Outside Wall

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Cementitious Material on Seams**

MATERIAL LOCATION: **Boiler by Outside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------|----------|
| HOMOGENEOUS AREA: | 17 | |
| MATERIAL DESCRIPTION: | Interior Brick | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------|----------|
| HOMOGENEOUS AREA: | 18 | |
| MATERIAL DESCRIPTION: | Interior Brick Mortar | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Basement

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--------------|----------|
| HOMOGENEOUS AREA: | 19 | |
| MATERIAL DESCRIPTION: | Cinder Block | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 2 | | |
| MATERIAL DESCRIPTION: | 2' x 4' Ceiling Panels | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|---------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout Facility | | |
| MATERIAL QUANTITY: | 11096 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **11096**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---------------------|----------|
| HOMOGENEOUS AREA: | 20 | |
| MATERIAL DESCRIPTION: | Cinder Block Mortar | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---------|----------|
| HOMOGENEOUS AREA: | 21 | |
| MATERIAL DESCRIPTION: | Block | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Block**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--------------|----------|
| HOMOGENEOUS AREA: | 22 | |
| MATERIAL DESCRIPTION: | Block Mortar | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Block Mortar**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--------------------------------|----------|
| HOMOGENEOUS AREA: | 23 | |
| MATERIAL DESCRIPTION: | Glazed (Finished) Brick Mortar | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boy's and Girl's Washrooms

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Glazed (Finished) Brick Mortar**

MATERIAL LOCATION: **Boy's and Girl's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--------------------------------|----------|
| HOMOGENEOUS AREA: | 24 | |
| MATERIAL DESCRIPTION: | Glazed (Finished) Block Mortar | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boy's and Girl's Washrooms

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Glazed (Finished) Block Mortar**

MATERIAL LOCATION: **Boy's and Girl's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-------------------|----------|
| HOMOGENEOUS AREA: | 25 | |
| MATERIAL DESCRIPTION: | Terrazzo Flooring | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Tank Room, Engineer's Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **Tank Room, Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 26 | | |
| MATERIAL DESCRIPTION: | 2' x 4' White Ceiling Panels | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout the 1996 Building | | |
| MATERIAL QUANTITY: | 6000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **2' x 4' White Ceiling Panels**

MATERIAL LOCATION: **Throughout the 1996 Building**

MATERIAL QUANTITY: **6000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------------|----------|
| HOMOGENEOUS AREA: | 27 | |
| MATERIAL DESCRIPTION: | Material Beneath Floor Tile | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 111

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Material Beneath Floor Tile**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---------------------------------|----------|
| HOMOGENEOUS AREA: | 28 | |
| MATERIAL DESCRIPTION: | 12" x 12" Multi-Blue Floor Tile | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 110

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" Multi-Blue Floor Tile**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--|----------|
| HOMOGENEOUS AREA: | 29 | |
| MATERIAL DESCRIPTION: | 12" x 12" Multi-Blue Floor Tile Mastic | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 110

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Multi-Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|----------------------------------|----------|----|
| HOMOGENEOUS AREA: | 30 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Multi-Brown Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

| | | | |
|------------------------|-------------------------------|-----------------|----|
| DAMAGE REASON: | Deterioration Delamination | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 112 | | |
| MATERIAL QUANTITY: | 1400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 30 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **30**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---|----------|
| HOMOGENEOUS AREA: | 31 | |
| MATERIAL DESCRIPTION: | 12" x 12" Multi-Brown Floor Tile Mastic | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 112

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile Mastic**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|------------------------|----------|
| HOMOGENEOUS AREA: | 32 | |
| MATERIAL DESCRIPTION: | 2' x 4' Ceiling Panels | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 110 & 112

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Room 110 & 112**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---------------|----------|
| HOMOGENEOUS AREA: | 33 | |
| MATERIAL DESCRIPTION: | Carpet Mastic | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|--|
| HOMOGENEOUS AREA: | 34 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Off-White Floor Tile w/Gray Streaks | | |
| HISTORICAL AHERA DAMAGE CATEGORY | | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 212 & 216

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Gray Streaks**

MATERIAL LOCATION: **Rooms 212 & 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--|----------|
| HOMOGENEOUS AREA: | 35 | |
| MATERIAL DESCRIPTION: | 12"x12" Off-White Floor Tile w/Gray Streaks Mastic | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 212 & 216

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12"x12" Off-White Floor Tile w/Gray Streaks Mastic**

MATERIAL LOCATION: **Rooms 212 & 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-------------------------|----------|
| HOMOGENEOUS AREA: | 36 | |
| MATERIAL DESCRIPTION: | Interior Window Glazing | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 110, 215, 312

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Interior Window Glazing**

MATERIAL LOCATION: **Rooms 110, 215, 312**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------------------|----------|
| HOMOGENEOUS AREA: | 37 | |
| MATERIAL DESCRIPTION: | Exterior Brick - Non AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Exterior Brick - Non AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------------------|----------|
| HOMOGENEOUS AREA: | 38 | |
| MATERIAL DESCRIPTION: | Exterior Brick Mortar - Not AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---------------------------------|----------|--|
| HOMOGENEOUS AREA: | 39 | | |
| MATERIAL DESCRIPTION: | Exterior Door Caulk - Not AHERA | | |
| HISTORICAL AHERA DAMAGE CATEGORY | | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 3A | | |
| MATERIAL DESCRIPTION: | 9" x 9" Beige Floor Tile w/Brown Streaks | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Corridors on 1st, 2nd, & 3rd Floors | | |
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

| | | | | | |
|-----------------------|---|-----------------|-----------|--|--|
| HOMOGENEOUS AREA: | 3A | | | | |
| MATERIAL DESCRIPTION: | 9" x 9" Beige Floor Tile w/Brown Streaks | | | | |
| MATERIAL LOCATION: | Corridors on 1st, 2nd, & 3rd Floors | | | | |
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF | | |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF | | |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 3B | | |
| MATERIAL DESCRIPTION: | 9" x 9" Tan Floor Tile w/Brown & White Streaks | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 111 | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **3B**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown & White Streaks**

MATERIAL LOCATION: **Room 111**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 3C | | |
| MATERIAL DESCRIPTION: | 9" x 9" Brown Floor Tile w/White Streaks | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

| | | | |
|------------------------|--|-----------------|----|
| DAMAGE REASON: | Deterioration Physical Damage Delamination | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Corridors on 1st, 2nd Floors, 3rd floors | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 40 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **3C**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/White Streaks**

MATERIAL LOCATION: **Corridors on 1st, 2nd Floors, 3rd floors**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|-----------|---------------|-----------|
| DAMAGE QUANTITY: | 40 | DAMAGE UNITS: | SF |
|------------------|-----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 3D | | |
| MATERIAL DESCRIPTION: | 9" x 9" Rusty Brown Speckled Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 215 | | |
| MATERIAL QUANTITY: | 1400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|------------------------|---------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: 3D

MATERIAL DESCRIPTION: 9" x 9" Rusty Brown Speckled Floor Tile

MATERIAL LOCATION: Room 215

MATERIAL QUANTITY: 1400

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/09/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 3E | | |
| MATERIAL DESCRIPTION: | 9" x 9" Beige Floor Tile w/Blue Streaks | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

| | | | |
|------------------------|-------------------------------|-----------------|----|
| DAMAGE REASON: | Deterioration Delamination | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 210 and 312 | | |
| MATERIAL QUANTITY: | 1352 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 30 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **3E**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/Blue Streaks**

MATERIAL LOCATION: **Rooms 210 and 312**

MATERIAL QUANTITY: **1352**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **30**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 3F | | |
| MATERIAL DESCRIPTION: | 9" x 9" Tan Floor Tile w/ Brown Streaks | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 3rd Floor Corridor | | |
| MATERIAL QUANTITY: | 5500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **3F**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Brown Streaks**

MATERIAL LOCATION: **3rd Floor Corridor**

MATERIAL QUANTITY: **5500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------------------|----------|
| HOMOGENEOUS AREA: | 40 | |
| MATERIAL DESCRIPTION: | Exterior Window Caulk - Not AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------------------|----------|
| HOMOGENEOUS AREA: | 41 | |
| MATERIAL DESCRIPTION: | Exterior Block Mortar - Not AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Exterior Block Mortar - Not AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|------------------------------|----------|
| HOMOGENEOUS AREA: | 42 | |
| MATERIAL DESCRIPTION: | Roofing Material - Not AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Roofing Material - Not AHERA**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---------------------------|----------|
| HOMOGENEOUS AREA: | 43 | |
| MATERIAL DESCRIPTION: | Roof Flashing - Not AHERA | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 44 | | |
| MATERIAL DESCRIPTION: | Insulation Inside of Vault Door | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Office | | |
| MATERIAL QUANTITY: | 32 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Insulation Inside of Vault Door**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **32**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 45 | | |
| MATERIAL DESCRIPTION: | Gray Carpet Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Office Complex | | |
| MATERIAL QUANTITY: | 8430 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Office Complex**

MATERIAL QUANTITY: **8430**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 46 | | |
| MATERIAL DESCRIPTION: | Drywall and Associated Joint Compound | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **100, 101, 105, Washrooms, 200, Btwn 202 & 204, Btwn 203 & 205, 206, Btwn 300 & 301, Btwn 303 & 305**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Drywall and Associated Joint Compound**

MATERIAL LOCATION: **100, 101, 105, Washrooms, 200, Btwn 202 & 204, Btwn 203 & 205, 206, Btwn 300 & 301, Btwn 303 & 305**

| | | | |
|--------------------|-------------|-----------------|-----------|
| MATERIAL QUANTITY: | 1500 | MATERIAL UNITS: | SF |
|--------------------|-------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 47 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Beige Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 306 - 1911 Building | | |
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Room 306 - 1911 Building**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 48 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Beige Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 306 - 1911 Building | | |
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 306 - 1911 Building**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---------------------------------|----------|
| HOMOGENEOUS AREA: | 49 | |
| MATERIAL DESCRIPTION: | 2' x 4' Fissured Ceiling Panels | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout South Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Panels**

MATERIAL LOCATION: **Throughout South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 4A | | |
| MATERIAL DESCRIPTION: | 9" x 9" Beige w/Brown Streaks Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Corridors on 1st and 2nd Floors | | |
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **4A**

MATERIAL DESCRIPTION: **9" x 9" Beige w/Brown Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Corridors on 1st and 2nd Floors**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 4B | | |
| MATERIAL DESCRIPTION: | 9" x 9" Tan Floor Tile w/Brn & Wh Streaks Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 111 | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **4B**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brn & Wh Streaks Mastic**

MATERIAL LOCATION: **Room 111**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 4C | | |
| MATERIAL DESCRIPTION: | 9" x 9" Brown Floor Tile w/White Streaks Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Corridors on 1st and 2nd Floors | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **4C**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/White Streaks Mastic**

MATERIAL LOCATION: **Corridors on 1st and 2nd Floors**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 4D | | |
| MATERIAL DESCRIPTION: | 9" x 9" Rusty Brown Speckled Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 215 | | |
| MATERIAL QUANTITY: | 1400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **4D**

MATERIAL DESCRIPTION: **9" x 9" Rusty Brown Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 4E | | |
| MATERIAL DESCRIPTION: | 9" x 9" Beige Floor Tile w/Blue Streaks Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 210, 212, 312 | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **4E**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/Blue Streaks Mastic**

MATERIAL LOCATION: **Rooms 210, 212, 312**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 4F | | |
| MATERIAL DESCRIPTION: | 9" x 9" Tan Floor Tile w/Brown Streaks Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 3rd Floor Corridor | | |
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **4F**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Brown Streaks Mastic**

MATERIAL LOCATION: **3rd Floor Corridor**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 5 | | |
| MATERIAL DESCRIPTION: | Ceramic Tile Grout | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Entrances | | |
| MATERIAL QUANTITY: | 50 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **Entrances**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|------------------------------|----------|
| HOMOGENEOUS AREA: | 50 | |
| MATERIAL DESCRIPTION: | 4" Dark Blue Vinyl Baseboard | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout South Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **4" Dark Blue Vinyl Baseboard**

MATERIAL LOCATION: **Throughout South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-------------------------------------|----------|
| HOMOGENEOUS AREA: | 51 | |
| MATERIAL DESCRIPTION: | 4" Dark Blue Vinyl Baseboard Mastic | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout South Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **4" Dark Blue Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--|----------|
| HOMOGENEOUS AREA: | 52 | |
| MATERIAL DESCRIPTION: | Soundproofing Material on Bottoms of Sinks | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 100, 101, 103, 105

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Soundproofing Material on Bottoms of Sinks**

MATERIAL LOCATION: **Rooms 100, 101, 103, 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--------------|----------|
| HOMOGENEOUS AREA: | 53 | |
| MATERIAL DESCRIPTION: | Cinder Block | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout South Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Throughout South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---------------------|----------|
| HOMOGENEOUS AREA: | 54 | |
| MATERIAL DESCRIPTION: | Cinder Block Mortar | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout South Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 55 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Blue Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Washroom Across From 105 | | |
| MATERIAL QUANTITY: | 180 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|----------------------------------|-----------------|-----------|
| HOMOGENEOUS AREA: | 55 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Blue Floor Tile | | |
| MATERIAL LOCATION: | Washroom Across From 105 | | |
| MATERIAL QUANTITY: | 180 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------------------------|----------|
| HOMOGENEOUS AREA: | 56 | |
| MATERIAL DESCRIPTION: | 12" x 12" Blue Floor Tile Mastic | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Washroom Across From 105

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Washroom Across From 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-------------------------------|----------|
| HOMOGENEOUS AREA: | 57 | |
| MATERIAL DESCRIPTION: | 2' x 4' Smooth Ceiling Panels | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen and lunch Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Panels**

MATERIAL LOCATION: **Kitchen and lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------|----------|
| HOMOGENEOUS AREA: | 58 | |
| MATERIAL DESCRIPTION: | Interior Window Caulk | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout South Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Throughout South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------|----------|
| HOMOGENEOUS AREA: | 59 | |
| MATERIAL DESCRIPTION: | Stored Gaskets | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Engineers Storage

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Stored Gaskets**

MATERIAL LOCATION: **Engineers Storage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 6 | | |
| MATERIAL DESCRIPTION: | Red and Tan Ceramic Tile Grout | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Washrooms | | |
| MATERIAL QUANTITY: | 150 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Red and Tan Ceramic Tile Grout**

MATERIAL LOCATION: **Washrooms**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 150 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 60 | | |
| MATERIAL DESCRIPTION: | Blue/Orange Carpet Adhesive | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 306, Main Office | | |
| MATERIAL QUANTITY: | 3020 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Blue/Orange Carpet Adhesive**

MATERIAL LOCATION: **Room 306, Main Office**

MATERIAL QUANTITY: **3020**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 61 | | |
| MATERIAL DESCRIPTION: | Duct Caulk | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Mechanical Room/South Building, Gym | | |
| MATERIAL QUANTITY: | 500 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Duct Caulk**

MATERIAL LOCATION: **Mechanical Room/South Building, Gym**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 500 | MATERIAL UNITS: | LF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 62 | | |
| MATERIAL DESCRIPTION: | Marker Board/Poster Board Adhesive | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | All Classrooms | | |
| MATERIAL QUANTITY: | 3584 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Marker Board/Poster Board Adhesive**

MATERIAL LOCATION: **All Classrooms**

MATERIAL QUANTITY: **3584**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 63 | | |
| MATERIAL DESCRIPTION: | Spray-on Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | South Building 1st & 2nd Floor | | |
| MATERIAL QUANTITY: | 15000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Spray-on Insulation**

MATERIAL LOCATION: **South Building 1st & 2nd Floor**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 64 | | |
| MATERIAL DESCRIPTION: | Duct Caulk | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Attic in North Building, Throughout Basement | | |
| MATERIAL QUANTITY: | 500 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Duct Caulk**

MATERIAL LOCATION: **Attic in North Building, Throughout Basement**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 500 | MATERIAL UNITS: | LF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 65 | | |
| MATERIAL DESCRIPTION: | Tar Paper | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Attic in North Building | | |
| MATERIAL QUANTITY: | 200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Tar Paper**

MATERIAL LOCATION: **Attic in North Building**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 66 | | |
| MATERIAL DESCRIPTION: | Black Sealant | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | At Links Between North & South Building Construction | | |
| MATERIAL QUANTITY: | 900 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Black Sealant**

MATERIAL LOCATION: **At Links Between North & South Building Construction**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 900 | MATERIAL UNITS: | SF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 67 | | |
| MATERIAL DESCRIPTION: | Green Stage Curtains | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Assembly Hall | | |
| MATERIAL QUANTITY: | 1000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Green Stage Curtains**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--------------------------------|----------|
| HOMOGENEOUS AREA: | 68 | |
| MATERIAL DESCRIPTION: | Gold/Brown Mix Carpet Adhesive | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 010

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Gold/Brown Mix Carpet Adhesive**

MATERIAL LOCATION: **Room 010**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 69 | | |
| MATERIAL DESCRIPTION: | Asbestos Insulated Wire | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Engineers Storage room in cabinet | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Asbestos Insulated Wire**

MATERIAL LOCATION: **Engineers Storage room in cabinet**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | LF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-------------------------------|----------|
| HOMOGENEOUS AREA: | 7 | |
| MATERIAL DESCRIPTION: | Multi-Brown Rubber Tile Grout | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boy's and Girl's Washrooms

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Multi-Brown Rubber Tile Grout**

MATERIAL LOCATION: **Boy's and Girl's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 70 | | |
| MATERIAL DESCRIPTION: | 12"x12" Grey Speckled VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | South Building Elevator, All Classrooms, South Building Corridor | | |
| MATERIAL QUANTITY: | 44068 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|---|-----------------|-----------|
| HOMOGENEOUS AREA: | 70 | | |
| MATERIAL DESCRIPTION: | 12"x12" Grey Speckled VFT | | |
| MATERIAL LOCATION: | South Building Elevator, All Classrooms, South Building Corridor | | |
| MATERIAL QUANTITY: | 44068 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 71 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Gray Speckled Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | South Building Elevator, All Classrooms, South Building Corridors | | |
| MATERIAL QUANTITY: | 44068 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

| | | | |
|-----------------------|--|-----------------|-----------|
| HOMOGENEOUS AREA: | 71 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Gray Speckled Floor Tile Mastic | | |
| MATERIAL LOCATION: | South Building Elevator, All Classrooms, South Building Corridors | | |
| MATERIAL QUANTITY: | 44068 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 8 | | |
| MATERIAL DESCRIPTION: | Insulation in Fire Doors | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Entrances, Exits, Boiler Room | | |
| MATERIAL QUANTITY: | 30 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Insulation in Fire Doors**

MATERIAL LOCATION: **Entrances, Exits, Boiler Room**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------|----------|
| HOMOGENEOUS AREA: | 9 | |
| MATERIAL DESCRIPTION: | Firebrick | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler By Inside Wall

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Firebrick**

MATERIAL LOCATION: **Boiler By Inside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------------------|----------|
| HOMOGENEOUS AREA: | A1 | |
| MATERIAL DESCRIPTION: | Boiler Insulation - ABATED | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Abated | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler By Inside Wall

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **A1**

MATERIAL DESCRIPTION: **Boiler Insulation - ABATED**

MATERIAL LOCATION: **Boiler By Inside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------------------|----------|
| HOMOGENEOUS AREA: | A2 | |
| MATERIAL DESCRIPTION: | Boiler Insulation - ABATED | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Abated | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler By Outside Wall

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **A2**

MATERIAL DESCRIPTION: **Boiler Insulation - ABATED**

MATERIAL LOCATION: **Boiler By Outside Wall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-------------------------|----------|
| HOMOGENEOUS AREA: | B-01 | |
| MATERIAL DESCRIPTION: | Boiler Gaskets - ABATED | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Abated | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler By Inside Wall

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **B-01**

MATERIAL DESCRIPTION: **Boiler Gaskets - ABATED**

MATERIAL LOCATION: **Boiler By Inside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------|----------|
| HOMOGENEOUS AREA: | B-02 | |
| MATERIAL DESCRIPTION: | Boiler Gaskets ABATED | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Abated | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler By Outside Wall

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **B-02**

MATERIAL DESCRIPTION: **Boiler Gaskets ABATED**

MATERIAL LOCATION: **Boiler By Outside Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------------------------|----------|
| HOMOGENEOUS AREA: | C | |
| MATERIAL DESCRIPTION: | Mag Block Pipe Insulation ABATED | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Abated | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | E | | |
| MATERIAL DESCRIPTION: | Cardboard Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Basement | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | LF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | F | | |
| MATERIAL DESCRIPTION: | Cardboard Pipe Insulation Joints | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Basement | | |
| MATERIAL QUANTITY: | 10 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation Joints**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------|----------|
| HOMOGENEOUS AREA: | G | |
| MATERIAL DESCRIPTION: | Tank Insulation | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | No ACBM | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Tank Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | H | | |
| MATERIAL DESCRIPTION: | Aircell Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | In Inaccessible Areas Throughout Facility | | |
| MATERIAL QUANTITY: | 200 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **In Inaccessible Areas Throughout Facility**

| | | | |
|--------------------|------------|-----------------|-----------|
| MATERIAL QUANTITY: | 200 | MATERIAL UNITS: | LF |
|--------------------|------------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | I | | |
| MATERIAL DESCRIPTION: | Aircell Pipe Insulation Joints | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | In Inaccessible Areas Throughout Facility | | |
| MATERIAL QUANTITY: | 15 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**

MATERIAL LOCATION: **In Inaccessible Areas Throughout Facility**

| | | | |
|--------------------|-----------|-----------------|-----------|
| MATERIAL QUANTITY: | 15 | MATERIAL UNITS: | LF |
|--------------------|-----------|-----------------|-----------|

| | | | |
|------------------|----------|---------------|-----------|
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
|------------------|----------|---------------|-----------|

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|----------------------------|----------|
| HOMOGENEOUS AREA: | J | |
| MATERIAL DESCRIPTION: | Fiberglass Pipe Insulation | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | | |
| ASBESTOS TYPE: | Not Tested | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Marcos Iwankiw | | |
| SCHOOL NAME: | Hedges School | INSPECTION DATE: | 4/25/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | K | | |
| MATERIAL DESCRIPTION: | Fiberglass Insulation Joints | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Basement | | |
| MATERIAL QUANTITY: | 30 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature: _____ Date: 04/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23681 | BUILDING ID: | 3900 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Evan Christian | | |
| SCHOOL NAME: | Hedges School | REVIEW DATE: | 5/9/2019 | | |
| ADDRESS: | 4735 S. Winchester | IDPH LICENSE NO: | 100-03175 | | |

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Fiberglass Insulation Joints**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019



Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|------|--|
| MATERIAL | | |
| | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | | |
| | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | | |
| | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | | |
| | Loc | Localized |
| | Dist | Distributed |