

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2324
SCHOOL NAME: Madison School
ADDRESS OF SCHOOL: 7433 S. Dorchester
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/10/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 207
IDPH INSPECTOR LICENSE NUMBER: 100-07839
IDPH LICENSED INSPECTOR NAME(Please Print): Lisa Laney
IDPH MP LICENSE NUMBER: 100-00440
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Shawn Brown

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Madison School

7433 S. Dorchester
Chicago, IL, 60619

Unit: 24301
Building ID: 4570

IDPH ID Number: 14-016-2990-2324

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

August 29, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24301 Region: 05 IDPH ID:14-016-2990-2324

School: Madison School Building ID: 4570

Address: 7433 S. Dorchester
Chicago, IL, 60619

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/28/2019

Inspector: Lisa Laney Inspector IDPH License: 100-07839
Management Planner: Shawn Brown Management Planner IDPH License: 100-00440

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Shawn Brown
100-00440

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 29, 2019

RE: Madison School, Unit 24301
7433 S. Dorchester
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Madison School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Madison School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Madison School
Address: 7433 S. Dorchester
IDPH ID: 14-016-2990-2324
Contact:
Unit: 24301
Chicago, IL, 60619
Building ID: 4570
Phone:
Region: 05

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 207
Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602
Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880
Fax: 630-790-0882

5. Inspector

Inspector Name: Lisa Laney

Inspector IDPH license # 100-07839

Signature:
Date: 8/29/2019

6. Management Planner

Management Planner Name: Shawn Brown

Management Planner IDPH license # 100-00440

Signature:
Date: 09/28/2019

7. Review Date:09/28/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Madison School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4570:

B. The following new homogenous areas have been identified for Building 4570:

- | | |
|----|-------------------|
| 31 | Blackboards |
| 32 | Blackboard Mastic |
| 33 | Plaster |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	Linoleum Flooring
03	12x12 Beige Floor Tile-NOT OBSERVED
03A	12x12 Tan Floor Tile-NOT OBSERVED
06	Brown Vinyl Baseboard
07	Brown Vinyl Baseboard Mastic
08	Linoleum Flooring Mastic
10	Carpet Mastic
13A	12x12 Beige VAT-NOT OBSERVED
17B	12"x12" Beige Floor Tile
17C	12"x12" Yellow Floor Tile
18B	12"X12" Beige Floor Tile Adhesive
18C	12"x12" Yellow Floor Tile Adhesive
20	Orange/Brown Carpet Mastic
21	Baseboard
22	Baseboard Mastic
23	Drywall
24	12x12 White Floor Tile
24B	12x12 Beige Floor Tile
24D	12x12 White Speck Floor Tile
25D	12x12 White Speck Floor Tile Mastic
26	2'x4' Ceiling Tile
27	2'x4' Ceiling Tile
31	Blackboards
32	Blackboard Mastic
33	Plaster
I	Pipe Joints-NOT OBSERVED

The following areas were deemed to be inaccessible:

003M	12" x 12" Brown w/Tan Streaks Floor Tile Mastic
07	Brown Vinyl Baseboard Mastic
08	Linoleum Flooring Mastic
10	Carpet Mastic
11B	12x12 White Floor Tile Mastic
18B	12"X12" Beige Floor Tile Adhesive
18C	12"x12" Yellow Floor Tile Adhesive
20	Orange/Brown Carpet Mastic
22	Baseboard Mastic
25	12x12 White Floor Tile Mastic
25A	12x12 Brown Floor Tile Mastic

25B	12x12 Beige Floor Tile Mastic
25D	12x12 White Speck Floor Tile Mastic
30	9"x9" Off-White w/Red Streaks Mastic
32	Blackboard Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Lisa Laney, IDPH License # 100-07839. The Management Plan was updated by Shawn Brown, IDPH License # 100-00440. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Madison School Building 4570 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Madison School Unit 24301 Building ID 4570

Address 7433 S. Dorchester Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
12A	9x9 Tan VAT Mastic			1938 Building-Teachers' Lounge	ABATED	MISC								
12B	9x9 Maroon VAT Mastic			1938 Building-Corridors	ABATED	MISC								
12C	9x9 White VAT Mastic			1938 Building-Engineer's Office	ABATED	MISC								
12D	9x9 Beige VAT Mastic			Rooms 200, 203, 103, 202, 204	ABATED	MISC								
12E	9x9 Black Streaked VAT Mastic ABATED			1st & 2nd Floor Corridors in patches	ABATED	MISC								Low
13	12x12 Tan Floor Tile-NOT OBSERVED			Rooms 206 & 208	CHR	MISC								
13A	12x12 Beige VAT-NOT OBSERVED			1961 Addition-Room 201, Corridors Across Rooms 100, 101	ASSUMED	MISC								
14	12x12 Tan Floor Tile Mastic-VFT NOT OBSERVED			Rooms 206 & 208	CHR	MISC								
14A	12x12 Beige VAT Mastic-VFT NOT OBSERVED			1961 Addition-Room 201, Corridors across Rooms 100, 101	CHR	MISC								
15	Black Baseboard ABATED			1961 Addition-Rooms 100, 101, 103, 201	ABATED	MISC								
16	Black Baseboard Mastic ABATED			1961 Addition-Rooms 100, 101, 103, 201	ABATED	MISC								
17	9x9 Beige VAT ABATED			1961 Addition-Rooms 200A, 203	ABATED	MISC								Low
17A	9x9 Crème VAT ABATED			1961 Addition-Room 203	ABATED	MISC								Low
17B	12"x12" Beige Floor Tile	8,800	SF	Rooms 100, 101, 103, 200, 201, 202, 203, 204, 206, 208, 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17C	12"x12" Yellow Floor Tile	7,300	SF	1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	9x9 Beige VAT Mastic ABATED			1961 Addition-Rooms 200A, 203	ABATED	MISC		Loc						Moderate
18A	9x9 Crème VAT Mastic ABATED			1961 Addition-Room 203	ABATED	MISC								Low
18B	12"x12" Beige Floor Tile Adhesive	8,800	SF	Rooms 100, 101, 103, 200, 201, 203, 204, 206, 208, 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Madison School Unit 24301 Building ID 4570

Address 7433 S. Dorchester Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
18C	12"x12" Yellow Floor Tile Adhesive	7,300	SF	1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Orange/Brown Carpet Mastic	900	SF	Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Baseboard	400	LF	Only in Classrooms & Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Baseboard Mastic	400	LF	Only in Classrooms & Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Drywall	11,000	SF	Modular Building-Stairwells & behind Steel Panels	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12x12 White Floor Tile	1,200	SF	Modular Building-Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24A	12x12 Brown Floor Tile	1,000	SF	Modular Building-Kitchen Area, Gym	CHR	MISC	N	LOC	10		No	ACBM with potential for significant damage	3	LOW
24B	12x12 Beige Floor Tile	600	SF	Modular Building-Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24C	9x9 Black Floor Tile ABATED			Modular Building Corridors	ABATED	MISC								
24D	12x12 White Speck Floor Tile	320	SF	Room 001	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12x12 White Floor Tile Mastic	1,200	SF	Modular Building-Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25A	12x12 Brown Floor Tile Mastic	1,000	SF	Modular Building-Kitchen Area & Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25B	12x12 Beige Floor Tile Mastic	600	SF	Modular Building-Cafeteria	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25C	9x9 Black Floor Tile Mastic ABATED			Modular Building-Corridors	ABATED	MISC								
25D	12x12 White Speck Floor Tile Mastic	320	SF	Room 001	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2'x4' Ceiling Tile	1,200	SF	1938 Building-Corridors	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
27	2'x4' Ceiling Tile	1,200	SF	1961 Addition - Corridors	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
29	9"x9" Off-White w/Red Streaks Floor Tile	200	SF	Engineer's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	9"x9" Off-White w/Red Streaks Mastic	200	SF	Engineer's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Blackboards	4,500	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Madison School Unit 24301 Building ID 4570
Address 7433 S. Dorchester Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/29/2019
Inspector Name <u>Lisa Laney</u>
100-07839 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
003M	
01	
01A	
01B	
01C	
01D	
01E	
02	Damage Located in Room 213
03	Not Observed Multiple Years
03A	Not Observed Multiple Years
03B	
03C	
03D	
03E	
06	
07	
08	Damage Located in Room 213
10	
11	VFT Not Observed Multiple Years
11A	VFT Not Observed Multiple Years
11B	
11C	VFT Abated pre-2004
11D	VFT abated pre-2004

Chicago Public Schools

School Madison School Unit 24301 Building ID 4570

Address 7433 S. Dorchester Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
11E	VFT Abated pre-2004
12	VFT Abated
12A	VFT Abated
12B	VFT Abated
12C	VFT Abated
12D	VFT Abated
12E	
13	Not Observed Multiple Years
13A	Not Observed Multiple Years
14	VFT Not Observed Multiple Years
14A	VFT Not Observed Multiple Years
15	
16	
17	
17A	
17B	
17C	
18	
18A	
18B	
18C	
20	
21	
22	
23	
24	
24A	Damage in Modular Building Kitchen, Floor Tile Buckling
24B	
24C	

Chicago Public Schools

School Madison School Unit 24301 Building ID 4570

Address 7433 S. Dorchester Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
24D	
25	
25A	
25B	
25C	
25D	
26	
27	
29	
30	
31	
32	
33	Damage in 2nd fl. Computer Lab
CMMI	
I	Not Observed Multiple Years
MD	

Table II

Management Planner's Review

Chicago Public Schools

School Madison School
Address 7433 S. Dorchester

Unit 24301
Chicago, IL, 60619

Building ID 4570
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
003M	12" x 12" Brown w/Tan Streaks Floor Tile Mastic	3,000	SF	Throughout 1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01	9x9 Black VAT ABATED			1938 Building- Corridors	Abated	MISC					
01A	9x9 Tan VAT ABATED			1938 Building- Teachers' Lounge	Abated	MISC					
01B	9x9 Maroon VAT ABATED			1938 Building- Corridors	Abated	MISC					
01C	9x9 White VAT ABATED			1938 Building- Engineer's Office	Abated	MISC					
01D	9x9 Beige VAT ABATED			Rooms 200, 203, 103, 202, 204	Abated	MISC					
01E	9x9 Black Streaked VAT ABATED			1st & 2nd Floor Corridors, in Patches	Abated	MISC					
02	Linoleum Flooring	660	SF	Room 213	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
03	12x12 Beige Floor Tile-NOT OBSERVED			Office	Assumed	MISC	No				
03A	12x12 Tan Floor Tile-NOT OBSERVED			1938 Building- Room 206 & 208	Assumed	MISC	No				
03B	12x12 White Floor Tile	150	SF	Engineer's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03C	12x12 White Floor Tile ABATED			Room 201	Abated	MISC					
03D	12x12 Salmon Floor Tile ABATED			Room 201	Abated	MISC					
03E	12x12 Gray VAT ABATED			Room 200	Abated	MISC					
06	Brown Vinyl Baseboard	1,300	LF	1938 Building- Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
07	Brown Vinyl Baseboard Mastic	1,300	LF	Throughout 1938 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
08	Linoleum Flooring Mastic	660	SF	Room 213	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Carpet Mastic	673	SF	1960 Addition- Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12x12 Beige Floor Tile Mastic-VFT NOT OBSERVED			Office	Chrysotile	MISC					
11A	12x12 Tan Floor Tile Mastic-VFT NOT OBSERVED			1938 Building- Room 206 & 208	Chrysotile	MISC					
11B	12x12 White Floor Tile Mastic	150	SF	Engineer's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11C	12x12 White Floor Tile Mastic			Room 201	Abated	MISC					
11D	12x12 Salmon Floor Tile Mastic			Room 201	Abated	MISC					
11E	12x12 Gray VAT Mastic			Room 200	Abated	MISC					
12	9x9 Black VAT Mastic			1938 Building- Corridors	Abated	MISC					
12A	9x9 Tan VAT Mastic			1938 Building- Teachers' Lounge	Abated	MISC					
12B	9x9 Maroon VAT Mastic			1938 Building- Corridors	Abated	MISC					
12C	9x9 White VAT Mastic			1938 Building- Engineer's Office	Abated	MISC					
12D	9x9 Beige VAT Mastic			Rooms 200, 203, 103, 202, 204	Abated	MISC					
12E	9x9 Black Streaked VAT Mastic ABATED			1st & 2nd Floor Corridors in patches	Abated	MISC					
13	12x12 Tan Floor Tile-NOT OBSERVED			Rooms 206 & 208	Chrysotile	MISC					
13A	12x12 Beige VAT-NOT OBSERVED			1961 Addition- Room 201, Corridors	Assumed	MISC					

Chicago Public Schools

School Madison School
Address 7433 S. Dorchester

Unit 24301
Chicago, IL, 60619

Building ID 4570
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Across Rooms 100, 101							
14	12x12 Tan Floor Tile Mastic-VFT NOT OBSERVED			Rooms 206 & 208	Chrysotile	MISC					
14A	12x12 Beige VAT Mastic-VFT NOT OBSERVED			1961 Addition- Room 201, Corridors across Rooms 100, 101	Chrysotile	MISC					
15	Black Baseboard ABATED			1961 Addition- Rooms 100, 101, 103, 201	Abated	MISC					
16	Black Baseboard Mastic ABATED			1961 Addition- Rooms 100, 101, 103, 201	Abated	MISC					
17	9x9 Beige VAT ABATED			1961 Addition- Rooms 200A, 203	Abated	MISC					
17A	9x9 Crème VAT ABATED			1961 Addition- Room 203	Abated	MISC					
17B	12"x12" Beige Floor Tile	8,800	SF	Rooms 100, 101, 103, 200, 201, 202, 203, 204, 206, 208, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17C	12"x12" Yellow Floor Tile	7,300	SF	1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9x9 Beige VAT Mastic ABATED			1961 Addition- Rooms 200A, 203	Abated	MISC					
18A	9x9 Crème VAT Mastic ABATED			1961 Addition- Room 203	Abated	MISC					
18B	12"X12" Beige Floor Tile Adhesive	8,800	SF	Rooms 100, 101, 103, 200, 201, 203, 204, 206, 208, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18C	12"x12" Yellow Floor Tile Adhesive	7,300	SF	1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Orange/Brown Carpet Mastic	900	SF	Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Baseboard	400	LF	Only in Classrooms & Cafeteria	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22	Baseboard Mastic	400	LF	Only in Classrooms & Cafeteria	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
23	Drywall	11,000	SF	Modular Building- Stairwells & behind Steel Panels	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12x12 White Floor Tile	1,200	SF	Modular Building- Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24A	12x12 Brown Floor Tile	1,000	SF	Modular Building- Kitchen Area, Gym	Chrysotile	MISC	No	10	SF	5 ACBM with potential for significant damage	Remove
24B	12x12 Beige Floor Tile	600	SF	Modular Building- Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24C	9x9 Black Floor Tile ABATED			Modular Building Corridors	Abated	MISC					
24D	12x12 White Speck Floor Tile	320	SF	Room 001	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12x12 White Floor Tile Mastic	1,200	SF	Modular Building- Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	12x12 Brown Floor Tile Mastic	1,000	SF	Modular Building- Kitchen Area & Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25B	12x12 Beige Floor Tile Mastic	600	SF	Modular Building- Cafeteria	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25C	9x9 Black Floor Tile Mastic ABATED			Modular Building- Corridors	Abated	MISC					

Chicago Public Schools

School Madison School
Address 7433 S. Dorchester

Unit 24301
Chicago, IL, 60619

Building ID 4570
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
25D	12x12 White Speck Floor Tile Mastic	320	SF	Room 001	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	2'x4' Ceiling Tile	1,200	SF	1938 Building- Corridors	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
27	2'x4' Ceiling Tile	1,200	SF	1961 Addition - Corridors	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
29	9"x9" Off-White w/Red Streaks Floor Tile	200	SF	Engineer's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	9"x9" Off-White w/Red Streaks Mastic	200	SF	Engineer's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Blackboards	4,500	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Blackboard Mastic	4,500	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Plaster	150,000	SF	Main Bldg.	Assumed	SURFACE	No	10	SF	6 ACBM with the potential for damage	Repair
CMMI	Cardboard Lagging ABATED			Engineer's Office Restroom, Teachers' Lounge (Abated)	Abated	TSI					
I	Pipe Joints-NOT OBSERVED			Above Ceiling in Modular Building 1st Floor	Assumed	TSI					
MD	Cardboard Elbows ABATED			1938 Building- Restroom Pipe Chases, Engineer's Office, Teachers' Restroom (Abated)	Abated	TSI					

Chicago Public Schools

School Madison School
Address 7433 S. Dorchester

Unit 24301
 Chicago, IL, 60619

Building ID 4570
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
 174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	09/28/2019
Manager Planner Name	Shawn Brown
100-00440	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
003M	
01	
01A	
01B	
01C	
01D	
01E	
02	
03	
03A	
03B	
03C	
03D	
03E	
06	
07	
08	
10	
11	

Chicago Public Schools

School Madison School
Address 7433 S. Dorchester

Unit 24301
 Chicago, IL, 60619

Building ID 4570
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
11A	
11B	
11C	
11D	
11E	
12	
12A	
12B	
12C	
12D	
12E	
13	
13A	
14	
14A	
15	
16	
17	
17A	
17B	
17C	
18	
18A	
18B	
18C	
20	

Chicago Public Schools

School Madison School
Address 7433 S. Dorchester

Unit 24301
 Chicago, IL, 60619

Building ID 4570
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
21	
22	
23	
24	
24A	
24B	
24C	
24D	
25	
25A	
25B	
25C	
25D	
26	
27	
29	
30	
31	
32	
33	
CMMI	
I	
MD	

Chicago Public Schools

School Madison School

Unit 24301

Building ID 4570

Address 7433 S. Dorchester

Chicago, IL, 60619

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003M**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Tan Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **003M**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Tan Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **9x9 Black VAT ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1938 Building- Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **9x9 Black VAT ABATED**

MATERIAL LOCATION: **1938 Building- Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **9x9 Tan VAT ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1938 Building- Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **9x9 Tan VAT ABATED**
MATERIAL LOCATION: **1938 Building- Teachers' Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **9x9 Maroon VAT ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1938 Building- Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **9x9 Maroon VAT ABATED**
MATERIAL LOCATION: **1938 Building- Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **9x9 White VAT ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1938 Building- Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **9x9 White VAT ABATED**
MATERIAL LOCATION: **1938 Building- Engineer's Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **9x9 Beige VAT ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 200, 203, 103, 202, 204**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **9x9 Beige VAT ABATED**
MATERIAL LOCATION: **Rooms 200, 203, 103, 202, 204**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **9x9 Black Streaked VAT ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, in Patches**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **9x9 Black Streaked VAT ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, in Patches**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Linoleum Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 213**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**
COMMENTS: **Damage Located in Room 213**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Linoleum Flooring**
MATERIAL LOCATION: **Room 213**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile-NOT OBSERVED**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Room 206 & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile-NOT OBSERVED**
MATERIAL LOCATION: **1938 Building- Room 206 & 208**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Lounge**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
MATERIAL LOCATION: **Engineer's Lounge**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03C**
MATERIAL DESCRIPTION: **12x12 White Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **03C**
MATERIAL DESCRIPTION: **12x12 White Floor Tile ABATED**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03D**
MATERIAL DESCRIPTION: **12x12 Salmon Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **03D**
MATERIAL DESCRIPTION: **12x12 Salmon Floor Tile ABATED**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03E**
MATERIAL DESCRIPTION: **12x12 Gray VAT ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 200**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **03E**
MATERIAL DESCRIPTION: **12x12 Gray VAT ABATED**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1938 Building- Throughout**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**
MATERIAL LOCATION: **1938 Building- Throughout**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1938 Building**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Throughout 1938 Building**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Linoleum Flooring Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 213**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**
COMMENTS: **Damage Located in Room 213**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Linoleum Flooring Mastic**
MATERIAL LOCATION: **Room 213**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1960 Addition- Room 100**
MATERIAL QUANTITY: **673** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **1960 Addition- Room 100**
MATERIAL QUANTITY: **673** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic-VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Not Observed Multiple Years**

Inspector's Signature: _____

Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic-VFT NOT OBSERVED**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic-VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Room 206 & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Not Observed Multiple Years**

Inspector's Signature: _____

Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **11A**

MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic-VFT NOT OBSERVED**

MATERIAL LOCATION: **1938 Building- Room 206 & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Lounge**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **11B**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Lounge**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11C**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Abated pre-2004**

Inspector's Signature: _____

Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **11C**

MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11D**
MATERIAL DESCRIPTION: **12x12 Salmon Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT abated pre-2004**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **11D**
MATERIAL DESCRIPTION: **12x12 Salmon Floor Tile Mastic**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11E**
MATERIAL DESCRIPTION: **12x12 Gray VAT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Abated pre-2004**

Inspector's Signature: _____

Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **11E**
MATERIAL DESCRIPTION: **12x12 Gray VAT Mastic**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9x9 Black VAT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Abated**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9x9 Black VAT Mastic**
MATERIAL LOCATION: **1938 Building- Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **9x9 Tan VAT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Teachers' Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Abated**

Inspector's Signature: _____

Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **9x9 Tan VAT Mastic**
MATERIAL LOCATION: **1938 Building- Teachers' Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12B**
MATERIAL DESCRIPTION: **9x9 Maroon VAT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Abated**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **12B**
MATERIAL DESCRIPTION: **9x9 Maroon VAT Mastic**
MATERIAL LOCATION: **1938 Building- Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12C**
MATERIAL DESCRIPTION: **9x9 White VAT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Abated**

Inspector's Signature: _____

Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **12C**
MATERIAL DESCRIPTION: **9x9 White VAT Mastic**
MATERIAL LOCATION: **1938 Building- Engineer's Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12D**
MATERIAL DESCRIPTION: **9x9 Beige VAT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 200, 203, 103, 202, 204**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Abated**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **12D**
MATERIAL DESCRIPTION: **9x9 Beige VAT Mastic**
MATERIAL LOCATION: **Rooms 200, 203, 103, 202, 204**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12E**
MATERIAL DESCRIPTION: **9x9 Black Streaked VAT Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st & 2nd Floor Corridors in patches**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **12E**
MATERIAL DESCRIPTION: **9x9 Black Streaked VAT Mastic ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors in patches**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 206 & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12x12 Tan Floor Tile-NOT OBSERVED**

MATERIAL LOCATION: **Rooms 206 & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **12x12 Beige VAT-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Addition- Room 201, Corridors Across Rooms 100, 101**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **12x12 Beige VAT-NOT OBSERVED**
MATERIAL LOCATION: **1961 Addition- Room 201, Corridors Across Rooms 100, 101**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic-VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 206 & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Not Observed Multiple Years**

Inspector's Signature: _____

Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic-VFT NOT OBSERVED**

MATERIAL LOCATION: **Rooms 206 & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **12x12 Beige VAT Mastic-VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Addition- Room 201, Corridors across Rooms 100, 101**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **VFT Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **12x12 Beige VAT Mastic-VFT NOT OBSERVED**
MATERIAL LOCATION: **1961 Addition- Room 201, Corridors across Rooms 100, 101**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Black Baseboard ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Addition- Rooms 100, 101, 103, 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Black Baseboard ABATED**

MATERIAL LOCATION: **1961 Addition- Rooms 100, 101, 103, 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Black Baseboard Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Addition- Rooms 100, 101, 103, 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Black Baseboard Mastic ABATED**

MATERIAL LOCATION: **1961 Addition- Rooms 100, 101, 103, 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9x9 Beige VAT ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1961 Addition- Rooms 200A, 203**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **9x9 Beige VAT ABATED**

MATERIAL LOCATION: **1961 Addition- Rooms 200A, 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **9x9 Crème VAT ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1961 Addition- Room 203**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **9x9 Crème VAT ABATED**
MATERIAL LOCATION: **1961 Addition- Room 203**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17B**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100, 101, 103, 200, 201, 202, 203, 204, 206, 208, 210**
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **17B**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**
MATERIAL LOCATION: **Rooms 100, 101, 103, 200, 201, 202, 203, 204, 206, 208, 210**
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17C**
MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **7300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **17C**
MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **7300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9x9 Beige VAT Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1961 Addition- Rooms 200A, 203**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **9x9 Beige VAT Mastic ABATED**

MATERIAL LOCATION: **1961 Addition- Rooms 200A, 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **9x9 Crème VAT Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1961 Addition- Room 203**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **18A**

MATERIAL DESCRIPTION: **9x9 Crème VAT Mastic ABATED**

MATERIAL LOCATION: **1961 Addition- Room 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18B**
MATERIAL DESCRIPTION: **12"X12" Beige Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100, 101, 103, 200, 201, 203, 204, 206, 208, 210**
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **18B**
MATERIAL DESCRIPTION: **12"X12" Beige Floor Tile Adhesive**
MATERIAL LOCATION: **Rooms 100, 101, 103, 200, 201, 203, 204, 206, 208, 210**
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18C**
MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **7300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **18C**
MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile Adhesive**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **7300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Orange/Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Building**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Orange/Brown Carpet Mastic**
MATERIAL LOCATION: **Modular Building**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Only in Classrooms & Cafeteria**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Baseboard**
MATERIAL LOCATION: **Only in Classrooms & Cafeteria**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Only in Classrooms & Cafeteria**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Baseboard Mastic**
MATERIAL LOCATION: **Only in Classrooms & Cafeteria**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Building- Stairwells & behind Steel Panels**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Modular Building- Stairwells & behind Steel Panels**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Building- Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
MATERIAL LOCATION: **Modular Building- Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24A**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Delamination**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Building- Kitchen Area, Gym**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**
COMMENTS: **Damage in Modular Building Kitchen, Floor Tile Buckling**

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **24A**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
MATERIAL LOCATION: **Modular Building- Kitchen Area, Gym**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24B**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Building- Cafeteria**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **24B**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**
MATERIAL LOCATION: **Modular Building- Cafeteria**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24C**
MATERIAL DESCRIPTION: **9x9 Black Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **24C**
MATERIAL DESCRIPTION: **9x9 Black Floor Tile ABATED**
MATERIAL LOCATION: **Modular Building Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24D**
MATERIAL DESCRIPTION: **12x12 White Speck Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 001**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **24D**
MATERIAL DESCRIPTION: **12x12 White Speck Floor Tile**
MATERIAL LOCATION: **Room 001**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Building- Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**
MATERIAL LOCATION: **Modular Building- Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Building- Kitchen Area & Gym**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**
MATERIAL LOCATION: **Modular Building- Kitchen Area & Gym**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25B**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Building- Cafeteria**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **25B**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**
MATERIAL LOCATION: **Modular Building- Cafeteria**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25C**
MATERIAL DESCRIPTION: **9x9 Black Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building- Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **25C**
MATERIAL DESCRIPTION: **9x9 Black Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Modular Building- Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25D**
MATERIAL DESCRIPTION: **12x12 White Speck Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 001**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **25D**
MATERIAL DESCRIPTION: **12x12 White Speck Floor Tile Mastic**
MATERIAL LOCATION: **Room 001**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1938 Building- Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **1938 Building- Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1961 Addition - Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **1961 Addition - Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **9"x9" Off-White w/Red Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **9"x9" Off-White w/Red Streaks Floor Tile**
MATERIAL LOCATION: **Engineer's Lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9"x9" Off-White w/Red Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9"x9" Off-White w/Red Streaks Mastic**
MATERIAL LOCATION: **Engineer's Lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CMMI**
MATERIAL DESCRIPTION: **Cardboard Lagging ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office Restroom, Teachers' Lounge (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **CMMI**
MATERIAL DESCRIPTION: **Cardboard Lagging ABATED**
MATERIAL LOCATION: **Engineer's Office Restroom, Teachers' Lounge (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Pipe Joints-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Above Ceiling in Modular Building 1st Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Pipe Joints-NOT OBSERVED**
MATERIAL LOCATION: **Above Ceiling in Modular Building 1st Floor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUIDLING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MD**
MATERIAL DESCRIPTION: **Cardboard Elbows ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Restroom Pipe Chases, Engineer's Office, Teachers' Restroom (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **MD**
MATERIAL DESCRIPTION: **Cardboard Elbows ABATED**
MATERIAL LOCATION: **1938 Building- Restroom Pipe Chases, Engineer's Office, Teachers' Restroom (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Blackboards**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Blackboard Mastic**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Madison School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Main Bldg.**
MATERIAL QUANTITY: **150000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **10** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in 2nd fl. Computer Lab

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24301** BUILDING ID: **4570**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Madison School** REVIEW DATE: **9/28/2019**
ADDRESS: **7433 S. Dorchester** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Main Bldg.**
MATERIAL QUANTITY: **150000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/28/2019**

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Lisa Laney

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/5/2019

Exam Date: 4/5/2019

Expiration Date: 4/5/2020

Certificate Number: BIR1904051198

Kathy DeSalvo, Director

Miss Nancy

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



PUBLIC HEALTH & SAFETY Inc.

Environmental and Occupational Services
37 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Penelf

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
371 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2501

Director of Training

Nicholas J. Peneff

Doctor of Public Health




Phone: 312-491-0081

FORM # A-011

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES	
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	3/19/2019
100 - 02950	3/6/2019	05/15/2020	PROJECT MANAGER	4/9/2019
KEITH CLOUGH			AIR SAMPLING PROFESSIONAL	
524 HOMELAND RD			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health	
MATTESON, IL 60443			This license is valid only when accompanied by a valid training course certificate.	
Environmental Health				

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed