

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2356  
SCHOOL NAME: ASPIRA - Mirta Ramirez @ Moos School  
ADDRESS OF SCHOOL: 1711 N. California  
CITY: Chicago, IL, 60647

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/5/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 467  
IDPH INSPECTOR LICENSE NUMBER: 100-11089  
IDPH LICENSED INSPECTOR NAME(Please Print): Panfilo Carrazco  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**ASPIRA - Mirta Ramirez @ Moos School**

1711 N. California  
Chicago, IL, 60647

Unit: 24551  
Building ID: 4870

IDPH ID Number: 14-016-2990-2356

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

June 13, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 24551                      Region: 02                      IDPH ID:14-016-2990-2356

School: ASPIRA - Mirta Ramirez @ Moos School                      Building ID: 4870

Address: 1711 N. California  
Chicago, IL, 60647

Building Contact:                      Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/16/2019

Inspector: Panfilo Carrazco                      Inspector IDPH License: 100-11089  
Management Planner: Jigar Shah                      Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: June 13, 2019

RE: ASPIRA - Mirta Ramirez @ Moos School, Unit 24551  
1711 N. California  
Chicago, IL, 60647

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at ASPIRA - Mirta Ramirez @ Moos School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at ASPIRA - Mirta Ramirez @ Moos School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: ASPIRA - Mirta Ramirez @ Moos School      Unit: 24551      Region: 02  
Address: 1711 N. California      Chicago, IL, 60647  
IDPH ID: 14-016-2990-2356      Building ID: 4870  
Contact:      Phone:

### 2. Description of Facility

Original Construction: 1896      Additional Construction: 2003  
Total Square Footage: 82022      No of Floors: 4  
Current Occupancy: 467

### 3. LEA Designated Person

Contact: Robert Christlieb      Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575      Fax:

### 5. Inspector

Inspector Name: Panfilo Carrazco

Inspector IDPH license # 100-11089      Signature:  
Date: 6/13/2019

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342      Signature:  
Date: 09/16/2019

### 7. Review Date: 09/16/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the ASPIRA - Mirta Ramirez @ Moos School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4870:

04	Aircell Duct Insulation (NOT OBSERVED)
07	9"x9" Beige VFT Mastic

B. The following new homogenous areas have been identified for Building 4870:

33	12" X 36" Black Floor tile
33A	12" X 36" Black floor tile mastic
34	12" X 12" White w/ tan streaks floor tile
34A	12" X 12" White w/ tan streaks floor tile mastic
35	12" X 12" Green w/ White streaks floor tile
35A	12" X 12" Green w/ White streaks floor tile Mastic
36	12" X 12" Beige w/ White Specks floor tile
36A	12" X 12" Beige w/ White Specks floor tile Mastic
37	Linoleum wood Grain Finsih
37A	Linoleum Wood Grain Finish
38	Linoleum Off white w/ Beige Specks
38A	Linoleum Off white w/ Beige Specks Mastic
39	12" X 12" Off White w/ Light specks Floor tile
39A	12" X 12" Off White w/ Light specks Floor tile Mastic
40	12" X 12" Gray w/ gray and black streaks floor tile
40A	12" X 12" Gray w/ gray and black streaks floor tile Mastic
41	12" X 12" Brown w/ Brown and white spec floor tile
41A	12" X 12" Brown w/ Brown and white spec floor tile Mastic
42	science Lab tables



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

08	12"x12" Black VFT
09	12"x12" Black VFT Mastic
10	Green Linoleum
11	Green Linoleum Mastic
12	Hard Plaster
14	12"x12" Tan w/ Brown Streaks VFT
15	12"x12" Tan w/ Brown Streaks VFT Mastic
17	12"x12" Green w/ White Streaks VFT Mastic
18	12"x12" Brown w/ Brown & White Streaks VFT
19	12"x12" Brown w/ Brown & White Streaks VFT Mastic
20	12" X 12" Brown floor tile and mastic
22	12"x12" Blue/Gray VFT
23	12"x12" Blue/Gray VFT Mastic
26	12"x12" Tan/Beige VFT
30	12x12 Black Floor Tile
31	12x12 Black Floor Tile Mastic
32	2 x 4 White Ceiling Tile
33	12" X 36" Black Floor tile
33A	12" X 36" Black floor tile mastic
34	12" X 12" White w/ tan streaks floor tile
34A	12" X 12" White w/ tan streaks floor tile mastic
35	12" X 12" Green w/ White streaks floor tile
35A	12" X 12" Green w/ White streaks floor tile Mastic
36	12" X 12" Beige w/ White Specks floor tile
36A	12" X 12" Beige w/ White Specks floor tile Mastic
37	Linoleum wood Grain Finish
37A	Linoleum Wood Grain Finish
38	Linoleum Off white w/ Beige Specks
38A	Linoleum Off white w/ Beige Specks Mastic
39	12" X 12" Off White w/ Light specks Floor tile
39A	12" X 12" Off White w/ Light specks Floor tile Mastic
40	12" X 12" Gray w/ gray and black streaks floor tile
40A	12" X 12" Gray w/ gray and black streaks floor tile Mastic
41	12" X 12" Brown w/ Brown and white spec floor tile
41A	12" X 12" Brown w/ Brown and white spec floor tile Mastic
42	science Lab tables
A001	12 x 12 White VFT
A002	12 x 12 White Mastic

A003	Terrazzo - White w/ Black
A004	Terrazzo - Burgundy with Black
A005	2 x 4 White CT - Sculpted
A006	2 x 4 White C.T. - Smooth
A007	Purple with Multi Colored Speck Carpet Mastic
A008	Drywall
A009	Drywall System Compound
A010	Vinyl Baseboard #1
A011	Vinyl Baseboard Mastic
A012	White Spray on Sink Undercoat
A013	Linoleum - Light Blue
A013M	Linoleum Lt. Blue- Mastic
A014	Vinyl Baseboard#2
A015	Vinyl Baseboard Mastic
A016	Gray Spray on Fire Proofing on Beams
A017	Red Spray on Fireproof Material

The following areas were deemed to be inaccessible:

31	12x12 Black Floor Tile Mastic
A017	Red Spray on Fireproof Material

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Panfilo Carrazco, IDPH License # 100-11089. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The ASPIRA - Mirta Ramirez @ Moos School Building 4870 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** ASPIRA - Mirta Ramirez @ Moos School **Unit** 24551 **Building ID** 4870

**Address** 1711 N. California **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04	Aircell Duct Insulation (NOT OBSERVED)	100	SF	East Side Basement Vestibule - Bldg 1893	CHR	TSI	Y	NONE	0		Yes	ACBM with the potential for damage	3	MODERATE
06	9"x9" Beige VFT	130	SF	Engineer's Old Office - Bldg 1893	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
07	9"x9" Beige VFT Mastic	130	SF	Engineer's Office & Room 004 Bldg 1893	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
08	12"x12" Black VFT	2,400	SF	Basement Hallway, Storage Room East of 006, 001 - Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09	12"x12" Black VFT Mastic	2,400	SF	Basement Hallway, Storage Room East of 006, 001 - Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Green Linoleum	800	SF	Room 100 Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
11	Green Linoleum Mastic	800	SF	Room 100 Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Hard Plaster	200,000	SF	Throughout; Base 1st, 2nd, 3rd Floor Bldg 1893	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		HIGH
13	Boiler Jacket	500	SF	Boiler #1 & #2; Bldg 1893	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
14	12"x12" Tan w/ Brown Streaks VFT	1,800	SF	Cafeteria, 001, 006,- Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12"x12" Tan w/ Brown Streaks VFT Mastic	1,800	SF	Cafeteria, 001, 006,- Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12"x12" Green w/ White Streaks VFT	2,300	SF	Rooms 001, 010, 012 (Engineer's Office) engineer's 2nd office & Vestibule To Storeroom Next To Room 006 - Bldg 1893	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
17	12"x12" Green w/ White Streaks VFT Mastic	2,300	SF	Rooms 001 (Not Observed) , 010, 012 (Engineer's Office) engineer's 2nd office & Vestibule To Storeroom Next To Room 006 - Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School ASPIRA - Mirta Ramirez @ Moos School Unit 24551 Building ID 4870

Address 1711 N. California Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
18	12"x12" Brown w/ Brown & White Streaks VFT	2,000	SF	Basement Teachers Lunchroom, 001 (Not Observed) , Assembly Hall -1893 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Brown w/ Brown & White Streaks VFT Mastic	2,000	SF	Basement Teachers Lunchroom, 001 (Not Observed) , Assembly Hall -1893 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12" X 12" Brown floor tile and mastic	750	SF	Room 002, Room 204 Bldg 1893	ASSUMED	MISC	N	LOC	20		No	ACBM with the potential for damage		MODERATE
21	9"x9" Brown VFT Mastic	750	SF	Room 002, Room 204 -Bldg 1893	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
22	12"x12" Blue/Gray VFT	600	SF	1st, 2nd, & 3rd Floor Teacher Toliets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12"x12" Blue/Gray VFT Mastic	600	SF	1st, 2nd, & 3rd Floor Teacher Toliets Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Off White VFT			Removed - Hardwood Floors & Terrazzo Tile - Bldg 1893	ABATED	MISC		NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
25	12"x12" Off White VFT Mastic			Removed	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		LOW
26	12"x12" Tan/Beige VFT	900	SF	Room 102 - Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage	5	MODERATE
27	12"x12" Tan/Beige VFT Mastic	900	SF	Room 102 - Bldg 1893	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	MJP E/F/V on Fiberglass Pipe Insulation (ABATED)			Room 012 Bldg 1893	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
29	Aircell Pipe Insulation (ABATED)			Room 012 (Engineer's Office) Bldg 1893	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
30	12x12 Black Floor Tile	1,400	SF	1st, 2nd, 3rd Floor North Hallway Entrance to New Building - Bldg 1893	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12x12 Black Floor Tile Mastic	1,400	SF	1st, 2nd, 3rd Floor North Hallway Entrance to New	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** ASPIRA - Mirta Ramirez @ Moos School **Unit** 24551 **Building ID** 4870

**Address** 1711 N. California **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building - Bldg 1893										
32	2 x 4 White Ceiling Tile	1,100	SF	1st Flr Main Office; 2nd Flr Rm. 204	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
33	12" X 36" Black Floor tile	100	SF	Room 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
33A	12" X 36" Black floor tile mastic	100	SF	Room 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12" X 12" White w/ tan streaks floor tile	120	SF	Room 121 MDF	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34A	12" X 12" White w/ tan streaks floor tile mastic	120	SF	Room 121 MDF	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12" X 12" Green w/ White streaks floor tile	400	SF	New engineers office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35A	12" X 12" Green w/ White streaks floor tile Mastic	400	SF	New engineers office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12" X 12" Beige w/ White Specks floor tile	500	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36A	12" X 12" Beige w/ White Specks floor tile Mastic	500	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Linoleum wood Grain Finsih	1,500	SF	Gymnasium/ 313	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37A	Linoleum Wood Grain Finish	1,500	SF	Gymnasium/313	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
38	Linoleum Off white w/ Beige Specks	800	SF	Room 303	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38A	Linoleum Off white w/ Beige Specks Mastic	800	SF	Room 303	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12" X 12" Off White w/ Light specks Floor tile	700	SF	Room 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39A	12" X 12" Off White w/ Light specks Floor tile Mastic	700	SF	Room 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12" X 12" Gray w/ gray and black streaks floor tile	70	SF	1st Floor women's facility toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40A	12" X 12" Gray w/ gray and black streaks floor tile Mastic	70	SF	1st floor women's facility toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	12" X 12" Brown w/ Brown and white spec floor tile	800	SF	Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41A	12" X 12" Brown w/ Brown and white spec floor tile Mastic	800	SF	Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	science Lab tables	300	SF	Room 303	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A001	12 x 12 White VFT	21,600	SF	1st, 2nd, 3rd Floor Classrooms ~2010	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** ASPIRA - Mirta Ramirez @ Moos School **Unit** 24551 **Building ID** 4870

**Address** 1711 N. California **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
A002	12 x 12 White Mastic	21,600	SF	Bldg 1st, 2nd, 3rd Floor Classrooms -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A003	Terrazzo - White w/ Black	5,500	SF	Throughout Corridors, Stairwells. 1st, 2nd, 3rd Floors -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A004	Terrazzo - Burgundy with Black	5,500	SF	Throughout Corridors, Stairwells. 1st, 2nd, 3rd Floors -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A005	2 x 4 White CT - Sculpted	5,500	SF	Throughout Classrooms & Offices 1st, 2nd, 3rd Floor -2010 Bldg	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
A006	2 x 4 White C.T. - Smooth	5,500	SF	Throughout Corridors. 1st, 2nd, 3rd Floors -2010 Bldg	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
A007	Purple with Multi Colored Speck Carpet Mastic	5,000	SF	Resource Center Offices -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A008	Drywall	12,000	SF	Throughout 1st, 2nd, 3rd Floors -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A009	Drywall System Compound	4,200	SF	Throughout 1st, 2nd, 3rd Floors -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A010	Vinyl Baseboard #1	6,500	SF	Classrooms 1st, 2nd, 3rd Floors -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A011	Vinyl Baseboard Mastic	6,500	SF	Classrooms 1st, 2nd, 3rd Floors -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A012	White Spray on Sink Undercoat	5	SF	#111- A -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A013	Linoleum - Light Blue	4,200	SF	1st Floor All Purpose Room -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A013M	Linoleum Lt. Blue- Mastic	4,200	SF	1st Floor All Purpose Room -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW



# Chicago Public Schools

**School** ASPIRA - Mirta Ramirez @ Moos School **Unit** 24551 **Building ID** 4870

**Address** 1711 N. California **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
A014	Vinyl Baseboard#2	1,000	SF	1st Floor All Purpose Room & Kitchen -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A015	Vinyl Baseboard Mastic	1,000	SF	1st Floor - All Purpose Room & Kitchen -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A016	Gray Spray on Fire Proofing on Beams	150	SF	2nd Floor Mechanical Room, MDF room 120 and janitors closet 126 -2010 Bldg	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
A017	Red Spray on Fireproof Material	150	SF	2nd Floor Mechanical Room on Beams & Walls -2010 Bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** ASPIRA - Mirta Ramirez @ Moos School **Unit** 24551 **Building ID** 4870  
**Address** 1711 N. California **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>6/13/2019</b>
Inspector Name <b>Panfilo Carrazco</b>
<b>100-11089</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
04	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	Day care
21	
22	
23	
24	
25	
26	
27	

# Chicago Public Schools

**School** ASPIRA - Mirta Ramirez @ Moos School **Unit** 24551 **Building ID** 4870

**Address** 1711 N. California **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
28	
29	
30	
31	
32	
33	
33A	Along perimeter walls
34	
34A	
35	Across from 010 office
35A	across from 010 office
36	
36A	
37	
37A	
38	
38A	
39	
39A	
40	
40A	
41	
41A	
42	
A001	
A002	
A003	
A004	
A005	

# Chicago Public Schools

**School** ASPIRA - Mirta Ramirez @ Moos School **Unit** 24551 **Building ID** 4870  
**Address** 1711 N. California **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
A006	
A007	
A008	
A009	
A010	
A011	
A012	
A013	
A013M	
A014	
A015	
A016	
A017	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School

ASPIRA - Mirta Ramirez @  
Moos School

Unit

24551

Building ID

4870

Address

1711 N. California

Chicago, IL, 60647

Region

02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC)

GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04	Aircell Duct Insulation (NOT OBSERVED)	100	SF	East Side Basement Vestibule - Bldg 1893	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x9" Beige VFT	130	SF	Engineer's Old Office - Bldg 1893	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x9" Beige VFT Mastic	130	SF	Engineer's Office & Room 004 Bldg 1893	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Black VFT	2,400	SF	Basement Hallway, Storage Room East of 006, 001 - Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Black VFT Mastic	2,400	SF	Basement Hallway, Storage Room East of 006, 001 - Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Green Linoleum	800	SF	Room 100 Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Green Linoleum Mastic	800	SF	Room 100 Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Hard Plaster	200,000	SF	Throughout; Base 1st, 2nd, 3rd Floor Bldg 1893	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Boiler Jacket	500	SF	Boiler #1 & #2; Bldg 1893	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" Tan w/ Brown Streaks VFT	1,800	SF	Cafeteria, 001, 006,-Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12"x12" Tan w/ Brown Streaks VFT Mastic	1,800	SF	Cafeteria, 001, 006,-Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" Green w/ White Streaks VFT	2,300	SF	Rooms 001, 010, 012 (Engineer's Office) engineer's 2nd office & Vestibule To Storeroom Next To Room 006 - Bldg 1893	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" Green w/ White Streaks VFT Mastic	2,300	SF	Rooms 001 (Not Observed) , 010, 012 (Engineer's Office) engineer's 2nd office & Vestibule To Storeroom Next To Room 006 - Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Brown w/ Brown & White Streaks VFT	2,000	SF	Basement Teachers Lunchroom, 001 (Not Observed) , Assembly Hall -1893 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Brown w/ Brown & White Streaks VFT Mastic	2,000	SF	Basement Teachers Lunchroom, 001 (Not Observed) , Assembly Hall -1893 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12" X 12" Brown floor tile and mastic	750	SF	Room 002, Room 204 Bldg 1893	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	9"x9" Brown VFT Mastic	750	SF	Room 002, Room 204 -Bldg 1893	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12"x12" Blue/Gray VFT	600	SF	1st, 2nd, & 3rd Floor Teacher Toliets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Blue/Gray VFT Mastic	600	SF	1st, 2nd, & 3rd Floor Teacher Toliets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School

ASPIRA - Mirta Ramirez @  
Moos School

Unit

24551

Building ID

4870

Address

1711 N. California

Chicago, IL, 60647

Region

02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC)

GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Bldg 1893							
24	12"x12" Off White VFT			Removed - Hardwood Floors & Terrazzo Tile - Bldg 1893	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
25	12"x12" Off White VFT Mastic			Removed	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
26	12"x12" Tan/Beige VFT	900	SF	Room 102 - Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12"x12" Tan/Beige VFT Mastic	900	SF	Room 102 - Bldg 1893	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	MJP E/F/V on Fiberglass Pipe Insulation (ABATED)			Room 012 Bldg 1893	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
29	Aircell Pipe Insulation (ABATED)			Room 012 (Engineer's Office) Bldg 1893	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
30	12x12 Black Floor Tile	1,400	SF	1st, 2nd, 3rd Floor North Hallway Entrance to New Building - Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12x12 Black Floor Tile Mastic	1,400	SF	1st, 2nd, 3rd Floor North Hallway Entrance to New Building - Bldg 1893	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	2 x 4 White Ceiling Tile	1,100	SF	1st Flr Main Office; 2nd Flr Rm. 204	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" X 36" Black Floor tile	100	SF	Room 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33A	12" X 36" Black floor tile mastic	100	SF	Room 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12" X 12" White w/ tan streaks floor tile	120	SF	Room 121 MDF	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34A	12" X 12" White w/ tan streaks floor tile mastic	120	SF	Room 121 MDF	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" X 12" Green w/ White streaks floor tile	400	SF	New engineers office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35A	12" X 12" Green w/ White streaks floor tile Mastic	400	SF	New engineers office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" X 12" Beige w/ White Specks floor tile	500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36A	12" X 12" Beige w/ White Specks floor tile Mastic	500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Linoleum wood Grain Finsih	1,500	SF	Gymnasium/ 313	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37A	Linoleum Wood Grain Finish	1,500	SF	Gymnasium/313	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Linoleum Off white w/ Beige Specks	800	SF	Room 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38A	Linoleum Off white w/ Beige Specks Mastic	800	SF	Room 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12" X 12" Off White w/ Light specks Floor tile	700	SF	Room 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39A	12" X 12" Off White w/ Light specks Floor tile Mastic	700	SF	Room 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12" X 12" Gray w/ gray and black streaks floor tile	70	SF	1st Floor women's facility toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40A	12" X 12" Gray w/ gray and black streaks floor tile	70	SF	1st floor women's facility toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School

ASPIRA - Mirta Ramirez @  
Moos School

Unit

24551

Building ID

4870

Address

1711 N. California

Chicago, IL, 60647

Region

02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC)

GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic										
41	12" X 12" Brown w/ Brown and white spec floor tile	800	SF	Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41A	12" X 12" Brown w/ Brown and white spec floor tile Mastic	800	SF	Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	science Lab tables	300	SF	Room 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A001	12 x 12 White VFT	21,600	SF	1st, 2nd, 3rd Floor Classrooms -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A002	12 x 12 White Mastic	21,600	SF	1st, 2nd, 3rd Floor Classrooms -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A003	Terrazzo - White w/ Black	5,500	SF	Throughout Corridors, Stairwells. 1st, 2nd, 3rd Floors -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A004	Terrazzo - Burgundy with Black	5,500	SF	Throughout Corridors, Stairwells. 1st, 2nd, 3rd Floors -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A005	2 x 4 White CT - Sculpted	5,500	SF	Throughout Classrooms & Offices 1st, 2nd, 3rd Floor -2010 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A006	2 x 4 White C.T. - Smooth	5,500	SF	Throughout Corridors. 1st, 2nd, 3rd Floors -2010 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A007	Purple with Multi Colored Speck Carpet Mastic	5,000	SF	Resource Center Offices -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A008	Drywall	12,000	SF	Throughout 1st, 2nd, 3rd Floors -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A009	Drywall System Compound	4,200	SF	Throughout 1st, 2nd, 3rd Floors -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A010	Vinyl Baseboard #1	6,500	SF	Classrooms 1st, 2nd, 3rd Floors -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A011	Vinyl Baseboard Mastic	6,500	SF	Classrooms 1st, 2nd, 3rd Floors -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A012	White Spray on Sink Undercoat	5	SF	#111- A -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A013	Linoleum - Light Blue	4,200	SF	1st Floor All Purpose Room -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A013M	Linoleum Lt. Blue- Mastic	4,200	SF	1st Floor All Purpose Room -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A014	Vinyl Baseboard#2	1,000	SF	1st Floor All Purpose Room & Kitchen -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A015	Vinyl Baseboard Mastic	1,000	SF	1st Floor - All Purpose Room & Kitchen -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

**School**

ASPIRA - Mirta Ramirez @  
Moos School

**Unit**

24551

**Building ID**

4870

**Address**

1711 N. California

Chicago, IL, 60647

**Region**

02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)**

GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
A016	Gray Spray on Fire Proofing on Beams	150	SF	2nd Floor Mechanical Room, MDF room 120 and janitors closet 126 -2010 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A017	Red Spray on Fireproof Material	150	SF	2nd Floor Mechanical Room on Beams & Walls -2010 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School**

ASPIRA - Mirta Ramirez @  
Moos School

**Unit**

24551

**Building ID**

4870

**Address**

1711 N. California

Chicago, IL, 60647

**Region**

02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)**

GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone:

3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

Review Date	09/16/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
04	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	replace damaged ACM/mastic under O&M
21	
22	
23	
24	
25	
26	
27	
28	

# Chicago Public Schools

School

ASPIRA - Mirta Ramirez @  
Moos School

Unit

24551

Building ID

4870

Address

1711 N. California

Chicago, IL, 60647

Region

02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC)

GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone:

3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
29	
30	
31	
32	
33	
33A	
34	
34A	
35	
35A	
36	
36A	
37	
37A	
38	
38A	
39	
39A	
40	
40A	
41	
41A	
42	
A001	
A002	

# Chicago Public Schools

**School** ASPIRA - Mirta Ramirez @  
Moos School

**Unit** 24551

**Building ID** 4870

**Address** 1711 N. California

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
A003	
A004	
A005	
A006	
A007	
A008	
A009	
A010	
A011	
A012	
A013	
A013M	
A014	
A015	
A016	
A017	

# Chicago Public Schools

GSG-Probe Consulting, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	Aircell Duct Insulation (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration Delamination		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration Delamination		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	East Side Basement Vestibule - Bldg 1893		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	Aircell Duct Insulation (NOT OBSERVED)		
MATERIAL LOCATION:	East Side Basement Vestibule - Bldg 1893		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	9"x9" Beige VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Engineer's Old Office - Bldg 1893		
MATERIAL QUANTITY:	130	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>06</b>		
MATERIAL DESCRIPTION:	<b>9"x9" Beige VFT</b>		
MATERIAL LOCATION:	<b>Engineer's Old Office - Bldg 1893</b>		
MATERIAL QUANTITY:	<b>130</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	9"x9" Beige VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Engineer's Office & Room 004 Bldg 1893		
MATERIAL QUANTITY:	130	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>07</b>				
MATERIAL DESCRIPTION:	<b>9"x9" Beige VFT Mastic</b>				
MATERIAL LOCATION:	<b>Engineer's Office &amp; Room 004 Bldg 1893</b>				
MATERIAL QUANTITY:	<b>130</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	12"x12" Black VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Basement Hallway, Storage Room East of 006, 001 - Bldg 1893		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>08</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Black VFT</b>		
MATERIAL LOCATION:	<b>Basement Hallway, Storage Room East of 006, 001 - Bldg 1893</b>		
MATERIAL QUANTITY:	<b>2400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12"x12" Black VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Hallway, Storage Room East of 006, 001 - Bldg 1893		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>09</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Black VFT Mastic</b>		
MATERIAL LOCATION:	<b>Basement Hallway, Storage Room East of 006, 001 - Bldg 1893</b>		
MATERIAL QUANTITY:	<b>2400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Green Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 100 Bldg 1893**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Green Linoleum		
MATERIAL LOCATION:	Room 100 Bldg 1893		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Green Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 100 Bldg 1893**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>11</b>		
MATERIAL DESCRIPTION:	<b>Green Linoleum Mastic</b>		
MATERIAL LOCATION:	<b>Room 100 Bldg 1893</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Hard Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	Throughout; Base 1st, 2nd, 3rd Floor Bldg 1893		
MATERIAL QUANTITY:	200000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>12</b>		
MATERIAL DESCRIPTION:	<b>Hard Plaster</b>		
MATERIAL LOCATION:	<b>Throughout; Base 1st, 2nd, 3rd Floor Bldg 1893</b>		
MATERIAL QUANTITY:	<b>200000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	Boiler Jacket		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler #1 & #2; Bldg 1893**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>13</b>		
MATERIAL DESCRIPTION:	<b>Boiler Jacket</b>		
MATERIAL LOCATION:	<b>Boiler #1 &amp; #2; Bldg 1893</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12"x12" Tan w/ Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, 001, 006,-Bldg 1893		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>14</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Tan w/ Brown Streaks VFT</b>		
MATERIAL LOCATION:	<b>Cafeteria, 001, 006,-Bldg 1893</b>		
MATERIAL QUANTITY:	<b>1800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12"x12" Tan w/ Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, 001, 006,-Bldg 1893		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>15</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Tan w/ Brown Streaks VFT Mastic</b>		
MATERIAL LOCATION:	<b>Cafeteria, 001, 006,-Bldg 1893</b>		
MATERIAL QUANTITY:	<b>1800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12"x12" Green w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 001, 010, 012 (Engineer's Office) engineer's 2nd office & Vestibule To Storeroom Next To Room 006 - Bldg 1893**

MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>16</b>				
MATERIAL DESCRIPTION:	<b>12"x12" Green w/ White Streaks VFT</b>				
MATERIAL LOCATION:	<b>Rooms 001, 010, 012 (Engineer's Office) engineer's 2nd office &amp; Vestibule To Storeroom Next To Room 006 - Bldg 1893</b>				
MATERIAL QUANTITY:	<b>2300</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12"x12" Green w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 001 (Not Observed) , 010, 012 (Engineer's Office) engineer's 2nd office & Vestibule To Storeroom Next To Room 006 - Bldg 1893**

MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12"x12" Green w/ White Streaks VFT Mastic		
MATERIAL LOCATION:	Rooms 001 (Not Observed) , 010, 012 (Engineer's Office) engineer's 2nd office & Vestibule To Storeroom Next To Room 006 - Bldg 1893		
MATERIAL QUANTITY:	2300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Brown & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Teachers Lunchroom, 001 (Not Observed) , Assembly Hall -1893 Bldg		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>18</b>				
MATERIAL DESCRIPTION:	<b>12"x12" Brown w/ Brown &amp; White Streaks VFT</b>				
MATERIAL LOCATION:	<b>Basement Teachers Lunchroom, 001 (Not Observed) , Assembly Hall -1893 Bldg</b>				
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Brown & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Teachers Lunchroom, 001 (Not Observed) , Assembly Hall -1893 Bldg**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>19</b>				
MATERIAL DESCRIPTION:	<b>12"x12" Brown w/ Brown &amp; White Streaks VFT Mastic</b>				
MATERIAL LOCATION:	<b>Basement Teachers Lunchroom, 001 (Not Observed) , Assembly Hall -1893 Bldg</b>				
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12" X 12" Brown floor tile and mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 002, Room 204 Bldg 1893		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	20	DAMAGE UNITS:	SF
COMMENTS:	Day care		

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12" X 12" Brown floor tile and mastic		
MATERIAL LOCATION:	Room 002, Room 204 Bldg 1893		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	20	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

replace damaged ACM/mastic under O&M

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	9"x9" Brown VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 002, Room 204 -Bldg 1893		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>21</b>		
MATERIAL DESCRIPTION:	<b>9"x9" Brown VFT Mastic</b>		
MATERIAL LOCATION:	<b>Room 002, Room 204 -Bldg 1893</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12"x12" Blue/Gray VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd, & 3rd Floor Teacher Toilets		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>22</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Blue/Gray VFT</b>		
MATERIAL LOCATION:	<b>1st, 2nd, &amp; 3rd Floor Teacher Toilets</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	12"x12" Blue/Gray VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Teacher Toilets Bldg 1893**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>23</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Blue/Gray VFT Mastic</b>		
MATERIAL LOCATION:	<b>1st, 2nd, &amp; 3rd Floor Teacher Toilets Bldg 1893</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez @ Moos School** INSPECTION DATE: **6/13/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Off White VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Removed - Hardwood Floors & Terrazzo Tile - Bldg 1893**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/13/2019**

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>24</b>	
MATERIAL DESCRIPTION:	<b>12"x12" Off White VFT</b>	
MATERIAL LOCATION:	<b>Removed - Hardwood Floors &amp; Terrazzo Tile - Bldg 1893</b>	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25	
MATERIAL DESCRIPTION:	12"x12" Off White VFT Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Removed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12"x12" Off White VFT Mastic**

MATERIAL LOCATION: **Removed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12"x12" Tan/Beige VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 102 - Bldg 1893		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>26</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Tan/Beige VFT</b>		
MATERIAL LOCATION:	<b>Room 102 - Bldg 1893</b>		
MATERIAL QUANTITY:	<b>900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12"x12" Tan/Beige VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 102 - Bldg 1893**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>27</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Tan/Beige VFT Mastic</b>		
MATERIAL LOCATION:	<b>Room 102 - Bldg 1893</b>		
MATERIAL QUANTITY:	<b>900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28	
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation (ABATED)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 012 Bldg 1893

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation (ABATED)**

MATERIAL LOCATION: **Room 012 Bldg 1893**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	Aircell Pipe Insulation (ABATED)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 012 (Engineer's Office) Bldg 1893

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation (ABATED)**

MATERIAL LOCATION: **Room 012 (Engineer's Office) Bldg 1893**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12x12 Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd, 3rd Floor North Hallway Entrance to New Building - Bldg 1893		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12x12 Black Floor Tile		
MATERIAL LOCATION:	1st, 2nd, 3rd Floor North Hallway Entrance to New Building - Bldg 1893		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12x12 Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd, 3rd Floor North Hallway Entrance to New Building - Bldg 1893		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12x12 Black Floor Tile Mastic		
MATERIAL LOCATION:	1st, 2nd, 3rd Floor North Hallway Entrance to New Building - Bldg 1893		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	2 x 4 White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Flr Main Office; 2nd Flr Rm. 204		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>32</b>		
MATERIAL DESCRIPTION:	<b>2 x 4 White Ceiling Tile</b>		
MATERIAL LOCATION:	<b>1st Flr Main Office; 2nd Flr Rm. 204</b>		
MATERIAL QUANTITY:	<b>1100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	ASBESTOS INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A001		
MATERIAL DESCRIPTION:	12 x 12 White VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd, 3rd Floor Classrooms -2010 Bldg		
MATERIAL QUANTITY:	21600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>A001</b>				
MATERIAL DESCRIPTION:	<b>12 x 12 White VFT</b>				
MATERIAL LOCATION:	<b>1st, 2nd, 3rd Floor Classrooms -2010 Bldg</b>				
MATERIAL QUANTITY:	<b>21600</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A002		
MATERIAL DESCRIPTION:	12 x 12 White Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd, 3rd Floor Classrooms -2010 Bldg		
MATERIAL QUANTITY:	21600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>A002</b>				
MATERIAL DESCRIPTION:	<b>12 x 12 White Mastic</b>				
MATERIAL LOCATION:	<b>1st, 2nd, 3rd Floor Classrooms -2010 Bldg</b>				
MATERIAL QUANTITY:	<b>21600</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A003		
MATERIAL DESCRIPTION:	Terrazzo - White w/ Black		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Corridors, Stairwells. 1st, 2nd, 3rd Floors -2010 Bldg		
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>A003</b>		
MATERIAL DESCRIPTION:	<b>Terrazzo - White w/ Black</b>		
MATERIAL LOCATION:	<b>Throughout Corridors, Stairwells. 1st, 2nd, 3rd Floors -2010 Bldg</b>		
MATERIAL QUANTITY:	<b>5500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A004		
MATERIAL DESCRIPTION:	Terrazzo - Burgundy with Black		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Corridors, Stairwells. 1st, 2nd, 3rd Floors -2010 Bldg**

MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>A004</b>		
MATERIAL DESCRIPTION:	<b>Terrazzo - Burgundy with Black</b>		
MATERIAL LOCATION:	<b>Throughout Corridors, Stairwells. 1st, 2nd, 3rd Floors -2010 Bldg</b>		
MATERIAL QUANTITY:	<b>5500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A005		
MATERIAL DESCRIPTION:	2 x 4 White CT - Sculpted		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Classrooms & Offices 1st, 2nd, 3rd Floor -2010 Bldg		
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>A005</b>		
MATERIAL DESCRIPTION:	<b>2 x 4 White CT - Sculpted</b>		
MATERIAL LOCATION:	<b>Throughout Classrooms &amp; Offices 1st, 2nd, 3rd Floor -2010 Bldg</b>		
MATERIAL QUANTITY:	<b>5500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A006		
MATERIAL DESCRIPTION:	2 x 4 White C.T. - Smooth		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Corridors. 1st, 2nd, 3rd Floors -2010 Bldg		
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	A006		
MATERIAL DESCRIPTION:	2 x 4 White C.T. - Smooth		
MATERIAL LOCATION:	Throughout Corridors. 1st, 2nd, 3rd Floors -2010 Bldg		
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A007		
MATERIAL DESCRIPTION:	Purple with Multi Colored Speck Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Resource Center Offices -2010 Bldg**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	A007		
MATERIAL DESCRIPTION:	Purple with Multi Colored Speck Carpet Mastic		
MATERIAL LOCATION:	Resource Center Offices -2010 Bldg		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A008		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1st, 2nd, 3rd Floors -2010 Bldg		
MATERIAL QUANTITY:	12000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>A008</b>		
MATERIAL DESCRIPTION:	<b>Drywall</b>		
MATERIAL LOCATION:	<b>Throughout 1st, 2nd, 3rd Floors -2010 Bldg</b>		
MATERIAL QUANTITY:	<b>12000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A009		
MATERIAL DESCRIPTION:	Drywall System Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1st, 2nd, 3rd Floors -2010 Bldg**

MATERIAL QUANTITY: **4200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	A009		
MATERIAL DESCRIPTION:	Drywall System Compound		
MATERIAL LOCATION:	Throughout 1st, 2nd, 3rd Floors -2010 Bldg		
MATERIAL QUANTITY:	4200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A010		
MATERIAL DESCRIPTION:	Vinyl Baseboard #1		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 1st, 2nd, 3rd Floors -2010 Bldg**

MATERIAL QUANTITY: **6500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	A010		
MATERIAL DESCRIPTION:	Vinyl Baseboard #1		
MATERIAL LOCATION:	Classrooms 1st, 2nd, 3rd Floors -2010 Bldg		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A011		
MATERIAL DESCRIPTION:	Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 1st, 2nd, 3rd Floors -2010 Bldg**

MATERIAL QUANTITY: **6500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	A011		
MATERIAL DESCRIPTION:	Vinyl Baseboard Mastic		
MATERIAL LOCATION:	Classrooms 1st, 2nd, 3rd Floors -2010 Bldg		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A012		
MATERIAL DESCRIPTION:	White Spray on Sink Undercoat		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **#111- A -2010 Bldg**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	A012		
MATERIAL DESCRIPTION:	White Spray on Sink Undercoat		
MATERIAL LOCATION:	#111- A -2010 Bldg		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A013		
MATERIAL DESCRIPTION:	Linoleum - Light Blue		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor All Purpose Room -2010 Bldg**

MATERIAL QUANTITY: **4200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>A013</b>				
MATERIAL DESCRIPTION:	<b>Linoleum - Light Blue</b>				
MATERIAL LOCATION:	<b>1st Floor All Purpose Room -2010 Bldg</b>				
MATERIAL QUANTITY:	<b>4200</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A013M		
MATERIAL DESCRIPTION:	Linoleum Lt. Blue- Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor All Purpose Room -2010 Bldg		
MATERIAL QUANTITY:	4200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	A013M		
MATERIAL DESCRIPTION:	Linoleum Lt. Blue- Mastic		
MATERIAL LOCATION:	1st Floor All Purpose Room -2010 Bldg		
MATERIAL QUANTITY:	4200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A014		
MATERIAL DESCRIPTION:	Vinyl Baseboard#2		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor All Purpose Room & Kitchen -2010 Bldg		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	A014		
MATERIAL DESCRIPTION:	Vinyl Baseboard#2		
MATERIAL LOCATION:	1st Floor All Purpose Room & Kitchen -2010 Bldg		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A015		
MATERIAL DESCRIPTION:	Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor - All Purpose Room & Kitchen -2010 Bldg**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>A015</b>		
MATERIAL DESCRIPTION:	<b>Vinyl Baseboard Mastic</b>		
MATERIAL LOCATION:	<b>1st Floor - All Purpose Room &amp; Kitchen -2010 Bldg</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A016		
MATERIAL DESCRIPTION:	Gray Spray on Fire Proofing on Beams		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Mechanical Room, MDF room 120 and janitors closet 126 -2010 Bldg**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24551</b>	BUILDING ID:	<b>4870</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>ASPIRA - Mirta Ramirez @ Moos School</b>	REVIEW DATE:	<b>9/16/2019</b>		
ADDRESS:	<b>1711 N. California</b>	IDPH LICENSE NO:	<b>100-11089</b>		

---

HOMOGENEOUS AREA:	<b>A016</b>				
MATERIAL DESCRIPTION:	<b>Gray Spray on Fire Proofing on Beams</b>				
MATERIAL LOCATION:	<b>2nd Floor Mechanical Room, MDF room 120 and janitors closet 126 -2010 Bldg</b>				
MATERIAL QUANTITY:	<b>150</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A017		
MATERIAL DESCRIPTION:	Red Spray on Fireproof Material		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Mechanical Room on Beams & Walls -2010 Bldg**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

HOMOGENEOUS AREA:	A017		
MATERIAL DESCRIPTION:	Red Spray on Fireproof Material		
MATERIAL LOCATION:	2nd Floor Mechanical Room on Beams & Walls -2010 Bldg		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019



# **Chicago Public Schools**

**GSG-Probe Consulting, Inc.**

***2019 AHERA REINSPECTION***

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	37A				
MATERIAL DESCRIPTION:	Linoleum Wood Grain Finish				
MATERIAL LOCATION:	Gymnasium/313				
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:		DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **37A**

MATERIAL DESCRIPTION: **Linoleum Wood Grain Finish**

MATERIAL LOCATION: **Gymnasium/313**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	36A				
MATERIAL DESCRIPTION:	12" X 12" Beige w/ White Specks floor tile Mastic				
MATERIAL LOCATION:	Auditorium				
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **36A**  
MATERIAL DESCRIPTION: **12" X 12" Beige w/ White Specks floor tile Mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Linoleum wood Grain Finsih		
MATERIAL LOCATION:	Gymnasium/ 313		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Linoleum wood Grain Finsih**  
MATERIAL LOCATION: **Gymnasium/ 313**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	33				
MATERIAL DESCRIPTION:	12" X 36" Black Floor tile				
MATERIAL LOCATION:	Room 204				
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" X 36" Black Floor tile**  
MATERIAL LOCATION: **Room 204**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	41A				
MATERIAL DESCRIPTION:	12" X 12" Brown w/ Brown and white spec floor tile Mastic				
MATERIAL LOCATION:	Room 103				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **41A**

MATERIAL DESCRIPTION: **12" X 12" Brown w/ Brown and white spec floor tile Mastic**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	39A				
MATERIAL DESCRIPTION:	12" X 12" Off White w/ Light specks Floor tile Mastic				
MATERIAL LOCATION:	Room 201				
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **39A**

MATERIAL DESCRIPTION: **12" X 12" Off White w/ Light specks Floor tile Mastic**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12" X 12" Gray w/ gray and black streaks floor tile		
MATERIAL LOCATION:	1st Floor women's facility toilet		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12" X 12" Gray w/ gray and black streaks floor tile**  
MATERIAL LOCATION: **1st Floor women's facility toilet**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Linoleum Off white w/ Beige Specks		
MATERIAL LOCATION:	Room 303		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	REVIEW DATE:	9/16/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

HOMOGENEOUS AREA: 38

MATERIAL DESCRIPTION: Linoleum Off white w/ Beige Specks

MATERIAL LOCATION: Room 303

MATERIAL QUANTITY: 800

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/16/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	34				
MATERIAL DESCRIPTION:	12" X 12" White w/ tan streaks floor tile				
MATERIAL LOCATION:	Room 121 MDF				
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12" X 12" White w/ tan streaks floor tile**  
MATERIAL LOCATION: **Room 121 MDF**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	34A				
MATERIAL DESCRIPTION:	12" X 12" White w/ tan streaks floor tile mastic				
MATERIAL LOCATION:	Room 121 MDF				
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **34A**  
MATERIAL DESCRIPTION: **12" X 12" White w/ tan streaks floor tile mastic**  
MATERIAL LOCATION: **Room 121 MDF**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	35A				
MATERIAL DESCRIPTION:	12" X 12" Green w/ White streaks floor tile Mastic				
MATERIAL LOCATION:	New engineers office				
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					
across from 010 office					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24551**      BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez**      REVIEW DATE: **9/16/2019**  
                  **@ Moos School**  
ADDRESS: **1711 N. California**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **35A**  
MATERIAL DESCRIPTION: **12" X 12" Green w/ White streaks floor tile Mastic**  
MATERIAL LOCATION: **New engineers office**  
MATERIAL QUANTITY: **400**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	33A		
MATERIAL DESCRIPTION:	12" X 36" Black floor tile mastic		
MATERIAL LOCATION:	Room 204		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			
Along perimeter walls			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019



# Chicago Public Schools

**GSG-Probe Consulting, Inc.**  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez** REVIEW DATE: **9/16/2019**  
**@ Moos School**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **33A**  
MATERIAL DESCRIPTION: **12" X 36" Black floor tile mastic**  
MATERIAL LOCATION: **Room 204**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	science Lab tables		
MATERIAL LOCATION:	Room 303		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **science Lab tables**  
MATERIAL LOCATION: **Room 303**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	39				
MATERIAL DESCRIPTION:	12" X 12" Off White w/ Light specks Floor tile				
MATERIAL LOCATION:	Room 201				
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12" X 12" Off White w/ Light specks Floor tile**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	38A				
MATERIAL DESCRIPTION:	Linoleum Off white w/ Beige Specks Mastic				
MATERIAL LOCATION:	Room 303				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **38A**

MATERIAL DESCRIPTION: **Linoleum Off white w/ Beige Specks Mastic**

MATERIAL LOCATION: **Room 303**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12" X 12" Green w/ White streaks floor tile		
MATERIAL LOCATION:	New engineers office		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			
Across from 010 office			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019



# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12" X 12" Green w/ White streaks floor tile**  
MATERIAL LOCATION: **New engineers office**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	41				
MATERIAL DESCRIPTION:	12" X 12" Brown w/ Brown and white spec floor tile				
MATERIAL LOCATION:	Room 103				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez** REVIEW DATE: **9/16/2019**  
**@ Moos School**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" X 12" Brown w/ Brown and white spec floor tile**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	40A				
MATERIAL DESCRIPTION:	12" X 12" Gray w/ gray and black streaks floor tile Mastic				
MATERIAL LOCATION:	1st floor women's facility toilet				
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

## GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez  
@ Moos School** REVIEW DATE: **9/16/2019**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **40A**

MATERIAL DESCRIPTION: **12" X 12" Gray w/ gray and black streaks floor tile Mastic**

MATERIAL LOCATION: **1st floor women's facility toilet**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24551	BUILDING ID:	4870
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Panfilo Carrazco		
SCHOOL NAME:	ASPIRA - Mirta Ramirez @ Moos School	INSPECTION DATE:	6/13/2019		
ADDRESS:	1711 N. California	IDPH LICENSE NO:	100-11089		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12" X 12" Beige w/ White Specks floor tile		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 06/13/2019

# Chicago Public Schools

**GSG-Probe Consulting, Inc.**  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24551** BUILDING ID: **4870**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **ASPIRA - Mirta Ramirez** REVIEW DATE: **9/16/2019**  
**@ Moos School**  
ADDRESS: **1711 N. California** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12" X 12" Beige w/ White Specks floor tile**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/16/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---



# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

PANFILO CARRAZCO

This is to certify that \_\_\_\_\_  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR10

Certificate Number:



*N. Penneff*

Director of Training

Nicholas J. Penneff

Director of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**PANFILO CARRAZCO**  
855 W ADAMS STREET, SUITE 200  
CHICAGO, IL 60607

4/28/2017

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	2/11/2018
100 - 11089	4/28/2017	05/15/2018		
<b>PANFILO CARRAZCO</b> 855 W ADAMS STREET, SUITE CHICAGO, IL 60607 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/4/2018
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PANFILO CARRAZCO  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



**PUBLIC HEALTH & SAFETY inc.**  
Environmental and Occupational Services  
312 S. Ashland Ave., Chicago, IL 60607  
www.public-health-safety.com  
Office: 312-491-0081  
Fax: 312-421-2501

02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR08

Certificate Number:

Phone: 312-491-0081

Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**PANFILO CARRAZCO**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

IDPH ILLINOIS DEPARTMENT OF PUBLIC HEALTH PROTECTING HEALTH. IMPROVING LIVES			ENDORSEMENTS	TC EXPIRES
<b>ASBESTOS PROFESSIONAL LICENSE</b>			INSPECTOR	2/9/2020
ID NUMBER 100 - 11089	ISSUED 4/19/2019	EXPIRES 05/15/2020	PROJECT MANAGER	2/2/2020
<b>PANFILO CARRAZCO</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			AIR SAMPLING PROFESSIONAL	
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois 62761-0201 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/18/2016

**PANFILO CARRAZCO**  
855 W ADAMS STREET, SUITE 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License			Back of License	
 <b>ASBESTOS PROFESSIONAL LICENSE</b>			<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 11089	<b>ISSUED</b> 4/18/2016	<b>EXPIRES</b> 05/15/2017	INSPECTOR	2/13/2017
<b>PANFILO CARRAZCO</b> 855 W ADAMS STREET, SUITE CHICAGO, IL 60607 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/6/2017
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH. IMPROVING LIVES**  
*Nationally Accredited by PHAB*



2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JIGAR M SHAH**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <b>ASBESTOS PROFESSIONAL LICENSE</b>			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	2/28/2020
100 - 07342	4/19/2019	05/15/2020	PROJECT DESIGNER	3/15/2020
<b>JIGAR M SHAH</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	2/28/2020
			PROJECT MANAGER	2/22/2020
			AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)

EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---



# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed