

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2381
SCHOOL NAME: Oglesby School
ADDRESS OF SCHOOL: 7646 S. Green
CITY: Chicago, IL, 60620

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/24/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 405
IDPH INSPECTOR LICENSE NUMBER: 100-07839
IDPH LICENSED INSPECTOR NAME(Please Print): Lisa Laney
IDPH MP LICENSE NUMBER: 100-09786
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): John Fenn

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Oglesby School

7646 S. Green
Chicago, IL, 60620

Unit: 24741
Building ID: 5170

IDPH ID Number: 14-016-2990-2381

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

August 29, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24741 Region: 05 IDPH ID:14-016-2990-2381

School: Oglesby School Building ID: 5170

Address: 7646 S. Green
Chicago, IL, 60620

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/27/2019

Inspector: Lisa Laney Inspector IDPH License: 100-07839
Management Planner: John Fenn Management Planner IDPH License: 100-09786

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

John Fenn
100-09786

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 29, 2019

RE: Oglesby School, Unit 24741
7646 S. Green
Chicago, IL, 60620

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Oglesby School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Oglesby School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Oglesby School
Address: 7646 S. Green
IDPH ID: 14-016-2990-2381
Contact:

Unit: 24741
Chicago, IL, 60620
Building ID: 5170
Phone:

Region: 05

2. Description of Facility

Original Construction: 1907
Total Square Footage: 77140
Current Occupancy: 405

Additional Construction:
No of Floors: 3

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Lisa Laney

Inspector IDPH license # 100-07839

Signature:
Date: 8/29/2019

6. Management Planner

Management Planner Name: John Fenn

Management Planner IDPH license # 100-09786

Signature:
Date: 09/27/2019

7. Review Date:09/27/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Oglesby School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5170:

34	Green Chalkboards
35	12x12 Tan w/White & Brown Floor Tile
35A	12x12 Tan w/White & Brown Floor Tile Mastic
A	Fiberglass Pipe w/Hard Elbows

B. The following new homogenous areas have been identified for Building 5170:

- | | |
|-----|---|
| 34 | Green Chalkboards |
| 35 | 12x12 Tan w/White & Brown Floor Tile |
| 35A | 12x12 Tan w/White & Brown Floor Tile Mastic |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

06C	12x12 Aqua Specked Floor Tile
06D	12x12 Tan Specked Floor Tile
06E	12x12 Beige Specked Floor Tile
06F	12x12 Gray Specked Floor Tile
06G	12x12 Violet Floor Tile
15A	12x12 Off-White Floor Tile Mastic
15C	12x12 Aqua Specked Floor Tile
15F	12x12 Gray Specked Floor Tile Mastic
15G	12x12 Floor Tile Mastic
17A	Green Carpet Mastic
18	12x12 Brown/Green Floor Tile
20	12x12 White w/Light Brown floor tile
21	12x12 White w/Light Brown Floor Tile
24	Brown Chalk Board Adhesive
25	2x4 White Ceiling Tile w/ Pinhole & Worm
27	12" x 12" Beige Speckled Vinyl Floor Tile
28	12" x 12" Beige Speckled Vinyl Floor Tile Mastic
29	12" x 12" Red Vinyl Floor Tile
30	12" x 12" Red Vinyl Floor Tile Mastic
31	12" x 12" Brown w/ White & Brown Vinyl Floor Tile
32	12" x 12" Brown w/White & Brown Vinyl Floor Tile Mastic
33	Carpet Mastic
34	Green Chalkboards
35	12x12 Tan w/White & Brown Floor Tile
35A	12x12 Tan w/White & Brown Floor Tile Mastic
A	Fiberglass Pipe w/Hard Elbows
B	Condensate Tank

The following areas were deemed to be inaccessible:

15A	12x12 Off-White Floor Tile Mastic
15D	12x12 Tan Specked Floor Tile Mastic
15E	12x12 Beige Specked Floor Tile Mastic
15F	12x12 Gray Specked Floor Tile Mastic
17A	Green Carpet Mastic
21	12x12 White w/Light Brown Floor Tile
24	Brown Chalk Board Adhesive
28	12" x 12" Beige Speckled Vinyl Floor Tile Mastic

30
33

12" x 12" Red Vinyl Floor Tile Mastic
Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Lisa Laney, IDPH License # 100-07839. The Management Plan was updated by John Fenn, IDPH License # 100-09786. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Oglesby School Building 5170 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Oglesby School Unit 24741 Building ID 5170

Address 7646 S. Green Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
06A	12x12 Off-White Floor Tile	3,000	SF	Engineer's Office, Office Storage, 005, 102	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06B	12x12 Off-White Specked Floor Tile	11,500	SF	Lunchroom, 1st & 2nd floor corridors, 1st floor west stair landing	CHR	MISC	N	NONE	0		No	ACBM with potential for significant damage		LOW
06C	12x12 Aqua Specked Floor Tile	1,800	SF	Main Office, Assistant Principal's Office, Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06D	12x12 Tan Specked Floor Tile	850	SF	1st Floor Adjustment Office 304	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06E	12x12 Beige Specked Floor Tile	850	SF	1st Floor Adjustment Office 304	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06F	12x12 Gray Specked Floor Tile	2,300	SF	1st & 2nd Floor East Stair Landings, 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06G	12x12 Violet Floor Tile	1,100	SF	2nd Floor East Stair Landing, 3rd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	12x12 Off-White Floor Tile Mastic	3,000	SF	Engineer's Office, Office Storage, 005, 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15B	12x12 Off-White Specked Floor Tile	8,000	SF	Lunchroom, 1st & 2nd floor corridors, 101, 100, 200, 206, 302, 1st floor West stair landing	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15C	12x12 Aqua Specked Floor Tile	1,800	SF	Main Office, Assistant Principal's Office, Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15D	12x12 Tan Specked Floor Tile Mastic	850	SF	1st Floor Adjustment Office, 304	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15E	12x12 Beige Specked Floor Tile Mastic	850	SF	1st Floor Adjustment Office, 304	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15F	12x12 Gray Specked Floor Tile Mastic	2,300	SF	1st & 2nd Floor East Stair Landings, 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15G	12x12 Floor Tile Mastic	1,100	SF	2nd Floor East Stair Landing, 3rd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Oglesby School Unit 24741 Building ID 5170

Address 7646 S. Green Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridor										
17A	Green Carpet Mastic	1,200	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12x12 Brown/Green Floor Tile	2,000	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19A	12x12 White Floor Tile (Building Demolished 2011)			Modular Building - Classrooms and Corridor		MISC								
19B	12x12 White Floor Tile Mastic (Building Demolished 2011)			Modular Building - Classrooms and Corridor		MISC								
20	12x12 White w/Light Brown floor tile	800	SF	Room 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12x12 White w/Light Brown Floor Tile	800	SF	Room 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	4" Tan Vinyl Basecover (Building Demolished 2011)			Modular Building Throughout (Building Demolished 2011)		MISC								
23	4" Tan Vinyl Basecover Adhesive (Building Demolished 2011)			Modular Building-Throughout (Building Demolished 2011)		MISC								
24	Brown Chalk Board Adhesive	3,700	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	2x4 White Ceiling Tile w/ Pinhole & Worm	10,000	SF	Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2x2 White Ceiling Tile (Building Demolished 2011)			Modular Building Throughout		MISC								
27	12" x 12" Beige Speckled Vinyl Floor Tile	5,208	SF	Engineer's Office, Main Office, Room 106, 107, 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12" x 12" Beige Speckled Vinyl Floor Tile Mastic	5,208	SF	Engineer's Office, Main Office, Room 106, 107, 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12" x 12" Red Vinyl Floor Tile	1,040	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12" x 12" Red Vinyl Floor Tile Mastic	1,040	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12" x 12" Brown w/ White & Brown Vinyl Floor Tile	5,000	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12" x 12" Brown w/White & Brown Vinyl Floor Tile Mastic	5,000	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Carpet Mastic	1,040	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Oglesby School Unit 24741 Building ID 5170

Address 7646 S. Green Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
34	Green Chalkboards		SF	Throughout Classrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
35	12x12 Tan w/White & Brown Floor Tile	3,600	SF	3rd Floor Gymnasium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
35A	12x12 Tan w/White & Brown Floor Tile Mastic	3,600	SF	3rd Floor Gymnasium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Fiberglass Pipe w/Hard Elbows	120	LF	Boiler Room, Fan and Pump Room, Basement, Lunch Break area, Custodian Closets Throughout	ASSUMED	TSI	Y	LOC	15		Yes	ACBM with potential for significant damage	3	MODERATE
B	Condensate Tank	170	SF	Pump Room	ASSUMED	TSI	Y	LOC	30		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE

Chicago Public Schools

School Oglesby School Unit 24741 Building ID 5170

Address 7646 S. Green Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/29/2019
Inspector Name <u>Lisa Laney</u>
100-07839 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
06A	
06B	
06C	
06D	
06E	
06F	
06G	
15A	
15B	
15C	
15D	
15E	
15F	
15G	
17A	
18	
19A	Building Demolished 2011
19B	Building Demolished 2011
20	
21	
22	Building Demolished 2011
23	Building Demolished 2011
24	

Chicago Public Schools

School Oglesby School Unit 24741 Building ID 5170

Address 7646 S. Green Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
25	
26	Building Demolished 2011
27	
28	
29	
30	
31	
32	
33	
34	
35	
35A	
A	15 LF of Damage in Pump Room and 2nd Floor Janitor's Closet (Photos Included)
B	30 Sq Ft Damaged (Photos included)

Table II

Management Planner's Review

Chicago Public Schools

School Oglesby School

Unit 24741

Building ID 5170

Address 7646 S. Green

Chicago, IL, 60620

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
06A	12x12 Off-White Floor Tile	3,000	SF	Engineer's Office, Office Storage, 005, 102	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06B	12x12 Off-White Specked Floor Tile	11,500	SF	Lunchroom, 1st & 2nd floor corridors, 1st floor west stair landing	Chrysotile	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
06C	12x12 Aqua Specked Floor Tile	1,800	SF	Main Office, Assistant Principal's Office, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06D	12x12 Tan Specked Floor Tile	850	SF	1st Floor Adjustment Office 304	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06E	12x12 Beige Specked Floor Tile	850	SF	1st Floor Adjustment Office 304	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06F	12x12 Gray Specked Floor Tile	2,300	SF	1st & 2nd Floor East Stair Landings, 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06G	12x12 Violet Floor Tile	1,100	SF	2nd Floor East Stair Landing, 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12x12 Off-White Floor Tile Mastic	3,000	SF	Engineer's Office, Office Storage, 005, 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15B	12x12 Off-White Specked Floor Tile	8,000	SF	Lunchroom, 1st & 2nd floor corridors, 101, 100, 200, 206, 302, 1st floor West stair landing	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15C	12x12 Aqua Specked Floor Tile	1,800	SF	Main Office, Assistant Principal's Office, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15D	12x12 Tan Specked Floor Tile Mastic	850	SF	1st Floor Adjustment Office, 304	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15E	12x12 Beige Specked Floor Tile Mastic	850	SF	1st Floor Adjustment Office, 304	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15F	12x12 Gray Specked Floor Tile Mastic	2,300	SF	1st & 2nd Floor East Stair Landings, 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15G	12x12 Floor Tile Mastic	1,100	SF	2nd Floor East Stair Landing, 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	Green Carpet Mastic	1,200	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12x12 Brown/Green Floor Tile	2,000	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12x12 White Floor Tile (Building Demolished 2011)			Modular Building - Classrooms and Corridor		MISC					
19B	12x12 White Floor Tile Mastic (Building Demolished 2011)			Modular Building - Classrooms and Corridor		MISC					
20	12x12 White w/Light Brown floor tile	800	SF	Room 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 White w/Light Brown Floor Tile	800	SF	Room 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	4" Tan Vinyl Basecover (Building Demolished 2011)			Modular Building Throughout (Building Demolished 2011)		MISC					

Chicago Public Schools

School Oglesby School

Unit 24741

Building ID 5170

Address 7646 S. Green

Chicago, IL, 60620

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
23	4" Tan Vinyl Basecover Adhesive (Building Demolished 2011)			Modular Building- Throughout (Building Demolished 2011)		MISC					
24	Brown Chalk Board Adhesive	3,700	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	2x4 White Ceiling Tile w/ Pinhole & Worm	10,000	SF	Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	2x2 White Ceiling Tile (Building Demolished 2011)			Modular Building Throughout		MISC					
27	12" x 12" Beige Speckled Vinyl Floor Tile	5,208	SF	Engineer's Office, Main Office, Room 106, 107, 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" x 12" Beige Speckled Vinyl Floor Tile Mastic	5,208	SF	Engineer's Office, Main Office, Room 106, 107, 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" x 12" Red Vinyl Floor Tile	1,040	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" x 12" Red Vinyl Floor Tile Mastic	1,040	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Brown w/ White & Brown Vinyl Floor Tile	5,000	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12" x 12" Brown w/White & Brown Vinyl Floor Tile Mastic	5,000	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Carpet Mastic	1,040	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Green Chalkboards		SF	Throughout Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12x12 Tan w/White & Brown Floor Tile	3,600	SF	3rd Floor Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
35A	12x12 Tan w/White & Brown Floor Tile Mastic	3,600	SF	3rd Floor Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
A	Fiberglass Pipe w/Hard Elbows	120	LF	Boiler Room, Fan and Pump Room, Basement, Lunch Break area, Custodian Closets Throughout	Assumed	TSI	Yes	15	LF	5 ACBM with potential for significant damage	Repair
B	Condensate Tank	170	SF	Pump Room	Assumed	TSI	Yes	30	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair

Chicago Public Schools

School Oglesby School
Address 7646 S. Green

Unit 24741
 Chicago, IL, 60620

Building ID 5170
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	09/27/2019
Manager Planner Name	John Fenn
100-09786	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
06A	
06B	
06C	
06D	
06E	
06F	
06G	
15A	
15B	
15C	
15D	
15E	
15F	

Chicago Public Schools

School Oglesby School
Address 7646 S. Green

Unit 24741
Chicago, IL, 60620

Building ID 5170
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
15G	
17A	
18	
19A	
19B	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
35A	
A	
B	

Chicago Public Schools

School Oglesby School

Unit 24741

Building ID 5170

Address 7646 S. Green

Chicago, IL, 60620

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office, Office Storage, 005, 102**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**
MATERIAL LOCATION: **Engineer's Office, Office Storage, 005, 102**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **12x12 Off-White Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, 1st & 2nd floor corridors, 1st floor west stair landing**
MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **12x12 Off-White Specked Floor Tile**
MATERIAL LOCATION: **Lunchroom, 1st & 2nd floor corridors, 1st floor west stair landing**
MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **12x12 Aqua Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, Assistant Principal's Office, Auditorium**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **12x12 Aqua Specked Floor Tile**
MATERIAL LOCATION: **Main Office, Assistant Principal's Office, Auditorium**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06D**
MATERIAL DESCRIPTION: **12x12 Tan Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Adjustment Office 304**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **06D**
MATERIAL DESCRIPTION: **12x12 Tan Specked Floor Tile**
MATERIAL LOCATION: **1st Floor Adjustment Office 304**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06E**
MATERIAL DESCRIPTION: **12x12 Beige Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Adjustment Office 304**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **06E**
MATERIAL DESCRIPTION: **12x12 Beige Specked Floor Tile**
MATERIAL LOCATION: **1st Floor Adjustment Office 304**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06F**
MATERIAL DESCRIPTION: **12x12 Gray Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor East Stair Landings, 3rd Floor Corridors**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **06F**
MATERIAL DESCRIPTION: **12x12 Gray Specked Floor Tile**
MATERIAL LOCATION: **1st & 2nd Floor East Stair Landings, 3rd Floor Corridors**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06G**
MATERIAL DESCRIPTION: **12x12 Violet Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor East Stair Landing, 3rd Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **06G**
MATERIAL DESCRIPTION: **12x12 Violet Floor Tile**
MATERIAL LOCATION: **2nd Floor East Stair Landing, 3rd Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office, Office Storage, 005, 102**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office, Office Storage, 005, 102**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **12x12 Off-White Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, 1st & 2nd floor corridors, 101, 100, 200, 206, 302, 1st floor West stair landing**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **12x12 Off-White Specked Floor Tile**
MATERIAL LOCATION: **Lunchroom, 1st & 2nd floor corridors, 101, 100, 200, 206, 302, 1st floor West stair landing**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15C**
MATERIAL DESCRIPTION: **12x12 Aqua Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, Assistant Principal's Office, Auditorium**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **15C**
MATERIAL DESCRIPTION: **12x12 Aqua Specked Floor Tile**
MATERIAL LOCATION: **Main Office, Assistant Principal's Office, Auditorium**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15D**
MATERIAL DESCRIPTION: **12x12 Tan Specked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Adjustment Office, 304**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **15D**
MATERIAL DESCRIPTION: **12x12 Tan Specked Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Adjustment Office, 304**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15E**
MATERIAL DESCRIPTION: **12x12 Beige Specked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Adjustment Office, 304**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **15E**
MATERIAL DESCRIPTION: **12x12 Beige Specked Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Adjustment Office, 304**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15F**
MATERIAL DESCRIPTION: **12x12 Gray Specked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor East Stair Landings, 3rd Floor Corridors**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **15F**
MATERIAL DESCRIPTION: **12x12 Gray Specked Floor Tile Mastic**
MATERIAL LOCATION: **1st & 2nd Floor East Stair Landings, 3rd Floor Corridors**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15G**
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor East Stair Landing, 3rd Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **15G**
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor East Stair Landing, 3rd Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12x12 Brown/Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12x12 Brown/Green Floor Tile**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **12x12 White Floor Tile (Building Demolished 2011)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building - Classrooms and Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Demolished 2011**

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **12x12 White Floor Tile (Building Demolished 2011)**
MATERIAL LOCATION: **Modular Building - Classrooms and Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19B**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic (Building Demolished 2011)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building - Classrooms and Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Demolished 2011**

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **19B**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic (Building Demolished 2011)**
MATERIAL LOCATION: **Modular Building - Classrooms and Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12x12 White w/Light Brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12x12 White w/Light Brown floor tile**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12x12 White w/Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12x12 White w/Light Brown Floor Tile**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **4" Tan Vinyl Basecover (Building Demolished 2011)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building Throughout (Building Demolished 2011)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Demolished 2011**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **4" Tan Vinyl Basecover (Building Demolished 2011)**

MATERIAL LOCATION: **Modular Building Throughout (Building Demolished 2011)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **4" Tan Vinyl Basecover Adhesive (Building Demolished 2011)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Modular Building- Throughout (Building Demolished 2011)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS: **Building Demolished 2011**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **4" Tan Vinyl Basecover Adhesive (Building Demolished 2011)**

MATERIAL LOCATION: **Modular Building- Throughout (Building Demolished 2011)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Brown Chalk Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Brown Chalk Board Adhesive**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **2x4 White Ceiling Tile w/ Pinhole & Worm**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallways**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **2x4 White Ceiling Tile w/ Pinhole & Worm**
MATERIAL LOCATION: **Hallways**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2x2 White Ceiling Tile (Building Demolished 2011)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Demolished 2011**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **2x2 White Ceiling Tile (Building Demolished 2011)**

MATERIAL LOCATION: **Modular Building Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office, Main Office, Room 106, 107, 201**
MATERIAL QUANTITY: **5208** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Vinyl Floor Tile**
MATERIAL LOCATION: **Engineer's Office, Main Office, Room 106, 107, 201**
MATERIAL QUANTITY: **5208** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office, Main Office, Room 106, 107, 201**
MATERIAL QUANTITY: **5208** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office, Main Office, Room 106, 107, 201**
MATERIAL QUANTITY: **5208** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Brown Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Brown Vinyl Floor Tile**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White & Brown Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White & Brown Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Library**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Fiberglass Pipe w/Hard Elbows**
HISTORICAL AHERA DAMAGE CATEGORY **5 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room, Fan and Pump Room, Basement, Lunch Break area, Custodian Closets Throughout**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**
COMMENTS: **15 LF of Damage in Pump Room and 2nd Floor Janitor's Closet (Photos Included)**

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Fiberglass Pipe w/Hard Elbows**
MATERIAL LOCATION: **Boiler Room, Fan and Pump Room, Basement, Lunch Break area, Custodian Closets Throughout**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Condensate Tank**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Pump Room**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**
COMMENTS: **30 Sq Ft Damaged (Photos included)**

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUIDLING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Condensate Tank**
MATERIAL LOCATION: **Pump Room**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **35A**
MATERIAL DESCRIPTION: **12x12 Tan w/White & Brown Floor Tile Mastic**
MATERIAL LOCATION: **3rd Floor Gymnasium**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Green Chalkboards**
MATERIAL LOCATION: **Throughout Classrooms**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/27/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Oglesby School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12x12 Tan w/White & Brown Floor Tile**
MATERIAL LOCATION: **3rd Floor Gymnasium**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24741** BUILDING ID: **5170**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Oglesby School** REVIEW DATE: **9/27/2019**
ADDRESS: **7646 S. Green** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12x12 Tan w/White & Brown Floor Tile**
MATERIAL LOCATION: **3rd Floor Gymnasium**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/27/2019**

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Lisa Laney


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/5/2019

Exam Date: 4/5/2019

Expiration Date: 4/5/2020

Certificate Number: BIR1904051198



Kathy DeSalvo, Director

Miss Nancy

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

John Fenn

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: BIR1903191011

A handwritten signature in black ink that reads 'Kathy DeSalvo'.

Kathy DeSalvo, Director

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

John Fenn


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: MPR1903191035



Kathy DeSalvo, Director

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/19/2020

ID NUMBER

ISSUED

EXPIRES

MANAGEMENT PLANNER

3/19/2020

100 - 09786

4/11/2019

05/15/2020

PROJECT MANAGER

3/18/2020

JOHN H FENN

2829 N TROY ST

CHICAGO, IL 60618

Environmental Health



AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed