

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2243  
SCHOOL NAME: Stevenson Middle  
ADDRESS OF SCHOOL: 4350 W. 79th St.  
CITY: Chicago, IL, 60652

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/15/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1220  
IDPH INSPECTOR LICENSE NUMBER: 100-09106  
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Hasier  
IDPH MP LICENSE NUMBER: 100-00440  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Shawn Brown

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Stevenson Middle**

4350 W. 79th St.  
Chicago, IL, 60652

Unit: 25471  
Building ID: 7370

IDPH ID Number: 14-016-2990-2243

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

August 26, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 55051                      Region: 05                      IDPH ID:14-016-2990-2243

School: Stevenson Middle                      Building ID: 7370

Address: 4350 W. 79th St.  
Chicago, IL, 60652

Building Contact:                      Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/24/2019

Inspector: Michael Hasier                      Inspector IDPH License: 100-09106  
Management Planner: Shawn Brown                      Management Planner IDPH License: 100-00440

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

Shawn Brown  
100-00440

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 26, 2019

RE: Stevenson Middle, Unit 25471  
4350 W. 79th St.  
Chicago, IL, 60652

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Stevenson Middle, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Stevenson Middle, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Stevenson Middle  
Address: 4350 W. 79th St.  
IDPH ID: 14-016-2990-2243  
Contact:

Unit: 55051  
Chicago, IL, 60652  
Building ID: 7370  
Phone:

Region: 05

### 2. Description of Facility

Original Construction: 1940  
Total Square Footage: 810  
Current Occupancy: 1220

Additional Construction: 1940  
No of Floors: 3

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Michael Hasier

Inspector IDPH license # 100-09106

Signature:  
Date: 8/26/2019

### 6. Management Planner

Management Planner Name: Shawn Brown

Management Planner IDPH license # 100-00440

Signature:  
Date: 09/24/2019

### 7. Review Date: 09/24/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Stevenson Middle. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7370:

25	1'x1' Ceiling Tile w/Holes
28	Ceramic Floor Tile Grout
29	Ceramic Wall Tile Grout
30	Ceramic Wall Tile Adhesive
H	Boiler Gasket

B. The following new homogenous areas have been identified for Building 7370:

28	Ceramic Floor Tile Grout
29	Ceramic Wall Tile Grout
30	Ceramic Wall Tile Adhesive



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	12x12 Brown Floor Tile
08	Fire Doors
13	3" Dark Brown Baseboard
14	3" Dark Brown Baseboard Mastic
15	3" Light Brown Baseboard
16	3' Light Brown Baseboard Mastic
17	12x12 White Floor Tile
18	12x12 White Floor Tile Mastic
23	Tectum Ceiling
24	2'x4' White Wormy Ceiling Tile
25	1'x1' Ceiling Tile w/Holes
26	1'x1' Ceiling Tile w/Holes Mastic
27	1'x1' Metal Ceiling Tile Backing
28	Ceramic Floor Tile Grout
29	Ceramic Wall Tile Grout
30	Ceramic Wall Tile Adhesive
H	Boiler Gasket

The following areas were deemed to be inaccessible:

09	9x9 Light Brown Floor Tile Mastic
10	12x12 Brown Floor Tile Mastic
12	9x9 Dark Brown Floor Tile Mastic
14	3" Dark Brown Baseboard Mastic
16	3' Light Brown Baseboard Mastic
18	12x12 White Floor Tile Mastic
20	9x9 Green Floor Tile Mastic
22	9x9 Tan Floor Tile Mastic
26	1'x1' Ceiling Tile w/Holes Mastic
27	1'x1' Metal Ceiling Tile Backing
30	Ceramic Wall Tile Adhesive
H	Boiler Gasket

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Hasier, IDPH License # 100-09106. The Management Plan was updated by Shawn Brown, IDPH License # 100-00440. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/19/2017  
7/19/2017

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Stevenson Middle Building 7370 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Stevenson Middle Unit 55051 Building ID 7370

Address 4350 W. 79th St. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	9x9 Light Brown Floor Tile	9,000	SF	Corridors and Rooms 111, 112, 113, 103, 104, 105	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	12x12 Brown Floor Tile	9,000	SF	Hallways, Classrooms & Gym	ASSUMED	MISC	N	LOC	5		No	ACBM with the potential for damage	5	LOW
08	Fire Doors	320	SF	Boiler Room and Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	9x9 Light Brown Floor Tile Mastic	9,000	SF	Corridors and Classrooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12x12 Brown Floor Tile Mastic	9,000	SF	Corridors, Classrooms & Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	9x9 Dark Brown Floor Tile	300	SF	Corridors and Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	9x9 Dark Brown Floor Tile Mastic	300	SF	Corridors and Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	3" Dark Brown Baseboard	1,000	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	3" Dark Brown Baseboard Mastic	1,000	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	3" Light Brown Baseboard	1,000	SF	Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	3" Light Brown Baseboard Mastic	1,000	SF	Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12x12 White Floor Tile	100	SF	Rooms 102, 109, 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12x12 White Floor Tile Mastic	100	SF	Rooms 102, 109 & 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	9x9 Green Floor Tile	2,800	SF	Gym (under 12x12 Brown Floor Tile) and Gym Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	9x9 Green Floor Tile Mastic	2,800	SF	Gym (under 12x12 Brown Floor Tile) and Gym Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	9x9 Tan Floor Tile	200	SF	Corridors and Main Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	9x9 Tan Floor Tile Mastic	200	SF	Corridors and Main Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Tectum Ceiling	3,440	SF	Gym and Boiler Room	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
24	2'x4' White Wormy Ceiling Tile	4,000	SF	Hallways	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Stevenson Middle Unit 55051 Building ID 7370

Address 4350 W. 79th St. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
25	1'x1' Ceiling Tile w/Holes	7,000	SF	401-406, 409-413	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
26	1'x1' Ceiling Tile w/Holes Mastic	7,000	SF	401-406 409-413	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	1'x1' Metal Ceiling Tile Backing	3,000	SF	Offices, 407, 408, 414	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Ceramic Floor Tile Grout	950	SF	Restrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
29	Ceramic Wall Tile Grout	1,440	SF	Restrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
30	Ceramic Wall Tile Adhesive	1,440	SF	Restrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
C	Cardboard Pipe Insulation	300	LF	Corridors, North End Boys' Restrooms and Boiler Room Restrooms	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
D	Cardboard Pipe Fittings	13	LF	Corridors, North End Boys' Restrooms & Boiler Room Restrooms	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
E	Mag Block Pipe Insulation	850	LF	Corridors and Gym	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Mag Block Pipe Fittings	75	LF	Corridors and Gym	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	Boiler Gasket	20	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

**School** Stevenson Middle **Unit** 55051 **Building ID** 7370  
**Address** 4350 W. 79th St. **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>8/26/2019</b>
Inspector Name <b>Michael Hasier</b>
<b>100-09106</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	Damage at Gym Entry, small cracks
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	All Room Numbers should be changed from 100s to 400s
18	All Room Numbers should be changed from 100s to 400s
19	
20	
21	Add Main Office
22	
23	
24	
25	
26	
27	
28	

# Chicago Public Schools

**School** Stevenson Middle **Unit** 55051 **Building ID** 7370  
**Address** 4350 W. 79th St. **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
29	
30	
C	
D	Previous Damage Not Oserved
E	Rooms 403 & 412 Abated; 405, 406, 411 & 413 Repaired in 2017
F	
H	

**Table II**

**Management Planner's Review**

---



# Chicago Public Schools

School Stevenson Middle

Unit 55051

Building ID 7370

Address 4350 W. 79th St.

Chicago, IL, 60652

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	9x9 Llight Brown Floor Tile	9,000	SF	Corridors and Rooms 111, 112, 113, 103, 104, 105	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12x12 Brown Floor Tile	9,000	SF	Hallways, Classrooms & Gym	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Fire Doors	320	SF	Boiler Room and Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	9x9 Light Brown Floor Tile Mastic	9,000	SF	Corridors and Classrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12x12 Brown Floor Tile Mastic	9,000	SF	Corridors, Classrooms & Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9x9 Dark Brown Floor Tile	300	SF	Corridors and Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9x9 Dark Brown Floor Tile Mastic	300	SF	Corridors and Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	3" Dark Brown Baseboard	1,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	3" Dark Brown Baseboard Mastic	1,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	3" Light Brown Baseboard	1,000	SF	Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	3' Light Brown Baseboard Mastic	1,000	SF	Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 White Floor Tile	100	SF	Rooms 102, 109, 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12x12 White Floor Tile Mastic	100	SF	Rooms 102, 109 & 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	9x9 Green Floor Tile	2,800	SF	Gym (under 12x12 Brown Floor Tile) and Gym Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9x9 Green Floor Tile Mastic	2,800	SF	Gym (under 12x12 Brown Floor Tile) and Gym Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	9x9 Tan Floor Tile	200	SF	Corridors and Main Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	9x9 Tan Floor Tile Mastic	200	SF	Corridors and Main Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Tectum Ceiling	3,440	SF	Gym and Boiler Room	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	2'x4' White Wormy Ceiling Tile	4,000	SF	Hallways	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
25	1'x1' Ceiling Tile w/Holes	7,000	SF	401-406, 409-413	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
26	1'x1' Ceiling Tile w/Holes Mastic	7,000	SF	401-406 409-413	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	1'x1' Metal Ceiling Tile Backing	3,000	SF	Offices, 407, 408, 414	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Ceramic Floor Tile Grout	950	SF	Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Ceramic Wall Tile Grout	1,440	SF	Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Ceramic Wall Tile Adhesive	1,440	SF	Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Cardboard Pipe Insulation	300	LF	Corridors, North End Boys' Restrooms and Boiler Room Restrooms	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Cardboard Pipe Fittings	13	LF	Corridors, North End Boys' Restrooms & Boiler Room Restrooms	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

School Stevenson Middle

Unit 55051

Building ID 7370

Address 4350 W. 79th St.

Chicago, IL, 60652

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
E	Mag Block Pipe Insulation	850	LF	Corridors and Gym	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Mag Block Pipe Fittings	75	LF	Corridors and Gym	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	Boiler Gasket	20	LF	Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

School Stevenson Middle

Unit 55051

Building ID 7370

Address 4350 W. 79th St.

Chicago, IL, 60652

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

Review Date	09/24/2019
Manager Planner Name	Shawn Brown
100-00440	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	

# Chicago Public Schools

School Stevenson Middle

Unit 55051

Building ID 7370

Address 4350 W. 79th St.

Chicago, IL, 60652

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.  
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
C	
D	
E	
F	
H	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	9x9 Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Rooms 111, 112, 113, 103, 104, 105		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	01				
MATERIAL DESCRIPTION:	9x9 Light Brown Floor Tile				
MATERIAL LOCATION:	Corridors and Rooms 111, 112, 113, 103, 104, 105				
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways, Classrooms & Gym		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	5	DAMAGE UNITS:	SF
COMMENTS:	Damage at Gym Entry, small cracks		

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	02				
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile				
MATERIAL LOCATION:	Hallways, Classrooms & Gym				
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	5	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019



# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room and Gym		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Fire Doors		
MATERIAL LOCATION:	Boiler Room and Gym		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	9x9 Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Classrooms		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>09</b>		
MATERIAL DESCRIPTION:	<b>9x9 Light Brown Floor Tile Mastic</b>		
MATERIAL LOCATION:	<b>Corridors and Classrooms</b>		
MATERIAL QUANTITY:	<b>9000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors, Classrooms & Gym		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>10</b>		
MATERIAL DESCRIPTION:	<b>12x12 Brown Floor Tile Mastic</b>		
MATERIAL LOCATION:	<b>Corridors, Classrooms &amp; Gym</b>		
MATERIAL QUANTITY:	<b>9000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	9x9 Dark Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	9x9 Dark Brown Floor Tile		
MATERIAL LOCATION:	Corridors and Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019



# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	9x9 Dark Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **Corridors and Office**

MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	3" Dark Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	3" Dark Brown Baseboard		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	3" Dark Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	3" Dark Brown Baseboard Mastic		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	3" Light Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **3" Light Brown Baseboard**

MATERIAL LOCATION: **Corridors**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	3' Light Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>16</b>		
MATERIAL DESCRIPTION:	<b>3' Light Brown Baseboard Mastic</b>		
MATERIAL LOCATION:	<b>Corridors</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12x12 White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 102, 109, 110		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	All Room Numbers should be changed from 100s to 400s		

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>17</b>		
MATERIAL DESCRIPTION:	<b>12x12 White Floor Tile</b>		
MATERIAL LOCATION:	<b>Rooms 102, 109, 110</b>		
MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12x12 White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 102, 109 & 110		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS: All Room Numbers should be changed from 100s to 400s

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12x12 White Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 102, 109 & 110		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	9x9 Green Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym (under 12x12 Brown Floor Tile) and Gym Storage Room		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>19</b>		
MATERIAL DESCRIPTION:	<b>9x9 Green Floor Tile</b>		
MATERIAL LOCATION:	<b>Gym (under 12x12 Brown Floor Tile) and Gym Storage Room</b>		
MATERIAL QUANTITY:	<b>2800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	9x9 Green Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym (under 12x12 Brown Floor Tile) and Gym Storage Room		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>20</b>		
MATERIAL DESCRIPTION:	<b>9x9 Green Floor Tile Mastic</b>		
MATERIAL LOCATION:	<b>Gym (under 12x12 Brown Floor Tile) and Gym Storage Room</b>		
MATERIAL QUANTITY:	<b>2800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	9x9 Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Main Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Add Main Office		

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	9x9 Tan Floor Tile		
MATERIAL LOCATION:	Corridors and Main Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	9x9 Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Main Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	9x9 Tan Floor Tile Mastic		
MATERIAL LOCATION:	Corridors and Main Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Tectum Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym and Boiler Room		
MATERIAL QUANTITY:	3440	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>23</b>		
MATERIAL DESCRIPTION:	<b>Tectum Ceiling</b>		
MATERIAL LOCATION:	<b>Gym and Boiler Room</b>		
MATERIAL QUANTITY:	<b>3440</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	2'x4' White Wormy Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>24</b>		
MATERIAL DESCRIPTION:	<b>2'x4' White Wormy Ceiling Tile</b>		
MATERIAL LOCATION:	<b>Hallways</b>		
MATERIAL QUANTITY:	<b>4000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Holes		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	401-406, 409-413		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>25</b>		
MATERIAL DESCRIPTION:	<b>1'x1' Ceiling Tile w/Holes</b>		
MATERIAL LOCATION:	<b>401-406, 409-413</b>		
MATERIAL QUANTITY:	<b>7000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Holes Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	401-406 409-413		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson Middle	REVIEW DATE:	9/24/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Holes Mastic		
MATERIAL LOCATION:	401-406 409-413		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	1'x1' Metal Ceiling Tile Backing		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Offices, 407, 408, 414		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>27</b>				
MATERIAL DESCRIPTION:	<b>1'x1' Metal Ceiling Tile Backing</b>				
MATERIAL LOCATION:	<b>Offices, 407, 408, 414</b>				
MATERIAL QUANTITY:	<b>3000</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACM or friable suspect ACM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Corridors, North End Boys' Restrooms and Boiler Room Restrooms		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>C</b>				
MATERIAL DESCRIPTION:	<b>Cardboard Pipe Insulation</b>				
MATERIAL LOCATION:	<b>Corridors, North End Boys' Restrooms and Boiler Room Restrooms</b>				
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>LF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Cardboard Pipe Fittings		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Corridors, North End Boys' Restrooms & Boiler Room Restrooms		
MATERIAL QUANTITY:	13	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:	Previous Damage Not Observed		

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>D</b>		
MATERIAL DESCRIPTION:	<b>Cardboard Pipe Fittings</b>		
MATERIAL LOCATION:	<b>Corridors, North End Boys' Restrooms &amp; Boiler Room Restrooms</b>		
MATERIAL QUANTITY:	<b>13</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Gym		
MATERIAL QUANTITY:	850	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

COMMENTS: Rooms 403 & 412 Abated; 405, 406, 411 & 413 Repaired in 2017

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>E</b>				
MATERIAL DESCRIPTION:	<b>Mag Block Pipe Insulation</b>				
MATERIAL LOCATION:	<b>Corridors and Gym</b>				
MATERIAL QUANTITY:	<b>850</b>	MATERIAL UNITS:	<b>LF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Mag Block Pipe Fittings		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Gym		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>F</b>		
MATERIAL DESCRIPTION:	<b>Mag Block Pipe Fittings</b>		
MATERIAL LOCATION:	<b>Corridors and Gym</b>		
MATERIAL QUANTITY:	<b>75</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Boiler Gasket		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

---

HOMOGENEOUS AREA:	<b>H</b>		
MATERIAL DESCRIPTION:	<b>Boiler Gasket</b>		
MATERIAL LOCATION:	<b>Boiler Room</b>		
MATERIAL QUANTITY:	<b>20</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.

***2019 AHERA REINSPECTION***

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	28				
MATERIAL DESCRIPTION:	Ceramic Floor Tile Grout				
MATERIAL LOCATION:	Restrooms				
MATERIAL QUANTITY:	950	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Restrooms**

MATERIAL QUANTITY: **950**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	Ceramic Wall Tile Adhesive		
MATERIAL LOCATION:	Restrooms		
MATERIAL QUANTITY:	1440	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Ceramic Wall Tile Adhesive**

MATERIAL LOCATION: **Restrooms**

MATERIAL QUANTITY: **1440**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
**2019 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	55051	BUILDING ID:	7370
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson Middle	INSPECTION DATE:	8/26/2019		
ADDRESS:	4350 W. 79th St.	IDPH LICENSE NO:	100-09106		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	29				
MATERIAL DESCRIPTION:	Ceramic Wall Tile Grout				
MATERIAL LOCATION:	Restrooms				
MATERIAL QUANTITY:	1440	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: \_\_\_\_\_ Date: 08/26/2019



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>55051</b>	BUILDING ID:	<b>7370</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Shawn Brown</b>		
SCHOOL NAME:	<b>Stevenson Middle</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>4350 W. 79th St.</b>	IDPH LICENSE NO:	<b>100-09106</b>		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Ceramic Wall Tile Grout**

MATERIAL LOCATION: **Restrooms**

MATERIAL QUANTITY: **1440**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MICHAEL HASIER  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 05/01/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

05/01/2019

Course Dates:

05/01/2020

Expires:

1905BIR02

Certificate Number:



**PUBLIC HEALTH & SAFETY inc.**

Environmental and Occupational Services  
375 S. Arland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

### ENDORSEMENTS

### TC EXPIRES

SUPERVISOR/WORKER

3/1/2020

INSPECTOR

5/1/2020

ID NUMBER

ISSUED

EXPIRES

100 - 09106

5/8/2019

05/15/2020

PROJECT MANAGER

3/1/2020

AIR SAMPLING PROFESSIONAL

**MICHAEL S HASIER**

444 OLD BARN RD., APT. B  
BARRINGTON, IL 60010

Environmental Health



Alteration of this license shall result in legal action  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



**PUBLIC HEALTH & SAFETY, INC.**

Environmental and Occupational Services  
975 Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Penelf

Director of Public Health

Phone: 312-491-0081

FORM # A-010B



# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



**PUBLIC HEALTH & SAFETY inc.**  
Environmental and Occupational Services  
3711 Ashland Ave., Chicago, IL 60607  
[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-3501

*N. Penoff*

Director of Training

Nicholas J. Penoff

Doctor of Public Health


Phone: 312-491-0081

FORM # A-011

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/19/2019

ID NUMBER

ISSUED

EXPIRES

100 - 02950

3/6/2019

05/15/2020

PROJECT MANAGER

4/9/2019

AIR SAMPLING PROFESSIONAL

**KEITH CLOUGH**

524 HOMELAND RD

MATTESON, IL 60443

Environmental Health



Alteration of this license shall result in legal action  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---



# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed