

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2465
SCHOOL NAME: Stevenson School
ADDRESS OF SCHOOL: 8010 S. Kostner
CITY: Chicago, IL, 60652

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/4/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1220
IDPH INSPECTOR LICENSE NUMBER: 100-09106
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Hasier
IDPH MP LICENSE NUMBER: 100-00440
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Shawn Brown

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Stevenson School

8010 S. Kostner
Chicago, IL, 60652

Unit: 25471
Building ID: 6030

IDPH ID Number: 14-016-2990-2465

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Shawn Brown
100-00440

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 27, 2019

RE: Stevenson School, Unit 25471
8010 S. Kostner
Chicago, IL, 60652

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Stevenson School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Stevenson School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Stevenson School
Address: 8010 S. Kostner
IDPH ID: 14-016-2990-2465
Contact:

Unit: 25471
Chicago, IL, 60652
Building ID: 6030
Phone:

Region: 05

2. Description of Facility

Original Construction: 1980
Total Square Footage: 3380
Current Occupancy: 1220

Additional Construction:
No of Floors: 1

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Michael Hasier

Inspector IDPH license # 100-09106

Signature:
Date: 8/27/2019

6. Management Planner

Management Planner Name: Shawn Brown

Management Planner IDPH license # 100-00440

Signature:
Date: 09/26/2019

7. Review Date: 09/26/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Stevenson School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6030:

17	Green Terrazzo Flooring
FT-11	1'x1' Ceiling Tile w/Holes

B. The following new homogenous areas have been identified for Building 6030:

17

Green Terrazzo Flooring

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

07	Linoleum
08	Baseboard
09	Baseboard Mastic
14	Linoleum Mastic
15	12x12 White w/Beige Specks Floor Tile
16	12x12 White w/Beige Specks Floor Tile Mastic
17	Green Terrazzo Flooring
BB-1	Baseboard
BBM-1	Baseboard Mastic
FT-10	1'x1' Ceiling Tile w/Fissures
FT-11	1'x1' Ceiling Tile w/Holes
FT-12	12x12 Cream Vinyl Floor Tile
FT-2	12x12 Blue w/Cream Streaks Floor Tile - Not Observed
FT-7	12x12 White w/Brown Specks
FT-8	12x12 Tan w/Black & White Streaks Floor Tile - Not Observed
FTM - 10	1'x1' Ceiling Tile w/Fissures Mastic
FTM - 11	1'x1' Ceiling Tile w/Holes Mastic
FTM - 12	12x12 Cream Vinyl Floor Tile Mastic
FTM-2	12x12 Blue w/Cream Streaks Floor Tile Mastic - Not Observed
FTM-7	12x12 White w/Brown Specks Floor Tile Mastic
WC-2	Window Caulk - Not Observed
WG-1	Window Glaze - Not Observed
WG-2	Window Glaze - Not Observed

The following areas were deemed to be inaccessible:

09	Baseboard Mastic
13	12x12 Tan w/Cream & Brown Floor Tile Mastic
14	Linoleum Mastic
16	12x12 White w/Beige Specks Floor Tile Mastic
FT-10	1'x1' Ceiling Tile w/Fissures
FTM - 10	1'x1' Ceiling Tile w/Fissures Mastic
FTM - 11	1'x1' Ceiling Tile w/Holes Mastic
FTM - 12	12x12 Cream Vinyl Floor Tile Mastic
FTM-1	12x12 Gray w/Black Cream & Red Streaks Floor Tile Mastic
FTM-3	12x12 Light Tan w/Cream & Red Streaks Floor Tile

FTM-7	mastic
J	12x12 White w/Brown Specks Floor Tile Mastic
M	Cementitious Pipe Fittings Fiberglass Runs
	Cementitious Pipe Fittings

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Hasier, IDPH License # 100-09106. The Management Plan was updated by Shawn Brown, IDPH License # 100-00440. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Stevenson School Building 6030 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Stevenson School Unit 25471 Building ID 6030

Address 8010 S. Kostner Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
05	9x9 Floor Tile ABATED			1957- 1st & 2nd Floor Hall	ABATED	MISC								
06	12x12 Tan w/Brown & Green Floor Tile ABATED			1954 Building	ABATED	MISC								
07	Linoleum	4,000	SF	1957 Building- Rooms 105, 107, 108, 110 (Nurse's Office) and 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Baseboard	2,500	LF	1957 Building- 1st & 2nd Floor Halls, Rooms 209 and 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Baseboard Mastic	2,500	LF	1957 Building- 1st and 2nd Floor Halls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12x12 Tan w/Cream & Brown Floor Tile	18,000	SF	1957 Building- 1st & 2nd Floor Classrooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	9x9 Floor Tile Mastic ABATED			1957 Building- 1st & 2nd Floor Halls	ABATED	MISC								
12	12x12 Mastic ABATED			Throughout 1957 Building	ABATED	MISC								
13	12x12 Tan w/Cream & Brown Floor Tile Mastic	18,000	SF	1957 Building- 1st & 2nd Floor Classrooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Linoleum Mastic	4,000	SF	1957 Building- 1st Floor- Rooms 105, 107, 108, 110 (Nurse's Office) and 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12x12 White w/Beige Specks Floor Tile	20,000	SF	1954 & 1957 Buildings- 1st & 2nd Floor Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12x12 White w/Beige Specks Floor Tile Mastic	20,000	SF	1954 & 1957 Buildings- 1st & 2nd Floor Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Green Terrazzo Flooring	2,500	SF	Entries and Stairwells	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation ABATED			1954 Building- Basement Boiler Room	ABATED	TSI								
B	Boiler Insulation ABATED			Boiler Room	ABATED	TSI								
BB-1	Baseboard	550	SF	Modular Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BBM-1	Baseboard Mastic	550	SF	Modular Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Stevenson School Unit 25471 Building ID 6030

Address 8010 S. Kostner Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
C	Preform Pipe Insulation	3,000	LF	1954 Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Water Tank Insulation ABATED			Boiler Room	ABATED	TSI								
E	Cardboard Pipe Insulation	200	LF	Bathrooms and Chases	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
FT-1	12x12 Gray w/Black Cream & Red Streaks Floor Tile	2,500	SF	Rooms 121, 123, 125, 129, 221, 223, and 225.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-10	1'x1' Ceiling Tile w/Fissures	425	SF	Basement Teachers' Lounge	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
FT-11	1'x1' Ceiling Tile w/Holes	425	SF	Basement Teacher's Lounge	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
FT-12	12x12 Cream Vinyl Floor Tile	800	SF	1st Floor Annex Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-2	12x12 Blue w/Cream Streaks Floor Tile - Not Observed			Room 201	ASSUMED	MISC		None						Low
FT-3	12x12 Light Tan w/Cream & Red Streaks Floor Tile	200	SF	Room 101	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-4	9x9 Tan w/w/Brown & Cream Streaks Floor Tile - Not Observed			Room 202	CHR	MISC		None						Low
FT-5	9x9 Tan w/Cream & Brown Streaks Floor Tile - Not Observed			1957 Building- 1st Floor Corridor	CHR	MISC								
FT-6	12x12 Peach & Tan Checker Floor Tile ABATED			Basement Lunchroom, Kitchen, Teachers' Lunchroom	ABATED	MISC		None						Low
FT-7	12x12 White w/Brown Specks	3,080	SF	Modular Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-8	12x12 Tan w/Black & White Streaks Floor Tile - Not Observed			Room 202	ASSUMED	MISC								
FT-9	12x12 Blue Floor Tile ABATED			Basement, Lunchroom, Kitchen, Teachers' Lunchroom	ABATED	MISC								Low
FTM - 10	1'x1' Ceiling Tile w/Fissures Mastic	425	SF	Basement Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM - 11	1'x1' Ceiling Tile w/Holes Mastic	425	SF	Basement Teacher's Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM - 12	12x12 Cream Vinyl Floor Tile Mastic	808	SF	1st Floor Annex Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	12x12 Gray w/Black Cream & Red Streaks	800	SF	Room 129	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Stevenson School Unit 25471 Building ID 6030

Address 8010 S. Kostner Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Floor Tile Mastic											potential for damage		
FTM-2	12x12 Blue w/Cream Streaks Floor Tile Mastic - Not Observed			Room 201	ASSUMED	MISC		None						Low
FTM-3	12x12 Light Tan w/Cream & Red Streaks Floor Tile mastic	200	SF	Room 101	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-4	9x9 Tan w/Brown & Cream Streaks Floor Tile Mastic - Not Observed			Room 202	CHR	MISC		None						Low
FTM-5	9x9 Tan w/Cream & Brown Streaks Floor Tile Mastic - Not Observed			1957 Building- 1st Floor Corridor	CHR	MISC								
FTM-6	12x12 Peach & Tan Checker Floor Tile Mastic ABATED			basement	ABATED	MISC		None						Low
FTM-7	12x12 White w/Brown Specks Floor Tile Mastic	3,080	SF	Modular Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G	Cementitious Pipe Fitting	480	LF	1954 Building Basement	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Breeching Cement ABATED			Boiler Room	ABATED	MISC								
J	Cementitious Pipe Fittings Fiberglass Runs	30	LF	1957 Building- Unexcavated Areas	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
K	Aircell Pipe Insulation - Not Observed			1957 Building- Bathrooms and Air Plenums	CHR	TSI								Low
L	Cardboard Pipe Insulation	1,000	LF	1957 Building- Air Plenum	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
M	Cementitious Pipe Fittings	300	LF	1957 Building- Air Plenum	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
N	Boiler Gasket ABATED			Boiler Room	ABATED	TSI								
WC-1	Window Caulk ABATED			1954 Building	ABATED	MISC								
WC-2	Window Caulk - Not Observed			1957 Building	ASSUMED	MISC								
WG-1	Window Glaze - Not Observed			1954 Building	ASSUMED	MISC								
WG-2	Window Glaze - Not Observed			1957 Addition	ASSUMED	MISC								

Chicago Public Schools

School Stevenson School Unit 25471 Building ID 6030

Address 8010 S. Kostner Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/27/2019
Inspector Name Michael Hasier
100-09106 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
A	
B	
BB-1	
BBM-1	
C	
D	
E	
FT-1	
FT-10	
FT-11	

Chicago Public Schools

School Stevenson School **Unit** 25471 **Building ID** 6030
Address 8010 S. Kostner **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
FT-12	
FT-2	Room 201 is HA-10
FT-3	
FT-4	Location is HA-10
FT-5	Location is HA-10
FT-6	
FT-7	
FT-8	Location is HA-10
FT-9	
FTM - 10	
FTM - 11	
FTM - 12	
FTM-1	
FTM-2	Room 201 is HA-10
FTM-3	
FTM-4	Location is HA-10
FTM-5	Location is HA-10
FTM-6	
FTM-7	
G	
H	
J	
K	Not Observed
L	
M	
N	
WC-1	
WC-2	
WG-1	Material Not Observed 2019

Chicago Public Schools

School Stevenson School **Unit** 25471 **Building ID** 6030
Address 8010 S. Kostner **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
WG-2	Material Not Observed 2019

Table II

Management Planner's Review

Chicago Public Schools

School Stevenson School

Unit 25471

Building ID 6030

Address 8010 S. Kostner

Chicago, IL, 60652

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
05	9x9 Floor Tile ABATED			1957- 1st & 2nd Floor Hall	Abated	MISC					
06	12x12 Tan w/Brown & Green Floor Tile ABATED			1954 Building	Abated	MISC					
07	Linoleum	4,000	SF	1957 Building- Rooms 105, 107, 108, 110 (Nurse's Office) and 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Baseboard	2,500	LF	1957 Building- 1st & 2nd Floor Halls, Rooms 209 and 211	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
09	Baseboard Mastic	2,500	LF	1957 Building- 1st and 2nd Floor Halls	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
10	12x12 Tan w/Cream & Brown Floor Tile	18,000	SF	1957 Building- 1st & 2nd Floor Classrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9x9 Floor Tile Mastic ABATED			1957 Building- 1st & 2nd Floor Halls	Abated	MISC					
12	12x12 Mastic ABATED			Throughout 1957 Building	Abated	MISC					
13	12x12 Tan w/Cream & Brown Floor Tile Mastic	18,000	SF	1957 Building- 1st & 2nd Floor Classrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Linoleum Mastic	4,000	SF	1957 Building- 1st Floor- Rooms 105, 107, 108, 110 (Nurse's Office) and 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12x12 White w/Beige Specks Floor Tile	20,000	SF	1954 & 1957 Buildings- 1st & 2nd Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12x12 White w/Beige Specks Floor Tile Mastic	20,000	SF	1954 & 1957 Buildings- 1st & 2nd Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Green Terrazzo Flooring	2,500	SF	Entries and Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation ABATED			1954 Building- Basement Boiler Room	Abated	TSI					
B	Boiler Insulation ABATED			Boiler Room	Abated	TSI					
BB-1	Baseboard	550	SF	Modular Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BBM-1	Baseboard Mastic	550	SF	Modular Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Preform Pipe Insulation	3,000	LF	1954 Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Water Tank Insulation ABATED			Boiler Room	Abated	TSI					
E	Cardboard Pipe Insulation	200	LF	Bathrooms and Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
FT-1	12x12 Gray w/Black Cream & Red Streaks Floor Tile	2,500	SF	Rooms 121, 123, 125, 129, 221, 223, and 225.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-10	1'x1' Ceiling Tile w/Fissures	425	SF	Basement Teachers' Lounge	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-11	1'x1' Ceiling Tile w/Holes	425	SF	Basement Teacher's Lounge	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Stevenson School

Unit 25471

Building ID 6030

Address 8010 S. Kostner

Chicago, IL, 60652

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
FT-12	12x12 Cream Vinyl Floor Tile	800	SF	1st Floor Annex Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-2	12x12 Blue w/Cream Streaks Floor Tile - Not Observed			Room 201	Assumed	MISC					
FT-3	12x12 Light Tan w/Cream & Red Streaks Floor Tile	200	SF	Room 101	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-4	9x9 Tan w/w/Brown & Cream Streaks Floor Tile - Not Observed			Room 202	Chrysotile	MISC					
FT-5	9x9 Tan w/Cream & Brown Streaks Floor Tile - Not Observed			1957 Building- 1st Floor Corridor	Chrysotile	MISC					
FT-6	12x12 Peach & Tan Checker Floor Tile ABATED			Basement Lunchroom, Kitchen, Teachers' Lunchroom	Abated	MISC					
FT-7	12x12 White w/Brown Specks	3,080	SF	Modular Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-8	12x12 Tan w/Black & White Streaks Floor Tile - Not Observed			Room 202	Assumed	MISC					
FT-9	12x12 Blue Floor Tile ABATED			Basement, Lunchroom, Kitchen, Teachers' Lunchroom	Abated	MISC					
FTM - 10	1'x1' Ceiling Tile w/Fissures Mastic	425	SF	Basement Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM - 11	1'x1' Ceiling Tile w/Holes Mastic	425	SF	Basement Teacher's Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM - 12	12x12 Cream Vinyl Floor Tile Mastic	808	SF	1st Floor Annex Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 Gray w/Black Cream & Red Streaks Floor Tile Mastic	800	SF	Room 129	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	12x12 Blue w/Cream Streaks Floor Tile Mastic - Not Observed			Room 201	Assumed	MISC					
FTM-3	12x12 Light Tan w/Cream & Red Streaks Floor Tile mastic	200	SF	Room 101	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-4	9x9 Tan w/Brown & Cream Streaks Floor Tile Mastic - Not Observed			Room 202	Chrysotile	MISC					
FTM-5	9x9 Tan w/Cream & Brown Streaks Floor Tile Mastic - Not Observed			1957 Building- 1st Floor Corridor	Chrysotile	MISC					
FTM-6	12x12 Peach & Tan Checker Floor Tile Mastic ABATED			basement	Abated	MISC					
FTM-7	12x12 White w/Brown Specks Floor Tile Mastic	3,080	SF	Modular Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Cementitious Pipe Fitting	480	LF	1954 Building Basement	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Breeching Cement ABATED			Boiler Room	Abated	MISC					

Chicago Public Schools

School Stevenson School

Unit 25471

Building ID 6030

Address 8010 S. Kostner

Chicago, IL, 60652

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
J	Cementitious Pipe Fittings Fiberglass Runs	30	LF	1957 Building- Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Aircell Pipe Insulation - Not Observed			1957 Building- Bathrooms and Air Plenums	Chrysotile	TSI					
L	Cardboard Pipe Insulation	1,000	LF	1957 Building- Air Plenum	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Cementitious Pipe Fittings	300	LF	1957 Building- Air Plenum	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
N	Boiler Gasket ABATED			Boiler Room	Abated	TSI					
WC-1	Window Caulk ABATED			1954 Building	Abated	MISC					
WC-2	Window Caulk - Not Observed			1957 Building	Assumed	MISC					
WG-1	Window Glaze - Not Observed			1954 Building	Assumed	MISC					
WG-2	Window Glaze - Not Observed			1957 Addition	Assumed	MISC					

Chicago Public Schools

School Stevenson School

Unit 25471

Building ID 6030

Address 8010 S. Kostner

Chicago, IL, 60652

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	09/26/2019
Manager Planner Name	Shawn Brown
100-00440	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
A	
B	
BB-1	
BBM-1	
C	
D	
E	
FT-1	
FT-10	
FT-11	

Chicago Public Schools

School Stevenson School

Unit 25471

Building ID 6030

Address 8010 S. Kostner

Chicago, IL, 60652

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
FT-12	
FT-2	
FT-3	
FT-4	
FT-5	
FT-6	
FT-7	
FT-8	
FT-9	
FTM - 10	
FTM - 11	
FTM - 12	
FTM-1	
FTM-2	
FTM-3	
FTM-4	
FTM-5	
FTM-6	
FTM-7	
G	
H	
J	
K	
L	
M	
N	

Chicago Public Schools

School Stevenson School

Unit 25471

Building ID 6030

Address 8010 S. Kostner

Chicago, IL, 60652

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
WC-1	
WC-2	
WG-1	
WG-2	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05	
MATERIAL DESCRIPTION:	9x9 Floor Tile ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1957- 1st & 2nd Floor Hall

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **9x9 Floor Tile ABATED**

MATERIAL LOCATION: **1957- 1st & 2nd Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06	
MATERIAL DESCRIPTION:	12x12 Tan w/Brown & Green Floor Tile ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1954 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **12x12 Tan w/Brown & Green Floor Tile ABATED**

MATERIAL LOCATION: **1954 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1957 Building- Rooms 105, 107, 108, 110 (Nurse's Office) and 111		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: 07

MATERIAL DESCRIPTION: Linoleum

MATERIAL LOCATION: 1957 Building- Rooms 105, 107, 108, 110 (Nurse's Office) and 111

MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
--------------------	------	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1957 Building- 1st & 2nd Floor Halls, Rooms 209 and 211		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	08				
MATERIAL DESCRIPTION:	Baseboard				
MATERIAL LOCATION:	1957 Building- 1st & 2nd Floor Halls, Rooms 209 and 211				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1957 Building- 1st and 2nd Floor Halls		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	09				
MATERIAL DESCRIPTION:	Baseboard Mastic				
MATERIAL LOCATION:	1957 Building- 1st and 2nd Floor Halls				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12x12 Tan w/Cream & Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1957 Building- 1st & 2nd Floor Classrooms		
MATERIAL QUANTITY:	18000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12x12 Tan w/Cream & Brown Floor Tile		
MATERIAL LOCATION:	1957 Building- 1st & 2nd Floor Classrooms		
MATERIAL QUANTITY:	18000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25471** BUILDING ID: **6030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **Stevenson School** INSPECTION DATE: **8/27/2019**
ADDRESS: **8010 S. Kostner** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9x9 Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1957 Building- 1st & 2nd Floor Halls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9x9 Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1957 Building- 1st & 2nd Floor Halls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25471** BUILDING ID: **6030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **Stevenson School** INSPECTION DATE: **8/27/2019**
ADDRESS: **8010 S. Kostner** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12x12 Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1957 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/27/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12x12 Mastic ABATED**

MATERIAL LOCATION: **Throughout 1957 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12x12 Tan w/Cream & Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1957 Building- 1st & 2nd Floor Classrooms		
MATERIAL QUANTITY:	18000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12x12 Tan w/Cream & Brown Floor Tile Mastic		
MATERIAL LOCATION:	1957 Building- 1st & 2nd Floor Classrooms		
MATERIAL QUANTITY:	18000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1957 Building- 1st Floor- Rooms 105, 107, 108, 110 (Nurse's Office) and 111		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Linoleum Mastic		
MATERIAL LOCATION:	1957 Building- 1st Floor- Rooms 105, 107, 108, 110 (Nurse's Office) and 111		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12x12 White w/Beige Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1954 & 1957 Buildings- 1st & 2nd Floor Hallways		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12x12 White w/Beige Specks Floor Tile		
MATERIAL LOCATION:	1954 & 1957 Buildings- 1st & 2nd Floor Hallways		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12x12 White w/Beige Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1954 & 1957 Buildings- 1st & 2nd Floor Hallways		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12x12 White w/Beige Specks Floor Tile Mastic		
MATERIAL LOCATION:	1954 & 1957 Buildings- 1st & 2nd Floor Hallways		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A	
MATERIAL DESCRIPTION:	Aircell Pipe Insulation ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1954 Building- Basement Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**

MATERIAL LOCATION: **1954 Building- Basement Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B	
MATERIAL DESCRIPTION:	Boiler Insulation ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Boiler Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	BB-1		
MATERIAL DESCRIPTION:	Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Modular Unit		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **BB-1**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **Modular Unit**

MATERIAL QUANTITY: **550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	BBM-1		
MATERIAL DESCRIPTION:	Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Modular Unit		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **BBM-1**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Modular Unit**

MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Preform Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1954 Building		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	C				
MATERIAL DESCRIPTION:	Preform Pipe Insulation				
MATERIAL LOCATION:	1954 Building				
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D	
MATERIAL DESCRIPTION:	Water Tank Insulation ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Water Tank Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bathrooms and Chases		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	E				
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation				
MATERIAL LOCATION:	Bathrooms and Chases				
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-1		
MATERIAL DESCRIPTION:	12x12 Gray w/Black Cream & Red Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 121, 123, 125, 129, 221, 223, and 225.		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FT-1				
MATERIAL DESCRIPTION:	12x12 Gray w/Black Cream & Red Streaks Floor Tile				
MATERIAL LOCATION:	Rooms 121, 123, 125, 129, 221, 223, and 225.				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-10		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Fissures		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Teachers' Lounge		
MATERIAL QUANTITY:	425	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FT-10				
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Fissures				
MATERIAL LOCATION:	Basement Teachers' Lounge				
MATERIAL QUANTITY:	425	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-11		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Holes		
HISTORICAL AHERA DAMAGE CATEGORY	7		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Teacher's Lounge		
MATERIAL QUANTITY:	425	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FT-11		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Holes		
MATERIAL LOCATION:	Basement Teacher's Lounge		
MATERIAL QUANTITY:	425	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-12		
MATERIAL DESCRIPTION:	12x12 Cream Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Annex Corridor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FT-12**

MATERIAL DESCRIPTION: **12x12 Cream Vinyl Floor Tile**

MATERIAL LOCATION: **1st Floor Annex Corridor**

MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25471** BUILDING ID: **6030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **Stevenson School** INSPECTION DATE: **8/27/2019**
ADDRESS: **8010 S. Kostner** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**
MATERIAL DESCRIPTION: **12x12 Blue w/Cream Streaks Floor Tile - Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Room 201 is HA-10**

Inspector's Signature: _____ Date: **08/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FT-2**

MATERIAL DESCRIPTION: **12x12 Blue w/Cream Streaks Floor Tile - Not Observed**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-3		
MATERIAL DESCRIPTION:	12x12 Light Tan w/Cream & Red Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FT-3**

MATERIAL DESCRIPTION: **12x12 Light Tan w/Cream & Red Streaks Floor Tile**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-4		
MATERIAL DESCRIPTION:	9x9 Tan w/w/Brown & Cream Streaks Floor Tile - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 202

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Location is HA-10

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FT-4**

MATERIAL DESCRIPTION: **9x9 Tan w/w/Brown & Cream Streaks Floor Tile - Not Observed**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-5		
MATERIAL DESCRIPTION:	9x9 Tan w/Cream & Brown Streaks Floor Tile - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1957 Building- 1st Floor Corridor

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Location is HA-10

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FT-5**

MATERIAL DESCRIPTION: **9x9 Tan w/Cream & Brown Streaks Floor Tile - Not Observed**

MATERIAL LOCATION: **1957 Building- 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-6	
MATERIAL DESCRIPTION:	12x12 Peach & Tan Checker Floor Tile ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Basement Lunchroom, Kitchen, Teachers' Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FT-6**

MATERIAL DESCRIPTION: **12x12 Peach & Tan Checker Floor Tile ABATED**

MATERIAL LOCATION: **Basement Lunchroom, Kitchen, Teachers' Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-7		
MATERIAL DESCRIPTION:	12x12 White w/Brown Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Modular Unit		
MATERIAL QUANTITY:	3080	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FT-7**

MATERIAL DESCRIPTION: **12x12 White w/Brown Specks**

MATERIAL LOCATION: **Modular Unit**

MATERIAL QUANTITY: **3080**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-8	
MATERIAL DESCRIPTION:	12x12 Tan w/Black & White Streaks Floor Tile - Not Observed	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 202

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Location is HA-10

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FT-8**

MATERIAL DESCRIPTION: **12x12 Tan w/Black & White Streaks Floor Tile - Not Observed**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-9	
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Basement, Lunchroom, Kitchen, Teachers' Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FT-9				
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile ABATED				
MATERIAL LOCATION:	Basement, Lunchroom, Kitchen, Teachers' Lunchroom				
MATERIAL QUANTITY:				MATERIAL UNITS:	
DAMAGE QUANTITY:				DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM - 10		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Fissures Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Teachers' Lounge		
MATERIAL QUANTITY:	425	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FTM - 10**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile w/Fissures Mastic**

MATERIAL LOCATION: **Basement Teachers' Lounge**

MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM - 11		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Holes Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Teacher's Lounge		
MATERIAL QUANTITY:	425	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FTM - 11				
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile w/Holes Mastic				
MATERIAL LOCATION:	Basement Teacher's Lounge				
MATERIAL QUANTITY:	425	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM - 12		
MATERIAL DESCRIPTION:	12x12 Cream Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Annex Corridor		
MATERIAL QUANTITY:	808	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FTM - 12				
MATERIAL DESCRIPTION:	12x12 Cream Vinyl Floor Tile Mastic				
MATERIAL LOCATION:	1st Floor Annex Corridor				
MATERIAL QUANTITY:	808		MATERIAL UNITS:	SF	
DAMAGE QUANTITY:	0		DAMAGE UNITS:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-1		
MATERIAL DESCRIPTION:	12x12 Gray w/Black Cream & Red Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 129		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FTM-1**

MATERIAL DESCRIPTION: **12x12 Gray w/Black Cream & Red Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 129**

MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-2	
MATERIAL DESCRIPTION:	12x12 Blue w/Cream Streaks Floor Tile Mastic - Not Observed	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 201

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Room 201 is HA-10

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FTM-2**

MATERIAL DESCRIPTION: **12x12 Blue w/Cream Streaks Floor Tile Mastic - Not Observed**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-3		
MATERIAL DESCRIPTION:	12x12 Light Tan w/Cream & Red Streaks Floor Tile mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FTM-3**

MATERIAL DESCRIPTION: **12x12 Light Tan w/Cream & Red Streaks Floor Tile mastic**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-4		
MATERIAL DESCRIPTION:	9x9 Tan w/Brown & Cream Streaks Floor Tile Mastic - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 202

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Location is HA-10

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FTM-4				
MATERIAL DESCRIPTION:	9x9 Tan w/Brown & Cream Streaks Floor Tile Mastic - Not Observed				
MATERIAL LOCATION:	Room 202				
MATERIAL QUANTITY:			MATERIAL UNITS:		
DAMAGE QUANTITY:			DAMAGE UNITS:		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-5		
MATERIAL DESCRIPTION:	9x9 Tan w/Cream & Brown Streaks Floor Tile Mastic - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1957 Building- 1st Floor Corridor

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Location is HA-10

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FTM-5				
MATERIAL DESCRIPTION:	9x9 Tan w/Cream & Brown Streaks Floor Tile Mastic - Not Observed				
MATERIAL LOCATION:	1957 Building- 1st Floor Corridor				
MATERIAL QUANTITY:				MATERIAL UNITS:	
DAMAGE QUANTITY:				DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-6	
MATERIAL DESCRIPTION:	12x12 Peach & Tan Checker Floor Tile Mastic ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/27/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FTM-6**

MATERIAL DESCRIPTION: **12x12 Peach & Tan Checker Floor Tile Mastic ABATED**

MATERIAL LOCATION: **basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-7		
MATERIAL DESCRIPTION:	12x12 White w/Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Modular Unit		
MATERIAL QUANTITY:	3080	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FTM-7**

MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **Modular Unit**

MATERIAL QUANTITY: **3080**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Cementitious Pipe Fitting		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1954 Building Basement		
MATERIAL QUANTITY:	480	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	G				
MATERIAL DESCRIPTION:	Cementitious Pipe Fitting				
MATERIAL LOCATION:	1954 Building Basement				
MATERIAL QUANTITY:	480	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H	
MATERIAL DESCRIPTION:	Breeching Cement ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Breeching Cement ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Cementitious Pipe Fittings Fiberglass Runs		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1957 Building- Unexcavated Areas		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Cementitious Pipe Fittings Fiberglass Runs**

MATERIAL LOCATION: **1957 Building- Unexcavated Areas**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: 1957 Building- Bathrooms and Air Plenums

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation - Not Observed**

MATERIAL LOCATION: **1957 Building- Bathrooms and Air Plenums**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1957 Building- Air Plenum		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	L				
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation				
MATERIAL LOCATION:	1957 Building- Air Plenum				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Cementitious Pipe Fittings		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1957 Building- Air Plenum		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	M				
MATERIAL DESCRIPTION:	Cementitious Pipe Fittings				
MATERIAL LOCATION:	1957 Building- Air Plenum				
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/26/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N	
MATERIAL DESCRIPTION:	Boiler Gasket ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Boiler Gasket ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	WC-1	
MATERIAL DESCRIPTION:	Window Caulk ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1954 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **WC-1**

MATERIAL DESCRIPTION: **Window Caulk ABATED**

MATERIAL LOCATION: **1954 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	WC-2	
MATERIAL DESCRIPTION:	Window Caulk - Not Observed	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1957 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **WC-2**

MATERIAL DESCRIPTION: **Window Caulk - Not Observed**

MATERIAL LOCATION: **1957 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	WG-1	
MATERIAL DESCRIPTION:	Window Glaze - Not Observed	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1954 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material Not Observed 2019

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **WG-1**

MATERIAL DESCRIPTION: **Window Glaze - Not Observed**

MATERIAL LOCATION: **1954 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	WG-2	
MATERIAL DESCRIPTION:	Window Glaze - Not Observed	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1957 Addition

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Material Not Observed 2019

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **WG-2**

MATERIAL DESCRIPTION: **Window Glaze - Not Observed**

MATERIAL LOCATION: **1957 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/26/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Stevenson School	INSPECTION DATE:	8/27/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Green Terrazzo Flooring		
MATERIAL LOCATION:	Entries and Stairwells		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/27/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25471	BUILDING ID:	6030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Shawn Brown		
SCHOOL NAME:	Stevenson School	REVIEW DATE:	9/26/2019		
ADDRESS:	8010 S. Kostner	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Green Terrazzo Flooring		
MATERIAL LOCATION:	Entries and Stairwells		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/26/2019**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MICHAEL HASIER
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 05/01/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

05/01/2019

Course Dates:

05/01/2020

Expires:

1905BIR02

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
375 S. Arland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TO EXPIRES

SUPERVISOR/WORKER

3/1/2020

INSPECTOR

5/1/2020

ID NUMBER

ISSUED

EXPIRES

100 - 09106

5/8/2019

05/15/2020

PROJECT MANAGER

3/1/2020

MICHAEL S HASIER

444 OLD BARN RD., APT. B
BARRINGTON, IL 60010

Environmental Health



AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



PUBLIC HEALTH & SAFETY, INC.

Environmental and Occupational Services
975 Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Director of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



PUBLIC HEALTH & SAFETY inc.
Environmental and Occupational Services
3711 Ashland Ave., Chicago, IL 60607
www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-3501

N. Penoff

Director of Training

Nicholas J. Penoff

Doctor of Public Health


Phone: 312-491-0081

FORM # A-011

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/19/2019

ID NUMBER

ISSUED

EXPIRES

100 - 02950

3/6/2019

05/15/2020

PROJECT MANAGER

4/9/2019

AIR SAMPLING PROFESSIONAL

KEITH CLOUGH

524 HOMELAND RD

MATTESON, IL 60443

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed