

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2490  
SCHOOL NAME: Twain School  
ADDRESS OF SCHOOL: 5131 S. Linder  
CITY: Chicago, IL, 60638

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/25/2016

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** (Please type or print)

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1063  
IDPH INSPECTOR LICENSE NUMBER: 100-19554  
IDPH LICENSED INSPECTOR NAME(Please Print): Carol Ashman  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Twain School**

5131 S. Linder  
Chicago, IL, 60638

Unit: 25661  
Building ID: 6240

IDPH ID Number: 14-016-2990-2490

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 25, 2019

RE: Twain School, Unit 25661  
5131 S. Linder  
Chicago, IL, 60638

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Twain School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Twain School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School:	Twain School	Unit:	25661	Region:	04
Address:	5131 S. Linder		Chicago, IL, 60638		
IDPH ID:	14-016-2990-2490		Building ID:	6240	
Contact:			Phone:		

### 2. Description of Facility

Original Construction:	Additional Construction:
Total Square Footage:	No of Floors:
Current Occupancy:	1063

### 3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	42 West Madison Street		
	Chicago, IL 60602		

### 4. Managing Environmental Consultant

MEC:	Carnow, Conibear and Associates		
Contact:	Doug McCormick		
Address	600 West Van Buren St., Ste 500		
	Chicago, IL, 60607		
Phone:	(312) 762-2900	Fax:	(312) 782-5145

### 5. Inspector

Inspector Name: Carol Ashman

Inspector IDPH license # 100-19554	Signature:
	Date: 9/25/2019

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466	Signature:
	Date: 10/18/2019

### 7. Review Date:10/18/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Twain School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6240:

20	12" x 12" Dark Beige Floor Tile
21.1	9" x 9" Orange w/ Brown Leopard Strips Floor Tile

B. The following new homogenous areas have been identified for Building 6240:

59

Creame hexagonal ceramic floor tile grout



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

20	12" x 12" Dark Beige Floor Tile
20.1	12" x 12" Light Olive Green Floor Tile
30	12" x 12" Light Blue Speckled Floor Tile
35	12" x 12" Beige Floor Tile w/Brown & White Streaks
44	12x12 Off-white with brown specks Floor Tile
45	12x12 Off-White with Brown Specks Floor tile Mastic
46	12" x 12" Tan w/ Brown and Green Specks VFT
47	12" x 12" Tan w/ Brown and Green Specks VFT Mastic
48	12" x 12" Yellow, Black, Salmon Patterned VFT
49	12" x 12" Yellow, Black, Salmon Patterned VFT Mastic
50	Brown Carpet Mastic
51	Spray-On Fireproofing
52	Gray Sink Undercoat
53	Transite Panels
54	6" Brown Baseboard
55	6" Brown Baseboard Mastic
56	Blue Carpet Mastic
57	6" Gray Baseboard
58	6" Gray Baseboard Mastic
59	Creame hexagonal ceramic floor tile grout

The following areas were deemed to be inaccessible:

20.1	12" x 12" Light Olive Green Floor Tile
22	12" x 12" Dark Beige Floor Tile Mastic
22.1	12" x 12" Light Olive Green Floor Tile Mastic
23.1	9" x 9" Orange w/ Brown Leopard Strips FT Mastic
45	12x12 Off-White with Brown Specks Floor tile Mastic
47	12" x 12" Tan w/ Brown and Green Specks VFT Mastic
49	12" x 12" Yellow, Black, Salmon Patterned VFT Mastic
50	Brown Carpet Mastic
55	6" Brown Baseboard Mastic
56	Blue Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Carol Ashman, IDPH License # 100-19554. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Twain School Building 6240 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

**School** Twain School **Unit** 25661 **Building ID** 6240  
**Address** 5131 S. Linder **Region** 04

### Inspector's Reinspection Findings Table 1

600 West Van Buren St., Ste 500 Chicago, Il, 60607

*Inspector's Comments are Summarized at the End of the Report*

[illegible]

**School** Twain School **Unit** 25661 **Building ID** 6240  
**Address** 5131 S. Linder **Region** 04

### Inspector's Reinspection Findings Table 1

600 West Van Buren St., Ste 500 Chicago, Il, 60607

*Inspector's Comments are Summarized at the End of the Report*

[illegible]

# Chicago Public Schools

School Twain School Unit 25661 Building ID 6240

Address 5131 S. Linder Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Modular Unit Demolished										
41a	6" Off-White Vinyl Baseboard			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
41b	6" Off-White Vinyl Baseboard			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
41c	6" Off-White Vinyl Baseboard			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
41d	6" Off-White Vinyl Baseboard			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
42	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
42a	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
42b	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
42c	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
42d	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
43	2' x 2' White Ceiling Tile			MATERIAL REMOVED - Modular Unit Demolished	UNDEFINE D									
44	12x12 Off-white with brown specks Floor Tile	400	SF	Boys Locker Room 114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12x12 Off-White with Brown Specks Floor	400	SF	Boys Locker Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Twain School Unit 25661 Building ID 6240

Address 5131 S. Linder Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	tile Mastic			114								potential for damage		
46	12" x 12" Tan w/ Brown and Green Specks VFT	5,548	SF	MDF Room, 108, 111, Engineer's Office, Copy Room, Main Office, 165	ASSUMED	MISC	N	LOC	2		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
47	12" x 12" Tan w/ Brown and Green Specks VFT Mastic	5,548	SF	MDF Room, 108, 111, Engineer's Office, Copy Room, Main Office, 165	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12" x 12" Yellow, Black, Salmon Patterned VFT	23,864	SF	All classrooms on 1st and 2nd Floors in New Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	12" x 12" Yellow, Black, Salmon Patterned VFT Mastic	23,864	SF	All Classrooms on the 1st and 2nd Floor in the New Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Brown Carpet Mastic	4,576	SF	Library, Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Spray-On Fireproofing	9,000	SF	Rm. 140, 141, Elevator Room, Above Ceiling in Old Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
52	Gray Sink Undercoat	60	SF	Rm. 162, 102, 260	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Transite Panels	72	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	6" Brown Baseboard	3,500	LF	Throughout Rooms in New Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	6" Brown Baseboard Mastic	3,500	LF	Throughout Rooms in New Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Blue Carpet Mastic	300	SF	Rm. 113, Auditorium Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	6" Gray Baseboard	280	LF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	6" Gray Baseboard Mastic	280	LF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Crete hexagonal ceramic floor tile grout	300	SF	1st floor girls restroom	ASSUMED	MISC	N	LOC	4		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
A	Cardboard Pipe Insulation			Janitor Closet Chases Throughout Building	NO_ACBM									
B	Fittings on Cardboard Pipe Insulation	3	LF	2nd Floor N. Janitor Closet Chase	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW



# Chicago Public Schools

**School** Twain School **Unit** 25661 **Building ID** 6240

**Address** 5131 S. Linder **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
C	Aircell Pipe Insulation-ABATED	3	LF	2nd Floor N. Janitor Closet Chase	CHR	TSI	Y	NONE	0		No	suspect ACBM Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Twain School Unit 25661 Building ID 6240  
Address 5131 S. Linder Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<u>9/25/2019</u>
Inspector Name	<u>Carol Ashman</u>
<u>100-19554</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

### Inspector's Comments

HA Number:	Inspector Comments:
20	Hall near 108. 12x12 dark beige floor tile 8 ft cracked, not observed in lunchroom
20.1	Not observed - still exists under HA 44/45
21.1	Room 214 9x9 orange brown leopard print floor tile 8 ft crack
22	Not observed in lunchroom
22.1	Not observed - still exists under HA 44/45
23.1	
24	
25	
26	
27	
28	
29	Not observed
30	
31	
32	
33	
34	
35	Not observed in lunchroom
36	
37	
38	
39	
39a	

# Chicago Public Schools

**School** Twain School **Unit** 25661 **Building ID** 6240  
**Address** 5131 S. Linder **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
39b	
39c	
39d	
40	
40a	
40b	
40c	
40d	
41	
41a	
41b	
41c	
41d	
42	
42a	
42b	
42c	
42d	
43	
44	
45	
46	Room 111 12x12 tan with green and brown speck 2 ft damage
47	
48	
49	
50	Not observed
51	Not observed
52	
53	

# Chicago Public Schools

**School** Twain School **Unit** 25661 **Building ID** 6240  
**Address** 5131 S. Linder **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
54	
55	
56	Not observed on Auditorium stage
57	
58	
59	1st floor girls restroom creme hexagonal ceramic tile grout 4 ft cracked or missing
A	
B	
C	Not observed - abated

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Twain School

Unit 25661

Building ID 6240

Address 5131 S. Linder

Chicago, IL, 60638

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
20	12" x 12" Dark Beige Floor Tile	4,000	SF	Corridor (3) & Lunch Room (2), Room 214	Assumed	MISC	No	8	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
20.1	12" x 12" Light Olive Green Floor Tile			Room 114 (Under HA 44/45)	Assumed	MISC					
21.1	9" x 9" Orange w/ Brown Leopard Strips Floor Tile	400	SF	Room 214	Chrysotile	MISC	No	8	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
22	12" x 12" Dark Beige Floor Tile Mastic	12,000	SF	Corridor (3), & Lunch Room (2), Office 108	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.1	12" x 12" Light Olive Green Floor Tile Mastic			Room 114 (Under HA 44/45)	Chrysotile	MISC					
23.1	9" x 9" Orange w/ Brown Leopard Strips FT Mastic	400	SF	Room 214	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Stage Curtain			Stage	No ACBM	MISC					
25	Plaster Walls			Throughout Building	No ACBM						
26	9" x 9" Brown Floor Tile w/Beige Streaks - REMOVED			Engineer's Office, Old Boiler Room BLDG	Chrysotile	MISC					
27	9" x 9" Brown Floor Tile w/Beige Streaks Mastic - REMOVED			Engineer's Office, Old Boiler Rm BLDG	Chrysotile	MISC					
28	9" x 9" Black Floor Tile w/Beige Streaks - REMOVED			Engineer's Office, Two Bathrooms and by entrance to Engineer's Office	Chrysotile	MISC					
29	9" x 9" Black Floor Tile w/Beige Streaks Mastic			Engineer's Office, Two Bathrooms and by entrance to Engineer's Office	Chrysotile	MISC					
30	12" x 12" Light Blue Speckled Floor Tile	480	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Light Blue Speckled Floor Tile Mastic			Room 200	No ACBM						
32	8" Black Vinyl Baseboard			Room 114	No ACBM						
33	8" Black Vinyl Baseboard Adhesive			Room 114	No ACBM						
34	Brown/Gold Mix Carpet Mastic			Room 111/Library	No ACBM						
35	12" x 12" Beige Floor Tile w/Brown & White Streaks	4,000	SF	Room 108/Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12"Beige Floor Tile w/Brn & Wht Streaks Mastic			Room 108/Lunchroom	No ACBM						
37	2' x 4' White Ceiling Tile			Rooms 114, 108/Lunchroom, and 105	No ACBM						
38	Drywall			Rooms 114 & 214	No ACBM						
39	12"x12" Beige Floor Tile w/Brown & White Speckles			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
39a	12"x12" Beige w/ Brown & White Speckles Floor			MATERIAL REMOVED - Modular Unit	Undefined						

# Chicago Public Schools

School Twain School

Unit 25661

Building ID 6240

Address 5131 S. Linder

Chicago, IL, 60638

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Tile			Demolished							
39b	12"x12" Beige w/ Brown & White Speckles Floor Tile			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
39c	12"x12" Beige w/ Brown & White Speckles Floor Tile			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
39d	12"x12" Beige w/ Brown & White Speckles Floor Tile			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
40	12"x12" Beige FT w/Brown & White Speckles Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
40a	12"x12" Beige w/Brown & White Speckles FT Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
40b	12"x12" Beige w/Brown & White Speckles FT Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
40c	12"x12" Beige w/Brown & White Speckles FT Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
40d	12"x12" Beige w/Brown & White Speckles FT Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
41	6" Off-White Vinyl Baseboard			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
41a	6" Off-White Vinyl Baseboard			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
41b	6" Off-White Vinyl Baseboard			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
41c	6" Off-White Vinyl Baseboard			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
41d	6" Off-White Vinyl Baseboard			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
42	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
42a	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
42b	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
42c	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						

# Chicago Public Schools

School Twain School

Unit 25661

Building ID 6240

Address 5131 S. Linder

Chicago, IL, 60638

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
42d	6" Off-White Vinyl Baseboard Mastic			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
43	2' x 2' White Ceiling Tile			MATERIAL REMOVED - Modular Unit Demolished	Undefined						
44	12x12 Off-white with brown specks Floor Tile	400	SF	Boys Locker Room 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12x12 Off-White with Brown Specks Floor tile Mastic	400	SF	Boys Locker Room 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" x 12" Tan w/ Brown and Green Specks VFT	5,548	SF	MDF Room, 108, 111, Engineer's Office, Copy Room, Main Office, 165	Assumed	MISC	No	2	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
47	12" x 12" Tan w/ Brown and Green Specks VFT Mastic	5,548	SF	MDF Room, 108, 111, Engineer's Office, Copy Room, Main Office, 165	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Yellow, Black, Salmon Patterned VFT	23,864	SF	All classrooms on 1st and 2nd Floors in New Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12" x 12" Yellow, Black, Salmon Patterned VFT Mastic	23,864	SF	All Classrooms on the 1st and 2nd Floor in the New Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Brown Carpet Mastic	4,576	SF	Library, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Spray-On Fireproofing	9,000	SF	Rm. 140, 141, Elevator Room, Above Ceiling in Old Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
52	Gray Sink Undercoat	60	SF	Rm. 162, 102, 260	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Transite Panels	72	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	6" Brown Baseboard	3,500	LF	Throughout Rooms in New Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
55	6" Brown Baseboard Mastic	3,500	LF	Throughout Rooms in New Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
56	Blue Carpet Mastic	300	SF	Rm. 113, Auditorium Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	6" Gray Baseboard	280	LF	Cafeteria	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
58	6" Gray Baseboard Mastic	280	LF	Cafeteria	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
59	Creme hexagonal ceramic floor tile grout	300	SF	1st floor girls restroom	Assumed	MISC	No	4	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
A	Cardboard Pipe Insulation			Janitor Closet Chases Throughout Building	No ACBM						
B	Fittings on Cardboard Pipe Insulation	3	LF	2nd Floor N. Janitor Closet Chase	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Aircell Pipe Insulation-ABATED	3	LF	2nd Floor N. Janitor Closet Chase	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan



# Chicago Public Schools

School Twain School

Unit 25661

Building ID 6240

Address 5131 S. Linder

Chicago, IL, 60638

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/18/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
20	
20.1	
21.1	
22	
22.1	
23.1	

# Chicago Public Schools

School Twain School

Unit 25661

Building ID 6240

Address 5131 S. Linder

Chicago, IL, 60638

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
39a	
39b	
39c	
39d	
40	
40a	
40b	
40c	
40d	
41	

# Chicago Public Schools

School Twain School

Unit 25661

Building ID 6240

Address 5131 S. Linder

Chicago, IL, 60638

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
41a	
41b	
41c	
41d	
42	
42a	
42b	
42c	
42d	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	

# Chicago Public Schools

**School** Twain School

**Unit** 25661

**Building ID** 6240

**Address** 5131 S. Linder

Chicago, IL, 60638

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
A	
B	
C	

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12" x 12" Dark Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	4 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridor (3) & Lunch Room (2), Room 214		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	8	DAMAGE UNITS:	SF
COMMENTS:	Hall near 108. 12x12 dark beige floor tile 8 ft cracked, not observed in lunchroom		

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Dark Beige Floor Tile**

MATERIAL LOCATION: **Corridor (3) & Lunch Room (2), Room 214**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20.1	
MATERIAL DESCRIPTION:	12" x 12" Light Olive Green Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 114 (Under HA 44/45)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed - still exists under HA 44/45

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **20.1**

MATERIAL DESCRIPTION: **12" x 12" Light Olive Green Floor Tile**

MATERIAL LOCATION: **Room 114 (Under HA 44/45)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21.1		
MATERIAL DESCRIPTION:	9" x 9" Orange w/ Brown Leopard Strips Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	4 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 214		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	8	DAMAGE UNITS:	SF
COMMENTS:	Room 214 9x9 orange brown leopard print floor tile 8 ft crack		

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **21.1**

MATERIAL DESCRIPTION: **9" x 9" Orange w/ Brown Leopard Strips Floor Tile**

MATERIAL LOCATION: **Room 214**

MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>8</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12" x 12" Dark Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridor (3), & Lunch Room (2), Office 108		
MATERIAL QUANTITY:	12000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in lunchroom		

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA:	<b>22</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Dark Beige Floor Tile Mastic</b>		
MATERIAL LOCATION:	<b>Corridor (3), &amp; Lunch Room (2), Office 108</b>		
MATERIAL QUANTITY:	<b>12000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.1		
MATERIAL DESCRIPTION:	12" x 12" Light Olive Green Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Room 114 (Under HA 44/45)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed - still exists under HA 44/45**

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **22.1**

MATERIAL DESCRIPTION: **12" x 12" Light Olive Green Floor Tile Mastic**

MATERIAL LOCATION: **Room 114 (Under HA 44/45)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.1		
MATERIAL DESCRIPTION:	9" x 9" Orange w/ Brown Leopard Strips FT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 214		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Twain School	REVIEW DATE:	10/18/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

HOMOGENEOUS AREA: 23.1

MATERIAL DESCRIPTION: 9" x 9" Orange w/ Brown Leopard Strips FT Mastic

MATERIAL LOCATION: Room 214

MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
--------------------	-----	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24	
MATERIAL DESCRIPTION:	Stage Curtain	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Stage

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Stage Curtain**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25	
MATERIAL DESCRIPTION:	Plaster Walls	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Plaster Walls**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile w/Beige Streaks - REMOVED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office, Old Boiler Room BLDG

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/Beige Streaks - REMOVED**

MATERIAL LOCATION: **Engineer's Office, Old Boiler Room BLDG**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile w/Beige Streaks Mastic - REMOVED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office, Old Boiler Rm BLDG

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/Beige Streaks Mastic - REMOVED**

MATERIAL LOCATION: **Engineer's Office, Old Boiler Rm BLDG**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile w/Beige Streaks - REMOVED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office, Two Bathrooms and by entrance to Engineer's Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/Beige Streaks - REMOVED**

MATERIAL LOCATION: **Engineer's Office, Two Bathrooms and by entrance to Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile w/Beige Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office, Two Bathrooms and by entrance to Engineer's Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/Beige Streaks Mastic**

MATERIAL LOCATION: **Engineer's Office, Two Bathrooms and by entrance to Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 200		
MATERIAL QUANTITY:	480	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Speckled Floor Tile**

MATERIAL LOCATION: **Room 200**

MATERIAL QUANTITY: **480**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 200

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32	
MATERIAL DESCRIPTION:	8" Black Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 114

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **8" Black Vinyl Baseboard**

MATERIAL LOCATION: **Room 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33	
MATERIAL DESCRIPTION:	8" Black Vinyl Baseboard Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 114

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **8" Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Room 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34	
MATERIAL DESCRIPTION:	Brown/Gold Mix Carpet Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 111/Library

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Brown/Gold Mix Carpet Mastic**

MATERIAL LOCATION: **Room 111/Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 108/Lunchroom		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in lunchroom		

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown & White Streaks**

MATERIAL LOCATION: **Room 108/Lunchroom**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12"x12"Beige Floor Tile w/Brn & Wht Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 108/Lunchroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12"x12"Beige Floor Tile w/Brn & Wht Streaks Mastic**

MATERIAL LOCATION: **Room 108/Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37	
MATERIAL DESCRIPTION:	2' x 4' White Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 114, 108/Lunchroom, and 105

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile**

MATERIAL LOCATION: **Rooms 114, 108/Lunchroom, and 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38	
MATERIAL DESCRIPTION:	Drywall	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 114 & 214

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Rooms 114 & 214**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39	
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile w/Brown & White Speckles	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/Brown & White Speckles**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39a	
MATERIAL DESCRIPTION:	12"x12" Beige w/ Brown & White Speckles Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **39a**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Speckles Floor Tile**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39b	
MATERIAL DESCRIPTION:	12"x12" Beige w/ Brown & White Speckles Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **39b**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Speckles Floor Tile**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39c	
MATERIAL DESCRIPTION:	12"x12" Beige w/ Brown & White Speckles Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **39c**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Speckles Floor Tile**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39d	
MATERIAL DESCRIPTION:	12"x12" Beige w/ Brown & White Speckles Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **39d**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Speckles Floor Tile**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40	
MATERIAL DESCRIPTION:	12"x12" Beige FT w/Brown & White Speckles Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" Beige FT w/Brown & White Speckles Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40a	
MATERIAL DESCRIPTION:	12"x12" Beige w/Brown & White Speckles FT Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **40a**

MATERIAL DESCRIPTION: **12"x12" Beige w/Brown & White Speckles FT Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40b	
MATERIAL DESCRIPTION:	12"x12" Beige w/Brown & White Speckles FT Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **40b**

MATERIAL DESCRIPTION: **12"x12" Beige w/Brown & White Speckles FT Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40c	
MATERIAL DESCRIPTION:	12"x12" Beige w/Brown & White Speckles FT Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **40c**

MATERIAL DESCRIPTION: **12"x12" Beige w/Brown & White Speckles FT Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40d	
MATERIAL DESCRIPTION:	12"x12" Beige w/Brown & White Speckles FT Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **40d**

MATERIAL DESCRIPTION: **12"x12" Beige w/Brown & White Speckles FT Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41a	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **41a**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41b	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **41b**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41c	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **41c**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41d	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **41d**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42a	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **42a**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42b	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **42b**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42c	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **42c**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42d	
MATERIAL DESCRIPTION:	6" Off-White Vinyl Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **42d**

MATERIAL DESCRIPTION: **6" Off-White Vinyl Baseboard Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43	
MATERIAL DESCRIPTION:	2' x 2' White Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED - Modular Unit Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tile**

MATERIAL LOCATION: **MATERIAL REMOVED - Modular Unit Demolished**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	12x12 Off-white with brown specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boys Locker Room 114		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12x12 Off-white with brown specks Floor Tile**

MATERIAL LOCATION: **Boys Locker Room 114**

MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12x12 Off-White with Brown Specks Floor tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boys Locker Room 114		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12x12 Off-White with Brown Specks Floor tile Mastic**

MATERIAL LOCATION: **Boys Locker Room 114**

MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Brown and Green Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	4 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	MDF Room, 108, 111, Engineer's Office, Copy Room, Main Office, 165		
MATERIAL QUANTITY:	5548	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	2	DAMAGE UNITS:	SF
COMMENTS:	Room 111 12x12 tan with green and brown speck 2 ft damage		

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA:	<b>46</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan w/ Brown and Green Specks VFT</b>		
MATERIAL LOCATION:	<b>MDF Room, 108, 111, Engineer's Office, Copy Room, Main Office, 165</b>		
MATERIAL QUANTITY:	<b>5548</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>2</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Brown and Green Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	MDF Room, 108, 111, Engineer's Office, Copy Room, Main Office, 165		
MATERIAL QUANTITY:	5548	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA:	<b>47</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan w/ Brown and Green Specks VFT Mastic</b>		
MATERIAL LOCATION:	<b>MDF Room, 108, 111, Engineer's Office, Copy Room, Main Office, 165</b>		
MATERIAL QUANTITY:	<b>5548</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	12" x 12" Yellow, Black, Salmon Patterned VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All classrooms on 1st and 2nd Floors in New Building		
MATERIAL QUANTITY:	23864	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12" x 12" Yellow, Black, Salmon Patterned VFT**

MATERIAL LOCATION: **All classrooms on 1st and 2nd Floors in New Building**

MATERIAL QUANTITY:	<b>23864</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	--------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12" x 12" Yellow, Black, Salmon Patterned VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Classrooms on the 1st and 2nd Floor in the New Building		
MATERIAL QUANTITY:	23864	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA:	<b>49</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Yellow, Black, Salmon Patterned VFT Mastic</b>		
MATERIAL LOCATION:	<b>All Classrooms on the 1st and 2nd Floor in the New Building</b>		
MATERIAL QUANTITY:	<b>23864</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Brown Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library, Main Office		
MATERIAL QUANTITY:	4576	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed		

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Library, Main Office**

MATERIAL QUANTITY: **4576**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Spray-On Fireproofing		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rm. 140, 141, Elevator Room, Above Ceiling in Old Building		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed		

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA:	<b>51</b>		
MATERIAL DESCRIPTION:	<b>Spray-On Fireproofing</b>		
MATERIAL LOCATION:	<b>Rm. 140, 141, Elevator Room, Above Ceiling in Old Building</b>		
MATERIAL QUANTITY:	<b>9000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	Gray Sink Undercoat		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rm. 162, 102, 260		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Gray Sink Undercoat**

MATERIAL LOCATION: **Rm. 162, 102, 260**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Transite Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	72	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Transite Panels**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **72**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	6" Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Rooms in New Building		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **6" Brown Baseboard**

MATERIAL LOCATION: **Throughout Rooms in New Building**

MATERIAL QUANTITY: **3500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	6" Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Rooms in New Building		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **6" Brown Baseboard Mastic**

MATERIAL LOCATION: **Throughout Rooms in New Building**

MATERIAL QUANTITY: **3500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rm. 113, Auditorium Stage		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed on Auditorium stage		

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Rm. 113, Auditorium Stage**

MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	6" Gray Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	280	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **6" Gray Baseboard**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **280**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	6" Gray Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	280	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **6" Gray Baseboard Mastic**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **280**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A	
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Janitor Closet Chases Throughout Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

**Carnow, Conibear and Associates**

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Janitor Closet Chases Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Fittings on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor N. Janitor Closet Chase		
MATERIAL QUANTITY:	3	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fittings on Cardboard Pipe Insulation**

MATERIAL LOCATION: **2nd Floor N. Janitor Closet Chase**

MATERIAL QUANTITY:	<b>3</b>	MATERIAL UNITS:	<b>LF</b>
--------------------	----------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>LF</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation-ABATED		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor N. Janitor Closet Chase		
MATERIAL QUANTITY:	3	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:	Not observed - abated		

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation-ABATED**

MATERIAL LOCATION: **2nd Floor N. Janitor Closet Chase**

MATERIAL QUANTITY: **3**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2019 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25661	BUILDING ID:	6240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Twain School	INSPECTION DATE:	9/25/2019		
ADDRESS:	5131 S. Linder	IDPH LICENSE NO:	100-19554		

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	59				
MATERIAL DESCRIPTION:	Creme hexagonal ceramic floor tile grout				
MATERIAL LOCATION:	1st floor girls restroom				
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	4 Damaged or significantly damaged friable misc. ACBM				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	4	DAMAGE UNITS:	SF		

#### COMMENTS:

1st floor girls restroom creme hexagonal ceramic tile grout 4 ft cracked or missing

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25661</b>	BUILDING ID:	<b>6240</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Evan Christian</b>		
SCHOOL NAME:	<b>Twain School</b>	REVIEW DATE:	<b>10/18/2019</b>		
ADDRESS:	<b>5131 S. Linder</b>	IDPH LICENSE NO:	<b>100-19554</b>		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Crete hexagonal ceramic floor tile grout**

MATERIAL LOCATION: **1st floor girls restroom**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **4**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/18/2019**


# APPENDIX B

## Inspector and Management Planner Licenses

---



2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

**Carol Ashman**


has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/22/2019 - 1/24/2019

Exam Date: 1/24/2019

Expiration Date: 1/24/2020

Certificate Number: ABI1901240283

  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**CAROL L ASHMAN**  
1633 Mc KAY ST.  
WAUKEGAN, IL 60087

3/8/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 19554

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 19554	ISSUED 3/8/2019	EXPIRES 05/15/2020	INSPECTOR	1/24/2020
<b>CAROL L ASHMAN</b> 1633 Mc KAY ST. WAUKEGAN, IL 60087 Environmental Health			PROJECT MANAGER	2/22/2020
			AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384

  
Kathy DeSalvo, Director



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
**100 - 19466**

ISSUED  
**4/12/2019**

EXPIRES  
**05/15/2020**

**EVAN I CHRISTIAN**  
3024 N RACINE AVE, APT 2  
CHICAGO, IL 60657

Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019

Expiration Date: 1/7/2020



Certificate Number: MPR1901070063

---

Kathy DeSalvo, Director

## Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW  
CONIBEAR**



# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed