

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2870
SCHOOL NAME: Brighton Park School
ADDRESS OF SCHOOL: 3825 S. Washtenaw
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/8/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 384
IDPH INSPECTOR LICENSE NUMBER: 100-05090
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Herman
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Brighton Park School

3825 S. Washtenaw
Chicago, IL, 60632

Unit: 26451
Building ID: 7470

IDPH ID Number: 14-016-2990-2870

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 22, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 26451 Region: 04 IDPH ID:14-016-2990-2870

School: Brighton Park School Building ID: 7470

Address: 3825 S. Washtenaw

Chicago, IL, 60632

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 05/17/2019

Inspector: Michael Herman

Inspector IDPH License: 100-05090

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 22, 2019

RE: Brighton Park School, Unit 26451
3825 S. Washtenaw
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Brighton Park School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Brighton Park School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Brighton Park School	Unit:	26451	Region:	04
Address:	3825 S. Washtenaw	Chicago, IL,	60632		
IDPH ID:	14-016-2990-2870	Building ID:	7470		
Contact:		Phone:			

2. Description of Facility

Original Construction:	Additional Construction:
Total Square Footage:	No of Floors:
Current Occupancy: 384	

3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	42 West Madison Street		
	Chicago, IL 60602		

4. Managing Environmental Consultant

MEC:	Carnow, Conibear and Associates		
Contact:	Doug McCormick		
Address	600 West Van Buren St., Ste 500		
	Chicago, IL, 60607		
Phone:	(312) 762-2900	Fax:	(312) 782-5145

5. Inspector

Inspector Name: Michael Herman

Inspector IDPH license # 100-05090

Signature:
Date: 4/22/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 05/17/2019

7. Review Date: 05/17/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Brighton Park School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7470:

B. The following new homogenous areas have been identified for Building 7470:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

14	12"x12" Light Brown/Off White Floor Tile
19	Insulation Inside of Fire Door
23	12"x12" Floor Tile
24	12"x12" Floor Tile Mastic
4	4"x4" Red and Black Floor Tile
5	4'x10' Ceiling Panels
51	Pegboard
56	12" x 12" White w/ Blue & Yellow Floor Tile
58	12" x 12" Blue Floor Tile
60	12" x 12" Yellow Floor Tile
64	12" x 12" Brown Floor Tile
66	12" X 12" Beige Floor Tile
68	2' x 4' Lay-in Ceiling Panels
69	Floor Tile Beneath 12" x 12" Floor Tile
70	Floor Tile Beneath 12" x 12" Floor Tile Mastic
71	Blue Carpet Adhesive
72	2' x 4' Ceiling Panels
73	Green Carpet Adhesive
74	Drywall
75	Drywall Compound
76	Sink Undercoat
77	12" x 12" Aqua Floor Tile
78	12" x 12" Aqua Floor Tile Mastic
79	12" x 12" Beige Floor Tile
80	12" x 12" Beige Floor Tile Mastic
81	4" Green Vinyl Baseboard
82	4" Green Vinyl Baseboard Adhesive
83	Spray On Insulation
84	Vibration Collars
85	Chalk Board/Marker Board Adhesive
86	Chalk Board/Marker Board Adhesive
87	Core in Green Pads
88	2' x 4' Smooth Ceiling Panels
89	12" x 12" Green and White Floor Tile
90	12" x 12" green and White Floor tile Mastic
A	Boiler Lag

The following areas were deemed to be inaccessible:

16	12"x12" Light Brown/Off White Floor Tile Mastic
----	---

19	Insulation Inside of Fire Door
24	12"x12" Floor Tile Mastic
25	Floor Tile Mastic
69	Floor Tile Beneath 12" x 12" Floor Tile
70	Floor Tile Beneath 12" x 12" Floor Tile Mastic
78	12" x 12" Aqua Floor Tile Mastic
80	12" x 12" Beige Floor Tile Mastic
82	4" Green Vinyl Baseboard Adhesive
85	Chalk Board/Marker Board Adhesive
86	Chalk Board/Marker Board Adhesive
90	12" x 12" green and White Floor tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Herman, IDPH License # 100-05090. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Brighton Park School Building 7470 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Brighton Park School Unit 26451 Building ID 7470

Address 3825 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	2'x4' Ceiling Panels			Classrooms of Original Building	NO_ACBM	MISC								
14	12"x12" Light Brown/Off White Floor Tile	4,000	SF	Hallways, and Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12"x12" Light Brown/Off White Floor Tile Mastic	4,000	SF	Hallways, and Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Insulation Inside of Fire Door	35	SF	Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
2	1'x1' Ceiling Tiles			Classrooms and Hallways of Original Building	NO_ACBM	MISC								
20	Drywall			Classrooms	NO_ACBM	MISC								
22	Transite Panels	500	SF	Behind Grills on Both Sides of Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12"x12" Floor Tile	150	SF	Entrance Foyer of Gym Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Floor Tile Mastic	150	SF	Entrance Foyer of Gym Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Floor Tile Mastic	500	SF	Girl's and Boy's Gym Washroom Vestibules	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	1"x1" White Ceramic Wall Tile Grout			Girl's Gym Washroom	NO_ACBM	MISC								
27	1"x1" Light Brown Ceramic Floor Tile Grout			Girl's Gym Washroom	NO_ACBM	MISC								
28	1"x1" Brown Ceramic Floor Tile Grout			Boy's Gym Washroom	NO_ACBM	MISC								
29	Ceramic Wall Tile Grout			Boy's Gym Washroom	NO_ACBM	MISC								
30	Terrazzo Flooring			Landing Between Washrooms by Gym	NO_ACBM	MISC								
31	2' x 4' Lay In Ceiling Panels			Girl's and Boy's Gym Washrooms	NO_ACBM	MISC								
32	Interior Brick			Gym	NO_ACBM	MISC								
33	Interior Brick Mortar			Gym	NO_ACBM	MISC								
34	Block			Gym	NO_ACBM	MISC								
35	Block Mortar			Gym	NO_ACBM	MISC								
36	Cementitious Patching Material			Boy's Gym Washroom Vestibule Windows	NO_ACBM	MISC								
37	Window Grout			Bleachers in Gym	NO_ACBM	MISC								
38	Green Wall Tile Caulk			Girl's and Boy's Washrooms-Original Building	NO_ACBM	MISC								

Chicago Public Schools

School Brighton Park School Unit 26451 Building ID 7470

Address 3825 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
39	Green Terrazzo Flooring			Girl's and Boy's Washrooms- Original Building	NO_ACBM	MISC								
4	4"x4" Red and Black Floor Tile	250	SF	Girl's and Boy's Washrooms- Gym Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Wall Tile Adhesive			Girl's and Boy's Washrooms- Original Building	NO_ACBM	MISC								
41	1'x1' Ceiling Tiles Adhesive			Throughout Original Building	NO_ACBM	MISC								
42	Terrazzo			Stairways and Landings in Original Building	NO_ACBM	MISC								
43	Interior Brick			Throughout Original Building	NO_ACBM	MISC								
44	Interior Brick Mortar			Throughout Original Building	NO_ACBM	MISC								
45	Terrazzo Wall Panels			Girl's Washroom- Original Building	NO_ACBM	MISC								
46	Grey Baseboard			Rooms 106, 107, 108	NO_ACBM	MISC								
47	Grey Baseboard mastic			Rooms 106, 107, 108	NO_ACBM	MISC								
48	Brown Baseboard			Rooms 110, 111, 204 & 205	NO_ACBM	MISC								
49	Brown Baseboard Mastic			Rooms 110, 111, 204 & 205	NO_ACBM	MISC								
5	4'x10' Ceiling Panels	3,500	SF	Gym	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
50	Ceiling Material			Garage	NO_ACBM	MISC								
51	Pegboard			Room 211	ASSUMED	MISC								
52	Exterior Brick - Non AHERA			Original Building	NO_ACBM	MISC								
53	Exterior Brick Mortar - Non AHERA			Original Building	NO_ACBM	MISC								
54	Exterior Door Grout - Non AHERA			Original Building	NO_ACBM	MISC								
55	Fire Block			Basement Stairs	NO_ACBM	MISC								
56	12" x 12" White w/ Blue & Yellow Floor Tile	2,000	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12"x12" White w/ Blue and Yellow Floor Tile Mastic			Library	NO_ACBM	MISC								
58	12" x 12" Blue Floor Tile	2,000	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	12"x12" Blue Floor Tile Mastic			Library	NO_ACBM	MISC								

Chicago Public Schools

School Brighton Park School Unit 26451 Building ID 7470

Address 3825 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
60	12" x 12" Yellow Floor Tile	2,500	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	12"x12" Yellow Floor Tile Mastic			Library	NO_ACBM	MISC								
62	4" Blue Vinyl Baseboard			Library	NO_ACBM	MISC								
63	4" Blue Vinyl Baseboard Adhesive			Library	NO_ACBM	MISC								
64	12" x 12" Brown Floor Tile	4,500	SF	Classrooms- Original Building with the Exception of 224 & 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12"x12" Brown Floor Tile Mastic			Classrooms - Original Building with the Exception of 224 & 225	NO_ACBM	MISC								
66	12" X 12" Beige Floor Tile	4,500	SF	Classrooms- Original Building with the Exception of 224 & 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12"x12" Beige Floor Tile Mastic			Classrooms - Original Building with the Exception of 224 & 225	NO_ACBM	MISC								
68	2' x 4' Lay-in Ceiling Panels	544	SF	Rear Room in Library	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
69	Floor Tile Beneath 12" x 12" Floor Tile	9,400	SF	All rooms of original building except Rooms 224 and 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	Floor Tile Beneath 12" x 12" Floor Tile Mastic	9,400	SF	All rooms of original building except Rooms 224 and 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	Blue Carpet Adhesive			Room 229	ASSUMED	MISC								
72	2' x 4' Ceiling Panels	24,250	SF	Rooms 224, 225, & the 2001 Addition Classrooms and Corridors	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
73	Green Carpet Adhesive			2001 Addition, Office, Rooms 105, 107, 109, 111, 205	ASSUMED	MISC		None						Low
74	Drywall	25,000	SF	2001 Addition	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
75	Drywall Compound	25,000	SF	2001 Addition	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable		LOW

Chicago Public Schools

School Brighton Park School Unit 26451 Building ID 7470

Address 3825 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												ACBM or friable suspect ACBM		
76	Sink Undercoat	10	SF	Office, Room 101	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
77	12" x 12" Aqua Floor Tile	9,117	SF	2001 Addition Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12" x 12" Aqua Floor Tile Mastic	9,532	SF	2001 Addition Classrooms, 205	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12" x 12" Beige Floor Tile	12,447	SF	2001 Addition Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	12" x 12" Beige Floor Tile Mastic	12,447	SF	2001 Addition Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	4" Green Vinyl Baseboard	1,300	LF	2001 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	4" Green Vinyl Baseboard Adhesive	1,300	LF	2001 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	Spray On Insulation	12,000	SF	2001 Addition	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
84	Vibration Collars	100	LF	2001 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	Chalk Board/Marker Board Adhesive	2,000	SF	Original Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	Chalk Board/Marker Board Adhesive	2,400	SF	2001 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	Core in Green Pads	2,520	SF	2001 Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	2' x 4' Smooth Ceiling Panels	1,368	SF	Kitchen and Serving Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	12" x 12" Green and White Floor Tile	3,500	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12" x 12" green and White Floor tile Mastic	3,500	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Boiler Lag	50	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Aircell Lag	10	LF	Girl's Washroom Vestibule in Gym Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Brighton Park School Unit 26451 Building ID 7470

Address 3825 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>4/22/2019</u>
Inspector Name	<u>Michael Herman</u>
<u>100-05090</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
1	
14	
16	
19	
2	
20	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	Not observed
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
66	
67	
68	
69	
70	
71	Not observed
72	
73	Not observed
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
A	
F	

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	2'x4' Ceiling Panels			Classrooms of Original Building	No ACBM	MISC					
14	12"x12" Light Brown/Off White Floor Tile	4,000	SF	Hallways, and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
16	12"x12" Light Brown/Off White Floor Tile Mastic	4,000	SF	Hallways, and Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
19	Insulation Inside of Fire Door	35	SF	Boiler Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	
2	1'x1' Ceiling Tiles			Classrooms and Hallways of Original Building	No ACBM	MISC					
20	Drywall			Classrooms	No ACBM	MISC					
22	Transite Panels	500	SF	Behind Grills on Both Sides of Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
23	12"x12" Floor Tile	150	SF	Entrance Foyer of Gym Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
24	12"x12" Floor Tile Mastic	150	SF	Entrance Foyer of Gym Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
25	Floor Tile Mastic	500	SF	Girl's and Boy's Gym Washroom Vestibules	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
26	1"x1" White Ceramic Wall Tile Grout			Girl's Gym Washroom	No ACBM	MISC					
27	1"x1" Light Brown Ceramic Floor Tile Grout			Girl's Gym Washroom	No ACBM	MISC					
28	1"x1" Brown Ceramic Floor Tile Grout			Boy's Gym Washroom	No ACBM	MISC					
29	Ceramic Wall Tile Grout			Boy's Gym Washroom	No ACBM	MISC					
30	Terrazzo Flooring			Landing Between Washrooms by Gym	No ACBM	MISC					
31	2' x 4' Lay In Ceiling Panels			Girl's and Boy's Gym Washrooms	No ACBM	MISC					
32	Interior Brick			Gym	No ACBM	MISC					
33	Interior Brick Mortar			Gym	No ACBM	MISC					
34	Block			Gym	No ACBM	MISC					
35	Block Mortar			Gym	No ACBM	MISC					
36	Cementitious Patching Material			Boy's Gym Washroom Vestibule Windows	No ACBM	MISC					
37	Window Grout			Bleachers in Gym	No ACBM	MISC					
38	Green Wall Tile Caulk			Girl's and Boy's Washrooms- Original Building	No ACBM	MISC					
39	Green Terrazzo Flooring			Girl's and Boy's Washrooms- Original Building	No ACBM	MISC					
4	4"x4" Red and Black Floor Tile	250	SF	Girl's and Boy's Washrooms- Gym Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
40	Wall Tile Adhesive			Girl's and Boy's Washrooms- Original Building	No ACBM	MISC					
41	1'x1' Ceiling Tiles Adhesive			Throughout Original Building	No ACBM	MISC					

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
42	Terrazzo			Stairways and Landings in Original Building	No ACBM	MISC					
43	Interior Brick			Throughout Original Building	No ACBM	MISC					
44	Interior Brick Mortar			Throughout Original Building	No ACBM	MISC					
45	Terrazzo Wall Panels			Girl's Washroom- Original Building	No ACBM	MISC					
46	Grey Baseboard			Rooms 106, 107, 108	No ACBM	MISC					
47	Grey Baseboard mastic			Rooms 106, 107, 108	No ACBM	MISC					
48	Brown Baseboard			Rooms 110, 111, 204 & 205	No ACBM	MISC					
49	Brown Baseboard Mastic			Rooms 110, 111, 204 & 205	No ACBM	MISC					
5	4'x10' Ceiling Panels	3,500	SF	Gym	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
50	Ceiling Material			Garage	No ACBM	MISC					
51	Pegboard			Room 211	Assumed	MISC					
52	Exterior Brick - Non AHERA			Original Building	No ACBM	MISC					
53	Exterior Brick Mortar - Non AHERA			Original Building	No ACBM	MISC					
54	Exterior Door Grout - Non AHERA			Original Building	No ACBM	MISC					
55	Fire Block			Basement Stairs	No ACBM	MISC					
56	12" x 12" White w/ Blue & Yellow Floor Tile	2,000	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
57	12"x12" White w/ Blue and Yellow Floor Tile Mastic			Library	No ACBM	MISC					
58	12" x 12" Blue Floor Tile	2,000	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
59	12"x12" Blue Floor Tile Mastic			Library	No ACBM	MISC					
60	12" x 12" Yellow Floor Tile	2,500	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
61	12"x12" Yellow Floor Tile Mastic			Library	No ACBM	MISC					
62	4" Blue Vinyl Baseboard			Library	No ACBM	MISC					
63	4" Blue Vinyl Baseboard Adhesive			Library	No ACBM	MISC					
64	12" x 12" Brown Floor Tile	4,500	SF	Classrooms- Original Building with the Exception of 224 & 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
65	12"x12" Brown Floor Tile Mastic			Classrooms - Original Building with the Exception of 224 & 225	No ACBM	MISC					
66	12" X 12" Beige Floor Tile	4,500	SF	Classrooms- Original Building with the Exception of 224 & 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
67	12"x12" Beige Floor Tile Mastic			Classrooms - Original Building with the Exception of 224 & 225	No ACBM	MISC					

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
68	2' x 4' Lay-in Ceiling Panels	544	SF	Rear Room in Library	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
69	Floor Tile Beneath 12" x 12" Floor Tile	9,400	SF	All rooms of original building except Rooms 224 and 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
70	Floor Tile Beneath 12" x 12" Floor Tile Mastic	9,400	SF	All rooms of original building except Rooms 224 and 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
71	Blue Carpet Adhesive			Room 229	Assumed	MISC					
72	2' x 4' Ceiling Panels	24,250	SF	Rooms 224, 225, & the 2001 Addition Classrooms and Corridors	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
73	Green Carpet Adhesive			2001 Addition, Office, Rooms 105, 107, 109, 111, 205	Assumed	MISC					
74	Drywall	25,000	SF	2001 Addition	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
75	Drywall Compound	25,000	SF	2001 Addition	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
76	Sink Undercoat	10	SF	Office, Room 101	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
77	12" x 12" Aqua Floor Tile	9,117	SF	2001 Addition Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
78	12" x 12" Aqua Floor Tile Mastic	9,532	SF	2001 Addition Classrooms, 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
79	12" x 12" Beige Floor Tile	12,447	SF	2001 Addition Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
80	12" x 12" Beige Floor Tile Mastic	12,447	SF	2001 Addition Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
81	4" Green Vinyl Baseboard	1,300	LF	2001 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
82	4" Green Vinyl Baseboard Adhesive	1,300	LF	2001 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
83	Spray On Insulation	12,000	SF	2001 Addition	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
84	Vibration Collars	100	LF	2001 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
85	Chalk Board/Marker Board Adhesive	2,000	SF	Original Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
86	Chalk Board/Marker Board Adhesive	2,400	SF	2001 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
87	Core in Green Pads	2,520	SF	2001 Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
88	2' x 4' Smooth Ceiling Panels	1,368	SF	Kitchen and Serving Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
89	12" x 12" Green and White Floor Tile	3,500	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
90	12" x 12" green and White Floor tile Mastic	3,500	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
A	Boiler Lag	50	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
F	Aircell Lag	10	LF	Girl's Washroom Vestibule in Gym	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable	

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Building						suspect ACBM	

Review Date	05/17/2019
Manager Planner Name	Evan Christian

HA Number	Management Comments
1	
14	

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
16	
19	
2	
20	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
A	
F	

Chicago Public Schools

School	Brighton Park School	Unit	26451	Building ID	7470
Address	3825 S. Washtenaw		Chicago, IL, 60632	Region	04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)	Carnow, Conibear and Associates
	600 West Van Buren St., Ste 500 Chicago, Il, 60607
	Phone: (312) 762-2900
	Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1	
MATERIAL DESCRIPTION:	2'x4' Ceiling Panels	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Classrooms of Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **2'x4' Ceiling Panels**

MATERIAL LOCATION: **Classrooms of Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12"x12" Light Brown/Off White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways, and Office		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12"x12" Light Brown/Off White Floor Tile**

MATERIAL LOCATION: **Hallways, and Office**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12"x12" Light Brown/Off White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways, and Office		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12"x12" Light Brown/Off White Floor Tile Mastic**

MATERIAL LOCATION: **Hallways, and Office**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Insulation Inside of Fire Door		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	35	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Insulation Inside of Fire Door**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **35**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2	
MATERIAL DESCRIPTION:	1'x1' Ceiling Tiles	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Classrooms and Hallways of Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tiles**

MATERIAL LOCATION: **Classrooms and Hallways of Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20	
MATERIAL DESCRIPTION:	Drywall	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Classrooms

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Transite Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Behind Grills on Both Sides of Gym		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Transite Panels**

MATERIAL LOCATION: **Behind Grills on Both Sides of Gym**

MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	12"x12" Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Entrance Foyer of Gym Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12"x12" Floor Tile**

MATERIAL LOCATION: **Entrance Foyer of Gym Building**

MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	12"x12" Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Entrance Foyer of Gym Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12"x12" Floor Tile Mastic**

MATERIAL LOCATION: **Entrance Foyer of Gym Building**

MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girl's and Boy's Gym Washroom Vestibules		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Floor Tile Mastic**

MATERIAL LOCATION: **Girl's and Boy's Gym Washroom Vestibules**

MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26	
MATERIAL DESCRIPTION:	1"x1" White Ceramic Wall Tile Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girl's Gym Washroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **1"x1" White Ceramic Wall Tile Grout**

MATERIAL LOCATION: **Girl's Gym Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27	
MATERIAL DESCRIPTION:	1"x1" Light Brown Ceramic Floor Tile Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girl's Gym Washroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **1"x1" Light Brown Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Girl's Gym Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28	
MATERIAL DESCRIPTION:	1"x1" Brown Ceramic Floor Tile Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boy's Gym Washroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **1"x1" Brown Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Boy's Gym Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	Ceramic Wall Tile Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boy's Gym Washroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Ceramic Wall Tile Grout**

MATERIAL LOCATION: **Boy's Gym Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30	
MATERIAL DESCRIPTION:	Terrazzo Flooring	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Landing Between Washrooms by Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **Landing Between Washrooms by Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31	
MATERIAL DESCRIPTION:	2' x 4' Lay In Ceiling Panels	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girl's and Boy's Gym Washrooms

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**

MATERIAL LOCATION: **Girl's and Boy's Gym Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32	
MATERIAL DESCRIPTION:	Interior Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34	
MATERIAL DESCRIPTION:	Block	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Block**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35	
MATERIAL DESCRIPTION:	Block Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Block Mortar**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36	
MATERIAL DESCRIPTION:	Cementitious Patching Material	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boy's Gym Washroom Vestibule Windows

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Cementitious Patching Material**

MATERIAL LOCATION: **Boy's Gym Washroom Vestibule Windows**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37	
MATERIAL DESCRIPTION:	Window Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Bleachers in Gym

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Window Grout**

MATERIAL LOCATION: **Bleachers in Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38	
MATERIAL DESCRIPTION:	Green Wall Tile Caulk	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girl's and Boy's Washrooms- Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Green Wall Tile Caulk**

MATERIAL LOCATION: **Girl's and Boy's Washrooms- Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39	
MATERIAL DESCRIPTION:	Green Terrazzo Flooring	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girl's and Boy's Washrooms- Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Green Terrazzo Flooring**

MATERIAL LOCATION: **Girl's and Boy's Washrooms- Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	4"x4" Red and Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girl's and Boy's Washrooms- Gym Building		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **4"x4" Red and Black Floor Tile**

MATERIAL LOCATION: **Girl's and Boy's Washrooms- Gym Building**

MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40	
MATERIAL DESCRIPTION:	Wall Tile Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girl's and Boy's Washrooms- Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Wall Tile Adhesive**

MATERIAL LOCATION: **Girl's and Boy's Washrooms- Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41	
MATERIAL DESCRIPTION:	1'x1' Ceiling Tiles Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Original Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tiles Adhesive**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42	
MATERIAL DESCRIPTION:	Terrazzo	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Stairways and Landings in Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Stairways and Landings in Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43	
MATERIAL DESCRIPTION:	Interior Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Original Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Original Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45	
MATERIAL DESCRIPTION:	Terrazzo Wall Panels	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girl's Washroom- Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Terrazzo Wall Panels**

MATERIAL LOCATION: **Girl's Washroom- Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46	
MATERIAL DESCRIPTION:	Grey Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 106, 107, 108

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Grey Baseboard**

MATERIAL LOCATION: **Rooms 106, 107, 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47	
MATERIAL DESCRIPTION:	Grey Baseboard mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 106, 107, 108

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Grey Baseboard mastic**

MATERIAL LOCATION: **Rooms 106, 107, 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48	
MATERIAL DESCRIPTION:	Brown Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 110, 111, 204 & 205

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Brown Baseboard**

MATERIAL LOCATION: **Rooms 110, 111, 204 & 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49	
MATERIAL DESCRIPTION:	Brown Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 110, 111, 204 & 205

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic**

MATERIAL LOCATION: **Rooms 110, 111, 204 & 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	4'x10' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	4'x10' Ceiling Panels		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50	
MATERIAL DESCRIPTION:	Ceiling Material	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Garage

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Ceiling Material**

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51	
MATERIAL DESCRIPTION:	Pegboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 211

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Pegboard**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52	
MATERIAL DESCRIPTION:	Exterior Brick - Non AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Exterior Brick - Non AHERA**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53	
MATERIAL DESCRIPTION:	Exterior Brick Mortar - Non AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non AHERA**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54	
MATERIAL DESCRIPTION:	Exterior Door Grout - Non AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Original Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Exterior Door Grout - Non AHERA**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55	
MATERIAL DESCRIPTION:	Fire Block	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement Stairs

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Fire Block**

MATERIAL LOCATION: **Basement Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue & Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue & Yellow Floor Tile**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57	
MATERIAL DESCRIPTION:	12"x12" White w/ Blue and Yellow Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12"x12" White w/ Blue and Yellow Floor Tile Mastic**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59	
MATERIAL DESCRIPTION:	12"x12" Blue Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61	
MATERIAL DESCRIPTION:	12"x12" Yellow Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62	
MATERIAL DESCRIPTION:	4" Blue Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63	
MATERIAL DESCRIPTION:	4" Blue Vinyl Baseboard Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms- Original Building with the Exception of 224 & 225		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Classrooms- Original Building with the Exception of 224 & 225**

MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65	
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Classrooms - Original Building with the Exception of 224 & 225

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms - Original Building with the Exception of 224 & 225**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12" X 12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms- Original Building with the Exception of 224 & 225		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" X 12" Beige Floor Tile**

MATERIAL LOCATION: **Classrooms- Original Building with the Exception of 224 & 225**

MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67	
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Classrooms - Original Building with the Exception of 224 & 225

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms - Original Building with the Exception of 224 & 225**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	2' x 4' Lay-in Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rear Room in Library		
MATERIAL QUANTITY:	544	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**

MATERIAL LOCATION: **Rear Room in Library**

MATERIAL QUANTITY:	544	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	Floor Tile Beneath 12" x 12" Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All rooms of original building except Rooms 224 and 225		
MATERIAL QUANTITY:	9400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**

MATERIAL LOCATION: **All rooms of original building except Rooms 224 and 225**

MATERIAL QUANTITY:	9400	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Floor Tile Beneath 12" x 12" Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All rooms of original building except Rooms 224 and 225		
MATERIAL QUANTITY:	9400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **All rooms of original building except Rooms 224 and 225**

MATERIAL QUANTITY:	9400	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71	
MATERIAL DESCRIPTION:	Blue Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 229

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not observed

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Room 229**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 224, 225, & the 2001 Addition Classrooms and Corridors		
MATERIAL QUANTITY:	24250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Rooms 224, 225, & the 2001 Addition Classrooms and Corridors**

MATERIAL QUANTITY:	24250	MATERIAL UNITS:	SF
--------------------	--------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73	
MATERIAL DESCRIPTION:	Green Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: 2001 Addition, Office, Rooms 105, 107, 109, 111, 205

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Green Carpet Adhesive**

MATERIAL LOCATION: **2001 Addition, Office, Rooms 105, 107, 109, 111, 205**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **25000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	Drywall Compound		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **25000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	Sink Undercoat		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office, Room 101		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Sink Undercoat**

MATERIAL LOCATION: **Office, Room 101**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	12" x 12" Aqua Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition Classrooms		
MATERIAL QUANTITY:	9117	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	12" x 12" Aqua Floor Tile		
MATERIAL LOCATION:	2001 Addition Classrooms		
MATERIAL QUANTITY:	9117	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	12" x 12" Aqua Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition Classrooms, 205		
MATERIAL QUANTITY:	9532	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	12" x 12" Aqua Floor Tile Mastic		
MATERIAL LOCATION:	2001 Addition Classrooms, 205		
MATERIAL QUANTITY:	9532	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition Classrooms		
MATERIAL QUANTITY:	12447	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **2001 Addition Classrooms**

MATERIAL QUANTITY: **12447**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition Classrooms		
MATERIAL QUANTITY:	12447	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile Mastic		
MATERIAL LOCATION:	2001 Addition Classrooms		
MATERIAL QUANTITY:	12447	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	4" Green Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **4" Green Vinyl Baseboard**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	4" Green Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **4" Green Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	Spray On Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	12000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Spray On Insulation**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **12000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	Vibration Collars		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Vibration Collars**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	Chalk Board/Marker Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Original Building		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **Chalk Board/Marker Board Adhesive**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	Chalk Board/Marker Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	Chalk Board/Marker Board Adhesive		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	Core in Green Pads		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Gym		
MATERIAL QUANTITY:	2520	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Core in Green Pads**

MATERIAL LOCATION: **2001 Gym**

MATERIAL QUANTITY: **2520**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	2' x 4' Smooth Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen and Serving Area		
MATERIAL QUANTITY:	1368	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Panels**

MATERIAL LOCATION: **Kitchen and Serving Area**

MATERIAL QUANTITY: **1368**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	12" x 12" Green and White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12" x 12" Green and White Floor Tile**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **3500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12" x 12" green and White Floor tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" green and White Floor tile Mastic**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **3500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Boiler Lag		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler Lag**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	4/22/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Aircell Lag		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girl's Washroom Vestibule in Gym Building		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	5/17/2019		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Aircell Lag**

MATERIAL LOCATION: **Girl's Washroom Vestibule in Gym Building**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MICHAEL D HERMAN
5121 N MONITOR
CHICAGO, IL 60630

4/10/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05090

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	ID NUMBER 100 - 05090	ISSUED 4/10/2019	INSPECTOR	1/17/2020
MICHAEL D HERMAN 5121 N MONITOR CHICAGO, IL 60630 Environmental Health		EXPIRES 05/15/2020 	PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/16/2020
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Michael Herman

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/17/2019

Exam Date: 1/17/2019

Expiration Date: 1/17/2020

Certificate Number: BIR1901170228

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MICHAEL D HERMAN
5121 N MONITOR
CHICAGO, IL 60630

4/25/2018


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05090

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

IDPH ILLINOIS DEPARTMENT OF PUBLIC HEALTH		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 05090	ISSUED 4/25/2018	EXPIRES 05/15/2019		INSPECTOR	1/18/2019
MICHAEL D HERMAN 5121 N MONITOR CHICAGO, IL 60630 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/17/2019
				Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

Michael D. Herman
[Signature]

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES
Nationally Accredited by PHAB

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019



Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed