

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2366
SCHOOL NAME: Murray Academy
ADDRESS OF SCHOOL: 5335 S. Kenwood
CITY: Chicago, IL, 60615

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/24/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 457
IDPH INSPECTOR LICENSE NUMBER: 100-19716
IDPH LICENSED INSPECTOR NAME(Please Print): Imani Robinson
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Murray Academy

5335 S. Kenwood
Chicago, IL, 60615

Unit: 29221
Building ID: 5030

IDPH ID Number: 14-016-2990-2366

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 15, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 29221 Region: 04 IDPH ID:14-016-2990-2366

School: Murray Academy Building ID: 5030

Address: 5335 S. Kenwood

Chicago, IL, 60615

Building Contact: Henehan, Jack

Contact Phone:773 494 5334

Current Building Owners: Chicago Public Schools

Review Date: 05/04/2019

Inspector: Imani Robinson

Inspector IDPH License: 100-19716

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 15, 2019

RE: Murray Academy, Unit 29221
5335 S. Kenwood
Chicago, IL, 60615

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Murray Academy, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Murray Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Murray Academy	Unit:	29221	Region:	04
Address:	5335 S. Kenwood		Chicago, IL, 60615		
IDPH ID:	14-016-2990-2366		Building ID:	5030	
Contact:	Henehan, Jack		Phone:	773 494 5334	

2. Description of Facility

Original Construction:	2002	Additional Construction:	1954,2002
Total Square Footage:	16760	No of Floors:	2
Current Occupancy:	457		

3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	42 West Madison Street		
	Chicago, IL 60602		

4. Managing Environmental Consultant

MEC:	Carnow, Conibear and Associates		
Contact:	Doug McCormick		
Address	600 West Van Buren St., Ste 500		
	Chicago, IL, 60607		
Phone:	(312) 762-2900	Fax:	(312) 782-5145

5. Inspector

Inspector Name: Imani Robinson

Inspector IDPH license # 100-19716

Signature:
Date: 4/15/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 05/04/2019

7. Review Date:05/04/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Murray Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5030:

010	12x12 gray with black specks
011	12x12 gray
012	12x12 light grey floor tile
FA	Cardboard Lag

B. The following new homogenous areas have been identified for Building 5030:

010	12x12 gray with black specks
011	12x12 gray
012	12x12 light grey floor tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

010	12x12 gray with black specks
011	12x12 gray
012	12x12 light grey floor tile
10	Paperwrap/Aircell Pipe Insulation Wrap
11	Paperwrap/Aircell Pipe Insulation
12	Paperwrap/Aircell Pipe Joint Insulation
28	Roof Materials (Non-AHERA)
35	12" x 12" Blue Floor Tile
36	12" x 12" White Floor Tile
37	12" x 12" Yellow Floor Tile
48	Blue Carpet Adhesive
49	Chalk Board and Poster Board Adhesive
50	12x12 light beige with brown spots floor tile
51	12x12 light beige with brown spots floor tile mastic
7A	12" x 12" Gray, White & Tan Floor Tile
CA	Paperwrap Pipe Insulation Wrap
E	Elbow Insulation
EA	Paperwrap Pipe Insulation
FA	Cardboard Lag

The following areas were deemed to be inaccessible:

10	Paperwrap/Aircell Pipe Insulation Wrap
11	Paperwrap/Aircell Pipe Insulation
12	Paperwrap/Aircell Pipe Joint Insulation
35A	12" x 12" Blue Floor Tile Mastic
48	Blue Carpet Adhesive
49	Chalk Board and Poster Board Adhesive
51	12x12 light beige with brown spots floor tile mastic
9A	12" x 12" Gray, White & Tan Floor Tile Mastic
9C	12" x 12" Dk Gray/Orange w/Blk & Tan Strks Mastic
9D	12"x12" Beige Floor Tile w/Dk Green Streaks Mastic
9E	12" x 12" Gray Floor Tile w/White Streaks Mastic
CA	Paperwrap Pipe Insulation Wrap
E	Elbow Insulation
FA	Cardboard Lag

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Imani Robinson, IDPH License # 100-19716. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Murray Academy Building 5030 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
010	12x12 gray with black specks	800	SF	Room 101	ASSUMED	MISC	N	DIST	30		Yes	ACBM with potential for significant damage	5	HIGH
011	12x12 gray	600	SF	Room 108	ASSUMED	MISC	N	DIST	30		Yes	ACBM with potential for significant damage	5	HIGH
012	12x12 light grey floor tile	300	SF	West boys bathroom	ASSUMED	MISC	N	LOC	3		Yes	ACBM with the potential for damage	5	MODERATE
1	Plaster			Throughout Facility	NO_ACBM	SURFACE								
10	Paperwrap/Aircell Pipe Insulation Wrap	250	LF	In various inaccessible areas throughout facility	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
11	Paperwrap/Aircell Pipe Insulation	250	LF	In various inaccessible areas throughout facility	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
12	Paperwrap/Aircell Pipe Joint Insulation	50	LF	In various inaccessible areas throughout facility	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
13	Boiler Gaskets			Boiler Room	NO_ACBM	MISC								
14	Interior Brick			Throughout Building	NO_ACBM	MISC								
15	Interior Brick Mortar			Throughout Building	NO_ACBM	MISC								
16	Elbow Wrap			Boy's Bathroom	NO_ACBM	MISC								
17	Duct Vibration Material			Equipment Room	NO_ACBM	MISC					No			
18	Exterior Brick - Not AHERA			Exterior of Building	NO_ACBM	MISC								
19	Exterior Brick Mortar (Not AHERA)			Exterior of Building	NO_ACBM	MISC								
20	Exterior Door Caulk - Not AHERA			Building Exterior	NO_ACBM	MISC								
21	Plaster			Throughout	NO_ACBM	SURFACE								
22	Green Vinyl Curtain (Cream and brown)			Gym	NO_ACBM	MISC								
23	12" x 12" Ceiling Tile			Gym, Rm. 210	NO_ACBM	MISC								
24	Brown Carpet			1st Floor Office	NO_ACBM	MISC								
25	Brown Carpet Adhesive			1st Floor Office	NO_ACBM	MISC								
26	Black Felt Door Trim			2nd Floor Fan Room	NO_ACBM	MISC								
28	Roof Materials (Non-AHERA)			Roof	ASSUMED	MISC								
35	12" x 12" Blue Floor Tile	25	SF	Room 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35A	12" x 12" Blue Floor Tile Mastic	25	SF	Room 201	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12" x 12" White Floor Tile	2,500	SF	1st & 2nd Floor Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36A	12" x 12" White Floor Tile Mastic			1st & 2nd Floor Hall	NO_ACBM	MISC								
37	12" x 12" Yellow Floor Tile	2,500	SF	1st & 2nd Floor Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37A	12" x 12" Yellow Floor Tile Mastic			1st & 2nd Hall	NO_ACBM	MISC								

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
48	Blue Carpet Adhesive	400	SF	Office and Principal's Office Rm. 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Chalk Board and Poster Board Adhesive	150	SF	All Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12x12 light beige with brown spots floor tile	100	SF	Engineer's office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	12x12 light beige with brown spots floor tile mastic	100	SF	engineer's office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6A	9" x 9" White Floor Tile w/Gray Streaks			Engineer's Office	CHR	MISC								
7A	12" x 12" Gray, White & Tan Floor Tile	2,500	SF	1st Floor Corridor, Room 107, & 2nd Floor Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7B	12" x 12" Lt Brown Floor Tile w/Dark Brown Streaks			1st & 2nd Floor Corridors - Abated	ABATED									
7C	12" x 12" Dk. Gray/Orange w/Black & Tan Streaks FT	11,825	SF	Rooms 104, 105, 107, 108, 201-203, 205, 206-208, 210, Library, Principal's Office, Teacher's Lunch Room	CHR	MISC	N	DIST	155		No	ACBM with the potential for damage	5	LOW
7D	12" x 12" Beige Floor Tile w/Dark Green Streaks	1,200	SF	Room 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7E	12" x 12" Gray Floor Tile w/White Streaks	2,250	SF	Rooms 103, 204	CHR	MISC	N	LOC	5		No	ACBM with the potential for damage	5	LOW
8A	9" x 9" White Floor Tile w/Gray Streaks Mastic			Engineer's Office	CHR	MISC								
9A	12" x 12" Gray, White & Tan Floor Tile Mastic	260	SF	1st Floor Corridor, Room 107, & Library	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9B	12" x 12" Lt Brown FT w/Dark Brown Streaks Mastic - Abated			1st & 2nd Floor Corridors	ABATED									
9C	12" x 12" Dk Gray/Orange w/Bk & Tan Strks Mastic	11,825	SF	Rooms 104, 105, 107, and 108, Teacher's Lunch Room, Principal's Office, 201-203, 205-208, Library	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9D	12"x12" Beige Floor Tile w/Dk Green Streaks Mastic	1,200	SF	Room 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9E	12" x 12" Gray Floor Tile w/White Streaks Mastic	1,200	SF	Rooms 204 (Removed from 103)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Boiler Tank Insulation			Boiler Room	NO_ACBM	MISC								
CA	Paperwrap Pipe Insulation Wrap	8	LF	Boy's Washroom	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable		LOW

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												ACBM or friable suspect ACBM		
E	Elbow Insulation	5	LF	Boy's Washroom	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
EA	Paperwrap Pipe Insulation	8	LF	Boy's Washroom Janitor Closet 1st Floor	ASSUMED	TSI	Y	LOC	1		No	Any remaining friable ACBM or friable suspect ACBM	5	LOW
FA	Cardboard Lag	5	LF	Boy's Washroom	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Murray Academy Unit 29221 Building ID 5030

Address 5335 S. Kenwood Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>4/15/2019</u>
Inspector Name	<u>Imani Robinson</u>
<u>100-19716</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
010	
011	
012	
1	
10	No access
11	No access
12	No access
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	Not observed
23	
24	
25	
26	Not observed
28	
35	No access

Chicago Public Schools

School Murray Academy **Unit** 29221 **Building ID** 5030

Address 5335 S. Kenwood **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
35A	No access
36	
36A	
37	
37A	
48	
49	
50	
51	
6A	Not observed
7A	
7B	Not observed
7C	Room 104 (30SF), Room 203 (50 SF), Room 205 (75 SF)
7D	
7E	Room 204 (5 SF)
8A	Not observed
9A	
9B	Not observed
9C	
9D	
9E	Not observed in room 103
A	
CA	Not observed
E	
EA	No access
FA	

Chicago Public Schools

School Murray Academy **Unit** 29221 **Building ID** 5030
Address 5335 S. Kenwood **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Murray Academy
Address 5335 S. Kenwood

Unit 29221
Chicago, IL, 60615

Building ID 5030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
010	12x12 gray with black specks	800	SF	Room 101	Assumed	MISC	No	30	SF	5 ACBM with potential for significant damage	Follow O&M Plan
011	12x12 gray	600	SF	Room 108	Assumed	MISC	No	30	SF	5 ACBM with potential for significant damage	Follow O&M Plan
012	12x12 light grey floor tile	300	SF	West boys bathroom	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Follow O&M Plan
1	Plaster			Throughout Facility	No ACBM	SURFACE					
10	Paperwrap/Aircell Pipe Insulation Wrap	250	LF	In various inaccessible areas throughout facility	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
11	Paperwrap/Aircell Pipe Insulation	250	LF	In various inaccessible areas throughout facility	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
12	Paperwrap/Aircell Pipe Joint Insulation	50	LF	In various inaccessible areas throughout facility	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	Boiler Gaskets			Boiler Room	No ACBM	MISC					
14	Interior Brick			Throughout Building	No ACBM	MISC					
15	Interior Brick Mortar			Throughout Building	No ACBM	MISC					
16	Elbow Wrap			Boy's Bathroom	No ACBM	MISC					
17	Duct Vibration Material			Equipment Room	No ACBM	MISC					
18	Exterior Brick - Not AHERA			Exterior of Building	No ACBM	MISC					
19	Exterior Brick Mortar (Not AHERA)			Exterior of Building	No ACBM	MISC					
20	Exterior Door Caulk - Not AHERA			Building Exterior	No ACBM	MISC					
21	Plaster			Throughout	No ACBM	SURFACE					
22	Green Vinyl Curtain (Cream and brown)			Gym	No ACBM	MISC					
23	12" x 12" Ceiling Tile			Gym, Rm. 210	No ACBM	MISC					
24	Brown Carpet			1st Floor Office	No ACBM	MISC					
25	Brown Carpet Adhesive			1st Floor Office	No ACBM	MISC					
26	Black Felt Door Trim			2nd Floor Fan Room	No ACBM	MISC					
28	Roof Materials (Non-AHERA)			Roof	Assumed	MISC					
35	12" x 12" Blue Floor Tile	25	SF	Room 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35A	12" x 12" Blue Floor Tile Mastic	25	SF	Room 201	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" White Floor Tile	2,500	SF	1st & 2nd Floor Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36A	12" x 12" White Floor Tile Mastic			1st & 2nd Floor Hall	No ACBM	MISC					
37	12" x 12" Yellow Floor Tile	2,500	SF	1st & 2nd Floor Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37A	12" x 12" Yellow Floor Tile Mastic			1st & 2nd Hall	No ACBM	MISC					
48	Blue Carpet Adhesive	400	SF	Office and Principal's Office Rm. 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Murray Academy

Unit 29221

Building ID 5030

Address 5335 S. Kenwood

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
49	Chalk Board and Poster Board Adhesive	150	SF	All Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12x12 light beige with brown spots floor tile	100	SF	Engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12x12 light beige with brown spots floor tile mastic	100	SF	engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6A	9" x 9" White Floor Tile w/Gray Streaks			Engineer's Office	Chrysotile	MISC					
7A	12" x 12" Gray, White & Tan Floor Tile	2,500	SF	1st Floor Corridor, Room 107, & 2nd Floor Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7B	12" x 12" Lt Brown Floor Tile w/Dark Brown Streaks			1st & 2nd Floor Corridors - Abated	Abated						
7C	12" x 12" Dk. Gray/Orange w/Black & Tan Streaks FT	11,825	SF	Rooms 104, 105, 107, 108, 201-203, 205, 206-208, 210, Library, Principal's Office, Teacher's Lunch Room	Chrysotile	MISC	No	155	SF	6 ACBM with the potential for damage	Remove
7D	12" x 12" Beige Floor Tile w/Dark Green Streaks	1,200	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7E	12" x 12" Gray Floor Tile w/White Streaks	2,250	SF	Rooms 103, 204	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Follow O&M Plan
8A	9" x 9" White Floor Tile w/Gray Streaks Mastic			Engineer's Office	Chrysotile	MISC					
9A	12" x 12" Gray, White & Tan Floor Tile Mastic	260	SF	1st Floor Corridor, Room 107, & Library	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9B	12" x 12" Lt Brown FT w/Dark Brown Streaks Mastic - Abated			1st & 2nd Floor Corridors	Abated						
9C	12" x 12" Dk Gray/Orange w/Blk & Tan Strks Mastic	11,825	SF	Rooms 104, 105, 107, and 108, Teacher's Lunch Room, Principal's Office, 201-203, 205-208, Library	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9D	12"x12" Beige Floor Tile w/Dk Green Streaks Mastic	1,200	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9E	12" x 12" Gray Floor Tile w/White Streaks Mastic	1,200	SF	Rooms 204 (Removed from 103)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boiler Tank Insulation			Boiler Room	No ACBM	MISC					
CA	Paperwrap Pipe Insulation Wrap	8	LF	Boy's Washroom	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Elbow Insulation	5	LF	Boy's Washroom	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
EA	Paperwrap Pipe Insulation	8	LF	Boy's Washroom Janitor Closet 1st Floor	Assumed	TSI	Yes	1	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
FA	Cardboard Lag	5	LF	Boy's Washroom	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Murray Academy

Unit 29221

Building ID 5030

Address 5335 S. Kenwood

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	05/04/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
010	Sample to determine asbestos content, remove damaged ACBM
011	Sample to determine asbestos content, remove damaged ACBM
012	Sample to determine asbestos content, remove damaged ACBM
1	
10	
11	

Chicago Public Schools

School Murray Academy

Unit 29221

Building ID 5030

Address 5335 S. Kenwood

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
28	
35	
35A	
36	
36A	
37	
37A	
48	
49	
50	
51	

Chicago Public Schools

School Murray Academy

Unit 29221

Building ID 5030

Address 5335 S. Kenwood

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
6A	
7A	
7B	
7C	Remove damaged materials
7D	
7E	Remove damaged materials
8A	
9A	
9B	
9C	
9D	
9E	
A	
CA	
E	
EA	
FA	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Paperwrap/Aircell Pipe Insulation Wrap		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	In various inaccessible areas throughout facility		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:	No access		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Paperwrap/Aircell Pipe Insulation Wrap		
MATERIAL LOCATION:	In various inaccessible areas throughout facility		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Paperwrap/Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	In various inaccessible areas throughout facility		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:	No access		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Paperwrap/Aircell Pipe Insulation		
MATERIAL LOCATION:	In various inaccessible areas throughout facility		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Paperwrap/Aircell Pipe Joint Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	In various inaccessible areas throughout facility		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:	No access		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Paperwrap/Aircell Pipe Joint Insulation**

MATERIAL LOCATION: **In various inaccessible areas throughout facility**

MATERIAL QUANTITY:	50	MATERIAL UNITS:	LF
--------------------	-----------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13	
MATERIAL DESCRIPTION:	Boiler Gaskets	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Interior Brick		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16	
MATERIAL DESCRIPTION:	Elbow Wrap	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boy's Bathroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Elbow Wrap**

MATERIAL LOCATION: **Boy's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Duct Vibration Material		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Equipment Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Duct Vibration Material**

MATERIAL LOCATION: **Equipment Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18	
MATERIAL DESCRIPTION:	Exterior Brick - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19	
MATERIAL DESCRIPTION:	Exterior Brick Mortar (Not AHERA)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Exterior Brick Mortar (Not AHERA)**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20	
MATERIAL DESCRIPTION:	Exterior Door Caulk - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Building Exterior

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21	
MATERIAL DESCRIPTION:	Plaster	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22	
MATERIAL DESCRIPTION:	Green Vinyl Curtain (Cream and brown)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Green Vinyl Curtain (Cream and brown)**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23	
MATERIAL DESCRIPTION:	12" x 12" Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym, Rm. 210

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile**

MATERIAL LOCATION: **Gym, Rm. 210**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24	
MATERIAL DESCRIPTION:	Brown Carpet	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Brown Carpet**

MATERIAL LOCATION: **1st Floor Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Brown Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Brown Carpet Adhesive**

MATERIAL LOCATION: **1st Floor Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Black Felt Door Trim		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Fan Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Black Felt Door Trim**

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28	
MATERIAL DESCRIPTION:	Roof Materials (Non-AHERA)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Roof Materials (Non-AHERA)**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 201		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	No access		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35A		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 201		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	No access		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA:	35A				
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic				
MATERIAL LOCATION:	Room 201				
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st & 2nd Floor Hall		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **1st & 2nd Floor Hall**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36A	
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Floor Hall

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **36A**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st & 2nd Floor Hall		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**

MATERIAL LOCATION: **1st & 2nd Floor Hall**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37A	
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Hall

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **37A**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **1st & 2nd Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Blue Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office and Principal's Office Rm. 200		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Office and Principal's Office Rm. 200**

MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	Chalk Board and Poster Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Classrooms		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Chalk Board and Poster Board Adhesive**

MATERIAL LOCATION: **All Classrooms**

MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12x12 light beige with brown spots floor tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12x12 light beige with brown spots floor tile**

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12x12 light beige with brown spots floor tile mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	engineer's office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12x12 light beige with brown spots floor tile mastic**

MATERIAL LOCATION: **engineer's office**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6A		
MATERIAL DESCRIPTION:	9" x 9" White Floor Tile w/Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **6A**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Gray Streaks**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7A		
MATERIAL DESCRIPTION:	12" x 12" Gray, White & Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor, Room 107, & 2nd Floor Library		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA:	7A				
MATERIAL DESCRIPTION:	12" x 12" Gray, White & Tan Floor Tile				
MATERIAL LOCATION:	1st Floor Corridor, Room 107, & 2nd Floor Library				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7B		
MATERIAL DESCRIPTION:	12" x 12" Lt Brown Floor Tile w/Dark Brown Streaks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Floor Corridors - Abated

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **7B**

MATERIAL DESCRIPTION: **12" x 12" Lt Brown Floor Tile w/Dark Brown Streaks**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7C		
MATERIAL DESCRIPTION:	12" x 12" Dk. Gray/Orange w/Black & Tan Streaks FT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 104, 105, 107, 108, 201-203, 205, 206-208, 210, Library, Principal's Office, Teacher's Lunch Room		
MATERIAL QUANTITY:	11825	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	155	DAMAGE UNITS:	SF
COMMENTS:	Room 104 (30SF), Room 203 (50 SF), Room 205 (75 SF)		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA:	7C				
MATERIAL DESCRIPTION:	12" x 12" Dk. Gray/Orange w/Black & Tan Streaks FT				
MATERIAL LOCATION:	Rooms 104, 105, 107, 108, 201-203, 205, 206-208, 210, Library, Principal's Office, Teacher's Lunch Room				
MATERIAL QUANTITY:	11825	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	155	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove damaged materials

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7D		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/Dark Green Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 106		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **7D**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Dark Green Streaks**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7E		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile w/White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103, 204		
MATERIAL QUANTITY:	2250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	5	DAMAGE UNITS:	SF
COMMENTS:	Room 204 (5 SF)		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **7E**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks**

MATERIAL LOCATION: **Rooms 103, 204**

MATERIAL QUANTITY: **2250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove damaged materials

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8A		
MATERIAL DESCRIPTION:	9" x 9" White Floor Tile w/Gray Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **8A**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Gray Streaks Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9A		
MATERIAL DESCRIPTION:	12" x 12" Gray, White & Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor, Room 107, & Library		
MATERIAL QUANTITY:	260	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA:	9A				
MATERIAL DESCRIPTION:	12" x 12" Gray, White & Tan Floor Tile Mastic				
MATERIAL LOCATION:	1st Floor Corridor, Room 107, & Library				
MATERIAL QUANTITY:	260	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9B		
MATERIAL DESCRIPTION:	12" x 12" Lt Brown FT w/Dark Brown Streaks Mastic - Abated		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Floor Corridors

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **9B**

MATERIAL DESCRIPTION: **12" x 12" Lt Brown FT w/Dark Brown Streaks Mastic - Abated**

MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9C		
MATERIAL DESCRIPTION:	12" x 12" Dk Gray/Orange w/Blk & Tan Strks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104, 105, 107, and 108, Teacher's Lunch Room, Principal's Office, 201-203, 205-208, Library**

MATERIAL QUANTITY: **11825**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA:	9C				
MATERIAL DESCRIPTION:	12" x 12" Dk Gray/Orange w/Blk & Tan Strks Mastic				
MATERIAL LOCATION:	Rooms 104, 105, 107, and 108, Teacher's Lunch Room, Principal's Office, 201-203, 205-208, Library				
MATERIAL QUANTITY:	11825	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9D		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile w/Dk Green Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 106		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **9D**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/Dk Green Streaks Mastic**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9E		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile w/White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 204 (Removed from 103)		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 103		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **9E**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks Mastic**

MATERIAL LOCATION: **Rooms 204 (Removed from 103)**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A	
MATERIAL DESCRIPTION:	Boiler Tank Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	CA		
MATERIAL DESCRIPTION:	Paperwrap Pipe Insulation Wrap		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boy's Washroom		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:	Not observed		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **CA**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation Wrap**

MATERIAL LOCATION: **Boy's Washroom**

MATERIAL QUANTITY: **8**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Elbow Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boy's Washroom		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Elbow Insulation**

MATERIAL LOCATION: **Boy's Washroom**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	EA		
MATERIAL DESCRIPTION:	Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boy's Washroom Janitor Closet 1st Floor		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	1	DAMAGE UNITS:	LF
COMMENTS:	No access		

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **EA**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Boy's Washroom Janitor Closet 1st Floor**

MATERIAL QUANTITY: **8**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **1**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FA		
MATERIAL DESCRIPTION:	Cardboard Lag		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boy's Washroom		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **FA**

MATERIAL DESCRIPTION: **Cardboard Lag**

MATERIAL LOCATION: **Boy's Washroom**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	011		
MATERIAL DESCRIPTION:	12x12 gray		
MATERIAL LOCATION:	Room 108		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	
AHERA DAMAGE CATEGORY:	5 ACBM with potential for significant damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	30	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **011**

MATERIAL DESCRIPTION: **12x12 gray**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **30**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	012				
MATERIAL DESCRIPTION:	12x12 light grey floor tile				
MATERIAL LOCATION:	West boys bathroom				
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	3	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **012**

MATERIAL DESCRIPTION: **12x12 light grey floor tile**

MATERIAL LOCATION: **West boys bathroom**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Murray Academy	INSPECTION DATE:	4/15/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	010				
MATERIAL DESCRIPTION:	12x12 gray with black specks				
MATERIAL LOCATION:	Room 101				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	HIGH	CONDITION:			
AHERA DAMAGE CATEGORY:	5 ACBM with potential for significant damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	30	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 04/15/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29221	BUILDING ID:	5030
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Murray Academy	REVIEW DATE:	5/4/2019		
ADDRESS:	5335 S. Kenwood	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **010**

MATERIAL DESCRIPTION: **12x12 gray with black specks**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **30**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: _____ Date: **05/04/2019**

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019



Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed