

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3725
SCHOOL NAME: Christopher School
ADDRESS OF SCHOOL: 5042 S. Artesian
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/25/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 358
IDPH INSPECTOR LICENSE NUMBER: 100-05090
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Herman
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Christopher School

5042 S. Artesian
Chicago, IL, 60632

Unit: 30031
Building ID: 2780

IDPH ID Number: 14-016-2990-3725

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 23, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 30031 Region: 04 IDPH ID:14-016-2990-3725

School: Christopher School Building ID: 2780

Address: 5042 S. Artesian
Chicago, IL, 60632

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 05/04/2019

Inspector: Michael Herman Inspector IDPH License: 100-05090
Management Planner: Evan Christian Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 23, 2019

RE: Christopher School, Unit 30031
5042 S. Artesian
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Christopher School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Christopher School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Christopher School
Address: 5042 S. Artesian
IDPH ID: 14-016-2990-3725
Contact:

Unit: 30031
Chicago, IL, 60632
Building ID: 2780
Phone:

Region: 04

2. Description of Facility

Original Construction: 2002
Total Square Footage: 4900
Current Occupancy: 358

Additional Construction:
No of Floors: 1

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, IL, 60607
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Michael Herman

Inspector IDPH license # 100-05090

Signature:
Date: 4/23/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 05/04/2019

7. Review Date: 05/04/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Christopher School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2780:

007 D	12" x 12" Black Floor Tile w/White Streaks
032	12" x 12" Black Floor Tile Mastic
033	12" x 12" Black Floor Tile w/ White Streaks Mastic
038	12" x 12" Off-White FT w/Brown Speckles Mastic
07 I	12" x 12" Off-White Floor Tile w/Brown Speckles
081	9" x 9" Multi-Brown Specked Floor Tile
082	9" x 9" Multi-Brown Specked Floor Tile Mastic
093	Boiler Gaskets
094	Insulation Under Steel Shell of Incinerator

111	2' x 4' Ceiling Tile
90B	Drywall Compound
C	Aircell Pipe Insulation Joints
D	Cardboard Pipe Insulation
F	Pipe Joint Insulation off Fiberglass

B. The following new homogenous areas have been identified for Building 2780:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

002	Burlap
003	Plaster
007 A	12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks
007 B	12" x 12" Beige Floor Tile w/White & Brown Streaks
007 C	12" x 12" Black Floor Tile
007 D	12" x 12" Black Floor Tile w/White Streaks
007 E	12" x 12" Black Floor Tile w/White Specks
007 F	12" x 12" White Floor Tile
007 G	12" x 12" Dk Gray Floor Tile w/Brn & White Streaks
007 H	12" x 12" Light Gray Floor Tile w/White Streaks
007 J	12" x 12" Cream Floor Tile w/ Brown & Gray Streaks
007 K	12"x12" Dk Gray Floor Tile w/Black & Gray Streaks
009	12" x 12" Ceiling Tiles
01	Hard Coat Plaster
028	9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic
040	12" x 12" Cream Floor Tile w/Brown & Gray Mastic
044	Cinder Block - New Construction
045	Cinder Block Mortar - New Construction
046	Rubber Flooring
047	4" Black Baseboard
048	4" Black Baseboard Mastic
049	6" Black Baseboard
050	6" Black Baseboard Mastic
053	Finished (Glazed) Brick Mortar
054	Terrazzo Wall Panels
055	Non-skid Strips
066	12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic
067	Non - Skid Strips
068	Ceramic Tile Grout
069	Grout Between Floor & Wall
07 I	12" x 12" Off-White Floor Tile w/Brown Speckles
070	Ceramic Tile Grout in Pool
071	Gray Baseboard
072	Gray Baseboard Mastic
073	Ceiling Panel Material
074	Insulation Above Ceiling Panels

078	Terrazzo Sink
079	2' x 2' Ceiling Panels
080	Insulation in Safe Door
083	12" x 12" Multi-Brown Streaked Floor Tile
084	12" x 12" Multi-Brown Streaked Floor Tile Mastic
085	Dark Gray Linoleum
086	Dark Gray Linoleum Mastic
087	2' x 4' Lay-In Ceiling Panels
088	Dark Gray Baseboard
089	Dark Gray Baseboard Mastic
090	Drywall
091	White and Light Blue Linoleum
092	White and Light Blue Linoleum Mastic
093	Boiler Gaskets
094	Insulation Under Steel Shell of Incinerator
095	12" x 12" White w/Gray Specks Floor Tile
096	12" x 12" White w/Gray Specks Floor Tile Mastic
097	4" Beige Baseboard
098	4" Beige Baseboard Adhesive
099	2' x 2' White Fissured Ceiling Tile
100	12"x12" Gray and Cream Speckled Floor Tile
101	12"x12" Gray and Cream Speckled Floor Tile-Mastic
102	12"x12" Brown Floor Tile
103	12"x12" Brown Floor Tile Mastic
104	12x12 Light BrownFT with Dark Brown & White
105	Mastic associated with 12x12Light Brown FT with Dark Brown & White
106	Cream with Light Brown Linoleum
107	Adhesive associated with Cream with Light Brown Linoleum
108	12"X12" Blue W/Gray White Streaks VFT
109	12"X12" Blue W/Gray & White Streaks VFT Mastic
111	2' x 4' Ceiling Tile
90A	Drywall Tape
90B	Drywall Compound

The following areas were deemed to be inaccessible:

018	9" x 9" Red w/White Streaks Floor Tile Mastic
020	9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic
021	9" x 9" Light Brown Speckled Floor Tile Mastic
022	9" x 9" Medium Brown Speckled Floor Tile Mastic
023	9" x 9" Dark Brown Speckled Floor Tile Mastic
024	9" x 9" Lt Brn w/Dk Brown & White Spots FT

	Mastic
026	9" x 9" Rusty Brown Speckled Floor Tile Mastic
030	12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks
	Mastic
032	12" x 12" Black Floor Tile Mastic
034	12" x 12" Black Floor Tile w/White Specks Mastic
039	12"x12"Cream Floor Tile w/(Lt) Brown & Gray
	Mastic
040	12" x 12" Cream Floor Tile w/Brown & Gray
	Mastic
048	4" Black Baseboard Mastic
050	6" Black Baseboard Mastic
066	12" x 12" Dk Gray FT w/Black & Gray Streaks
	Mastic
076	Linoleum Like Material Mastic
079	2' x 2' Ceiling Panels
080	Insulation in Safe Door
084	12" x 12" Multi-Brown Streaked Floor Tile Mastic
086	Dark Gray Linoleum Mastic
088	Dark Gray Baseboard
089	Dark Gray Baseboard Mastic
093	Boiler Gaskets
094	Insulation Under Steel Shell of Incinerator
100	12"x12" Gray and Cream Speckled Floor Tile
101	12"x12" Gray and Cream Speckled Floor Tile-
	Mastic
103	12"x12" Brown Floor Tile Mastic
105	Mastic associated with 12x12Light Brown FT with
	Dark Brown & White
107	Adhesive associated with Cream with Light Brown
	Linoleum
109	12"X12" Blue W/Gray & White Streaks VFT Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Herman, IDPH License # 100-05090. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Christopher School Building 2780 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Christopher School **Unit** 30031 **Building ID** 2780

Address 5042 S. Artesian **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	2' x 4' Ceiling Panels			Throughout Facility	NO_ACBM	MISC								
002	Burlap	50,000	SF	On Walls Throughout Facility	ASSUMED	MISC	N	DIST	20		No	ACBM with the potential for damage	5	LOW
003	Plaster	100,000	SF	Throughout Original Construction	ASSUMED	SURFACE	N	DIST	30		No	ACBM with the potential for damage	5	LOW
004	2' x 2' Ceiling Panels - ABATED			Gym	ABATED	MISC								
005	2' x 4' Ceiling Panels			Throughout Facility	NO_ACBM	MISC								
006 A	9"x9" Dark Brown Floor Tile w/ Red & White Streaks	2,500	SF	Computer Room, Science Lab (125-A), Office, 104, 133, 135, Principal's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 B	9"x9" Light Brown Floor Tile w/ Dark Brown Streaks			Science Lab and Office	CHR	MISC								
006 C	9" x 9" Black Floor Tile w/ White Streaks			Science Lab, Hall, Speech, Cafeteria, Rooms 104, 106, 116, 117, 126	CHR	MISC								
006 D	9" x 9" Light Brown Floor Tile w/White Streaks	1,000	SF	Hallways on 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 E	9" x 9" Green Floor Tile w/ White Streaks	1,000	SF	Hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 F	9" x 9" Gray FT w/Red, Yellow, Blue, & White Dots			Rooms 116, 117, 125 and 127	CHR	MISC								
006 G	9" x 9" Red Floor Tile w/White Streaks			Hallways on 1st Floor and Rooms 104, 129	CHR	MISC								
006 H	9"x9 Light Brown FT w/ Blue, Red, Yel & White Dots			Room 123	CHR	MISC		None						
006 I	9" x 9" Light Brn w/Brn & White Streaks Floor Tile			Rooms 122, 123, 126 and as Patches in the Cafeteria	CHR	MISC								
006 K	9" x 9" Medium Brown Speckled Floor Tile			Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	CHR	MISC								
006 L	9" x 9" Dark Brown Speckled Floor Tile	800	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 M	9" x 9" Light Brown FT w/ Dark Brown & White Spots			Women's Teacher's Lounge, Rooms 101,	CHR	MISC								

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				113, 115, 122, 123, and 126										
006 N	9" x 9" Beige Floor Tile w/Brown & White Streaks			Cafeteria, Hall between Mobile Units, 103, Physical Therapy, Office, 122, 123, 126, 133, 135	CHR	MISC								
006 O	9" x 9" Rusty Brown Speckled Floor Tile	200	SF	Cafeteria, Rooms 103, 104, 124, and 126, 138 Computer Lab	CHR	MISC	Y	DIST	25		No	ACBM with the potential for damage	3	LOW
006 P	9" x 9" White Floor Tile w/ Black Streaks			Kitchen	CHR	MISC		None						
006 Q	9" x 9" Gray Floor Tile w/White & Brown Streaks			Room 130	CHR	MISC								
006 R	9" x 9" Lt Brn Floor Tile w/Dk Brown & White Spots			Room 113	CHR	MISC		None						High
006 S	9" x 9" Multi-Brown Speckled Floor Tile	700	SF	Room 111	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 A	12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks	75	SF	Custodians Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 B	12" x 12" Beige Floor Tile w/White & Brown Streaks	750	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 C	12" x 12" Black Floor Tile			Room 123	ASSUMED	MISC								
007 D	12" x 12" Black Floor Tile w/White Streaks	150	SF	Speech, Entrance by 127, Room 126	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
007 E	12" x 12" Black Floor Tile w/White Specks	350	SF	Speech, Cafeteria, Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 F	12" x 12" White Floor Tile	100	SF	Teachers Lounge, Speech	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 G	12" x 12" Dk Gray Floor Tile w/Brn & White Streaks	25	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 H	12" x 12" Light Gray Floor Tile w/White Streaks	100	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 J	12" x 12" Cream Floor Tile w/ Brown & Gray Streaks	300	SF	Boy's and Girl's Locker Room, Pool Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 K	12"x12" Dk Gray Floor Tile w/Black & Gray Streaks	900	SF	Room 130	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008 A	Linoleum (Lt Green Patterned)			Room 129 - NOT OBSERVED	CHR	MISC								
008 B	Linoleum (Lt Brown Patterned)	100	SF	Women's Washroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008 C	Beige Patterned Linoleum			Physical Therapy	CHR	MISC								

Chicago Public Schools

School Christopher School **Unit** 30031 **Building ID** 2780

Address 5042 S. Artesian **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room										
008 D	Linoleum (Yellow Patterned)	100	SF	Washroom Across From Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
009	12" x 12" Ceiling Tiles	80	SF	Assembly Hall on Walls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01	Hard Coat Plaster	100,000	SF	Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
010	Block			Boiler Room	NO_ACBM	MISC								
011	Block Mortar	250	SF	Boiler Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
012	9"x9" Dark Brown FT w/ Red & White Streaks Mastic	2,500	SF	Computer Room, Science Room (125-A), Office, Principal's Office, Rooms 133, 135	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
013	9" x 9" Light Brown FT w/Dk Brown Streaks Mastic			Science Lab and Office	CHR	MISC								
014	9" x 9" Black Floor Tile w/White Streaks Mastic	1,000	SF	Rooms 104, 106, 116, 117, 125-A, Hall, Speech and as Patches in the Cafeteria, Science Lab	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
015	9" x 9" Lt Brown FT w/White Streaks Mastic	1,000	SF	Hallways on 1st Floor	CHR	MISC	N	LOC	0		No	ACBM with the potential for damage	3	LOW
016	9" x 9" Green FT w/White Streaks Mastic	1,000	SF	Hallways on 1st Floor	CHR	MISC	Y	LOC			No	ACBM with the potential for damage	3	LOW
017	9"x9" Gray w/Red,Yel, Blue & White Dots FT Mastic			Rooms 116, 117 and 125/127	CHR	MISC								
018	9" x 9" Red w/White Streaks Floor Tile Mastic	1,000	SF	Rooms 104 and 129 and Hallways on 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
019	9"x9" Lt Brn w/Blue, Red, Yel, & Wh Dots FT Mastic			Room123	CHR	MISC		None						Low
020	9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic	20	SF	Rooms 122, 123, 126 and as Patches in the Cafeteria	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021	9" x 9" Light Brown Speckled Floor Tile Mastic	700	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022	9" x 9" Medium Brown Speckled Floor Tile Mastic	1,500	SF	103-109, 124, 126, 127, 129,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Christopher School **Unit** 30031 **Building ID** 2780

Address 5042 S. Artesian **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy										
023	9" x 9" Dark Brown Speckled Floor Tile Mastic	800	SF	103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
024	9" x 9" Lt Brn w/Dk Brown & White Spots FT Mastic	700	SF	Rooms 113, 115, 122, 123, 126 and Women's Teacher's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
025	9" x 9" Beige w/Brown & White Streaks FT Mastic	800	SF	Rooms 103, 122, and 126, 133, 135 Office, Physical Therapy, Cafeteria, and Hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
026	9" x 9" Rusty Brown Speckled Floor Tile Mastic	200	SF	Rooms 103, 104, 124, and 126, 138, Technology Room and the Cafeteria	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
027	9" x 9" White w/Black Streaks Floor Tile Mastic			Kitchen	CHR	MISC		None						Low
028	9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic			Room 128-(Number Has Been Changed From 130)	ASSUMED	MISC								
029	9"x9" Lt. Brn FT w/Dark Brown & White Spots Mastic			Room 113	CHR	MISC		None						Low
030	12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks Mastic	200	SF	Custodian's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
031	12" x 12" Beige FT w/ Wh & Brown Streaks Mastic	1,600	SF	Assembly Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
032	12" x 12" Black Floor Tile Mastic	600	SF	Room 123	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
033	12" x 12" Black Floor Tile w/ White Streaks Mastic	200	SF	Speech, Entrance by 127, Room 126	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
034	12" x 12" Black Floor Tile w/White Specks Mastic	350	SF	Speech, Cafeteria, Assembly Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
035	12" x 12" White Floor Tile Mastic			Speech, Teacher's Lounge	CHR	MISC								
036	12"x12" Dark Gray FT w/Brown & White Strks Mastic			Cafeteria	CHR	MISC		None						Low

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
037	12" x 12" Light Gray FT w/White Streaks Mastic			Cafeteria	CHR	MISC		None						Low
038	12" x 12" Off-White FT w/Brown Speckles Mastic	500	SF	Cafeteria, Boy's Washroom, Room 108	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
039	12"x12"Cream Floor Tile w/(Lt) Brown & Gray Mastic	300	SF	Girl's and Boy's Locker Room, Pool Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
040	12" x 12" Cream Floor Tile w/Brown & Gray Mastic	300	SF	Girl's and Boy's Locker Room, Pool Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
041	Interior Brick Mortar			Throughout Building	NO_ACBM	MISC								
042	Black Border Tiles	1,000	SF	Throughout Building halls on 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
043	Black Border Tile Mastic	1,000	SF	Throughout Building Halls on 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
044	Cinder Block - New Construction	4,000	SF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
045	Cinder Block Mortar - New Construction	40,000	SF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
046	Rubber Flooring	3,550	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
047	4" Black Baseboard	1,000	LF	Gym, Boy's and Girl's Locker Room throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
048	4" Black Baseboard Mastic	1,000	SF	Gym, Boy's and Girl's Locker Room Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
049	6" Black Baseboard	250	LF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
050	6" Black Baseboard Mastic	250	LF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
051	Spray-on Material			Attic	NO_ACBM	MISC								
052	Plaster			Attic	NO_ACBM	SURFACE								
053	Finished (Glazed) Brick Mortar	200,000	LF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
054	Terrazzo Wall Panels	400	SF	Boys and Women's Washroom, Room 129	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
055	Non-skid Strips	100	SF	Women's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
056	Exterior Brick - Not AHERA			Exterior of Building - Original Construction	NO_ACBM	MISC								
057	Exterior Brick Mortar - Not AHERA			Exterior of Building - Original Construction	NO_ACBM	MISC								
058	Exterior Door Caulk - Not AHERA)			Exterior of All Doors in Original Construction	CHR									
059	Cinder Block in Original Construction			Throughout Basement	NO_ACBM	MISC								
060	Cinderblock Mortar - Original Construction			Throughout Basement	NO_ACBM	MISC								
061	2' x 4' Ceiling Panels			Throughout Building	NO_ACBM	MISC								
062	Exterior Window Caulk - Not AHERA			Exterior of Building - Original Building	CHR	MISC								
063	Exterior Brick - Not AHERA			Exterior of New Addition	NO_ACBM	MISC								
064	Exterior Brick Mortar - Not AHERA			Exterior of New Addition	NO_ACBM	MISC								
065	Exterior Door Caulk - Not AHERA			Exterior of New Addition	CHR	MISC								
066	12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic	900	SF	Room 130	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
067	Non - Skid Strips	100	SF	Boy's and Girl's Locker Room, Pool Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
068	Ceramic Tile Grout	800	SF	Pool Deck	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
069	Grout Between Floor & Wall	400	SF	Pool Deck	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
071	12" x 12" Off-White Floor Tile w/Brown Speckles	500	SF	Cafeteria, Boys Washroom, Room 108	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
070	Ceramic Tile Grout in Pool	1,000	SF	Pool	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
071	Gray Baseboard			Room 130	ASSUMED	MISC		None						Low
072	Gray Baseboard Mastic			Room 130	ASSUMED	MISC		None						Low
073	Ceiling Panel Material			Room 130	ASSUMED	MISC		None						Low
074	Insulation Above Ceiling Panels			Room 130	ASSUMED	MISC		None						Low
075	Linoleum Like Flooring Material	10	SF	Storage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
076	Linoleum Like Material Mastic	10	SF	Storage	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
077	Vibration Absorbers			Attic	NO_ACBM	MISC		None						Moderate
078	Terrazzo Sink			Boy's Washroom	ASSUMED	MISC								
079	2' x 2' Ceiling Panels	3,600	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
080	Insulation in Safe Door	32	SF	Hallway Across From Assembly Hall	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
081	9" x 9" Multi-Brown Specked Floor Tile	700	SF	Room 111	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
082	9" x 9" Multi-Brown Specked Floor Tile Mastic	700	SF	Room 111	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
083	12" x 12" Multi-Brown Streaked Floor Tile	500	SF	Room 132	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
084	12" x 12" Multi-Brown Streaked Floor Tile Mastic	500	SF	Room 132	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
085	Dark Gray Linoleum	400	SF	Outside Hall by Rooms 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
086	Dark Gray Linoleum Mastic	400	SF	Hall outside Rooms 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
087	2' x 4' Lay-In Ceiling Panels	1,000	SF	Room 180/181 and as Patch in Exit by Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
088	Dark Gray Baseboard	250	SF	Room 401, 403, 405, 407 and Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
089	Dark Gray Baseboard Mastic	250	SF	Room 401, 403, 405, 407, Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
090	Drywall	2,600	SF	New Building 401, 403, 405, 407 and Hall, Unisex Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
091	White and Light Blue Linoleum	1,600	SF	Rooms 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
092	White and Light Blue Linoleum Mastic	1,600	SF	Rooms 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
093	Boiler Gaskets	50	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
094	Insulation Under Steel Shell of Incinerator	100	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
095	12" x 12" White w/Gray Specks Floor Tile	3,900	SF	New Annex - Rooms 302 - 309,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Changing Room and Laundry Room, Halls on 1st Floor										
096	12" x 12" White w/Gray Specks Floor Tile Mastic	3,900	SF	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, and Halls on 1st Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
097	4" Beige Baseboard	800	LF	New Annex - All Rooms except Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
098	4" Beige Baseboard Adhesive	800	LF	New Annex - All Rooms except Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
099	2' x 2' White Fissured Ceiling Tile	4,000	SF	New Annex - All Rooms, 1st Floor Hall	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
100	12"x12" Gray and Cream Speckled Floor Tile	3,600	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	12"x12" Gray and Cream Speckled Floor Tile-Mastic	3,600	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	12"x12" Brown Floor Tile	120	SF	Auditorium, Stairs, Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	12"x12" Brown Floor Tile Mastic	300	SF	Auditorium, Stairs, Landing, Engineer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12x12 Light BrownFT with Dark Brown & White	3,000	SF	Rooms 111, 103, 132, 135, 136, 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	Mastic associated with 12x12Light Brown FT with Dark Brown & White	3,000	SF	Rooms 111, 103, 132, 135, 136, 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	Cream with Light Brown Linoleum	750	SF	Washrooms across from 129/131	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	Adhesive associated with Cream with Light Brown Linoleum	750	SF	Washrooms across from room 129/131	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12"X12" Blue W/Gray White Streaks VFT	11,000	SF	Room 113,116,117 /119,121/123, 143,101,105,107,10 9,125, 127,128,137,141, cafeteria lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12"X12" Blue W/Gray & White Streaks VFT Mastic	11,000	SF	Room 113,116,117 /119,121/123, 143,101,105,107,10 9,125, 127,128,137,141,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
111	2' x 4' Ceiling Tile	11,000	SF	cafeteria lounge Rooms 113, 116, 117/119, 121/123, 143, 101, 105, 107, 109, 125, 127, 128, 137, 141, Cafeteria Lounge, Lunch Room, Teacher's Lounge	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
90A	Drywall Tape	250	SF	Addition for 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90B	Drywall Compound	250	LF	Addition for 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
B	Aircell Pipe Insulation	1,500	LF	Tunnel, Basement, Crawl Spaces	CHR	TSI	Y	LOC	100		No	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
C	Aircell Pipe Insulation Joints	50	LF	Basement, Tunnel, Crawl Spaces	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Cardboard Pipe Insulation	35	LF	Tunnel / Kitchen Storage Room	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Cardboard Pipe Insulation Joints			Tunnel/Kitchen Storage	NO_ACBM	MISC								
F	Pipe Joint Insulation off Fiberglass	10	LF	Tunnel, Kitchen Storage Room	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Boiler Insulation - ABATED				ABATED	TSI								
H	Tank Insulation - ABATED				ABATED	TSI								
I	Aircell Pipe Wrap (Jacketing)	1,500	LF	Tunnel, Basement, Crawl Spaces, Maintenance Areas	CHR	TSI	Y	LOC	100		No	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
J	Fiberglass Pipe Insulation			Tunnel	NO_ACBM	TSI								

Chicago Public Schools

School Christopher School **Unit** 30031 **Building ID** 2780
Address 5042 S. Artesian **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>4/23/2019</u>
Inspector Name <u>Michael Herman</u>
<u>100-05090</u> <u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	
002	Damage located in various areas throughout building
003	Damage located in various areas throughout building
004	
005	
006 A	
006 B	Not observed
006 C	Not observed
006 D	Minor Damage throughout school hallways
006 E	Minor Damage throughout school hallways
006 F	Not observed
006 G	Not observed
006 H	Not observed
006 I	Not observed
006 K	Not observed
006 L	
006 M	Not observed
006 N	Not observed
006 O	
006 P	Not observed
006 Q	Not observed
006 R	
006 S	

Chicago Public Schools

School Christopher School **Unit** 30031 **Building ID** 2780
Address 5042 S. Artesian **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
007 A	
007 B	
007 C	Not observed
007 D	
007 E	
007 F	
007 G	
007 H	
007 J	
007 K	
008 A	Not observed
008 B	
008 C	Not observed
008 D	
009	
01	
010	
011	
012	
013	Not observed
014	
015	
016	
017	Not observed
018	
019	Not observed
020	
021	
022	

Chicago Public Schools

School Christopher School **Unit** 30031 **Building ID** 2780
Address 5042 S. Artesian **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
023	
024	
025	
026	
027	Not observed
028	Not observed
029	Not observed
030	
031	
032	
033	
034	
035	Not observed
036	Not observed
037	Not observed
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	

Chicago Public Schools

School Christopher School **Unit** 30031 **Building ID** 2780
Address 5042 S. Artesian **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
052	
053	
054	
055	
056	
057	
058	
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	Not observed
072	Not observed
073	Not observed
074	Not observed
075	
076	
077	
078	Not observed
079	

Chicago Public Schools

School Christopher School **Unit** 30031 **Building ID** 2780
Address 5042 S. Artesian **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
080	
081	
082	
083	
084	
085	
086	
087	
088	
089	
090	
091	
092	
093	
094	
095	
096	
097	
098	
099	
100	
101	
102	
103	
104	
105	
106	
107	
108	

Chicago Public Schools

School Christopher School **Unit** 30031 **Building ID** 2780
Address 5042 S. Artesian **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
109	
111	
90A	
90B	
B	Damaged ACBM is located in unexcavated crawlspaces. Access is restricted and areas secured.
C	
D	
E	
F	
G	
H	
I	Damaged Materials are located in uncavated crawlspaces, and secured from access
J	

Table II

Management Planner's Review

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	2' x 4' Ceiling Panels			Throughout Facility	No ACBM	MISC					
002	Burlap	50,000	SF	On Walls Throughout Facility	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Follow O&M Plan
003	Plaster	100,000	SF	Throughout Original Construction	Assumed	SURFACE	No	30	SF	6 ACBM with the potential for damage	Repair
004	2' x 2' Ceiling Panels - ABATED			Gym	Abated	MISC					
005	2' x 4' Ceiling Panels			Throughout Facility	No ACBM	MISC					
006 A	9"x9" Dark Brown Floor Tile w/ Red & White Streaks	2,500	SF	Computer Room, Science Lab (125-A), Office, 104, 133, 135, Principal's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006 B	9"x9" Light Brown Floor Tile w/ Dark Brown Streaks			Science Lab and Office	Chrysotile	MISC					
006 C	9" x 9" Black Floor Tile w/ White Streaks			Science Lab, Hall, Speech, Cafeteria, Rooms 104, 106, 116, 117, 126	Chrysotile	MISC					
006 D	9" x 9" Light Brown Floor Tile w/White Streaks	1,000	SF	Hallways on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006 E	9" x 9" Green Floor Tile w/ White Streaks	1,000	SF	Hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006 F	9" x 9" Gray FT w/Red, Yellow, Blue, & White Dots			Rooms 116, 117, 125 and 127	Chrysotile	MISC					
006 G	9" x 9" Red Floor Tile w/White Streaks			Hallways on 1st Floor and Rooms 104, 129	Chrysotile	MISC					
006 H	9"x9 Light Brown FT w/ Blue, Red, Yel & White Dots			Room 123	Chrysotile	MISC					
006 I	9" x 9" Light Brn w/Brn & White Streaks Floor Tile			Rooms 122, 123, 126 and as Patches in the Cafeteria	Chrysotile	MISC					
006 K	9" x 9" Medium Brown Speckled Floor Tile			Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	Chrysotile	MISC					
006 L	9" x 9" Dark Brown Speckled Floor Tile	800	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006 M	9" x 9" Light Brown FT w/ Dark Brown & White Spots			Women's Teacher's Lounge, Rooms 101, 113, 115, 122, 123, and 126	Chrysotile	MISC					
006 N	9" x 9" Beige Floor Tile w/Brown & White Streaks			Cafeteria, Hall between Mobile Units, 103, Physical Therapy, Office, 122, 123, 126, 133, 135	Chrysotile	MISC					
006 O	9" x 9" Rusty Brown Speckled Floor Tile	200	SF	Cafeteria, Rooms 103, 104, 124, and 126, 138 Computer Lab	Chrysotile	MISC	Yes	25	SF	6 ACBM with the potential for damage	Follow O&M Plan
006 P	9" x 9" White Floor Tile w/ Black Streaks			Kitchen	Chrysotile	MISC					

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
006 Q	9" x 9" Gray Floor Tile w/White & Brown Streaks			Room 130	Chrysotile	MISC					
006 R	9" x 9" Lt Brn Floor Tile w/Dk Brown & White Spots			Room 113	Chrysotile	MISC					
006 S	9" x 9" Multi-Brown Specked Floor Tile	700	SF	Room 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 A	12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks	75	SF	Custodians Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 B	12" x 12" Beige Floor Tile w/White & Brown Streaks	750	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 C	12" x 12" Black Floor Tile			Room 123	Assumed	MISC					
007 D	12" x 12" Black Floor Tile w/White Streaks	150	SF	Speech, Entrance by 127, Room 126	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 E	12" x 12" Black Floor Tile w/White Specks	350	SF	Speech, Cafeteria, Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 F	12" x 12" White Floor Tile	100	SF	Teachers Lounge, Speech	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 G	12" x 12" Dk Gray Floor Tile w/Brn & White Streaks	25	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 H	12" x 12" Light Gray Floor Tile w/White Streaks	100	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 J	12" x 12" Cream Floor Tile w/ Brown & Gray Streaks	300	SF	Boy's and Girl's Locker Room, Pool Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 K	12"x12" Dk Gray Floor Tile w/Black & Gray Streaks	900	SF	Room 130	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008 A	Linoleum (Lt Green Patterned)			Room 129 - NOT OBSERVED	Chrysotile	MISC					
008 B	Linoleum (Lt Brown Patterned)	100	SF	Women's Washroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008 C	Beige Patterned Linoleum			Physical Therapy Room	Chrysotile	MISC					
008 D	Linoleum (Yellow Patterned)	100	SF	Washroom Across From Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
009	12" x 12" Ceiling Tiles	80	SF	Assembly Hall on Walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01	Hard Coat Plaster	100,000	SF	Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
010	Block			Boiler Room	No ACBM	MISC					
011	Block Mortar	250	SF	Boiler Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
012	9"x9" Dark Brown FT w/ Red & White Streaks Mastic	2,500	SF	Computer Room, Science Room (125-A), Office, Principal's Office, Rooms 133, 135	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
013	9" x 9" Light Brown FT w/Dk Brown Streaks Mastic			Science Lab and Office	Chrysotile	MISC					
014	9" x 9" Black Floor Tile w/White Streaks Mastic	1,000	SF	Rooms 104, 106, 116, 117, 125-A, Hall, Speech and as Patches in the Cafeteria, Science Lab	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
015	9" x 9" Lt Brown FT w/White Streaks Mastic	1,000	SF	Hallways on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
016	9" x 9" Green FT w/White Streaks Mastic	1,000	SF	Hallways on 1st Floor	Chrysotile	MISC	Yes		SF	6 ACBM with the potential for damage	Follow O&M Plan
017	9"x9" Gray w/Red,Yel, Blue & White Dots FT Mastic			Rooms 116, 117 and 125/127	Chrysotile	MISC					
018	9" x 9" Red w/White Streaks Floor Tile Mastic	1,000	SF	Rooms 104 and 129 and Hallways on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
019	9"x9" Lt Brn w/Blue, Red, Yel, & Wh Dots FT Mastic			Room123	Chrysotile	MISC					
020	9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic	20	SF	Rooms 122, 123, 126 and as Patches in the Cafeteria	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021	9" x 9" Light Brown Speckled Floor Tile Mastic	700	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022	9" x 9" Medium Brown Speckled Floor Tile Mastic	1,500	SF	103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023	9" x 9" Dark Brown Speckled Floor Tile Mastic	800	SF	103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024	9" x 9" Lt Brn w/Dk Brown & White Spots FT Mastic	700	SF	Rooms 113, 115, 122, 123, 126 and Women's Teacher's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
025	9" x 9" Beige w/Brown & White Streaks FT Mastic	800	SF	Rooms 103, 122, and 126, 133, 135 Office, Physical Therapy, Cafeteria, and Hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
026	9" x 9" Rusty Brown Speckled Floor Tile Mastic	200	SF	Rooms 103, 104, 124, and 126, 138, Technology Room and the Cafeteria	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
027	9" x 9" White w/Black Streaks Floor Tile Mastic			Kitchen	Chrysotile	MISC					
028	9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic			Room 128-(Number Has Been Changed From 130)	Assumed	MISC					
029	9"x9" Lt. Brn FT w/Dark Brown & White Spots Mastic			Room 113	Chrysotile	MISC					
030	12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks Mastic	200	SF	Custodian's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
031	12" x 12" Beige FT w/ Wh & Brown Streaks Mastic	1,600	SF	Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
032	12" x 12" Black Floor Tile Mastic	600	SF	Room 123	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
033	12" x 12" Black Floor Tile w/ White Streaks Mastic	200	SF	Speech, Entrance by 127, Room 126	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
034	12" x 12" Black Floor Tile w/White Specks Mastic	350	SF	Speech, Cafeteria, Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
035	12" x 12" White Floor Tile Mastic			Speech, Teacher's Lounge	Chrysotile	MISC					
036	12"x12" Dark Gray FT w/Brown & White Strks Mastic			Cafeteria	Chrysotile	MISC					
037	12" x 12" Light Gray FT w/White Streaks Mastic			Cafeteria	Chrysotile	MISC					
038	12" x 12" Off-White FT w/Brown Speckles Mastic	500	SF	Cafeteria, Boy's Washroom, Room 108	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
039	12"x12"Cream Floor Tile w/(Lt) Brown & Gray Mastic	300	SF	Girl's and Boy's Locker Room, Pool Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
040	12" x 12" Cream Floor Tile w/Brown & Gray Mastic	300	SF	Girl's and Boy's Locker Room, Pool Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
041	Interior Brick Mortar			Throughout Building	No ACBM	MISC					
042	Black Border Tiles	1,000	SF	Throughout Building halls on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
043	Black Border Tile Mastic	1,000	SF	Throughout Building Halls on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
044	Cinder Block - New Construction	4,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
045	Cinder Block Mortar - New Construction	40,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
046	Rubber Flooring	3,550	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
047	4" Black Baseboard	1,000	LF	Gym, Boy's and Girl's Locker Room throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
048	4" Black Baseboard Mastic	1,000	SF	Gym, Boy's and Girl's Locker Room Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
049	6" Black Baseboard	250	LF	Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
050	6" Black Baseboard Mastic	250	LF	Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
051	Spray-on Material			Attic	No ACBM	MISC					
052	Plaster			Attic	No ACBM	SURFACE					
053	Finished (Glazed) Brick Mortar	200,000	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
054	Terrazzo Wall Panels	400	SF	Boys and Women's Washroom, Room 129	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
055	Non-skid Strips	100	SF	Women's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
056	Exterior Brick - Not AHERA			Exterior of Building - Original Construction	No ACBM	MISC					
057	Exterior Brick Mortar - Not AHERA			Exterior of Building - Original Construction	No ACBM	MISC					

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
058	Exterior Door Caulk - Not AHERA)			Exterior of All Doors in Original Construction	Chrysotile						
059	Cinder Block in Original Construction			Throughout Basement	No ACBM	MISC					
060	Cinderblock Mortar - Original Construction			Throughout Basement	No ACBM	MISC					
061	2' x 4' Ceiling Panels			Throughout Building	No ACBM	MISC					
062	Exterior Window Caulk - Not AHERA			Exterior of Building - Original Building	Chrysotile	MISC					
063	Exterior Brick - Not AHERA			Exterior of New Addition	No ACBM	MISC					
064	Exterior Brick Mortar - Not AHERA			Exterior of New Addition	No ACBM	MISC					
065	Exterior Door Caulk - Not AHERA			Exterior of New Addition	Chrysotile	MISC					
066	12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic	900	SF	Room 130	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
067	Non - Skid Strips	100	SF	Boy's and Girl's Locker Room, Pool Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
068	Ceramic Tile Grout	800	SF	Pool Deck	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
069	Grout Between Floor & Wall	400	SF	Pool Deck	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
070	12" x 12" Off-White Floor Tile w/Brown Speckles	500	SF	Cafeteria, Boys Washroom, Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
071	Ceramic Tile Grout in Pool	1,000	SF	Pool	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
072	Gray Baseboard			Room 130	Assumed	MISC					Follow O&M Plan
073	Gray Baseboard Mastic			Room 130	Assumed	MISC					
074	Ceiling Panel Material			Room 130	Assumed	MISC					
075	Insulation Above Ceiling Panels			Room 130	Assumed	MISC					
076	Linoleum Like Flooring Material	10	SF	Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
077	Linoleum Like Material Mastic	10	SF	Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
078	Vibration Absorbers			Attic	No ACBM	MISC					
079	Terrazzo Sink			Boy's Washroom	Assumed	MISC					
080	2' x 2' Ceiling Panels	3,600	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
081	Insulation in Safe Door	32	SF	Hallway Across From Assembly Hall	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
082	9" x 9" Multi-Brown Specked Floor Tile	700	SF	Room 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
083	9" x 9" Multi-Brown Specked Floor Tile Mastic	700	SF	Room 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
084	12" x 12" Multi-Brown Streaked Floor Tile	500	SF	Room 132	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
085	12" x 12" Multi-Brown Streaked Floor Tile Mastic	500	SF	Room 132	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
086	Dark Gray Linoleum	400	SF	Outside Hall by Rooms 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
086	Dark Gray Linoleum Mastic	400	SF	Hall outside Rooms 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
087	2' x 4' Lay-In Ceiling Panels	1,000	SF	Room 180/181 and as Patch in Exit by Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
088	Dark Gray Baseboard	250	SF	Room 401, 403, 405, 407 and Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
089	Dark Gray Baseboard Mastic	250	SF	Room 401, 403, 405, 407, Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
090	Drywall	2,600	SF	New Building 401, 403, 405, 407 and Hall, Unisex Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
091	White and Light Blue Linoleum	1,600	SF	Rooms 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
092	White and Light Blue Linoleum Mastic	1,600	SF	Rooms 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
093	Boiler Gaskets	50	LF	Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
094	Insulation Under Steel Shell of Incinerator	100	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
095	12" x 12" White w/Gray Specks Floor Tile	3,900	SF	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, Halls on 1st Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
096	12" x 12" White w/Gray Specks Floor Tile Mastic	3,900	SF	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, and Halls on 1st Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
097	4" Beige Baseboard	800	LF	New Annex - All Rooms except Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
098	4" Beige Baseboard Adhesive	800	LF	New Annex - All Rooms except Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
099	2' x 2' White Fissured Ceiling Tile	4,000	SF	New Annex - All Rooms, 1st Floor Hall	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
100	12"x12" Gray and Cream Speckled Floor Tile	3,600	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12"x12" Gray and Cream Speckled Floor Tile-Mastic	3,600	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12"x12" Brown Floor Tile	120	SF	Auditorium, Stairs, Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12"x12" Brown Floor Tile Mastic	300	SF	Auditorium, Stairs, Landing, Engineer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12x12 Light BrownFT with Dark Brown & White	3,000	SF	Rooms 111, 103, 132, 135, 136, 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	Mastic associated with 12x12Light Brown FT with Dark Brown & White	3,000	SF	Rooms 111, 103, 132, 135, 136, 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	Cream with Light Brown Linoleum	750	SF	Washrooms across from 129/131	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
107	Adhesive associated with Cream with Light Brown Linoleum	750	SF	Washrooms across from room 129/131	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12"X12" Blue W/Gray White Streaks VFT	11,000	SF	Room 113,116,117/119,121/123, 143,101,105,107,109,125, 127,128,137,141, cafeteria lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12"X12" Blue W/Gray & White Streaks VFT Mastic	11,000	SF	Room 113,116,117/119,121/123, 143,101,105,107,109,125, 127,128,137,141, cafeteria lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	2' x 4' Ceiling Tile	11,000	SF	Rooms 113, 116, 117/119, 121/123, 143, 101, 105, 107, 109, 125, 127, 128, 137, 141, Cafeteria Lounge, Lunch Room, Teacher's Lounge	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
90A	Drywall Tape	250	SF	Addition for 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90B	Drywall Compound	250	LF	Addition for 401, 403, 405, 407	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Aircell Pipe Insulation	1,500	LF	Tunnel, Basement, Crawl Spaces	Chrysotile	TSI	Yes	100	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
C	Aircell Pipe Insulation Joints	50	LF	Basement, Tunnel, Crawl Spaces	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Cardboard Pipe Insulation	35	LF	Tunnel / Kitchen Storage Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Cardboard Pipe Insulation Joints			Tunnel/Kitchen Storage	No ACBM	MISC					
F	Pipe Joint Insulation off Fiberglass	10	LF	Tunnel, Kitchen Storage Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Boiler Insulation - ABATED				Abated	TSI					
H	Tank Insulation - ABATED				Abated	TSI					
I	Aircell Pipe Wrap (Jacketing)	1,500	LF	Tunnel, Basement, Crawl Spaces, Maintenance Areas	Chrysotile	TSI	Yes	100	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
J	Fiberglass Pipe Insulation			Tunnel	No ACBM	TSI					

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	05/04/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	
002	
003	Sample to determine asbestos content, repair all damaged ACBM
004	
005	
006 A	
006 B	
006 C	
006 D	
006 E	

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
006 F	
006 G	
006 H	
006 I	
006 K	
006 L	
006 M	
006 N	
006 O	Remove all damaged materials
006 P	
006 Q	
006 R	
006 S	
007 A	
007 B	
007 C	
007 D	
007 E	
007 F	
007 G	
007 H	
007 J	
007 K	
008 A	
008 B	
008 C	

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
008 D	
009	
01	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
021	
022	
023	
024	
025	
026	
027	
028	
029	
030	
031	
032	

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	
057	
058	

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
071	
070	
071	
072	
073	
074	
075	
076	
077	
078	
079	
080	
081	
082	
083	

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
084	
085	
086	
087	
088	
089	
090	
091	
092	
093	
094	
095	
096	
097	
098	
099	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
111	
90A	
90B	
B	Maintain accessible materials in Good Condition following O&M Plan
C	
D	
E	
F	
G	
H	
I	Maintain all accessible material in good condition following O&M plan
J	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	001	
MATERIAL DESCRIPTION:	2' x 4' Ceiling Panels	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **001**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	002		
MATERIAL DESCRIPTION:	Burlap		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	On Walls Throughout Facility		
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	20	DAMAGE UNITS:	SF
COMMENTS:	Damage located in various areas throughout building		

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	002		
MATERIAL DESCRIPTION:	Burlap		
MATERIAL LOCATION:	On Walls Throughout Facility		
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	20	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	003		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Original Construction		
MATERIAL QUANTITY:	100000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	30	DAMAGE UNITS:	SF
COMMENTS:	Damage located in various areas throughout building		

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	003		
MATERIAL DESCRIPTION:	Plaster		
MATERIAL LOCATION:	Throughout Original Construction		
MATERIAL QUANTITY:	100000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	30	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine asbestos content, repair all damaged ACBM

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	004	
MATERIAL DESCRIPTION:	2' x 2' Ceiling Panels - ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **004**

MATERIAL DESCRIPTION: **2' x 2' Ceiling Panels - ABATED**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	005	
MATERIAL DESCRIPTION:	2' x 4' Ceiling Panels	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **005**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 A		
MATERIAL DESCRIPTION:	9"x9" Dark Brown Floor Tile w/ Red & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Computer Room, Science Lab (125-A), Office, 104, 133, 135, Principal's Office		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	006 A				
MATERIAL DESCRIPTION:	9"x9" Dark Brown Floor Tile w/ Red & White Streaks				
MATERIAL LOCATION:	Computer Room, Science Lab (125-A), Office, 104, 133, 135, Principal's Office				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 B	
MATERIAL DESCRIPTION:	9"x9" Light Brown Floor Tile w/ Dark Brown Streaks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Science Lab and Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 B**

MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile w/ Dark Brown Streaks**

MATERIAL LOCATION: **Science Lab and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 C	
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile w/ White Streaks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Science Lab, Hall, Speech, Cafeteria, Rooms 104, 106, 116, 117, 126

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 C**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/ White Streaks**

MATERIAL LOCATION: **Science Lab, Hall, Speech, Cafeteria, Rooms 104, 106, 116, 117, 126**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 D		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile w/White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Minor Damage throughout school hallways		

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 D**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile w/White Streaks**

MATERIAL LOCATION: **Hallways on 1st Floor**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 E		
MATERIAL DESCRIPTION:	9" x 9" Green Floor Tile w/ White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Minor Damage throughout school hallways		

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 E**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/ White Streaks**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 F	
MATERIAL DESCRIPTION:	9" x 9" Gray FT w/Red, Yellow, Blue, & White Dots	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 116, 117, 125 and 127

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 F**

MATERIAL DESCRIPTION: **9" x 9" Gray FT w/Red, Yellow, Blue, & White Dots**

MATERIAL LOCATION: **Rooms 116, 117, 125 and 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 G	
MATERIAL DESCRIPTION:	9" x 9" Red Floor Tile w/White Streaks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hallways on 1st Floor and Rooms 104, 129

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 G**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/White Streaks**

MATERIAL LOCATION: **Hallways on 1st Floor and Rooms 104, 129**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 H	
MATERIAL DESCRIPTION:	9"x9 Light Brown FT w/ Blue, Red, Yel & White Dots	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 123

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 H**

MATERIAL DESCRIPTION: **9"x9 Light Brown FT w/ Blue, Red, Yel & White Dots**

MATERIAL LOCATION: **Room 123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 I		
MATERIAL DESCRIPTION:	9" x 9" Light Brn w/Brn & White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 122, 123, 126 and as Patches in the Cafeteria

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 I**

MATERIAL DESCRIPTION: **9" x 9" Light Brn w/Brn & White Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 122, 123, 126 and as Patches in the Cafeteria**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 K	
MATERIAL DESCRIPTION:	9" x 9" Medium Brown Speckled Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 K**

MATERIAL DESCRIPTION: **9" x 9" Medium Brown Speckled Floor Tile**

MATERIAL LOCATION: **Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 L		
MATERIAL DESCRIPTION:	9" x 9" Dark Brown Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 L**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown Speckled Floor Tile**

MATERIAL LOCATION: **Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge**

MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 M	
MATERIAL DESCRIPTION:	9" x 9" Light Brown FT w/ Dark Brown & White Spots	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Women's Teacher's Lounge, Rooms 101, 113, 115, 122, 123, and 126

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 M**

MATERIAL DESCRIPTION: **9" x 9" Light Brown FT w/ Dark Brown & White Spots**

MATERIAL LOCATION: **Women's Teacher's Lounge, Rooms 101, 113, 115, 122, 123, and 126**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 N		
MATERIAL DESCRIPTION:	9" x 9" Beige Floor Tile w/Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Cafeteria, Hall between Mobile Units, 103, Physical Therapy, Office, 122, 123, 126, 133, 135

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 N**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/Brown & White Streaks**

MATERIAL LOCATION: **Cafeteria, Hall between Mobile Units, 103, Physical Therapy, Office, 122, 123, 126, 133, 135**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 O		
MATERIAL DESCRIPTION:	9" x 9" Rusty Brown Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, Rooms 103, 104, 124, and 126, 138 Computer Lab		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	25	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 O**

MATERIAL DESCRIPTION: **9" x 9" Rusty Brown Speckled Floor Tile**

MATERIAL LOCATION: **Cafeteria, Rooms 103, 104, 124, and 126, 138 Computer Lab**

MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	25	DAMAGE UNITS:	SF
------------------	-----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove all damaged materials

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 P	
MATERIAL DESCRIPTION:	9" x 9" White Floor Tile w/ Black Streaks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not observed

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 P**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/ Black Streaks**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 Q	
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile w/White & Brown Streaks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 130

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 Q**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/White & Brown Streaks**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 R		
MATERIAL DESCRIPTION:	9" x 9" Lt Brn Floor Tile w/Dk Brown & White Spots		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 R**

MATERIAL DESCRIPTION: **9" x 9" Lt Brn Floor Tile w/Dk Brown & White Spots**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006 S		
MATERIAL DESCRIPTION:	9" x 9" Multi-Brown Specked Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **006 S**

MATERIAL DESCRIPTION: **9" x 9" Multi-Brown Specked Floor Tile**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 A		
MATERIAL DESCRIPTION:	12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Custodians Lounge		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 A**

MATERIAL DESCRIPTION: **12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks**

MATERIAL LOCATION: **Custodians Lounge**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 B		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/White & Brown Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 B**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/White & Brown Streaks**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 C	
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 123

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 C**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**

MATERIAL LOCATION: **Room 123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 D		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile w/White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Speech, Entrance by 127, Room 126		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 D**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Streaks**

MATERIAL LOCATION: **Speech, Entrance by 127, Room 126**

MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 E		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile w/White Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Speech, Cafeteria, Assembly Hall		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 E**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Specks**

MATERIAL LOCATION: **Speech, Cafeteria, Assembly Hall**

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 F		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers Lounge, Speech		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 F**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **Teachers Lounge, Speech**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 G		
MATERIAL DESCRIPTION:	12" x 12" Dk Gray Floor Tile w/Brn & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 G**

MATERIAL DESCRIPTION: **12" x 12" Dk Gray Floor Tile w/Brn & White Streaks**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 H		
MATERIAL DESCRIPTION:	12" x 12" Light Gray Floor Tile w/White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 H**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile w/White Streaks**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 J		
MATERIAL DESCRIPTION:	12" x 12" Cream Floor Tile w/ Brown & Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boy's and Girl's Locker Room, Pool Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 J**

MATERIAL DESCRIPTION: **12" x 12" Cream Floor Tile w/ Brown & Gray Streaks**

MATERIAL LOCATION: **Boy's and Girl's Locker Room, Pool Office**

MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007 K		
MATERIAL DESCRIPTION:	12"x12" Dk Gray Floor Tile w/Black & Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 130		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **007 K**

MATERIAL DESCRIPTION: **12"x12" Dk Gray Floor Tile w/Black & Gray Streaks**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	008 A	
MATERIAL DESCRIPTION:	Linoleum (Lt Green Patterned)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 129 - NOT OBSERVED

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **008 A**

MATERIAL DESCRIPTION: **Linoleum (Lt Green Patterned)**

MATERIAL LOCATION: **Room 129 - NOT OBSERVED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	008 B		
MATERIAL DESCRIPTION:	Linoleum (Lt Brown Patterned)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Women's Washroom		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **008 B**

MATERIAL DESCRIPTION: **Linoleum (Lt Brown Patterned)**

MATERIAL LOCATION: **Women's Washroom**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	008 C		
MATERIAL DESCRIPTION:	Beige Patterned Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Physical Therapy Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **008 C**

MATERIAL DESCRIPTION: **Beige Patterned Linoleum**

MATERIAL LOCATION: **Physical Therapy Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	008 D		
MATERIAL DESCRIPTION:	Linoleum (Yellow Patterned)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Washroom Across From Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **008 D**

MATERIAL DESCRIPTION: **Linoleum (Yellow Patterned)**

MATERIAL LOCATION: **Washroom Across From Office**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	009		
MATERIAL DESCRIPTION:	12" x 12" Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall on Walls		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	009		
MATERIAL DESCRIPTION:	12" x 12" Ceiling Tiles		
MATERIAL LOCATION:	Assembly Hall on Walls		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	100000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **100000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	010	
MATERIAL DESCRIPTION:	Block	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **010**

MATERIAL DESCRIPTION: **Block**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	011		
MATERIAL DESCRIPTION:	Block Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	011		
MATERIAL DESCRIPTION:	Block Mortar		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	012		
MATERIAL DESCRIPTION:	9"x9" Dark Brown FT w/ Red & White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Computer Room, Science Room (125-A), Office, Principal's Office, Rooms 133, 135**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	012		
MATERIAL DESCRIPTION:	9"x9" Dark Brown FT w/ Red & White Streaks Mastic		
MATERIAL LOCATION:	Computer Room, Science Room (125-A), Office, Principal's Office, Rooms 133, 135		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	013		
MATERIAL DESCRIPTION:	9" x 9" Light Brown FT w/Dk Brown Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Science Lab and Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **013**

MATERIAL DESCRIPTION: **9" x 9" Light Brown FT w/Dk Brown Streaks Mastic**

MATERIAL LOCATION: **Science Lab and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	014		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile w/White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104, 106, 116, 117, 125-A, Hall, Speech and as Patches in the Cafeteria, Science Lab**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	014				
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile w/White Streaks Mastic				
MATERIAL LOCATION:	Rooms 104, 106, 116, 117, 125-A, Hall, Speech and as Patches in the Cafeteria, Science Lab				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	015		
MATERIAL DESCRIPTION:	9" x 9" Lt Brown FT w/White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	015		
MATERIAL DESCRIPTION:	9" x 9" Lt Brown FT w/White Streaks Mastic		
MATERIAL LOCATION:	Hallways on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	016		
MATERIAL DESCRIPTION:	9" x 9" Green FT w/White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	016		
MATERIAL DESCRIPTION:	9" x 9" Green FT w/White Streaks Mastic		
MATERIAL LOCATION:	Hallways on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	017	
MATERIAL DESCRIPTION:	9"x9" Gray w/Red,Yel, Blue & White Dots FT Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 116, 117 and 125/127

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **017**

MATERIAL DESCRIPTION: **9"x9" Gray w/Red,Yel, Blue & White Dots FT Mastic**

MATERIAL LOCATION: **Rooms 116, 117 and 125/127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	018		
MATERIAL DESCRIPTION:	9" x 9" Red w/White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 104 and 129 and Hallways on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	018		
MATERIAL DESCRIPTION:	9" x 9" Red w/White Streaks Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 104 and 129 and Hallways on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	019		
MATERIAL DESCRIPTION:	9"x9" Lt Brn w/Blue, Red, Yel, & Wh Dots FT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **019**

MATERIAL DESCRIPTION: **9"x9" Lt Brn w/Blue, Red, Yel, & Wh Dots FT Mastic**

MATERIAL LOCATION: **Room123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	020		
MATERIAL DESCRIPTION:	9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 122, 123, 126 and as Patches in the Cafeteria		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	020		
MATERIAL DESCRIPTION:	9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic		
MATERIAL LOCATION:	Rooms 122, 123, 126 and as Patches in the Cafeteria		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	021		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **021**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge**

MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	022		
MATERIAL DESCRIPTION:	9" x 9" Medium Brown Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	022				
MATERIAL DESCRIPTION:	9" x 9" Medium Brown Speckled Floor Tile Mastic				
MATERIAL LOCATION:	103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy				
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/04/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023		
MATERIAL DESCRIPTION:	9" x 9" Dark Brown Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	023				
MATERIAL DESCRIPTION:	9" x 9" Dark Brown Speckled Floor Tile Mastic				
MATERIAL LOCATION:	103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024		
MATERIAL DESCRIPTION:	9" x 9" Lt Brn w/Dk Brown & White Spots FT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 113, 115, 122, 123, 126 and Women's Teacher's Lounge		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	024		
MATERIAL DESCRIPTION:	9" x 9" Lt Brn w/Dk Brown & White Spots FT Mastic		
MATERIAL LOCATION:	Rooms 113, 115, 122, 123, 126 and Women's Teacher's Lounge		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	025		
MATERIAL DESCRIPTION:	9" x 9" Beige w/Brown & White Streaks FT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103, 122, and 126, 133, 135 Office, Physical Therapy, Cafeteria, and Hallways		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	025		
MATERIAL DESCRIPTION:	9" x 9" Beige w/Brown & White Streaks FT Mastic		
MATERIAL LOCATION:	Rooms 103, 122, and 126, 133, 135 Office, Physical Therapy, Cafeteria, and Hallways		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	026		
MATERIAL DESCRIPTION:	9" x 9" Rusty Brown Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103, 104, 124, and 126, 138, Technology Room and the Cafeteria		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	026				
MATERIAL DESCRIPTION:	9" x 9" Rusty Brown Speckled Floor Tile Mastic				
MATERIAL LOCATION:	Rooms 103, 104, 124, and 126, 138, Technology Room and the Cafeteria				
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	027	
MATERIAL DESCRIPTION:	9" x 9" White w/Black Streaks Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **027**

MATERIAL DESCRIPTION: **9" x 9" White w/Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	028		
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 128-(Number Has Been Changed From 130)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **028**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic**

MATERIAL LOCATION: **Room 128-(Number Has Been Changed From 130)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	029		
MATERIAL DESCRIPTION:	9"x9" Lt. Brn FT w/Dark Brown & White Spots Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **029**

MATERIAL DESCRIPTION: **9"x9" Lt. Brn FT w/Dark Brown & White Spots Mastic**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	030		
MATERIAL DESCRIPTION:	12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Custodian's Lounge		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	030		
MATERIAL DESCRIPTION:	12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks Mastic		
MATERIAL LOCATION:	Custodian's Lounge		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	031		
MATERIAL DESCRIPTION:	12" x 12" Beige FT w/ Wh & Brown Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **031**

MATERIAL DESCRIPTION: **12" x 12" Beige FT w/ Wh & Brown Streaks Mastic**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	032		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 123		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	032		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile Mastic		
MATERIAL LOCATION:	Room 123		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	033		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile w/ White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Speech, Entrance by 127, Room 126		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	033		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile w/ White Streaks Mastic		
MATERIAL LOCATION:	Speech, Entrance by 127, Room 126		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	034		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile w/White Specks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Speech, Cafeteria, Assembly Hall		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	034		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile w/White Specks Mastic		
MATERIAL LOCATION:	Speech, Cafeteria, Assembly Hall		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	035		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Speech, Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **035**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **Speech, Teacher's Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	036		
MATERIAL DESCRIPTION:	12"x12" Dark Gray FT w/Brown & White Strks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **036**

MATERIAL DESCRIPTION: **12"x12" Dark Gray FT w/Brown & White Strks Mastic**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	037	
MATERIAL DESCRIPTION:	12" x 12" Light Gray FT w/White Streaks Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **037**

MATERIAL DESCRIPTION: **12" x 12" Light Gray FT w/White Streaks Mastic**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	038		
MATERIAL DESCRIPTION:	12" x 12" Off-White FT w/Brown Speckles Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, Boy's Washroom, Room 108		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	038		
MATERIAL DESCRIPTION:	12" x 12" Off-White FT w/Brown Speckles Mastic		
MATERIAL LOCATION:	Cafeteria, Boy's Washroom, Room 108		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	039		
MATERIAL DESCRIPTION:	12"x12" Cream Floor Tile w/(Lt) Brown & Gray Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girl's and Boy's Locker Room, Pool Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	039		
MATERIAL DESCRIPTION:	12"x12"Cream Floor Tile w/(Lt) Brown & Gray Mastic		
MATERIAL LOCATION:	Girl's and Boy's Locker Room, Pool Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	040		
MATERIAL DESCRIPTION:	12" x 12" Cream Floor Tile w/Brown & Gray Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girl's and Boy's Locker Room, Pool Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	040		
MATERIAL DESCRIPTION:	12" x 12" Cream Floor Tile w/Brown & Gray Mastic		
MATERIAL LOCATION:	Girl's and Boy's Locker Room, Pool Office		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	041	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **041**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	042		
MATERIAL DESCRIPTION:	Black Border Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building halls on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	042		
MATERIAL DESCRIPTION:	Black Border Tiles		
MATERIAL LOCATION:	Throughout Building halls on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/04/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	043		
MATERIAL DESCRIPTION:	Black Border Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building Halls on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	043		
MATERIAL DESCRIPTION:	Black Border Tile Mastic		
MATERIAL LOCATION:	Throughout Building Halls on 1st Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	044		
MATERIAL DESCRIPTION:	Cinder Block - New Construction		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	044		
MATERIAL DESCRIPTION:	Cinder Block - New Construction		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	045		
MATERIAL DESCRIPTION:	Cinder Block Mortar - New Construction		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	40000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	045		
MATERIAL DESCRIPTION:	Cinder Block Mortar - New Construction		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	40000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	046		
MATERIAL DESCRIPTION:	Rubber Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	3550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	046		
MATERIAL DESCRIPTION:	Rubber Flooring		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	3550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	047		
MATERIAL DESCRIPTION:	4" Black Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym, Boy's and Girl's Locker Room throughout		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	047		
MATERIAL DESCRIPTION:	4" Black Baseboard		
MATERIAL LOCATION:	Gym, Boy's and Girl's Locker Room throughout		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	048		
MATERIAL DESCRIPTION:	4" Black Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym, Boy's and Girl's Locker Room Throughout		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	048		
MATERIAL DESCRIPTION:	4" Black Baseboard Mastic		
MATERIAL LOCATION:	Gym, Boy's and Girl's Locker Room Throughout		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	049		
MATERIAL DESCRIPTION:	6" Black Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	049		
MATERIAL DESCRIPTION:	6" Black Baseboard		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	050		
MATERIAL DESCRIPTION:	6" Black Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	050		
MATERIAL DESCRIPTION:	6" Black Baseboard Mastic		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	051	
MATERIAL DESCRIPTION:	Spray-on Material	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Attic

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **Spray-on Material**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	052	
MATERIAL DESCRIPTION:	Plaster	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Attic

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **052**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	053		
MATERIAL DESCRIPTION:	Finished (Glazed) Brick Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	200000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	053		
MATERIAL DESCRIPTION:	Finished (Glazed) Brick Mortar		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	200000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	054		
MATERIAL DESCRIPTION:	Terrazzo Wall Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boys and Women's Washroom, Room 129		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	054		
MATERIAL DESCRIPTION:	Terrazzo Wall Panels		
MATERIAL LOCATION:	Boys and Women's Washroom, Room 129		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	055		
MATERIAL DESCRIPTION:	Non-skid Strips		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Women's Washroom		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	055		
MATERIAL DESCRIPTION:	Non-skid Strips		
MATERIAL LOCATION:	Women's Washroom		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	056	
MATERIAL DESCRIPTION:	Exterior Brick - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building - Original Construction

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **056**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Building - Original Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	057	
MATERIAL DESCRIPTION:	Exterior Brick Mortar - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building - Original Construction

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **057**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Exterior of Building - Original Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	058	
MATERIAL DESCRIPTION:	Exterior Door Caulk - Not AHERA)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of All Doors in Original Construction

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **058**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA)**

MATERIAL LOCATION: **Exterior of All Doors in Original Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	059	
MATERIAL DESCRIPTION:	Cinder Block in Original Construction	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Basement

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **059**

MATERIAL DESCRIPTION: **Cinder Block in Original Construction**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	060	
MATERIAL DESCRIPTION:	Cinderblock Mortar - Original Construction	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Basement

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **060**

MATERIAL DESCRIPTION: **Cinderblock Mortar - Original Construction**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	061	
MATERIAL DESCRIPTION:	2' x 4' Ceiling Panels	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **061**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	062	
MATERIAL DESCRIPTION:	Exterior Window Caulk - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building - Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **062**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**

MATERIAL LOCATION: **Exterior of Building - Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	063	
MATERIAL DESCRIPTION:	Exterior Brick - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of New Addition

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **063**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	064	
MATERIAL DESCRIPTION:	Exterior Brick Mortar - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of New Addition

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **064**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Exterior of New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	065	
MATERIAL DESCRIPTION:	Exterior Door Caulk - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of New Addition

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **065**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA**

MATERIAL LOCATION: **Exterior of New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	066		
MATERIAL DESCRIPTION:	12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 130		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	066		
MATERIAL DESCRIPTION:	12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic		
MATERIAL LOCATION:	Room 130		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	067		
MATERIAL DESCRIPTION:	Non - Skid Strips		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boy's and Girl's Locker Room, Pool Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	067		
MATERIAL DESCRIPTION:	Non - Skid Strips		
MATERIAL LOCATION:	Boy's and Girl's Locker Room, Pool Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/04/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	068		
MATERIAL DESCRIPTION:	Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pool Deck		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	068		
MATERIAL DESCRIPTION:	Ceramic Tile Grout		
MATERIAL LOCATION:	Pool Deck		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	069		
MATERIAL DESCRIPTION:	Grout Between Floor & Wall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pool Deck		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	069		
MATERIAL DESCRIPTION:	Grout Between Floor & Wall		
MATERIAL LOCATION:	Pool Deck		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07 I		
MATERIAL DESCRIPTION:	12" x 12" Off-White Floor Tile w/Brown Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, Boys Washroom, Room 108		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	07 I		
MATERIAL DESCRIPTION:	12" x 12" Off-White Floor Tile w/Brown Speckles		
MATERIAL LOCATION:	Cafeteria, Boys Washroom, Room 108		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	070		
MATERIAL DESCRIPTION:	Ceramic Tile Grout in Pool		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pool		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	070		
MATERIAL DESCRIPTION:	Ceramic Tile Grout in Pool		
MATERIAL LOCATION:	Pool		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	071	
MATERIAL DESCRIPTION:	Gray Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 130

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **071**

MATERIAL DESCRIPTION: **Gray Baseboard**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	072	
MATERIAL DESCRIPTION:	Gray Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 130

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **072**

MATERIAL DESCRIPTION: **Gray Baseboard Mastic**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	073	
MATERIAL DESCRIPTION:	Ceiling Panel Material	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 130

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **073**

MATERIAL DESCRIPTION: **Ceiling Panel Material**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	074	
MATERIAL DESCRIPTION:	Insulation Above Ceiling Panels	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **074**

MATERIAL DESCRIPTION: **Insulation Above Ceiling Panels**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	075		
MATERIAL DESCRIPTION:	Linoleum Like Flooring Material		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Storage		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	075		
MATERIAL DESCRIPTION:	Linoleum Like Flooring Material		
MATERIAL LOCATION:	Storage		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	076		
MATERIAL DESCRIPTION:	Linoleum Like Material Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Storage		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	076		
MATERIAL DESCRIPTION:	Linoleum Like Material Mastic		
MATERIAL LOCATION:	Storage		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	077	
MATERIAL DESCRIPTION:	Vibration Absorbers	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **077**

MATERIAL DESCRIPTION: **Vibration Absorbers**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	078	
MATERIAL DESCRIPTION:	Terrazzo Sink	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boy's Washroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **078**

MATERIAL DESCRIPTION: **Terrazzo Sink**

MATERIAL LOCATION: **Boy's Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	079		
MATERIAL DESCRIPTION:	2' x 2' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	079		
MATERIAL DESCRIPTION:	2' x 2' Ceiling Panels		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	080		
MATERIAL DESCRIPTION:	Insulation in Safe Door		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallway Across From Assembly Hall		
MATERIAL QUANTITY:	32	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	080		
MATERIAL DESCRIPTION:	Insulation in Safe Door		
MATERIAL LOCATION:	Hallway Across From Assembly Hall		
MATERIAL QUANTITY:	32	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	081		
MATERIAL DESCRIPTION:	9" x 9" Multi-Brown Specked Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	081				
MATERIAL DESCRIPTION:	9" x 9" Multi-Brown Specked Floor Tile				
MATERIAL LOCATION:	Room 111				
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	082		
MATERIAL DESCRIPTION:	9" x 9" Multi-Brown Specked Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	082				
MATERIAL DESCRIPTION:	9" x 9" Multi-Brown Specked Floor Tile Mastic				
MATERIAL LOCATION:	Room 111				
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	083		
MATERIAL DESCRIPTION:	12" x 12" Multi-Brown Streaked Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 132		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	083				
MATERIAL DESCRIPTION:	12" x 12" Multi-Brown Streaked Floor Tile				
MATERIAL LOCATION:	Room 132				
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	084		
MATERIAL DESCRIPTION:	12" x 12" Multi-Brown Streaked Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 132		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	084		
MATERIAL DESCRIPTION:	12" x 12" Multi-Brown Streaked Floor Tile Mastic		
MATERIAL LOCATION:	Room 132		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	085		
MATERIAL DESCRIPTION:	Dark Gray Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Outside Hall by Rooms 401, 403, 405, 407		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	085		
MATERIAL DESCRIPTION:	Dark Gray Linoleum		
MATERIAL LOCATION:	Outside Hall by Rooms 401, 403, 405, 407		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	086		
MATERIAL DESCRIPTION:	Dark Gray Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hall outside Rooms 401, 403, 405, 407		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	086		
MATERIAL DESCRIPTION:	Dark Gray Linoleum Mastic		
MATERIAL LOCATION:	Hall outside Rooms 401, 403, 405, 407		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	087		
MATERIAL DESCRIPTION:	2' x 4' Lay-In Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 180/181 and as Patch in Exit by Gym		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	087		
MATERIAL DESCRIPTION:	2' x 4' Lay-In Ceiling Panels		
MATERIAL LOCATION:	Room 180/181 and as Patch in Exit by Gym		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	088		
MATERIAL DESCRIPTION:	Dark Gray Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 401, 403, 405, 407 and Hall		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	088		
MATERIAL DESCRIPTION:	Dark Gray Baseboard		
MATERIAL LOCATION:	Room 401, 403, 405, 407 and Hall		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	089		
MATERIAL DESCRIPTION:	Dark Gray Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 401, 403, 405, 407, Hall		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	089		
MATERIAL DESCRIPTION:	Dark Gray Baseboard Mastic		
MATERIAL LOCATION:	Room 401, 403, 405, 407, Hall		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	090		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	New Building 401, 403, 405, 407 and Hall, Unisex Washroom		
MATERIAL QUANTITY:	2600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	090		
MATERIAL DESCRIPTION:	Drywall		
MATERIAL LOCATION:	New Building 401, 403, 405, 407 and Hall, Unisex Washroom		
MATERIAL QUANTITY:	2600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	091		
MATERIAL DESCRIPTION:	White and Light Blue Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 401, 403, 405, 407		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	091		
MATERIAL DESCRIPTION:	White and Light Blue Linoleum		
MATERIAL LOCATION:	Rooms 401, 403, 405, 407		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	092		
MATERIAL DESCRIPTION:	White and Light Blue Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 401, 403, 405, 407		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	092		
MATERIAL DESCRIPTION:	White and Light Blue Linoleum Mastic		
MATERIAL LOCATION:	Rooms 401, 403, 405, 407		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	093		
MATERIAL DESCRIPTION:	Boiler Gaskets		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	093		
MATERIAL DESCRIPTION:	Boiler Gaskets		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	094		
MATERIAL DESCRIPTION:	Insulation Under Steel Shell of Incinerator		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACM or friable suspect ACM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACM or friable suspect ACM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	094				
MATERIAL DESCRIPTION:	Insulation Under Steel Shell of Incinerator				
MATERIAL LOCATION:	Boiler Room				
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	095		
MATERIAL DESCRIPTION:	12" x 12" White w/Gray Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, Halls on 1st Floor		
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	095				
MATERIAL DESCRIPTION:	12" x 12" White w/Gray Specks Floor Tile				
MATERIAL LOCATION:	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, Halls on 1st Floor				
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	096		
MATERIAL DESCRIPTION:	12" x 12" White w/Gray Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **New Annex - Rooms 302 - 309, Changing Room and Laundry Room, and Halls on 1st Floor**

MATERIAL QUANTITY: **3900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	096				
MATERIAL DESCRIPTION:	12" x 12" White w/Gray Specks Floor Tile Mastic				
MATERIAL LOCATION:	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, and Halls on 1st Floor				
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	097		
MATERIAL DESCRIPTION:	4" Beige Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	New Annex - All Rooms except Washroom		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	097		
MATERIAL DESCRIPTION:	4" Beige Baseboard		
MATERIAL LOCATION:	New Annex - All Rooms except Washroom		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	098		
MATERIAL DESCRIPTION:	4" Beige Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	New Annex - All Rooms except Washroom		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	098		
MATERIAL DESCRIPTION:	4" Beige Baseboard Adhesive		
MATERIAL LOCATION:	New Annex - All Rooms except Washroom		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	099		
MATERIAL DESCRIPTION:	2' x 2' White Fissured Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	New Annex - All Rooms, 1st Floor Hall		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	099		
MATERIAL DESCRIPTION:	2' x 2' White Fissured Ceiling Tile		
MATERIAL LOCATION:	New Annex - All Rooms, 1st Floor Hall		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	12"x12" Gray and Cream Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	12"x12" Gray and Cream Speckled Floor Tile		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	12"x12" Gray and Cream Speckled Floor Tile-Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	12"x12" Gray and Cream Speckled Floor Tile-Mastic		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, Stairs, Landing		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile		
MATERIAL LOCATION:	Auditorium, Stairs, Landing		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, Stairs, Landing, Engineer		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile Mastic		
MATERIAL LOCATION:	Auditorium, Stairs, Landing, Engineer		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	12x12 Light Brown FT with Dark Brown & White		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 111, 103, 132, 135, 136, 113		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	12x12 Light Brown FT with Dark Brown & White		
MATERIAL LOCATION:	Rooms 111, 103, 132, 135, 136, 113		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	Mastic associated with 12x12Light Brown FT with Dark Brown & White		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 111, 103, 132, 135, 136, 113		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	Mastic associated with 12x12Light Brown FT with Dark Brown & White		
MATERIAL LOCATION:	Rooms 111, 103, 132, 135, 136, 113		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	Cream with Light Brown Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Washrooms across from 129/131		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	Cream with Light Brown Linoleum		
MATERIAL LOCATION:	Washrooms across from 129/131		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	Adhesive associated with Cream with Light Brown Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Washrooms across from room 129/131		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	Adhesive associated with Cream with Light Brown Linoleum		
MATERIAL LOCATION:	Washrooms across from room 129/131		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	12"X12" Blue W/Gray White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 113,116,117/119,121/123,143,101,105,107,109,125, 127,128,137,141, cafeteria lounge**

MATERIAL QUANTITY: **11000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	108				
MATERIAL DESCRIPTION:	12"X12" Blue W/Gray White Streaks VFT				
MATERIAL LOCATION:	Room 113,116,117/119,121/123,143,101,105,107,109,125, 127,128,137,141, cafeteria lounge				
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	12"X12" Blue W/Gray & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 113,116,117/119,121/123,143,101,105,107,109,125, 127,128,137,141, cafeteria lounge**

MATERIAL QUANTITY: **11000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	12"X12" Blue W/Gray & White Streaks VFT Mastic		
MATERIAL LOCATION:	Room 113,116,117/119,121/123,143,101,105,107,109,125, 127,128,137,141, cafeteria lounge		
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 113, 116, 117/119, 121/123, 143, 101, 105, 107, 109, 125, 127, 128, 137, 141, Cafeteria Lounge, Lunch Room, Teacher's Lounge		
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	111				
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile				
MATERIAL LOCATION:	Rooms 113, 116, 117/119, 121/123, 143, 101, 105, 107, 109, 125, 127, 128, 137, 141, Cafeteria Lounge, Lunch Room, Teacher's Lounge				
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90A		
MATERIAL DESCRIPTION:	Drywall Tape		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Addition for 401, 403, 405, 407		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **90A**

MATERIAL DESCRIPTION: **Drywall Tape**

MATERIAL LOCATION: **Addition for 401, 403, 405, 407**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90B		
MATERIAL DESCRIPTION:	Drywall Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Addition for 401, 403, 405, 407		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	90B		
MATERIAL DESCRIPTION:	Drywall Compound		
MATERIAL LOCATION:	Addition for 401, 403, 405, 407		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 1. **Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Tunnel, Basement, Crawl Spaces		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	100	DAMAGE UNITS:	LF
COMMENTS:	Damaged ACM is located in unexcavated crawlspaces. Access is restricted and areas secured.		

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Tunnel, Basement, Crawl Spaces**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **100**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Maintain accessible materials in Good Condition following O&M Plan

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation Joints		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement, Tunnel, Crawl Spaces		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**

MATERIAL LOCATION: **Basement, Tunnel, Crawl Spaces**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Tunnel / Kitchen Storage Room		
MATERIAL QUANTITY:	35	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Tunnel / Kitchen Storage Room**

MATERIAL QUANTITY:	35	MATERIAL UNITS:	LF
--------------------	-----------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E	
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation Joints	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Tunnel/Kitchen Storage

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation Joints**

MATERIAL LOCATION: **Tunnel/Kitchen Storage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Pipe Joint Insulation off Fiberglass		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Tunnel, Kitchen Storage Room		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Pipe Joint Insulation off Fiberglass**

MATERIAL LOCATION: **Tunnel, Kitchen Storage Room**

MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
--------------------	-----------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G	
MATERIAL DESCRIPTION:	Boiler Insulation - ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Boiler Insulation - ABATED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H	
MATERIAL DESCRIPTION:	Tank Insulation - ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Tank Insulation - ABATED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	Aircell Pipe Wrap (Jacketing)		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Tunnel, Basement, Crawl Spaces, Maintenance Areas		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	100	DAMAGE UNITS:	LF
COMMENTS:	Damaged Materials are located in unexcavated crawlspaces, and secured from access		

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Aircell Pipe Wrap (Jacketing)**

MATERIAL LOCATION: **Tunnel, Basement, Crawl Spaces, Maintenance Areas**

MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	100	DAMAGE UNITS:	LF
------------------	------------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Maintain all accessible material in good condition following O&M plan

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Christopher School	INSPECTION DATE:	4/23/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J	
MATERIAL DESCRIPTION:	Fiberglass Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Tunnel

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	30031	BUILDING ID:	2780
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Christopher School	REVIEW DATE:	5/4/2019		
ADDRESS:	5042 S. Artesian	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Tunnel**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/04/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MICHAEL D HERMAN
5121 N MONITOR
CHICAGO, IL 60630

4/10/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05090

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	ID NUMBER 100 - 05090	ISSUED 4/10/2019	INSPECTOR	1/17/2020
MICHAEL D HERMAN 5121 N MONITOR CHICAGO, IL 60630 Environmental Health		EXPIRES 05/15/2020 	PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/16/2020
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Michael Herman

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/17/2019

Exam Date: 1/17/2019

Expiration Date: 1/17/2020

Certificate Number: BIR1901170228

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MICHAEL D HERMAN
5121 N MONITOR
CHICAGO, IL 60630

4/25/2018


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05090

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

IDPH ILLINOIS DEPARTMENT OF PUBLIC HEALTH		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 05090	ISSUED 4/25/2018	EXPIRES 05/15/2019		INSPECTOR	1/18/2019
MICHAEL D HERMAN 5121 N MONITOR CHICAGO, IL 60630 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/17/2019
				Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

Michael D. Herman
[Signature]

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES
Nationally Accredited by PHAB

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019



Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed