

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2050
SCHOOL NAME: Air Force High School (formerly Abbott School)
ADDRESS OF SCHOOL: 3630 S. Wells
CITY: Chicago, IL, 60609

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/24/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 194
IDPH INSPECTOR LICENSE NUMBER: 100-04437
IDPH LICENSED INSPECTOR NAME(Please Print): Mary Hicks
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Air Force High School (formerly Abbott School)

3630 S. Wells
Chicago, IL, 60609

Unit: 45231
Building ID: 2010

IDPH ID Number: 14-016-2990-2050

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 5, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 45231 Region: 04 IDPH ID:14-016-2990-2050

School: Air Force High School (formerly Abbott School) Building ID: 2010

Address: 3630 S. Wells

Chicago, IL, 60609

Building Contact: Guerrero, Samuel

Contact Phone:773 537 8944

Current Building Owners: Chicago Public Schools

Review Date: 05/03/2019

Inspector: Mary Hicks

Inspector IDPH License: 100-04437

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 05, 2019

RE: Air Force High School (formerly Abbott School), Unit 45231
3630 S. Wells
Chicago, IL, 60609

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Air Force High School (formerly Abbott School), following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Air Force High School (formerly Abbott School), there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Air Force High School Unit: 45231 Region: 04
(formerly Abbott School)
Address: 3630 S. Wells Chicago, IL, 60609
IDPH ID: 14-016-2990-2050 Building ID: 2010
Contact: Guerrero, Samuel Phone: 773 537 8944

2. Description of Facility

Original Construction: 1954 Additional Construction: 1949,1961
Total Square Footage: 11792 No of Floors: 2
Current Occupancy: 194

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, Il, 60607
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Mary Hicks

Inspector IDPH license # 100-04437

Signature:
Date: 4/5/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 05/03/2019

7. Review Date:05/03/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Air Force High School (formerly Abbott School). This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2010:

B. The following new homogenous areas have been identified for Building 2010:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

082	12" x 12" Sandy Beige Floor Tile
086	12" x 12" Off White Floor Tile
096	Vault Door Insulation
107	Roofing Materials (NON AHERA)
108	Roofing Materials (NON AHERA)
109	Roofing Materials (NON AHERA)
110	Interior Window Caulk
111	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT
112	12" x 12" White w/Off White & Beige Streaks
113	Mastic for HA 111 & HA 112 Checkerboard FT Pattern
114	12" x 12" Red Floor Tile
115	12" x 12" Red Floor Tile Mastic
116	12" x 12" Blue Floor Tile
117	12" x 12" Blue Floor Tile Mastic
118	Green Carpet Adhesive
119	Acoustical Ceiling
120	12x12 beige mix floor tile
121	mastic associated with 12x12 beige mix floor tile
122	Red Carpet Adhesive
123	Black Board/ Marker Board Adhesive
124	Grey and Black Mix Terrazzo Flooring
125	12" X 12" Tand w/Brown and White Streaks Floor Tile
126	12" X 12" Tand w/Brown and White Streaks Floor Tile Mastic
127	Cork Board Adhesive
128	Green Carpet Adhesive
139	Transite Laboratory Countertop
142	Blue Sheet Flooring
143	Blue Sheet Flooring Mastic
144	Transite Electrical Panel

The following areas were deemed to be inaccessible:

075	Mastic on 9" x 9" Light Brown Floor Tile
083	Mastic on 12" x 12" Sandy Beige Floor Tile
085	Mastic on 9" x 9" Orange Floor Tile
087	Mastic on 12" x 12" Off White Floor Tile
145	Electrical Wiring Associated with Wall Mounted

Clocks

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mary Hicks, IDPH License # 100-04437. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Air Force High School (formerly Abbott School) Building 2010 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
006	12" x 12" Beige Floor Tile w/Brown & White Streaks			Material Not Present	NO_ACBM									
007	12"x12" Lt Brown Floor Tile w/Brn & White Streaks			Material Not Present	CHR	MISC		None						Moderate
008	Mastic on 9" x 9" Dark Brown Floor Tile			Material Not Present	CHR	MISC		None						Moderate
009	Mastic on 12x12 Dk Brn w/Brn & Wh Strks Floor Tile			Material Not Present	CHR	MISC		None						Moderate
010	Mastic on 12x12 Lt. Brown w/Brn & Wh Streaks FT			1953 Building, Room 212A (MDF Room)	CHR	MISC								
011	Partition Floor Joiner Compound			1946/53 Connection by Room 104	NO_ACBM			None						
012	12"x12" Lt Brown w/Brn & White Streaks Floor Tile			Material Not Present	CHR	MISC		None						Moderate
013	Mastic on 12 x 12 Lt Brn w/Brn & White Strks FT			Material Not Present	CHR	MISC		None						Moderate
014	Carpet Adhesive			Material Not Present	CHR	MISC		None						Moderate
015	Black Vinyl Baseboard			Material Not Present	NO_ACBM	MISC		None						
016	Black Vinyl Baseboard Adhesive			Material Not Present	NO_ACBM	MISC		None						
017	Sink Bottom Caulking			Material Not Present	CHR	MISC		None						Moderate
018	Plaster			1946 Building	NO_ACBM			None						
019	Interior Brick Walls			1946 Building	NO_ACBM			None						
020	Interior Brick Walls Mortar			1946 Building	NO_ACBM			None						
021	12" x 12" Green Floor Tile			Material Not Present	CHR	MISC		None						Low
022	Mastic on 12" x 12" Green Floor Tile			Material Not Present	CHR	MISC		None						Moderate
023	Tar Paper and Mastic in Vault Closet Areas			Material Not Present	CHR	MISC		None						Moderate
024	Vibration Isolator			1946 Building, Attic Above 200 and 201	NO_ACBM			None						
025	Fan Unit Door Lining			1946 Building, Attic above 200 and 201	NO_ACBM			None						
026	Dirt on Floor			Material Not Present	CHR	TSI		Loc						Moderate
027	Mastic on 12"x12" Beige w/Brown & White Streaks FT			Material Not Present	CHR	MISC		None						Moderate
028	Partition Wall Joiner Compound			1946/1953 Buildings by 104 & 204	CHR	MISC								
029	12" x 12" Dark Gray w/White & Brown Streaks FT			Material Not Present	NO_ACBM									
030	12" x 12" Dark Gray Floor Tile w/Beige Mix			Material Not Present	NO_ACBM									
031	Mastic on 12"x12" Dark Gray w/Beige Mix Floor Tile			Material Not Present	CHR	MISC		None						Moderate
032	12" x 12" Light Beige Mix Floor Tile			Material Not Present	NO_ACBM									
033	Mastic on 12" x 12" Light Beige Mix Floor			Material Not Present	CHR	MISC		None						Moderate

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

Inspector's Reinspection Findings Table 1

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Inspector's Comments are Summarized at the End of the Report

[illegible]

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

Inspector's Reinspection Findings Table 1

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Inspector's Comments are Summarized at the End of the Report

[illegible]

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
089	12" x 12" Light Gray Mix Floor Tile Mastic			Material Not Present	NO_ACBM									
090	Radiator Grill Lining Material			1960 Building	NO_ACBM									
091	Incinerator Gasket Material by Fire Hole			Material Not Present	CHR	TSI								
092	Incinerator Interior Brick			Material Not Present	NO_ACBM									
093	Incinerator Ash Chamber Brick			Material Not Present	NO_ACBM									
094	Vibration Isolator			1946 Building, Fan Unit	NO_ACBM									
095	White Chalky Material and Soil Mix			1953 Building, Unfinished Pipe Space	NO_ACBM									
096	Vault Door Insulation			Material Not Present	ASSUMED	MISC								
097	Light Gray Vinyl Baseboard			Material Not Present	NO_ACBM									
098	Light Gray Vinyl Baseboard Adhesive			Material Not Present	NO_ACBM									
099	Beaver Board			Material Not Present	NO_ACBM									
100	Exterior Brick			1946 Building	NO_ACBM									
101	Exterior Brick Mortar			1946 Building	NO_ACBM									
102	Exterior Brick			1953 Building	NO_ACBM									
103	Exterior Brick Mortar			1953 Building	NO_ACBM									
104	Exterior Brick			1960 Building	NO_ACBM									
105	Exterior Brick Mortar			1960 Building	NO_ACBM									
106	Exterior Door Caulk (NON AHERA)			1960 Building	NO_ACBM									
107	Roofing Materials (NON AHERA)			1946 Building	ASSUMED									
108	Roofing Materials (NON AHERA)			1953 Building	ASSUMED									
109	Roofing Materials (NON AHERA)			1960 Building	ASSUMED									
110	Interior Window Caulk			Material Not Present	ASSUMED	MISC		None						Low
111	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT			Material Not Present	ASSUMED	MISC		None						Moderate
112	12" x 12" White w/Off White & Beige Streaks			Material Not Present	ASSUMED	MISC		None						Moderate
113	Mastic for HA 111 & HA 112 Checkerboard FT Pattern			Material Not Present	ASSUMED	MISC		None						Moderate
114	12" x 12" Red Floor Tile			Material Not Present	ASSUMED	MISC		None						Moderate
115	12" x 12" Red Floor Tile Mastic			Material Not Present	ASSUMED	MISC		None						Moderate
116	12" x 12" Blue Floor Tile			Material Not Present	ASSUMED	MISC		None						Moderate
117	12" x 12" Blue Floor Tile Mastic			Material Not Present	ASSUMED	MISC		None						Low
118	Green Carpet Adhesive			Material Not Present	ASSUMED	MISC		None						Moderate
119	Acoustical Ceiling	10,000	SF	Throughout Hallways of the 1960 Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
120	12x12 beige mix floor tile			Material Not Present	ASSUMED	MISC		None						Moderate
121	mastic associated with 12x12 beige mix floor tile			Material Not Present	ASSUMED	MISC		None						Moderate

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
122	Red Carpet Adhesive			Material Not Present	ASSUMED	MISC		None						Moderate
123	Black Board/ Marker Board Adhesive	5,000	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
124	Grey and Black Mix Terrazzo Flooring	4,000	SF	East Entrances and Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
125	12" X 12" Tand w/Brown and White Streaks Floor Tile			Material Not Present	ASSUMED	MISC		None						Moderate
126	12" X 12" Tand w/Brown and White Streaks Floor Tile Mastic			Material Not Present	ASSUMED	MISC		None						Moderate
127	Cork Board Adhesive			Material Not Present	ASSUMED	MISC		None						Moderate
128	Green Carpet Adhesive			Material Not Present	ASSUMED	MISC		None						Moderate
129	12"x12" White Mottled Floor Tile			Throughout Corridors, Classrooms, and Offices	NO_ACBM	MISC								
130	12"x12" White Mottled Floor Tile Mastic			Throughout Corridors, Classrooms, and Offices	NO_ACBM	MISC								
131	12"x12" Blue Mottled Floor Tile			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	NO_ACBM	MISC								
132	12"x12" Blue Mottled Floor Tile Mastic			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	NO_ACBM	MISC								
133	2'x2' Lay-in Ceiling Tile			First Floor Corridor	NO_ACBM	MISC								
134	2'x4' Lay-in Ceiling Tile			Rooms 112A, 126, and 226	NO_ACBM	MISC								
135	4" Gray Baseboard			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.	NO_ACBM	MISC								
136	4" Gray Baseboard Mastic			Rooms 115, 117,	NO_ACBM	MISC								

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.										
137	Gray Sink Undercoating			Rooms 128, 130, and 133	NO_ACBM	MISC								
138	Carpet Mastic			Rooms 134 and 212	NO_ACBM	MISC								
139	Transite Laboratory Countertop	400	SF	Rooms 109 and 226	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
140	Wood Pattern Sheet Flooring			Gymnasium	NO_ACBM	MISC								
141	Wood Pattern Sheet Flooring Mastic			Gymnasium	NO_ACBM	MISC								
142	Blue Sheet Flooring	650	SF	Room 126	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143	Blue Sheet Flooring Mastic	650	SF	Room 126	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144	Transite Electrical Panel	200	SF	Basement Electrical Vault	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
145	Electrical Wiring Associated with Wall Mounted Clocks	150	LF	Throughout Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
B	Distributed Pipe Insulation on Floor			Material Not Present	CHR	MISC								
C	Aircell Pipe Insulation			1946 Building, Walls and Pipe Chases	CHR	TSI								
D	Joint Compound off Fiberglass Pipe Insulation			Material Not Present	CHR	TSI		None						Moderate
E	Joint Compound Off Fiberglass Pipe Insulation			Material Not Present	CHR	TSI		None						Moderate
F	Distributed Pipe Insulation in Dirt on Floor			Material Not Present	CHR	TSI		Dist						Moderate
G	Distributed Pipe Insulation in Dirt on Floor			Material Not Present	CHR	TSI		Dist						Moderate
H	Aircell Pipe Insulation			Material Not Present	CHR	TSI		None						Moderate
I	Aircell Pipe Insulation			Material Not Present	CHR	TSI		None						Moderate
J	Paperwrap Pipe Insulation			1946 Building, Pipe Chases	NO_ACBM									
K	Hard Joint Compound off Paperwrap Pipe Insulation	75	LF	1946 Building, Walls and Pipe Chases	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present	CHR	TSI		Dist						Moderate

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
L-1	Hard Joint Compound off Aircell Pipe Insulation			1946 Building, Walls and Pipe Chases	CHR	TSI								
M	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present	CHR	TSI		None						Moderate
N	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present	CHR	TSI		None						Moderate
O	Duct Interior Insulation			1960 Building, Boiler Room	NO_ACBM									
P	Magblock Pipe Insulation			Material Not Present	AMO_CHR	TSI		Loc						Moderate
Q	Magblock Pipe Insulation Joint Compound			Material Not Present	CHR	TSI		None						Moderate
R	Water Tank Insulation			Material Not Present	CHR	TSI		None						Moderate
S	Aircell Duct Insulation			Material Not Present	CHR	TSI								
T	Magblock Insulation	15	LF	1946 Building, Coal/Ash Room Abandoned Mech. Unit	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
U	Duct Insulation - Black Tar Like Adhesive			1953 Building, Unfinished Pipe Spaces	CHR	TSI								

Chicago Public Schools

School Air Force High School (formerly Abbott School) Unit 45231 Building ID 2010

Address 3630 S. Wells Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>4/5/2019</u>
Inspector Name <u>Mary Hicks</u>
<u>100-04437</u> <u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
006	
007	
008	
009	
010	Not observed 2019
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
021	
022	
023	
024	
025	
026	
027	
028	Not observed 2019

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	
057	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
058	
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	
073	
074	
075	
076	
077	
078	
079	
080	
081	
082	
083	
084	
085	
086	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
087	
088	
089	
090	
091	
092	
093	
094	
095	
096	
097	
098	
099	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010

Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
145	
B	
C	Not observed 2019
D	
E	
F	
G	
H	
I	
J	
K	
L	
L-1	Not observed 2019
M	
N	
O	
P	
Q	
R	
S	
T	
U	Not observed 2019

Table II

Management Planner's Review

Chicago Public Schools

School

Air Force High School
(formerly Abbott School)

Unit

45231

Building ID

2010

Address

3630 S. Wells

Chicago, IL, 60609

Region

04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone:

(312) 762-2900

Fax:

(312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
006	12" x 12" Beige Floor Tile w/Brown & White Streaks			Material Not Present	No ACBM						
007	12"x12" Lt Brown Floor Tile w/Brn & White Streaks			Material Not Present	Chrysotile	MISC					
008	Mastic on 9" x 9" Dark Brown Floor Tile			Material Not Present	Chrysotile	MISC					
009	Mastic on 12x12 Dk Brn w/Brn & Wh Strks Floor Tile			Material Not Present	Chrysotile	MISC					
010	Mastic on 12x12 Lt. Brown w/Brn & Wh Streaks FT			1953 Building, Room 212A (MDF Room)	Chrysotile	MISC					
011	Partition Floor Joiner Compound			1946/53 Connection by Room 104	No ACBM						
012	12"x12" Lt Brown w/Brn & White Streaks Floor Tile			Material Not Present	Chrysotile	MISC					
013	Mastic on 12 x 12 Lt Brn w/Brn & White Strks FT			Material Not Present	Chrysotile	MISC					
014	Carpet Adhesive			Material Not Present	Chrysotile	MISC					
015	Black Vinyl Baseboard			Material Not Present	No ACBM	MISC					
016	Black Vinyl Baseboard Adhesive			Material Not Present	No ACBM	MISC					
017	Sink Bottom Caulking			Material Not Present	Chrysotile	MISC					
018	Plaster			1946 Building	No ACBM						
019	Interior Brick Walls			1946 Building	No ACBM						
020	Interior Brick Walls Mortar			1946 Building	No ACBM						
021	12" x 12" Green Floor Tile			Material Not Present	Chrysotile	MISC					
022	Mastic on 12" x 12" Green Floor Tile			Material Not Present	Chrysotile	MISC					
023	Tar Paper and Mastic in Vault Closet Areas			Material Not Present	Chrysotile	MISC					
024	Vibration Isolator			1946 Building, Attic Above 200 and 201	No ACBM						
025	Fan Unit Door Lining			1946 Building, Attic above 200 and 201	No ACBM						
026	Dirt on Floor			Material Not Present	Chrysotile	TSI					
027	Mastic on 12"x12" Beige w/Brown & White Streaks FT			Material Not Present	Chrysotile	MISC					
028	Partition Wall Joiner Compound			1946/1953 Buildings by 104 & 204	Chrysotile	MISC					
029	12" x 12" Dark Gray w/White & Brown Streaks FT			Material Not Present	No ACBM						
030	12" x 12" Dark Gray Floor Tile w/Beige Mix			Material Not Present	No ACBM						
031	Mastic on 12"x12" Dark Gray w/Beige Mix Floor Tile			Material Not Present	Chrysotile	MISC					

Chicago Public Schools

School

Air Force High School
(formerly Abbott School)

Unit

45231

Building ID

2010

Address

3630 S. Wells

Chicago, IL, 60609

Region

04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone:

(312) 762-2900

Fax:

(312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
032	12" x 12" Light Beige Mix Floor Tile			Material Not Present	No ACBM						
033	Mastic on 12" x 12" Light Beige Mix Floor Tile			Material Not Present	Chrysotile	MISC					
034	12" x 12" Dark Pink Floor Tile			Material Not Present	No ACBM						
035	Adhesive for 12" x 12" Dark Pink Floor Tile			Material Not Present	No ACBM						
036	12" x 12" Dark Beige w/ Brown & White Streaks FT			Material Not Present	No ACBM						
037	Mastic on 12x12 Dk Beige w/Brn & White Strks FT			Material Not Present	No ACBM						
038	12" x 12" Light Gray Mix Floor Tile			Material Not Present	No ACBM						
039	Mastic on 12" x 12" Light Gray Mix Floor Tile			Material Not Present	Chrysotile	MISC					
040	Gray and Yellow Mix Linoleum			Material Not Present	No ACBM						
041	Burlap with Adhesive Under Grey & Yellow Linoleum			Material Not Present	No ACBM						
042	12" x 12" Blue Floor Tile			Material Not Present	No ACBM						
043	Mastic on 12" x 12" Blue Floor Tile			Material Not Present	Chrysotile	MISC					
044	Mastic 12x12 Dk. Gray w/White & Brown Streaks FT			Material Not Present	Chrysotile	MISC					
045	Interior Brick			1953 Building	No ACBM						
046	Interior Brick Mortar			1953 Building	No ACBM						
047	Plaster			1953 Building	No ACBM						
048	Light Gray Vinyl Baseboard			Material Not Present	No ACBM						
049	9" x 9" Brown Floor Tile			Material Not Present	Chrysotile	MISC					
050	Mastic on 9" x 9" Brown Floor Tile			Material Not Present	Chrysotile	MISC					
051	Desk Top Linoleum			Material Not Present	No ACBM						
052	Desk Top Linoleum Adhesive			Material Not Present	No ACBM						
053	Black Vinyl Baseboard			Material Not Present	No ACBM						
054	Black Vinyl Baseboard Adhesive			Material Not Present	No ACBM						
055	12x12 Dk Beige w/Brown & White Streaks Floor Tile			Material Not Present	Chrysotile	MISC					
056	12" x 12" Blue Floor Tile			Material Not Present	No ACBM						
057	12" x 12" Blue Floor Tile Adhesive			Material Not Present	No ACBM						
058	Dark Gray Vinyl Baseboard			Material Not Present	No ACBM						
059	Dark Gray Vinyl Baseboard Adhesive			Material Not Present	No ACBM						

Chicago Public Schools

School

Air Force High School
(formerly Abbott School)

Unit

45231

Building ID

2010

Address

3630 S. Wells

Chicago, IL, 60609

Region

04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone:

(312) 762-2900

Fax:

(312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
060	12" x 12" Gray Mix Floor Tile			Material Not Present	No ACBM						
061	Mastic on 12" x 12" Gray Mix Floor Tile			Material Not Present	Chrysotile	MISC					
062	Cork Insulation			Fan Room by 214	No ACBM						
063	Vibration Isolator			Fan Room by 214	No ACBM						
064	12" x 12" Beige Floor Tile w/Brown & White Streaks			Material Not Present	No ACBM						
065	Mastic on 12"x12" Beige FT w/Brn & White Streaks			Material Not Present	No ACBM						
066	12" x 12" Light Brown Floor Tile			Material Not Present	No ACBM						
067	12" x 12" Light Brown Floor Tile Adhesive			Material Not Present	No ACBM						
068	12" x 12" Dark Pink Floor Tile			Material Not Present	No ACBM						
069	12" x 12" Dark Pink Floor Tile Adhesive			Material Not Present	No ACBM						
070	Fan Unit Door Lining Insulation			1946 Building, Basement	No ACBM						
071	9" x 9" Gray Floor Tile			Material Not Present	Chrysotile	MISC					
072	Mastic on 12" x 12" Gray Floor Tile			Material Not Present	Chrysotile	MISC					
073	Partition Wall Compound			Between 1953/60 Buildings, 1st and 2nd Floor Corridors	No ACBM						
074	9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office	Chrysotile	MISC	No	10	SF	6 ACBM with the potential for damage	Follow O&M Plan
075	Mastic on 9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
076	Dark Gray Vinyl Baseboard			Material Not Present	No ACBM						
077	Dark Gray Vinyl Baseboard Adhesive			Material Not Present	No ACBM						
078	Pump Floor/Unit Caulk			1960 Building, Boiler Room	No ACBM						
079	Boiler Gasket Material			Material Not Present	Chrysotile	TSI					
080	Interior Brick			1960 Building	No ACBM						
081	Interior Brick Mortar			1960 Building	No ACBM						
082	12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
083	Mastic on 12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
084	9" x 9" Orange Floor Tile	108	SF	1960 Building, Engineer's Office Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
085	Mastic on 9" x 9" Orange Floor Tile	108	SF	1960 building, Engineer's Office Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School

Air Force High School
(formerly Abbott School)

Unit

45231

Building ID

2010

Address

3630 S. Wells

Chicago, IL, 60609

Region

04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone:

(312) 762-2900

Fax:

(312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
086	12" x 12" Off White Floor Tile	30	SF	1960 Building, Store Room Toilet Across from Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
087	Mastic on 12" x 12" Off White Floor Tile	30	SF	1960 Building, Store Room Toilet Across from Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
088	12" x 12" Light Gray Mix Floor Tile			Material Not Present	No ACBM						
089	12" x 12" Light Gray Mix Floor Tile Mastic			Material Not Present	No ACBM						
090	Radiator Grill Lining Material			1960 Building	No ACBM						
091	Incinerator Gasket Material by Fire Hole			Material Not Present	Chrysotile	TSI					
092	Incinerator Interior Brick			Material Not Present	No ACBM						
093	Incinerator Ash Chamber Brick			Material Not Present	No ACBM						
094	Vibration Isolator			1946 Building, Fan Unit	No ACBM						
095	White Chalky Material and Soil Mix			1953 Building, Unfinished Pipe Space	No ACBM						
096	Vault Door Insulation			Material Not Present	Assumed	MISC					
097	Light Gray Vinyl Baseboard			Material Not Present	No ACBM						
098	Light Gray Vinyl Baseboard Adhesive			Material Not Present	No ACBM						
099	Beaver Board			Material Not Present	No ACBM						
100	Exterior Brick			1946 Building	No ACBM						
101	Exterior Brick Mortar			1946 Building	No ACBM						
102	Exterior Brick			1953 Building	No ACBM						
103	Exterior Brick Mortar			1953 Building	No ACBM						
104	Exterior Brick			1960 Building	No ACBM						
105	Exterior Brick Mortar			1960 Building	No ACBM						
106	Exterior Door Caulk (NON AHERA)			1960 Building	No ACBM						
107	Roofing Materials (NON AHERA)			1946 Building	Assumed						
108	Roofing Materials (NON AHERA)			1953 Building	Assumed						
109	Roofing Materials (NON AHERA)			1960 Building	Assumed						
110	Interior Window Caulk			Material Not Present	Assumed	MISC					
111	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT			Material Not Present	Assumed	MISC					
112	12" x 12" White w/Off White & Beige Streaks			Material Not Present	Assumed	MISC					
113	Mastic for HA 111 & HA 112 Checkerboard FT Pattern			Material Not Present	Assumed	MISC					
114	12" x 12" Red Floor Tile			Material Not Present	Assumed	MISC					
115	12" x 12" Red Floor Tile Mastic			Material Not Present	Assumed	MISC					

Chicago Public Schools

School

Air Force High School
(formerly Abbott School)

Unit

45231

Building ID

2010

Address

3630 S. Wells

Chicago, IL, 60609

Region

04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone:

(312) 762-2900

Fax:

(312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
116	12" x 12" Blue Floor Tile			Material Not Present	Assumed	MISC					
117	12" x 12" Blue Floor Tile Mastic			Material Not Present	Assumed	MISC					
118	Green Carpet Adhesive			Material Not Present	Assumed	MISC					
119	Acoustical Ceiling	10,000	SF	Throughout Hallways of the 1960 Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
120	12x12 beige mix floor tile			Material Not Present	Assumed	MISC					
121	mastic associated with 12x12 beige mix floor tile			Material Not Present	Assumed	MISC					
122	Red Carpet Adhesive			Material Not Present	Assumed	MISC					
123	Black Board/ Marker Board Adhesive	5,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	Grey and Black Mix Terrazzo Flooring	4,000	SF	East Enterances and Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12" X 12" Tand w/Brown and White Streaks Floor Tile			Material Not Present	Assumed	MISC					
126	12" X 12" Tand w/Brown and White Streaks Floor Tile Mastic			Material Not Present	Assumed	MISC					
127	Cork Board Adhesive			Material Not Present	Assumed	MISC					
128	Green Carpet Adhesive			Material Not Present	Assumed	MISC					
129	12"x12" White Mottled Floor Tile			Thtoughout Corridors, Classrooms, and Offices	No ACBM	MISC					
130	12"x12" White Mottled Floor Tile Mastic			Thtoughout Corridors, Classrooms, and Offices	No ACBM	MISC					
131	12"x12" Blue Mottled Floor Tile			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	No ACBM	MISC					
132	12"x12" Blue Mottled Floor Tile Mastic			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	No ACBM	MISC					
133	2'x2' Lay-in Ceiling Tile			First Floor Corridor	No ACBM	MISC					
134	2'x4' Lay-in Ceiling Tile			Rooms 112A, 126, and 226	No ACBM	MISC					
135	4" Gray Baseboard			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.	No ACBM	MISC					

Chicago Public Schools

School

Air Force High School
(formerly Abbott School)

Unit

45231

Building ID

2010

Address

3630 S. Wells

Chicago, IL, 60609

Region

04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone:

(312) 762-2900

Fax:

(312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
136	4" Gray Baseboard Mastic			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.	No ACBM	MISC					
137	Gray Sink Undercoating			Rooms 128, 130, and 133	No ACBM	MISC					
138	Carpet Mastic			Rooms 134 and 212	No ACBM	MISC					
139	Transite Laboratory Countertop	400	SF	Rooms 109 and 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	Wood Pattern Sheet Flooring			Gymnasium	No ACBM	MISC					
141	Wood Pattern Sheet Flooring Mastic			Gymnasium	No ACBM	MISC					
142	Blue Sheet Flooring	650	SF	Room 126	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	Blue Sheet Flooring Mastic	650	SF	Room 126	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	Transite Electrical Panel	200	SF	Basement Electrical Vault	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	Electrical Wiring Associated with Wall Mounted Clocks	150	LF	Throughout Building	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Distributed Pipe Insulation on Floor			Material Not Present	Chrysotile	MISC					
C	Aircell Pipe Insulation			1946 Building, Walls and Pipe Chases	Chrysotile	TSI					
D	Joint Compound off Fiberglass Pipe Insulation			Material Not Present	Chrysotile	TSI					
E	Joint Compound Off Fiberglass Pipe Insulation			Material Not Present	Chrysotile	TSI					
F	Distributed Pipe Insulation in Dirt on Floor			Material Not Present	Chrysotile	TSI					
G	Distributed Pipe Insulation in Dirt on Floor			Material Not Present	Chrysotile	TSI					
H	Aircell Pipe Insulation			Material Not Present	Chrysotile	TSI					
I	Aircell Pipe Insulation			Material Not Present	Chrysotile	TSI					
J	Paperwrap Pipe Insulation			1946 Building, Pipe Chases	No ACBM						
K	Hard Joint Compound off Paperwrap Pipe Insulation	75	LF	1946 Building, Walls and Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present	Chrysotile	TSI					
L-1	Hard Joint Compound off Aircell Pipe Insulation			1946 Building, Walls and Pipe Chases	Chrysotile	TSI					
M	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present	Chrysotile	TSI					
N	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present	Chrysotile	TSI					
O	Duct Interior Insulation			1960 Building, Boiler Room	No ACBM						
P	Magblock Pipe Insulation			Material Not Present	Amosite,	TSI					

Chicago Public Schools

School

Air Force High School
(formerly Abbott School)

Unit

45231

Building ID

2010

Address

3630 S. Wells

Chicago, IL, 60609

Region

04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone:

(312) 762-2900

Fax:

(312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
					Chrysotile						
Q	Magblock Pipe Insulation Joint Compound			Material Not Present	Chrysotile	TSI					
R	Water Tank Insulation			Material Not Present	Chrysotile	TSI					
S	Aircell Duct Insulation			Material Not Present	Chrysotile	TSI					
T	Magblock Insulation	15	LF	1946 Building, Coal/Ash Room Abandoned Mech. Unit	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
U	Duct Insulation - Black Tar Like Adhesive			1953 Building, Unfinished Pipe Spaces	Chrysotile	TSI					

Chicago Public Schools

School Air Force High School
 (formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	05/03/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
021	
022	
023	
024	
025	
026	
027	
028	
029	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	

Chicago Public Schools

School Air Force High School
 (formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
055	
056	
057	
058	
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	
073	
074	
075	
076	
077	
078	
079	

Chicago Public Schools

School Air Force High School
 (formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
080	
081	
082	
083	
084	
085	
086	
087	
088	
089	
090	
091	
092	
093	
094	
095	
096	
097	
098	
099	
100	
101	
102	
103	
104	

Chicago Public Schools

School Air Force High School
 (formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
B	
C	
D	
E	
F	
G	
H	
I	
J	

Chicago Public Schools

School Air Force High School
 (formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
K	
L	
L-1	
M	
N	
O	
P	
Q	
R	
S	
T	
U	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	006	
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/Brown & White Streaks	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007		
MATERIAL DESCRIPTION:	12"x12" Lt Brown Floor Tile w/Brn & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	007	
MATERIAL DESCRIPTION:	12"x12" Lt Brown Floor Tile w/Brn & White Streaks	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	008	
MATERIAL DESCRIPTION:	Mastic on 9" x 9" Dark Brown Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	008	
MATERIAL DESCRIPTION:	Mastic on 9" x 9" Dark Brown Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	009		
MATERIAL DESCRIPTION:	Mastic on 12x12 Dk Brn w/Brn & Wh Strks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	009	
MATERIAL DESCRIPTION:	Mastic on 12x12 Dk Brn w/Brn & Wh Strks Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	010		
MATERIAL DESCRIPTION:	Mastic on 12x12 Lt. Brown w/Brn & Wh Streaks FT		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building, Room 212A (MDF Room)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	010	
MATERIAL DESCRIPTION:	Mastic on 12x12 Lt. Brown w/Brn & Wh Streaks FT	
MATERIAL LOCATION:	1953 Building, Room 212A (MDF Room)	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	011	
MATERIAL DESCRIPTION:	Partition Floor Joiner Compound	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946/53 Connection by Room 104

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	011	
MATERIAL DESCRIPTION:	Partition Floor Joiner Compound	
MATERIAL LOCATION:	1946/53 Connection by Room 104	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	012		
MATERIAL DESCRIPTION:	12"x12" Lt Brown w/Brn & White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	012	
MATERIAL DESCRIPTION:	12"x12" Lt Brown w/Brn & White Streaks Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	013		
MATERIAL DESCRIPTION:	Mastic on 12 x 12 Lt Brn w/Brn & White Strks FT		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	013	
MATERIAL DESCRIPTION:	Mastic on 12 x 12 Lt Brn w/Brn & White Strks FT	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	014	
MATERIAL DESCRIPTION:	Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	014	
MATERIAL DESCRIPTION:	Carpet Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	015	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	015	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	016		
MATERIAL DESCRIPTION:	Black Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	016	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	017	
MATERIAL DESCRIPTION:	Sink Bottom Caulking	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	017	
MATERIAL DESCRIPTION:	Sink Bottom Caulking	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	018	
MATERIAL DESCRIPTION:	Plaster	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	018	
MATERIAL DESCRIPTION:	Plaster	
MATERIAL LOCATION:	1946 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	019		
MATERIAL DESCRIPTION:	Interior Brick Walls		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	019	
MATERIAL DESCRIPTION:	Interior Brick Walls	
MATERIAL LOCATION:	1946 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	020	
MATERIAL DESCRIPTION:	Interior Brick Walls Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	020	
MATERIAL DESCRIPTION:	Interior Brick Walls Mortar	
MATERIAL LOCATION:	1946 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	021	
MATERIAL DESCRIPTION:	12" x 12" Green Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	021	
MATERIAL DESCRIPTION:	12" x 12" Green Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	022	
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Green Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	022	
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Green Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023		
MATERIAL DESCRIPTION:	Tar Paper and Mastic in Vault Closet Areas		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	023	
MATERIAL DESCRIPTION:	Tar Paper and Mastic in Vault Closet Areas	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024		
MATERIAL DESCRIPTION:	Vibration Isolator		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Attic Above 200 and 201

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	024	
MATERIAL DESCRIPTION:	Vibration Isolator	
MATERIAL LOCATION:	1946 Building, Attic Above 200 and 201	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	025	
MATERIAL DESCRIPTION:	Fan Unit Door Lining	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Attic above 200 and 201

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	025	
MATERIAL DESCRIPTION:	Fan Unit Door Lining	
MATERIAL LOCATION:	1946 Building, Attic above 200 and 201	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	026	
MATERIAL DESCRIPTION:	Dirt on Floor	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	026	
MATERIAL DESCRIPTION:	Dirt on Floor	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	027		
MATERIAL DESCRIPTION:	Mastic on 12"x12" Beige w/Brown & White Streaks FT		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	027	
MATERIAL DESCRIPTION:	Mastic on 12"x12" Beige w/Brown & White Streaks FT	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	028	
MATERIAL DESCRIPTION:	Partition Wall Joiner Compound	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946/1953 Buildings by 104 & 204

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	028	
MATERIAL DESCRIPTION:	Partition Wall Joiner Compound	
MATERIAL LOCATION:	1946/1953 Buildings by 104 & 204	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	029		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/White & Brown Streaks FT		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	029	
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/White & Brown Streaks FT	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	030		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Floor Tile w/Beige Mix		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	030	
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Floor Tile w/Beige Mix	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	031		
MATERIAL DESCRIPTION:	Mastic on 12"x12" Dark Gray w/Beige Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	031	
MATERIAL DESCRIPTION:	Mastic on 12"x12" Dark Gray w/Beige Mix Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	032		
MATERIAL DESCRIPTION:	12" x 12" Light Beige Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	032	
MATERIAL DESCRIPTION:	12" x 12" Light Beige Mix Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	033		
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Light Beige Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	033	
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Light Beige Mix Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	034		
MATERIAL DESCRIPTION:	12" x 12" Dark Pink Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	034	
MATERIAL DESCRIPTION:	12" x 12" Dark Pink Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	035		
MATERIAL DESCRIPTION:	Adhesive for 12" x 12" Dark Pink Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	035	
MATERIAL DESCRIPTION:	Adhesive for 12" x 12" Dark Pink Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	036		
MATERIAL DESCRIPTION:	12" x 12" Dark Beige w/ Brown & White Streaks FT		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	036	
MATERIAL DESCRIPTION:	12" x 12" Dark Beige w/ Brown & White Streaks FT	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	037		
MATERIAL DESCRIPTION:	Mastic on 12x12 Dk Beige w/Brn & White Strks FT		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	037	
MATERIAL DESCRIPTION:	Mastic on 12x12 Dk Beige w/Brn & White Strks FT	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	038		
MATERIAL DESCRIPTION:	12" x 12" Light Gray Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	038	
MATERIAL DESCRIPTION:	12" x 12" Light Gray Mix Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	039		
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Light Gray Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	039	
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Light Gray Mix Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	040	
MATERIAL DESCRIPTION:	Gray and Yellow Mix Linoleum	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	040	
MATERIAL DESCRIPTION:	Gray and Yellow Mix Linoleum	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	041		
MATERIAL DESCRIPTION:	Burlap with Adhesive Under Grey & Yellow Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	041	
MATERIAL DESCRIPTION:	Burlap with Adhesive Under Grey & Yellow Linoleum	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	042	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	042	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	043		
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	043	
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Blue Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	044		
MATERIAL DESCRIPTION:	Mastic 12x12 Dk. Gray w/White & Brown Streaks FT		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	044	
MATERIAL DESCRIPTION:	Mastic 12x12 Dk. Gray w/White & Brown Streaks FT	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	045	
MATERIAL DESCRIPTION:	Interior Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	045	
MATERIAL DESCRIPTION:	Interior Brick	
MATERIAL LOCATION:	1953 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	046	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	046	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
MATERIAL LOCATION:	1953 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	047	
MATERIAL DESCRIPTION:	Plaster	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	047	
MATERIAL DESCRIPTION:	Plaster	
MATERIAL LOCATION:	1953 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	048		
MATERIAL DESCRIPTION:	Light Gray Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	048	
MATERIAL DESCRIPTION:	Light Gray Vinyl Baseboard	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	049	
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	049	
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	050		
MATERIAL DESCRIPTION:	Mastic on 9" x 9" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	050	
MATERIAL DESCRIPTION:	Mastic on 9" x 9" Brown Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	051	
MATERIAL DESCRIPTION:	Desk Top Linoleum	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	051	
MATERIAL DESCRIPTION:	Desk Top Linoleum	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	052		
MATERIAL DESCRIPTION:	Desk Top Linoleum Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	052	
MATERIAL DESCRIPTION:	Desk Top Linoleum Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	053	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	053	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	054	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	054	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	055		
MATERIAL DESCRIPTION:	12x12 Dk Beige w/Brown & White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	055	
MATERIAL DESCRIPTION:	12x12 Dk Beige w/Brown & White Streaks Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	056	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	056	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	057	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	057	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	058	
MATERIAL DESCRIPTION:	Dark Gray Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	058	
MATERIAL DESCRIPTION:	Dark Gray Vinyl Baseboard	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	059		
MATERIAL DESCRIPTION:	Dark Gray Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	059	
MATERIAL DESCRIPTION:	Dark Gray Vinyl Baseboard Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	060		
MATERIAL DESCRIPTION:	12" x 12" Gray Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	060	
MATERIAL DESCRIPTION:	12" x 12" Gray Mix Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	061	
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Gray Mix Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	061	
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Gray Mix Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	062	
MATERIAL DESCRIPTION:	Cork Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Fan Room by 214

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	062	
MATERIAL DESCRIPTION:	Cork Insulation	
MATERIAL LOCATION:	Fan Room by 214	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	063	
MATERIAL DESCRIPTION:	Vibration Isolator	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Fan Room by 214

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	063	
MATERIAL DESCRIPTION:	Vibration Isolator	
MATERIAL LOCATION:	Fan Room by 214	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	064		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	064	
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/Brown & White Streaks	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	065		
MATERIAL DESCRIPTION:	Mastic on 12"x12" Beige FT w/Brn & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	065	
MATERIAL DESCRIPTION:	Mastic on 12"x12" Beige FT w/Brn & White Streaks	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	066	
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	066	
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	067		
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	067	
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	068	
MATERIAL DESCRIPTION:	12" x 12" Dark Pink Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	068	
MATERIAL DESCRIPTION:	12" x 12" Dark Pink Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	069		
MATERIAL DESCRIPTION:	12" x 12" Dark Pink Floor Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	069	
MATERIAL DESCRIPTION:	12" x 12" Dark Pink Floor Tile Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	070	
MATERIAL DESCRIPTION:	Fan Unit Door Lining Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Basement

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	070	
MATERIAL DESCRIPTION:	Fan Unit Door Lining Insulation	
MATERIAL LOCATION:	1946 Building, Basement	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	071	
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	071	
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	072	
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Gray Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	072	
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Gray Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	073	
MATERIAL DESCRIPTION:	Partition Wall Compound	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Between 1953/60 Buildings, 1st and 2nd Floor Corridors

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	073	
MATERIAL DESCRIPTION:	Partition Wall Compound	
MATERIAL LOCATION:	Between 1953/60 Buildings, 1st and 2nd Floor Corridors	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	074		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Store Room by Engineer's Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	10	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	074				
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile				
MATERIAL LOCATION:	1960 Building, Store Room by Engineer's Office				
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	10	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	075		
MATERIAL DESCRIPTION:	Mastic on 9" x 9" Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	075				
MATERIAL DESCRIPTION:	Mastic on 9" x 9" Light Brown Floor Tile				
MATERIAL LOCATION:	1960 Building, Store Room by Engineer's Office				
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/03/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	076	
MATERIAL DESCRIPTION:	Dark Gray Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	076	
MATERIAL DESCRIPTION:	Dark Gray Vinyl Baseboard	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	077	
MATERIAL DESCRIPTION:	Dark Gray Vinyl Baseboard Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	077	
MATERIAL DESCRIPTION:	Dark Gray Vinyl Baseboard Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	078	
MATERIAL DESCRIPTION:	Pump Floor/Unit Caulk	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building, Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	078	
MATERIAL DESCRIPTION:	Pump Floor/Unit Caulk	
MATERIAL LOCATION:	1960 Building, Boiler Room	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	079	
MATERIAL DESCRIPTION:	Boiler Gasket Material	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	079	
MATERIAL DESCRIPTION:	Boiler Gasket Material	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	080	
MATERIAL DESCRIPTION:	Interior Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	080	
MATERIAL DESCRIPTION:	Interior Brick	
MATERIAL LOCATION:	1960 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	081	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	081	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
MATERIAL LOCATION:	1960 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	082		
MATERIAL DESCRIPTION:	12" x 12" Sandy Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 Building, Engineer's Office**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	082				
MATERIAL DESCRIPTION:	12" x 12" Sandy Beige Floor Tile				
MATERIAL LOCATION:	1960 Building, Engineer's Office				
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	083		
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Sandy Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 Building, Engineer's Office**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	083				
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Sandy Beige Floor Tile				
MATERIAL LOCATION:	1960 Building, Engineer's Office				
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/03/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	084		
MATERIAL DESCRIPTION:	9" x 9" Orange Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Engineer's Office Corridor		
MATERIAL QUANTITY:	108	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	084				
MATERIAL DESCRIPTION:	9" x 9" Orange Floor Tile				
MATERIAL LOCATION:	1960 Building, Engineer's Office Corridor				
MATERIAL QUANTITY:	108	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	085		
MATERIAL DESCRIPTION:	Mastic on 9" x 9" Orange Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 building, Engineer's Office Corridor**

MATERIAL QUANTITY: **108**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	085				
MATERIAL DESCRIPTION:	Mastic on 9" x 9" Orange Floor Tile				
MATERIAL LOCATION:	1960 building, Engineer's Office Corridor				
MATERIAL QUANTITY:	108	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/03/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	086		
MATERIAL DESCRIPTION:	12" x 12" Off White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Store Room Toilet Across from Engineer's Office		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	086		
MATERIAL DESCRIPTION:	12" x 12" Off White Floor Tile		
MATERIAL LOCATION:	1960 Building, Store Room Toilet Across from Engineer's Office		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	087		
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Off White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Store Room Toilet Across from Engineer's Office		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	087				
MATERIAL DESCRIPTION:	Mastic on 12" x 12" Off White Floor Tile				
MATERIAL LOCATION:	1960 Building, Store Room Toilet Across from Engineer's Office				
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/03/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	088	
MATERIAL DESCRIPTION:	12" x 12" Light Gray Mix Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	088	
MATERIAL DESCRIPTION:	12" x 12" Light Gray Mix Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	089		
MATERIAL DESCRIPTION:	12" x 12" Light Gray Mix Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	089	
MATERIAL DESCRIPTION:	12" x 12" Light Gray Mix Floor Tile Mastic	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	090		
MATERIAL DESCRIPTION:	Radiator Grill Lining Material		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	090	
MATERIAL DESCRIPTION:	Radiator Grill Lining Material	
MATERIAL LOCATION:	1960 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	091	
MATERIAL DESCRIPTION:	Incinerator Gasket Material by Fire Hole	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	091	
MATERIAL DESCRIPTION:	Incinerator Gasket Material by Fire Hole	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	092		
MATERIAL DESCRIPTION:	Incinerator Interior Brick		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	092	
MATERIAL DESCRIPTION:	Incinerator Interior Brick	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	093	
MATERIAL DESCRIPTION:	Incinerator Ash Chamber Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	093	
MATERIAL DESCRIPTION:	Incinerator Ash Chamber Brick	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	094	
MATERIAL DESCRIPTION:	Vibration Isolator	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Fan Unit

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	094	
MATERIAL DESCRIPTION:	Vibration Isolator	
MATERIAL LOCATION:	1946 Building, Fan Unit	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	095	
MATERIAL DESCRIPTION:	White Chalky Material and Soil Mix	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building, Unfinished Pipe Space

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	095	
MATERIAL DESCRIPTION:	White Chalky Material and Soil Mix	
MATERIAL LOCATION:	1953 Building, Unfinished Pipe Space	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	096	
MATERIAL DESCRIPTION:	Vault Door Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	096	
MATERIAL DESCRIPTION:	Vault Door Insulation	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	097	
MATERIAL DESCRIPTION:	Light Gray Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	097	
MATERIAL DESCRIPTION:	Light Gray Vinyl Baseboard	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	098	
MATERIAL DESCRIPTION:	Light Gray Vinyl Baseboard Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	098	
MATERIAL DESCRIPTION:	Light Gray Vinyl Baseboard Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	099	
MATERIAL DESCRIPTION:	Beaver Board	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	099	
MATERIAL DESCRIPTION:	Beaver Board	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100	
MATERIAL DESCRIPTION:	Exterior Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	100	
MATERIAL DESCRIPTION:	Exterior Brick	
MATERIAL LOCATION:	1946 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	Exterior Brick Mortar		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	101	
MATERIAL DESCRIPTION:	Exterior Brick Mortar	
MATERIAL LOCATION:	1946 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102	
MATERIAL DESCRIPTION:	Exterior Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	102	
MATERIAL DESCRIPTION:	Exterior Brick	
MATERIAL LOCATION:	1953 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103	
MATERIAL DESCRIPTION:	Exterior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	103	
MATERIAL DESCRIPTION:	Exterior Brick Mortar	
MATERIAL LOCATION:	1953 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	104	
MATERIAL DESCRIPTION:	Exterior Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	104	
MATERIAL DESCRIPTION:	Exterior Brick	
MATERIAL LOCATION:	1960 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105	
MATERIAL DESCRIPTION:	Exterior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	105	
MATERIAL DESCRIPTION:	Exterior Brick Mortar	
MATERIAL LOCATION:	1960 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	106	
MATERIAL DESCRIPTION:	Exterior Door Caulk (NON AHERA)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	106	
MATERIAL DESCRIPTION:	Exterior Door Caulk (NON AHERA)	
MATERIAL LOCATION:	1960 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	107	
MATERIAL DESCRIPTION:	Roofing Materials (NON AHERA)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	107	
MATERIAL DESCRIPTION:	Roofing Materials (NON AHERA)	
MATERIAL LOCATION:	1946 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	108	
MATERIAL DESCRIPTION:	Roofing Materials (NON AHERA)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	108	
MATERIAL DESCRIPTION:	Roofing Materials (NON AHERA)	
MATERIAL LOCATION:	1953 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109	
MATERIAL DESCRIPTION:	Roofing Materials (NON AHERA)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	109	
MATERIAL DESCRIPTION:	Roofing Materials (NON AHERA)	
MATERIAL LOCATION:	1960 Building	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110	
MATERIAL DESCRIPTION:	Interior Window Caulk	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	110	
MATERIAL DESCRIPTION:	Interior Window Caulk	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	111	
MATERIAL DESCRIPTION:	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12" x 12" White w/Off White & Beige Streaks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	112	
MATERIAL DESCRIPTION:	12" x 12" White w/Off White & Beige Streaks	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	Mastic for HA 111 & HA 112 Checkerboard FT Pattern		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	113	
MATERIAL DESCRIPTION:	Mastic for HA 111 & HA 112 Checkerboard FT Pattern	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	114	
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	114	
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	115	
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	115	
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile Mastic	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	116	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	116	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	117	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	117	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	118	
MATERIAL DESCRIPTION:	Green Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	118	
MATERIAL DESCRIPTION:	Green Carpet Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	119		
MATERIAL DESCRIPTION:	Acoustical Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Hallways of the 1960 Building		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	119				
MATERIAL DESCRIPTION:	Acoustical Ceiling				
MATERIAL LOCATION:	Throughout Hallways of the 1960 Building				
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	120	
MATERIAL DESCRIPTION:	12x12 beige mix floor tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	120	
MATERIAL DESCRIPTION:	12x12 beige mix floor tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	121		
MATERIAL DESCRIPTION:	mastic associated with 12x12 beige mix floor tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **mastic associated with 12x12 beige mix floor tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	122	
MATERIAL DESCRIPTION:	Red Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	122	
MATERIAL DESCRIPTION:	Red Carpet Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	123		
MATERIAL DESCRIPTION:	Black Board/ Marker Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	123		
MATERIAL DESCRIPTION:	Black Board/ Marker Board Adhesive		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/03/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	124		
MATERIAL DESCRIPTION:	Grey and Black Mix Terrazzo Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **East Enterances and Stairwells**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	124		
MATERIAL DESCRIPTION:	Grey and Black Mix Terrazzo Flooring		
MATERIAL LOCATION:	East Entrances and Stairwells		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/03/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	125		
MATERIAL DESCRIPTION:	12" X 12" Tand w/Brown and White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	125	
MATERIAL DESCRIPTION:	12" X 12" Tand w/Brown and White Streaks Floor Tile	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	126		
MATERIAL DESCRIPTION:	12" X 12" Tand w/Brown and White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	126	
MATERIAL DESCRIPTION:	12" X 12" Tand w/Brown and White Streaks Floor Tile Mastic	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	127	
MATERIAL DESCRIPTION:	Cork Board Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	127	
MATERIAL DESCRIPTION:	Cork Board Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	128	
MATERIAL DESCRIPTION:	Green Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	128	
MATERIAL DESCRIPTION:	Green Carpet Adhesive	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	129	
MATERIAL DESCRIPTION:	12"x12" White Mottled Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Thtoughout Corridors, Classrooms, and Offices

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	129	
MATERIAL DESCRIPTION:	12"x12" White Mottled Floor Tile	
MATERIAL LOCATION:	Throughout Corridors, Classrooms, and Offices	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	130	
MATERIAL DESCRIPTION:	12"x12" White Mottled Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Thtoughout Corridors, Classrooms, and Offices

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	130	
MATERIAL DESCRIPTION:	12"x12" White Mottled Floor Tile Mastic	
MATERIAL LOCATION:	Throughout Corridors, Classrooms, and Offices	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	131	
MATERIAL DESCRIPTION:	12"x12" Blue Mottled Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	131	
MATERIAL DESCRIPTION:	12"x12" Blue Mottled Floor Tile	
MATERIAL LOCATION:	Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	132	
MATERIAL DESCRIPTION:	12"x12" Blue Mottled Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	132	
MATERIAL DESCRIPTION:	12"x12" Blue Mottled Floor Tile Mastic	
MATERIAL LOCATION:	Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	133	
MATERIAL DESCRIPTION:	2'x2' Lay-in Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: First Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	133	
MATERIAL DESCRIPTION:	2'x2' Lay-in Ceiling Tile	
MATERIAL LOCATION:	First Floor Corridor	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	134	
MATERIAL DESCRIPTION:	2'x4' Lay-in Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 112A, 126, and 226

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	134	
MATERIAL DESCRIPTION:	2'x4' Lay-in Ceiling Tile	
MATERIAL LOCATION:	Rooms 112A, 126, and 226	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	135	
MATERIAL DESCRIPTION:	4" Gray Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	135		
MATERIAL DESCRIPTION:	4" Gray Baseboard		
MATERIAL LOCATION:	Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	136	
MATERIAL DESCRIPTION:	4" Gray Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	136		
MATERIAL DESCRIPTION:	4" Gray Baseboard Mastic		
MATERIAL LOCATION:	Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	137	
MATERIAL DESCRIPTION:	Gray Sink Undercoating	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 128, 130, and 133

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	137	
MATERIAL DESCRIPTION:	Gray Sink Undercoating	
MATERIAL LOCATION:	Rooms 128, 130, and 133	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	138	
MATERIAL DESCRIPTION:	Carpet Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 134 and 212

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	138	
MATERIAL DESCRIPTION:	Carpet Mastic	
MATERIAL LOCATION:	Rooms 134 and 212	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	139		
MATERIAL DESCRIPTION:	Transite Laboratory Countertop		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109 and 226		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	139		
MATERIAL DESCRIPTION:	Transite Laboratory Countertop		
MATERIAL LOCATION:	Rooms 109 and 226		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	140	
MATERIAL DESCRIPTION:	Wood Pattern Sheet Flooring	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	140	
MATERIAL DESCRIPTION:	Wood Pattern Sheet Flooring	
MATERIAL LOCATION:	Gymnasium	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	141	
MATERIAL DESCRIPTION:	Wood Pattern Sheet Flooring Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gymnasium

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	141	
MATERIAL DESCRIPTION:	Wood Pattern Sheet Flooring Mastic	
MATERIAL LOCATION:	Gymnasium	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	142		
MATERIAL DESCRIPTION:	Blue Sheet Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 126		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	142		
MATERIAL DESCRIPTION:	Blue Sheet Flooring		
MATERIAL LOCATION:	Room 126		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	143		
MATERIAL DESCRIPTION:	Blue Sheet Flooring Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY: **650**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	143		
MATERIAL DESCRIPTION:	Blue Sheet Flooring Mastic		
MATERIAL LOCATION:	Room 126		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/03/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	144		
MATERIAL DESCRIPTION:	Transite Electrical Panel		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Electrical Vault		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	144		
MATERIAL DESCRIPTION:	Transite Electrical Panel		
MATERIAL LOCATION:	Basement Electrical Vault		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/03/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	145		
MATERIAL DESCRIPTION:	Electrical Wiring Associated with Wall Mounted Clocks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	145		
MATERIAL DESCRIPTION:	Electrical Wiring Associated with Wall Mounted Clocks		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B	
MATERIAL DESCRIPTION:	Distributed Pipe Insulation on Floor	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Distributed Pipe Insulation on Floor**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Walls and Pipe Chases

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	C	
MATERIAL DESCRIPTION:	Aircell Pipe Insulation	
MATERIAL LOCATION:	1946 Building, Walls and Pipe Chases	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Joint Compound off Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Joint Compound off Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Joint Compound Off Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Joint Compound Off Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Distributed Pipe Insulation in Dirt on Floor		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Distributed Pipe Insulation in Dirt on Floor**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Distributed Pipe Insulation in Dirt on Floor		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Distributed Pipe Insulation in Dirt on Floor**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H	
MATERIAL DESCRIPTION:	Aircell Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	H	
MATERIAL DESCRIPTION:	Aircell Pipe Insulation	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Pipe Chases

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**

MATERIAL LOCATION: **1946 Building, Pipe Chases**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Hard Joint Compound off Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1946 Building, Walls and Pipe Chases		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	K				
MATERIAL DESCRIPTION:	Hard Joint Compound off Paperwrap Pipe Insulation				
MATERIAL LOCATION:	1946 Building, Walls and Pipe Chases				
MATERIAL QUANTITY:	75	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/03/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Hard Joint Compound off Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L-1		
MATERIAL DESCRIPTION:	Hard Joint Compound off Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Walls and Pipe Chases

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **L-1**

MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**

MATERIAL LOCATION: **1946 Building, Walls and Pipe Chases**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Hard Joint Compound off Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Hard Joint Compound off Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Hard Joint Compound off Aircell Pipe Insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	O		
MATERIAL DESCRIPTION:	Duct Interior Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building, Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Duct Interior Insulation**

MATERIAL LOCATION: **1960 Building, Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P		
MATERIAL DESCRIPTION:	Magblock Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Amosite, Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Magblock Pipe Insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Q		
MATERIAL DESCRIPTION:	Magblock Pipe Insulation Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Magblock Pipe Insulation Joint Compound**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	R		
MATERIAL DESCRIPTION:	Water Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	R	
MATERIAL DESCRIPTION:	Water Tank Insulation	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	S	
MATERIAL DESCRIPTION:	Aircell Duct Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	S	
MATERIAL DESCRIPTION:	Aircell Duct Insulation	
MATERIAL LOCATION:	Material Not Present	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	T		
MATERIAL DESCRIPTION:	Magblock Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1946 Building, Coal/Ash Room Abandoned Mech. Unit		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	T		
MATERIAL DESCRIPTION:	Magblock Insulation		
MATERIAL LOCATION:	1946 Building, Coal/Ash Room Abandoned Mech. Unit		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/5/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	U		
MATERIAL DESCRIPTION:	Duct Insulation - Black Tar Like Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building, Unfinished Pipe Spaces

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/3/2019		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-04437		

HOMOGENEOUS AREA:	U				
MATERIAL DESCRIPTION:	Duct Insulation - Black Tar Like Adhesive				
MATERIAL LOCATION:	1953 Building, Unfinished Pipe Spaces				
MATERIAL QUANTITY:				MATERIAL UNITS:	
DAMAGE QUANTITY:				DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 04437

ISSUED
4/15/2019

EXPIRES
05/15/2020

MARY H HICKS
12823 S GREEN
CHICAGO, IL 60643

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/18/2020

MANAGEMENT PLANNER

3/18/2020

PROJECT MANAGER

4/27/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MARY HICKS
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR05

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
37 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

N. Penneff

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MARY HICKS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR08

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
37 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

N. J. Peneff

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019



Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed