

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0023
SCHOOL NAME: Kelvyn Park High School
ADDRESS OF SCHOOL: 4343 W. Wrightwood Ave.
CITY: Chicago, IL, 60639

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/9/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 425
IDPH INSPECTOR LICENSE NUMBER: 100-18350
IDPH LICENSED INSPECTOR NAME(Please Print): Joseph Hennigan
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Kelvyn Park High School

4343 W. Wrightwood Ave.
Chicago, IL, 60639

Unit: 46191
Building ID: 1410

IDPH ID Number: 14-016-2990-0023

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

GSG-Probe Consulting, Inc.

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

September 30, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46191 Region: 02 IDPH ID:14-016-2990-0023

School: Kelvyn Park High School Building ID: 1410

Address: 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/22/2019

Inspector: Joseph Hennigan

Inspector IDPH License: 100-18350

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,
GSG-Probe Consulting, Inc.

Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 30, 2019

RE: Kelvyn Park High School, Unit 46191
4343 W. Wrightwood Ave.
Chicago, IL, 60639

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Kelvyn Park High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Kelvyn Park High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Kelvyn Park High School	Unit:	46191	Region:	02
Address:	4343 W. Wrightwood Ave.	Chicago, IL,	60639		
IDPH ID:	14-016-2990-0023	Building ID:	1410		
Contact:		Phone:			

2. Description of Facility

Original Construction:	1918	Additional Construction:	1928
Total Square Footage:	98284	No of Floors:	3
Current Occupancy:	425		

3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	42 West Madison Street		
	Chicago, IL 60602		

4. Managing Environmental Consultant

MEC:	GSG-Probe Consulting, Inc.		
Contact:	Jigar Shah		
Address	2942 W. Van Buren		
	Chicago, IL, 60612		
Phone:	3123197575	Fax:	

5. Inspector

Inspector Name: Joseph Hennigan

Inspector IDPH license #	100-18350	Signature:	
		Date:	9/30/2019

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license #	100-07342	Signature:	
		Date:	10/22/2019

7. Review Date:10/22/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Kelvyn Park High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1410:

B. The following new homogenous areas have been identified for Building 1410:

093B	9" x 9" Light Brown VFT
093C	9" x 9" Light Brown VFT Mastic
140	2' x 4' White w/ Dots & Pinholes Ceiling Tile
140B	2' x 4' White w/ Dots & Pinholes Ceiling Tile
141	Cloth Wire Insulation
141B	Cloth Wire Insulation
142	12" x 12" Light Gray w/ White & Gray Specks VFT
142A	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic
142B	12" x 12" Light Gray w/ White & Gray Specks VFT
142C	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic
143	12" x 12" Black w/ Gray Streaks VFT
143A	12" x 12" Black w/ Gray Streaks VFT Mastic
143B	12" x 12" Black w/ Gray Streaks VFT
143C	12" x 12" Black w/ Gray Streaks VFT Mastic
144	12" x 12" Light Gray w/ Multicolor Specks VFT
144A	12" x 12" Light Gray w/ Multicolor Specks VFT Mastic
145	12" x 12" White w/ Beige Streaks VFT
145A	12" x 12" White w/ Beige Streaks VFT Mastic
146	Light Gray w/ Dark Gray Specks Linoleum
146A	Light Gray w/ Dark Gray Specks Linoleum Mastic
147	12" x 12" Dark Gray w/ White & Gray Specks VFT

147A	12" x 12" Dark Gray w/ White & Gray Specks VFT Mastic
148	Vinyl Basboard Adhesive
149	Drywall System (wallboard, joint compound & tape)
150	Hardcoat Plaster
151	Hardcoat Plaster
152	Hardcoat Plaster
56A	MJP on Aircell Pipe Insulaion

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

008A	12" x 12" Black w/ Brown Streaks Floor Tile Mastic
080	MJP E/F/V on Fiberglass Pipe Insulation
092	9" x 9" Gray w/Speckles Floor Tile
092A	9" x 9" Gray w/Speckles VFT Mastic
093B	9" x 9" Light Brown VFT
093C	9" x 9" Light Brown VFT Mastic
098	12" x 12" Light Brown w/ White & Dark Streaks Floor Tile
098A	12" x 12" Light Brown w/ White & Dark Streaks Floor Tile Mastic
099	12" x 12" Gray Floor Tile
099A	12" x 12" Gray Floor Tile Mastic
101	12" x 12" Light Pink Floor Tile - (NOT OBSERVED)
101A	12" x 12" Light Pink Floor Tile Mastic - (NOT OBSERVED)
102	12" x 12" Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)
102A	12" x 12" Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)
103	12" x 12" Light Beige w/ White Streaks Floor Tile
103A	12" x 12" Light Beige w/ White Streaks VFT Mastic
104	12" x 12" Light Blue Floor Tile
106	12" x 12" Tan w/ Brown & White Spots VFT
107	12" x 12" Tan w/ Brown & White Spots VFT Mastic
108	12" x 12" Grey W/ Specks VFT
109	12" x 12" Grey W/ Specks VFT Mastic
110	Blue Linoleum
110A	Blue Linoleum Mastic
111	12" x 12" Black w/White Specks Floor Tile
111A	12" x 12" Black w/White Specks Floor Tile Mastic
112	12" x 12" Blue w/White Specks Floor Tile
112A	12" x 12" Blue w/White Specks Floor Tile Mastic
113	12" x 12" White w/Specks Floor Tile
113A	12" x 12" White w/Specks Floor Tile Mastic
114	12" x 12" Light Blue w/Specks Floor Tile
114A	12" x 12" Light Blue w/Specks Floor Tile Mastic
115	Blue Carpet Adhesive
116	12" x 12" Ceramic Tile Grout
117	12" x 12" Ceramic Tile Adhesive
118	2' x 4' White with swirls ceiling tile
119	12" x 12" Yellow Speckle VFT

120	12" x 12" Yellow Speckle VFT Mastic
121	12" x 12" Black with white specks VFT (DUPLICATE OF 001)
122	12" x 12" Black with white specks VFT Mastic (DUPLICATE OF 004A)
123	12" x 12" Yellow speckled VFT
124	12" x 12" Yellow speckled VFT Mastic
125	12" x 12" Black with dark brown specks VFT
126	12" x 12" Black with dark brown specks VFT Mastic
127	12" x 12" Blue speckled VFT
128	12" x 12" Blue speckled VFT mastic
129	12" x 12" Gray speckled VFT
130	12" x 12" Gray speckled VFT Mastic
131	Fume Hood
132	12" x 12" Gray, Black and Beige VFT
133	12" x 12" Gray, Black and Beige VFT Mastic
134	12" x 12" Gray, Black and White VFT
135	12" x 12" Gray, Black and White VFT Mastic
136	12" x 12" Gray and Black VFT
137	12" x 12" Gray and Black VFT Mastic
138	12" x 12" White VFT
139	12" x 12" White VFT Mastic
140	2' x 4' White w/ Dots & Pinholes Ceiling Tile
140B	2' x 4' White w/ Dots & Pinholes Ceiling Tile
141	Cloth Wire Insulation
141B	Cloth Wire Insulation
142	12" x 12" Light Gray w/ White & Gray Specks VFT
142A	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic
142B	12" x 12" Light Gray w/ White & Gray Specks VFT
142C	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic
143	12" x 12" Black w/ Gray Streaks VFT
143A	12" x 12" Black w/ Gray Streaks VFT Mastic
143B	12" x 12" Black w/ Gray Streaks VFT
143C	12" x 12" Black w/ Gray Streaks VFT Mastic
144	12" x 12" Light Gray w/ Multicolor Specks VFT
144A	12" x 12" Light Gray w/ Multicolor Specks VFT Mastic
145	12" x 12" White w/ Beige Streaks VFT
145A	12" x 12" White w/ Beige Streaks VFT Mastic
146	Light Gray w/ Dark Gray Specks Linoleum
146A	Light Gray w/ Dark Gray Specks Linoleum Mastic
147	12" x 12" Dark Gray w/ White & Gray Specks VFT
147A	12" x 12" Dark Gray w/ White & Gray Specks VFT Mastic
148	Vinyl Basboard Adhesive

149	Drywall System (wallboard, joint compound & tape)
150	Hardcoat Plaster
151	Hardcoat Plaster
152	Hardcoat Plaster
56A	MJP on Aircell Pipe Insulaion
B	2'x4' White Wormy Ceiling Tile
C	2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)
D	2'x4' Dark White w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)
E	2'x4' Off White Large Wormy Ceiling Tile
F	1'x1' Off White Wormy Ceiling Tile
G	1'x1' Off White Large Wormy Ceiling Tile
H	Spray-on Fireproofing (Walls & Beams above Grid)
I	18"x18" Dirty White Ceiling Tile
J	1'x1' Dirty White Ceiling Tile
K	2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)
L	1'x1' White Wormy Ceiling Tile
N	Sheeted Walls

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Joseph Hennigan, IDPH License # 100-18350. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Kelvyn Park High School Building 1410 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410
Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001A	1' x 1' Black w/ White Streaks Floor Tile	13,500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206, 1st Floor Womens, Mens and Unisex Restrooms under Stairwell - 1918 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
004A	1' x 1' Black w/ White Streaks Floor Tile Mastic	13,500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206, 1st Floor Womens, Mens and Unisex Restrooms under Stairwell - 1918 Bldg. NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006A	1' x 1' Black w/ Brown Streaks Floor Tile (NOT OBSERVED)	900	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007A	9" x 9" Dark Red Floor Tile - (NOT OBSERVED)	4,000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008A	12" x 12" Black w/ Brown Streaks Floor Tile Mastic	2,400	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
009A	9" x 9" Dark Red Floor Tile Mastic - (NOT OBSERVED)	4,000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
017	Boiler Gasket (Abated)			Boiler Room - 1918	ABATED	TSI						Any remaining friable		

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg								ACBM or friable suspect ACBM		
018	Boiler Insulation (Abated)			Boiler Room - 1918 Bldg	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
019	Boiler Lagging (Abated)			Boiler Room - 1918 Bldg	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
020	Boiler Brick - Abated			Boiler Room - 1918 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
040	Vent Debris (Removed)			Inside Ducts - Throughout 1918 Bldg	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
057	Cardboard Pipe Insulation	1,500	LF	1st Floor Janitor Closet (West), Above Corridor Ceilings - 1918 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
058	Aircell Pipe Insulation	1,500	LF	1st Floor Janitor Closet (West), Above Corridor Ceilings, 2nd Floor Staff Lounge 211 - 1918 Bldg.	CHR	TSI	Y	DIST	2		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
080	MJP E/F/V on Fiberglass Pipe Insulation	300	FITTING	1st Floor: Men's Toilet Pipe Chases, Rooms 119 & 123, Throughout Basement - 1928 Bldg.	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
087	1' x 1' Brown w/ White Streaks Floor Tile	4,200	SF	Rooms 398, 300, 302, 304, 311, 398 - 1918 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
087A	1' x 1' Brown w/ White Streaks Floor Tile Mastic	4,200	SF	Rooms 398, 300, 302, 304, 311 - 1918 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
088	12" x 12" Off White w/ Speckles Floor Tile	6,400	SF	Rooms 398, 300, 302, 304, 311 - 1918 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
088A	12" x 12" Off White w/ Speckles Floor Tile Mastic	6,400	SF	Rooms 398, 300, 302, 304, 311 - 1918 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
090	12" x 12" Green w/White Speckles Floor Tile	2,500	SF	2nd Floor Kitchen, Serving Area.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Managers Office - 1928 Bldg.										
090A	12" x 12" Green w/White Speckles Floor Tile Mastic	2,500	SF	2nd Floor Kitchen, Serving Area, Managers Office - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
092	9" x 9" Gray w/Speckles Floor Tile	5,000	SF	Main Office (211) Closet, Auditorium (Not Observed), 2nd Floor Corridor Closet - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
092A	9" x 9" Gray w/Speckles VFT Mastic	5,000	SF	Main Office (211) Closet, Auditorium (Not Observed), 2nd Floor Corridor Closet - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
093	9" x 9" Light Brown Floor Tile	2,700	SF	Room 205, 107 Closet, 105 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.	CHR	MISC	N	NONE	2		No	ACBM with potential for significant damage	5	LOW
093A	9" x 9" Light Brown Floor Tile Mastic	3,000	SF	Room 205, 107 Closet, 105 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
093B	9" x 9" Light Brown VFT	50	SF	Room 125 Vault - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
093C	9" x 9" Light Brown VFT Mastic	50	SF	Room 125 Vault - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
094	9" x 9" Beige w/ Green Streaks Floor Tile	250	SF	Room 211 Locker and Restroom - 1918 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
094A	9" x 9" Beige w/ Green Streaks VFT Mastic	250	SF	Room 211 Locker and Restroom - 1918 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
097	9" x 9" Black Floor Tile (Not Observed)	6,000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
097A	9" x 9" Black Floor Tile Mastic - (NOT OBSERVED)	6,000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
098	12" x 12" Light Brown w/ White & Dark	4,800	SF	Room 213, 215, 1st	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Streaks Floor Tile			Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.								potential for damage		
098A	12" x 12" Light Brown w/ White & Dark Streaks Floor Tile Mastic	4,800	SF	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
099	12" x 12" Gray Floor Tile	5,500	SF	3rd Floor Computer Room & Office; Rooms 113, 119, 123, 221 & 227 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
099A	12" x 12" Gray Floor Tile Mastic	5,500	SF	3rd Floor Computer Room & Office; Rooms 113, 119, 123, 221 & 227 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100	12" x 12" Light Brown VFT - (NOT OBSERVED)	1,800	SF	3rd Floor Corridor to Room 314, Rooms 121, 223 & 227 - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100A	12" x 12" Light Brown Floor Tile Mastic - (NOT OBSERVED)	3,300	SF	3rd Floor Corridor to Room 314, Rooms 121, 223 & 227 - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	12" x 12" Light Pink Floor Tile - (NOT OBSERVED)	1,600	SF	Rooms 113, 125, 221 & 223 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101A	12" x 12" Light Pink Floor Tile Mastic - (NOT OBSERVED)	1,600	SF	Rooms 113, 125, 221 & 223 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	12" x 12" Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)	1,600	SF	Rooms 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102A	12" x 12" Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)	1,600	SF	Rooms 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	12" x 12" Light Beige w/ White Streaks Floor Tile	1,950	SF	Rooms 117, 121, 123 & 125 - 1928	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.										
103A	12" x 12" Light Beige w/ White Streaks VFT Mastic	1,950	SF	Rooms 117, 121, 123 & 125 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12" x 12" Light Blue Floor Tile	1,150	SF	Room 312B, Gym, ROTC - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	12" x 12" Light Blue Floor Tile Mastic	1,150	SF	Room 312B, Gym, ROTC - 1918 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12" x 12" Tan w/ Brown & White Spots VFT	3,000	SF	Rooms 099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers, Room 312, Gym, ROTC - 1918 Bldg. Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12" x 12" Tan w/ Brown & White Spots VFT Mastic	3,000	SF	Rooms 099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers, Room 312, Gym, ROTC - 1918 Bldg. Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12" x 12" Grey W/ Specks VFT	6,000	SF	1st Floor Corridor, Old Engineers Former Office - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12" x 12" Grey W/ Specks VFT Mastic	6,000	SF	1st Floor Corridor, Old Engineers Former Office - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	Blue Linoleum	3,200	SF	Rooms 115, 221, 225, 227 - 1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110A	Blue Linoleum Mastic	3,200	SF	Rooms 115, 221, 225, 227 - 1928	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
111	12" x 12" Black w/White Specks Floor Tile	800	SF	Bldg Music Room (313), 319, 323, 327 - 1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111A	12" x 12" Black w/White Specks Floor Tile Mastic	800	SF	Music Room (313), 319, 323, 327 - 1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	12" x 12" Blue w/White Specks Floor Tile	700	SF	Music Room (313) - 1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112A	12" x 12" Blue w/White Specks Floor Tile Mastic	700	SF	Music Room (313) - 1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	12" x 12" White w/Specks Floor Tile	1,400	SF	Rooms 316, 318, 216, 220 - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113A	12" x 12" White w/Specks Floor Tile Mastic	1,400	SF	Rooms 316, 318, 216, 220 - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12" x 12" Light Blue w/Specks Floor Tile	200	SF	Room 400 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114A	12" x 12" Light Blue w/Specks Floor Tile Mastic	200	SF	Room 400 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	Blue Carpet Adhesive	3,800	SF	Library, Main Office, Principal's Office and Rooms 104 and 211; 205, 207, 209A, 209B, 219 - 1918 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	12" x 12" Ceramic Tile Grout	1,300	SF	Main Office, Library (100) - 1918 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12" x 12" Ceramic Tile Adhesive	1,300	SF	Main Office, Library (100) - 1918 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	2' x 4' White with swirls ceiling tile	2,400	SF	Rooms 216, 220, 316, 318 - 1999 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
119	12" x 12" Yellow Speckle VFT	11,700	SF	1st and 2nd floor corridors, 3rd Floor E-W Corridor, Room 104, Auditorium - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	12" x 12" Yellow Speckle VFT Mastic	11,700	SF	1st and 2nd floor corridors, 3rd Floor E-W Corridor, Room 104,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Auditorium - 1918 Bldg.										
121	12" x 12" Black with white specks VFT (DUPLICATE OF 001)	3,600	SF	2nd and 3rd floor corridors - 1928 bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	12" x 12" Black with white specks VFT Mastic (DUPLICATE OF 004A)	3,600	SF	2nd and 3rd floor corridors - 1928 bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
123	12" x 12" Yellow speckled VFT	14,200	SF	2nd and 3rd floor corridors - 1928 bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
124	12" x 12" Yellow speckled VFT Mastic	14,200	SF	2nd and 3rd floor corridors - 1928 bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
125	12" x 12" Black with dark brown specks VFT	650	SF	Room 206 (Not Observed), 398 Office - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
126	12" x 12" Black with dark brown specks VFT Mastic	650	SF	Room 206 (Not Observed), 398 Office - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
127	12" x 12" Blue speckled VFT	500	SF	Room 211 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
128	12" x 12" Blue speckled VFT mastic	500	SF	Room 211 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
129	12" x 12" Gray speckled VFT	600	SF	Room 211 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
130	12" x 12" Gray speckled VFT Mastic	600	SF	Room 211 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131	Fume Hood	40	SF	Room 223 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132	12" x 12" Gray, Black and Beige VFT	2,400	SF	Rooms 327, 323, 319 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133	12" x 12" Gray, Black and Beige VFT Mastic	2,400	SF	Rooms 327, 323, 319 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	12" x 12" Gray, Black and White VFT	3,350	SF	2nd floor main office, Rooms 104, 105 (Not Observed), 312 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
135	12" x 12" Gray, Black and White VFT Mastic	3,350	SF	2nd floor main office, Rooms 104, 105 (Not Observed), 312 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
136	12" x 12" Gray and Black VFT	5,600	SF	Rooms 107G, 205, 206, 211, 303, 304,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				308 - 1918 Bldg.										
137	12" x 12" Gray and Black VFT Mastic	5,600	SF	Rooms 107G, 205, 206, 211, 303, 304, 308 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
138	12" x 12" White VFT	17,500	SF	1st and 3rd floor corridors, Elevator Machine Room - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
139	12" x 12" White VFT Mastic	17,500	SF	1st and 3rd floor corridors, Elevator Machine Room - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
140	2' x 4' White w/ Dots & Pinholes Ceiling Tile	3,000	SF	Rooms 212, 209, 112, 199 ROTC Office - 1918 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
140B	2' x 4' White w/ Dots & Pinholes Ceiling Tile	3,500	SF	Room 123, 125, 223, 119, 117, Engineer's Office - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
141	Cloth Wire Insulation	5	LF	Wall Heaters in Engineer's Office, Main Office (above vault), Main Office Restroom - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
141B	Cloth Wire Insulation	1	LF	Boys Locker Room Rear Stairwell - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142	12" x 12" Light Gray w/ White & Gray Specks VFT	5,075	SF	Rooms 300, 302, 303, 304, 312, 309, 206, 212, 103, 107 & Closet, 109 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142A	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic	5,075	SF	Rooms 300, 302, 303, 304, 312, 309, 206, 212, 103, 107 & Closet, 109 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142B	12" x 12" Light Gray w/ White & Gray Specks VFT	1,000	SF	Rooms 129, 313 & Vestibule - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142C	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic	1,000	SF	Room 129, 313 & Vestibule - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143	12" x 12" Black w/ Gray Streaks VFT	2,245	SF	Rooms 300, 206, 303, Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Vestibule, 309, 302, 304, 312, 212, 103, 109, 107 & Closet - 1918 Bldg.										
143A	12" x 12" Black w/ Gray Streaks VFT Mastic	2,245	SF	Rooms 300, 206, 303, Elevator Vestibule, 309, 302, 304, 312, 212, 103, 109, 107 & Closet - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143B	12" x 12" Black w/ Gray Streaks VFT	782	SF	Room 129, 313 & Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143C	12" x 12" Black w/ Gray Streaks VFT Mastic	782	SF	Room 129, 313 & Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144	12" x 12" Light Gray w/ Multicolor Specks VFT	800	SF	Room 125 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144A	12" x 12" Light Gray w/ Multicolor Specks VFT Mastic	800	SF	Room 125 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
145	12" x 12" White w/ Beige Streaks VFT	72	SF	Room 201B - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
145A	12" x 12" White w/ Beige Streaks VFT Mastic	72	SF	Room 201B - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
146	Light Gray w/ Dark Gray Specks Linoleum	800	SF	Room 229 Lab Prep Room, 223 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
146A	Light Gray w/ Dark Gray Specks Linoleum Mastic	800	SF	Room 229 Lab Prep Room, 223 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
147	12" x 12" Dark Gray w/ White & Gray Specks VFT	300	SF	Room 212 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
147A	12" x 12" Dark Gray w/ White & Gray Specks VFT Mastic	300	SF	Room 212 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148	Vinyl Basboard Adhesive	1,000	LF	Rooms 316, 316A, 318, 216, 220 - 1999 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
149	Drywall System (wallboard, joint compound & tape)	3,000	SF	Throughout Various Locations - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
150	Hardcoat Plaster	75,000	SF	Throughout - 1918 Bldg.	ASSUMED	SURFACE	N	NONE	30		No	ACBM with potential for significant damage	10	LOW
151	Hardcoat Plaster	75,000	SF	Throughout - 1928 Bldg.	ASSUMED	SURFACE	N	NONE	20		No	ACBM with potential for significant damage	10	LOW
152	Hardcoat Plaster	15,000	SF	Throughout - 1999 Addition	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
56	Aircell Pipe Insulation	1,500	LF	SW Unexcavated Area, Above Corridor Ceilings - 1928 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		
56A	MJP on Aircell Pipe Insulaion	50	FITTING	Above Corridor Ceilings, 125 Prep Room, 1st Floor Janitors Closets - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
B	2'x4' White Wormy Ceiling Tile	2,850	SF	Rooms 206 Closet, 208 & 398, 302, 304, 200 & 300 - 1918 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
C	2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)		SF	Rooms 200 & 300 - 1918 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	2'x4' Dark White w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)	900	SF	Rooms 104 & 300 - 1918 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	2'x4' Off White Large Wormy Ceiling Tile	300	SF	Room 208 - 1918 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	1'x1' Off White Wormy Ceiling Tile	2,400	SF	ROTC, ROTC Office, Rooms 110 & 212, Engineer's Former Office - 1918 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	1'x1' Off White Large Wormy Ceiling Tile	1,500	SF	ROTC, Room 212, Cafeteria by Lunchroom & Auditorium - 1918 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Spray-on Fireproofing (Walls & Beams above Grid)	800	SF	3rd Floor Computer Room, 316, 316A, 318, 220, 216 - 1999 Bldg.	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	18"x18" Dirty White Ceiling Tile	1,000	SF	3rd Floor Music Room - 1928 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	1'x1' Dirty White Ceiling Tile	200	SF	Room 314 East & West Vestibule - 1928 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)	1,200	SF	Rooms 127 & 220 - 1928 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	1'x1' White Wormy Ceiling Tile	1,400	SF	Rooms 123 and 213 - 1928 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M	Transite Table Tops	1,250	SF	Rooms 123, 125, 127, 221, 223, 225,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410
Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612
Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				227 - 1928 Bldg. (129 Abated in 2003)										
N	Sheeted Walls	800	SF	1st Floor Supply Storage near Exit - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410
Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>9/30/2019</u>
Inspector Name	<u>Joseph Hennigan</u>
<u>100-18350</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
001A	
004A	
006A	
007A	
008A	
009A	
017	
018	
019	
020	
040	
057	
058	
080	
087	
087A	
088	
088A	
090	
090A	
092	
092A	
093	

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410
Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
093A	
093B	
093C	
094	
094A	
097	
097A	
098	
098A	
099	
099A	
100	
100A	
101	
101A	
102	
102A	
103	
103A	
104	
105	
106	
107	
108	
109	
110	
110A	
111	
111A	

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410
Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
112	
112A	
113	
113A	
114	
114A	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410
Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
138	
139	
140	
140B	
141	
141B	
142	
142A	
142B	
142C	
143	
143A	
143B	
143C	
144	
144A	
145	
145A	
146	
146A	
147	
147A	
148	
149	
150	
151	
152	
56	
56A	

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410
Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	

Table II

Management Planner's Review

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001A	1' x 1' Black w/ White Streaks Floor Tile	13,500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206, 1st Floor Womens, Mens and Unisex Restrooms under Stairwell - 1918 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
004A	1' x 1' Black w/ White Streaks Floor Tile Mastic	13,500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206, 1st Floor Womens, Mens and Unisex Restrooms under Stairwell - 1918 Bldg. NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006A	1' x 1' Black w/ Brown Streaks Floor Tile (NOT OBSERVED)	900	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007A	9" x 9" Dark Red Floor Tile - (NOT OBSERVED)	4,000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008A	12" x 12" Black w/ Brown Streaks Floor Tile Mastic	2,400	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
009A	9" x 9" Dark Red Floor Tile Mastic - (NOT OBSERVED)	4,000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
017	Boiler Gasket (Abated)			Boiler Room - 1918 Bldg	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
018	Boiler Insulation (Abated)			Boiler Room - 1918 Bldg	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
019	Boiler Lagging (Abated)			Boiler Room - 1918 Bldg	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
020	Boiler Brick - Abated			Boiler Room - 1918 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
040	Vent Debris (Removed)			Inside Ducts - Throughout 1918 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
057	Cardboard Pipe Insulation	1,500	LF	1st Floor Janitor Closet (West), Above Corridor Ceilings - 1918 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
058	Aircell Pipe Insulation	1,500	LF	1st Floor Janitor Closet (West), Above Corridor Ceilings, 2nd Floor Staff Lounge 211 - 1918 Bldg.	Chrysotile	TSI	Yes	2	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
080	MJP E/F/V on Fiberglass Pipe Insulation	300	FITTING	1st Floor: Men's Toilet Pipe Chases, Rooms 119 & 123, Throughout Basement - 1928 Bldg.	Assumed	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
087	1' x 1' Brown w/ White Streaks Floor Tile	4,200	SF	Rooms 398, 300, 302, 304, 311, 398 - 1918 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
087A	1' x 1' Brown w/ White Streaks Floor Tile Mastic	4,200	SF	Rooms 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
088	12" x 12" Off White w/ Speckles Floor Tile	6,400	SF	Rooms 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
088A	12" x 12" Off White w/ Speckles Floor Tile Mastic	6,400	SF	Rooms 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
090	12" x 12" Green w/White Speckles Floor Tile	2,500	SF	2nd Floor Kitchen, Serving Area, Managers Office - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
090A	12" x 12" Green w/White Speckles Floor Tile Mastic	2,500	SF	2nd Floor Kitchen, Serving Area, Managers Office - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
092	9" x 9" Gray w/Speckles Floor Tile	5,000	SF	Main Office (211) Closet, Auditorium (Not Observed), 2nd Floor Corridor Closet - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
092A	9" x 9" Gray w/Speckles VFT Mastic	5,000	SF	Main Office (211) Closet, Auditorium (Not Observed), 2nd Floor Corridor Closet - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
093	9" x 9" Light Brown Floor Tile	2,700	SF	Room 205, 107 Closet, 105 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.	Chrysotile	MISC	No	2	SF	5 ACBM with potential for significant damage	Follow O&M Plan
093A	9" x 9" Light Brown Floor Tile Mastic	3,000	SF	Room 205, 107 Closet, 105 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
093B	9" x 9" Light Brown VFT	50	SF	Room 125 Vault - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
093C	9" x 9" Light Brown VFT Mastic	50	SF	Room 125 Vault - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
094	9" x 9" Beige w/ Green Streaks Floor Tile	250	SF	Room 211 Locker and Restroom - 1918 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
094A	9" x 9" Beige w/ Green Streaks VFT Mastic	250	SF	Room 211 Locker and Restroom - 1918	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Bldg.							
097	9" x 9" Black Floor Tile (Not Observed)	6,000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
097A	9" x 9" Black Floor Tile Mastic - (NOT OBSERVED)	6,000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
098	12" x 12" Light Brown w/ White & Dark Streaks Floor Tile	4,800	SF	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
098A	12" x 12" Light Brown w/ White & Dark Streaks Floor Tile Mastic	4,800	SF	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
099	12" x 12" Gray Floor Tile	5,500	SF	3rd Floor Computer Room & Office; Rooms 113, 119, 123, 221 & 227 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
099A	12" x 12" Gray Floor Tile Mastic	5,500	SF	3rd Floor Computer Room & Office; Rooms 113, 119, 123, 221 & 227 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	12" x 12" Light Brown VFT - (NOT OBSERVED)	1,800	SF	3rd Floor Corridor to Room 314, Rooms 121, 223 & 227 - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100A	12" x 12" Light Brown Floor Tile Mastic - (NOT OBSERVED)	3,300	SF	3rd Floor Corridor to Room 314, Rooms 121, 223 & 227 - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12" x 12" Light Pink Floor Tile - (NOT OBSERVED)	1,600	SF	Rooms 113, 125, 221 & 223 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101A	12" x 12" Light Pink Floor Tile Mastic - (NOT OBSERVED)	1,600	SF	Rooms 113, 125, 221 & 223 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12" x 12" Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)	1,600	SF	Rooms 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102A	12" x 12" Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)	1,600	SF	Rooms 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12" x 12" Light Beige w/ White Streaks Floor Tile	1,950	SF	Rooms 117, 121, 123 & 125 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103A	12" x 12" Light Beige w/ White Streaks VFT Mastic	1,950	SF	Rooms 117, 121, 123 & 125 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
104	12" x 12" Light Blue Floor Tile	1,150	SF	Room 312B, Gym, ROTC - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" Light Blue Floor Tile Mastic	1,150	SF	Room 312B, Gym, ROTC - 1918 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12" x 12" Tan w/ Brown & White Spots VFT	3,000	SF	Rooms 099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers, Room 312, Gym, ROTC - 1918 Bldg. Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" Tan w/ Brown & White Spots VFT Mastic	3,000	SF	Rooms 099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers, Room 312, Gym, ROTC - 1918 Bldg. Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Grey W/ Specks VFT	6,000	SF	1st Floor Corridor, Old Engineers Former Office - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12" x 12" Grey W/ Specks VFT Mastic	6,000	SF	1st Floor Corridor, Old Engineers Former Office - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	Blue Linoleum	3,200	SF	Rooms 115, 221, 225, 227 - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110A	Blue Linoleum Mastic	3,200	SF	Rooms 115, 221, 225, 227 - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12" x 12" Black w/White Specks Floor Tile	800	SF	Music Room (313), 319, 323, 327 - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111A	12" x 12" Black w/White Specks Floor Tile Mastic	800	SF	Music Room (313), 319, 323, 327 - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12" x 12" Blue w/White Specks Floor Tile	700	SF	Music Room (313) - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112A	12" x 12" Blue w/White Specks Floor Tile Mastic	700	SF	Music Room (313) - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12" x 12" White w/Specks Floor Tile	1,400	SF	Rooms 316, 318, 216, 220 - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113A	12" x 12" White w/Specks Floor Tile Mastic	1,400	SF	Rooms 316, 318, 216, 220 - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12" x 12" Light Blue w/Specks Floor Tile	200	SF	Room 400 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114A	12" x 12" Light Blue w/Specks Floor Tile Mastic	200	SF	Room 400 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	Blue Carpet Adhesive	3,800	SF	Library, Main Office, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				and Rooms 104 and 211; 205, 207, 209A, 209B, 219 - 1918 Bldg							
116	12" x 12" Ceramic Tile Grout	1,300	SF	Main Office, Library (100) - 1918 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12" x 12" Ceramic Tile Adhesive	1,300	SF	Main Office, Library (100) - 1918 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	2' x 4' White with swirls ceiling tile	2,400	SF	Rooms 216, 220, 316, 318 - 1999 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	12" x 12" Yellow Speckle VFT	11,700	SF	1st and 2nd floor corridors, 3rd Floor E-W Corridor, Room 104, Auditorium - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12" x 12" Yellow Speckle VFT Mastic	11,700	SF	1st and 2nd floor corridors, 3rd Floor E-W Corridor, Room 104, Auditorium - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12" x 12" Black with white specks VFT (DUPLICATE OF 001)	3,600	SF	2nd and 3rd floor corridors - 1928 bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	12" x 12" Black with white specks VFT Mastic (DUPLICATE OF 004A)	3,600	SF	2nd and 3rd floor corridors - 1928 bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	12" x 12" Yellow speckled VFT	14,200	SF	2nd and 3rd floor corridors - 1928 bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	12" x 12" Yellow speckled VFT Mastic	14,200	SF	2nd and 3rd floor corridors - 1928 bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12" x 12" Black with dark brown specks VFT	650	SF	Room 206 (Not Observed), 398 Office - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126	12" x 12" Black with dark brown specks VFT Mastic	650	SF	Room 206 (Not Observed), 398 Office - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127	12" x 12" Blue speckled VFT	500	SF	Room 211 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128	12" x 12" Blue speckled VFT mastic	500	SF	Room 211 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
129	12" x 12" Gray speckled VFT	600	SF	Room 211 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
130	12" x 12" Gray speckled VFT Mastic	600	SF	Room 211 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	Fume Hood	40	SF	Room 223 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12" x 12" Gray, Black and Beige VFT	2,400	SF	Rooms 327, 323, 319 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133	12" x 12" Gray, Black and Beige VFT Mastic	2,400	SF	Rooms 327, 323, 319 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	12" x 12" Gray, Black and White VFT	3,350	SF	2nd floor main office, Rooms 104, 105 (Not Observed), 312 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	12" x 12" Gray, Black and White VFT Mastic	3,350	SF	2nd floor main office, Rooms 104, 105 (Not Observed), 312 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	12" x 12" Gray and Black VFT	5,600	SF	Rooms 107G, 205, 206, 211, 303, 304, 308 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
137	12" x 12" Gray and Black VFT Mastic	5,600	SF	Rooms 107G, 205, 206, 211, 303, 304, 308 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	12" x 12" White VFT	17,500	SF	1st and 3rd floor corridors, Elevator Machine Room - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	12" x 12" White VFT Mastic	17,500	SF	1st and 3rd floor corridors, Elevator Machine Room - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	2' x 4' White w/ Dots & Pinholes Ceiling Tile	3,000	SF	Rooms 212, 209, 112, 199 ROTC Office - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140B	2' x 4' White w/ Dots & Pinholes Ceiling Tile	3,500	SF	Room 123, 125, 223, 119, 117, Engineer's Office - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	Cloth Wire Insulation	5	LF	Wall Heaters in Engineer's Office, Main Office (above vault), Main Office Restroom - 1918 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
141B	Cloth Wire Insulation	1	LF	Boys Locker Room Rear Stairwell - 1928 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
142	12" x 12" Light Gray w/ White & Gray Specks VFT	5,075	SF	Rooms 300, 302, 303, 304, 312, 309, 206, 212, 103, 107 & Closet, 109 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142A	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic	5,075	SF	Rooms 300, 302, 303, 304, 312, 309, 206, 212, 103, 107 & Closet, 109 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Remove
142B	12" x 12" Light Gray w/ White & Gray Specks VFT	1,000	SF	Rooms 129, 313 & Vestibule - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142C	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic	1,000	SF	Room 129, 313 & Vestibule - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	12" x 12" Black w/ Gray Streaks VFT	2,245	SF	Rooms 300, 206, 303, Elevator Vestibule, 309, 302, 304, 312, 212, 103, 109, 107 & Closet - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143A	12" x 12" Black w/ Gray Streaks VFT Mastic	2,245	SF	Rooms 300, 206, 303, Elevator Vestibule, 309, 302, 304, 312, 212, 103, 109, 107 & Closet - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143B	12" x 12" Black w/ Gray Streaks VFT	782	SF	Room 129, 313 & Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143C	12" x 12" Black w/ Gray Streaks VFT Mastic	782	SF	Room 129, 313 & Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	12" x 12" Light Gray w/ Multicolor Specks VFT	800	SF	Room 125 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144A	12" x 12" Light Gray w/ Multicolor Specks VFT	800	SF	Room 125 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic										
145	12" x 12" White w/ Beige Streaks VFT	72	SF	Room 201B - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145A	12" x 12" White w/ Beige Streaks VFT Mastic	72	SF	Room 201B - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	Light Gray w/ Dark Gray Specks Linoleum	800	SF	Room 229 Lab Prep Room, 223 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146A	Light Gray w/ Dark Gray Specks Linoleum Mastic	800	SF	Room 229 Lab Prep Room, 223 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147	12" x 12" Dark Gray w/ White & Gray Specks VFT	300	SF	Room 212 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147A	12" x 12" Dark Gray w/ White & Gray Specks VFT Mastic	300	SF	Room 212 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	Vinyl Basboard Adhesive	1,000	LF	Rooms 316, 316A, 318, 216, 220 - 1999 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
149	Drywall System (wallboard, joint compound & tape)	3,000	SF	Throughout Various Locations - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150	Hardcoat Plaster	75,000	SF	Throughout - 1918 Bldg.	Assumed	SURFACE	No	30	SF	5 ACBM with potential for significant damage	Repair
151	Hardcoat Plaster	75,000	SF	Throughout - 1928 Bldg.	Assumed	SURFACE	No	20	SF	5 ACBM with potential for significant damage	Repair
152	Hardcoat Plaster	15,000	SF	Throughout - 1999 Addition	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Aircell Pipe Insulation	1,500	LF	SW Unexcavated Area, Above Corridor Ceilings - 1928 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
56A	MJP on Aircell Pipe Insulaion	50	FITTING	Above Corridor Ceilings, 125 Prep Room, 1st Floor Janitors Closets - 1928 Bldg.	Assumed	MISC	No	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
B	2'x4' White Wormy Ceiling Tile	2,850	SF	Rooms 206 Closet, 208 & 398, 302, 304, 200 & 300 - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)		SF	Rooms 200 & 300 - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	2'x4' Dark White w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)	900	SF	Rooms 104 & 300 - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
E	2'x4' Off White Large Wormy Ceiling Tile	300	SF	Room 208 - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
F	1'x1' Off White Wormy Ceiling Tile	2,400	SF	ROTC, ROTC Office, Rooms 110 & 212, Engineer's Former Office - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	1'x1' Off White Large Wormy Ceiling Tile	1,500	SF	ROTC, Room 212, Cafeteria by	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Lunchroom & Auditorium - 1918 Bldg.							
H	Spray-on Fireproofing (Walls & Beams above Grid)	800	SF	3rd Floor Computer Room, 316, 316A, 318, 220, 216 - 1999 Bldg.	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	18"x18" Dirty White Ceiling Tile	1,000	SF	3rd Floor Music Room - 1928 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	1'x1' Dirty White Ceiling Tile	200	SF	Room 314 East & West Vestibule - 1928 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)	1,200	SF	Rooms 127 & 220 - 1928 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	1'x1' White Wormy Ceiling Tile	1,400	SF	Rooms 123 and 213 - 1928 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	Transite Table Tops	1,250	SF	Rooms 123, 125, 127, 221, 223, 225, 227 - 1928 Bldg. (129 Abated in 2003)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N	Sheeted Walls	800	SF	1st Floor Supply Storage near Exit - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	10/22/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
001A	
004A	
006A	
007A	
008A	
009A	
017	
018	
019	
020	
040	
057	
058	Repair Damaged ACM ASAP
080	
087	
087A	
088	
088A	
090	
090A	
092	

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
092A	
093	Replace Damaged Floor tiles/mastic
093A	
093B	
093C	
094	
094A	
097	
097A	
098	
098A	
099	
099A	
100	
100A	
101	
101A	
102	
102A	
103	
103A	
104	
105	
106	
107	
108	

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
109	
110	
110A	
111	
111A	
112	
112A	
113	
113A	
114	
114A	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
140B	
141	
141B	
142	
142A	
142B	
142C	
143	
143A	
143B	
143C	
144	
144A	
145	
145A	

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
146	
146A	
147	
147A	
148	
149	
150	Repair Damaged Plaster
151	Repair Damaged Plaster
152	
56	
56A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	

Chicago Public Schools

School	Kelvyn Park High School	Unit	46191	Building ID	1410
Address	4343 W. Wrightwood Ave.		Chicago, IL, 60639	Region	02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)	GSG-Probe Consulting, Inc.
	2942 W. Van Buren Chicago, IL, 60612
	Phone: 3123197575
	Fax:

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	001A		
MATERIAL DESCRIPTION:	1' x 1' Black w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206, 1st Floor Womens, Mens and Unisex Restrooms under Stairwell - 1918 Bldg.**

MATERIAL QUANTITY:	13500	MATERIAL UNITS:	SF
--------------------	-------	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	001A				
MATERIAL DESCRIPTION:	1' x 1' Black w/ White Streaks Floor Tile				
MATERIAL LOCATION:	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206, 1st Floor Womens, Mens and Unisex Restrooms under Stairwell - 1918 Bldg.				
MATERIAL QUANTITY:	13500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	004A		
MATERIAL DESCRIPTION:	1' x 1' Black w/ White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206, 1st Floor Womens, Mens and Unisex Restrooms under Stairwell - 1918 Bldg.**

NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206

MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	004A		
MATERIAL DESCRIPTION:	1' x 1' Black w/ White Streaks Floor Tile Mastic		
MATERIAL LOCATION:	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206, 1st Floor Womens, Mens and Unisex Restrooms under Stairwell - 1918 Bldg.		
	NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206		
MATERIAL QUANTITY:	13500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006A		
MATERIAL DESCRIPTION:	1' x 1' Black w/ Brown Streaks Floor Tile (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg.
NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	006A		
MATERIAL DESCRIPTION:	1' x 1' Black w/ Brown Streaks Floor Tile (NOT OBSERVED)		
MATERIAL LOCATION:	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007A		
MATERIAL DESCRIPTION:	9" x 9" Dark Red Floor Tile - (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st 2nd & 3rd Floor Corridors - 1928 Bldg.		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	007A				
MATERIAL DESCRIPTION:	9" x 9" Dark Red Floor Tile - (NOT OBSERVED)				
MATERIAL LOCATION:	1st 2nd & 3rd Floor Corridors - 1928 Bldg.				
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	008A		
MATERIAL DESCRIPTION:	12" x 12" Black w/ Brown Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg.
NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	008A		
MATERIAL DESCRIPTION:	12" x 12" Black w/ Brown Streaks Floor Tile Mastic		
MATERIAL LOCATION:	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	009A		
MATERIAL DESCRIPTION:	9" x 9" Dark Red Floor Tile Mastic - (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st 2nd & 3rd Floor Corridors - 1928 Bldg.		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	009A				
MATERIAL DESCRIPTION:	9" x 9" Dark Red Floor Tile Mastic - (NOT OBSERVED)				
MATERIAL LOCATION:	1st 2nd & 3rd Floor Corridors - 1928 Bldg.				
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **9/30/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **Boiler Gasket (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - 1918 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/30/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	017	
MATERIAL DESCRIPTION:	Boiler Gasket (Abated)	
MATERIAL LOCATION:	Boiler Room - 1918 Bldg	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	018	
MATERIAL DESCRIPTION:	Boiler Insulation (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - 1918 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	018	
MATERIAL DESCRIPTION:	Boiler Insulation (Abated)	
MATERIAL LOCATION:	Boiler Room - 1918 Bldg	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **9/30/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Boiler Lagging (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - 1918 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/30/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	019	
MATERIAL DESCRIPTION:	Boiler Lagging (Abated)	
MATERIAL LOCATION:	Boiler Room - 1918 Bldg	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	020	
MATERIAL DESCRIPTION:	Boiler Brick - Abated	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - 1918 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	020	
MATERIAL DESCRIPTION:	Boiler Brick - Abated	
MATERIAL LOCATION:	Boiler Room - 1918 Bldg.	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	040	
MATERIAL DESCRIPTION:	Vent Debris (Removed)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Inside Ducts - Throughout 1918 Bldg

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	040	
MATERIAL DESCRIPTION:	Vent Debris (Removed)	
MATERIAL LOCATION:	Inside Ducts - Throughout 1918 Bldg	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	057		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Janitor Closet (West), Above Corridor Ceilings - 1918 Bldg.		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	057		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
MATERIAL LOCATION:	1st Floor Janitor Closet (West), Above Corridor Ceilings - 1918 Bldg.		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	058		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Deterioration Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Janitor Closet (West), Above Corridor Ceilings, 2nd Floor Staff Lounge 211 - 1918 Bldg.		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	2	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	058				
MATERIAL DESCRIPTION:	Aircell Pipe Insulation				
MATERIAL LOCATION:	1st Floor Janitor Closet (West), Above Corridor Ceilings, 2nd Floor Staff Lounge 211 - 1918 Bldg.				
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	2	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Repair Damaged ACM ASAP

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	080		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor: Men's Toilet Pipe Chases, Rooms 119 & 123, Throughout Basement - 1928 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	080		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
MATERIAL LOCATION:	1st Floor: Men's Toilet Pipe Chases, Rooms 119 & 123, Throughout Basement - 1928 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	087		
MATERIAL DESCRIPTION:	1' x 1' Brown w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 398, 300, 302, 304, 311, 398 - 1918 Bldg		
MATERIAL QUANTITY:	4200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	087		
MATERIAL DESCRIPTION:	1' x 1' Brown w/ White Streaks Floor Tile		
MATERIAL LOCATION:	Rooms 398, 300, 302, 304, 311, 398 - 1918 Bldg		
MATERIAL QUANTITY:	4200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	087A		
MATERIAL DESCRIPTION:	1' x 1' Brown w/ White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 398, 300, 302, 304, 311 - 1918 Bldg		
MATERIAL QUANTITY:	4200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	087A		
MATERIAL DESCRIPTION:	1' x 1' Brown w/ White Streaks Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 398, 300, 302, 304, 311 - 1918 Bldg		
MATERIAL QUANTITY:	4200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	088		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Speckles Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 398, 300, 302, 304, 311 - 1918 Bldg		
MATERIAL QUANTITY:	6400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	088		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Speckles Floor Tile		
MATERIAL LOCATION:	Rooms 398, 300, 302, 304, 311 - 1918 Bldg		
MATERIAL QUANTITY:	6400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	088A		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Speckles Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 398, 300, 302, 304, 311 - 1918 Bldg		
MATERIAL QUANTITY:	6400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	088A		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Speckles Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 398, 300, 302, 304, 311 - 1918 Bldg		
MATERIAL QUANTITY:	6400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	090		
MATERIAL DESCRIPTION:	12" x 12" Green w/White Speckles Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Kitchen, Serving Area, Managers Office - 1928 Bldg.		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	090		
MATERIAL DESCRIPTION:	12" x 12" Green w/White Speckles Floor Tile		
MATERIAL LOCATION:	2nd Floor Kitchen, Serving Area, Managers Office - 1928 Bldg.		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	090A		
MATERIAL DESCRIPTION:	12" x 12" Green w/White Speckles Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Kitchen, Serving Area, Managers Office - 1928 Bldg.		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	090A		
MATERIAL DESCRIPTION:	12" x 12" Green w/White Speckles Floor Tile Mastic		
MATERIAL LOCATION:	2nd Floor Kitchen, Serving Area, Managers Office - 1928 Bldg.		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	092		
MATERIAL DESCRIPTION:	9" x 9" Gray w/Speckles Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office (211) Closet, Auditorium (Not Observed), 2nd Floor Corridor Closet - 1918 Bldg.		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	092				
MATERIAL DESCRIPTION:	9" x 9" Gray w/Speckles Floor Tile				
MATERIAL LOCATION:	Main Office (211) Closet, Auditorium (Not Observed), 2nd Floor Corridor Closet - 1918 Bldg.				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	092A		
MATERIAL DESCRIPTION:	9" x 9" Gray w/Speckles VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office (211) Closet, Auditorium (Not Observed), 2nd Floor Corridor Closet - 1918 Bldg.**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	092A				
MATERIAL DESCRIPTION:	9" x 9" Gray w/Speckles VFT Mastic				
MATERIAL LOCATION:	Main Office (211) Closet, Auditorium (Not Observed), 2nd Floor Corridor Closet - 1918 Bldg.				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	093		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 205, 107 Closet, 105 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.		
MATERIAL QUANTITY:	2700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	2	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	093				
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile				
MATERIAL LOCATION:	Room 205, 107 Closet, 105 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.				
MATERIAL QUANTITY:	2700	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	2	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Replace Damaged Floor tiles/mastic

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	093A		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 205, 107 Closet, 105 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	093A				
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile Mastic				
MATERIAL LOCATION:	Room 205, 107 Closet, 105 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.				
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	094		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ Green Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 211 Locker and Restroom - 1918 Bldg.		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	094		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ Green Streaks Floor Tile		
MATERIAL LOCATION:	Room 211 Locker and Restroom - 1918 Bldg.		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	094A		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ Green Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 211 Locker and Restroom - 1918 Bldg.		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	094A		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ Green Streaks VFT Mastic		
MATERIAL LOCATION:	Room 211 Locker and Restroom - 1918 Bldg.		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	097		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	097				
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile (Not Observed)				
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.				
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	097A		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile Mastic - (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	097A		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile Mastic - (NOT OBSERVED)		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	098		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White & Dark Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.		
MATERIAL QUANTITY:	4800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	098				
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White & Dark Streaks Floor Tile				
MATERIAL LOCATION:	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.				
MATERIAL QUANTITY:	4800	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	098A		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White & Dark Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.		
MATERIAL QUANTITY:	4800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	098A		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White & Dark Streaks Floor Tile Mastic		
MATERIAL LOCATION:	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.		
MATERIAL QUANTITY:	4800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	099		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Computer Room & Office; Rooms 113, 119, 123, 221 & 227 - 1928 Bldg.		
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	099				
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile				
MATERIAL LOCATION:	3rd Floor Computer Room & Office; Rooms 113, 119, 123, 221 & 227 - 1928 Bldg.				
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	099A		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Computer Room & Office; Rooms 113, 119, 123, 221 & 227 - 1928 Bldg.		
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	099A				
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic				
MATERIAL LOCATION:	3rd Floor Computer Room & Office; Rooms 113, 119, 123, 221 & 227 - 1928 Bldg.				
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	12" x 12" Light Brown VFT - (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor to Room 314, Rooms 121, 223 & 227 - 1928 Bldg.		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	12" x 12" Light Brown VFT - (NOT OBSERVED)		
MATERIAL LOCATION:	3rd Floor Corridor to Room 314, Rooms 121, 223 & 227 - 1928 Bldg.		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100A		
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile Mastic - (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor to Room 314, Rooms 121, 223 & 227 - 1928 Bldg.		
MATERIAL QUANTITY:	3300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	100A		
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile Mastic - (NOT OBSERVED)		
MATERIAL LOCATION:	3rd Floor Corridor to Room 314, Rooms 121, 223 & 227 - 1928 Bldg.		
MATERIAL QUANTITY:	3300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	12" x 12" Light Pink Floor Tile - (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 113, 125, 221 & 223 - 1928 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	12" x 12" Light Pink Floor Tile - (NOT OBSERVED)		
MATERIAL LOCATION:	Rooms 113, 125, 221 & 223 - 1928 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101A		
MATERIAL DESCRIPTION:	12" x 12" Light Pink Floor Tile Mastic - (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 113, 125, 221 & 223 - 1928 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	101A		
MATERIAL DESCRIPTION:	12" x 12" Light Pink Floor Tile Mastic - (NOT OBSERVED)		
MATERIAL LOCATION:	Rooms 113, 125, 221 & 223 - 1928 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg.
NOT OBSERVED**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)		
MATERIAL LOCATION:	Rooms 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102A		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg.
NOT OBSERVED**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	102A		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)		
MATERIAL LOCATION:	Rooms 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 117, 121, 123 & 125 - 1928 Bldg.**

MATERIAL QUANTITY: **1950**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ White Streaks Floor Tile		
MATERIAL LOCATION:	Rooms 117, 121, 123 & 125 - 1928 Bldg.		
MATERIAL QUANTITY:	1950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103A		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 117, 121, 123 & 125 - 1928 Bldg.**

MATERIAL QUANTITY: **1950**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	103A		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ White Streaks VFT Mastic		
MATERIAL LOCATION:	Rooms 117, 121, 123 & 125 - 1928 Bldg.		
MATERIAL QUANTITY:	1950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 312B, Gym, ROTC - 1918 Bldg.**

MATERIAL QUANTITY: **1150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Floor Tile		
MATERIAL LOCATION:	Room 312B, Gym, ROTC - 1918 Bldg.		
MATERIAL QUANTITY:	1150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 312B, Gym, ROTC - 1918 Bldg.**

MATERIAL QUANTITY: **1150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Floor Tile Mastic		
MATERIAL LOCATION:	Room 312B, Gym, ROTC - 1918 Bldg.		
MATERIAL QUANTITY:	1150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Brown & White Spots VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers, Room 312, Gym, ROTC - 1918 Bldg.
Rooms 121, 123 & 125 - 1928 Bldg.
NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Brown & White Spots VFT		
MATERIAL LOCATION:	Rooms 099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers, Room 312, Gym, ROTC - 1918 Bldg. Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Brown & White Spots VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers, Room 312, Gym, ROTC - 1918 Bldg. Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Brown & White Spots VFT Mastic		
MATERIAL LOCATION:	Rooms 099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers, Room 312, Gym, ROTC - 1918 Bldg. Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	12" x 12" Grey W/ Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor, Old Engineers Former Office - 1928 Bldg.		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	12" x 12" Grey W/ Specks VFT		
MATERIAL LOCATION:	1st Floor Corridor, Old Engineers Former Office - 1928 Bldg.		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	12" x 12" Grey W/ Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor, Old Engineers Former Office - 1928 Bldg.		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	12" x 12" Grey W/ Specks VFT Mastic		
MATERIAL LOCATION:	1st Floor Corridor, Old Engineers Former Office - 1928 Bldg.		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	Blue Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 115, 221, 225, 227 - 1928 Bldg		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	Blue Linoleum		
MATERIAL LOCATION:	Rooms 115, 221, 225, 227 - 1928 Bldg		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110A		
MATERIAL DESCRIPTION:	Blue Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 115, 221, 225, 227 - 1928 Bldg		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	110A		
MATERIAL DESCRIPTION:	Blue Linoleum Mastic		
MATERIAL LOCATION:	Rooms 115, 221, 225, 227 - 1928 Bldg		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	12" x 12" Black w/White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Music Room (313), 319, 323, 327 - 1928 Bldg		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	111				
MATERIAL DESCRIPTION:	12" x 12" Black w/White Specks Floor Tile				
MATERIAL LOCATION:	Music Room (313), 319, 323, 327 - 1928 Bldg				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111A		
MATERIAL DESCRIPTION:	12" x 12" Black w/White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Music Room (313), 319, 323, 327 - 1928 Bldg		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	111A		
MATERIAL DESCRIPTION:	12" x 12" Black w/White Specks Floor Tile Mastic		
MATERIAL LOCATION:	Music Room (313), 319, 323, 327 - 1928 Bldg		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12" x 12" Blue w/White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Music Room (313) - 1928 Bldg		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12" x 12" Blue w/White Specks Floor Tile		
MATERIAL LOCATION:	Music Room (313) - 1928 Bldg		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112A		
MATERIAL DESCRIPTION:	12" x 12" Blue w/White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Music Room (313) - 1928 Bldg		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	112A				
MATERIAL DESCRIPTION:	12" x 12" Blue w/White Specks Floor Tile Mastic				
MATERIAL LOCATION:	Music Room (313) - 1928 Bldg				
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	12" x 12" White w/Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 316, 318, 216, 220 - 1999 Addition		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	12" x 12" White w/Specks Floor Tile		
MATERIAL LOCATION:	Rooms 316, 318, 216, 220 - 1999 Addition		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113A		
MATERIAL DESCRIPTION:	12" x 12" White w/Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 316, 318, 216, 220 - 1999 Addition		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	113A		
MATERIAL DESCRIPTION:	12" x 12" White w/Specks Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 316, 318, 216, 220 - 1999 Addition		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 400 - 1918 Bldg.		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/Specks Floor Tile		
MATERIAL LOCATION:	Room 400 - 1918 Bldg.		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	114A		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 400 - 1918 Bldg.		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	114A				
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/Specks Floor Tile Mastic				
MATERIAL LOCATION:	Room 400 - 1918 Bldg.				
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	115		
MATERIAL DESCRIPTION:	Blue Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, Main Office, Principal's Office and Rooms 104 and 211; 205, 207, 209A, 209B, 219 - 1918 Bldg**

MATERIAL QUANTITY: **3800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	115				
MATERIAL DESCRIPTION:	Blue Carpet Adhesive				
MATERIAL LOCATION:	Library, Main Office, Principal's Office and Rooms 104 and 211; 205, 207, 209A, 209B, 219 - 1918 Bldg				
MATERIAL QUANTITY:	3800	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	116		
MATERIAL DESCRIPTION:	12" x 12" Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Library (100) - 1918 Bldg		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	116		
MATERIAL DESCRIPTION:	12" x 12" Ceramic Tile Grout		
MATERIAL LOCATION:	Main Office, Library (100) - 1918 Bldg		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	117		
MATERIAL DESCRIPTION:	12" x 12" Ceramic Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Library (100) - 1918 Bldg		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	117		
MATERIAL DESCRIPTION:	12" x 12" Ceramic Tile Adhesive		
MATERIAL LOCATION:	Main Office, Library (100) - 1918 Bldg		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	118		
MATERIAL DESCRIPTION:	2' x 4' White with swirls ceiling tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 216, 220, 316, 318 - 1999 Bldg.		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	118		
MATERIAL DESCRIPTION:	2' x 4' White with swirls ceiling tile		
MATERIAL LOCATION:	Rooms 216, 220, 316, 318 - 1999 Bldg.		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	119		
MATERIAL DESCRIPTION:	12" x 12" Yellow Speckle VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd floor corridors, 3rd Floor E-W Corridor, Room 104, Auditorium - 1918 Bldg.		
MATERIAL QUANTITY:	11700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	119		
MATERIAL DESCRIPTION:	12" x 12" Yellow Speckle VFT		
MATERIAL LOCATION:	1st and 2nd floor corridors, 3rd Floor E-W Corridor, Room 104, Auditorium - 1918 Bldg.		
MATERIAL QUANTITY:	11700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	120		
MATERIAL DESCRIPTION:	12" x 12" Yellow Speckle VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd floor corridors, 3rd Floor E-W Corridor, Room 104, Auditorium - 1918 Bldg.		
MATERIAL QUANTITY:	11700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	120				
MATERIAL DESCRIPTION:	12" x 12" Yellow Speckle VFT Mastic				
MATERIAL LOCATION:	1st and 2nd floor corridors, 3rd Floor E-W Corridor, Room 104, Auditorium - 1918 Bldg.				
MATERIAL QUANTITY:	11700	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	121		
MATERIAL DESCRIPTION:	12" x 12" Black with white specks VFT (DUPLICATE OF 001)		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd floor corridors - 1928 bldg.		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	121		
MATERIAL DESCRIPTION:	12" x 12" Black with white specks VFT (DUPLICATE OF 001)		
MATERIAL LOCATION:	2nd and 3rd floor corridors - 1928 bldg.		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	122		
MATERIAL DESCRIPTION:	12" x 12" Black with white specks VFT Mastic (DUPLICATE OF 004A)		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd floor corridors - 1928 bldg.		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	122		
MATERIAL DESCRIPTION:	12" x 12" Black with white specks VFT Mastic (DUPLICATE OF 004A)		
MATERIAL LOCATION:	2nd and 3rd floor corridors - 1928 bldg.		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	123		
MATERIAL DESCRIPTION:	12" x 12" Yellow speckled VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd floor corridors - 1928 bldg.		
MATERIAL QUANTITY:	14200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	123				
MATERIAL DESCRIPTION:	12" x 12" Yellow speckled VFT				
MATERIAL LOCATION:	2nd and 3rd floor corridors - 1928 bldg.				
MATERIAL QUANTITY:	14200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	124		
MATERIAL DESCRIPTION:	12" x 12" Yellow speckled VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd floor corridors - 1928 bldg.		
MATERIAL QUANTITY:	14200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	124		
MATERIAL DESCRIPTION:	12" x 12" Yellow speckled VFT Mastic		
MATERIAL LOCATION:	2nd and 3rd floor corridors - 1928 bldg.		
MATERIAL QUANTITY:	14200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	125		
MATERIAL DESCRIPTION:	12" x 12" Black with dark brown specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 206 (Not Observed), 398 Office - 1918 Bldg.		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	125		
MATERIAL DESCRIPTION:	12" x 12" Black with dark brown specks VFT		
MATERIAL LOCATION:	Room 206 (Not Observed), 398 Office - 1918 Bldg.		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	126		
MATERIAL DESCRIPTION:	12" x 12" Black with dark brown specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 206 (Not Observed), 398 Office - 1918 Bldg.		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	126		
MATERIAL DESCRIPTION:	12" x 12" Black with dark brown specks VFT Mastic		
MATERIAL LOCATION:	Room 206 (Not Observed), 398 Office - 1918 Bldg.		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	127		
MATERIAL DESCRIPTION:	12" x 12" Blue speckled VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 211 - 1918 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	127		
MATERIAL DESCRIPTION:	12" x 12" Blue speckled VFT		
MATERIAL LOCATION:	Room 211 - 1918 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	128		
MATERIAL DESCRIPTION:	12" x 12" Blue speckled VFT mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 211 - 1918 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	128		
MATERIAL DESCRIPTION:	12" x 12" Blue speckled VFT mastic		
MATERIAL LOCATION:	Room 211 - 1918 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	129		
MATERIAL DESCRIPTION:	12" x 12" Gray speckled VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 211 - 1918 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	129		
MATERIAL DESCRIPTION:	12" x 12" Gray speckled VFT		
MATERIAL LOCATION:	Room 211 - 1918 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	130		
MATERIAL DESCRIPTION:	12" x 12" Gray speckled VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 211 - 1918 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	130		
MATERIAL DESCRIPTION:	12" x 12" Gray speckled VFT Mastic		
MATERIAL LOCATION:	Room 211 - 1918 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	131		
MATERIAL DESCRIPTION:	Fume Hood		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 223 - 1928 Bldg.		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	131		
MATERIAL DESCRIPTION:	Fume Hood		
MATERIAL LOCATION:	Room 223 - 1928 Bldg.		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	132		
MATERIAL DESCRIPTION:	12" x 12" Gray, Black and Beige VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 327, 323, 319 - 1928 Bldg.		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	132		
MATERIAL DESCRIPTION:	12" x 12" Gray, Black and Beige VFT		
MATERIAL LOCATION:	Rooms 327, 323, 319 - 1928 Bldg.		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	133		
MATERIAL DESCRIPTION:	12" x 12" Gray, Black and Beige VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 327, 323, 319 - 1928 Bldg.		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	133		
MATERIAL DESCRIPTION:	12" x 12" Gray, Black and Beige VFT Mastic		
MATERIAL LOCATION:	Rooms 327, 323, 319 - 1928 Bldg.		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	134		
MATERIAL DESCRIPTION:	12" x 12" Gray, Black and White VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd floor main office, Rooms 104, 105 (Not Observed), 312 - 1918 Bldg.		
MATERIAL QUANTITY:	3350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	134		
MATERIAL DESCRIPTION:	12" x 12" Gray, Black and White VFT		
MATERIAL LOCATION:	2nd floor main office, Rooms 104, 105 (Not Observed), 312 - 1918 Bldg.		
MATERIAL QUANTITY:	3350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	135		
MATERIAL DESCRIPTION:	12" x 12" Gray, Black and White VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd floor main office, Rooms 104, 105 (Not Observed), 312 - 1918 Bldg.		
MATERIAL QUANTITY:	3350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	135		
MATERIAL DESCRIPTION:	12" x 12" Gray, Black and White VFT Mastic		
MATERIAL LOCATION:	2nd floor main office, Rooms 104, 105 (Not Observed), 312 - 1918 Bldg.		
MATERIAL QUANTITY:	3350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	136		
MATERIAL DESCRIPTION:	12" x 12" Gray and Black VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 107G, 205, 206, 211, 303, 304, 308 - 1918 Bldg.		
MATERIAL QUANTITY:	5600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	136		
MATERIAL DESCRIPTION:	12" x 12" Gray and Black VFT		
MATERIAL LOCATION:	Rooms 107G, 205, 206, 211, 303, 304, 308 - 1918 Bldg.		
MATERIAL QUANTITY:	5600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	137		
MATERIAL DESCRIPTION:	12" x 12" Gray and Black VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 107G, 205, 206, 211, 303, 304, 308 - 1918 Bldg.		
MATERIAL QUANTITY:	5600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	137		
MATERIAL DESCRIPTION:	12" x 12" Gray and Black VFT Mastic		
MATERIAL LOCATION:	Rooms 107G, 205, 206, 211, 303, 304, 308 - 1918 Bldg.		
MATERIAL QUANTITY:	5600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	138		
MATERIAL DESCRIPTION:	12" x 12" White VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 3rd floor corridors, Elevator Machine Room - 1918 Bldg.		
MATERIAL QUANTITY:	17500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	138		
MATERIAL DESCRIPTION:	12" x 12" White VFT		
MATERIAL LOCATION:	1st and 3rd floor corridors, Elevator Machine Room - 1918 Bldg.		
MATERIAL QUANTITY:	17500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	139		
MATERIAL DESCRIPTION:	12" x 12" White VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 3rd floor corridors, Elevator Machine Room - 1918 Bldg.		
MATERIAL QUANTITY:	17500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	139		
MATERIAL DESCRIPTION:	12" x 12" White VFT Mastic		
MATERIAL LOCATION:	1st and 3rd floor corridors, Elevator Machine Room - 1918 Bldg.		
MATERIAL QUANTITY:	17500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:	SW Unexcavated Area, Above Corridor Ceilings - 1928 Bldg.		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
MATERIAL LOCATION:	SW Unexcavated Area, Above Corridor Ceilings - 1928 Bldg.		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	2'x4' White Wormy Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 206 Closet, 208 & 398, 302, 304, 200 & 300 - 1918 Bldg.**

MATERIAL QUANTITY: **2850**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **2'x4' White Wormy Ceiling Tile**

MATERIAL LOCATION: **Rooms 206 Closet, 208 & 398, 302, 304, 200 & 300 - 1918 Bldg.**

MATERIAL QUANTITY: **2850**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 200 & 300 - 1918 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)		
MATERIAL LOCATION:	Rooms 200 & 300 - 1918 Bldg.		
MATERIAL QUANTITY:		MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	2'x4' Dark White w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104 & 300 - 1918 Bldg.**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	D				
MATERIAL DESCRIPTION:	2'x4' Dark White w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)				
MATERIAL LOCATION:	Rooms 104 & 300 - 1918 Bldg.				
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	2'x4' Off White Large Wormy Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 208 - 1918 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	E				
MATERIAL DESCRIPTION:	2'x4' Off White Large Wormy Ceiling Tile				
MATERIAL LOCATION:	Room 208 - 1918 Bldg.				
MATERIAL QUANTITY:	300		MATERIAL UNITS:	SF	
DAMAGE QUANTITY:	0		DAMAGE UNITS:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	1'x1' Off White Wormy Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	ROTC, ROTC Office, Rooms 110 & 212, Engineer's Former Office - 1918 Bldg.		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	F				
MATERIAL DESCRIPTION:	1'x1' Off White Wormy Ceiling Tile				
MATERIAL LOCATION:	ROTC, ROTC Office, Rooms 110 & 212, Engineer's Former Office - 1918 Bldg.				
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	1'x1' Off White Large Wormy Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	ROTC, Room 212, Cafeteria by Lunchroom & Auditorium - 1918 Bldg.		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	G				
MATERIAL DESCRIPTION:	1'x1' Off White Large Wormy Ceiling Tile				
MATERIAL LOCATION:	ROTC, Room 212, Cafeteria by Lunchroom & Auditorium - 1918 Bldg.				
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Spray-on Fireproofing (Walls & Beams above Grid)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Computer Room, 316, 316A, 318, 220, 216 - 1999 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Spray-on Fireproofing (Walls & Beams above Grid)		
MATERIAL LOCATION:	3rd Floor Computer Room, 316, 316A, 318, 220, 216 - 1999 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	18"x18" Dirty White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Music Room - 1928 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	I				
MATERIAL DESCRIPTION:	18"x18" Dirty White Ceiling Tile				
MATERIAL LOCATION:	3rd Floor Music Room - 1928 Bldg.				
MATERIAL QUANTITY:	1000		MATERIAL UNITS:	SF	
DAMAGE QUANTITY:	0		DAMAGE UNITS:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	1'x1' Dirty White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 314 East & West Vestibule - 1928 Bldg.		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	J				
MATERIAL DESCRIPTION:	1'x1' Dirty White Ceiling Tile				
MATERIAL LOCATION:	Room 314 East & West Vestibule - 1928 Bldg.				
MATERIAL QUANTITY:	200		MATERIAL UNITS:	SF	
DAMAGE QUANTITY:	0		DAMAGE UNITS:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 127 & 220 - 1928 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	K				
MATERIAL DESCRIPTION:	2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)				
MATERIAL LOCATION:	Rooms 127 & 220 - 1928 Bldg.				
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	1'x1' White Wormy Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 123 and 213 - 1928 Bldg.		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	L				
MATERIAL DESCRIPTION:	1'x1' White Wormy Ceiling Tile				
MATERIAL LOCATION:	Rooms 123 and 213 - 1928 Bldg.				
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Transite Table Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 123, 125, 127, 221, 223, 225, 227 - 1928 Bldg. (129 Abated in 2003)		
MATERIAL QUANTITY:	1250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Transite Table Tops		
MATERIAL LOCATION:	Rooms 123, 125, 127, 221, 223, 225, 227 - 1928 Bldg. (129 Abated in 2003)		
MATERIAL QUANTITY:	1250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Sheeted Walls		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Supply Storage near Exit - 1928 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Kelvyn Park High School	REVIEW DATE:	10/22/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA:	N				
MATERIAL DESCRIPTION:	Sheeted Walls				
MATERIAL LOCATION:	1st Floor Supply Storage near Exit - 1928 Bldg.				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	142C				
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic				
MATERIAL LOCATION:	Room 129, 313 & Vestibule - 1928 Bldg.				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **142C**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White & Gray Specks VFT Mastic**
MATERIAL LOCATION: **Room 129, 313 & Vestibule - 1928 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	149				
MATERIAL DESCRIPTION:	Drywall System (wallboard, joint compound & tape)				
MATERIAL LOCATION:	Throughout Various Locations - 1999 Addition				
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **Drywall System (wallboard, joint compound & tape)**
MATERIAL LOCATION: **Throughout Various Locations - 1999 Addition**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	143A				
MATERIAL DESCRIPTION:	12" x 12" Black w/ Gray Streaks VFT Mastic				
MATERIAL LOCATION:	Rooms 300, 206, 303, Elevator Vestibule, 309, 302, 304, 312, 212, 103, 109, 107 & Closet - 1918 Bldg.				
MATERIAL QUANTITY:	2245	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **143A**
MATERIAL DESCRIPTION: **12" x 12" Black w/ Gray Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 300, 206, 303, Elevator Vestibule, 309, 302, 304, 312, 212, 103, 109, 107 & Closet - 1918 Bldg.**
MATERIAL QUANTITY: **2245** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	144A				
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Multicolor Specks VFT Mastic				
MATERIAL LOCATION:	Room 125 - 1928 Bldg.				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **144A**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Multicolor Specks VFT Mastic**
MATERIAL LOCATION: **Room 125 - 1928 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	147A				
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/ White & Gray Specks VFT Mastic				
MATERIAL LOCATION:	Room 212 - 1918 Bldg.				
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **147A**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ White & Gray Specks VFT Mastic**

MATERIAL LOCATION: **Room 212 - 1918 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	148		
MATERIAL DESCRIPTION:	Vinyl Basboard Adhesive		
MATERIAL LOCATION:	Rooms 316, 316A, 318, 216, 220 - 1999 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **Vinyl Basboard Adhesive**
MATERIAL LOCATION: **Rooms 316, 316A, 318, 216, 220 - 1999 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	140B		
MATERIAL DESCRIPTION:	2' x 4' White w/ Dots & Pinholes Ceiling Tile		
MATERIAL LOCATION:	Room 123, 125, 223, 119, 117, Engineer's Office - 1928 Bldg.		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **140B**
MATERIAL DESCRIPTION: **2' x 4' White w/ Dots & Pinholes Ceiling Tile**
MATERIAL LOCATION: **Room 123, 125, 223, 119, 117, Engineer's Office - 1928 Bldg.**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	141B		
MATERIAL DESCRIPTION:	Cloth Wire Insulation		
MATERIAL LOCATION:	Boys Locker Room Rear Stairwell - 1928 Bldg.		
MATERIAL QUANTITY:	1	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **141B**

MATERIAL DESCRIPTION: **Cloth Wire Insulation**

MATERIAL LOCATION: **Boys Locker Room Rear Stairwell - 1928 Bldg.**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	093B				
MATERIAL DESCRIPTION:	9" x 9" Light Brown VFT				
MATERIAL LOCATION:	Room 125 Vault - 1918 Bldg.				
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **093B**
MATERIAL DESCRIPTION: **9" x 9" Light Brown VFT**
MATERIAL LOCATION: **Room 125 Vault - 1918 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	143				
MATERIAL DESCRIPTION:	12" x 12" Black w/ Gray Streaks VFT				
MATERIAL LOCATION:	Rooms 300, 206, 303, Elevator Vestibule, 309, 302, 304, 312, 212, 103, 109, 107 & Closet - 1918 Bldg.				
MATERIAL QUANTITY:	2245	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **143**

MATERIAL DESCRIPTION: **12" x 12" Black w/ Gray Streaks VFT**

MATERIAL LOCATION: **Rooms 300, 206, 303, Elevator Vestibule, 309, 302, 304, 312, 212, 103, 109, 107 & Closet - 1918 Bldg.**

MATERIAL QUANTITY: **2245** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	143B				
MATERIAL DESCRIPTION:	12" x 12" Black w/ Gray Streaks VFT				
MATERIAL LOCATION:	Room 129, 313 & Vestibule				
MATERIAL QUANTITY:	782	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **143B**
MATERIAL DESCRIPTION: **12" x 12" Black w/ Gray Streaks VFT**
MATERIAL LOCATION: **Room 129, 313 & Vestibule**
MATERIAL QUANTITY: **782** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	143C				
MATERIAL DESCRIPTION:	12" x 12" Black w/ Gray Streaks VFT Mastic				
MATERIAL LOCATION:	Room 129, 313 & Vestibule				
MATERIAL QUANTITY:	782	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **143C**
MATERIAL DESCRIPTION: **12" x 12" Black w/ Gray Streaks VFT Mastic**
MATERIAL LOCATION: **Room 129, 313 & Vestibule**
MATERIAL QUANTITY: **782** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	145		
MATERIAL DESCRIPTION:	12" x 12" White w/ Beige Streaks VFT		
MATERIAL LOCATION:	Room 201B - 1918 Bldg.		
MATERIAL QUANTITY:	72	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Streaks VFT**
MATERIAL LOCATION: **Room 201B - 1918 Bldg.**
MATERIAL QUANTITY: **72** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	145A				
MATERIAL DESCRIPTION:	12" x 12" White w/ Beige Streaks VFT Mastic				
MATERIAL LOCATION:	Room 201B - 1918 Bldg.				
MATERIAL QUANTITY:	72	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **145A**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Streaks VFT Mastic**
MATERIAL LOCATION: **Room 201B - 1918 Bldg.**
MATERIAL QUANTITY: **72** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	146				
MATERIAL DESCRIPTION:	Light Gray w/ Dark Gray Specks Linoleum				
MATERIAL LOCATION:	Room 229 Lab Prep Room, 223 - 1928 Bldg.				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **Light Gray w/ Dark Gray Specks Linoleum**
MATERIAL LOCATION: **Room 229 Lab Prep Room, 223 - 1928 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	140				
MATERIAL DESCRIPTION:	2' x 4' White w/ Dots & Pinholes Ceiling Tile				
MATERIAL LOCATION:	Rooms 212, 209, 112, 199 ROTC Office - 1918 Bldg.				
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **2' x 4' White w/ Dots & Pinholes Ceiling Tile**
MATERIAL LOCATION: **Rooms 212, 209, 112, 199 ROTC Office - 1918 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	141				
MATERIAL DESCRIPTION:	Cloth Wire Insulation				
MATERIAL LOCATION:	Wall Heaters in Engineer's Office, Main Office (above vault), Main Office Restroom - 1918 Bldg.				
MATERIAL QUANTITY:	5	MATERIAL UNITS:	LF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE UNITS:	LF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **141**

MATERIAL DESCRIPTION: **Cloth Wire Insulation**

MATERIAL LOCATION: **Wall Heaters in Engineer's Office, Main Office (above vault), Main Office Restroom - 1918 Bldg.**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	142A		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ White & Gray Specks VFT Mastic		
MATERIAL LOCATION:	Rooms 300, 302, 303, 304, 312, 309, 206, 212, 103, 107 & Closet, 109 - 1918 Bldg.		
MATERIAL QUANTITY:	5075	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **142A**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White & Gray Specks VFT Mastic**
MATERIAL LOCATION: **Rooms 300, 302, 303, 304, 312, 309, 206, 212, 103, 107 & Closet, 109 - 1918 Bldg.**
MATERIAL QUANTITY: **5075** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	144		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Multicolor Specks VFT		
MATERIAL LOCATION:	Room 125 - 1928 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Multicolor Specks VFT**
MATERIAL LOCATION: **Room 125 - 1928 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	146A		
MATERIAL DESCRIPTION:	Light Gray w/ Dark Gray Specks Linoleum Mastic		
MATERIAL LOCATION:	Room 229 Lab Prep Room, 223 - 1928 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **146A**
MATERIAL DESCRIPTION: **Light Gray w/ Dark Gray Specks Linoleum Mastic**
MATERIAL LOCATION: **Room 229 Lab Prep Room, 223 - 1928 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	147				
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/ White & Gray Specks VFT				
MATERIAL LOCATION:	Room 212 - 1918 Bldg.				
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ White & Gray Specks VFT**
MATERIAL LOCATION: **Room 212 - 1918 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	151		
MATERIAL DESCRIPTION:	Hardcoat Plaster		
MATERIAL LOCATION:	Throughout - 1928 Bldg.		
MATERIAL QUANTITY:	75000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	SURFACE	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	5 ACBM with potential for significant damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	20	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **Throughout - 1928 Bldg.**
MATERIAL QUANTITY: **75000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:
Repair Damaged Plaster

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	152		
MATERIAL DESCRIPTION:	Hardcoat Plaster		
MATERIAL LOCATION:	Throughout - 1999 Addition		
MATERIAL QUANTITY:	15000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	SURFACE	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	142B		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ White & Gray Specks VFT		
MATERIAL LOCATION:	Rooms 129, 313 & Vestibule - 1928 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **142B**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White & Gray Specks VFT**
MATERIAL LOCATION: **Rooms 129, 313 & Vestibule - 1928 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	142				
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ White & Gray Specks VFT				
MATERIAL LOCATION:	Rooms 300, 302, 303, 304, 312, 309, 206, 212, 103, 107 & Closet, 109 - 1918 Bldg.				
MATERIAL QUANTITY:	5075	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White & Gray Specks VFT**
MATERIAL LOCATION: **Rooms 300, 302, 303, 304, 312, 309, 206, 212, 103, 107 & Closet, 109 - 1918 Bldg.**
MATERIAL QUANTITY: **5075** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	093C				
MATERIAL DESCRIPTION:	9" x 9" Light Brown VFT Mastic				
MATERIAL LOCATION:	Room 125 Vault - 1918 Bldg.				
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **093C**

MATERIAL DESCRIPTION: **9" x 9" Light Brown VFT Mastic**

MATERIAL LOCATION: **Room 125 Vault - 1918 Bldg.**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	56A				
MATERIAL DESCRIPTION:	MJP on Aircell Pipe Insulaion				
MATERIAL LOCATION:	Above Corridor Ceilings, 125 Prep Room, 1st Floor Janitors Closets - 1928 Bldg.				
MATERIAL QUANTITY:	50	MATERIAL UNITS:	FITTING		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING		
COMMENTS:					

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **56A**
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**
MATERIAL LOCATION: **Above Corridor Ceilings, 125 Prep Room, 1st Floor Janitors Closets - 1928 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46191	BUILDING ID:	1410
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Kelvyn Park High School	INSPECTION DATE:	9/30/2019		
ADDRESS:	4343 W. Wrightwood Ave.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	150		
MATERIAL DESCRIPTION:	Hardcoat Plaster		
MATERIAL LOCATION:	Throughout - 1918 Bldg.		
MATERIAL QUANTITY:	75000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	SURFACE	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	5 ACBM with potential for significant damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	30	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/30/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **10/22/2019**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **150**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **Throughout - 1918 Bldg.**
MATERIAL QUANTITY: **75000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:
Repair Damaged Plaster

Management Planner's Signature: _____ Date: **10/22/2019**

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

JOSEPH L HENNIGAN
855 W ADAMS, SUITE 200
CHICAGO, IL 60607


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	2/13/2017
1G0 - 1G350	4/18/2016	05/15/2017		
JOSEPH L HENNIGAN			PROJECT MANAGER	2/6/2017
855 W ADAMS, SUITE 200 CHICAGO, IL 60607			AIR SAMPLING PROFESSIONAL	
Environmental Health		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JOSEPH L HENNIGAN
2942 W VAN BUREN ST
CHICAGO, IL 60612

5/9/2018

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

Front of License			Back of License	
			ENDORSEMENTS	TC EXPIRES
ASBESTOS PROFESSIONAL LICENSE			INSPECTOR	2/10/2019
ID NUMBER	ISSUED	EXPIRES	PROJECT MANAGER	2/3/2019
100 - 18350	5/9/2018	05/15/2019	AIR SAMPLING PROFESSIONAL	
JOSEPH L HENNIGAN 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



Office: 312-491-0081
Fax: 312-421-2501
www.public-health-safety.com

02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR15

Certificate Number:

Phone: 312-491-0081

Nicholas J. Peneff
Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

JOSEPH L. HENNIGAN

This is to certify that _____
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR15

Certificate Number:

Phone: 312-491-0081

Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JOSEPH L HENNIGAN
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 18350	ISSUED 4/19/2019	EXPIRES 05/15/2020	INSPECTOR	2/9/2020
JOSEPH L HENNIGAN 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/2/2020
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



PUBLIC HEALTH & SAFETY inc.
Environmental and Occupational Services
315 Ashland Ave., Chicago, IL 60607
www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR15

Certificate Number:

Phone: 312-491-0081

Nicholas J. Peneff
Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	2/28/2020
100 - 07342	4/19/2019	05/15/2020	PROJECT DESIGNER	3/15/2020
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	2/28/2020
			PROJECT MANAGER	2/22/2020
			AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos

EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed