

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0037
SCHOOL NAME: Senn Academy
ADDRESS OF SCHOOL: 5900 N. Glenwood
CITY: Chicago, IL, 60660

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/16/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1538
IDPH INSPECTOR LICENSE NUMBER: 100-11093
IDPH LICENSED INSPECTOR NAME(Please Print): David Avila
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Senn Academy

5900 N. Glenwood
Chicago, IL, 60660

Unit: 47061
Building ID: 1540

IDPH ID Number: 14-016-2990-0037

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

GSG-Probe Consulting, Inc.

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

October 10, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 47061 Region: 01 IDPH ID:14-016-2990-0037

School: Senn Academy Building ID: 1540

Address: 5900 N. Glenwood

Chicago, IL, 60660

Building Contact: Kerrigan, Edward

Contact Phone:312-246-3800

Current Building Owners: Chicago Public Schools

Review Date: 10/25/2019

Inspector: David Avila

Inspector IDPH License: 100-11093

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,
GSG-Probe Consulting, Inc.

Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 10, 2019

RE: Senn Academy, Unit 47061
5900 N. Glenwood
Chicago, IL, 60660

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Senn Academy, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Senn Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Senn Academy	Unit:	47061	Region:	01
Address:	5900 N. Glenwood		Chicago, IL, 60660		
IDPH ID:	14-016-2990-0037		Building ID:	1540	
Contact:	Kerrigan, Edward		Phone:	312-246-3800	

2. Description of Facility

Original Construction:	1930	Additional Construction:	1913,1930
Total Square Footage:	37798	No of Floors:	3
Current Occupancy:	1538		

3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	42 West Madison Street		
	Chicago, IL 60602		

4. Managing Environmental Consultant

MEC:	GSG-Probe Consulting, Inc.		
Contact:	Jigar Shah		
Address	2942 W. Van Buren		
	Chicago, IL, 60612		
Phone:	3123197575	Fax:	

5. Inspector

Inspector Name: David Avila

Inspector IDPH license #	100-11093	Signature:	
		Date:	10/10/2019

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license #	100-07342	Signature:	
		Date:	10/25/2019

7. Review Date:10/25/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Senn Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1540:

B. The following new homogenous areas have been identified for Building 1540:

197	12" x 12" Beige w/ Beige Specs VFT
198	12" x 12" Beige w/ Beige Specs VFT Mastic
199	20" x 20" Off White w/ Specks VFT
200	20" x 20" Off White w/ Specks VFT Mastic
201	20" x 20" Beige w/ Specks VFT
202	20" x 20" Beige w/ Specks VFT Mastic
203	20" x 20" Brown w/ Specks VFT
204	20" x 20" Brown w/ Specks VFT Mastic
205	Linoleum Gray w/ Granite Pattern
206	Linoleum Gray w/ Granite Pattern Mastic
207	Linoleum Gray w/ Black Spots
208	Linoleum Gray w/ Black Spots Mastic
209	12" x 12" Light Gray w/ Specks VFT
210	12" x 12" Light Gray w/ Specks VFT Mastic
211	12" x 12" Dark Gray w/ Specks VFT
212	12" x 12" Dark Gray w/ Specks VFT Mastic
213	12" x 12" White w/ Red, Blue & Yellow Specks VFT
214	12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic
215	12" x 12" Light Gray w/ Specks VFT
216	12" x 12" Light Gray w/ Specks VFT Mastic
217	12" x 12" Dark Gray w/ Specks VFT
218	12" x 12" Dark Gray w/ Specks VFT Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

104	12" x 12" Light Green w/ White Streaks VFT (Not Observed)
105	12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)
106	12" x 12" Beige w/ Dark & White Streaks VFT
127	12" x 12" White w/Beige Streaks VFT
127 A	12" x 12" White w/Beige Streaks VFT Mastic
128	12" x 12" White w/Blue Streaks VFT
128 A	12" x 12" White w/Blue Streaks VFT Mastic
133	Lt Blue Speckled Linoleum- NOT OBSERVED
134	Lt Blue Speckled Linoleum Mastic- NOT OBSERVED
135	12" x 12" White w/ Gold Specks VFT (Not Observed)
136	12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)
137	2' x 4' White Pin-Hole Ceiling Tile
138	12" x 12" White w/ Beige VFT
139	12" x 12" White w/ Beige VFT Mastic
140	12" x 12" Light Gray VFT
141	12" x 12" Light Gray VFT Mastic
142	12" x 12" Light Blue VFT
143	12" x 12" Light Blue VFT Mastic
144	12" x 12" Green VFT (Not Observed)
145	12" x 12" Green VFT Mastic (Not Observed)
146	12" x 12" White VFT (Not Observed)
147	12" x 12" White VFT Mastic (Not Observed)
148	Linoleum, Gray w/Gray Streaks
148M	Linoleum, Gray w/Gray Streaks Mastic
149	Linoleum, Blue Solid
149M	Linoleum, Blue Solid Mastic
150	12" x 12" VFT- NOT OBSERVED
150M	12" x 12" VFT Mastic - NOT OBSERVED
151	12" x 12" Solid Gray VFT
151M	12" x 12" Solid Gray VFT Mastic
152	12" x 12" Tan w/Brown Speckles VFT (Not Observed)
152M	12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)
153	12" x 12" White w/ Tan Speckles VFT (Not Observed)
153M	12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)

	Observed)
154M	Gold, Blue Carpet Mastic
155	Linoleum, White w/Gray Streaks
155M	Linoleum, White w/Gray Streaks Mastic
156	12" x 12" Light Gray w/ Gray and White Specks VFT
156A	12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC
157	2' x 4' Smooth Ceiling Tile
158	1' x 1' Ceiling Tile w/ Grooves
159	1' x 1' Ceiling Tile w/ Grooves above HA 161
160	2' x 4' Ceiling Tile w/ Grooves
161	2' x 4' Ceiling Tile w/ Grooves
162	2' x 4' Ceiling Tile - pinhole
163	2' x 4' Ceiling Tile - pinholes
164	12" x 12" Tan w/ light brown specks VFT
164A	12" x 12" Tan w/ light brown specks VFT MASTIC
165	9" x 9" Brown w/ yellow design VFT (Not Observed)
165A	9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)
166	12" x 12" Light Blue w/ blue specks VFT (Not Observed)
166A	12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)
167	12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)
167A	12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)
168	Black Lab Table Tops
169	Black Lab Counter Tops
170	Blue Linoleum with MASTIC
171	12" x 12" Gray w/ tan streaks VFT w/ MASTIC
172	Decorative Plaster
173	Terrazzo
174	Terrazzo
175	12" x 12" Blue Speckled VFT (Not Observed)
176	12" x 12" Blue Speckled VFT Mastic (Not Observed)
177	12" x 12" Light Blue w/ Specks VFT (Not Observed)
178	12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)
179	12" x 12" Gray w/ Streaks VFT (Not Observed)
180	12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)
181	Gray Linoleum w/ Granite Pattern
182	Gray Linoleum w/ Granite Pattern Mastic

183	Gray Linoleum
184	Gray Linoleum Mastic
185	12" x 12" Red w/ Streaks VFT
186	12" x 12" Red w/ Streaks VFT Mastic
187	12" x 12" Yellow w/Streaks VFT
188	12" x 12" Yellow w/Streaks VFT Mastic
189	12" x 12" Green w/ Streaks VFT
190	12" x 12" Green w/ Streaks VFT Mastic
191	12" x 12" Dark Gray Linoleum w/ Granite Pattern (Not Observed)
192	12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)
193	12" x 12" Pink w/ Maroon Specks VFT
194	12" x 12" Pink w/ Maroon Specks VFT Mastic
195	12" x 12" Maroon w/ Pink Specks VFT
196	12" x 12" Maroon w/ Pink Specks VFT Mastic
197	12" x 12" Beige w/ Beige Specs VFT
198	12" x 12" Beige w/ Beige Specs VFT Mastic
199	20" x 20" Off White w/ Specks VFT
200	20" x 20" Off White w/ Specks VFT Mastic
201	20" x 20" Beige w/ Specks VFT
202	20" x 20" Beige w/ Specks VFT Mastic
203	20" x 20" Brown w/ Specks VFT
204	20" x 20" Brown w/ Specks VFT Mastic
205	Linoleum Gray w/ Granite Pattern
206	Linoleum Gray w/ Granite Pattern Mastic
207	Linoleum Gray w/ Black Spots
208	Linoleum Gray w/ Black Spots Mastic
209	12" x 12" Light Gray w/ Specks VFT
210	12" x 12" Light Gray w/ Specks VFT Mastic
211	12" x 12" Dark Gray w/ Specks VFT
212	12" x 12" Dark Gray w/ Specks VFT Mastic
213	12" x 12" White w/ Red, Blue & Yellow Specks VFT
214	12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic
215	12" x 12" Light Gray w/ Specks VFT
216	12" x 12" Light Gray w/ Specks VFT Mastic
217	12" x 12" Dark Gray w/ Specks VFT
218	12" x 12" Dark Gray w/ Specks VFT Mastic
25	Insulation in Vault Door
64	12" x 12" Light Brown w/ White Streaks VFT (Not Observed)
65	12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)
80	12" x 12" White w/ Brown Speckles VFT (Not Observed)
81	12" x 12" White w/ Brown Speckles VFT Mastic

86	12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)
88	Brown Linoleum
89	Green Linoleum (Not Observed)
AA	12" x 12" Green Floor Tile - NOT OBSERVED
BB	Mastic associated with HA AA - NOT OBSERVED
CC	Lab Counter Tops
DD	Lab Tables
EE	Lab Fume Hoods

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by David Avila, IDPH License # 100-11093. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Senn Academy Building 1540 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Boiler Lagging (ABATED 2010)			Boiler # 1 - 1931 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
02	Boiler Lagging (ABATED 2010)			Boiler # 2 - 1931 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
03	Boiler Lagging (ABATED 2010)			Boiler # 3 - 1931 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
04	Boiler Lagging (ABATED 2010)			Boiler # 4 - 1931 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
05	Boiler Gasket (ABATED 2010)			Boiler # 1 - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
06	Boiler Gasket (ABATED 2010)			Boiler # 2 - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
09	MJP on Fiberglass Pipe Insulation	600	FITTING	Throughout (See Hatching Maps) - 1912 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
10	MJP on Fiberglass Pipe Insulation	425	FITTING	ROTC Room, Boiler & Pump Rooms, Main Tunnel, 2nd & 3rd Floor South Janitors Closet Chase, 2nd Floor Boys Toilet (N), 3rd Floor Unisex Toilet; 1st Floor Janitor's Closet; Under Sinks in Rooms 310, 352, and 366; BookRoom Between Room 315 and 317; Mens Room Next to Room 322 - 1931 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
100	9" x 9" Red w/ White Streaks VFT- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1000	12" x 12" Orange/Brown VFT- NOT OBSERVED	24	SF	Room 180 wooden stage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1001	12" x 12" Orange/Brown VFT Black Mastic - NOT OBSERVED	24	SF	Room 180 wooden stage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	9" x 9" Red w/ White Streaks VFT Mastic- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
102	9" x 9" Gray w/ White Streaks VFT (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	9" x 9" Gray w/ White Streaks VFT Mastic (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12" x 12" Light Green w/ White Streaks VFT (Not Observed)	350	SF	Room 123A - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)	350	SF	Room 123A - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12" x 12" Beige w/ Dark & White Streaks VFT	6,100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12" x 12" Beige w/ Dark & White Streaks VFT Mastic	6,100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	9" x 9" Lt. Brown w/ Dark Red Streaks VFT	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	9" x 9" Lt. Brown w/ Dark Red Streaks VFT Mastic	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	9" x 9" Green w/ White Streaks VFT	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111	9" x 9" Green w/ White Streaks VFT Mastic	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
112	12" x 12" Lt. Brown w/ Gray Speckles VFT (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	12" x 12" Lt. Brown w/ Gray Speckles VFT Mastic (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12" x 12" Beige w/ Brown Streaks VFT- NOT OBSERVED	1,400	SF	Rooms 166, & 162 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	12" x 12" Beige w/ Brown Streaks VFT Mastic - NOT OBSERVED	1,400	SF	Rooms 166, & 162 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	12" x 12" Blue-Gray w/ White Streaks VFT	500	SF	Room 373 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
117	12" x 12" Blue-Gray w/ White Streaks VFT Mastic	500	SF	Room 373 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12" x 12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	12" x 12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	12" x 12" Lt Gray w/ White Speckles VFT- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	12" x 12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	12" x 12" Brown VFT- NOT OBSERVED		SF	Stage - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
123	12" x 12" Brown VFT Mastic- NOT OBSERVED	0	SF	Stage - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
124	2' x 2' Black Border VFT (Abated)			115 Kitchen - 1912 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
125	2' x 2' Black Border VFT Mastic- Abated			115 Kitchen - 1912 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
126	2' x 2' Ceiling Tile- NOT OBSERVED	1,700	SF	Room 425, & 326 - 1912 Bldg.	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
127	12" x 12" White w/Beige Streaks VFT	1,000	SF	Room 377A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
127 A	12" x 12" White w/Beige Streaks VFT Mastic	1,000	SF	Room 377A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
128	12" x 12" White w/Blue Streaks VFT	880	SF	Room 351	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
128 A	12" x 12" White w/Blue Streaks VFT Mastic	880	SF	Room 351	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	MJP on Paperwrap Pipe Insulation	370	FITTING	1st Floor South JC, 2nd Floor Janitor's Closet, 238 Chase, 188, Autoshop - 1931 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
133	Lt Blue Speckled Linoleum- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	Lt Blue Speckled Linoleum Mastic- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
135	12" x 12" White w/ Gold Specks VFT (Not Observed)	1,000	SF	Rooms 174, 176, & 180 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
136	12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)	1,000	SF	Rooms 174, 176, & 180 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
137	2' x 4' White Pin-Hole Ceiling Tile	1,000	SF	Room 356 - 1912	ASSUMED	MISC	Y	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.								potential for damage		
138	12" x 12" White w/ Beige VFT	2,000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
139	12" x 12" White w/ Beige VFT Mastic	2,000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Paperwrap Pipe Insulation	300	LF	ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
140	12" x 12" Light Gray VFT	800	SF	Room 210, & Engineer's Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
141	12" x 12" Light Gray VFT Mastic	800	SF	210, & Engineer's Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142	12" x 12" Light Blue VFT	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143	12" x 12" Light Blue VFT Mastic	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144	12" x 12" Green VFT (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
145	12" x 12" Green VFT Mastic (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
146	12" x 12" White VFT (Not Observed)	1,000	SF	1st Floor Hall (N&S) - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
147	12" x 12" White VFT Mastic (Not Observed)	1,000	SF	1st Floor Hall (N&S) - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148	Linoleum, Gray w/Gray Streaks	4,500	SF	Rooms 350, 352, 356 Vault, 306 and 310	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148M	Linoleum, Gray w/Gray Streaks Mastic	4,500	SF	Rooms 350, 352, 356 Vault, 306 and 310	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
149	Linoleum, Blue Solid	2,000	SF	Rooms 100, 106, and 106 Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
149M	Linoleum, Blue Solid Mastic	2,000	SF	Rooms 100, 106, and 106 Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
150	12" x 12" VFT- NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Along N. and S. Walls - NOT OBSERVED										
150M	12" x 12" VFT Mastix - NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
151	12" x 12" Solid Gray VFT	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
151M	12" x 12" Solid Gray VFT Mastix	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
152	12" x 12" Tan w/Brown Speckles VFT (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
152M	12" x 12" Tan w/Brown Speckles VFT Mastix (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153	12" x 12" White w/ Tan Speckles VFT (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153M	12" x 12" White w/ Tan Speckles VFT Mastix (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
154M	Gold, Blue Carpet Mastix	1,000	SF	Rooms 379, 375, 326, 315, and 272 (not observed), Room 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155	Linoleum, White w/Gray Streaks	750	SF	Room 352	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
155M	Linoleum, White w/Gray Streaks Mastic	750	SF	Room 352	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156	12" x 12" Light Gray w/ Gray and White Specks VFT	600	SF	Room 377	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156A	12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC	600	SF	Room 377	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
157	2' x 4' Smooth Ceiling Tile	700	SF	Room 351	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
158	1' x 1' Ceiling Tile w/ Grooves	2,600	SF	Room 320, 425 - 1911 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
159	1' x 1' Ceiling Tile w/ Grooves above HA 161	1,000	SF	Rooms 108, 148, 149, 146	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
160	2' x 4' Ceiling Tile w/ Grooves	22,000	SF	South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet - 1930 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
161	2' x 4' Ceiling Tile w/ Grooves	45,000	SF	Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134,	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 - 1911 Bldg.										
162	2' x 4' Ceiling Tile - pinhole	13,000	SF	1st Floor Hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352, 364, 366 - 1911 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
163	2' x 4' Ceiling Tile - pinholes	4,500	SF	Corridor from pump room- room 184, kitchen, cafeteria - 1930 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
164	12" x 12" Tan w/ light brown specks VFT	1,600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
164A	12" x 12" Tan w/ light brown specks VFT MASTIC	1,600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
165	9" x 9" Brown w/ yellow design VFT (Not Observed)	100	SF	Room 123 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
165A	9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)	100	SF	Room 123 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166	12" x 12" Light Blue w/ blue specks VFT (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166A	12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
167	12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)	7,000	SF	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167A	12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)	7,000	SF	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
168	Black Lab Table Tops	700	SF	Rooms 358, 364, 367	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
169	Black Lab Counter Tops	300	SF	Rooms 358, 364, 367	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
170	Blue Linoleum with MASTIC	2,300	SF	Rooms 358, 364, 366	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
171	12" x 12" Gray w/ tan streaks VFT w/ MASTIC	400	SF	Room 170	ASSUMED	MISC	N	LOC	40		No	ACBM with potential for significant damage		LOW
172	Decorative Plaster	1,200	SF	Assembly hall, vestibule leading to assembly hall	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
173	Terrazzo	2,000	SF	Stairwells, 1st fl. corridor west of pump room - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
174	Terrazzo	1,000	SF	1st Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
175	12" x 12" Blue Speckled VFT (Not Observed)	1,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
176	12" x 12" Blue Speckled VFT Mastic (Not Observed)	1,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
177	12" x 12" Light Blue w/ Specks VFT (Not Observed)	8,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
178	12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)	8,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
179	12" x 12" Gray w/ Streaks VFT (Not Observed)	900	SF	Room 221	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
180	12" x 12" Gray w/ Streaks VFT Mastic	900	SF	Room 221	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	(Not Observed)											potential for damage		
181	Gray Linoleum w/ Granite Pattern	1,200	SF	Room 100, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
182	Gray Linoleum w/ Granite Pattern Mastic	1,200	SF	Room 100, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
183	Gray Linoleum	2,400	SF	Rooms 105, 105A, 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
184	Gray Linoleum Mastic	2,400	SF	Rooms 105, 105A, 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
185	12" x 12" Red w/ Streaks VFT	400	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
186	12" x 12" Red w/ Streaks VFT Mastic	400	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
187	12" x 12" Yellow w/Streaks VFT	400	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
188	12" x 12" Yellow w/Streaks VFT Mastic	400	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
189	12" x 12" Green w/ Streaks VFT	200	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
190	12" x 12" Green w/ Streaks VFT Mastic	200	SF	Health Center (144)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
191	12" x 12" Dark Gray Linoleum w/ Granite Pattern (Not Observed)	2,000	SF	Main Office (131-134)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
192	12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)	2,000	SF	Main Office (131-134)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
193	12" x 12" Pink w/ Maroon Specks VFT	1,200	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
194	12" x 12" Pink w/ Maroon Specks VFT Mastic	1,200	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
195	12" x 12" Maroon w/ Pink Specks VFT	200	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
196	12" x 12" Maroon w/ Pink Specks VFT Mastic	200	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
197	12" x 12" Beige w/ Beige Specs VFT	2,500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
198	12" x 12" Beige w/ Beige Specs VFT Mastic	2,500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
199	20" x 20" Off White w/ Specks VFT	2,800	SF	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	Mudded Joint Packing on Aircell Pipe Insulation	603	FITTING	thru 117 Mixing Room, 219, 319, Auditorium Crawlspace, Room 120A - 1912 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
200	20" x 20" Off White w/ Specks VFT Mastic	2,800	SF	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
201	20" x 20" Beige w/ Specks VFT	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
202	20" x 20" Beige w/ Specks VFT Mastic	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
203	20" x 20" Brown w/ Specks VFT	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
204	20" x 20" Brown w/ Specks VFT Mastic	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
205	Linoleum Gray w/ Granite Pattern	2,500	SF	Main Office and Associated Offices (131-134)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
206	Linoleum Gray w/ Granite Pattern Mastic	2,500	SF	Main Office and Associated Offices (131-134)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
207	Linoleum Gray w/ Black Spots	2,300	SF	Rooms 151, 155	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
208	Linoleum Gray w/ Black Spots Mastic	2,500	SF	Rooms 151, 155	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
209	12" x 12" Light Gray w/ Specks VFT	20,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
210	12" x 12" Light Gray w/ Specks VFT Mastic	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
211	12" x 12" Dark Gray w/ Specks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
212	12" x 12" Dark Gray w/ Specks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
213	12" x 12" White w/ Red, Blue & Yellow	2,500	SF	1st, 2nd and 3rd	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Specks VFT			Floor Corridors - 1912 Bldg.								potential for damage		
214	12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
215	12" x 12" Light Gray w/ Specks VFT	10,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
216	12" x 12" Light Gray w/ Specks VFT Mastic	10,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
217	12" x 12" Dark Gray w/ Specks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
218	12" x 12" Dark Gray w/ Specks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Insulation in Vault Door	28	SF	Office - 1912 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
26	Mudded Joint Packing on Aircell Insulation	300	FITTING	Room 238 Chase, Autoshop, Autoshop Tool Room - 1931 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
27	Aircell Pipe Insulation	1,000	LF	Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room - 1931 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
30	Aircell Pipe Insulation	2,600	LF	Rooms 219, 319, & Auditorium Crawlspace - 1912 Bldg.	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
33	Paperwrap Pipe Insulation	400	LF	Auditorium Crawlspace - 1912 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
34	MJP E/F/V on Paperwrap Pipe Insulation	50	FITTING	Auditorium Crawlspace - 1912 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
39	Hard Coat Plaster			Throughout - 1912 Bldg.	NO_ACBM						No			
40	Hard Coat Plaster			Throughout - 1931 Bldg.	NO_ACBM						No			
55	12" x 12" Tan w/Speckles VFT	5,000	SF	3rd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(N), 326, 233, 227, 225 (Library) - 1912 Bldg.								potential for damage		
56	9" x 9" Brown w/Streaks VFT Mastic	500	SF	Room 356	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12" x 12" Tan w/Speckles VFT Mastic	5,000	SF	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	9" x 9" Maroon VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
61	9" x 9" Maroon VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
62	9" x 9" Brown w/Streaks VFT NOT OBSERVED	500	SF	Room 356 - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12" x 12" Light Brown w/ White Streaks VFT (Not Observed)	200	SF	Rooms 100, 106, & 106 Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)	200	SF	Rooms 100, 106, & 106 Office - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	9" x 9" Black VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
67	9" x 9" Black VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
68	9" x 9" Black w/Large White Streaks VFT (Abated)			3rd Floor Hall (S&N) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
69	9" x 9" Black w/Large White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
70	9" x 9" Brown w/Large White Streaks VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		LOW
71	9" x 9" Brown w/Large White Streaks VFT			3rd Floor Hall	ABATED	MISC						Any remaining friable		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Mastic (Abated)			(S&N), 2nd Floor Hall (N) - 1931 Bldg.								ACBM or friable suspect ACBM		
72	9" x 9" Orange w/White VFT Streaks (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
73	9" x 9" Orange w/White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
76	9" x 9" Maroon w/ White Streaks VFT (Abated)			2nd Floor Hall (S) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
77	9" x 9" Maroon w/ White Streaks VFT Mastic (Abated)			2nd Floor Hall (S) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
78	9" x 9" Black w/ Faint White Streaks VFT (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
79	9" x 9" Black w/ Faint White Streaks VFT Mastic (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
80	12" x 12" White w/ Brown Speckles VFT (Not Observed)	1,200	SF	Room 341 & 213 - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	12" x 12" White w/ Brown Speckles VFT Mastic	1,200	SF	Room 341 & 213 - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)	600	SF	Room 239 - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	12" x 12" Brown w/ Light Brown Speckles VFT Mastic (Not Observed)	600	SF	Room 239 - 1931 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	Brown Linoleum	250	SF	238 North Storage - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	Green Linoleum (Not Observed)	5,500	SF	Main Gym, Office & Locker - 1931 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12" x 12" Peach w/ Speckles VFT- NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	12" x 12" Peach w/ Speckles VFT Mastic - NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	12" x 12" Light Brown w/ Dark Speckles VFT	700	SF	Room 355, 373, 375 - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93	12" x 12" Light Brown w/ Dark Speckles	700	SF	Room 355, 373, 375	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	VFT Mastic			- 1912 Bldg.								potential for damage		
94	12" x 12" Beige w/ Dark Speckles VFT (Not Observed)	2,000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
95	12" x 12" Beige w/ Dark Speckles VFT Mastic (Not Observed)	2,000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
96	12" x 12" Dark Brown w/White & Dark Streaks VFT- NOT OBSERVED	1,900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97	12" x 12" Dark Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED	1,900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	12" x 12" Black w/ White Speckles VFT- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99	12" x 12" Black w/ White Speckles VFT Mastic- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AA	12" x 12" Green Floor Tile - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BB	Mastic associated with HA AA - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas - NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CC	Lab Counter Tops	3,500	SF	Classrooms 100, 106, 108, 110, 302, 310, 350	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
DD	Lab Tables	2,600	SF	Classrooms 110, 302, 310, 350	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
EE	Lab Fume Hoods	750	SF	Classrooms 100, 106, 350	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>10/10/2019</u>
Inspector Name	<u>David Avila</u>
<u>100-11093</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
09	
10	
100	
1000	
1001	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	

Chicago Public Schools

School Senn Academy **Unit** 47061 **Building ID** 1540
Address 5900 N. Glenwood **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
113	
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
127 A	
128	
128 A	
13	
133	
134	
135	
136	
137	
138	Not Observed in Rooms 319, 110, 108
139	Not observed in Rooms 310, 110, 108
14	
140	
141	

Chicago Public Schools

School Senn Academy **Unit** 47061 **Building ID** 1540

Address 5900 N. Glenwood **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
142	
143	
144	
145	
146	
147	
148	
148M	
149	
149M	
150	
150M	
151	
151M	
152	
152M	
153	
153M	
154M	Observed in Room 379 only
155	Observed in Room 379 only
155M	
156	
156A	
157	
158	
159	
160	
161	
162	

Chicago Public Schools

School Senn Academy **Unit** 47061 **Building ID** 1540
Address 5900 N. Glenwood **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
163	
164	Not observed in 1st Floor Corridor
164A	Not observed in 1st floor corridor
165	
165A	
166	
166A	
167	
167A	
168	
169	
170	
171	
172	
173	
174	
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	

Chicago Public Schools

School Senn Academy **Unit** 47061 **Building ID** 1540

Address 5900 N. Glenwood **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
188	
189	
190	
191	
192	
193	
194	
195	
196	
197	
198	
199	
20	
200	
201	
202	
203	
204	
205	
206	
207	
208	
209	
210	
211	
212	
213	
214	
215	

Chicago Public Schools

School Senn Academy **Unit** 47061 **Building ID** 1540

Address 5900 N. Glenwood **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
216	
217	
218	
25	
26	
27	
30	
33	
34	
39	
40	
55	Not observed in 3rd Floor Corridor
56	
57	Not observed in 3rd Floor Corridor
60	
61	
62	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
76	
77	

Chicago Public Schools

School Senn Academy **Unit** 47061 **Building ID** 1540

Address 5900 N. Glenwood **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
78	
79	
80	
81	
86	
87	
88	
89	
90	
91	
92	Not observed in rooms 373 and 375
93	Not observed in Rooms 373 and 375
94	
95	
96	
97	
98	
99	
AA	
BB	
CC	
DD	
EE	

Chicago Public Schools

School Senn Academy **Unit** 47061 **Building ID** 1540
Address 5900 N. Glenwood **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Boiler Lagging (ABATED 2010)			Boiler # 1 - 1931 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
02	Boiler Lagging (ABATED 2010)			Boiler # 2 - 1931 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
03	Boiler Lagging (ABATED 2010)			Boiler # 3 - 1931 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
04	Boiler Lagging (ABATED 2010)			Boiler # 4 - 1931 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
05	Boiler Gasket (ABATED 2010)			Boiler # 1 - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
06	Boiler Gasket (ABATED 2010)			Boiler # 2 - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
09	MJP on Fiberglass Pipe Insulation	600	FITTING	Throughout (See Hatching Maps) - 1912 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
10	MJP on Fiberglass Pipe Insulation	425	FITTING	ROTC Room, Boiler & Pump Rooms, Main Tunnel, 2nd & 3rd Floor South Janitors Closet Chase, 2nd Floor Boys Toilet (N), 3rd Floor Unisex Toilet; 1st Floor Janitor's Closet; Under Sinks in Rooms 310, 352, and 366; BookRoom Between Room 315 and 317; Mens Room Next to Room 322 - 1931 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
100	9" x 9" Red w/ White Streaks VFT- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1000	12" x 12" Orange/Brown VFT- NOT OBSERVED	24	SF	Room 180 wooden stage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1001	12" x 12" Orange/Brown VFT Black Mastic - NOT OBSERVED	24	SF	Room 180 wooden stage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	9" x 9" Red w/ White Streaks VFT Mastic- NOT OBSERVED	300	SF	115 Kitchen - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	9" x 9" Gray w/ White Streaks VFT (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	9" x 9" Gray w/ White Streaks VFT Mastic (Not Observed)	800	SF	Rooms 117A - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" Light Green w/ White Streaks VFT (Not Observed)	350	SF	Room 123A - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
105	12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)	350	SF	Room 123A - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12" x 12" Beige w/ Dark & White Streaks VFT	6,100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" Beige w/ Dark & White Streaks VFT Mastic	6,100	SF	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	9" x 9" Lt. Brown w/ Dark Red Streaks VFT	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	9" x 9" Lt. Brown w/ Dark Red Streaks VFT Mastic	455	SF	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	9" x 9" Green w/ White Streaks VFT	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	9" x 9" Green w/ White Streaks VFT Mastic	300	SF	Teacher Lunchroom/Lounge - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12" x 12" Lt. Brown w/ Gray Speckles VFT (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12" x 12" Lt. Brown w/ Gray Speckles VFT Mastic (Not Observed)	80	SF	153 Vest., 120 Vest. - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12" x 12" Beige w/ Brown Streaks VFT- NOT OBSERVED	1,400	SF	Rooms 166, & 162 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	12" x 12" Beige w/ Brown Streaks VFT Mastic - NOT OBSERVED	1,400	SF	Rooms 166, & 162 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12" x 12" Blue-Gray w/ White Streaks VFT	500	SF	Room 373 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12" x 12" Blue-Gray w/ White Streaks VFT Mastic	500	SF	Room 373 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12" x 12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	12" x 12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12" x 12" Lt Gray w/ White Speckles VFT- NOT OBSERVED	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12" x 12" Lt Gray w/ White Speckles VFT Mastic-	2,000	SF	Rooms 176, 174, 180 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	NOT OBSERVED										
122	12" x 12" Brown VFT- NOT OBSERVED		SF	Stage - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	12" x 12" Brown VFT Mastic- NOT OBSERVED	0	SF	Stage - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	2' x 2' Black Border VFT (Abated)			115 Kitchen - 1912 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
125	2' x 2' Black Border VFT Mastic- Abated			115 Kitchen - 1912 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
126	2' x 2' Ceiling Tile- NOT OBSERVED	1,700	SF	Room 425, & 326 - 1912 Bldg.	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127	12" x 12" White w/Beige Streaks VFT	1,000	SF	Room 377A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127 A	12" x 12" White w/Beige Streaks VFT Mastic	1,000	SF	Room 377A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128	12" x 12" White w/Blue Streaks VFT	880	SF	Room 351	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128 A	12" x 12" White w/Blue Streaks VFT Mastic	880	SF	Room 351	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	MJP on Paperwrap Pipe Insulation	370	FITTING	1st Floor South JC, 2nd Floor Janitor's Closet, 238 Chase, 188, Autoshop - 1931 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
133	Lt Blue Speckled Linoleum- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	Lt Blue Speckled Linoleum Mastic- NOT OBSERVED	800	SF	Rooms 356, 326 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	12" x 12" White w/ Gold Specks VFT (Not Observed)	1,000	SF	Rooms 174, 176, & 180 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)	1,000	SF	Rooms 174, 176, & 180 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	2' x 4' White Pin-Hole Ceiling Tile	1,000	SF	Room 356 - 1912 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	12" x 12" White w/ Beige VFT	2,000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	12" x 12" White w/ Beige VFT Mastic	2,000	SF	310 & Office, 302, 108, 110 - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Paperwrap Pipe Insulation	300	LF	ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
140	12" x 12" Light Gray VFT	800	SF	Room 210, & Engineer's Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	12" x 12" Light Gray VFT Mastic	800	SF	210, & Engineer's Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	12" x 12" Light Blue VFT	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
143	12" x 12" Light Blue VFT Mastic	900	SF	Room 210, 195A & Engineer's Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	12" x 12" Green VFT (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	12" x 12" Green VFT Mastic (Not Observed)	300	SF	1st Floor Hall (N&S) - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	12" x 12" White VFT (Not Observed)	1,000	SF	1st Floor Hall (N&S) - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147	12" x 12" White VFT Mastic (Not Observed)	1,000	SF	1st Floor Hall (N&S) - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	Linoleum, Gray w/Gray Streaks	4,500	SF	Rooms 350, 352, 356 Vault, 306 and 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148M	Linoleum, Gray w/Gray Streaks Mastic	4,500	SF	Rooms 350, 352, 356 Vault, 306 and 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149	Linoleum, Blue Solid	2,000	SF	Rooms 100, 106, and 106 Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149M	Linoleum, Blue Solid Mastic	2,000	SF	Rooms 100, 106, and 106 Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150	12" x 12" VFT- NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150M	12" x 12" VFT Mastic - NOT OBSERVED	200	SF	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	12" x 12" Solid Gray VFT	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151M	12" x 12" Solid Gray VFT Mastic	800	SF	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	12" x 12" Tan w/Brown Speckles VFT (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152M	12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)	800	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153	12" x 12" White w/ Tan Speckles VFT (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153M	12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)	200	SF	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
154M	Gold, Blue Carpet Mastic	1,000	SF	Rooms 379, 375, 326, 315, and 272	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				(not observed), Room 225							
155	Linoleum, White w/Gray Streaks	750	SF	Room 352	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155M	Linoleum, White w/Gray Streaks Mastic	750	SF	Room 352	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156	12" x 12" Light Gray w/ Gray and White Specks VFT	600	SF	Room 377	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156A	12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC	600	SF	Room 377	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
157	2' x 4' Smooth Ceiling Tile	700	SF	Room 351	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
158	1' x 1' Ceiling Tile w/ Grooves	2,600	SF	Room 320, 425 - 1911 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159	1' x 1' Ceiling Tile w/ Grooves above HA 161	1,000	SF	Rooms 108, 148, 149, 146	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
160	2' x 4' Ceiling Tile w/ Grooves	22,000	SF	South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet - 1930 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161	2' x 4' Ceiling Tile w/ Grooves	45,000	SF	Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 - 1911 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162	2' x 4' Ceiling Tile - pinhole	13,000	SF	1st Floor Hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				350-361-380 and from room 369-328 and classrooms 352, 364, 366 - 1911 Bldg.							
163	2' x 4' Ceiling Tile - pinholes	4,500	SF	Corridor from pump room- room 184, kitchen, cafeteria - 1930 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
164	12" x 12" Tan w/ light brown specks VFT	1,600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
164A	12" x 12" Tan w/ light brown specks VFT MASTIC	1,600	SF	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
165	9" x 9" Brown w/ yellow design VFT (Not Observed)	100	SF	Room 123 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
165A	9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)	100	SF	Room 123 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
166	12" x 12" Light Blue w/ blue specks VFT (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
166A	12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)	500	SF	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
167	12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)	7,000	SF	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
167A	12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)	7,000	SF	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
168	Black Lab Table Tops	700	SF	Rooms 358, 364, 367	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
169	Black Lab Counter Tops	300	SF	Rooms 358, 364, 367	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
170	Blue Linoleum with MASTIC	2,300	SF	Rooms 358, 364, 366	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
171	12" x 12" Gray w/ tan streaks VFT w/ MASTIC	400	SF	Room 170	Assumed	MISC	No	40	SF	5 ACBM with potential for significant damage	Follow O&M Plan
172	Decorative Plaster	1,200	SF	Assembly hall, vestibule leading to assembly hall	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
173	Terrazzo	2,000	SF	Stairwells, 1st fl. corridor west of pump room - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
174	Terrazzo	1,000	SF	1st Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
175	12" x 12" Blue Speckled VFT (Not Observed)	1,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
176	12" x 12" Blue Speckled VFT Mastic (Not Observed)	1,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
177	12" x 12" Light Blue w/ Specks VFT (Not Observed)	8,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
178	12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)	8,000	SF	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
179	12" x 12" Gray w/ Streaks VFT (Not Observed)	900	SF	Room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
180	12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)	900	SF	Room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
181	Gray Linoleum w/ Granite Pattern	1,200	SF	Room 100, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
182	Gray Linoleum w/ Granite Pattern Mastic	1,200	SF	Room 100, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
183	Gray Linoleum	2,400	SF	Rooms 105, 105A, 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
184	Gray Linoleum Mastic	2,400	SF	Rooms 105, 105A, 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
185	12" x 12" Red w/ Streaks VFT	400	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
186	12" x 12" Red w/ Streaks VFT Mastic	400	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
187	12" x 12" Yellow w/Streaks VFT	400	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
188	12" x 12" Yellow w/Streaks VFT Mastic	400	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
189	12" x 12" Green w/ Streaks VFT	200	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
190	12" x 12" Green w/ Streaks VFT Mastic	200	SF	Health Center (144)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
191	12" x 12" Dark Gray ILnoleum w/ Granite Pattern (Not Observed)	2,000	SF	Main Office (131-134)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
192	12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)	2,000	SF	Main Office (131-134)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
193	12" x 12" Pink w/ Maroon Specks VFT	1,200	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
194	12" x 12" Pink w/ Maroon Specks VFT Mastic	1,200	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
195	12" x 12" Maroon w/ Pink Specks VFT	200	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
196	12" x 12" Maroon w/ Pink Specks VFT Mastic	200	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
197	12" x 12" Beige w/ Beige Specs VFT	2,500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
198	12" x 12" Beige w/ Beige Specs VFT Mastic	2,500	SF	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
199	20" x 20" Off White w/ Specks VFT	2,800	SF	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Mudded Joint Packing on Aircell Pipe Insulation	603	FITTING	Mixing Room, 219, 319, Auditorium	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Crawlspace, Room 120A - 1912 Bldg.							
200	20" x 20" Off White w/ Specks VFT Mastic	2,800	SF	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
201	20" x 20" Beige w/ Specks VFT	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
202	20" x 20" Beige w/ Specks VFT Mastic	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
203	20" x 20" Brown w/ Specks VFT	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
204	20" x 20" Brown w/ Specks VFT Mastic	5,000	SF	Room 225A, Library, 276, 278, 280, 123A thru 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
205	Linoleum Gray w/ Granite Pattern	2,500	SF	Main Office and Associated Offices (131-134)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
206	Linoleum Gray w/ Granite Pattern Mastic	2,500	SF	Main Office and Associated Offices (131-134)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
207	Linoleum Gray w/ Black Spots	2,300	SF	Rooms 151, 155	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
208	Linoleum Gray w/ Black Spots Mastic	2,500	SF	Rooms 151, 155	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
209	12" x 12" Light Gray w/ Specks VFT	20,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
210	12" x 12" Light Gray w/ Specks VFT Mastic	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
211	12" x 12" Dark Gray w/ Specks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
212	12" x 12" Dark Gray w/ Specks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
213	12" x 12" White w/ Red, Blue & Yellow Specks VFT	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
214	12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic	2,500	SF	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
215	12" x 12" Light Gray w/ Specks VFT	10,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
216	12" x 12" Light Gray w/ Specks VFT Mastic	10,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
217	12" x 12" Dark Gray w/ Specks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
218	12" x 12" Dark Gray w/ Specks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Insulation in Vault Door	28	SF	Office - 1912 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Mudded Joint Packing on Aircell Insulation	300	FITTING	Room 238 Chase, Autoshop, Autoshop Tool Room - 1931 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
27	Aircell Pipe Insulation	1,000	LF	Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room - 1931 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
30	Aircell Pipe Insulation	2,600	LF	Rooms 219, 319, & Auditorium Crawlspace - 1912 Bldg.	Chrysotile	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
33	Paperwrap Pipe Insulation	400	LF	Auditorium Crawlspace - 1912 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
34	MJP E/F/V on Paperwrap Pipe Insulation	50	FITTING	Auditorium Crawlspace - 1912 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
39	Hard Coat Plaster			Throughout - 1912 Bldg.	No ACBM						
40	Hard Coat Plaster			Throughout - 1931 Bldg.	No ACBM						
55	12" x 12" Tan w/Speckles VFT	5,000	SF	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	9" x 9" Brown w/Streaks VFT Mastic	500	SF	Room 356	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" Tan w/Speckles VFT Mastic	5,000	SF	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	9" x 9" Maroon VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
61	9" x 9" Maroon VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
62	9" x 9" Brown w/Streaks VFT NOT OBSERVED	500	SF	Room 356 - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" Light Brown w/ White Streaks VFT (Not Observed)	200	SF	Rooms 100, 106, & 106 Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)	200	SF	Rooms 100, 106, & 106 Office - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	9" x 9" Black VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
67	9" x 9" Black VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
68	9" x 9" Black w/Large White Streaks VFT (Abated)			3rd Floor Hall (S&N) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
69	9" x 9" Black w/Large White Streaks VFT Mastic			3rd Floor Hall (S&N) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	(Abated)									suspect ACBM	
70	9" x 9" Brown w/Large White Streaks VFT (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
71	9" x 9" Brown w/Large White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
72	9" x 9" Orange w/White VFT Streaks (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
73	9" x 9" Orange w/White Streaks VFT Mastic (Abated)			3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
76	9" x 9" Maroon w/ White Streaks VFT (Abated)			2nd Floor Hall (S) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
77	9" x 9" Maroon w/ White Streaks VFT Mastic (Abated)			2nd Floor Hall (S) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
78	9" x 9" Black w/ Faint White Streaks VFT (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
79	9" x 9" Black w/ Faint White Streaks VFT Mastic (Abated)			2nd & 3rd Floor Halls (N&S) - 1931 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
80	12" x 12" White w/ Brown Speckles VFT (Not Observed)	1,200	SF	Room 341 & 213 - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12" x 12" White w/ Brown Speckles VFT Mastic	1,200	SF	Room 341 & 213 - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)	600	SF	Room 239 - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12" x 12" Brown w/ Light Brown Speckles VFT Mastic (Not Observed)	600	SF	Room 239 - 1931 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Brown Linoleum	250	SF	238 North Storage - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	Green Linoleum (Not Observed)	5,500	SF	Main Gym, Office & Locker - 1931 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12" x 12" Peach w/ Speckles VFT- NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12" x 12" Peach w/ Speckles VFT Mastic - NOT OBSERVED	700	SF	Rooms 352, 379, 350 Storage - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" x 12" Light Brown w/ Dark Speckles VFT	700	SF	Room 355, 373, 375 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12" x 12" Light Brown w/ Dark Speckles VFT Mastic	700	SF	Room 355, 373, 375 - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Beige w/ Dark Speckles VFT (Not Observed)	2,000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
95	12" x 12" Beige w/ Dark Speckles VFT Mastic (Not Observed)	2,000	SF	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	12" x 12" Dark Brown w/White & Dark Streaks VFT- NOT OBSERVED	1,900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	12" x 12" Dark Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED	1,900	SF	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	12" x 12" Black w/ White Speckles VFT- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12" x 12" Black w/ White Speckles VFT Mastic- NOT OBSERVED	250	SF	3rd Floor Corridor (N) - 1912 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AA	12" x 12" Green Floor Tile - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BB	Mastic associated with HA AA - NOT OBSERVED		SF	3rd floor, side corridor, East to West navy areas - NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CC	Lab Counter Tops	3,500	SF	Classrooms 100, 106, 108, 110, 302, 310, 350	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
DD	Lab Tables	2,600	SF	Classrooms 110, 302, 310, 350	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
EE	Lab Fume Hoods	750	SF	Classrooms 100, 106, 350	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	10/25/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
09	
10	
100	
1000	
1001	
101	
102	
103	
104	
105	
106	
107	
108	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
127 A	
128	
128 A	
13	
133	
134	
135	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
136	
137	
138	
139	
14	
140	
141	
142	
143	
144	
145	
146	
147	
148	
148M	
149	
149M	
150	
150M	
151	
151M	
152	
152M	
153	
153M	
154M	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
155	
155M	
156	
156A	
157	
158	
159	
160	
161	
162	
163	
164	
164A	
165	
165A	
166	
166A	
167	
167A	
168	
169	
170	
171	Replace Damaged VFT
172	
173	
174	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	
188	
189	
190	
191	
192	
193	
194	
195	
196	
197	
198	
199	
20	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
200	
201	
202	
203	
204	
205	
206	
207	
208	
209	
210	
211	
212	
213	
214	
215	
216	
217	
218	
25	
26	
27	
30	
33	
34	
39	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
40	
55	
56	
57	
60	
61	
62	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
76	
77	
78	
79	
80	
81	
86	
87	
88	

Chicago Public Schools

School Senn Academy
Address 5900 N. Glenwood

Unit 47061
Chicago, IL, 60660

Building ID 1540
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
AA	
BB	
CC	
DD	
EE	

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01	
MATERIAL DESCRIPTION:	Boiler Lagging (ABATED 2010)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 1 - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 1 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02	
MATERIAL DESCRIPTION:	Boiler Lagging (ABATED 2010)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 2 - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 2 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03	
MATERIAL DESCRIPTION:	Boiler Lagging (ABATED 2010)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 3 - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 3 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04	
MATERIAL DESCRIPTION:	Boiler Lagging (ABATED 2010)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 4 - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 4 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05	
MATERIAL DESCRIPTION:	Boiler Gasket (ABATED 2010)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 1 - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 1 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06	
MATERIAL DESCRIPTION:	Boiler Gasket (ABATED 2010)	
HISTORICAL AHERA DAMAGE CATEGORY	7	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 2 - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 2 - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	MJP on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1912 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1912 Bldg.**

MATERIAL QUANTITY:	600	MATERIAL UNITS:	FITTING
--------------------	------------	-----------------	----------------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING
------------------	----------	---------------	----------------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	MJP on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **ROTC Room, Boiler & Pump Rooms, Main Tunnel, 2nd & 3rd Floor South Janitors Closet Chase, 2nd Floor Boys Toilet (N), 3rd Floor Unisex Toilet; 1st Floor Janitor's Closet; Under Sinks in Rooms 310, 352, and 366; BookRoom Between Room 315 and 317; Mens Room Next to Room 322 - 1931 Bldg.**

MATERIAL QUANTITY: **425** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **ROTC Room, Boiler & Pump Rooms, Main Tunnel, 2nd & 3rd Floor South Janitors Closet Chase, 2nd Floor Boys Toilet (N), 3rd Floor Unisex Toilet; 1st Floor Janitor's Closet; Under Sinks in Rooms 310, 352, and 366; BookRoom Between Room 315 and 317; Mens Room Next to Room 322 - 1931 Bldg.**

MATERIAL QUANTITY:	425	MATERIAL UNITS:	FITTING
--------------------	------------	-----------------	----------------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING
------------------	----------	---------------	----------------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	9" x 9" Red w/ White Streaks VFT- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	115 Kitchen - 1912 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	9" x 9" Red w/ White Streaks VFT- NOT OBSERVED		
MATERIAL LOCATION:	115 Kitchen - 1912 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1000		
MATERIAL DESCRIPTION:	12" x 12" Orange/Brown VFT- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 180 wooden stage		
MATERIAL QUANTITY:	24	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **1000**

MATERIAL DESCRIPTION: **12" x 12" Orange/Brown VFT- NOT OBSERVED**

MATERIAL LOCATION: **Room 180 wooden stage**

MATERIAL QUANTITY: **24**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1001		
MATERIAL DESCRIPTION:	12" x 12" Orange/Brown VFT Black Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 180 wooden stage		
MATERIAL QUANTITY:	24	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **1001**

MATERIAL DESCRIPTION: **12" x 12" Orange/Brown VFT Black Mastic - NOT OBSERVED**

MATERIAL LOCATION: **Room 180 wooden stage**

MATERIAL QUANTITY: **24**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	9" x 9" Red w/ White Streaks VFT Mastic- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	115 Kitchen - 1912 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	9" x 9" Red w/ White Streaks VFT Mastic- NOT OBSERVED		
MATERIAL LOCATION:	115 Kitchen - 1912 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ White Streaks VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 117A - 1912 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ White Streaks VFT (Not Observed)		
MATERIAL LOCATION:	Rooms 117A - 1912 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ White Streaks VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 117A - 1912 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ White Streaks VFT Mastic (Not Observed)		
MATERIAL LOCATION:	Rooms 117A - 1912 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	12" x 12" Light Green w/ White Streaks VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 123A - 1912 Bldg.		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	12" x 12" Light Green w/ White Streaks VFT (Not Observed)		
MATERIAL LOCATION:	Room 123A - 1912 Bldg.		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 123A - 1912 Bldg.		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	12" x 12" Light Green w/ White Streaks VFT Mastic (Not Observed)		
MATERIAL LOCATION:	Room 123A - 1912 Bldg.		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.**

MATERIAL QUANTITY: **6100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark & White Streaks VFT		
MATERIAL LOCATION:	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.		
MATERIAL QUANTITY:	6100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.**

MATERIAL QUANTITY: **6100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark & White Streaks VFT Mastic		
MATERIAL LOCATION:	Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190 (Engineer's Office), 239 - 1912 Bldg.		
MATERIAL QUANTITY:	6100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	9" x 9" Lt. Brown w/ Dark Red Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.		
MATERIAL QUANTITY:	455	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	9" x 9" Lt. Brown w/ Dark Red Streaks VFT		
MATERIAL LOCATION:	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.		
MATERIAL QUANTITY:	455	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	9" x 9" Lt. Brown w/ Dark Red Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.		
MATERIAL QUANTITY:	455	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	9" x 9" Lt. Brown w/ Dark Red Streaks VFT Mastic		
MATERIAL LOCATION:	Teacher Lunchroom/Lounge, Rooms 300 (under sink), 310 (lab vault) - 1912 Bldg.		
MATERIAL QUANTITY:	455	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	9" x 9" Green w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teacher Lunchroom/Lounge - 1912 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	9" x 9" Green w/ White Streaks VFT		
MATERIAL LOCATION:	Teacher Lunchroom/Lounge - 1912 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	9" x 9" Green w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:	Teacher Lunchroom/Lounge - 1912 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	9" x 9" Green w/ White Streaks VFT Mastic		
MATERIAL LOCATION:	Teacher Lunchroom/Lounge - 1912 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12" x 12" Lt. Brown w/ Gray Speckles VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	153 Vest., 120 Vest. - 1912 Bldg.		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12" x 12" Lt. Brown w/ Gray Speckles VFT (Not Observed)		
MATERIAL LOCATION:	153 Vest., 120 Vest. - 1912 Bldg.		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	12" x 12" Lt. Brown w/ Gray Speckles VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	153 Vest., 120 Vest. - 1912 Bldg.		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	12" x 12" Lt. Brown w/ Gray Speckles VFT Mastic (Not Observed)		
MATERIAL LOCATION:	153 Vest., 120 Vest. - 1912 Bldg.		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown Streaks VFT- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 166, & 162 - 1912 Bldg.		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown Streaks VFT- NOT OBSERVED		
MATERIAL LOCATION:	Rooms 166, & 162 - 1912 Bldg.		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	115		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown Streaks VFT Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 166, & 162 - 1912 Bldg.		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	115		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown Streaks VFT Mastic - NOT OBSERVED		
MATERIAL LOCATION:	Rooms 166, & 162 - 1912 Bldg.		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	116		
MATERIAL DESCRIPTION:	12" x 12" Blue-Gray w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 373 - 1912 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	116		
MATERIAL DESCRIPTION:	12" x 12" Blue-Gray w/ White Streaks VFT		
MATERIAL LOCATION:	Room 373 - 1912 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	117		
MATERIAL DESCRIPTION:	12" x 12" Blue-Gray w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 373 - 1912 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **12" x 12" Blue-Gray w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 373 - 1912 Bldg.**

MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	118		
MATERIAL DESCRIPTION:	12" x 12" Dk Gray w/ Beige Streaks	VFT- NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 176, 174, 180 - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	118		
MATERIAL DESCRIPTION:	12" x 12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED		
MATERIAL LOCATION:	Rooms 176, 174, 180 - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	119		
MATERIAL DESCRIPTION:	12" x 12" Dk Gray w/ Beige Streaks VFT Mastic-	NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 176, 174, 180 - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	119		
MATERIAL DESCRIPTION:	12" x 12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED		
MATERIAL LOCATION:	Rooms 176, 174, 180 - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	120		
MATERIAL DESCRIPTION:	12" x 12" Lt Gray w/ White Speckles VFT- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 176, 174, 180 - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	120		
MATERIAL DESCRIPTION:	12" x 12" Lt Gray w/ White Speckles VFT- NOT OBSERVED		
MATERIAL LOCATION:	Rooms 176, 174, 180 - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	121		
MATERIAL DESCRIPTION:	12" x 12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 176, 174, 180 - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	121		
MATERIAL DESCRIPTION:	12" x 12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED		
MATERIAL LOCATION:	Rooms 176, 174, 180 - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	122		
MATERIAL DESCRIPTION:	12" x 12" Brown VFT- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stage - 1912 Bldg.		
MATERIAL QUANTITY:		MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **122**

MATERIAL DESCRIPTION: **12" x 12" Brown VFT- NOT OBSERVED**

MATERIAL LOCATION: **Stage - 1912 Bldg.**

MATERIAL QUANTITY:		MATERIAL UNITS:	SF
--------------------	--	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	123		
MATERIAL DESCRIPTION:	12" x 12" Brown VFT Mastic- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stage - 1912 Bldg.		
MATERIAL QUANTITY:	0	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **123**

MATERIAL DESCRIPTION: **12" x 12" Brown VFT Mastic- NOT OBSERVED**

MATERIAL LOCATION: **Stage - 1912 Bldg.**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	124	
MATERIAL DESCRIPTION:	2' x 2' Black Border VFT (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 115 Kitchen - 1912 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **124**

MATERIAL DESCRIPTION: **2' x 2' Black Border VFT (Abated)**

MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	125	
MATERIAL DESCRIPTION:	2' x 2' Black Border VFT Mastic- Abated	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 115 Kitchen - 1912 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **125**

MATERIAL DESCRIPTION: **2' x 2' Black Border VFT Mastic- Abated**

MATERIAL LOCATION: **115 Kitchen - 1912 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	126		
MATERIAL DESCRIPTION:	2' x 2' Ceiling Tile- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 425, & 326 - 1912 Bldg.		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	126		
MATERIAL DESCRIPTION:	2' x 2' Ceiling Tile- NOT OBSERVED		
MATERIAL LOCATION:	Room 425, & 326 - 1912 Bldg.		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	127		
MATERIAL DESCRIPTION:	12" x 12" White w/Beige Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 377A		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	127		
MATERIAL DESCRIPTION:	12" x 12" White w/Beige Streaks VFT		
MATERIAL LOCATION:	Room 377A		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	127 A		
MATERIAL DESCRIPTION:	12" x 12" White w/Beige Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 377A		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **127 A**

MATERIAL DESCRIPTION: **12" x 12" White w/Beige Streaks VFT Mastic**

MATERIAL LOCATION: **Room 377A**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	128		
MATERIAL DESCRIPTION:	12" x 12" White w/Blue Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 351		
MATERIAL QUANTITY:	880	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	128		
MATERIAL DESCRIPTION:	12" x 12" White w/Blue Streaks VFT		
MATERIAL LOCATION:	Room 351		
MATERIAL QUANTITY:	880	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	128 A		
MATERIAL DESCRIPTION:	12" x 12" White w/Blue Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 351		
MATERIAL QUANTITY:	880	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **128 A**

MATERIAL DESCRIPTION: **12" x 12" White w/Blue Streaks VFT Mastic**

MATERIAL LOCATION: **Room 351**

MATERIAL QUANTITY: **880**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	MJP on Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor South JC, 2nd Floor Janitor's Closet, 238 Chase, 188, Autoshop - 1931 Bldg.		
MATERIAL QUANTITY:	370	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	13				
MATERIAL DESCRIPTION:	MJP on Paperwrap Pipe Insulation				
MATERIAL LOCATION:	1st Floor South JC, 2nd Floor Janitor's Closet, 238 Chase, 188, Autoshop - 1931 Bldg.				
MATERIAL QUANTITY:	370	MATERIAL UNITS:	FITTING		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	133		
MATERIAL DESCRIPTION:	Lt Blue Speckled Linoleum- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 356, 326 - 1912 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	133		
MATERIAL DESCRIPTION:	Lt Blue Speckled Linoleum- NOT OBSERVED		
MATERIAL LOCATION:	Rooms 356, 326 - 1912 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	134		
MATERIAL DESCRIPTION:	Lt Blue Speckled Linoleum Mastic- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 356, 326 - 1912 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	134		
MATERIAL DESCRIPTION:	Lt Blue Speckled Linoleum Mastic- NOT OBSERVED		
MATERIAL LOCATION:	Rooms 356, 326 - 1912 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	135		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gold Specks VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 174, 176, & 180 - 1912 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	135		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gold Specks VFT (Not Observed)		
MATERIAL LOCATION:	Rooms 174, 176, & 180 - 1912 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	136		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 174, 176, & 180 - 1912 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	136		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gold Specks VFT Mastic (Not Observed)		
MATERIAL LOCATION:	Rooms 174, 176, & 180 - 1912 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	137		
MATERIAL DESCRIPTION:	2' x 4' White Pin-Hole Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 356 - 1912 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	137		
MATERIAL DESCRIPTION:	2' x 4' White Pin-Hole Ceiling Tile		
MATERIAL LOCATION:	Room 356 - 1912 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	138		
MATERIAL DESCRIPTION:	12" x 12" White w/ Beige VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	310 & Office, 302, 108, 110 - 1931 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not Observed in Rooms 319, 110, 108		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	138		
MATERIAL DESCRIPTION:	12" x 12" White w/ Beige VFT		
MATERIAL LOCATION:	310 & Office, 302, 108, 110 - 1931 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	139		
MATERIAL DESCRIPTION:	12" x 12" White w/ Beige VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	310 & Office, 302, 108, 110 - 1931 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in Rooms 310, 110, 108		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	139		
MATERIAL DESCRIPTION:	12" x 12" White w/ Beige VFT Mastic		
MATERIAL LOCATION:	310 & Office, 302, 108, 110 - 1931 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**

MATERIAL LOCATION: **ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 Bldg.**

MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	140		
MATERIAL DESCRIPTION:	12" x 12" Light Gray VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 210, & Engineer's Office - 1931 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	140		
MATERIAL DESCRIPTION:	12" x 12" Light Gray VFT		
MATERIAL LOCATION:	Room 210, & Engineer's Office - 1931 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	141		
MATERIAL DESCRIPTION:	12" x 12" Light Gray VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	210, & Engineer's Office - 1931 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	141		
MATERIAL DESCRIPTION:	12" x 12" Light Gray VFT Mastic		
MATERIAL LOCATION:	210, & Engineer's Office - 1931 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	142		
MATERIAL DESCRIPTION:	12" x 12" Light Blue VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 210, 195A & Engineer's Office - 1931 Bldg.		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	142		
MATERIAL DESCRIPTION:	12" x 12" Light Blue VFT		
MATERIAL LOCATION:	Room 210, 195A & Engineer's Office - 1931 Bldg.		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	143		
MATERIAL DESCRIPTION:	12" x 12" Light Blue VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 210, 195A & Engineer's Office - 1931 Bldg.		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	143		
MATERIAL DESCRIPTION:	12" x 12" Light Blue VFT Mastic		
MATERIAL LOCATION:	Room 210, 195A & Engineer's Office - 1931 Bldg.		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	144		
MATERIAL DESCRIPTION:	12" x 12" Green VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Hall (N&S) - 1931 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	144		
MATERIAL DESCRIPTION:	12" x 12" Green VFT (Not Observed)		
MATERIAL LOCATION:	1st Floor Hall (N&S) - 1931 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	145		
MATERIAL DESCRIPTION:	12" x 12" Green VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Hall (N&S) - 1931 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	145		
MATERIAL DESCRIPTION:	12" x 12" Green VFT Mastic (Not Observed)		
MATERIAL LOCATION:	1st Floor Hall (N&S) - 1931 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	146		
MATERIAL DESCRIPTION:	12" x 12" White VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Hall (N&S) - 1931 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	146		
MATERIAL DESCRIPTION:	12" x 12" White VFT (Not Observed)		
MATERIAL LOCATION:	1st Floor Hall (N&S) - 1931 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	147		
MATERIAL DESCRIPTION:	12" x 12" White VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Hall (N&S) - 1931 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	147		
MATERIAL DESCRIPTION:	12" x 12" White VFT Mastic (Not Observed)		
MATERIAL LOCATION:	1st Floor Hall (N&S) - 1931 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	148		
MATERIAL DESCRIPTION:	Linoleum, Gray w/Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 350, 352, 356 Vault, 306 and 310		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	148		
MATERIAL DESCRIPTION:	Linoleum, Gray w/Gray Streaks		
MATERIAL LOCATION:	Rooms 350, 352, 356 Vault, 306 and 310		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	148M		
MATERIAL DESCRIPTION:	Linoleum, Gray w/Gray Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 350, 352, 356 Vault, 306 and 310		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	148M		
MATERIAL DESCRIPTION:	Linoleum, Gray w/Gray Streaks Mastic		
MATERIAL LOCATION:	Rooms 350, 352, 356 Vault, 306 and 310		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	149		
MATERIAL DESCRIPTION:	Linoleum, Blue Solid		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 100, 106, and 106 Office		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	149		
MATERIAL DESCRIPTION:	Linoleum, Blue Solid		
MATERIAL LOCATION:	Rooms 100, 106, and 106 Office		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	149M		
MATERIAL DESCRIPTION:	Linoleum, Blue Solid Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 100, 106, and 106 Office		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **149M**

MATERIAL DESCRIPTION: **Linoleum, Blue Solid Mastic**

MATERIAL LOCATION: **Rooms 100, 106, and 106 Office**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	150		
MATERIAL DESCRIPTION:	12" x 12" VFT- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	150				
MATERIAL DESCRIPTION:	12" x 12" VFT- NOT OBSERVED				
MATERIAL LOCATION:	3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED				
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	150M		
MATERIAL DESCRIPTION:	12" x 12" VFT Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **150M**

MATERIAL DESCRIPTION: **12" x 12" VFT Mastic - NOT OBSERVED**

MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**

MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	151		
MATERIAL DESCRIPTION:	12" x 12" Solid Gray VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	151		
MATERIAL DESCRIPTION:	12" x 12" Solid Gray VFT		
MATERIAL LOCATION:	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	151M		
MATERIAL DESCRIPTION:	12" x 12" Solid Gray VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **151M**

MATERIAL DESCRIPTION: **12" x 12" Solid Gray VFT Mastic**

MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor**

MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	152		
MATERIAL DESCRIPTION:	12" x 12" Tan w/Brown Speckles VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	152		
MATERIAL DESCRIPTION:	12" x 12" Tan w/Brown Speckles VFT (Not Observed)		
MATERIAL LOCATION:	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	152M		
MATERIAL DESCRIPTION:	12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	152M		
MATERIAL DESCRIPTION:	12" x 12" Tan w/Brown Speckles VFT Mastic (Not Observed)		
MATERIAL LOCATION:	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Center of Corridor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	153		
MATERIAL DESCRIPTION:	12" x 12" White w/ Tan Speckles VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	153		
MATERIAL DESCRIPTION:	12" x 12" White w/ Tan Speckles VFT (Not Observed)		
MATERIAL LOCATION:	3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	153M		
MATERIAL DESCRIPTION:	12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **153M**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Speckles VFT Mastic (Not Observed)**

MATERIAL LOCATION: **3rd Floor Side Corridor-North, Runs East-to-West in Naval Area, Border Along N. and S. Walls**

MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	154M		
MATERIAL DESCRIPTION:	Gold, Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 379, 375, 326, 315, and 272 (not observed), Room 225		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Observed in Room 379 only		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **154M**

MATERIAL DESCRIPTION: **Gold, Blue Carpet Mastic**

MATERIAL LOCATION: **Rooms 379, 375, 326, 315, and 272 (not observed), Room 225**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	155		
MATERIAL DESCRIPTION:	Linoleum, White w/Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 352		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Observed in Room 379 only		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	155		
MATERIAL DESCRIPTION:	Linoleum, White w/Gray Streaks		
MATERIAL LOCATION:	Room 352		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	155M		
MATERIAL DESCRIPTION:	Linoleum, White w/Gray Streaks	Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 352		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **155M**

MATERIAL DESCRIPTION: **Linoleum, White w/Gray Streaks Mastic**

MATERIAL LOCATION: **Room 352**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	156		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Gray and White Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 377		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	156		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Gray and White Specks VFT		
MATERIAL LOCATION:	Room 377		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	156A		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 377**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **156A**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Gray and White Specks VFT MASTIC**

MATERIAL LOCATION: **Room 377**

MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	157		
MATERIAL DESCRIPTION:	2' x 4' Smooth Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 351		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	157		
MATERIAL DESCRIPTION:	2' x 4' Smooth Ceiling Tile		
MATERIAL LOCATION:	Room 351		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	158		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile w/ Grooves		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 320, 425 - 1911 Bldg.		
MATERIAL QUANTITY:	2600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	158		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile w/ Grooves		
MATERIAL LOCATION:	Room 320, 425 - 1911 Bldg.		
MATERIAL QUANTITY:	2600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	159		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile w/ Grooves above HA 161		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 108, 148, 149, 146		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	159		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile w/ Grooves above HA 161		
MATERIAL LOCATION:	Rooms 108, 148, 149, 146		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	160		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile w/ Grooves		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet - 1930 Bldg.**

MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: 160

MATERIAL DESCRIPTION: 2' x 4' Ceiling Tile w/ Grooves

MATERIAL LOCATION: South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet - 1930 Bldg.

MATERIAL QUANTITY: 22000

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	161		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile w/ Grooves		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 - 1911 Bldg.**

MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **10/10/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: 161

MATERIAL DESCRIPTION: 2' x 4' Ceiling Tile w/ Grooves

MATERIAL LOCATION: Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 - 1911 Bldg.

MATERIAL QUANTITY: 45000

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	162		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile - pinhole		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352, 364, 366 - 1911 Bldg.**

MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	162				
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile - pinhole				
MATERIAL LOCATION:	1st Floor Hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352, 364, 366 - 1911 Bldg.				
MATERIAL QUANTITY:	13000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	163		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile - pinholes		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridor from pump room- room 184, kitchen, cafeteria - 1930 Bldg.		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	163		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile - pinholes		
MATERIAL LOCATION:	Corridor from pump room- room 184, kitchen, cafeteria - 1930 Bldg.		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	164		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ light brown specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in 1st Floor Corridor		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	164		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ light brown specks VFT		
MATERIAL LOCATION:	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	164A		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ light brown specks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in 1st floor corridor		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	164A		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ light brown specks VFT MASTIC		
MATERIAL LOCATION:	Rooms 119, 121, 1st Floor South corridor - 1912 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	165		
MATERIAL DESCRIPTION:	9" x 9" Brown w/ yellow design VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 123 - 1912 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	165		
MATERIAL DESCRIPTION:	9" x 9" Brown w/ yellow design VFT (Not Observed)		
MATERIAL LOCATION:	Room 123 - 1912 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	165A		
MATERIAL DESCRIPTION:	9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 123 - 1912 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **165A**

MATERIAL DESCRIPTION: **9" x 9" Brown w/ yellow design VFT MASTIC (Not Observed)**

MATERIAL LOCATION: **Room 123 - 1912 Bldg.**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	166		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ blue specks VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	166		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ blue specks VFT (Not Observed)		
MATERIAL LOCATION:	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	166A		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	166A		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ blue specks VFT MASTIC (Not Observed)		
MATERIAL LOCATION:	2nd, 3rd Floor main center corridor, Health Center (144) - 1912 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	167		
MATERIAL DESCRIPTION:	12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	167		
MATERIAL DESCRIPTION:	12" x 12" White w/light blue, gray and yellow specks VFT (Not Observed)		
MATERIAL LOCATION:	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	167A		
MATERIAL DESCRIPTION:	12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	167A		
MATERIAL DESCRIPTION:	12" x 12" White w/ light blue, gray and yellow specks VFT MASTIC (Not Observed)		
MATERIAL LOCATION:	2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 - 1912 Bldg.		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	168		
MATERIAL DESCRIPTION:	Black Lab Table Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 358, 364, 367		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	168		
MATERIAL DESCRIPTION:	Black Lab Table Tops		
MATERIAL LOCATION:	Rooms 358, 364, 367		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	169		
MATERIAL DESCRIPTION:	Black Lab Counter Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 358, 364, 367		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	169		
MATERIAL DESCRIPTION:	Black Lab Counter Tops		
MATERIAL LOCATION:	Rooms 358, 364, 367		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	170		
MATERIAL DESCRIPTION:	Blue Linoleum with MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 358, 364, 366		
MATERIAL QUANTITY:	2300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	170		
MATERIAL DESCRIPTION:	Blue Linoleum with MASTIC		
MATERIAL LOCATION:	Rooms 358, 364, 366		
MATERIAL QUANTITY:	2300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	171		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ tan streaks VFT w/ MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 170		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	40	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **171**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ tan streaks VFT w/ MASTIC**

MATERIAL LOCATION: **Room 170**

MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	40	DAMAGE UNITS:	SF
------------------	-----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Replace Damaged VFT

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	172		
MATERIAL DESCRIPTION:	Decorative Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly hall, vestibule leading to assembly hall		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	172		
MATERIAL DESCRIPTION:	Decorative Plaster		
MATERIAL LOCATION:	Assembly hall, vestibule leading to assembly hall		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	173		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairwells, 1st fl. corridor west of pump room - 1931 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	173		
MATERIAL DESCRIPTION:	Terrazzo		
MATERIAL LOCATION:	Stairwells, 1st fl. corridor west of pump room - 1931 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	174		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridors - 1912 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	174		
MATERIAL DESCRIPTION:	Terrazzo		
MATERIAL LOCATION:	1st Floor Corridors - 1912 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	175		
MATERIAL DESCRIPTION:	12" x 12" Blue Speckled VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor NW & W corridor, 2nd floor W & center corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	175		
MATERIAL DESCRIPTION:	12" x 12" Blue Speckled VFT (Not Observed)		
MATERIAL LOCATION:	3rd Floor NW & W corridor, 2nd floor W & center corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	176		
MATERIAL DESCRIPTION:	12" x 12" Blue Speckled VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor NW & W corridor, 2nd floor W & center corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	176		
MATERIAL DESCRIPTION:	12" x 12" Blue Speckled VFT Mastic (Not Observed)		
MATERIAL LOCATION:	3rd Floor NW & W corridor, 2nd floor W & center corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	177		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ Specks VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	177		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ Specks VFT (Not Observed)		
MATERIAL LOCATION:	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	178		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	178		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ Specks VFT Mastic (Not Observed)		
MATERIAL LOCATION:	3rd Floor NW & W corridor, 2nd floor W & center corridor - 1912 Bldg.		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	179		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Streaks VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 221		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	179		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Streaks VFT (Not Observed)		
MATERIAL LOCATION:	Room 221		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	180		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 221		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	180		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Streaks VFT Mastic (Not Observed)		
MATERIAL LOCATION:	Room 221		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	181		
MATERIAL DESCRIPTION:	Gray Linoleum w/ Granite Pattern		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 100, 108		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **181**

MATERIAL DESCRIPTION: **Gray Linoleum w/ Granite Pattern**

MATERIAL LOCATION: **Room 100, 108**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	182		
MATERIAL DESCRIPTION:	Gray Linoleum w/ Granite Pattern Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 100, 108		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	182		
MATERIAL DESCRIPTION:	Gray Linoleum w/ Granite Pattern Mastic		
MATERIAL LOCATION:	Room 100, 108		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	183		
MATERIAL DESCRIPTION:	Gray Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 105, 105A, 110		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	183		
MATERIAL DESCRIPTION:	Gray Linoleum		
MATERIAL LOCATION:	Rooms 105, 105A, 110		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	184		
MATERIAL DESCRIPTION:	Gray Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 105, 105A, 110		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	184		
MATERIAL DESCRIPTION:	Gray Linoleum Mastic		
MATERIAL LOCATION:	Rooms 105, 105A, 110		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	185		
MATERIAL DESCRIPTION:	12" x 12" Red w/ Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	185		
MATERIAL DESCRIPTION:	12" x 12" Red w/ Streaks VFT		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	186		
MATERIAL DESCRIPTION:	12" x 12" Red w/ Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	186		
MATERIAL DESCRIPTION:	12" x 12" Red w/ Streaks VFT Mastic		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	187		
MATERIAL DESCRIPTION:	12" x 12" Yellow w/Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	187		
MATERIAL DESCRIPTION:	12" x 12" Yellow w/Streaks VFT		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	188		
MATERIAL DESCRIPTION:	12" x 12" Yellow w/Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	188		
MATERIAL DESCRIPTION:	12" x 12" Yellow w/Streaks VFT Mastic		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	189		
MATERIAL DESCRIPTION:	12" x 12" Green w/ Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	189		
MATERIAL DESCRIPTION:	12" x 12" Green w/ Streaks VFT		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	190		
MATERIAL DESCRIPTION:	12" x 12" Green w/ Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	190		
MATERIAL DESCRIPTION:	12" x 12" Green w/ Streaks VFT Mastic		
MATERIAL LOCATION:	Health Center (144)		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	191		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray ILnoleum w/ Granite Pattern (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office (131-134)		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **191**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray ILnoleum w/ Granite Pattern (Not Observed)**

MATERIAL LOCATION: **Main Office (131-134)**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	192		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office (131-134)		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	192		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Linoleum w/ Granite Pattern Mastic (Not Observed)		
MATERIAL LOCATION:	Main Office (131-134)		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	193		
MATERIAL DESCRIPTION:	12" x 12" Pink w/ Maroon Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 115		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	193		
MATERIAL DESCRIPTION:	12" x 12" Pink w/ Maroon Specks VFT		
MATERIAL LOCATION:	Room 115		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	194		
MATERIAL DESCRIPTION:	12" x 12" Pink w/ Maroon Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 115		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	194		
MATERIAL DESCRIPTION:	12" x 12" Pink w/ Maroon Specks VFT Mastic		
MATERIAL LOCATION:	Room 115		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	195		
MATERIAL DESCRIPTION:	12" x 12" Maroon w/ Pink Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 115		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	195		
MATERIAL DESCRIPTION:	12" x 12" Maroon w/ Pink Specks VFT		
MATERIAL LOCATION:	Room 115		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	196		
MATERIAL DESCRIPTION:	12" x 12" Maroon w/ Pink Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 115		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	196		
MATERIAL DESCRIPTION:	12" x 12" Maroon w/ Pink Specks VFT Mastic		
MATERIAL LOCATION:	Room 115		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Mudded Joint Packing on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mixing Room, 219, 319, Auditorium Crawlspace, Room 120A - 1912 Bldg.		
MATERIAL QUANTITY:	603	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**

MATERIAL LOCATION: **Mixing Room, 219, 319, Auditorium Crawlspce, Room 120A - 1912 Bldg.**

MATERIAL QUANTITY:	603	MATERIAL UNITS:	FITTING
--------------------	------------	-----------------	----------------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING
------------------	----------	---------------	----------------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Insulation in Vault Door		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office - 1912 Bldg.		
MATERIAL QUANTITY:	28	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Insulation in Vault Door**

MATERIAL LOCATION: **Office - 1912 Bldg.**

MATERIAL QUANTITY: **28**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Mudded Joint Packing on Aircell Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 238 Chase, Autoshop, Autoshop Tool Room - 1931 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Insulation**

MATERIAL LOCATION: **Room 238 Chase, Autoshop, Autoshop Tool Room - 1931 Bldg.**

MATERIAL QUANTITY:	300	MATERIAL UNITS:	FITTING
--------------------	------------	-----------------	----------------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING
------------------	----------	---------------	----------------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room - 1931 Bldg.**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room - 1931 Bldg.**

MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 219, 319, & Auditorium Crawlspace - 1912 Bldg.		
MATERIAL QUANTITY:	2600	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Rooms 219, 319, & Auditorium Crawlspace - 1912 Bldg.**

MATERIAL QUANTITY:	2600	MATERIAL UNITS:	LF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Crawlspace - 1912 Bldg.		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Auditorium Crawlspace - 1912 Bldg.**

MATERIAL QUANTITY:	400	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	MJP E/F/V on Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Crawlspace - 1912 Bldg.		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	0	DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Auditorium Crawlspace - 1912 Bldg.**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39	
MATERIAL DESCRIPTION:	Hard Coat Plaster	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout - 1912 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout - 1912 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40	
MATERIAL DESCRIPTION:	Hard Coat Plaster	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout - 1931 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	12" x 12" Tan w/Speckles VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in 3rd Floor Corridor		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	12" x 12" Tan w/Speckles VFT		
MATERIAL LOCATION:	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	9" x 9" Brown w/Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 356		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT Mastic**

MATERIAL LOCATION: **Room 356**

MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	12" x 12" Tan w/Speckles VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in 3rd Floor Corridor		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" Tan w/Speckles VFT Mastic**

MATERIAL LOCATION: **3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 Bldg.**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60	
MATERIAL DESCRIPTION:	9" x 9" Maroon VFT (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9" x 9" Maroon VFT (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61	
MATERIAL DESCRIPTION:	9" x 9" Maroon VFT Mastic (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **9" x 9" Maroon VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	9" x 9" Brown w/Streaks VFT NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 356 - NOT OBSERVED		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT NOT OBSERVED**

MATERIAL LOCATION: **Room 356 - NOT OBSERVED**

MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White Streaks VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 100, 106, & 106 Office - 1931 Bldg.		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Streaks VFT (Not Observed)**

MATERIAL LOCATION: **Rooms 100, 106, & 106 Office - 1931 Bldg.**

MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 100, 106, & 106 Office - 1931 Bldg.		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White Streaks VFT Mastic (Not Observed)		
MATERIAL LOCATION:	Rooms 100, 106, & 106 Office - 1931 Bldg.		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66	
MATERIAL DESCRIPTION:	9" x 9" Black VFT (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **9" x 9" Black VFT (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67	
MATERIAL DESCRIPTION:	9" x 9" Black VFT Mastic (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **9" x 9" Black VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68	
MATERIAL DESCRIPTION:	9" x 9" Black w/Large White Streaks VFT (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Hall (S&N) - 1931 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **9" x 9" Black w/Large White Streaks VFT (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69	
MATERIAL DESCRIPTION:	9" x 9" Black w/Large White Streaks VFT Mastic (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Hall (S&N) - 1931 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **9" x 9" Black w/Large White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70	
MATERIAL DESCRIPTION:	9" x 9" Brown w/Large White Streaks VFT (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **9" x 9" Brown w/Large White Streaks VFT (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71	
MATERIAL DESCRIPTION:	9" x 9" Brown w/Large White Streaks VFT Mastic (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **9" x 9" Brown w/Large White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72	
MATERIAL DESCRIPTION:	9" x 9" Orange w/White VFT Streaks (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:	Deterioration	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **9" x 9" Orange w/White VFT Streaks (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73	
MATERIAL DESCRIPTION:	9" x 9" Orange w/White Streaks VFT Mastic (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **9" x 9" Orange w/White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76	
MATERIAL DESCRIPTION:	9" x 9" Maroon w/ White Streaks VFT (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Hall (S) - 1931 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **9" x 9" Maroon w/ White Streaks VFT (Abated)**

MATERIAL LOCATION: **2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77	
MATERIAL DESCRIPTION:	9" x 9" Maroon w/ White Streaks VFT Mastic (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Hall (S) - 1931 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **9" x 9" Maroon w/ White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **2nd Floor Hall (S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78	
MATERIAL DESCRIPTION:	9" x 9" Black w/ Faint White Streaks VFT (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd & 3rd Floor Halls (N&S) - 1931 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **9" x 9" Black w/ Faint White Streaks VFT (Abated)**

MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79	
MATERIAL DESCRIPTION:	9" x 9" Black w/ Faint White Streaks VFT Mastic (Abated)	
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd & 3rd Floor Halls (N&S) - 1931 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **9" x 9" Black w/ Faint White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	12" x 12" White w/ Brown Speckles VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 341 & 213 - 1931 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Speckles VFT (Not Observed)**

MATERIAL LOCATION: **Room 341 & 213 - 1931 Bldg.**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	12" x 12" White w/ Brown Speckles VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 341 & 213 - 1931 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Speckles VFT Mastic**

MATERIAL LOCATION: **Room 341 & 213 - 1931 Bldg.**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 239 - 1931 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Brown Speckles VFT (Not observed)**

MATERIAL LOCATION: **Room 239 - 1931 Bldg.**

MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Light Brown Speckles VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 239 - 1931 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Brown Speckles VFT Mastic (Not Observed)**

MATERIAL LOCATION: **Room 239 - 1931 Bldg.**

MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	Brown Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	238 North Storage - 1931 Bldg.		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Brown Linoleum**

MATERIAL LOCATION: **238 North Storage - 1931 Bldg.**

MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	Green Linoleum (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Gym, Office & Locker - 1931 Bldg.		
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **Green Linoleum (Not Observed)**

MATERIAL LOCATION: **Main Gym, Office & Locker - 1931 Bldg.**

MATERIAL QUANTITY: **5500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12" x 12" Peach w/ Speckles VFT- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 352, 379, 350 Storage - 1912 Bldg.		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" Peach w/ Speckles VFT- NOT OBSERVED**

MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912 Bldg.**

MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	12" x 12" Peach w/ Speckles VFT Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 352, 379, 350 Storage - 1912 Bldg.		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12" x 12" Peach w/ Speckles VFT Mastic - NOT OBSERVED**

MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912 Bldg.**

MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	92		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Dark Speckles VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 355, 373, 375 - 1912 Bldg.		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in rooms 373 and 375		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Speckles VFT**

MATERIAL LOCATION: **Room 355, 373, 375 - 1912 Bldg.**

MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	93		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Dark Speckles VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 355, 373, 375 - 1912 Bldg.		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in Rooms 373 and 375		

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Speckles VFT Mastic**

MATERIAL LOCATION: **Room 355, 373, 375 - 1912 Bldg.**

MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	94		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark Speckles VFT (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Speckles VFT (Not Observed)**

MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	95		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark Speckles VFT Mastic (Not Observed)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Speckles VFT Mastic (Not Observed)**

MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912 Bldg.**

MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	96		
MATERIAL DESCRIPTION:	12" x 12" Dark Brown w/White & Dark Streaks VFT- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.		
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/White & Dark Streaks VFT- NOT OBSERVED**

MATERIAL LOCATION: **3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.**

MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	97		
MATERIAL DESCRIPTION:	12" x 12" Dark Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.		
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	97		
MATERIAL DESCRIPTION:	12" x 12" Dark Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED		
MATERIAL LOCATION:	3rd Floor Corridors, 223, 221, 117B - 1912 Bldg.		
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	98		
MATERIAL DESCRIPTION:	12" x 12" Black w/ White Speckles VFT- NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor (N) - 1912 Bldg.		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT- NOT OBSERVED**

MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912 Bldg.**

MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	99		
MATERIAL DESCRIPTION:	12" x 12" Black w/ White Speckles VFT Mastic-	NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor (N) - 1912 Bldg.		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT Mastic- NOT OBSERVED**

MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912 Bldg.**

MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	AA		
MATERIAL DESCRIPTION:	12" x 12" Green Floor Tile - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **AA**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile - NOT OBSERVED**

MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas**

MATERIAL QUANTITY:		MATERIAL UNITS:	SF
--------------------	--	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	BB		
MATERIAL DESCRIPTION:	Mastic associated with HA AA - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd floor, side corridor, East to West navy areas - NOT OBSERVED		
MATERIAL QUANTITY:		MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **BB**

MATERIAL DESCRIPTION: **Mastic associated with HA AA - NOT OBSERVED**

MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas - NOT OBSERVED**

MATERIAL QUANTITY:		MATERIAL UNITS:	SF
--------------------	--	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	CC		
MATERIAL DESCRIPTION:	Lab Counter Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms 100, 106, 108, 110, 302, 310, 350		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **CC**

MATERIAL DESCRIPTION: **Lab Counter Tops**

MATERIAL LOCATION: **Classrooms 100, 106, 108, 110, 302, 310, 350**

MATERIAL QUANTITY: **3500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	DD		
MATERIAL DESCRIPTION:	Lab Tables		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms 110, 302, 310, 350		
MATERIAL QUANTITY:	2600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **DD**

MATERIAL DESCRIPTION: **Lab Tables**

MATERIAL LOCATION: **Classrooms 110, 302, 310, 350**

MATERIAL QUANTITY: **2600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	EE		
MATERIAL DESCRIPTION:	Lab Fume Hoods		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms 100, 106, 350		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **EE**

MATERIAL DESCRIPTION: **Lab Fume Hoods**

MATERIAL LOCATION: **Classrooms 100, 106, 350**

MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	197		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Beige Specs VFT		
MATERIAL LOCATION:	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **10/10/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	197		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Beige Specs VFT		
MATERIAL LOCATION:	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	218				
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/ Specks VFT Mastic				
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/25/2019**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **218**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	201		
MATERIAL DESCRIPTION:	20" x 20" Beige w/ Specks VFT		
MATERIAL LOCATION:	Room 225A, Library, 276, 278, 280, 123A thru 117		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/25/2019**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **201**
MATERIAL DESCRIPTION: **20" x 20" Beige w/ Specks VFT**
MATERIAL LOCATION: **Room 225A, Library, 276, 278, 280, 123A thru 117**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	207		
MATERIAL DESCRIPTION:	Linoleum Gray w/ Black Spots		
MATERIAL LOCATION:	Rooms 151, 155		
MATERIAL QUANTITY:	2300	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/25/2019**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **207**
MATERIAL DESCRIPTION: **Linoleum Gray w/ Black Spots**
MATERIAL LOCATION: **Rooms 151, 155**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	214		
MATERIAL DESCRIPTION:	12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/25/2019**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **214**
MATERIAL DESCRIPTION: **12" x 12" White w/ Red, Blue & Yellow Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	198		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Beige Specs VFT Mastic		
MATERIAL LOCATION:	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **10/10/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	198		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Beige Specs VFT Mastic		
MATERIAL LOCATION:	Rooms 366 Storage, 364 Storage, 358 Storage, 315, 195B, 139		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	203				
MATERIAL DESCRIPTION:	20" x 20" Brown w/ Specks VFT				
MATERIAL LOCATION:	Room 225A, Library, 276, 278, 280, 123A thru 117				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	203				
MATERIAL DESCRIPTION:	20" x 20" Brown w/ Specks VFT				
MATERIAL LOCATION:	Room 225A, Library, 276, 278, 280, 123A thru 117				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	208		
MATERIAL DESCRIPTION:	Linoleum Gray w/ Black Spots Mastic		
MATERIAL LOCATION:	Rooms 151, 155		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	208				
MATERIAL DESCRIPTION:	Linoleum Gray w/ Black Spots Mastic				
MATERIAL LOCATION:	Rooms 151, 155				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	213				
MATERIAL DESCRIPTION:	12" x 12" White w/ Red, Blue & Yellow Specks VFT				
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/25/2019**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **213**
MATERIAL DESCRIPTION: **12" x 12" White w/ Red, Blue & Yellow Specks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	217		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/ Specks VFT		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	217				
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/ Specks VFT				
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	202				
MATERIAL DESCRIPTION:	20" x 20" Beige w/ Specks VFT Mastic				
MATERIAL LOCATION:	Room 225A, Library, 276, 278, 280, 123A thru 117				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	202				
MATERIAL DESCRIPTION:	20" x 20" Beige w/ Specks VFT Mastic				
MATERIAL LOCATION:	Room 225A, Library, 276, 278, 280, 123A thru 117				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	204				
MATERIAL DESCRIPTION:	20" x 20" Brown w/ Specks VFT Mastic				
MATERIAL LOCATION:	Room 225A, Library, 276, 278, 280, 123A thru 117				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	204				
MATERIAL DESCRIPTION:	20" x 20" Brown w/ Specks VFT Mastic				
MATERIAL LOCATION:	Room 225A, Library, 276, 278, 280, 123A thru 117				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	206				
MATERIAL DESCRIPTION:	Linoleum Gray w/ Granite Pattern Mastic				
MATERIAL LOCATION:	Main Office and Associated Offices (131-134)				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	206				
MATERIAL DESCRIPTION:	Linoleum Gray w/ Granite Pattern Mastic				
MATERIAL LOCATION:	Main Office and Associated Offices (131-134)				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	199		
MATERIAL DESCRIPTION:	20" x 20" Off White w/ Specks VFT		
MATERIAL LOCATION:	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/25/2019**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **199**
MATERIAL DESCRIPTION: **20" x 20" Off White w/ Specks VFT**
MATERIAL LOCATION: **Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	200				
MATERIAL DESCRIPTION:	20" x 20" Off White w/ Specks VFT Mastic				
MATERIAL LOCATION:	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117				
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	200				
MATERIAL DESCRIPTION:	20" x 20" Off White w/ Specks VFT Mastic				
MATERIAL LOCATION:	Rooms 339, 239, 225A, Library, 213, 276, 278, 280, 123A thru 117				
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	212		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/ Specks VFT Mastic		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/25/2019**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **212**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	209				
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Specks VFT				
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.				
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	209				
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Specks VFT				
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.				
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	215				
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Specks VFT				
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.				
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	215				
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Specks VFT				
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.				
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	205				
MATERIAL DESCRIPTION:	Linoleum Gray w/ Granite Pattern				
MATERIAL LOCATION:	Main Office and Associated Offices (131-134)				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	205				
MATERIAL DESCRIPTION:	Linoleum Gray w/ Granite Pattern				
MATERIAL LOCATION:	Main Office and Associated Offices (131-134)				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	210		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Specks VFT Mastic		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Senn Academy	REVIEW DATE:	10/25/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA:	210				
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Specks VFT Mastic				
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.				
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	211				
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/ Specks VFT				
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1912 Bldg.				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/25/2019**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **211**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Specks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1912 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	47061	BUILDING ID:	1540
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Senn Academy	INSPECTION DATE:	10/10/2019		
ADDRESS:	5900 N. Glenwood	IDPH LICENSE NO:	100-11093		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	216		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Specks VFT Mastic		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors - 1931 Bldg.		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/10/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Senn Academy** REVIEW DATE: **10/25/2019**
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **216**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1931 Bldg.**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/25/2019**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

DAVID AVILA

This is to certify that _____
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/13/2016 _____ with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR08

Certificate Number:

Phone: 312-491-0081

Director of Training

Nicholas J. Penoff

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

5/9/2018

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11093	ISSUED 5/9/2018	EXPIRES 05/15/2019		INSPECTOR	2/10/2019
DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		PROJECT MANAGER 9/16/2018 AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that DAVID AVILA
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



PUBLIC HEALTH & SAFETY INC.

Environmental and Occupational Services
378 Ashland Ave., Chicago, IL 60617
www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR05

Certificate Number:

Nicholas J. Peneff

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11093	ISSUED 4/19/2019	INSPECTOR	2/9/2020
EXPIRES 05/15/2020		PROJECT MANAGER	9/15/2019
DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	2/28/2020
100 - 07342	4/19/2019	05/15/2020	PROJECT DESIGNER	3/15/2020
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	2/28/2020
			PROJECT MANAGER	2/22/2020
			AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos

EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed