

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0617
SCHOOL NAME: Curie Metro High School
ADDRESS OF SCHOOL: 4959 S. Archer
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/23/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 2828
IDPH INSPECTOR LICENSE NUMBER: 100-05090
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Herman
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Curie Metro High School

4959 S. Archer
Chicago, IL, 60632

Unit: 53101
Building ID: 1820

IDPH ID Number: 14-016-2990-0617

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

May 7, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 53101 Region: 04 IDPH ID:14-016-2990-0617

School: Curie Metro High School Building ID: 1820

Address: 4959 S. Archer

Chicago, IL, 60632

Building Contact: Damico, Justin

Contact Phone:(773) 255-5134

Current Building Owners: Chicago Public Schools

Review Date: 05/31/2019

Inspector: Michael Herman

Inspector IDPH License: 100-05090

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 07, 2019

RE: Curie Metro High School, Unit 53101
4959 S. Archer
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Curie Metro High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Curie Metro High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Curie Metro High School	Unit: 53101	Region: 04
Address:	4959 S. Archer	Chicago, IL, 60632	
IDPH ID:	14-016-2990-0617	Building ID: 1820	
Contact:	Damico, Justin	Phone: (773) 255-5134	

2. Description of Facility

Original Construction: 1973	Additional Construction:
Total Square Footage: 245084	No of Floors: 3
Current Occupancy: 2828	

3. LEA Designated Person

Contact: Robert Christlieb	Phone: (773) 553-3197
Address: 42 West Madison Street	
Chicago, IL 60602	

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates	
Contact: Doug McCormick	
Address 600 West Van Buren St., Ste 500	
Chicago, IL, 60607	
Phone: (312) 762-2900	Fax: (312) 782-5145

5. Inspector

Inspector Name: Michael Herman

Inspector IDPH license # 100-05090

Signature:
Date: 5/7/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 05/31/2019

7. Review Date: 05/31/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Curie Metro High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1820:

11	Duct Work Tape
15	Inner Duct Insulation
16	Spray-on Fire Proofing
19	Fire Doors
27	Dry Wall
28A	Drywall Joint Compound
2B	2x4 Ceiling
31A	Interior Casing Caulk
7	Plaster

70	Vault Door Insulation
8	2x4 Insulation

B. The following new homogenous areas have been identified for Building 1820:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

15	Inner Duct Insulation
16	Spray-on Fire Proofing
17	2' x 4' Sound Baffles
18	Metal Encased Sound baffles
20	Fiberglass Batting Above Lights
22.10	12" x 12" White w/Brown Specks Floor Tile
22.11	12" x 12" Pinkish Beige Mix Floor Tile
22.12	12" x 12" Lt. Gray w/Brown Streaks Floor Tile
22.13	12" x 12" White w/Peach Specks Floor Tile
22.14	12" x 12" White Floor Tile
22.3	12"x12" Off-White Floor Tile Brown/White Speckles
22.4	12x12 Brown VFT w/ Brown & White Speckles
22.5	12x12 Cream VAT w/ White Speckles
22.6	12x12 Black VFT w/ Black & Brown Speckles
22.7	12x12 VFT w/ Brown, White, and Tan Speckles
22.8	12x12 Off White FT w/Brn, Tan, White Speckles
22.9	12x12 Yellow FT w/Tan,Yellow,White Speckles
23.1A	Mastic under 12x12 VFT Brown, Tan, White Speckles
23.1B	Mastic Under 12x12 Off-Wh VFT w/ Yel & Bwn Speckle
23.1C	Mastic for 12x12 Off-Wh VAT w/ Bwn & Wh Speckles
23.1D	Mastic for 12x12 Bwn VATw/ Bwn & Wh Speckles
23.1E	Mastic for 12x12 Cream VAT, Wht Speckles
23.1F	Mastic for 12x12 Black Vat w/ Blk & Bwn Speckles
23.2	Mastic for 12x12 VAT, Brown, Tan, & Wht Speckles
23.3	12x12 Off White FT w/Brn, Tan, White Speck Mastic
23.4	12x12 Yellow w/Tan, Yell,White Speckles FT Mastic
23.5	12" x 12" White w/Brown Specks Floor Tile Mastic
23.6	12" x 12" Pinkish Beige Mix Floor Tile Mastic
23.7	12" x 12" Lt. Gray w/Brown Streaks FT Mastic
23.8	12" x 12" White w/Peach Specks Floor Tile Mastic
23.9	12" x 12" White Floor Tile Mastic
24	4" Black Baseboard
25	4" Black Baseboard Mastic
27	Dry Wall
28A	Drywall Joint Compound

2B	2x4 Ceiling
31A	Interior Casing Caulk
34	Carpet Mastic
34.1	Gray Carpet Adhesive
34.10	Brown/Green/Light Brown Carpet Adhesive
34.11	Green Carpet Adhesive
34.2	Brown Carpet Adhesive
34.4	Bright Blue Carpet Adhesive
34.5	Light Brown Carpet Adhesive
34.6	Gray/White Mix Carpet Adhesive
34.7	Brown/Light Brown Carpet Adhesive
34.8	Gray/Red Carpet Adhesive
34.9	Blue/Blue/Orange Carpet Adhesive
36	A Building Roof Material
37	B Building Roof Material
38	Blue Floor Matting Adhesive
39	Red Floor Matting Adhesive
40	White Stair Treads
41	White Stair Treads Adhesive
42	4" Black Vinyl Baseboard
43	4" Black Vinyl Baseboard Adhesive
44	4" Brown Vinyl Baseboard
45	4" Brown Vinyl Baseboard Adhesive
46	Chalk Board/Poster Board/ Marker Board Adhesive
47	Brown/Gray Swirl Flooring
48	Brown/Gray Swirl Flooring Adhesive
49	2' x 4' Lay in Ceiling Panels
50	Lab Counters & Sinks
51	Fume Hood
52	Lab Table Top
53	Lab Sink Tops
54	Flange Gaskets
55	Cement Mat.on F.glass Insul. Jacket Water Heater
58	Interior Materials in Kilns
59	Tan Mix Terrazzo Flooring
60	Grey Mix Carpet Adhesive
61	Black Stairway Landing Tread
62	Black Stairway Adhesive
63	Brown Stairway Tread
64	Brown Stairway Tread Adhesive
65	Yellowish Terrazzo
66	9"x9" Carmel w/White Streaks VFT
67	9"x9" Carmel w/White Streaks VFT Mastic
68	12"x12" Carmel VFT
69	12"x12" Carmel VFT Mastic
7	Plaster
70	Vault Door Insulation
8	2x4 Insulation

The following areas were deemed to be inaccessible:

67	9"x9" Carmel w/White Streaks VFT Mastic
69	12"x12" Carmel VFT Mastic
70	Vault Door Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Herman, IDPH License # 100-05090. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Curie Metro High School Building 1820 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820

Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1 A	1' x 1' Ceiling Tile			A Building - Lobby Hallway Stairwells, Building B Corridor	NO_ACBM	MISC								
10	2' x 4' Fiberglass Ceiling Panel			Building A -TV Studio Closet	NOT_TEST ED									
11	Duct Work Tape	1,040	SF	A Building - Metal Shop	CHR	TSI	Y	DIST	15		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
12	Fiberglass Duct Insulation			A Building - Metal Shop	NOT_TEST ED	TSI								
13	Tank Breeching	600	SF	B Building - Pool Equipment Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
14	Tank Insulation	320	SF	B Building - Pool Equipment Room	AMO_CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
15	Inner Duct Insulation	500	SF	B Building - Auditorium	ASSUMED	TSI	N	NONE	0		Yes	ACBM with the potential for damage		LOW
16	Spray-on Fire Proofing	1,600	SF	Building B - Small Room at Rear of Auditorium	ASSUMED	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
17	2' x 4' Sound Baffles	3,500	SF	Building B - Rooms 510, 514, and 616	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Metal Encased Sound baffles	2,000	SF	B Building - Little Theatre	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Fire Doors	23,730	SF	Throughout Building A and B, Original Doors	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
20	Fiberglass Batting Above Lights	50,000	SF	A Building - Classrooms, Corridors, Main Office, Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Klieg Lights	1,000	LF	B Building - Room 606 in Stage Cat Walk	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.1	12" x 12" Cream/Brown/Tan/White Speckles FT	52,000	SF	B Building - Classrooms, Lockers, Lunch Rooms, Bldg A- throughout	CHR	MISC	N	DIST	100		No	ACBM with potential for significant damage	10	LOW
22.10	12" x 12" White w/Brown Specks Floor Tile	4,500	SF	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820

Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				333										
22.11	12" x 12" Pinkish Beige Mix Floor Tile	28,000	SF	See Locations in the Comments Section Below	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.12	12" x 12" Lt. Gray w/Brown Streaks Floor Tile	13,000	SF	Room 143,148,152,159,160,165,380,381	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.13	12" x 12" White w/Peach Specks Floor Tile	600	SF	Principal's Office & Conference Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.14	12" x 12" White Floor Tile	81	SF	Room 620	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.3	12"x12" Off-White Floor Tile Brown/White Speckles	1,160	SF	A & B Buildings, Class Rooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.4	12x12 Brown VFT w/ Brown & White Speckles	25,000	SF	A Building, Classrooms, Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.5	12x12 Cream VAT w/ White Speckles	2,000	SF	A Building, Faculty Dining Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.6	12x12 Black VFT w/ Black & Brown Speckles	8,000	SF	B Building, 1st & 2nd Floor Hallway, Rooms 643, and 635	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.7	12x12 VFT w/ Brown, White, and Tan Speckles	3,200	SF	A Building, 3rd and 2nd Floor Rooms, Lunchrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.8	12x12 Off White FT w/Brn, Tan, White Speckles	1,160	SF	160 West Section, 161 and 144	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22.9	12x12 Yellow FT w/Tan, Yellow, White Speckles	1,200	SF	Room 150	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.1	12x12 VAT Mastic	125,500	SF	HA was split into HA 23.1A-23.1F	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.1A	Mastic under 12x12 VFT Brown, Tan, White Speckles	52,000	SF	B Building, Classrooms, Lockers, Lunch Rooms, Bldg A-Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.1B	Mastic Under 12x12 Off-Wh VFT w/ Yel & Bwn Speckle	15,000	SF	Bldg. A and Bldg B Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.1C	Mastic for 12x12 Off-Wh VAT w/ Bwn & Wh Speckles	20,000	SF	Bldg. A -2nd, 3rd Flr Hall 263, Bldg. B 1st Flr Hall, 619	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.1D	Mastic for 12x12 Bwn VATw/ Bwn & Wh Speckles	25,000	SF	bldg A: 1st Flr Hall, 334, 364, 366, 367	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.1E	Mastic for 12x12 Cream VAT, Wht Speckles	2,000	SF	bldg. A: 1st flr NW Corner Faculty	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820

Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Dining Area										
23.1F	Mastic for 12x12 Black Vat w/ Blk & Bwn Speckles	8,000	SF	bldg. B: 1st Flr Hall, 2nd Flr Hall, Room 635,643	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.2	Mastic for 12x12 VAT, Brown, Tan, & Wht Speckles	17,500	SF	Throughout Bldg A Class Rooms-249, 290	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.3	12x12 Off White FT w/Brn, Tan, White Speck Mastic	1,160	SF	Room 160	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.4	12x12 Yellow w/Tan, Yell,White Speckles FT Mastic	1,200	SF	Room 150	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.5	12" x 12" White w/Brown Specks Floor Tile Mastic	4,500	SF	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.6	12" x 12" Pinkish Beige Mix Floor Tile Mastic	28,000	SF	See Locations in the Comments Section Below	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.7	12" x 12" Lt. Gray w/Brown Streaks FT Mastic	13,000	SF	Room 159	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.8	12" x 12" White w/Peach Specks Floor Tile Mastic	600	SF	Principal's Office & Conference Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23.9	12" x 12" White Floor Tile Mastic	81	SF	Room 620	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	4" Black Baseboard	150	LF	A Building, Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	4" Black Baseboard Mastic	200	LF	A Building Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Main Water Fitting	32	SF	A Building Pump Room	CHR	TSI	Y	LOC	3		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
27	Dry Wall	1,000	SF	Stairway to Roof, Basement Corridor, Rms 163, 164, 165, 524	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
28A	Drywall Joint Compound	200	LF	A Building, Stairway to Roof, Basement Hallway, Rooms 163, 164, 165, and 524	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
28B	Drywall Joint compound			Rooms 524, 163, 164, 165	NO_ACBM	SURFACE		None						Moderate
29	Exterior Brick			Exterior of Building	NO_ACBM	MISC								

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820

Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
2A	2x4 Ceiling Tile			A Building, Kitchen	NO_ACBM	MISC								
2B	2x4 Ceiling	9,600	SF	B Building, Pool	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
3	Spray-on Fire Proofing			Throughout Building	NO_ACBM	SURFACE								
30	Exterior Brick Mortar - Non AHERA			Exterior of Building	NO_ACBM	MISC								
31A	Interior Casing Caulk	7,000	LF	A Building, 3rd Floor (Rm 313, Elec. Box), 2nd Floor (SW Stairway, Rm 164 Entrance)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
31B	Interior Casing Caulk	7,000	LF	B building, Auditorium E. Hallway S. Door, Rm 536, 1st Floor Hallway Storage Cabinet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32A	Exterior Casing Caulk - Non AHERA			A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances)	NO_ACBM	MISC								
32B	Exterior Casing Caulk - Non AHERA			A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances)	NO_ACBM	MISC								
33	Fiberglass Pipe Fitting			B Building, Pool Equipment Room	NO_ACBM	MISC								
34	Carpet Mastic	28,000	SF	A Building, Offices, Classrooms, Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34.1	Gray Carpet Adhesive	3,875	SF	Office, Spotlight Room, Projection Room, 242B, 525B & 611A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34.10	Brown/Green/Light Brown Carpet Adhesive	750	SF	Room 613	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34.11	Green Carpet Adhesive			Room 236C	ASSUMED	MISC		None						
34.2	Brown Carpet Adhesive	6,000	SF	Library 234, All Rooms Branching Off, 242B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34.3	Blue Carpet Adhesive			Main Office Rear	NO_ACBM	MISC		None						Moderate

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820

Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room, Rooms 165, 167A, 238										
34.4	Bright Blue Carpet Adhesive	1,320	SF	Room 270	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34.5	Light Brown Carpet Adhesive	750	SF	Room 153	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34.6	Gray/White Mix Carpet Adhesive	1,700	SF	Room 145, 168A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34.7	Brown/Light Brown Carpet Adhesive	1,320	SF	Rooms 192 & 193	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34.8	Gray/Red Carpet Adhesive	5,950	SF	Auditorium Balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34.9	Blue/Blue/Orange Carpet Adhesive	2,404	SF	Rooms 611, 612, 616 & 620	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Science Lab Black Tables			A Building Rms 346, 347, 349, 350, 351, 353, 354, 355, 383, 363, 361 & 360	NO_ACBM	MISC	N							
36	A Building Roof Material			A Building Roof	ASSUMED	SURFACE								
37	B Building Roof Material			B Building Roof	ASSUMED	SURFACE								
38	Blue Floor Matting Adhesive	2,400	SF	Room 544	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Red Floor Matting Adhesive	2,500	SF	Room 540	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
4	Fiberglass Pipe			Throughout Building A and B	NOT_TEST ED									
40	White Stair Treads	90	SF	Pool Steps	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	White Stair Treads Adhesive	90	SF	Pool Steps	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	4" Black Vinyl Baseboard	266	LF	Rooms 144 & 167	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	4" Black Vinyl Baseboard Adhesive	266	SF	Rooms 144 & 167	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	4" Brown Vinyl Baseboard	156	LF	Rooms 146B, 150	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	4" Brown Vinyl Baseboard Adhesive	156	LF	Rooms 146B, 150	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Chalk Board/Poster Board/ Marker Board Adhesive	11,000	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Brown/Gray Swirl Flooring	1,320	SF	Room 340	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Brown/Gray Swirl Flooring Adhesive	1,320	SF	Room 340	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820

Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
49	2' x 4' Lay in Ceiling Panels	1,320	SF	Room 340	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5	Fiberglass Pipe Hard Fitting			Throughout Building A and B	NO_ACBM	TSI								
50	Lab Counters & Sinks	200	SF	Room 340	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Fume Hood	20	SF	Room 340	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Lab Table Top	20	SF	Room 346	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Lab Sink Tops	45	SF	Rooms 346, 349	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Flange Gaskets	8	SF	Pool Equipment Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Cement Mat.on F.glass Insul. Jacket Water Heater	200	SF	NE Penthouse	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Tank Insulation			NW Penthouse	ABATED	TSI								
57	Tank Insulation			Equipment Room Behind Second Floor Men's Washroom	ABATED	TSI			0					
58	Interior Materials in Kilns	200	SF	Room 627	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Tan Mix Terrazzo Flooring	14,000	SF	Kitchen, 1st-3rd Floor Service Areas, Stairwells, Room 359	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	Fiberglass Duct Insulation			Throughout Building A	NOT_TESTED									
60	Grey Mix Carpet Adhesive	800	SF	Room 145	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Black Stairway Landing Tread	500	SF	Stairway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Black Stairway Adhesive	500	SF	Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Brown Stairway Tread	300	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	Brown Stairway Tread Adhesive	300	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	Yellowish Terrazzo	3,000	SF	Gym Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	9"x9" Carmel w/White Streaks VFT	200	SF	Room 538A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	9"x9" Carmel w/White Streaks VFT Mastic	200	SF	Room 538A	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820

Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
68	12"x12" Carmel VFT	550	SF	1st Floor Middle Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12"x12" Carmel VFT Mastic	550	PERCENT	1st Floor Middle Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7	Plaster	5,000	SF	Men's Room and Rooms 623B, 525, 309, 201, Hall, B20	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
70	Vault Door Insulation	42	SF	Main Office	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
71	hot Water Storage Tank Insulation	0		Penthouses NE and NW	ABATED	TSI	Y				No		3	MODERATE
8	2x4 Insulation	350,000	SF	Classroom Hallways, Main Office, Library, (A/B Buildings)	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
9.1	Transite Board Lab Hood, Classrooms and Pool	3,252	SF	Rooms 346, 349, 350, 352, 353, 354B, 363 & 360	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9.2	Trasite Board Around Ceiling and Sky Lights	3,252	SF	Sky Light Board in Pool	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820
Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>5/7/2019</u>
Inspector Name	<u>Michael Herman</u>
<u>100-05090</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
1 A	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22.1	
22.10	
22.11	
22.12	
22.13	
22.14	
22.3	
22.4	
22.5	
22.6	

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820
Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
22.7	
22.8	
22.9	
23.1	
23.1A	
23.1B	
23.1C	
23.1D	
23.1E	
23.1F	
23.2	
23.3	
23.4	
23.5	
23.6	
23.7	
23.8	
23.9	
24	
25	
26	
27	
28A	
28B	
29	
2A	
2B	
3	
30	

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820
Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
31A	
31B	
32A	
32B	
33	
34	
34.1	
34.10	
34.11	Not observed
34.2	
34.3	
34.4	
34.5	
34.6	
34.7	
34.8	
34.9	
35	
36	Not observed
37	Not observed
38	
39	
4	
40	
41	
42	
43	
44	
45	

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820
Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	Removed in 2018
57	Removed in 2018
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	Removed in 2018

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820
Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
8	
9.1	
9.2	

Table II

Management Planner's Review

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1 A	1' x 1' Ceiling Tile			A Building - Lobby Hallway Stairwells, Building B Corridor	No ACBM	MISC					
10	2' x 4' Fiberglass Ceiling Panel			Building A -TV Studio Closet	Not Tested						
11	Duct Work Tape	1,040	SF	A Building - Metal Shop	Chrysotile	TSI	Yes	15	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
12	Fiberglass Duct Insulation			A Building - Metal Shop	Not Tested	TSI					
13	Tank Breeching	600	SF	B Building - Pool Equipment Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	Tank Insulation	320	SF	B Building - Pool Equipment Room	Amosite, Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15	Inner Duct Insulation	500	SF	B Building - Auditorium	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Spray-on Fire Proofing	1,600	SF	Building B - Small Room at Rear of Auditorium	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
17	2' x 4' Sound Baffles	3,500	SF	Building B - Rooms 510, 514, and 616	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Metal Encased Sound baffles	2,000	SF	B Building - Little Theatre	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Fire Doors	23,730	SF	Throughout Building A and B, Original Doors	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
20	Fiberglass Batting Above Lights	50,000	SF	A Building - Classrooms, Corridors, Main Office, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Klieg Lights	1,000	LF	B Building - Room 606 in Stage Cat Walk	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22.1	12" x 12" Cream/Brown/Tan/White Speckles FT	52,000	SF	B Building - Classrooms, Lockers, Lunch Rooms, Bldg A-throughout	Chrysotile	MISC	No	100	SF	5 ACBM with potential for significant damage	Follow O&M Plan
22.10	12" x 12" White w/Brown Specks Floor Tile	4,500	SF	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.11	12" x 12" Pinkish Beige Mix Floor Tile	28,000	SF	See Locations in the Comments Section Below	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.12	12" x 12" Lt. Gray w/Brown Streaks Floor Tile	13,000	SF	Room 143,148,152,159,160,165,380,381	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.13	12" x 12" White w/Peach Specks Floor Tile	600	SF	Principal's Office & Conference Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.14	12" x 12" White Floor Tile	81	SF	Room 620	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.3	12"x12" Off-White Floor Tile Brown/White Speckles	1,160	SF	A & B Buildings, Class Rooms and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.4	12x12 Brown VFT w/ Brown & White Speckles	25,000	SF	A Building, Classrooms, Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
22.5	12x12 Cream VAT w/ White Speckles	2,000	SF	A Building, Faculty Dining Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.6	12x12 Black VFT w/ Black & Brown Speckles	8,000	SF	B Building, 1st & 2nd Floor Hallway, Rooms 643, and 635	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.7	12x12 VFT w/ Brown, White, and Tan Speckles	3,200	SF	A Building, 3rd and 2nd Floor Rooms, Lunchrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.8	12x12 Off White FT w/Brn, Tan, White Speckles	1,160	SF	160 West Section, 161 and 144	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.9	12x12 Yellow FT w/Tan,Yellow,White Speckles	1,200	SF	Room 150	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1	12x12 VAT Mastic	125,500	SF	HA was split into HA 23.1A-23.1F	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1A	Mastic under 12x12 VFT Brown, Tan, White Speckles	52,000	SF	B Building, Classrooms, Lockers, Lunch Rooms, Bldg A-Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1B	Mastic Under 12x12 Off-Wh VFT w/ Yel & Bwn Speckle	15,000	SF	Bldg. A and Bldg B Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1C	Mastic for 12x12 Off-Wh VAT w/ Bwn & Wh Speckles	20,000	SF	Bldg. A -2nd, 3rd Flr Hall 263, Bldg. B 1st Flr Hall, 619	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1D	Mastic for 12x12 Bwn VATw/ Bwn & Wh Speckles	25,000	SF	bldg A: 1st Flr Hall, 334, 364, 366, 367	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1E	Mastic for 12x12 Cream VAT, Wht Speckles	2,000	SF	bldg. A: 1st flr NW Corner Faculty Dining Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1F	Mastic for 12x12 Black Vat w/ Blk & Bwn Speckles	8,000	SF	bldg. B: 1st Flr Hall, 2nd Flr Hall, Room 635,643	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.2	Mastic for 12x12 VAT, Brown, Tan, & Wht Speckles	17,500	SF	Throughout Bldg A Class Rooms-249, 290	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.3	12x12 Off White FT w/Brn, Tan, White Speck Mastic	1,160	SF	Room 160	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.4	12x12 Yellow w/Tan, Yell,White Speckles FT Mastic	1,200	SF	Room 150	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.5	12" x 12" White w/Brown Specks Floor Tile Mastic	4,500	SF	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.6	12" x 12" Pinkish Beige Mix Floor Tile Mastic	28,000	SF	See Locations in the Comments Section Below	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.7	12" x 12" Lt. Gray w/Brown Streaks FT Mastic	13,000	SF	Room 159	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.8	12" x 12" White w/Peach Specks Floor Tile Mastic	600	SF	Principal's Office & Conference Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.9	12" x 12" White Floor Tile Mastic	81	SF	Room 620	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	4" Black Baseboard	150	LF	A Building, Basement	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
25	4" Black Baseboard Mastic	200	LF	A Building Basement	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
26	Main Water Fitting	32	SF	A Building Pump Room	Chrysotile	TSI	Yes	3	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
27	Dry Wall	1,000	SF	Stairway to Roof, Basement Corridor, Rms 163, 164, 165, 524	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28A	Drywall Joint Compound	200	LF	A Building, Stairway to Roof, Basement Hallway, Rooms 163, 164, 165, and 524	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
28B	Drywall Joint compound			Rooms 524, 163, 164, 165	No ACBM	SURFACE					
29	Exterior Brick			Exterior of Building	No ACBM	MISC					
2A	2x4 Ceiling Tile			A Building, Kitchen	No ACBM	MISC					
2B	2x4 Ceiling	9,600	SF	B Building, Pool	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
3	Spray-on Fire Proofing			Throughout Building	No ACBM	SURFACE					
30	Exterior Brick Mortar - Non AHERA			Exterior of Building	No ACBM	MISC					
31A	Interior Casing Caulk	7,000	LF	A Building, 3rd Floor (Rm 313, Elec. Box), 2nd Floor (SW Stairway, Rm 164 Entrance)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
31B	Interior Casing Caulk	7,000	LF	B building, Auditorium E. Hallway S. Door, Rm 536, 1st Floor Hallway Storage Cabinet	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
32A	Exterior Casing Caulk - Non AHERA			A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances)	No ACBM	MISC					
32B	Exterior Casing Caulk - Non AHERA			A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances)	No ACBM	MISC					
33	Fiberglass Pipe Fitting			B Building, Pool Equipment Room	No ACBM	MISC					
34	Carpet Mastic	28,000	SF	A Building, Offices, Classrooms, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.1	Gray Carpet Adhesive	3,875	SF	Office, Spotlight Room, Projection Room, 242B,525B & 611A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.10	Brown/Green/Light Brown Carpet Adhesive	750	SF	Room 613	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.11	Green Carpet Adhesive			Room 236C	Assumed	MISC					
34.2	Brown Carpet Adhesive	6,000	SF	Library 234, All Rooms Branching Off, 242B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
34.3	Blue Carpet Adhesive			Main Office Rear Room, Rooms 165, 167A,238	No ACBM	MISC					
34.4	Bright Blue Carpet Adhesive	1,320	SF	Room 270	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.5	Light Brown Carpet Adhesive	750	SF	Room 153	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.6	Gray/White Mix Carpet Adhesive	1,700	SF	Room 145, 168A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.7	Brown/Light Brown Carpet Adhesive	1,320	SF	Rooms 192 & 193	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.8	Gray/Red Carpet Adhesive	5,950	SF	Auditorium Balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.9	Blue/Blue/Orange Carpet Adhesive	2,404	SF	Rooms 611, 612, 616 & 620	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Science Lab Black Tables			A Building Rms 346, 347, 349, 350, 351, 353, 354, 355, 383, 363, 361 & 360	No ACBM	MISC	No				
36	A Building Roof Material			A Building Roof	Assumed	SURFACE					
37	B Building Roof Material			B Building Roof	Assumed	SURFACE					
38	Blue Floor Matting Adhesive	2,400	SF	Room 544	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Red Floor Matting Adhesive	2,500	SF	Room 540	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	Fiberglass Pipe			Throughout Building A and B	Not Tested						
40	White Stair Treads	90	SF	Pool Steps	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	White Stair Treads Adhesive	90	SF	Pool Steps	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	4" Black Vinyl Baseboard	266	LF	Rooms 144 & 167	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
43	4" Black Vinyl Baseboard Adhesive	266	SF	Rooms 144 & 167	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	4" Brown Vinyl Baseboard	156	LF	Rooms 146B, 150	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
45	4" Brown Vinyl Baseboard Adhesive	156	LF	Rooms 146B, 150	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
46	Chalk Board/Poster Board/ Marker Board Adhesive	11,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Brown/Gray Swirl Flooring	1,320	SF	Room 340	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Brown/Gray Swirl Flooring Adhesive	1,320	SF	Room 340	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	2' x 4' Lay in Ceiling Panels	1,320	SF	Room 340	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	Fiberglass Pipe Hard Fitting			Throughout Building A and B	No ACBM	TSI					
50	Lab Counters & Sinks	200	SF	Room 340	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Fume Hood	20	SF	Room 340	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Lab Table Top	20	SF	Room 346	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Lab Sink Tops	45	SF	Rooms 346, 349	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Flange Gaskets	8	SF	Pool Equipment Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Cement Mat.on F.glass Insul. Jacket Water	200	SF	NE Penthouse	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Heater										
56	Tank Insulation			NW Penthouse	Abated	TSI					
57	Tank Insulation			Equipment Room Behind Second Floor Men's Washroom	Abated	TSI		0			
58	Interior Materials in Kilns	200	SF	Room 627	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Tan Mix Terrazzo Flooring	14,000	SF	Kitchen, 1st-3rd Floor Service Areas, Stairwells, Room 359	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Fiberglass Duct Insulation			Throughout Building A	Not Tested						
60	Grey Mix Carpet Adhesive	800	SF	Room 145	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Black Stairway Landing Tread	500	SF	Stairway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Black Stairway Adhesive	500	SF	Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Brown Stairway Tread	300	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Brown Stairway Tread Adhesive	300	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Yellowish Terrazzo	3,000	SF	Gym Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	9"x9" Carmel w/White Streaks VFT	200	SF	Room 538A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	9"x9" Carmel w/White Streaks VFT Mastic	200	SF	Room 538A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12"x12" Carmel VFT	550	SF	1st Floor Middle Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12"x12" Carmel VFT Mastic	550	PERCENT	1st Floor Middle Hallway	Assumed	MISC	No	0	PERCENT	6 ACBM with the potential for damage	Follow O&M Plan
7	Plaster	5,000	SF	Men's Room and Rooms 623B, 525, 309, 201, Hall, B20	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Vault Door Insulation	42	SF	Main Office	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
71	hot Water Storage Tank Insulation	0		Penthouses NE and NW	Abated	TSI	Yes				
8	2x4 Insulation	350,000	SF	Classroom Hallways, Main Office, Library, (A/B Buildings)	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
9.1	Transite Board Lab Hood, Classrooms and Pool	3,252	SF	Rooms 346, 349, 350, 352, 353, 354B, 363 & 360	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9.2	Trasite Board Around Ceiling and Sky Lights	3,252	SF	Sky Light Board in Pool	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	05/31/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
1 A	
10	
11	Remove or Repair Damaged Material
12	
13	
14	
15	
16	
17	
18	

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
19	
20	
21	
22.1	Remove damaged materials
22.10	
22.11	
22.12	
22.13	
22.14	
22.3	
22.4	
22.5	
22.6	
22.7	
22.8	
22.9	
23.1	
23.1A	
23.1B	
23.1C	
23.1D	
23.1E	
23.1F	
23.2	
23.3	
23.4	

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
23.5	
23.6	
23.7	
23.8	
23.9	
24	
25	
26	Repair or remove damaged material
27	
28A	
28B	
29	
2A	
2B	
3	
30	
31A	
31B	
32A	
32B	
33	
34	
34.1	
34.10	
34.11	
34.2	

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
34.3	
34.4	
34.5	
34.6	
34.7	
34.8	
34.9	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
8	
9.1	
9.2	

Chicago Public Schools

School	Curie Metro High School	Unit	53101	Building ID	1820
Address	4959 S. Archer		Chicago, IL, 60632	Region	04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)	Carnow, Conibear and Associates
	600 West Van Buren St., Ste 500 Chicago, Il, 60607
	Phone: (312) 762-2900
	Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 A	
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: A Building - Lobby Hallway Stairwells, Building B Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **1 A**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **A Building - Lobby Hallway Stairwells, Building B Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10	
MATERIAL DESCRIPTION:	2' x 4' Fiberglass Ceiling Panel	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Not Tested	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Building A -TV Studio Closet

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **2' x 4' Fiberglass Ceiling Panel**

MATERIAL LOCATION: **Building A -TV Studio Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Duct Work Tape		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:	Deterioration Delamination Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:	Deterioration Delamination Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building - Metal Shop		
MATERIAL QUANTITY:	1040	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	15	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Duct Work Tape		
MATERIAL LOCATION:	A Building - Metal Shop		
MATERIAL QUANTITY:	1040	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	15	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or Repair Damaged Material

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12	
MATERIAL DESCRIPTION:	Fiberglass Duct Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Not Tested	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: A Building - Metal Shop

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Fiberglass Duct Insulation**

MATERIAL LOCATION: **A Building - Metal Shop**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	Tank Breeching		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B Building - Pool Equipment Room		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	Tank Breeching		
MATERIAL LOCATION:	B Building - Pool Equipment Room		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Amosite, Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B Building - Pool Equipment Room		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Tank Insulation		
MATERIAL LOCATION:	B Building - Pool Equipment Room		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	Inner Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B Building - Auditorium		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	Inner Duct Insulation		
MATERIAL LOCATION:	B Building - Auditorium		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Spray-on Fire Proofing		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building B - Small Room at Rear of Auditorium		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Spray-on Fire Proofing		
MATERIAL LOCATION:	Building B - Small Room at Rear of Auditorium		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	2' x 4' Sound Baffles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building B - Rooms 510, 514, and 616		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	2' x 4' Sound Baffles		
MATERIAL LOCATION:	Building B - Rooms 510, 514, and 616		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	Metal Encased Sound baffles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B Building - Little Theatre		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	Metal Encased Sound baffles		
MATERIAL LOCATION:	B Building - Little Theatre		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building A and B, Original Doors		
MATERIAL QUANTITY:	23730	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Fire Doors		
MATERIAL LOCATION:	Throughout Building A and B, Original Doors		
MATERIAL QUANTITY:	23730	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Fiberglass Batting Above Lights		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building - Classrooms, Corridors, Main Office, Library		
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Fiberglass Batting Above Lights		
MATERIAL LOCATION:	A Building - Classrooms, Corridors, Main Office, Library		
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Klieg Lights		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B Building - Room 606 in Stage Cat Walk		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Klieg Lights		
MATERIAL LOCATION:	B Building - Room 606 in Stage Cat Walk		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.1		
MATERIAL DESCRIPTION:	12" x 12" Cream/Brown/Tan/White Speckles FT		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Water		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B Building - Classrooms, Lockers, Lunch Rooms, Bldg A-throughout		
MATERIAL QUANTITY:	52000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	100	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.1		
MATERIAL DESCRIPTION:	12" x 12" Cream/Brown/Tan/White Speckles FT		
MATERIAL LOCATION:	B Building - Classrooms, Lockers, Lunch Rooms, Bldg A-throughout		
MATERIAL QUANTITY:	52000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	100	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove damaged materials

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.10		
MATERIAL DESCRIPTION:	12" x 12" White w/Brown Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.10		
MATERIAL DESCRIPTION:	12" x 12" White w/Brown Specks Floor Tile		
MATERIAL LOCATION:	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.11		
MATERIAL DESCRIPTION:	12" x 12" Pinkish Beige Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	See Locations in the Comments Section Below		
MATERIAL QUANTITY:	28000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 22.11

MATERIAL DESCRIPTION: 12" x 12" Pinkish Beige Mix Floor Tile

MATERIAL LOCATION: See Locations in the Comments Section Below

MATERIAL QUANTITY: 28000

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.12		
MATERIAL DESCRIPTION:	12" x 12" Lt. Gray w/Brown Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 143,148,152,159,160,165,380,381		
MATERIAL QUANTITY:	13000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 22.12

MATERIAL DESCRIPTION: 12" x 12" Lt. Gray w/Brown Streaks Floor Tile

MATERIAL LOCATION: Room 143,148,152,159,160,165,380,381

MATERIAL QUANTITY: 13000

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.13		
MATERIAL DESCRIPTION:	12" x 12" White w/Peach Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office & Conference Room		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.13				
MATERIAL DESCRIPTION:	12" x 12" White w/Peach Specks Floor Tile				
MATERIAL LOCATION:	Principal's Office & Conference Room				
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.14		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 620		
MATERIAL QUANTITY:	81	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 22.14

MATERIAL DESCRIPTION: 12" x 12" White Floor Tile

MATERIAL LOCATION: Room 620

MATERIAL QUANTITY: 81

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.3		
MATERIAL DESCRIPTION:	12"x12" Off-White Floor Tile Brown/White Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A & B Buildings, Class Rooms and Corridors		
MATERIAL QUANTITY:	1160	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.3				
MATERIAL DESCRIPTION:	12"x12" Off-White Floor Tile Brown/White Speckles				
MATERIAL LOCATION:	A & B Buildings, Class Rooms and Corridors				
MATERIAL QUANTITY:	1160	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.4		
MATERIAL DESCRIPTION:	12x12 Brown VFT w/ Brown & White Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building, Classrooms, Office		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.4		
MATERIAL DESCRIPTION:	12x12 Brown VFT w/ Brown & White Speckles		
MATERIAL LOCATION:	A Building, Classrooms, Office		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.5		
MATERIAL DESCRIPTION:	12x12 Cream VAT w/ White Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building, Faculty Dining Area		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.5		
MATERIAL DESCRIPTION:	12x12 Cream VAT w/ White Speckles		
MATERIAL LOCATION:	A Building, Faculty Dining Area		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.6		
MATERIAL DESCRIPTION:	12x12 Black VFT w/ Black & Brown Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B Building, 1st & 2nd Floor Hallway, Rooms 643, and 635		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.6		
MATERIAL DESCRIPTION:	12x12 Black VFT w/ Black & Brown Speckles		
MATERIAL LOCATION:	B Building, 1st & 2nd Floor Hallway, Rooms 643, and 635		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.7		
MATERIAL DESCRIPTION:	12x12 VFT w/ Brown, White, and Tan Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building, 3rd and 2nd Floor Rooms, Lunchrooms		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.7				
MATERIAL DESCRIPTION:	12x12 VFT w/ Brown, White, and Tan Speckles				
MATERIAL LOCATION:	A Building, 3rd and 2nd Floor Rooms, Lunchrooms				
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.8		
MATERIAL DESCRIPTION:	12x12 Off White FT w/Brn, Tan, White Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	160 West Section, 161 and 144		
MATERIAL QUANTITY:	1160	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.8		
MATERIAL DESCRIPTION:	12x12 Off White FT w/Brn, Tan, White Speckles		
MATERIAL LOCATION:	160 West Section, 161 and 144		
MATERIAL QUANTITY:	1160	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22.9		
MATERIAL DESCRIPTION:	12x12 Yellow FT w/Tan, Yellow, White Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 150		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	22.9		
MATERIAL DESCRIPTION:	12x12 Yellow FT w/Tan, Yellow, White Speckles		
MATERIAL LOCATION:	Room 150		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.1		
MATERIAL DESCRIPTION:	12x12 VAT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	HA was split into HA 23.1A-23.1F		
MATERIAL QUANTITY:	125500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.1		
MATERIAL DESCRIPTION:	12x12 VAT Mastic		
MATERIAL LOCATION:	HA was split into HA 23.1A-23.1F		
MATERIAL QUANTITY:	125500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.1A		
MATERIAL DESCRIPTION:	Mastic under 12x12 VFT Brown, Tan, White Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B Building, Classrooms, Lockers, Lunch Rooms, Bldg A-Throughout		
MATERIAL QUANTITY:	52000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.1A				
MATERIAL DESCRIPTION:	Mastic under 12x12 VFT Brown, Tan, White Speckles				
MATERIAL LOCATION:	B Building, Classrooms, Lockers, Lunch Rooms, Bldg A-Throughout				
MATERIAL QUANTITY:	52000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.1B		
MATERIAL DESCRIPTION:	Mastic Under 12x12 Off-Wh VFT w/ Yel & Bwn Speckle		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bldg. A and Bldg B Throughout		
MATERIAL QUANTITY:	15000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 23.1B

MATERIAL DESCRIPTION: Mastic Under 12x12 Off-Wh VFT w/ Yel & Bwn Speckle

MATERIAL LOCATION: Bldg. A and Bldg B Throughout

MATERIAL QUANTITY: 15000

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.1C		
MATERIAL DESCRIPTION:	Mastic for 12x12 Off-Wh VAT w/ Bwn & Wh Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bldg. A -2nd, 3rd Flr Hall 263, Bldg. B 1st Flr Hall, 619		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.1C		
MATERIAL DESCRIPTION:	Mastic for 12x12 Off-Wh VAT w/ Bwn & Wh Speckles		
MATERIAL LOCATION:	Bldg. A -2nd, 3rd Flr Hall 263, Bldg. B 1st Flr Hall, 619		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.1D		
MATERIAL DESCRIPTION:	Mastic for 12x12 Bwn VATw/ Bwn & Wh Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	bldg A: 1st Flr Hall, 334, 364, 366, 367		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 23.1D

MATERIAL DESCRIPTION: Mastic for 12x12 Bwn VATw/ Bwn & Wh Speckles

MATERIAL LOCATION: bldg A: 1st Flr Hall, 334, 364, 366, 367

MATERIAL QUANTITY: 25000

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.1E		
MATERIAL DESCRIPTION:	Mastic for 12x12 Cream VAT, Wht Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	bldg. A: 1st flr NW Corner Faculty Dining Area		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.1E		
MATERIAL DESCRIPTION:	Mastic for 12x12 Cream VAT, Wht Speckles		
MATERIAL LOCATION:	bldg. A: 1st flr NW Corner Faculty Dining Area		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.1F		
MATERIAL DESCRIPTION:	Mastic for 12x12 Black Vat w/ Blk & Bwn Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	bldg. B: 1st Flr Hall, 2nd Flr Hall, Room 635,643		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.1F		
MATERIAL DESCRIPTION:	Mastic for 12x12 Black Vat w/ Blk & Bwn Speckles		
MATERIAL LOCATION:	bldg. B: 1st Flr Hall, 2nd Flr Hall, Room 635,643		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.2		
MATERIAL DESCRIPTION:	Mastic for 12x12 VAT, Brown, Tan, & Wht Speckles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Bldg A Class Rooms-249, 290		
MATERIAL QUANTITY:	17500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.2		
MATERIAL DESCRIPTION:	Mastic for 12x12 VAT, Brown, Tan, & Wht Speckles		
MATERIAL LOCATION:	Throughout Bldg A Class Rooms-249, 290		
MATERIAL QUANTITY:	17500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.3		
MATERIAL DESCRIPTION:	12x12 Off White FT w/Brn, Tan, White Speck Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 160		
MATERIAL QUANTITY:	1160	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.3				
MATERIAL DESCRIPTION:	12x12 Off White FT w/Brn, Tan, White Speck Mastic				
MATERIAL LOCATION:	Room 160				
MATERIAL QUANTITY:	1160	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.4		
MATERIAL DESCRIPTION:	12x12 Yellow w/Tan, Yell,White Speckles FT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 150		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.4		
MATERIAL DESCRIPTION:	12x12 Yellow w/Tan, Yell,White Speckles FT Mastic		
MATERIAL LOCATION:	Room 150		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.5		
MATERIAL DESCRIPTION:	12" x 12" White w/Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.5		
MATERIAL DESCRIPTION:	12" x 12" White w/Brown Specks Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.6		
MATERIAL DESCRIPTION:	12" x 12" Pinkish Beige Mix Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	See Locations in the Comments Section Below		
MATERIAL QUANTITY:	28000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.6		
MATERIAL DESCRIPTION:	12" x 12" Pinkish Beige Mix Floor Tile Mastic		
MATERIAL LOCATION:	See Locations in the Comments Section Below		
MATERIAL QUANTITY:	28000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.7		
MATERIAL DESCRIPTION:	12" x 12" Lt. Gray w/Brown Streaks FT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 159		
MATERIAL QUANTITY:	13000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.7				
MATERIAL DESCRIPTION:	12" x 12" Lt. Gray w/Brown Streaks FT Mastic				
MATERIAL LOCATION:	Room 159				
MATERIAL QUANTITY:	13000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.8		
MATERIAL DESCRIPTION:	12" x 12" White w/Peach Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office & Conference Room		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	23.8		
MATERIAL DESCRIPTION:	12" x 12" White w/Peach Specks Floor Tile Mastic		
MATERIAL LOCATION:	Principal's Office & Conference Room		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23.9		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 620		
MATERIAL QUANTITY:	81	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 23.9

MATERIAL DESCRIPTION: 12" x 12" White Floor Tile Mastic

MATERIAL LOCATION: Room 620

MATERIAL QUANTITY: 81

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	4" Black Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building, Basement		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	4" Black Baseboard		
MATERIAL LOCATION:	A Building, Basement		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	4" Black Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building Basement		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	4" Black Baseboard Mastic		
MATERIAL LOCATION:	A Building Basement		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Main Water Fitting		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:	Deterioration Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:	Deterioration Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building Pump Room		
MATERIAL QUANTITY:	32	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	3	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Main Water Fitting		
MATERIAL LOCATION:	A Building Pump Room		
MATERIAL QUANTITY:	32	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	3	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair or remove damaged material

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Dry Wall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairway to Roof, Basement Corridor, Rms 163, 164, 165, 524		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	27				
MATERIAL DESCRIPTION:	Dry Wall				
MATERIAL LOCATION:	Stairway to Roof, Basement Corridor, Rms 163, 164, 165, 524				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28A		
MATERIAL DESCRIPTION:	Drywall Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building, Stairway to Roof, Basement Hallway, Rooms 163, 164, 165, and 524		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	28A				
MATERIAL DESCRIPTION:	Drywall Joint Compound				
MATERIAL LOCATION:	A Building, Stairway to Roof, Basement Hallway, Rooms 163, 164, 165, and 524				
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28B	
MATERIAL DESCRIPTION:	Drywall Joint compound	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Rooms 524, 163, 164, 165**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/07/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	28B	
MATERIAL DESCRIPTION:	Drywall Joint compound	
MATERIAL LOCATION:	Rooms 524, 163, 164, 165	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	Exterior Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2A	
MATERIAL DESCRIPTION:	2x4 Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: A Building, Kitchen

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **2x4 Ceiling Tile**

MATERIAL LOCATION: **A Building, Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2B		
MATERIAL DESCRIPTION:	2x4 Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B Building, Pool		
MATERIAL QUANTITY:	9600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	2B		
MATERIAL DESCRIPTION:	2x4 Ceiling		
MATERIAL LOCATION:	B Building, Pool		
MATERIAL QUANTITY:	9600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3	
MATERIAL DESCRIPTION:	Spray-on Fire Proofing	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Spray-on Fire Proofing**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30	
MATERIAL DESCRIPTION:	Exterior Brick Mortar - Non AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31A		
MATERIAL DESCRIPTION:	Interior Casing Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building, 3rd Floor (Rm 313, Elec. Box), 2nd Floor (SW Stairway, Rm 164 Entrance)		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	31A				
MATERIAL DESCRIPTION:	Interior Casing Caulk				
MATERIAL LOCATION:	A Building, 3rd Floor (Rm 313, Elec. Box), 2nd Floor (SW Stairway, Rm 164 Entrance)				
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31B		
MATERIAL DESCRIPTION:	Interior Casing Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	B building, Auditorium E. Hallway S. Door, Rm 536, 1st Floor Hallway Storage Cabinet		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	31B				
MATERIAL DESCRIPTION:	Interior Casing Caulk				
MATERIAL LOCATION:	B building, Auditorium E. Hallway S. Door, Rm 536, 1st Floor Hallway Storage Cabinet				
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32A	
MATERIAL DESCRIPTION:	Exterior Casing Caulk - Non AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	32A	
MATERIAL DESCRIPTION:	Exterior Casing Caulk - Non AHERA	
MATERIAL LOCATION:	A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances)	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32B	
MATERIAL DESCRIPTION:	Exterior Casing Caulk - Non AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	32B	
MATERIAL DESCRIPTION:	Exterior Casing Caulk - Non AHERA	
MATERIAL LOCATION:	A Building, (Rm 187, 159, SW Entrance), B Building (N, NE, SE Entrances)	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33	
MATERIAL DESCRIPTION:	Fiberglass Pipe Fitting	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: B Building, Pool Equipment Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Fiberglass Pipe Fitting**

MATERIAL LOCATION: **B Building, Pool Equipment Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A Building, Offices, Classrooms, Auditorium		
MATERIAL QUANTITY:	28000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Carpet Mastic		
MATERIAL LOCATION:	A Building, Offices, Classrooms, Auditorium		
MATERIAL QUANTITY:	28000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.1		
MATERIAL DESCRIPTION:	Gray Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office, Spotlight Room, Projection Room, 242B,525B & 611A		
MATERIAL QUANTITY:	3875	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34.1		
MATERIAL DESCRIPTION:	Gray Carpet Adhesive		
MATERIAL LOCATION:	Office, Spotlight Room, Projection Room, 242B, 525B & 611A		
MATERIAL QUANTITY:	3875	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.10		
MATERIAL DESCRIPTION:	Brown/Green/Light Brown Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 613		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34.10				
MATERIAL DESCRIPTION:	Brown/Green/Light Brown Carpet Adhesive				
MATERIAL LOCATION:	Room 613				
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.11	
MATERIAL DESCRIPTION:	Green Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 236C

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **34.11**

MATERIAL DESCRIPTION: **Green Carpet Adhesive**

MATERIAL LOCATION: **Room 236C**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.2		
MATERIAL DESCRIPTION:	Brown Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library 234, All Rooms Branching Off, 242B		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34.2				
MATERIAL DESCRIPTION:	Brown Carpet Adhesive				
MATERIAL LOCATION:	Library 234, All Rooms Branching Off, 242B				
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.3	
MATERIAL DESCRIPTION:	Blue Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Main Office Rear Room, Rooms 165, 167A,238**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/07/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **34.3**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Main Office Rear Room, Rooms 165, 167A,238**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.4		
MATERIAL DESCRIPTION:	Bright Blue Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 270		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34.4		
MATERIAL DESCRIPTION:	Bright Blue Carpet Adhesive		
MATERIAL LOCATION:	Room 270		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.5		
MATERIAL DESCRIPTION:	Light Brown Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 153		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34.5		
MATERIAL DESCRIPTION:	Light Brown Carpet Adhesive		
MATERIAL LOCATION:	Room 153		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.6		
MATERIAL DESCRIPTION:	Gray/White Mix Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 145, 168A		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34.6		
MATERIAL DESCRIPTION:	Gray/White Mix Carpet Adhesive		
MATERIAL LOCATION:	Room 145, 168A		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.7		
MATERIAL DESCRIPTION:	Brown/Light Brown Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 192 & 193		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34.7		
MATERIAL DESCRIPTION:	Brown/Light Brown Carpet Adhesive		
MATERIAL LOCATION:	Rooms 192 & 193		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.8		
MATERIAL DESCRIPTION:	Gray/Red Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Balcony		
MATERIAL QUANTITY:	5950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34.8		
MATERIAL DESCRIPTION:	Gray/Red Carpet Adhesive		
MATERIAL LOCATION:	Auditorium Balcony		
MATERIAL QUANTITY:	5950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34.9		
MATERIAL DESCRIPTION:	Blue/Blue/Orange Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 611, 612, 616 & 620		
MATERIAL QUANTITY:	2404	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	34.9		
MATERIAL DESCRIPTION:	Blue/Blue/Orange Carpet Adhesive		
MATERIAL LOCATION:	Rooms 611, 612, 616 & 620		
MATERIAL QUANTITY:	2404	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	Science Lab Black Tables		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: A Building Rms 346, 347, 349, 350, 351, 353, 354, 355, 383, 363, 361 & 360

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Science Lab Black Tables**

MATERIAL LOCATION: **A Building Rms 346, 347, 349, 350, 351, 353, 354, 355, 383, 363, 361 & 360**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36	
MATERIAL DESCRIPTION:	A Building Roof Material	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: A Building Roof

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **A Building Roof Material**

MATERIAL LOCATION: **A Building Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37	
MATERIAL DESCRIPTION:	B Building Roof Material	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: B Building Roof

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **B Building Roof Material**

MATERIAL LOCATION: **B Building Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Blue Floor Matting Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 544		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Blue Floor Matting Adhesive		
MATERIAL LOCATION:	Room 544		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Red Floor Matting Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 540		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Red Floor Matting Adhesive		
MATERIAL LOCATION:	Room 540		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4	
MATERIAL DESCRIPTION:	Fiberglass Pipe	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Not Tested	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building A and B

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Fiberglass Pipe**

MATERIAL LOCATION: **Throughout Building A and B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	White Stair Treads		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pool Steps		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 40

MATERIAL DESCRIPTION: White Stair Treads

MATERIAL LOCATION: Pool Steps

MATERIAL QUANTITY: 90

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	White Stair Treads Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pool Steps		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 41

MATERIAL DESCRIPTION: White Stair Treads Adhesive

MATERIAL LOCATION: Pool Steps

MATERIAL QUANTITY: 90

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 144 & 167		
MATERIAL QUANTITY:	266	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard		
MATERIAL LOCATION:	Rooms 144 & 167		
MATERIAL QUANTITY:	266	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 144 & 167		
MATERIAL QUANTITY:	266	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard Adhesive		
MATERIAL LOCATION:	Rooms 144 & 167		
MATERIAL QUANTITY:	266	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 146B, 150		
MATERIAL QUANTITY:	156	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**

MATERIAL LOCATION: **Rooms 146B, 150**

MATERIAL QUANTITY:	156	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 146B, 150		
MATERIAL QUANTITY:	156	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard Adhesive		
MATERIAL LOCATION:	Rooms 146B, 150		
MATERIAL QUANTITY:	156	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	Chalk Board/Poster Board/ Marker Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 46

MATERIAL DESCRIPTION: Chalk Board/Poster Board/ Marker Board Adhesive

MATERIAL LOCATION: Classrooms

MATERIAL QUANTITY: 11000

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Brown/Gray Swirl Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Brown/Gray Swirl Flooring		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Brown/Gray Swirl Flooring Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Brown/Gray Swirl Flooring Adhesive		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	2' x 4' Lay in Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	2' x 4' Lay in Ceiling Panels		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	1320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5	
MATERIAL DESCRIPTION:	Fiberglass Pipe Hard Fitting	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building A and B

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **Fiberglass Pipe Hard Fitting**

MATERIAL LOCATION: **Throughout Building A and B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Lab Counters & Sinks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Lab Counters & Sinks		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Fume Hood		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Fume Hood		
MATERIAL LOCATION:	Room 340		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	Lab Table Top		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 346		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 52

MATERIAL DESCRIPTION: Lab Table Top

MATERIAL LOCATION: Room 346

MATERIAL QUANTITY: 20

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Lab Sink Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 346, 349		
MATERIAL QUANTITY:	45	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Lab Sink Tops		
MATERIAL LOCATION:	Rooms 346, 349		
MATERIAL QUANTITY:	45	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Flange Gaskets		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pool Equipment Room		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Flange Gaskets		
MATERIAL LOCATION:	Pool Equipment Room		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	Cement Mat.on F.glass Insul. Jacket Water Heater		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	NE Penthouse		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	Cement Mat.on F.glass Insul. Jacket Water Heater		
MATERIAL LOCATION:	NE Penthouse		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56	
MATERIAL DESCRIPTION:	Tank Insulation	
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: NW Penthouse

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Removed in 2018

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **NW Penthouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57	
MATERIAL DESCRIPTION:	Tank Insulation	
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Equipment Room Behind Second Floor Men's Washroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: 0 DAMAGE UNITS:

COMMENTS: Removed in 2018

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Equipment Room Behind Second Floor Men's Washroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	Interior Materials in Kilns		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 627		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	Interior Materials in Kilns		
MATERIAL LOCATION:	Room 627		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	Tan Mix Terrazzo Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen, 1st-3rd Floor Service Areas, Stairwells, Room 359		
MATERIAL QUANTITY:	14000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	59				
MATERIAL DESCRIPTION:	Tan Mix Terrazzo Flooring				
MATERIAL LOCATION:	Kitchen, 1st-3rd Floor Service Areas, Stairwells, Room 359				
MATERIAL QUANTITY:	14000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6	
MATERIAL DESCRIPTION:	Fiberglass Duct Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Not Tested	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building A

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Fiberglass Duct Insulation**

MATERIAL LOCATION: **Throughout Building A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	Grey Mix Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 145		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 60

MATERIAL DESCRIPTION: Grey Mix Carpet Adhesive

MATERIAL LOCATION: Room 145

MATERIAL QUANTITY: 800 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	Black Stairway Landing Tread		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairway		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	Black Stairway Landing Tread		
MATERIAL LOCATION:	Stairway		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	Black Stairway Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairways		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	Black Stairway Adhesive		
MATERIAL LOCATION:	Stairways		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	Brown Stairway Tread		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	Brown Stairway Tread		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	Brown Stairway Tread Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	Brown Stairway Tread Adhesive		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	Yellowish Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Lobby		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	Yellowish Terrazzo		
MATERIAL LOCATION:	Gym Lobby		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	9"x9" Carmel w/White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 538A		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	9"x9" Carmel w/White Streaks VFT		
MATERIAL LOCATION:	Room 538A		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	9"x9" Carmel w/White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 538A		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	9"x9" Carmel w/White Streaks VFT Mastic		
MATERIAL LOCATION:	Room 538A		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12"x12" Carmel VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Middle Hallway		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12"x12" Carmel VFT		
MATERIAL LOCATION:	1st Floor Middle Hallway		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	12"x12" Carmel VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Middle Hallway		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	PERCENT
DAMAGE QUANTITY:	0	DAMAGE UNITS:	PERCENT

COMMENTS:

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	12"x12" Carmel VFT Mastic		
MATERIAL LOCATION:	1st Floor Middle Hallway		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	PERCENT
DAMAGE QUANTITY:	0	DAMAGE UNITS:	PERCENT

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Men's Room and Rooms 623B, 525, 309, 201, Hall, B20		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	7		
MATERIAL DESCRIPTION:	Plaster		
MATERIAL LOCATION:	Men's Room and Rooms 623B, 525, 309, 201, Hall, B20		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Vault Door Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	42	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 70

MATERIAL DESCRIPTION: Vault Door Insulation

MATERIAL LOCATION: Main Office

MATERIAL QUANTITY: 42

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	hot Water Storage Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:	Deterioration Vibration Water		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Abated	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:	Deterioration Vibration Water		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Penthouses NE and NW		
MATERIAL QUANTITY:	0	MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	
COMMENTS:	Removed in 2018		

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	71	
MATERIAL DESCRIPTION:	hot Water Storage Tank Insulation	
MATERIAL LOCATION:	Penthouses NE and NW	
MATERIAL QUANTITY:	0	MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8		
MATERIAL DESCRIPTION:	2x4 Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classroom Hallways, Main Office, Library, (A/B Buildings)		
MATERIAL QUANTITY:	350000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	8		
MATERIAL DESCRIPTION:	2x4 Insulation		
MATERIAL LOCATION:	Classroom Hallways, Main Office, Library, (A/B Buildings)		
MATERIAL QUANTITY:	350000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9.1		
MATERIAL DESCRIPTION:	Transite Board Lab Hood, Classrooms and Pool		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 346, 349, 350, 352, 353, 354B, 363 & 360		
MATERIAL QUANTITY:	3252	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA:	9.1				
MATERIAL DESCRIPTION:	Transite Board Lab Hood, Classrooms and Pool				
MATERIAL LOCATION:	Rooms 346, 349, 350, 352, 353, 354B, 363 & 360				
MATERIAL QUANTITY:	3252	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/31/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Herman		
SCHOOL NAME:	Curie Metro High School	INSPECTION DATE:	5/7/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9.2		
MATERIAL DESCRIPTION:	Trasite Board Around Ceiling and Sky Lights		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Sky Light Board in Pool		
MATERIAL QUANTITY:	3252	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/07/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53101	BUILDING ID:	1820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Curie Metro High School	REVIEW DATE:	5/31/2019		
ADDRESS:	4959 S. Archer	IDPH LICENSE NO:	100-05090		

HOMOGENEOUS AREA: 9.2

MATERIAL DESCRIPTION: Trasite Board Around Ceiling and Sky Lights

MATERIAL LOCATION: Sky Light Board in Pool

MATERIAL QUANTITY: 3252 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 05/31/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MICHAEL D HERMAN
5121 N MONITOR
CHICAGO, IL 60630

4/10/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05090

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	ID NUMBER 100 - 05090	ISSUED 4/10/2019	INSPECTOR	1/17/2020
MICHAEL D HERMAN 5121 N MONITOR CHICAGO, IL 60630 Environmental Health		EXPIRES 05/15/2020 	PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/16/2020
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Michael Herman

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/17/2019

Exam Date: 1/17/2019

Expiration Date: 1/17/2020

Certificate Number: BIR1901170228

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MICHAEL D HERMAN
5121 N MONITOR
CHICAGO, IL 60630

4/25/2018


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05090

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

IDPH ILLINOIS DEPARTMENT OF PUBLIC HEALTH		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 05090	ISSUED 4/25/2018	EXPIRES 05/15/2019		INSPECTOR	1/18/2019
MICHAEL D HERMAN 5121 N MONITOR CHICAGO, IL 60630 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/17/2019
				Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

Michael D. Herman
[Signature]

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES
Nationally Accredited by PHAB

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019



Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed