

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2051  
SCHOOL NAME: Addams School  
ADDRESS OF SCHOOL: 10810 S. Avenue H  
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **10/3/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 9/8/2022 ENROLLMENT 555  
IDPH INSPECTOR LICENSE NUMBER: 100-02950  
IDPH LICENSED INSPECTOR NAME (Please Print): Keith Clough  
IDPH MP LICENSE NUMBER: 100-01784  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer*

9/20/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Addams School**

10810 S. Avenue H  
Chicago, IL, 60617

Unit: 22021  
Building ID: 2020

IDPH ID Number: 14-016-2990-2051

**REPORT DATE:**

Tuesday, September 20, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

09/20/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 22021                      Region: 06                      IDPH ID: 14-016-2990-2051

School: Addams School                      Building ID: 2020

Address: 10810 S. Avenue H  
Chicago, IL, 60617

Building Contact: Gibbons, Kevin                      Contact Phone: 3126234306

Current Building Owners: Chicago Public Schools


Reinspection Date: 9/8/2022

Review Date: 09/20/2022

Inspector: Keith Clough                      Inspector IDPH License: 100-02950  
Management Planner: Steven Geneser                      Management Planner IDPH License: 100-01784

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Steven Geneser  
100-01784

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 20, 2022

RE: Addams School, Unit 22021  
10810 S. Avenue H  
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Addams School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Addams School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Addams School Unit: 22021 Region: 06  
Address: 10810 S. Avenue H Chicago, IL, 60617  
IDPH ID: 14-016-2990-2051 Building ID: 2020  
Contact: Gibbons, Kevin Phone: 3126234306

### 2. Description of Facility

Original Construction: 1994 Additional Construction: 1948  
Total Square Footage: 3959 No of Floors: 1  
Current Occupancy: 555

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880 Fax: 630-790-0882

### 5. Inspector

Inspector Name: Keith Clough




Inspector IDPH license # 100-02950  
Reinspection Date: 9/8/2022

Signature:  
Date: 9/8/2022

### 6. Management Planner

Management Planner Name: Steven Geneser



Management Planner IDPH license # 100-01784

Signature:  
Date: 09/20/2022

### 7. Review Date: 09/20/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 9/20/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Addams School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2020:

A	Aircell Pipe Insulation ABATED
B	Cardboard Pipe Wrap ABATED
C	Mudded Fittings/Elbows on Aircell Pipe Runs ABATED
D	Aircell Duct Wrap ABATED
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 2020:

NEW

Newly Installed Suspect ACM



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	12x12 Off-White Floor Tile
02A	12x12 Beige Floor Tile
03	Blue Carpet/Tan Mastic NOT OBSERVED
04	12x12 Off-White Floor Tile Mastic
04A	12x12 Beige Floor Tile Mastic
05	Beige Baseboard
05A	Gray Baseboard
05B	Beige Baseboard
06	Beige Baseboard Mastic
06A	Gray Baseboard Mastic
06C	Beige Baseboard Mastic
07	Tan Linoleum
07A	Brown Linoleum NOT OBSERVED
07B	12x12 Tan Floor Tile w/Streaks
07C	12x12 White Floor w/Black Specks Floor Tile
07D	12x12 Beige Floor Tile w/Streaks
08	Tan Linoleum Mastic
08A	Brown Linoleum Mastic NOT OBSERVED
08C	12x12 White Floor w/Black Specks Floor Tile Mastic
08D	12x12 Beige Floor Tile w/Streaks Mastic
09	2'x2' Smooth White Ceiling Tile
10	2'x2' White Ceiling Tile
11	2'x4' White Ceiling Tile
12	Solid Ceiling Panels
13	2'x2' White Ceiling Tile
14	2'x2' White Ceiling Tile
15A	Beige Baseboard
15B	Beige Baseboard Mastic
16A	12x12 White Speckled Floor Tile
16B	12x12 White Speckled Floor Tile Mastic
17	Blue Linoleum
18	Pink Linoleum
19	Plaster
20	12x12 White w/Blue Specks Vinyl Floor Tile
21	12x12 White w/Blue Specks Vinyl Floor Tile Mastic
8B	12x12 Tan Floor Tile w/Streaks Mastic
F	Duct Manifold
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

03	Blue Carpet/Tan Mastic NOT OBSERVED
04	12x12 Off-White Floor Tile Mastic
04A	12x12 Beige Floor Tile Mastic
06	Beige Baseboard Mastic
06A	Gray Baseboard Mastic
06C	Beige Baseboard Mastic
08	Tan Linoleum Mastic
08C	12x12 White Floor w/Black Specks Floor Tile Mastic
08D	12x12 Beige Floor Tile w/Streaks Mastic
15B	Beige Baseboard Mastic
16B	12x12 White Speckled Floor Tile Mastic
21	12x12 White w/Blue Specks Vinyl Floor Tile Mastic
8B	12x12 Tan Floor Tile w/Streaks Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Keith Clough, IDPH License # 100-02950. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	9/1/2022
	9/1/2022
	9/1/2022
	9/1/2022

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Addams School Building 2020 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	12x12 Off-White Floor Tile	1,700	SF	1st Floor Corridor and Teachers' Lounge; Office (Wood Tile over VFT)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02A	12x12 Beige Floor Tile	2,450	SF	2nd Floor Corridor, Room 203 (27x23), Room 202, Room 200 (33x6)	ASSUMED	MISC	N	DIST	0		No	ACBM with the potential for damage	5	MODERATE
03	Blue Carpet/Tan Mastic NOT OBSERVED	2,000	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	12x12 Off-White Floor Tile Mastic	1,500	SF	1st Floor Corridor and Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04A	12x12 Beige Floor Tile Mastic	1,650	SF	2nd Floor Corridor, and Rooms 202 & 203	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		LOW
05	Beige Baseboard	900	LF	Kitchen, Cafeteria, and 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	Gray Baseboard	1,210	LF	1996 Annex-Corridor and All Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	Beige Baseboard	325	LF	Rooms 120-123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Beige Baseboard Mastic	900	LF	Kitchen, Cafeteria, and 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	Gray Baseboard Mastic	1,210	LF	1996 Annex-Corridor and All Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06C	Beige Baseboard Mastic	325	LF	Mobile Unit- Rooms 120-123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	Tan Linoleum	1,600	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	Brown Linoleum NOT OBSERVED			Cafeteria	ASSUMED	MISC								
07B	12x12 Tan Floor Tile w/Streaks	580	SF	1995 Addition-Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07C	12x12 White Floor w/Black Specks Floor Tile	2,490	SF	Throughout 1996 Annex- All Classrooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07D	12x12 Beige Floor Tile w/Streaks	5,000	SF	Mobile Unit Rooms 120-123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
08	Tan Linoleum Mastic	1,600	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	Brown Linoleum Mastic NOT OBSERVED			Cafeteria	ASSUMED	MISC								
08C	12x12 White Floor w/Black Specks Floor Tile Mastic	2,490	SF	Throughout 1996 Annex, All Classrooms and Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08D	12x12 Beige Floor Tile w/Streaks Mastic	5,000	SF	Mobile Unit- Rooms 120-123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	2'x2' Smooth White Ceiling Tile	770	SF	1995 Addition-Kitchen	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
10	2'x2' White Ceiling Tile	2,100	SF	1995 Addition-Cafeteria	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
11	2'x4' White Ceiling Tile	2,340	SF	1996 Annex-Corridor and All Classrooms, except 115	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
12	Solid Ceiling Panels	2,500	SF	North Mobile Unit - Rooms 120 & 121	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
13	2'x2' White Ceiling Tile	2,500	SF	South Mobile Unit-Rooms 122 & 123	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
14	2'x2' White Ceiling Tile	5,000	SF	East Mobile Unit	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
15A	Beige Baseboard	3,000	LF	East Mobile Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15B	Beige Baseboard Mastic	3,000	LF	East Mobile Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16A	12x12 White Speckled Floor Tile	5,000	SF	East Mobile Unit	ASSUMED	MISC	N	DIST	0		No	ACBM with the potential for damage	5	LOW
16B	12x12 White Speckled Floor Tile Mastic	5,000	SF	East Mobile Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Blue Linoleum	400	SF	East Mobile Unit-Boys' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Pink Linoleum	400	SF	East Mobile Unit-Girls' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Plaster	60,000	SF	Main Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12x12 White w/Blue Specks Vinyl Floor Tile	2,400	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
Z1	12x12 White w/Blue Specks Vinyl Floor Tile Mastic	2,400	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8B	12x12 Tan Floor Tile w/Streaks Mastic	580	SF	1995 Addition-Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation ABATED	240	LF	Basement, Pipe Chase/Air Tunnel, Crawlspace	CHR	TSI					Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Cardboard Pipe Wrap ABATED	200	LF	Basement	CHR	TSI					Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Mudded Fittings/Elbows on Aircell Pipe Runs ABATED	278	LF	Basement Pipe Chases, Air Tunnel, Crawlspace	CHR	TSI					Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Aircell Duct Wrap ABATED			Basement and Unexcavated Area, Crawlspace	ABATED	TSI					Yes			
E	Mag Block Pipe Insulation ABATED			Boiler Room	ABATED	TSI								
F	Duct Manifold	3	LF	Fan Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/8/2022</b>
Inspector Name <b>Keith Clough</b>
<b>100-02950</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
02	
02A	120 Floor Tiles Cracked and Chipped but Intact
03	
04	
04A	120 Floor Tiles chipped and cracked but intact
05	
05A	
05B	
06	
06A	
06C	
07	
07A	
07B	
07C	
07D	
08	
08A	
08C	
08D	
09	
10	
11	
12	



# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
13	
14	
15A	
15B	
16A	50 Floor Tiles chipped and cracked but Intact
16B	50 Floor tiles chipped and cracked but Intact
17	
18	
19	
20	
21	
8B	
A	Basement Area and Crawlspace Areas Abated Summer of 2022
B	Basement and Crawl Space Areas Abated Summer of 2022
C	Basement and Crawl Spaces Abated Summer of 2022
D	
E	
F	
NEW	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Addams School  
Address 10810 S. Avenue H

Unit 22021  
Chicago, IL, 60617

Building ID 2020  
Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	12x12 Off-White Floor Tile	1,700	SF	1st Floor Corridor and Teachers' Lounge; Office (Wood Tile over VFT)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02A	12x12 Beige Floor Tile	2,450	SF	2nd Floor Corridor, Room 203 (27x23), Room 202, Room 200 (33x6)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	Blue Carpet/Tan Mastic NOT OBSERVED	2,000	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
04	12x12 Off-White Floor Tile Mastic	1,500	SF	1st Floor Corridor and Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04A	12x12 Beige Floor Tile Mastic	1,650	SF	2nd Floor Corridor, and Rooms 202 & 203	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
05	Beige Baseboard	900	LF	Kitchen, Cafeteria, and 1st Floor Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
05A	Gray Baseboard	1,210	LF	1996 Annex- Corridor and All Classrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
05B	Beige Baseboard	325	LF	Rooms 120-123	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06	Beige Baseboard Mastic	900	LF	Kitchen, Cafeteria, and 1st Floor Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06A	Gray Baseboard Mastic	1,210	LF	1996 Annex- Corridor and All Classrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06C	Beige Baseboard Mastic	325	LF	Mobile Unit- Rooms 120-123	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
07	Tan Linoleum	1,600	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	Brown Linoleum NOT OBSERVED			Cafeteria	Assumed	MISC					
07B	12x12 Tan Floor Tile w/Streaks	580	SF	1995 Addition- Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07C	12x12 White Floor w/Black Specks Floor Tile	2,490	SF	Throughout 1996 Annex- All Classrooms and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07D	12x12 Beige Floor Tile w/Streaks	5,000	SF	Mobile Unit Rooms 120-123	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Tan Linoleum Mastic	1,600	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	Brown Linoleum Mastic NOT OBSERVED			Cafeteria	Assumed	MISC					
08C	12x12 White Floor w/Black Specks Floor Tile Mastic	2,490	SF	Throughout 1996 Annex, All Classrooms and Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08D	12x12 Beige Floor Tile w/Streaks Mastic	5,000	SF	Mobile Unit- Rooms 120-123	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	2'x2' Smooth White Ceiling Tile	770	SF	1995 Addition- Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
10	2'x2' White Ceiling Tile	2,100	SF	1995 Addition- Cafeteria	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
11	2'x4' White Ceiling Tile	2,340	SF	1996 Annex- Corridor and All Classrooms, except 115	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Addams School  
**Address** 10810 S. Avenue H

**Unit** 22021  
Chicago, IL, 60617

**Building ID** 2020  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
12	Solid Ceiling Panels	2,500	SF	North Mobile Unit - Rooms 120 & 121	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	2'x2' White Ceiling Tile	2,500	SF	South Mobile Unit- Rooms 122 & 123	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	2'x2' White Ceiling Tile	5,000	SF	East Mobile Unit	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15A	Beige Baseboard	3,000	LF	East Mobile Unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
15B	Beige Baseboard Mastic	3,000	LF	East Mobile Unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12x12 White Speckled Floor Tile	5,000	SF	East Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16B	12x12 White Speckled Floor Tile Mastic	5,000	SF	East Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Blue Linoleum	400	SF	East Mobile Unit- Boys' Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Pink Linoleum	400	SF	East Mobile Unit- Girls' Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Plaster	60,000	SF	Main Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12x12 White w/Blue Specks Vinyl Floor Tile	2,400	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 White w/Blue Specks Vinyl Floor Tile Mastic	2,400	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8B	12x12 Tan Floor Tile w/Streaks Mastic	580	SF	1995 Addition- Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation ABATED	240	LF	Basement, Pipe Chase/Air Tunnel, Crawlspace	Chrysotile	TSI			LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Cardboard Pipe Wrap ABATED	200	LF	Basement	Chrysotile	TSI			LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Mudded Fittings/Elbows on Aircell Pipe Runs ABATED	278	LF	Basement Pipe Chases, Air Tunnel, Crawlspace	Chrysotile	TSI			LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Aircell Duct Wrap ABATED			Basement and Unexcavated Area, Crawlspace	Abated	TSI					
E	Mag Block Pipe Insulation ABATED			Boiler Room	Abated	TSI					
F	Duct Manifold	3	LF	Fan Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Addams School  
**Address** 10810 S. Avenue H

**Unit** 22021  
 Chicago, IL, 60617

**Building ID** 2020  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	9/20/2022
Manager Planner Name	Steven Geneser
100-01784	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
02A	
03	
04	
04A	
05	
05A	
05B	
06	
06A	
06C	

# Chicago Public Schools

**School** Addams School  
**Address** 10810 S. Avenue H

**Unit** 22021  
 Chicago, IL, 60617

**Building ID** 2020  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
07	
07A	
07B	
07C	
07D	
08	
08A	
08C	
08D	
09	
10	
11	
12	
13	
14	
15A	
15B	
16A	
16B	
17	
18	
19	
20	
21	
8B	
A	
B	

# Chicago Public Schools

**School** Addams School  
**Address** 10810 S. Avenue H

**Unit** 22021  
Chicago, IL, 60617

**Building ID** 2020  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
C	
D	
E	
F	
NEW	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---



# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

## 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor and Teachers' Lounge; Office (Wood Tile over VFT)**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**  
MATERIAL LOCATION: **1st Floor Corridor and Teachers' Lounge; Office (Wood Tile over VFT)**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **2nd Floor Corridor, Room 203 (27x23), Room 202, Room 200 (33x6)**  
MATERIAL QUANTITY: **2450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2450** DAMAGE UNITS: **SF**  
COMMENTS: **120 Floor Tiles Cracked and Chipped but Intact**

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **2nd Floor Corridor, Room 203 (27x23), Room 202, Room 200 (33x6)**  
MATERIAL QUANTITY: **2450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Blue Carpet/Tan Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Blue Carpet/Tan Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor and Teachers' Lounge**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Corridor and Teachers' Lounge**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Corridor, and Rooms 202 & 203**  
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **120 Floor Tiles chipped and cracked but intact**

Inspector's Signature: \_\_\_\_\_



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **2nd Floor Corridor, and Rooms 202 & 203**  
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen, Cafeteria, and 1st Floor Corridor**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
MATERIAL LOCATION: **Kitchen, Cafeteria, and 1st Floor Corridor**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **Gray Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms**  
MATERIAL QUANTITY: **1210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **Gray Baseboard**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms**  
MATERIAL QUANTITY: **1210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 120-123**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
MATERIAL LOCATION: **Rooms 120-123**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen, Cafeteria, and 1st Floor Corridor**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
MATERIAL LOCATION: **Kitchen, Cafeteria, and 1st Floor Corridor**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms**  
MATERIAL QUANTITY: **1210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms**  
MATERIAL QUANTITY: **1210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mobile Unit- Rooms 120-123**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **06C**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
MATERIAL LOCATION: **Mobile Unit- Rooms 120-123**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **Brown Linoleum NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **Brown Linoleum NOT OBSERVED**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile w/Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1995 Addition- Corridor**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile w/Streaks**  
MATERIAL LOCATION: **1995 Addition- Corridor**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **12x12 White Floor w/Black Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1996 Annex- All Classrooms and Corridors**  
MATERIAL QUANTITY: **2490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **12x12 White Floor w/Black Specks Floor Tile**  
MATERIAL LOCATION: **Throughout 1996 Annex- All Classrooms and Corridors**  
MATERIAL QUANTITY: **2490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile w/Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mobile Unit Rooms 120-123**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile w/Streaks**  
MATERIAL LOCATION: **Mobile Unit Rooms 120-123**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08C**  
MATERIAL DESCRIPTION: **12x12 White Floor w/Black Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1996 Annex, All Classrooms and Corridor**  
MATERIAL QUANTITY: **2490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **08C**  
MATERIAL DESCRIPTION: **12x12 White Floor w/Black Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout 1996 Annex, All Classrooms and Corridor**  
MATERIAL QUANTITY: **2490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08D**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile w/Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mobile Unit- Rooms 120-123**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **08D**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile w/Streaks Mastic**  
MATERIAL LOCATION: **Mobile Unit- Rooms 120-123**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **2'x2' Smooth White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1995 Addition- Kitchen**  
MATERIAL QUANTITY: **770** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **2'x2' Smooth White Ceiling Tile**  
MATERIAL LOCATION: **1995 Addition- Kitchen**  
MATERIAL QUANTITY: **770** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1995 Addition- Cafeteria**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **1995 Addition- Cafeteria**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms, except 115**  
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms, except 115**  
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Solid Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **North Mobile Unit - Rooms 120 & 121**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **09/08/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Solid Ceiling Panels**  
MATERIAL LOCATION: **North Mobile Unit - Rooms 120 & 121**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **South Mobile Unit- Rooms 122 & 123**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **South Mobile Unit- Rooms 122 & 123**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **15B**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12x12 White Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5000** DAMAGE UNITS: **SF**  
COMMENTS: **50 Floor Tiles chipped and cracked but Intact**

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12x12 White Speckled Floor Tile**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16B**  
MATERIAL DESCRIPTION: **12x12 White Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **50 Floor tiles chipped and cracked but Intact**

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **16B**  
MATERIAL DESCRIPTION: **12x12 White Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit- Boys' Restroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
MATERIAL LOCATION: **East Mobile Unit- Boys' Restroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Pink Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit- Girls' Restroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Pink Linoleum**  
MATERIAL LOCATION: **East Mobile Unit- Girls' Restroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Building**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Main Building**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile w/Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1995 Addition- Corridor**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile w/Streaks Mastic**  
MATERIAL LOCATION: **1995 Addition- Corridor**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement, Pipe Chase/Air Tunnel, Crawlspace**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Basement Area and Crawlspace Areas Abated Summer of 2022**

Inspector's Signature: \_\_\_\_\_



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**  
MATERIAL LOCATION: **Basement, Pipe Chase/Air Tunnel, Crawlspace**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cardboard Pipe Wrap ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Basement and Crawl Space Areas Abated Summer of 2022**

Inspector's Signature: \_\_\_\_\_



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cardboard Pipe Wrap ABATED**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Mudded Fittings/Elbows on Aircell Pipe Runs ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Pipe Chases, Air Tunnel, Crawlspace**  
MATERIAL QUANTITY: **278** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Basement and Crawl Spaces Abated Summer of 2022**

Inspector's Signature: \_\_\_\_\_



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Mudded Fittings/Elbows on Aircell Pipe Runs ABATED**  
MATERIAL LOCATION: **Basement Pipe Chases, Air Tunnel, Crawlspace**  
MATERIAL QUANTITY: **278** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Duct Wrap ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY: **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement and Unexcavated Area, Crawlspace**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/08/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Duct Wrap ABATED**  
MATERIAL LOCATION: **Basement and Unexcavated Area, Crawlspace**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation ABATED**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Duct Manifold**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Fan Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/08/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School** REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Duct Manifold**  
MATERIAL LOCATION: **Fan Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22021**      BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Addams School**      INSPECTION DATE: **9/8/2022**  
ADDRESS: **10810 S. Avenue H**      IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **09/08/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22021**      BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Steven Geneser**  
SCHOOL NAME: **Addams School**      REVIEW DATE: **9/20/2022**  
ADDRESS: **10810 S. Avenue H**      IDPH LICENSE NO: **100-02950**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **09/20/2022**

# APPENDIX B

## Inspector and Management Planner Licenses

---





525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**KEITH CLOUGH**  
 524 HOMELAND RD  
 MATTESON, IL 60443

3/16/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 02950

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<table border="1"> <thead> <tr> <th>ENDORSEMENTS</th> <th>TC EXPIRES</th> </tr> </thead> <tbody> <tr> <td>INSPECTOR</td> <td>3/9/2023</td> </tr> <tr> <td>PROJECT MANAGER</td> <td>5/20/2022</td> </tr> <tr> <td>AIR SAMPLING PROFESSIONAL</td> <td></td> </tr> </tbody> </table> <p><b>Alteration of this license shall result in legal action</b>          This license issued under authority of the State of Illinois          Department of Public Health          This license is valid only when accompanied by a valid training course certificate.</p>		ENDORSEMENTS	TC EXPIRES	INSPECTOR	3/9/2023	PROJECT MANAGER	5/20/2022	AIR SAMPLING PROFESSIONAL	
ENDORSEMENTS	TC EXPIRES										
INSPECTOR	3/9/2023										
PROJECT MANAGER	5/20/2022										
AIR SAMPLING PROFESSIONAL											

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that KEITH CLOUGH  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/09/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/09/2022

Course Dates:

03/09/2023

Expires:

2203BIR03

Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

A handwritten signature in black ink, which appears to read "N Peneff". The signature is written in a cursive style.

**Director of Training**  
**Nicholas J. Peneff**  
**Doctor of Public Health**

Phone: 312-491-0081

**FORM # A-010B**

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that*

**Steve Geneser**

*has on 4/6/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: April 6, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: April 6, 2022

Expiration Date: April 6, 2023

Certificate Number: BIR/1044

*William S. Williams*

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois ☐ 217.787.9800 ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that*

**Steve Geneser**

*has on 4/06/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: April 6, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: April 6, 2022

Expiration Date: April 6, 2023

Certificate Number: MPR/0470

*William S. Williams*

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois ☐ 217.787.9800 ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



**ASBESTOS  
 PROFESSIONAL  
 LICENSE**

**ID NUMBER**  
 100 - 01784

**ISSUED**  
 3/1/2022

**EXPIRES**  
 05/15/2023

**STEVEN B GENESER**  
 210 BARNSIDE CIRCLE  
 GENEVA, IL 60134

Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

5/5/2022

MANAGEMENT PLANNER

5/5/2022

PROJECT MANAGER

8/4/2022

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
 This license issued under authority of the State of Illinois  
 Department of Public Health  
 This license is valid only when accompanied by a valid  
 training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed