

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2700
SCHOOL NAME: Clark School
ADDRESS OF SCHOOL: 1045 S. Monitor
CITY: Chicago, IL, 60644

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **11/5/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/7/2022 ENROLLMENT 151
IDPH INSPECTOR LICENSE NUMBER: 100-05020
IDPH LICENSED INSPECTOR NAME (Please Print): Devon Jackson
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

10/26/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Clark School

1045 S. Monitor
Chicago, IL, 60644

Unit: 22191
Building ID: 2230

IDPH ID Number: 14-016-2990-2700

REPORT DATE:

Wednesday, October 26, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

10/26/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22191 Region: 03 IDPH ID: 14-016-2990-2700

School: Clark School Building ID: 2230

Address: 1045 S. Monitor

Chicago, IL, 60644

Building Contact: Agate, Joseph

Contact Phone: 3124288928

Current Building Owners: Chicago Public Schools

Reinspection Date: 10/7/2022

Review Date: 10/26/2022

Inspector: Devon Jackson

Inspector IDPH License: 100-05020

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

A handwritten signature in black ink, appearing to read "Evan Christian". The signature is fluid and cursive.

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 26, 2022

RE: Clark School, Unit 22191
1045 S. Monitor
Chicago, IL, 60644

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Clark School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Clark School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Clark School Unit: 22191 Region: 03
Address: 1045 S. Monitor Chicago, IL, 60644
IDPH ID: 14-016-2990-2700 Building ID: 2230
Contact: Agate, Joseph Phone: 3124288928

2. Description of Facility

Original Construction: 1927 Additional Construction: 1996
Total Square Footage: 10900 No of Floors: 1
Current Occupancy: 151

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Devon Jackson


Inspector IDPH license # 100-05020
Reinspection Date: 10/7/2022

Signature: 
Date: 10/7/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature: 
Date: 10/26/2022

7. Review Date: 10/26/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/26/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Clark School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2230:

12	12" x 12" White w/Blue Brown gray Streaks Floor Tile
43	Hard Joints on Fiberglass Pipe Insulation
47	Duct insulation
B	12" x 12" Blue Gray Vinyl Floor Tile
C	12" x 12" Blue Gray Vinyl Floor Tile Mastic
D	12" x 12" Pink Vinyl Floor Tile
E	12" x 12" Pink Vinyl Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 2230:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	12" x 12" Floor Tile associated Mastic
12	12" x 12" White w/Blue Brown gray Streaks Floor Tile
14	12" x 12" Green Vinyl Floor Tile w/Beige, Dark Green Streaks
16	Canvas
17	12" x 12" yellow w/Dark yellow & White Specks Floor Tile
19	12" x 12" Dark Green w/White and Green Specks Floor Tile
2	Exterior window glazing - Non-AHERA
21	12" x 12" Pink Floor Tile w/White Streaks
23	12" x 12" Light Green Floor Tile w/Dark Green Specks
3	Exterior brick- non ahera
31	12" x 12" Light yellow Floor Tile w/White Specks
4	Exterior brick associated mortar Non AHERA
45	Mag block pipe insulation
46	Mag block insulation joints
47	Duct insulation
48	Vibration collar
49	Un-recognizable floor materials
5	Exterior door caulk - non ahera
50	Un-recognizable floor material mastic
51	Yellow linoleum
51M	Yellow linoleum mastic
52	12" x 12" Brown w/ White & Brown Vinyl Floor Tile
52M	12" x 12" Brown w/ White & Brown Vinyl Floor Tile Mastic
7	Roofing material - non ahera
8	9" x 9" Vinyl Floor Tile -
8A	9" x 9" Vinyl Floor Tile Mastic
9	12" x 12" Floor Tile
B	12" x 12" Blue Gray Vinyl Floor Tile
C	12" x 12" Blue Gray Vinyl Floor Tile Mastic
D	12" x 12" Pink Vinyl Floor Tile
E	12" x 12" Pink Vinyl Floor Tile Mastic

The following areas were deemed to be inaccessible:

A	Cementitious pipe joint insulation
10	12" x 12" Floor Tile associated Mastic
52M	12" x 12" Brown w/ White & Brown Vinyl Floor Tile Mastic
C	12" x 12" Blue Gray Vinyl Floor Tile Mastic
E	12" x 12" Pink Vinyl Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Devon Jackson, IDPH License # 100-05020. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Clark School Building 2230 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Clark School Unit 22191 Building ID 2230

Address 1045 S. Monitor Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
27	2' x 4' White wormy pinhole Ceiling Tile			Annex- 305, 303, 301	NO_ACBM	MISC								
28	2x2 White wormy pinhole Ceiling Tile			Annex-1st and 2nd floor hall	NO_ACBM	MISC								
29	2' x 2' Pink Linoleum			Annex-stairway	NO_ACBM	MISC								
3	Exterior brick- non ahera			Exterior Walls	ASSUMED	MISC								
30	2x2 pink linoleum mastic			Annex-stairway	NO_ACBM	MISC								
31	12" x 12" Light yellow Floor Tile w/White Specks	1,125	SF	Annex-1st floor class rooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
32	12" x 12" Light yellow FloorTile w/White Specks Mastic			Annex-1st floor class rooms	NO_ACBM	MISC								
33	Vibration caulk			Annex-2nd floor mech. Room	NO_ACBM	MISC								
34	Gray linoleum			annex-gym	NO_ACBM	MISC								
35	Gray linoleum Mastic			Annex-gym	NO_ACBM	MISC								
36	Sink undercoat			Annex-classrooms	NO_ACBM	SURFACE								
37	Red/Green carpet Mastic			Annex-Library and Main Office	ABATED	MISC								
38	4" Gray base board			Annex-gym	NO_ACBM	MISC								
39	4" Gray base board mastic			Annex-gym	NO_ACBM	MISC								
4	Exterior brick associated mortar Non AHERA			exterior walls	ASSUMED	MISC								
40	Drywall			Throughout Building	NO_ACBM	MISC								
41	Drywall compound			Throughout Building	NO_ACBM	MISC								
42	Spray-on			Throughout Building	NO_ACBM	SURFACE								
43	Hard Joints on Fiberglass Pipe Insulation	71	LF	Basement, Crawl Space and storage room	CHR	TSI	Y	NONE	0	LF	Yes	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
44	Lab table tops			Annex-306	NO_ACBM	MISC								
45	Mag block pipe insulation	170	LF	Crawl Space 1	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
46	Mag block insulation joints	20	LF	Crawl Space 1	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
47	Duct insulation	800	SF	Crawl Space 1, 2, 3, 4	ASSUMED	TSI	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
48	Vibration collar	5	LF	Mechanical Room	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the		LOW

Chicago Public Schools

School Clark School Unit 22191 Building ID 2230

Address 1045 S. Monitor Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
49	Un-recognizable floor materials			Slop Sink in Old Building	ASSUMED	MISC								
5	Exterior door caulk - non abera			Exterior Walls	ASSUMED	MISC								
50	Un-recognizable floor material mastic			Slop sink in Old building	ASSUMED	MISC								
51	Yellow linoleum			Basement Boiler Room Bathroom	ASSUMED	MISC								
51M	Yellow linoleum mastic			Basement Boiler Room Bathroom	ASSUMED	MISC								
52	12" x 12" Brown w/ White & Brown Vinyl Floor Tile	600	SF	Main Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
52M	12" x 12" Brown w/ White & Brown Vinyl Floor Tile Mastic	600	SF	Main Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
6	Incinerator mortar			Boiler Room	NO_ACBM	MISC								
7	Roofing material - non abera			Roof	ASSUMED	MISC								
8	9" x 9" Vinyl Floor Tile -			Throughout school	ASSUMED	MISC								
8A	9" x 9" Vinyl Floor Tile Mastic			Throughout School - Old Building	ASSUMED	MISC								
9	12" x 12" Floor Tile			throughout- This material has been separated into HA's 12, 13, 14, 15	ASSUMED	MISC								
B	12" x 12" Blue Gray Vinyl Floor Tile	25	SF	Boiler Room Bathroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
C	12" x 12" Blue Gray Vinyl Floor Tile Mastic	25	SF	Boiler Room Bathroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
D	12" x 12" Pink Vinyl Floor Tile	25	SF	Boiler Room Bathroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
E	12" x 12" Pink Vinyl Floor Tile Mastic	25	SF	Boiler Room Bathroom	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Clark School Unit 22191 Building ID 2230

Address 1045 S. Monitor Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date **10/7/2022**
Inspector Name **Devon Jackson**
100-05020 **5/15/2023**
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
A	
1	
10	
12	
13	
14	
15	
16	Not observed 2022
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	

Chicago Public Schools

School Clark School Unit 22191 Building ID 2230

Address 1045 S. Monitor Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	Not observed 2022
5	
50	Not observed 2022
51	Not observed 2022
51M	Not observed 2022
52	
52M	
6	
7	
8	Not observed 2022

Chicago Public Schools

School Clark School Unit 22191 Building ID 2230

Address 1045 S. Monitor Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
8A	Not observed 2022
9	Not observed 2022
B	
C	
D	
E	

Table II

Management Planner's Review

Chicago Public Schools

School Clark School
Address 1045 S. Monitor

Unit 22191
Chicago, IL, 60644

Building ID 2230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
A	Cementitious pipe joint insulation	200	LF	Maintenance Room, Room 4, Above Ceilings	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
1	Exterior window caulk - non ahera			Exterior Window	Chrysotile	MISC					Follow O&M Plan
10	12" x 12" Floor Tile associated Mastic	4,500	SF	throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12" x 12" White w/Blue Brown gray Streaks Floor Tile	2,880	SF	Old Building, hall, office, 204 and 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12" x 12" White w/Blue Brown gray Streaks Floor Tile Mastic			Old Building, hall, office, 204 and 206	No ACBM	MISC					
14	12" x 12" Green Vinyl Floor Tile w/Beige, Dark Green Streaks	480	SF	Old Building Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12" x 12" Green Vinyl Floor Tile w/Beige, Dark Green Streaks Mastic			Old Building Hall	No ACBM	MISC					
16	Canvas			Old Building, Main Office	Assumed	MISC					Follow O&M Plan
17	12" x 12" yellow w/Dark yellow & White Specks Floor Tile	7,320	SF	Annex-Throughout 1st floor and 2nd floor hall and classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12" x 12" yellow w/Dark yellow & White Specks Floor Tile Mastic			Annex-throughout 1st flr and 2nd flr hall and class Rooms	No ACBM	MISC					
19	12" x 12" Dark Green w/White and Green Specks Floor Tile	7,320	SF	Annex-throughout 1st, 2nd flr hall and class rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2	Exterior window glazing - Non-AHERA			Exterior Window Walls	Assumed	MISC					Follow O&M Plan
20	12" x 12" Dark Green w/White and Green Specks Floor Tile Mastic			Annex-throughout 1st, 2nd flr hall and class rooms	No ACBM	MISC					
21	12" x 12" Pink Floor Tile w/White Streaks	1,880	SF	Annex-throughout 2nd flr class rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Pink Floor Tile w/White Streaks Mastic			Annex-throughout 2nd flr class rooms	No ACBM	MISC					
23	12" x 12" Light Green Floor Tile w/Dark Green Specks	7,076	SF	Annex-throughout 1st, 2nd floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" Light Green Floor Tile w/Dark Green Specks Mastic			Annex-throughout 1st, 2nd floor	No ACBM	MISC					
25	4" Green base board			Annex- throughout classroom and hall	No ACBM	MISC					
26	4" Green base board Mastic			Annex- throughout classroom and hall	No ACBM	MISC					
27	2' x 4' White wormy pinhole Ceiling Tile			Annex- 305, 303, 301	No ACBM	MISC					
28	2x2 White wormy pinhole Ceiling Tile			Annex-1st and 2nd floor hall	No ACBM	MISC					
29	2' x 2' Pink Linoleum			Annex-stairway	No ACBM	MISC					
3	Exterior brick- non ahera			Exterior Walls	Assumed	MISC					Follow O&M Plan
30	2x2 pink linoleum mastic			Annex-stairway	No ACBM	MISC					
31	12" x 12" Light yellow Floor Tile w/White Specks	1,125	SF	Annex-1st floor class rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clark School
Address 1045 S. Monitor

Unit 22191
Chicago, IL, 60644

Building ID 2230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	12" x 12" Light yellow FloorTile w/White Specks Mastic			Annex-1st floor class rooms	No ACBM	MISC					
33	Vibration caulk			Annex-2nd floor mech. Room	No ACBM	MISC					
34	Gray linoleum			annex-gym	No ACBM	MISC					
35	Gray linoleum Mastic			Annex-gym	No ACBM	MISC					
36	Sink undercoat			Annex-classrooms	No ACBM	SURFACE					
37	Red/Green carpet Mastic			Annex-Library and Main Office	Abated	MISC					
38	4" Gray base board			Annex-gym	No ACBM	MISC					
39	4" Gray base board mastic			Annex-gym	No ACBM	MISC					
4	Exterior brick associated mortar Non AHERA			exterior walls	Assumed	MISC					Follow O&M Plan
40	Drywall			Throughout Building	No ACBM	MISC					
41	Drywall compound			Throughout Building	No ACBM	MISC					
42	Spray-on			Throughout Building	No ACBM	SURFACE					
43	Hard Joints on Fiberglass Pipe Insulation	71	LF	Basement, Crawl Space and storage room	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
44	Lab table tops			Annex-306	No ACBM	MISC					
45	Mag block pipe insulation	170	LF	Crawl Space 1	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
46	Mag block insulation joints	20	LF	Crawl Space 1	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
47	Duct insulation	800	SF	Crawl Space 1, 2, 3, 4	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
48	Vibration collar	5	LF	Mechanical Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
49	Un-recognizable floor materials			Slop Sink in Old Building	Assumed	MISC					Follow O&M Plan
5	Exterior door caulk - non ahera			Exterior Walls	Assumed	MISC					Follow O&M Plan
50	Un-recognizable floor material mastic			Slop sink in Old building	Assumed	MISC					Follow O&M Plan
51	Yellow linoleum			Basement Boiler Room Bathroom	Assumed	MISC					Follow O&M Plan
51M	Yellow linoleum mastic			Basement Boiler Room Bathroom	Assumed	MISC					Follow O&M Plan
52	12" x 12" Brown w/ White & Brown Vinyl Floor Tile	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52M	12" x 12" Brown w/ White & Brown Vinyl Floor Tile Mastic	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Incinerator mortar			Boiler Room	No ACBM	MISC					
7	Roofing material - non ahera			Roof	Assumed	MISC					Follow O&M Plan
8	9" x 9" Vinyl Floor Tile -			Throughout school	Assumed	MISC					Follow O&M Plan
8A	9" x 9" Vinyl Floor Tile Mastic			Throughout School - Old Building	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Clark School
Address 1045 S. Monitor

Unit 22191
 Chicago, IL, 60644

Building ID 2230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
9	12" x 12" Floor Tile			throughout- This material has been separated into HA's 12, 13, 14, 15	Assumed	MISC					Follow O&M Plan
B	12" x 12" Blue Gray Vinyl Floor Tile	25	SF	Boiler Room Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	12" x 12" Blue Gray Vinyl Floor Tile Mastic	25	SF	Boiler Room Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	12" x 12" Pink Vinyl Floor Tile	25	SF	Boiler Room Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
E	12" x 12" Pink Vinyl Floor Tile Mastic	25	SF	Boiler Room Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clark School
Address 1045 S. Monitor

Unit 22191
 Chicago, IL, 60644

Building ID 2230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	10/26/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
A	
1	
10	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	

Chicago Public Schools

School Clark School
Address 1045 S. Monitor

Unit 22191
 Chicago, IL, 60644

Building ID 2230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
51M	
52	
52M	
6	
7	
8	
8A	

Chicago Public Schools

School Clark School
Address 1045 S. Monitor

Unit 22191
Chicago, IL, 60644

Building ID 2230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
9	
B	
C	
D	
E	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Cementitious pipe joint insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Maintenance Room, Room 4, Above Ceilings**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Cementitious pipe joint insulation**
MATERIAL LOCATION: **Maintenance Room, Room 4, Above Ceilings**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Exterior window caulk - non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Window**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Exterior window caulk - non ahera**

MATERIAL LOCATION: **Exterior Window**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile associated Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **throughout**

MATERIAL QUANTITY: **4500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile associated Mastic**

MATERIAL LOCATION: **throughout**

MATERIAL QUANTITY: **4500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Brown gray Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Old Building, hall, office, 204 and 206**

MATERIAL QUANTITY: **2880**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Brown gray Streaks Floor Tile**
MATERIAL LOCATION: **Old Building, hall, office, 204 and 206**
MATERIAL QUANTITY: **2880** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Brown gray Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Old Building, hall, office, 204 and 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12" x 12" White w/Blue Brown gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Old Building, hall, office, 204 and 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" x 12" Green Vinyl Floor Tile w/Beige, Dark Green Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Old Building Hall**

MATERIAL QUANTITY: **480**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" x 12" Green Vinyl Floor Tile w/Beige, Dark Green Streaks**
MATERIAL LOCATION: **Old Building Hall**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12" x 12" Green Vinyl Floor Tile w/Beige, Dark Green Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Old Building Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" Green Vinyl Floor Tile w/Beige, Dark Green Streaks Mastic**

MATERIAL LOCATION: **Old Building Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Canvas**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Old Building, Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Canvas**

MATERIAL LOCATION: **Old Building, Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" yellow w/Dark yellow & White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex-Throughout 1st floor and 2nd floor hall and classrooms**

MATERIAL QUANTITY: **7320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" yellow w/Dark yellow & White Specks Floor Tile**
MATERIAL LOCATION: **Annex-Throughout 1st floor and 2nd floor hall and classrooms**
MATERIAL QUANTITY: **7320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" yellow w/Dark yellow & White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-throughout 1st flr and 2nd flr hall and class Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" yellow w/Dark yellow & White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Annex-throughout 1st flr and 2nd flr hall and class Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12" x 12" Dark Green w/White and Green Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex-throughout 1st, 2nd flr hall and class rooms**

MATERIAL QUANTITY: **7320**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12" x 12" Dark Green w/White and Green Specks Floor Tile**
MATERIAL LOCATION: **Annex-throughout 1st, 2nd flr hall and class rooms**
MATERIAL QUANTITY: **7320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **Exterior window glazing - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Window Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **Exterior window glazing - Non-AHERA**

MATERIAL LOCATION: **Exterior Window Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12" x 12" Dark Green w/White and Green Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-throughout 1st, 2nd flr hall and class rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Dark Green w/White and Green Specks Floor Tile Mastic**

MATERIAL LOCATION: **Annex-throughout 1st, 2nd flr hall and class rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex-throughout 2nd flr class rooms**

MATERIAL QUANTITY: **1880**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile w/White Streaks**

MATERIAL LOCATION: **Annex-throughout 2nd flr class rooms**

MATERIAL QUANTITY: **1880**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-throughout 2nd flr class rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile w/White Streaks Mastic**

MATERIAL LOCATION: **Annex-throughout 2nd flr class rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile w/Dark Green Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex-throughout 1st, 2nd floor**

MATERIAL QUANTITY: **7076**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile w/Dark Green Specks**
MATERIAL LOCATION: **Annex-throughout 1st, 2nd floor**
MATERIAL QUANTITY: **7076** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile w/Dark Green Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-throughout 1st, 2nd floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile w/Dark Green Specks Mastic**

MATERIAL LOCATION: **Annex-throughout 1st, 2nd floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **4" Green base board**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex- throughout classroom and hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **4" Green base board**

MATERIAL LOCATION: **Annex- throughout classroom and hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **4" Green base board Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex- throughout classroom and hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **4" Green base board Mastic**

MATERIAL LOCATION: **Annex- throughout classroom and hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **2' x 4' White wormy pinhole Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex- 305, 303, 301**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **2' x 4' White wormy pinhole Ceiling Tile**

MATERIAL LOCATION: **Annex- 305, 303, 301**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **2x2 White wormy pinhole Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-1st and 2nd floor hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **2x2 White wormy pinhole Ceiling Tile**

MATERIAL LOCATION: **Annex-1st and 2nd floor hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **2' x 2' Pink Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-stairway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **2' x 2' Pink Linoleum**

MATERIAL LOCATION: **Annex-stairway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **Exterior brick- non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Exterior brick- non ahera**

MATERIAL LOCATION: **Exterior Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2x2 pink linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-stairway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **2x2 pink linoleum mastic**

MATERIAL LOCATION: **Annex-stairway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Light yellow Floor Tile w/White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex-1st floor class rooms**

MATERIAL QUANTITY: **1125**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Light yellow Floor Tile w/White Specks**
MATERIAL LOCATION: **Annex-1st floor class rooms**
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Light yellow FloorTile w/White Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-1st floor class rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Light yellow FloorTile w/White Specks Mastic**

MATERIAL LOCATION: **Annex-1st floor class rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Vibration caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-2nd floor mech. Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Vibration caulk**

MATERIAL LOCATION: **Annex-2nd floor mech. Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Gray linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **annex-gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Gray linoleum**

MATERIAL LOCATION: **annex-gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Gray linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Gray linoleum Mastic**

MATERIAL LOCATION: **Annex-gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Sink undercoat**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Sink undercoat**

MATERIAL LOCATION: **Annex-classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Red/Green carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-Library and Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Red/Green carpet Mastic**

MATERIAL LOCATION: **Annex-Library and Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **4" Gray base board**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **4" Gray base board**

MATERIAL LOCATION: **Annex-gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **4" Gray base board mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **4" Gray base board mastic**

MATERIAL LOCATION: **Annex-gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **Exterior brick associated mortar Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **exterior walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Exterior brick associated mortar Non AHERA**

MATERIAL LOCATION: **exterior walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Drywall compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Drywall compound**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Spray-on**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Spray-on**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Hard Joints on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement, Crawl Space and storage room**

MATERIAL QUANTITY: **71**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Hard Joints on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Basement, Crawl Space and storage room**

MATERIAL QUANTITY: **71**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Lab table tops**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex-306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Lab table tops**

MATERIAL LOCATION: **Annex-306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Mag block pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Crawl Space 1**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Mag block pipe insulation**

MATERIAL LOCATION: **Crawl Space 1**

MATERIAL QUANTITY: **170**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Mag block insulation joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Crawl Space 1**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Mag block insulation joints**

MATERIAL LOCATION: **Crawl Space 1**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Duct insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage
Water
Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Crawl Space 1, 2, 3, 4**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Duct insulation**
MATERIAL LOCATION: **Crawl Space 1, 2, 3, 4**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Vibration collar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mechanical Room**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Vibration collar**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Un-recognizable floor materials**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Slop Sink in Old Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Un-recognizable floor materials**

MATERIAL LOCATION: **Slop Sink in Old Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Exterior door caulk - non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **Exterior door caulk - non ahera**

MATERIAL LOCATION: **Exterior Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Un-recognizable floor material mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Slop sink in Old building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Un-recognizable floor material mastic**

MATERIAL LOCATION: **Slop sink in Old building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Yellow linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Boiler Room Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Yellow linoleum**

MATERIAL LOCATION: **Basement Boiler Room Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51M**
MATERIAL DESCRIPTION: **Yellow linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Boiler Room Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **51M**

MATERIAL DESCRIPTION: **Yellow linoleum mastic**

MATERIAL LOCATION: **Basement Boiler Room Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Brown Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Brown Vinyl Floor Tile**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52M**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Brown Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **52M**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Brown Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Incinerator mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Incinerator mortar**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Roofing material - non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUILDING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Roofing material - non ahera**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile -**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout school**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile -**

MATERIAL LOCATION: **Throughout school**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8A**
MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School - Old Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **8A**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Throughout School - Old Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **throughout- This material has been separated into HA's 12, 13, 14, 15**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile**
MATERIAL LOCATION: **throughout- This material has been separated into HA's 12, 13, 14, 15**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **12" x 12" Blue Gray Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **12" x 12" Blue Gray Vinyl Floor Tile**
MATERIAL LOCATION: **Boiler Room Bathroom**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **12" x 12" Blue Gray Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room Bathroom**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **12" x 12" Blue Gray Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Boiler Room Bathroom**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **12" x 12" Pink Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **12" x 12" Pink Vinyl Floor Tile**
MATERIAL LOCATION: **Boiler Room Bathroom**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Devon Jackson**
SCHOOL NAME: **Clark School** INSPECTION DATE: **10/7/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **12" x 12" Pink Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room Bathroom**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **10/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22191** BUIDLING ID: **2230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark School** REVIEW DATE: **10/26/2022**
ADDRESS: **1045 S. Monitor** IDPH LICENSE NO: **100-05020**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **12" x 12" Pink Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Boiler Room Bathroom**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/26/2022**

Chicago Public Schools

Carnow, Conibear and Associates


2022 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

Devon Jackson

has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/1/2022 - 3/3/2022

Exam Date: 3/3/2022




Expiration Date: 3/3/2023

Certificate Number: ABI2203030658

Kathy DeSalvo, Director

Devon Jackson

Illinois Licensed Building Inspector, Air Sampling Professional

 ILLINOIS DEPARTMENT OF PUBLIC HEALTH IDPH PROTECTING HEALTH. IMPROVING LIVES.	ASBESTOS PROFESSIONAL LICENSE	
ID NUMBER 100 - 05020	ISSUED 5/13/2022	EXPIRES 05/15/2023
DEVON A JACKSON 10657 SOUTH AVENUE D CHICAGO, IL 60617 Environmental Health		

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/3/2023
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	11/18/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER

3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed