

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2089
SCHOOL NAME: Boone School
ADDRESS OF SCHOOL: 6710 N. Washtenaw Ave.
CITY: Chicago, IL, 60645

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **9/10/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/8/2022 ENROLLMENT 728
IDPH INSPECTOR LICENSE NUMBER: 100-20525
IDPH LICENSED INSPECTOR NAME (Please Print): Kevin Hanna
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



10/7/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Boone School

6710 N. Washtenaw Ave.
Chicago, IL, 60645

Unit: 22271
Building ID: 2320

IDPH ID Number: 14-016-2990-2089

REPORT DATE:

Friday, October 07, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Specialty Consulting, Inc.

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

10/07/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22271 Region: 01 IDPH ID: 14-016-2990-2089

School: Boone School Building ID: 2320

Address: 6710 N. Washtenaw Ave.

Chicago, IL, 60645

Building Contact: Monaghan, Kevin

Contact Phone: 7737105687

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/8/2022

Review Date: 10/07/2022

Inspector: Kevin Hanna

Inspector IDPH License: 100-20525

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 07, 2022

RE: Boone School, Unit 22271
6710 N. Washtenaw Ave.
Chicago, IL, 60645

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Boone School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Boone School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Boone School Unit: 22271 Region: 01
Address: 6710 N. Washtenaw Ave. Chicago, IL, 60645
IDPH ID: 14-016-2990-2089 Building ID: 2320
Contact: Monaghan, Kevin Phone: 7737105687

2. Description of Facility

Original Construction: 1955 Additional Construction: 1927,1996
Total Square Footage: 24672 No of Floors: 2
Current Occupancy: 728

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Kevin Hanna


Inspector IDPH license # 100-20525
Reinspection Date: 9/8/2022


Signature:
Date: 9/8/2022

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342



Signature:
Date: 10/07/2022

7. Review Date: 10/07/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/7/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Boone School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2320:

11	Grey Speckled Linoleum NOT OBSERVED
13	12"x12" White VFT
14	12"x12" Brown VFT
20	Grey Speckled Linoleum Mastic
31	12"x12" Brown w/ Tan Streaks VFT
32	12"x12" Off White VFT
40	12"x12" Beige VFT
43	Blue Linoleum
47	12"x12" White w/ Tan Spots VFT

60	12"x12" White VFT Mastic
61	12"x12" Brown VFT Mastic
67	12" x 12" Brown w/ Tan Streaks VFT Mastic
68	12" x 12" Off White VFT Mastic
75	Blue Linoleum Mastic
85	Green Table Top Linoleum NOT OBSERVED
86	Green Table Top Linoleum Mastic NOT OBSERVED
A	MJP on Fiberglass Pipe Insulation
K	Water Tank Insulation
L	Boiler Breeching
M	Boiler Gasket
P	MJP on Fiberglass Pipe Insulation

B. The following new homogenous areas have been identified for Building 2320:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	Carpet Mastic
101	12" X 12" Cream w/ White Specks VFT
102	12" X 12" Cream w/ White Specks VFT Mastic
103	12" x 12" Gray VFT
104	12" x 12" Gray VFT Mastic
105	12" x 12" Black VFT
106	12" x 12" Black VF Mastic
107	Black Linoleum
108	Black Linoleum Mastic
109	Vinyl Baseboard
11	Grey Speckled Linoleum NOT OBSERVED
110	Vinyl Baseboard Mastic
111	2' x 2' Ceiling Tile
112	2' x 2' Ceiling Tile
113	12 x 12 inch Tan Mottled VFT
113 A	12 x 12 inch Tan Mottled VFT Mastic
114	12 x 12 inch Tan Mottled VFT
114 A	12 x 12 inch Tan Mottled VFT Mastic
115	1 x 1 ft Wavy Ceiling Tile
116	2 x 4 ft Dot Wave Ceiling Tile
117	2 x 4 ft Dot/Wave Ceiling Tile
118	Carpet Mastic
119	Terrazo
120	Terrazo
121	12"x12" White VFT NOT OBSERVED
121A	12"x12" White VFT Mastic
122	Blue/White VFT
122A	Blue/White VFT Mastic
123	Carpet Mastic
124	12'X12" Gray VFT
124A	12'X12" Gray VFT Mastic
125	12"X12" White and Tan VFT
125A	12"X12" White and Tan VFT Mastic
126	12"X12" White, Gray VFT
126A	12"X12" White, Gray VFT Mastic
127	12"x12" Tan VFT
127A	12"x12" Tan VFT Mastic
128	12"X12' Tan VFT
129	VFT 12" x 12" White with Tan & Beige Specs
129A	VFT Mastic 12" x 12" White with Tan & Beige Specs
13	12"x12" White VFT

130	Fire doors
131	VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED
131A	VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED
132	VFT 12" x 12" Tan with White Specs NOT OBSERVED
132A	VFT Mastic 12" x 12" Tan with White Specs
133	VFT 12" x 12" Tan, Light Brown with White Specks
133A	VFT Mastic 12" x 12" Tan, Light Brown with White Specks
134	VFT 12" x 12" Tan, Light Brown with White Specks
134A	VFT Mastic 12" x 12" Tan, Light Brown with White Specks
135	Tectum Tiles
136	Carpet Mastic
137	Decorative Plaster Trim
138	VFT 12" x 12" Gray
138A	VFT Mastic 12" x 12" Gray
139	VFT 12" x 12" White
139A	VFT Mastic 12" x 12" White
14	12"x12" Brown VFT
140	2" x 2" White Ceiling Tile
141	Fire Door
142	Fire Door
143	Sink Undercoating
144	Sink Undercoating
145	Vinyl Baseboard Mastic
146	Drywall System (Drywall, Tape, Compound)
147	12" x 12" White w/ Tan specks VFT
147A	12" x 12" White w/ Tan specks VFT mastic
148	Drywall System (Drywall, Tape, Compound)
149	Drywall System (Drywall, Tape, Compound)
15	Hard Coat Plaster
20	Grey Speckled Linoleum Mastic
21	Hard Coat Plaster
31	12"x12" Brown w/ Tan Streaks VFT
32	12"x12" Off White VFT
33	Hard Coat Plaster
40	12"x12" Beige VFT
43	Blue Linoleum
47	12"x12" White w/ Tan Spots VFT
60	12"x12" White VFT Mastic
61	12"x12" Brown VFT Mastic
67	12" x 12" Brown w/ Tan Streaks VFT Mastic
68	12" x 12" Off White VFT Mastic
75	Blue Linoleum Mastic
85	Green Table Top Linoleum NOT OBSERVED

86	Green Table Top Linoleum Mastic NOT OBSERVED
92	12" x 12" White w/ Light Gray Specks VFT
93	12" x 12" White w/ Light Gray Specks VFT Mastic
94	12" x 12" Dark Blue w/ Blue Specks VFT
95	12" x 12" Dark Blue w/ Blue Specks VFT Mastic
96	12" x 12" Light Gray w/ Speckles VFT
97	12" x 12" Light Gray w/ Speckles VFT Mastic
98	12" x 12" Black w/ White Speckles VFT
99	12" x 12" Black w/ White Speckles VFT Mastic
A	MJP on Fiberglass Pipe Insulation
K	Water Tank Insulation
L	Boiler Breeching
M	Boiler Gasket
P	MJP on Fiberglass Pipe Insulation

The following areas were deemed to be inaccessible:

66	9"x9" White w/ Green Streaks VFT Mastic
----	---

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Kevin Hanna, IDPH License # 100-20525. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/10/2019
 7/10/2019

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Boone School Building 2320 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12" x 12" Red VFT	850	SF	Auditorium & Vestibule Room (not observed), 1927 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	9"x9" Red w/ White Streaks VFT - NOT OBSERVED	1,500	SF	1st Fl Corridor - 1927 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	9"x9" Red VFT - NOT OBSERVED	330	SF	1st Fl Corridor - 1955 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	12"x12" Grey Beige VFT	2,925	SF	Room 201 - 1927 Bldg. Rooms 101,102,103, 105, 202, 202A, 203, 205 - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	12"x12" Light Brown VFT	1,300	SF	Rm 111, (107 not observed) and 304 - 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	9"x9" Green w/ White Streaks VFT	325	SF	Rm 306 - 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	9"X9" Gray VFT NOT OBSERVED	1,100	SF	Rm 214 - 1957 Bldg. NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9"x9" Tan VFT	1,200	SF	Rm 119 (Under New Tile and Carpet), 219 - 1957 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100	Carpet Mastic	0		Room 112 and 119, 1957 Building - Not Observed	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	12" X 12" Cream w/ White Specks VFT	1,000	SF	Lunchroom, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	12" X 12" Cream w/ White Specks VFT Mastic	1,000	SF	Lunchroom, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	12" x 12" Gray VFT	750	SF	Lunchroom, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12" x 12" Gray VFT Mastic	750	SF	Lunchroom, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	12" x 12" Black VFT	1,908	SF	Lunch Room and Breezeway, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
106	12" x 12" Black VF Mastic	1,908	SF	Lunchroom and Breezeway, 1996	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Annex										
107	Black Linoleum	2,500	SF	Serving Area, Men and Women Lunchroom Area Bathrooms, Kitchen, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	Black Linoleum Mastic	2,500	SF	Serving Area, Men and Women Lunchroom Aea Bathrooms, Kitchen, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	Vinyl Baseboard	800	SF	Lunchroom, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
11	Grey Speckled Linoleum NOT OBSERVED	1,600	SF	Rms 114 and 221-1957 Bldg. - Not Observed	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
110	Vinyl Baseboard Mastic	0		Lunch Room, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111	2' x 2' Ceiling Tile	0	SF	Serving Area, Kitchen, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	2' x 2' Ceiling Tile	0		Lunchroom Hall, 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
113	12 x 12 inch Tan Mottled VFT	2,000	SF	1929 Building- 2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
113 A	12 x 12 inch Tan Mottled VFT Mastic	2,000	SF	1929 Building- 2nd and 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12 x 12 inch Tan Mottled VFT	2,000	SF	1957 Building- 2nd and 3rd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114 A	12 x 12 inch Tan Mottled VFT Mastic	2,000	SF	1957 Building- 2nd and 3rd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	1 x 1 ft Wavy Ceiling Tile	2,500	SF	1957 Building- Rooms: 214, 221 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	2 x 4 ft Dot Wave Ceiling Tile	10,000	SF	1929 Building: Rooms 301- 304, 305 306-308,106, 109-111, 113, 114, 115, 117, 204, 206, 208-211, main office	ASSUMED	MISC	Y	LOC	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
117	2 x 4 ft Dot/Wave Ceiling Tile	3,000	SF	1957 Building: Rooms 112, 121, 207, 213, 215 219	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	Carpet Mastic	3,000	SF	1929 - Building: Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	Terrazo	3,000	SF	(Throughout) 1929 Building: Entry way, Auditorium Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	9"x9" Burgandy VFT NOT OBSERVED	50	SF	Engineers Bathroom - 1929 Bldg. -NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	Terrazo	2,000	SF	(Throughout) 1954 Building: Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	12"x12" White VFT NOT OBSERVED	1,000	SF	Rm 214 (1957 Bldg) - NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
121A	12"x12" White VFT Mastic	1,000	SF	Rm 214 (1957 Bldg) - Not Observed	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
122	Blue/White VFT	750	SF	Rms 112, 119 (1957 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
122A	Blue/White VFT Mastic	750	SF	Rms 112, 119 (1957 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
123	Carpet Mastic	1,000	SF	Rm 221 (1957 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
124	12"X12" Gray VFT	1,000	SF	Rm 114 (1957 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
124A	12"X12" Gray VFT Mastic	1,000	SF	Rm 114 (1957 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
125	12"X12" White and Tan VFT	800	SF	Rm 212 (1957 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
125A	12"X12" White and Tan VFT Mastic	800	SF	Rm 212 (1957 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
126	12"X12" White, Gray VFT	50	SF	Engineer's Bathroom (1929 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
126A	12"X12" White, Gray VFT Mastic	50	SF	Engineer's Bathroom (1929 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
127	12"x12" Tan VFT	500	SF	1st Floor Corridor (1954 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
127A	12"x12" Tan VFT Mastic	500	SF	1st Floor Corridor (1954 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
128	12"X12" Tan VFT	500	SF	2nd Floor Corridor (1954 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
129	VFT 12" x 12" White with Tan & Beige	1,000	SF	Room 214	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Specs											potential for damage		
129A	VFT Mastic 12" x 12" White with Tan & Beige Specs	1,000	SF	Room 214	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12"x12" White VFT	500	SF	Main Office - 1929 Bldg - Not Observed	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
130	Fire doors	4	EA	Stage, Balcony and Projector Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131	VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED	400	SF	Room 201 NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131A	VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED	400	SF	Room 201 NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132	VFT 12" x 12" Tan with White Specs NOT OBSERVED	400	SF	Room 201 NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132A	VFT Mastic 12" x 12" Tan with White Specs	400	SF	Room 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133	VFT 12" x 12" Tan, Light Brown with White Specks	800	SF	1st Floor Corridor - (1954)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133A	VFT Mastic 12" x 12" Tan, Light Brown with White Specks	800	SF	1st Floor Corridor - (1954)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	VFT 12" x 12" Tan, Light Brown with White Specks	5,000	SF	1st Floor Corridor - (1929)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134A	VFT Mastic 12" x 12" Tan, Light Brown with White Specks	5,000	SF	1st Floor Corridor - (1929)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
135	Tectum Tiles	5,000	SF	Gymnasium Walls	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
136	Carpet Mastic	800	SF	Room 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
137	Decorative Plaster Trim	1,200	SF	Auditorium, Stage & Balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
138	VFT 12" x 12" Gray	120	SF	Engineer Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
138A	VFT Mastic 12" x 12" Gray	120	SF	Engineer Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
139	VFT 12" x 12" White	120	SF	Engineer Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
139A	VFT Mastic 12" x 12" White	120	SF	Engineer Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12"x12" Brown VFT	1,600	SF	Rm 301, 303 - 1929 Bldg.	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
140	2" x 2" White Ceiling Tile	720	SF	Room 720 - 1927 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
141	Fire Door	9	EA	Breezeway, Entry Vestibules, Kitchen (1996 Annex)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
142	Fire Door	4	EA	Entry Vestibule - 1955 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
143	Sink Undercoating	6	EA	219, 212, 214, 119, 112 - 1955 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
144	Sink Undercoating	3	EA	Room 210 - 1927 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
145	Vinyl Baseboard Mastic	2,800	SF	Rooms 121, 114, 119, 112 - 1955 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
146	Drywall System (Drywall, Tape, Compound)	3,000	SF	Bridgeway, Kitchen - 1996 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
147	12" x 12" White w/ Tan specks VFT	905	SF	Room 210 - 1927 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
147A	12" x 12" White w/ Tan specks VFT mastic	905	SF	Room 210 - 1927 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
148	Drywall System (Drywall, Tape, Compound)	1,500	SF	Rooms 110, 115 - 1927 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
149	Drywall System (Drywall, Tape, Compound)	1,500	SF	Rooms 114, 121, 112, 119 (Toilets) - 1955 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
15	Hard Coat Plaster	15,000	SF	Throughout - 1929 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	9"x9" Red w/ Black Streaks VFT Mastic	1,500	SF	1st Fl Corridor - 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Red Black VFT Mastic	850	SF	Auditorium, 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Grey Speckled Linoleum Mastic	1,600	SF	Rm 1957 Bldg. - Not Observed	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
21	Hard Coat Plaster	7,000	SF	Throughout - 1954 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Vibration Dampening Cloth	40	SF	Attic - 1954 Bldg.	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
26	12"x12" Black VFT	850	SF	Auditorium 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	9"x9" Black w/ White Streaks VFT	0	SF	2nd & 3rd Fl Corridors - 1929 Bldg - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	9"x9" Black VFT Not Observed	0	SF	1st & 2nd Fl Corridor - 1954 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12"x12" Green VFT	2,925	SF	Rm 101-103, 105, 201, 202, 202A, 203, 205 - 1927	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.										
30	9"x9" White w/ Green Streaks VFT	325	SF	Rm 306 - 1929 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12"x12" Brown w/ Tan Streaks VFT	500	SF	Main Office (Wood) - 1929 Bldg.	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
32	12"x12" Off White VFT	1,600	SF	Rm 301, 303 - 1929 Bldg.	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
33	Hard Coat Plaster	0	SF	Throughout - 1957 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	9"x9" Burgandy w/ White Streaks VFT	0	SF	2nd & 3rd Fl Hallways - 1929 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	6"x18" Black VFT	0	SF	2nd & 3rd Fl Corridors, Auditorium, 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12"x12" Green w/ White Streaks VFT	900	SF	Rm 210 - 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12"x12" Beige VFT	900	SF	Rm 117 - 1929	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
41	9"x9" Coal Black w/ White Streaks VFT	1,500	SF	1st Fl Corridor - 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	9"x9" Black w/ Green & White Streaks VFT	350	SF	Rm 108 - 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Blue Linoleum	350	SF	2nd Fl Copy Rm (206A) - 1929 Bldg.	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
44	9"x18" Black VFT	152	SF	1st fl Corridor - 1954 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	9"x9" Black w/ White Streaks VFT	200	SF	1st Fl Corridor - 1957 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	9"x9" Red w/ White Streaks VFT	340	SF	1st Fl Corridor, Rm 112 & 119 (Under New Tile and Carpet), 1957 Building - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
47	12"x12" White w/ Tan Spots VFT	900	SF	Rm 121, 1957 Bldg.	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
48	9"x9" White w/ Green VFT	1,350	SF	Rm 112, 212 - 1957 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
49	9"x9" Black VFT	25	SF	Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	9"x9" Red VFT	25	SF	Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51	9"x24" Black VFT NOT OBSERVED	10	SF	Stairwell Landing Between 1st and 2nd Floor - 1957 Bldg - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
52	9"x18" Black VFT NOT OBSERVED	25	SF	Stairwell Landing, 1957 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53	9"x9" Red VFT	330	SF	1st fl Corridor - 1954 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12"x12" Grey VFT Mastic	2,925	SF	Rm 101-103, 105, 201, 202, 202A, 203, 205 - 1927 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
55	12"x12" Light Brown VFT Mastic	1,300	SF	Rm 111, 304 - 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	9"x9" Green w/ White Streaks VFT Mastic	325	SF	Rm 306 - 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	9"x9" Grey VFT Mastic	1,100	SF	Rm 214 - 1957 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	9"x9" Tan VFT Mastic	1,200	SF	Rm 119 (Under New Tile and Carpet), 219 - 1957 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
59	9"x9" Burgandy VFT Mastic NOT OBSERVED	50	SF	Engineers Office Bathroom - 1929 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	12"x12" White VFT Mastic	500	SF	Main Office - 1929 Bldg. - Not Observed	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
61	12"x12" Brown VFT Mastic	1,700	SF	Rm 301, 303 - 1929 Bldg.	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
62	12"x12" Black VFT Mastic	850	SF	Auditorium - 1929 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
63	9"x9" Black w/ White Streaks VFT Mastic NOT OBSERVED	0	SF	2nd & 3rd Fl Corridor - 1929 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	9"x9" Black VFT Mastic	0	SF	1st & 2nd Fl Corridor - 1954 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12"x12" Green VFT Mastic	2,925	SF	Rm 101, 102, 103, 105, 201, 202, 202A, 203, 205 - 1954 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
66	9"x9" White w/ Green Streaks VFT Mastic	325	SF	Rm 306 - 1929	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12" x 12" Brown w/ Tan Streaks VFT Mastic	500	SF	Main Office, 1929 Building - Not Observed	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
68	12" x 12" Off White VFT Mastic	1,700	SF	Room # 301 & 303, 1929 Building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
69	9"x9" Burgandy w/ White Streaks VFT Mastic	0	SF	2nd and 3rd Floor Hallways, 1929 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	6"x18" Black VFT Mastic	200	SF	2nd & 3rd Fl Corridors, Auditorium, 1929 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12"x12" Green w/ White Streaks VFT Mastic NOT OBSERVED	900	SF	Rm 210 - 1929 Bldg. NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	12"x12" Beige VFT Mastic	900	SF	Rm 117 - 1929 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	9"x9" Coal Black w/ White Streaks VFT Mastic	1,500	SF	1st Fl Corridor - 1929 Bldg. - Not observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
74	9"x9" Black w/ Green & White Streaks VFT Mastic	350	SF	Rm 108 - 1929 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	Blue Linoleum Mastic	350	SF	2nd Fl Copy Rm, Room 205A - 1929 Bldg.	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
76	9"x18" Black VFT Mastic	152	SF	1st fl Corridor - 1954 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
77	9"x9" Black w/ White Streaks VFT Mastic	200	SF	1st Fl Corridor - 1957 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	9"x9" Red w/ White Streaks VFT Mastic	340	SF	1st Fl Corridor, Rm 112 & 119 (Under New Tile and Carpet), 1957 Building - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12"x12" White w/ Tan Spots VFT Mastic	1,400	SF	Rm 121, 1957 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	9"x9" White w/ Green VFT Mastic	1,350	SF	Rm 112, 212 - 1957 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	9"x9" Black VFT Mastic	25	SF	Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
82	9"x9" Red VFT Mastic	25	SF	Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
83	9"x24" Black VFT Mastic	10	SF	Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
84	9"x18" Black VFT Mastic	25	SF	Stairwell Landing, 1957 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
85	Green Table Top Linoleum NOT OBSERVED	900	SF	Rm 210 - 1929 Bldg. - Not Observed	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
86	Green Table Top Linoleum Mastic NOT OBSERVED	900	SF	Rm 210 - 1929 Bldg. - Not Observed	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
87	Aircell Pipe Insulation	0	LF	Unexcavated Area - 1957 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
88	MJP on Aircell Pipe Insulation	0	LF	Unexcavated Area - 1957 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
89	Aircell Duct Insulation	0	SF	N.W. Unexcavated Area Near Fan Rm - 1954 Bldg.	ABATED	TSI	Y	NONE			No	ACBM with the potential for damage		LOW
92	12" x 12" White w/ Light Gray Specks VFT	300	SF	Room 112 and 119, 1957 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93	12" x 12" White w/ Light Gray Specks VFT Mastic	300	SF	Room 112 and 119, 1957 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
94	12" x 12" Dark Blue w/ Blue Specks VFT	300	SF	Room 112 and 119, 1957 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
95	12" x 12" Dark Blue w/ Blue Specks VFT Mastic	300	SF	Room 112 and 119, 1957 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
96	12" x 12" Light Gray w/ Speckles VFT	100	SF	Tank Room/Storage, 1929 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97	12" x 12" Light Gray w/ Speckles VFT Mastic	100	SF	Tank Room/Storage, 1929 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	12" x 12" Black w/ White Speckles VFT	100	SF	Hall Link to 1996 Annex Lunchroom, 1929 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99	12" x 12" Black w/ White Speckles VFT Mastic	100	SF	Hall Link to 1996 Annex Lunchroom, 1929 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	MJP on Fiberglass Pipe Insulation	120	LF	Throughout Basement (Excluding Air Tunnel) (See Hatching Maps) - 1929 Bldg.	ASSUMED	TSI	Y	LOC	0		Yes	ACBM with the potential for damage		LOW
B	Aircell Pipe Insulation	200	LF	Throughout - 1929 Bldg.	CHR	TSI	Y	DIST	0		No	ACBM with the potential for damage		LOW
C	12"x12" White VFT Mastic	1,000	LF	Rm 214 (1957 Bldg) - Same as HA - 121A (Duplicated?)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
D	Cardboard Pipe Insulation	100	LF	Throughout (See Hatching Maps), 1929 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	MJP on Cardboard Pipe Insulation	100	LF	Throughout (See Hatching Maps), 1929 Bldg	CHR	TSI	Y	LOC	0		No	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
J	Condensation Tank Insulation	150	SF	Boiler Rm - 1929 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	Water Tank Insulation	140	SF	Boiler Rm, Storage Rm - 1929 Bldg.	ASSUMED	TSI	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
L	Boiler Breeching	70	LF	Boiler Rm - 1929 Bldg.	ASSUMED	TSI	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
M	Boiler Gasket	75	LF	Boiler #1 & #2 - 1929 Bldg.	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
N	Aircell Pipe Insulation	0	LF	Janitor's closet next to Rm 102, Fan Area (Supply Fan - 5), Engine Rm/Walkway 5.	CHR	TSI	Y	DIST	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Unexcavated Fan Rm										
O	MJP on Aircell Pipe Insulation	40	LF	Unexcavated Area, Fan Room, 1st Flr. Janitors Closet and Girls Toilet by Room 102, 1954 Bldg. (Per 2010 Re-inspection Girls Toilet Was Abated)	CHR	TSI	Y	DIST	0		No	ACBM with the potential for damage	3	MODERATE
P	MJP on Fiberglass Pipe Insulation	100	LF	Rm 221 - 1957 Bldg.	ASSUMED	TSI	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
Q	Cardboard Pipe Insulation	300	LF	Unexcavated Area, Fan Room, 1st Flr. Janitors Closet by Room 102, 1954 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
R	MJP on Cardboard Pipe Insulation	300	LF	Unexcavated Area, Fan Room, 1st Flr. Janitors Closet by Room 102, 1954 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/8/2022
Inspector Name Kevin Hanna
100-20525 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
07	
08	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
11	
110	
111	
112	
113	
113 A	

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
114	
114 A	
115	
116	
117	
118	
119	
12	
120	
121	
121A	
122	
122A	
123	
124	
124A	
125	
125A	
126	
126A	
127	
127A	
128	
129	
129A	
13	
130	
131	
131A	

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
132	
132A	
133	
133A	
134	
134A	
135	
136	Not observed
137	
138	
138A	
139	
139A	
14	
140	
141	
142	
143	
144	
145	
146	
147	
147A	
148	
149	
15	
18	
19	
20	

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
21	
25	
26	
27	
28	
29	
30	
31	
32	
33	
37	
38	Not observed
39	Not observed
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	

Chicago Public Schools

School Boone School Unit 22271 Building ID 2320

Address 6710 N. Washtenaw Ave. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
85	
86	
87	
88	
89	
92	
93	
94	
95	
96	
97	
98	
99	
A	
B	
C	
D	
E	
J	
K	
L	
M	
N	
O	
P	Not observed
Q	
R	

Chicago Public Schools

School Boone School **Unit** 22271 **Building ID** 2320

Address 6710 N. Washtenaw Ave. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
 Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12" x 12" Red VFT	850	SF	Auditorium & Vestibule Room (not observed), 1927 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	9"x9" Red w/ White Streaks VFT - NOT OBSERVED	1,500	SF	1st Fl Corridor - 1927 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	9"x9" Red VFT - NOT OBSERVED	330	SF	1st Fl Corridor - 1955 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" Grey Beige VFT	2,925	SF	Room 201 - 1927 Bldg. Rooms 101,102,103, 105, 202, 202A, 203, 205 - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12"x12" Light Brown VFT	1,300	SF	Rm 111, (107 not observed) and 304 - 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x9" Green w/ White Streaks VFT	325	SF	Rm 306 - 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	9"x9" Gray VFT NOT OBSERVED	1,100	SF	Rm 214 - 1957 Bldg. NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9"x9" Tan VFT	1,200	SF	Rm 119 (Under New Tile and Carpet), 219 - 1957 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	Carpet Mastic	0		Room 112 and 119, 1957 Building - Not Observed	Assumed	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
101	12" X 12" Cream w/ White Specks VFT	1,000	SF	Lunchroom, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12" X 12" Cream w/ White Specks VFT Mastic	1,000	SF	Lunchroom, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12" x 12" Gray VFT	750	SF	Lunchroom, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" Gray VFT Mastic	750	SF	Lunchroom, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" Black VFT	1,908	SF	Lunch Room and Breezeway, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12" x 12" Black VF Mastic	1,908	SF	Lunchroom and Breezeway, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	Black Linoleum	2,500	SF	Serving Area, Men and Women Lunchroom Area Bathrooms, Kitchen, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	Black Linoleum Mastic	2,500	SF	Serving Area, Men and Women Lunchroom Aea Bathrooms, Kitchen, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	Vinyl Baseboard	800	SF	Lunchroom, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Grey Speckled Linoleum NOT OBSERVED	1,600	SF	Rms 114 and 221- 1957 Bldg. - Not Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	Vinyl Baseboard Mastic	0		Lunch Room, 1996 Annex	Assumed	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
111	2' x 2' Ceiling Tile	0	SF	Serving Area, Kitchen, 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
112	2' x 2' Ceiling Tile	0		Lunchroom Hall, 1996 Annex	Assumed	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
113	12 x 12 inch Tan Mottled VFT	2,000	SF	1929 Building- 2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113 A	12 x 12 inch Tan Mottled VFT Mastic	2,000	SF	1929 Building- 2nd and 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12 x 12 inch Tan Mottled VFT	2,000	SF	1957 Building- 2nd and 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114 A	12 x 12 inch Tan Mottled VFT Mastic	2,000	SF	1957 Building- 2nd and 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	1 x 1 ft Wavy Ceiling Tile	2,500	SF	1957 Building- Rooms: 214, 221 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	2 x 4 ft Dot Wave Ceiling Tile	10,000	SF	1929 Building: Rooms 301- 304, 305 306-308,106, 109-111, 113, 114, 115, 117, 204, 206, 208-211, main office	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	2 x 4 ft Dot/Wave Ceiling Tile	3,000	SF	1957 Building: Rooms 112, 121, 207, 213, 215 219	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	Carpet Mastic	3,000	SF	1929 - Building: Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	Terrazo	3,000	SF	(Throughout) 1929 Building: Entry way, Auditorium Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9"x9" Burgandy VFT NOT OBSERVED	50	SF	Engineers Bathroom - 1929 Bldg. -NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	Terrazo	2,000	SF	(Throughout) 1954 Building: Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12"x12" White VFT NOT OBSERVED	1,000	SF	Rm 214 (1957 Bldg) - NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121A	12"x12" White VFT Mastic	1,000	SF	Rm 214 (1957 Bldg) - Not Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	Blue/White VFT	750	SF	Rms 112, 119 (1957 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122A	Blue/White VFT Mastic	750	SF	Rms 112, 119 (1957 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	Carpet Mastic	1,000	SF	Rm 221 (1957 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	12"X12" Gray VFT	1,000	SF	Rm 114 (1957 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124A	12"X12" Gray VFT Mastic	1,000	SF	Rm 114 (1957 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12"X12" White and Tan VFT	800	SF	Rm 212 (1957 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125A	12"X12" White and Tan VFT Mastic	800	SF	Rm 212 (1957 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126	12"X12" White, Gray VFT	50	SF	Engineer's Bathroom (1929 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126A	12"X12" White, Gray VFT Mastic	50	SF	Engineer's Bathroom (1929 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127	12"x12" Tan VFT	500	SF	1st Floor Corridor (1954 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127A	12"x12" Tan VFT Mastic	500	SF	1st Floor Corridor (1954 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
128	12"X12' Tan VFT	500	SF	2nd Floor Corridor. (1954 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
129	VFT 12" x 12" White with Tan & Beige Specs	1,000	SF	Room 214	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
129A	VFT Mastic 12" x 12" White with Tan & Beige Specs	1,000	SF	Room 214	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" White VFT	500	SF	Main Office - 1929 Bldg - Not Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
130	Fire doors	4	EA	Stage, Balcony and Projector Room	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
131	VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED	400	SF	Room 201 NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131A	VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED	400	SF	Room 201 NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	VFT 12" x 12" Tan with White Specs NOT OBSERVED	400	SF	Room 201 NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132A	VFT Mastic 12" x 12" Tan with White Specs	400	SF	Room 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133	VFT 12" x 12" Tan, Light Brown with White Specks	800	SF	1st Floor Corridor - (1954)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133A	VFT Mastic 12" x 12" Tan, Light Brown with White Specks	800	SF	1st Floor Corridor - (1954)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	VFT 12" x 12" Tan, Light Brown with White Specks	5,000	SF	1st Floor Corridor - (1929)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134A	VFT Mastic 12" x 12" Tan, Light Brown with White Specks	5,000	SF	1st Floor Corridor - (1929)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	Tectum Tiles	5,000	SF	Gymnasium Walls	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	Carpet Mastic	800	SF	Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	Decorative Plaster Trim	1,200	SF	Auditorium, Stage & Balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	VFT 12" x 12" Gray	120	SF	Engineer Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138A	VFT Mastic 12" x 12" Gray	120	SF	Engineer Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	VFT 12" x 12" White	120	SF	Engineer Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139A	VFT Mastic 12" x 12" White	120	SF	Engineer Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" Brown VFT	1,600	SF	Rm 301, 303 - 1929 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	2" x 2" White Ceiling Tile	720	SF	Room 720 - 1927 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	Fire Door	9	EA	Breezeway, Entry Vestibules, Kitchen (1996 Annex)	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
142	Fire Door	4	EA	Entry Vestibule - 1955 Bldg.	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
143	Sink Undercoating	6	EA	219, 212, 214, 119, 112 - 1955 Bldg.	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
144	Sink Undercoating	3	EA	Room 210 - 1927 Bldg.	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
145	Vinyl Baseboard Mastic	2,800	SF	Rooms 121,114, 119, 112 - 1955 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	Drywall System (Drywall, Tape, Compound)	3,000	SF	Bridgeway, Kitchen - 1996 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
147	12" x 12" White w/ Tan specks VFT	905	SF	Room 210 - 1927 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147A	12" x 12" White w/ Tan specks VFT mastic	905	SF	Room 210 - 1927 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	Drywall System (Drywall, Tape, Compound)	1,500	SF	Rooms 110, 115 - 1927 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149	Drywall System (Drywall, Tape, Compound)	1,500	SF	Rooms 114, 121, 112, 119 (Toilets) - 1955 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Hard Coat Plaster	15,000	SF	Throughout - 1929 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9"x9" Red w/ Black Streaks VFT Mastic	1,500	SF	1st FI Corridor - 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Red Black VFT Mastic	850	SF	Auditorium, 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Grey Speckled Linoleum Mastic	1,600	SF	Rm 1957 Bldg. - Not Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Hard Coat Plaster	7,000	SF	Throughout - 1954 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Vibration Dampening Cloth	40	SF	Attic - 1954 Bldg.	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12"x12" Black VFT	850	SF	Auditorium 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	9"x9" Black w/ White Streaks VFT	0	SF	2nd & 3rd FI Corridors - 1929 Bldg - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	9"x9" Black VFT Not Observed	0	SF	1st & 2nd FI Corridor - 1954 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" Green VFT	2,925	SF	Rm 101-103, 105, 201, 202, 202A, 203, 205 - 1927 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	9"x9" White w/ Green Streaks VFT	325	SF	Rm 306 - 1929 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" Brown w/ Tan Streaks VFT	500	SF	Main Office (Wood) - 1929 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Off White VFT	1,600	SF	Rm 301, 303 - 1929 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Hard Coat Plaster	0	SF	Throughout - 1957 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9"x9" Burgandy w/ White Streaks VFT	0	SF	2nd & 3rd FI Hallways - 1929 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	6"x18" Black VFT	0	SF	2nd & 3rd FI Corridors, Auditorium, 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12"x12" Green w/ White Streaks VFT	900	SF	Rm 210 - 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12"x12" Beige VFT	900	SF	Rm 117 - 1929	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	9"x9" Coal Black w/ White Streaks VFT	1,500	SF	1st FI Corridor - 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	9"x9" Black w/ Green & White Streaks VFT	350	SF	Rm 108 - 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Blue Linoleum	350	SF	2nd FI Copy Rm (206A) - 1929 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	9"x18" Black VFT	152	SF	1st fl Corridor - 1954 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	9"x9" Black w/ White Streaks VFT	200	SF	1st FI Corridor - 1957 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
46	9"x9" Red w/ White Streaks VFT	340	SF	1st Fl Corridor, Rm 112 & 119 (Under New Tile and Carpet), 1957 Building - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12"x12" White w/ Tan Spots VFT	900	SF	Rm 121, 1957 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	9"x9" White w/ Green VFT	1,350	SF	Rm 112, 212 - 1957 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	9"x9" Black VFT	25	SF	Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	9"x9" Red VFT	25	SF	Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	9"x24" Black VFT NOT OBSERVED	10	SF	Stairwell Landing Between 1st and 2nd Floor - 1957 Bldg - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	9"x18" Black VFT NOT OBSERVED	25	SF	Stairwell Landing, 1957 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	9"x9" Red VFT	330	SF	1st fl Corridor - 1954 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12"x12" Grey VFT Mastic	2,925	SF	Rm 101-103, 105, 201, 202, 202A, 203, 205 - 1927 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12"x12" Light Brown VFT Mastic	1,300	SF	Rm 111, 304 - 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	9"x9" Green w/ White Streaks VFT Mastic	325	SF	Rm 306 - 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	9"x9" Grey VFT Mastic	1,100	SF	Rm 214 - 1957 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	9"x9" Tan VFT Mastic	1,200	SF	Rm 119 (Under New Tile and Carpet), 219 - 1957 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	9"x9" Burgandy VFT Mastic NOT OBSERVED	50	SF	Engineers Office Bathroom - 1929 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12"x12" White VFT Mastic	500	SF	Main Office - 1929 Bldg. - Not Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12"x12" Brown VFT Mastic	1,700	SF	Rm 301, 303 - 1929 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12"x12" Black VFT Mastic	850	SF	Auditorium - 1929 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	9"x9" Black w/ White Streaks VFT Mastic NOT OBSERVED	0	SF	2nd & 3rd Fl Corridor - 1929 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	9"x9" Black VFT Mastic	0	SF	1st & 2nd Fl Corridor - 1954 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12"x12' Green VFT Mastic	2,925	SF	Rm 101, 102, 103, 105, 201, 202, 202A, 203, 205 - 1954 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	9"x9" White w/ Green Streaks VFT Mastic	325	SF	Rm 306 - 1929	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
67	12" x 12" Brown w/ Tan Streaks VFT Mastic	500	SF	Main Office, 1929 Building - Not Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Off White VFT Mastic	1,700	SF	Room # 301 & 303, 1929 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	9"x9" Burgandy w/ White Streaks VFT Mastic	0	SF	2nd and 3rd Floor Hallways, 1929 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	6"x18" Black VFT Mastic	200	SF	2nd & 3rd FI Corridors, Auditorium, 1929 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12"x12" Green w/ White Streaks VFT Mastic NOT OBSERVED	900	SF	Rm 210 - 1929 Bldg. NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12"x12" Beige VFT Mastic	900	SF	Rm 117 - 1929 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	9"x9" Coal Black w/ White Streaks VFT Mastic	1,500	SF	1st FI Corridor - 1929 Bldg. - Not observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	9"x9" Black w/ Green & White Streaks VFT Mastic	350	SF	Rm 108 - 1929 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Blue Linoleum Mastic	350	SF	2nd FI Copy Rm, Room 205A - 1929 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	9"x18" Black VFT Mastic	152	SF	1st fl Corridor - 1954 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	9"x9" Black w/ White Streaks VFT Mastic	200	SF	1st FI Corridor - 1957 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	9"x9" Red w/ White Streaks VFT Mastic	340	SF	1st FI Corridor, Rm 112 & 119 (Under New Tile and Carpet), 1957 Building - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12"x12" White w/ Tan Spots VFT Mastic	1,400	SF	Rm 121, 1957 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	9"x9" White w/ Green VFT Mastic	1,350	SF	Rm 112, 212 - 1957 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	9"x9" Black VFT Mastic	25	SF	Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	9"x9" Red VFT Mastic	25	SF	Stairwell Landing Between 1st and 2nd Flrr - 1957 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	9"x24" Black VFT Mastic	10	SF	Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	9"x18" Black VFT Mastic	25	SF	Stairwell Landing, 1957 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Green Table Top Linoleum NOT OBSERVED	900	SF	Rm 210 - 1929 Bldg. - Not Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	Green Table Top Linoleum Mastic NOT OBSERVED	900	SF	Rm 210 - 1929 Bldg. - Not Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Aircell Pipe Insulation	0	LF	Unexcavated Area - 1957 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
88	MJP on Aircell Pipe Insulation	0	LF	Unexcavated Area - 1957 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
89	Aircell Duct Insulation	0	SF	N.W. Unexcavated Area Near Fan Rm - 1954 Bldg.	Abated	TSI	Yes		SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" x 12" White w/ Light Gray Specks VFT	300	SF	Room 112 and 119, 1957 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12" x 12" White w/ Light Gray Specks VFT Mastic	300	SF	Room 112 and 119, 1957 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Dark Blue w/ Blue Specks VFT	300	SF	Room 112 and 119, 1957 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
95	12" x 12" Dark Blue w/ Blue Specks VFT Mastic	300	SF	Room 112 and 119, 1957 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	12" x 12" Light Gray w/ Speckles VFT	100	SF	Tank Room/Storage, 1929 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	12" x 12" Light Gray w/ Speckles VFT Mastic	100	SF	Tank Room/Storage, 1929 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	12" x 12" Black w/ White Speckles VFT	100	SF	Hall Link to 1996 Annex Lunchroom, 1929 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12" x 12" Black w/ White Speckles VFT Mastic	100	SF	Hall Link to 1996 Annex Lunchroom, 1929 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	MJP on Fiberglass Pipe Insulation	120	LF	Throughout Basement (Excluding Air Tunnel) (See Hatching Maps) - 1929 Bldg.	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Aircell Pipe Insulation	200	LF	Throughout - 1929 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
C	12"x12" White VFT Mastic	1,000	LF	Rm 214 (1957 Bldg) - Same as HA - 121A (Duplicated?)	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	Cardboard Pipe Insulation	100	LF	Throughout (See Hatching Maps), 1929 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	MJP on Cardboard Pipe Insulation	100	LF	Throughout (See Hatching Maps), 1929 Bldg	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
J	Condensation Tank Insulation	150	SF	Boiler Rm - 1929 Bldg.	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	Water Tank Insulation	140	SF	Boiler Rm, Storage Rm - 1929 Bldg.	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	Boiler Breeching	70	LF	Boiler Rm - 1929 Bldg.	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
M	Boiler Gasket	75	LF	Boiler #1 & #2 - 1929 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
N	Aircell Pipe Insulation	0	LF	Janitor's closet next to Rm 102, Fan Area (Supply Fan - 5), Engine Rm/Walkway 5, Unexcavated Fan Rm	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
O	MJP on Aircell Pipe Insulation	40	LF	Unexcavated Area, Fan Room, 1st Flr. Janitors Closet and Girls Toilet by Room 102, 1954 Bldg. (Per 2010 Re-inspection Girls Toilet Was Abated)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
P	MJP on Fiberglass Pipe Insulation	100	LF	Rm 221 - 1957 Bldg.	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Q	Cardboard Pipe Insulation	300	LF	Unexcavated Area, Fan Room, 1st Flr.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
 Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Janitors Closet by Room 102, 1954 Bldg.							
R	MJP on Cardboard Pipe Insulation	300	LF	Unexcavated Area, Fan Room, 1st Flr. Janitors Closet by Room 102, 1954 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Review Date 10/7/2022

HA Number	Management Comments
-----------	---------------------

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
 Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Manager Planner Name	Jigar Shah
100-07342	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
07	
08	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
11	
110	
111	
112	
113	
113 A	
114	
114 A	
115	

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
116	
117	
118	
119	
12	
120	
121	
121A	
122	
122A	
123	
124	
124A	
125	
125A	
126	
126A	
127	
127A	
128	
129	
129A	
13	
130	
131	
131A	
132	

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
 Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
132A	
133	
133A	
134	
134A	
135	
136	
137	
138	
138A	
139	
139A	
14	
140	
141	
142	
143	
144	
145	
146	
147	
147A	
148	
149	
15	
18	
19	

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
20	
21	
25	
26	
27	
28	
29	
30	
31	
32	
33	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
 Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
92	
93	
94	
95	
96	
97	
98	
99	
A	
B	
C	
D	
E	
J	
K	
L	
M	

Chicago Public Schools

School Boone School
Address 6710 N. Washtenaw Ave.

Unit 22271
Chicago, IL, 60645

Building ID 2320
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
N	0
O	
P	
Q	
R	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12" x 12" Red VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium & Vestibule Room (not observed), 1927 Bldg.**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12" x 12" Red VFT**
MATERIAL LOCATION: **Auditorium & Vestibule Room (not observed), 1927 Bldg.**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Fl Corridor - 1927 Bldg. - Not Observed**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT - NOT OBSERVED**
MATERIAL LOCATION: **1st Fl Corridor - 1927 Bldg. - Not Observed**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Red VFT - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Fl Corridor - 1955 Bldg. - Not Observed**
MATERIAL QUANTITY: **330** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Red VFT - NOT OBSERVED**
MATERIAL LOCATION: **1st Fl Corridor - 1955 Bldg. - Not Observed**
MATERIAL QUANTITY: **330** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" Grey Beige VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 201 - 1927 Bldg.
Rooms 101,102,103, 105, 202, 202A, 203, 205 - Not Observed**

MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" Grey Beige VFT**
MATERIAL LOCATION: **Room 201 - 1927 Bldg.
Rooms 101,102,103, 105, 202, 202A, 203, 205 - Not Observed**
MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" Light Brown VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 111, (107 not observed) and 304 - 1929 Bldg.**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" Light Brown VFT**
MATERIAL LOCATION: **Rm 111, (107 not observed) and 304 - 1929 Bldg.**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 306 - 1929 Bldg.**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**
MATERIAL LOCATION: **Rm 306 - 1929 Bldg.**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"X9" Gray VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 214 - 1957 Bldg. NOT OBSERVED**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"X9" Gray VFT NOT OBSERVED**
MATERIAL LOCATION: **Rm 214 - 1957 Bldg. NOT OBSERVED**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9"x9" Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 119 (Under New Tile and Carpet), 219 - 1957 Bldg. - NOT OBSERVED**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9"x9" Tan VFT**
MATERIAL LOCATION: **Rm 119 (Under New Tile and Carpet), 219 - 1957 Bldg. - NOT OBSERVED**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112 and 119, 1957 Building - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Room 112 and 119, 1957 Building - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12" X 12" Cream w/ White Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, 1996 Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12" X 12" Cream w/ White Specks VFT**
MATERIAL LOCATION: **Lunchroom, 1996 Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12" X 12" Cream w/ White Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, 1996 Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12" X 12" Cream w/ White Specks VFT Mastic**
MATERIAL LOCATION: **Lunchroom, 1996 Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **12" x 12" Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom, 1996 Annex**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **12" x 12" Gray VFT**
MATERIAL LOCATION: **Lunchroom, 1996 Annex**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12" x 12" Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, 1996 Annex**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12" x 12" Gray VFT Mastic**
MATERIAL LOCATION: **Lunchroom, 1996 Annex**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Lunch Room and Breezeway, 1996 Annex**
MATERIAL QUANTITY: **1908** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" Black VFT**
MATERIAL LOCATION: **Lunch Room and Breezeway, 1996 Annex**
MATERIAL QUANTITY: **1908** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12" x 12" Black VF Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom and Breezeway, 1996 Annex**

MATERIAL QUANTITY: **1908**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12" x 12" Black VF Mastic**
MATERIAL LOCATION: **Lunchroom and Breezeway, 1996 Annex**
MATERIAL QUANTITY: **1908** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Black Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Serving Area, Men and Women Lunchroom Area Bathrooms, Kitchen, 1996 Annex**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Black Linoleum**
MATERIAL LOCATION: **Serving Area, Men and Women Lunchroom Area Bathrooms, Kitchen, 1996 Annex**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **Black Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Serving Area, Men and Women Lunchroom Aea Bathrooms, Kitchen, 1996 Annex**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **Black Linoleum Mastic**
MATERIAL LOCATION: **Serving Area, Men and Women Lunchroom Aea Bathrooms, Kitchen, 1996 Annex**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, 1996 Annex**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **Vinyl Baseboard**
MATERIAL LOCATION: **Lunchroom, 1996 Annex**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Grey Speckled Linoleum NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 114 and 221- 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Grey Speckled Linoleum NOT OBSERVED**
MATERIAL LOCATION: **Rms 114 and 221- 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room, 1996 Annex**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Lunch Room, 1996 Annex**
MATERIAL QUANTITY: **0** MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Serving Area, Kitchen, 1996 Annex**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**
MATERIAL LOCATION: **Serving Area, Kitchen, 1996 Annex**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom Hall, 1996 Annex**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**
MATERIAL LOCATION: **Lunchroom Hall, 1996 Annex**
MATERIAL QUANTITY: **0** MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12 x 12 inch Tan Mottled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1929 Building- 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12 x 12 inch Tan Mottled VFT**
MATERIAL LOCATION: **1929 Building- 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113 A**
MATERIAL DESCRIPTION: **12 x 12 inch Tan Mottled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1929 Building- 2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **113 A**
MATERIAL DESCRIPTION: **12 x 12 inch Tan Mottled VFT Mastic**
MATERIAL LOCATION: **1929 Building- 2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12 x 12 inch Tan Mottled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1957 Building- 2nd and 3rd Floor Corridor**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12 x 12 inch Tan Mottled VFT**
MATERIAL LOCATION: **1957 Building- 2nd and 3rd Floor Corridor**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114 A**
MATERIAL DESCRIPTION: **12 x 12 inch Tan Mottled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1957 Building- 2nd and 3rd Floor Corridor**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **114 A**
MATERIAL DESCRIPTION: **12 x 12 inch Tan Mottled VFT Mastic**
MATERIAL LOCATION: **1957 Building- 2nd and 3rd Floor Corridor**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **1 x 1 ft Wavy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1957 Building- Rooms: 214, 221 (Library)**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **1 x 1 ft Wavy Ceiling Tile**
MATERIAL LOCATION: **1957 Building- Rooms: 214, 221 (Library)**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **2 x 4 ft Dot Wave Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1929 Building: Rooms 301- 304, 305 306-308,106, 109-111, 113, 114, 115, 117, 204, 206, 208-211, main office**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **2 x 4 ft Dot Wave Ceiling Tile**
MATERIAL LOCATION: **1929 Building: Rooms 301- 304, 305 306-308,106, 109-111, 113, 114, 115, 117, 204, 206, 208-211, main office**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **2 x 4 ft Dot/Wave Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1957 Building: Rooms 112, 121, 207, 213, 215 219**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **2 x 4 ft Dot/Wave Ceiling Tile**
MATERIAL LOCATION: **1957 Building: Rooms 112, 121, 207, 213, 215 219**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1929 - Building: Auditorium**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **1929 - Building: Auditorium**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Terrazo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **(Throughout) 1929 Building: Entry way, Auditorium Stage**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Terrazo**
MATERIAL LOCATION: **(Throughout) 1929 Building: Entry way, Auditorium Stage**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9"x9" Burgandy VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineers Bathroom - 1929 Bldg. -NOT OBSERVED**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9"x9" Burgandy VFT NOT OBSERVED**
MATERIAL LOCATION: **Engineers Bathroom - 1929 Bldg. -NOT OBSERVED**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **Terrazo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **(Throughout) 1954 Building: Stairwells**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **Terrazo**
MATERIAL LOCATION: **(Throughout) 1954 Building: Stairwells**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **12"x12" White VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 214 (1957 Bldg) - NOT OBSERVED**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **12"x12" White VFT NOT OBSERVED**
MATERIAL LOCATION: **Rm 214 (1957 Bldg) - NOT OBSERVED**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121A**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 214 (1957 Bldg) - Not Observed**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **121A**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**
MATERIAL LOCATION: **Rm 214 (1957 Bldg) - Not Observed**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Blue/White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 112, 119 (1957 Bldg)**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Blue/White VFT**
MATERIAL LOCATION: **Rms 112, 119 (1957 Bldg)**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122A**
MATERIAL DESCRIPTION: **Blue/White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 112, 119 (1957 Bldg)**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **122A**
MATERIAL DESCRIPTION: **Blue/White VFT Mastic**
MATERIAL LOCATION: **Rms 112, 119 (1957 Bldg)**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 221 (1957 Bldg)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Rm 221 (1957 Bldg)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **12'X12" Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 114 (1957 Bldg)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **12'X12" Gray VFT**
MATERIAL LOCATION: **Rm 114 (1957 Bldg)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124A**
MATERIAL DESCRIPTION: **12'X12" Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 114 (1957 Bldg)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **124A**
MATERIAL DESCRIPTION: **12'X12" Gray VFT Mastic**
MATERIAL LOCATION: **Rm 114 (1957 Bldg)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **12"X12" White and Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 212 (1957 Bldg)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **12"X12" White and Tan VFT**
MATERIAL LOCATION: **Rm 212 (1957 Bldg)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125A**
MATERIAL DESCRIPTION: **12"X12" White and Tan VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 212 (1957 Bldg)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **125A**
MATERIAL DESCRIPTION: **12"X12" White and Tan VFT Mastic**
MATERIAL LOCATION: **Rm 212 (1957 Bldg)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12"X12" White, Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Engineer's Bathroom (1929 Bldg)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12"X12" White, Gray VFT**
MATERIAL LOCATION: **Engineer's Bathroom (1929 Bldg)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126A**
MATERIAL DESCRIPTION: **12"X12" White, Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Engineer's Bathroom (1929 Bldg)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **126A**
MATERIAL DESCRIPTION: **12"X12" White, Gray VFT Mastic**
MATERIAL LOCATION: **Engineer's Bathroom (1929 Bldg)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **12"x12" Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor (1954 Bldg)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **12"x12" Tan VFT**
MATERIAL LOCATION: **1st Floor Corridor (1954 Bldg)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127A**
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor (1954 Bldg)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **127A**
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor (1954 Bldg)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **12"X12' Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd Floor Corridor (1954 Bldg)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **12"X12' Tan VFT**
MATERIAL LOCATION: **2nd Floor Corridor (1954 Bldg)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **VFT 12" x 12" White with Tan & Beige Specs**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 214**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **VFT 12" x 12" White with Tan & Beige Specs**
MATERIAL LOCATION: **Room 214**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" White with Tan & Beige Specs**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 214**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **129A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" White with Tan & Beige Specs**
MATERIAL LOCATION: **Room 214**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12"x12" White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office - 1929 Bldg - Not Observed**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12"x12" White VFT**
MATERIAL LOCATION: **Main Office - 1929 Bldg - Not Observed**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **Fire doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stage, Balcony and Projector Room**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **Fire doors**
MATERIAL LOCATION: **Stage, Balcony and Projector Room**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 201 NOT OBSERVED**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED**
MATERIAL LOCATION: **Room 201 NOT OBSERVED**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131A**
MATERIAL DESCRIPTION: **VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 201 NOT OBSERVED**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **131A**
MATERIAL DESCRIPTION: **VFT 12" x 12" Light Brown with Tan Brown Specs NOT OBSERVED**
MATERIAL LOCATION: **Room 201 NOT OBSERVED**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **VFT 12" x 12" Tan with White Specs NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 201 NOT OBSERVED**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **VFT 12" x 12" Tan with White Specs NOT OBSERVED**
MATERIAL LOCATION: **Room 201 NOT OBSERVED**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" Tan with White Specs**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **132A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" Tan with White Specs**
MATERIAL LOCATION: **Room 201**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **VFT 12" x 12" Tan, Light Brown with White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor - (1954)**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **VFT 12" x 12" Tan, Light Brown with White Specks**
MATERIAL LOCATION: **1st Floor Corridor - (1954)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" Tan, Light Brown with White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor - (1954)**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **133A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" Tan, Light Brown with White Specks**
MATERIAL LOCATION: **1st Floor Corridor - (1954)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **VFT 12" x 12" Tan, Light Brown with White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor - (1929)**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **VFT 12" x 12" Tan, Light Brown with White Specks**
MATERIAL LOCATION: **1st Floor Corridor - (1929)**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" Tan, Light Brown with White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor - (1929)**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **134A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" Tan, Light Brown with White Specks**
MATERIAL LOCATION: **1st Floor Corridor - (1929)**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **Tectum Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gymnasium Walls**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **Tectum Tiles**
MATERIAL LOCATION: **Gymnasium Walls**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 110**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Room 110**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **Decorative Plaster Trim**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, Stage & Balcony**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **Decorative Plaster Trim**
MATERIAL LOCATION: **Auditorium, Stage & Balcony**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **VFT 12" x 12" Gray**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **VFT 12" x 12" Gray**
MATERIAL LOCATION: **Engineer Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" Gray**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **138A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" Gray**
MATERIAL LOCATION: **Engineer Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **VFT 12" x 12" White**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer Office**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **VFT 12" x 12" White**
MATERIAL LOCATION: **Engineer Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" White**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **139A**
MATERIAL DESCRIPTION: **VFT Mastic 12" x 12" White**
MATERIAL LOCATION: **Engineer Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" Brown VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 301, 303 - 1929 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" Brown VFT**
MATERIAL LOCATION: **Rm 301, 303 - 1929 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **2" x 2" White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 720 - 1927 Bldg.**
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **2" x 2" White Ceiling Tile**
MATERIAL LOCATION: **Room 720 - 1927 Bldg.**
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **Fire Door**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Breezway, Entry Vestibules, Kitchen (1996 Annex)**
MATERIAL QUANTITY: **9** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **Fire Door**
MATERIAL LOCATION: **Breezway, Entry Vestibules, Kitchen (1996 Annex)**
MATERIAL QUANTITY: **9** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **Fire Door**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entry Vestibule - 1955 Bldg.**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **Fire Door**
MATERIAL LOCATION: **Entry Vestibule - 1955 Bldg.**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **Sink Undercoating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **219, 212, 214, 119, 112 - 1955 Bldg.**

MATERIAL QUANTITY: **6**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **Sink Undercoating**
MATERIAL LOCATION: **219, 212, 214, 119, 112 - 1955 Bldg.**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **Sink Undercoating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 210 - 1927 Bldg.**

MATERIAL QUANTITY: **3**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **Sink Undercoating**
MATERIAL LOCATION: **Room 210 - 1927 Bldg.**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 121,114, 119, 112 - 1955 Bldg.**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Rooms 121,114, 119, 112 - 1955 Bldg.**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **Drywall System (Drywall, Tape, Compound)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Bridgeway, Kitchen - 1996 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **Drywall System (Drywall, Tape, Compound)**
MATERIAL LOCATION: **Bridgeway, Kitchen - 1996 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 210 - 1927 Bldg.**
MATERIAL QUANTITY: **905** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan specks VFT**
MATERIAL LOCATION: **Room 210 - 1927 Bldg.**
MATERIAL QUANTITY: **905** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147A**
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan specks VFT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 210 - 1927 Bldg.**

MATERIAL QUANTITY: **905**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **147A**
MATERIAL DESCRIPTION: **12" x 12" White w/ Tan specks VFT mastic**
MATERIAL LOCATION: **Room 210 - 1927 Bldg.**
MATERIAL QUANTITY: **905** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **Drywall System (Drywall, Tape, Compound)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 110, 115 - 1927 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **Drywall System (Drywall, Tape, Compound)**
MATERIAL LOCATION: **Rooms 110, 115 - 1927 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **Drywall System (Drywall, Tape, Compound)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114, 121, 112, 119 (Toilets) - 1955 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **Drywall System (Drywall, Tape, Compound)**
MATERIAL LOCATION: **Rooms 114, 121, 112, 119 (Toilets) - 1955 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1929 Bldg.**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout - 1929 Bldg.**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x9" Red w/ Black Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Fl Corridor - 1929 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x9" Red w/ Black Streaks VFT Mastic**
MATERIAL LOCATION: **1st Fl Corridor - 1929 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Red Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, 1929 Bldg.**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Red Black VFT Mastic**
MATERIAL LOCATION: **Auditorium, 1929 Bldg.**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Grey Speckled Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Grey Speckled Linoleum Mastic**
MATERIAL LOCATION: **Rm 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1954 Bldg**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout - 1954 Bldg**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Vibration Dampening Cloth**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Attic - 1954 Bldg.**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Vibration Dampening Cloth**
MATERIAL LOCATION: **Attic - 1954 Bldg.**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12"x12" Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium 1929 Bldg.**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12"x12" Black VFT**
MATERIAL LOCATION: **Auditorium 1929 Bldg.**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd FI Corridors - 1929 Bldg - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT**
MATERIAL LOCATION: **2nd & 3rd FI Corridors - 1929 Bldg - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9"x9" Black VFT Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd FI Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9"x9" Black VFT Not Observed**
MATERIAL LOCATION: **1st & 2nd Fl Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12"x12" Green VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 101-103, 105, 201, 202, 202A, 203, 205 - 1927 Bldg.**
MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12"x12" Green VFT**
MATERIAL LOCATION: **Rm 101-103, 105, 201, 202, 202A, 203, 205 - 1927 Bldg.**
MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9"x9" White w/ Green Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 306 - 1929 Bldg**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9"x9" White w/ Green Streaks VFT**
MATERIAL LOCATION: **Rm 306 - 1929 Bldg**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" Brown w/ Tan Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office (Wood) - 1929 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" Brown w/ Tan Streaks VFT**
MATERIAL LOCATION: **Main Office (Wood) - 1929 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"x12" Off White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 301, 303 - 1929 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"x12" Off White VFT**
MATERIAL LOCATION: **Rm 301, 303 - 1929 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1957 Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout - 1957 Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **9"x9" Burgandy w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd FI Hallways - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **9"x9" Burgandy w/ White Streaks VFT**
MATERIAL LOCATION: **2nd & 3rd FI Hallways - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **6"x18" Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd FI Corridors, Auditorium, 1929 Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **6"x18" Black VFT**
MATERIAL LOCATION: **2nd & 3rd FI Corridors, Auditorium, 1929 Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 210 - 1929 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks VFT**
MATERIAL LOCATION: **Rm 210 - 1929 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"x12" Beige VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 117 - 1929**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"x12" Beige VFT**
MATERIAL LOCATION: **Rm 117 - 1929**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9"x9" Coal Black w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Fl Corridor - 1929 Bldg.**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9"x9" Coal Black w/ White Streaks VFT**
MATERIAL LOCATION: **1st Fl Corridor - 1929 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **9"x9" Black w/ Green & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 108 - 1929 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **9"x9" Black w/ Green & White Streaks VFT**
MATERIAL LOCATION: **Rm 108 - 1929 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Blue Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd FI Copy Rm (206A) - 1929 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Blue Linoleum**
MATERIAL LOCATION: **2nd Fl Copy Rm (206A) - 1929 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **9"x18" Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **152** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **9"x18" Black VFT**
MATERIAL LOCATION: **1st fl Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **152** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Fl Corridor - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT**
MATERIAL LOCATION: **1st Fl Corridor - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st Fl Corridor, Rm 112 & 119 (Under New Tile and Carpet), 1957 Building - Not Observed**

MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT**
MATERIAL LOCATION: **1st Fl Corridor, Rm 112 & 119 (Under New Tile and Carpet), 1957 Building - Not Observed**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 121, 1957 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT**
MATERIAL LOCATION: **Rm 121, 1957 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **9"x9" White w/ Green VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 112, 212 - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **9"x9" White w/ Green VFT**
MATERIAL LOCATION: **Rm 112, 212 - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **9"x9" Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **9"x9" Black VFT**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **9"x9" Red VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **9"x9" Red VFT**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9"x24" Black VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Floor - 1957 Bldg - NOT OBSERVED**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9"x24" Black VFT NOT OBSERVED**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Floor - 1957 Bldg - NOT OBSERVED**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **9"x18" Black VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairwell Landing, 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **9"x18" Black VFT NOT OBSERVED**
MATERIAL LOCATION: **Stairwell Landing, 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **9"x9" Red VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **330** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **9"x9" Red VFT**
MATERIAL LOCATION: **1st fl Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **330** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12"x12" Grey VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 101-103, 105, 201, 202, 202A, 203, 205 - 1927 Bldg.**
MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12"x12" Grey VFT Mastic**
MATERIAL LOCATION: **Rm 101-103, 105, 201, 202, 202A, 203, 205 - 1927 Bldg.**
MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x12" Light Brown VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 111, 304 - 1929 Bldg.**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x12" Light Brown VFT Mastic**
MATERIAL LOCATION: **Rm 111, 304 - 1929 Bldg.**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 306 - 1929 Bldg.**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Rm 306 - 1929 Bldg.**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **9"x9" Grey VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 214 - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **9"x9" Grey VFT Mastic**
MATERIAL LOCATION: **Rm 214 - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 119 (Under New Tile and Carpet), 219 - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic**
MATERIAL LOCATION: **Rm 119 (Under New Tile and Carpet), 219 - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **9"x9" Burgandy VFT Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineers Office Bathroom - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **9"x9" Burgandy VFT Mastic NOT OBSERVED**
MATERIAL LOCATION: **Engineers Office Bathroom - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**
MATERIAL LOCATION: **Main Office - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 301, 303 - 1929 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic**
MATERIAL LOCATION: **Rm 301, 303 - 1929 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12"x12" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium - 1929 Bldg**

MATERIAL QUANTITY: **850**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12"x12" Black VFT Mastic**
MATERIAL LOCATION: **Auditorium - 1929 Bldg**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd FI Corridor - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic NOT OBSERVED**
MATERIAL LOCATION: **2nd & 3rd FI Corridor - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd FI Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**
MATERIAL LOCATION: **1st & 2nd Fl Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12"x12' Green VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 101, 102, 103, 105, 201, 202, 202A, 203, 205 - 1954 Bldg.**
MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12"x12' Green VFT Mastic**
MATERIAL LOCATION: **Rm 101, 102, 103, 105, 201, 202, 202A, 203, 205 - 1954 Bldg.**
MATERIAL QUANTITY: **2925** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9"x9" White w/ Green Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 306 - 1929**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9"x9" White w/ Green Streaks VFT Mastic**
MATERIAL LOCATION: **Rm 306 - 1929**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Tan Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office, 1929 Building - Not Observed**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Tan Streaks VFT Mastic**
MATERIAL LOCATION: **Main Office, 1929 Building - Not Observed**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Off White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room # 301 & 303, 1929 Building**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Off White VFT Mastic**
MATERIAL LOCATION: **Room # 301 & 303, 1929 Building**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **9"x9" Burgandy w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd and 3rd Floor Hallways, 1929 Bldg. - Not Observed**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **9"x9" Burgandy w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **2nd and 3rd Floor Hallways, 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **6"x18" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd FI Corridors, Auditorium, 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **6"x18" Black VFT Mastic**
MATERIAL LOCATION: **2nd & 3rd FI Corridors, Auditorium, 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks VFT Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 210 - 1929 Bldg. NOT OBSERVED**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks VFT Mastic NOT OBSERVED**
MATERIAL LOCATION: **Rm 210 - 1929 Bldg. NOT OBSERVED**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 117 - 1929 Bldg**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic**
MATERIAL LOCATION: **Rm 117 - 1929 Bldg**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9"x9" Coal Black w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Fl Corridor - 1929 Bldg. - Not observed**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9"x9" Coal Black w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **1st Fl Corridor - 1929 Bldg. - Not observed**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **9"x9" Black w/ Green & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 108 - 1929 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **9"x9" Black w/ Green & White Streaks VFT Mastic**
MATERIAL LOCATION: **Rm 108 - 1929 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd FI Copy Rm, Room 205A - 1929 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
MATERIAL LOCATION: **2nd Fl Copy Rm, Room 205A - 1929 Bldg.**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **9"x18" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **152** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **9"x18" Black VFT Mastic**
MATERIAL LOCATION: **1st fl Corridor - 1954 Bldg. - Not Observed**
MATERIAL QUANTITY: **152** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **9'x9" Black w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Fl Corridor - 1957 Bldg. - Not Observed**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **9'x9" Black w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **1st Fl Corridor - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Fl Corridor, Rm 112 & 119 (Under New Tile and Carpet), 1957 Building - Not Observed**

MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **1st Fl Corridor, Rm 112 & 119 (Under New Tile and Carpet), 1957 Building - Not Observed**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 121, 1957 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT Mastic**
MATERIAL LOCATION: **Rm 121, 1957 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **9"x9" White w/ Green VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 112, 212 - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **9"x9" White w/ Green VFT Mastic**
MATERIAL LOCATION: **Rm 112, 212 - 1957 Bldg. - Not Observed**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg.**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg.**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **9"x9" Red VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flrr - 1957 Bldg.**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **9"x9" Red VFT Mastic**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flrr - 1957 Bldg.**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **9"x24" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **9"x24" Black VFT Mastic**
MATERIAL LOCATION: **Stairwell Landing Between 1st and 2nd Flr - 1957 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **9"x18" Black VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Stairwell Landing, 1957 Bldg.**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **9"x18" Black VFT Mastic**
MATERIAL LOCATION: **Stairwell Landing, 1957 Bldg.**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **Green Table Top Linoleum NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 210 - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **Green Table Top Linoleum NOT OBSERVED**
MATERIAL LOCATION: **Rm 210 - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **Green Table Top Linoleum Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 210 - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **Green Table Top Linoleum Mastic NOT OBSERVED**
MATERIAL LOCATION: **Rm 210 - 1929 Bldg. - Not Observed**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Unexcavated Area - 1957 Bldg.**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Unexcavated Area - 1957 Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Unexcavated Area - 1957 Bldg.**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**
MATERIAL LOCATION: **Unexcavated Area - 1957 Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **N.W. Unexcavated Area Near Fan Rm - 1954 Bldg.**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
MATERIAL LOCATION: **N.W. Unexcavated Area Near Fan Rm - 1954 Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Gray Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112 and 119, 1957 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Gray Specks VFT**
MATERIAL LOCATION: **Room 112 and 119, 1957 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Gray Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112 and 119, 1957 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Gray Specks VFT Mastic**
MATERIAL LOCATION: **Room 112 and 119, 1957 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue w/ Blue Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 112 and 119, 1957 Building**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue w/ Blue Specks VFT**
MATERIAL LOCATION: **Room 112 and 119, 1957 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue w/ Blue Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112 and 119, 1957 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue w/ Blue Specks VFT Mastic**
MATERIAL LOCATION: **Room 112 and 119, 1957 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Tank Room/Storage, 1929 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Speckles VFT**
MATERIAL LOCATION: **Tank Room/Storage, 1929 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Tank Room/Storage, 1929 Building**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Speckles VFT Mastic**
MATERIAL LOCATION: **Tank Room/Storage, 1929 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hall Link to 1996 Annex Lunchroom, 1929 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT**
MATERIAL LOCATION: **Hall Link to 1996 Annex Lunchroom, 1929 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hall Link to 1996 Annex Lunchroom, 1929 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Speckles VFT Mastic**
MATERIAL LOCATION: **Hall Link to 1996 Annex Lunchroom, 1929 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Basement (Excluding Air Tunnel) (See Hatching Maps) - 1929 Bldg.**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Throughout Basement (Excluding Air Tunnel) (See Hatching Maps) - 1929 Bldg.**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout - 1929 Bldg.**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout - 1929 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 214 (1957 Bldg) - Same as HA - 121A (Duplicated?)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**
MATERIAL LOCATION: **Rm 214 (1957 Bldg) - Same as HA - 121A (Duplicated?)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout (See Hatching Maps), 1929 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUILDING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps), 1929 Bldg.**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout (See Hatching Maps), 1929 Bldg**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**


HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps), 1929 Bldg**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Condensation Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Rm - 1929 Bldg.**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Condensation Tank Insulation**
MATERIAL LOCATION: **Boiler Rm - 1929 Bldg.**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Water Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Rm, Storage Rm - 1929 Bldg.**
MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 09/08/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Water Tank Insulation**
MATERIAL LOCATION: **Boiler Rm, Storage Rm - 1929 Bldg.**
MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Boiler Breeching**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Rm - 1929 Bldg.**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Boiler Breeching**
MATERIAL LOCATION: **Boiler Rm - 1929 Bldg.**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Boiler Gasket**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler #1 & #2 - 1929 Bldg.**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Boiler Gasket**
MATERIAL LOCATION: **Boiler #1 & #2 - 1929 Bldg.**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration Water**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Janitor's closet next to Rm 102, Fan Area (Supply Fan - 5), Engine Rm/Walkway 5, Unexcavated Fan Rm**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Janitor's closet next to Rm 102, Fan Area (Supply Fan - 5), Engine Rm/Walkway 5, Unexcavated Fan Rm**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

0

Management Planner's Signature: _____

Jigar Shah

Date: 10/07/2022

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Water**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Water**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Unexcavated Area, Fan Room, 1st Flr. Janitors Closet and Girls Toilet by Room 102,
1954 Bldg. (Per 2010 Re-inspection Girls Toilet Was Abated)**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**
MATERIAL LOCATION: **Unexcavated Area, Fan Room, 1st Flr. Janitors Closet and Girls Toilet by Room 102, 1954 Bldg. (Per 2010 Re-inspection Girls Toilet Was Abated)**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 221 - 1957 Bldg.**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Not observed**

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Rm 221 - 1957 Bldg.**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Unexcavated Area, Fan Room, 1st Flr. Janitors Closet by Room 102, 1954 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Unexcavated Area, Fan Room, 1st Flr. Janitors Closet by Room 102, 1954 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kevin Hanna**
SCHOOL NAME: **Boone School** INSPECTION DATE: **9/8/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Unexcavated Area, Fan Room, 1st Flr. Janitors Closet by Room 102, 1954 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **09/08/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22271** BUIDLING ID: **2320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Boone School** REVIEW DATE: **10/7/2022**
ADDRESS: **6710 N. Washtenaw Ave.** IDPH LICENSE NO: **100-20525**

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Unexcavated Area, Fan Room, 1st Flr. Janitors Closet by Room 102, 1954 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **10/07/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that KEVIN HANNA
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA-II, Authorized by both AHERA & ASHARA.

01/15/2022
Course Dates:

01/15/2023
Expires:

2201BIR10
Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in blue ink, which appears to read "N. Peneff", is written over a light-colored rectangular background.

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 20525

ISSUED
4/14/2022

EXPIRES
05/15/2023


KEVIN HANNA
7809 KOLMAR AVE
SKOKIE, IL 60076

Environmental Health



7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023

Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 07342

ISSUED
4/1/2022

EXPIRES
05/15/2023

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612



Environmental Health

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>		<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 07342</p>	<p>ISSUED 4/1/2022</p>	<p>EXPIRES 05/15/2023</p>	<p>INSPECTOR</p> <p>PROJECT DESIGNER</p> <p>MANAGEMENT PLANNER</p> <p>PROJECT MANAGER</p> <p>AIR SAMPLING PROFESSIONAL</p>	<p>3/9/2023</p> <p>3/24/2023</p> <p>3/9/2023</p> <p>3/2/2023</p>	
<p>JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612</p> <p>Environmental Health</p>					<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed