

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-601X
SCHOOL NAME: Bridge Schools Branch
ADDRESS OF SCHOOL: 3800 North New England Avenue
CITY: Chicago, IL, 60634

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **9/13/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/21/2022 ENROLLMENT 1107
IDPH INSPECTOR LICENSE NUMBER: 100-20485
IDPH LICENSED INSPECTOR NAME (Please Print): Jeffin Chakkalake
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 7/13/2022
Signature of Designated Person *Date*

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Bridge Schools Branch

3800 North New England Avenue
Chicago, IL, 60634

Unit: 22321
Building ID: 2380

IDPH ID Number: 14-016-2990-601X

REPORT DATE:

Wednesday, July 13, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Specialty Consulting, Inc.

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

07/13/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22321 Region: 01 IDPH ID: 14-016-2990-601X

School: Bridge Schools Branch Building ID: 2380

Address: 3800 North New England Avenue

Chicago, IL, 60634

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 6/21/2022

Review Date: 07/13/2022

Inspector: Jeffin Chakkalake

Inspector IDPH License: 100-20485

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Arturo Saenz
100-04019

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: July 13, 2022

RE: Bridge Schools Branch , Unit 22321
3800 North New England Avenue
Chicago, IL, 60634

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Bridge Schools Branch , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Bridge Schools Branch , there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Bridge Schools Branch Unit: 22321 Region: 01
Address: 3800 North New England Chicago, IL, 60634
Avenue
IDPH ID: 14-016-2990-601X Building ID: 2380
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 1107

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Jeffin Chakkalake


Inspector IDPH license # 100-20485
Reinspection Date: 6/21/2022

Signature: 
Date: 6/21/2022

6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

Signature: 
Date: 07/13/2022

7. Review Date: 07/13/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 7/13/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bridge Schools Branch . This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2380:

B. The following new homogenous areas have been identified for Building 2380:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|-----|--|
| 01 | MJP on Aircell |
| 02 | Aircell |
| 03 | MJP on Paperwrap |
| 04 | Paperwrap |
| 05 | MJP on Paperwrap |
| 06 | Paperwrap |
| 08 | 9x9 multicolored VFT |
| 18 | 12x12 VFT (under carpet) |
| 19 | 9x9 multicolored VFT MASTIC |
| 20 | 12x12 VFT MASTIC (under carpet) |
| 50 | Black Vinyl Baseboard |
| 51 | Black Vinyl Baseboard MASTIC |
| 52 | Terrazzo |
| 53 | Plaster |
| 54 | 9x9 Tan VFT |
| 54A | 9x9 Tan VFT MASTIC |
| 55 | 12x12 Beige w/ dark streaks VFT |
| 55A | 12x12 Beige w/ dark streaks VFT MASTIC |
| 56 | Drywall |
| 57 | 12x12 light gray streaked VFT |
| 57A | 12x12 light gray streaked VFT MASTIC |
| 58 | Carpet MASTIC |
| 59 | 12x12 Burnt orange VFT |
| 59A | 12x12 Burnt orange VFT MASTIC |
| 60 | 12x12 Light yellow VFT |
| 60A | 12x12 light yellow VFT MASTIC |
| 61 | 1x1 white w/ grooves ceiling tile |
| 62 | 12x12 sand VFT |
| 62A | 12x12 Sand VFT MASTIC |
| 63 | 12x12 pink VFT |
| 63A | 12x12 pink VFT MASTIC |
| 64 | 2'x4' white grooved ceiling tile |
| 65 | 1x1 white grooved ceiling tile |
| 66 | Brown Vinyl Baseboard MASTIC |
| 67 | 9x9 brown w/ brown and white streaks VFT |
| 67A | 9x9 brown w/ brown and white streaks VFT MASTIC |
| 68 | 12x12 Sand VFT |
| 68A | 12x12 Sand VFT MASTIC |
| 69 | Terrazzo Floors |

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jeffin Chakkalakeel , IDPH License # 100-20485. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Bridge Schools Branch Building 2380 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Bridge Schools Branch Unit 22321 Building ID 2380

Address 3800 North New England Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| 01 | MJP on Aircell | 1,040 | EA | Throughout building | ASSUMED | TSI | Y | DIST | 30 | | | Damaged or significantly damaged friable thermal system insulating ACBM | | HIGH |
| 02 | Aircell | 2,067 | LF | Throughout building | ASSUMED | TSI | Y | DIST | 40 | | | Damaged or significantly damaged friable thermal system insulating ACBM | 10 | HIGH |
| 03 | MJP on Paperwrap | 627 | EA | Throughout Building | ASSUMED | TSI | Y | DIST | 10 | | | Damaged or significantly damaged friable thermal system insulating ACBM | | HIGH |
| 04 | Paperwrap | 1,123 | LF | Throughout building | ASSUMED | TSI | Y | DIST | 25 | | | Damaged or significantly damaged friable thermal system insulating ACBM | | HIGH |
| 05 | MJP on Paperwrap | 640 | EA | Throughout building | ASSUMED | TSI | Y | DIST | 10 | | | Damaged or significantly damaged friable thermal system insulating ACBM | | HIGH |
| 06 | Paperwrap | 1,101 | LF | Throughout Building | ASSUMED | TSI | Y | DIST | 25 | | | Damaged or significantly damaged friable thermal system insulating ACBM | | MODERATE |
| 08 | 9x9 multicolored VFT | 2,760 | SF | Basement halls and rooms | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 18 | 12x12 VFT (under carpet) | 9,217 | SF | 1st floor east wing | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 19 | 9x9 multicolored VFT MASTIC | 2,460 | SF | Bsmt halls and rooms | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 20 | 12x12 VFT MASTIC (under carpet) | 9,217 | SF | 1st floor; east wing | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 50 | Black Vinyl Baseboard | 350 | LF | Teacher's lounge, principal's office, computer room | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 51 | Black Vinyl Baseboard MASTIC | 350 | LF | Teacher's lounge, principal's office, computer room | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 52 | Terrazzo | 3,690 | SF | East wing hallway, stair landings, bathroom | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 53 | Plaster | 35,000 | SF | Throughout Main Bldg | ASSUMED | SURFACE | N | NONE | 0 | | No | | | LOW |
| 54 | 9x9 Tan VFT | 75 | SF | 3rd fl. teacher's | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the | | LOW |

Chicago Public Schools

School Bridge Schools Branch Unit 22321 Building ID 2380

Address 3800 North New England Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | lounge and toilet | | | | | | | | potential for damage | | |
| 54A | 9x9 Tan VFT MASTIC | 75 | SF | 3rd fl. teacher's lounge and toilet | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 55 | 12x12 Beige w/ dark streaks VFT | 200 | SF | 3rd fl. teacher's lounge | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 55A | 12x12 Beige w/ dark streaks VFT MASTIC | 200 | SF | #rd fl. teacher's lounge | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 56 | Drywall | 1,200 | SF | 3rd floor boys' toilet; rooms 101, 102, 104, 107 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 57 | 12x12 light gray streaked VFT | 200 | SF | 2nd fl. Teachers' lounge | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 57A | 12x12 light gray streaked VFT MASTIC | 200 | SF | 2nd fl. teachers' lounge | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 58 | Carpet MASTIC | 250 | SF | 2nd fl. storage, 3rd fl. copy room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 59 | 12x12 Burnt orange VFT | 500 | SF | 1st fl center stair landing, 1st fl east stair landing, 1st fl corridor border | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 59A | 12x12 Burnt orange VFT MASTIC | 500 | SF | 1st fl center stair landing, 2st fl east stair landing, 1st fl corridor border | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 60 | 12x12 Light yellow VFT | 1,600 | SF | 1st floor corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 60A | 12x12 light yellow VFT MASTIC | 1,600 | SF | 1st floor corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 61 | 1x1 white w/ grooves ceiling tile | 4,000 | SF | Rooms 101, 103, 105, 102, 104 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 62 | 12x12 sand VFT | 744 | SF | Room 103 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 62A | 12x12 Sand VFT MASTIC | 744 | SF | Room 103 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 63 | 12x12 pink VFT | 600 | SF | 1st fl classroom-Annex | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 63A | 12x12 pink VFT MASTIC | 600 | SF | 1st fl classroom-Annex | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 64 | 2'x4' white grooved ceiling tile | 600 | SF | 1st fl classroom-Annex | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 65 | 1x1 white grooved ceiling tile | 7,000 | SF | 1st floor lunch room, kitchen, storage rooms, 2nd floor corridors- Annex | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Bridge Schools Branch Unit 22321 Building ID 2380

Address 3800 North New England Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | Bldg | | | | | | | | | | |
| 66 | Brown Vinyl Baseboard MASTIC | 800 | SF | Throughout Annex Bldg | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 67 | 9x9 brown w/ brown and white streaks VFT | 5,500 | SF | Annex- Lunchroom rooms 17, 18, 19, 20 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 67A | 9x9 brown w/ brown and white streaks VFT MASTIC | 5,500 | SF | Annex- Lunchroom rooms 17, 18, 19, 20 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 68 | 12x12 Sand VFT | 400 | SF | Annex- Kitchen and storage rooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 68A | 12x12 Sand VFT MASTIC | 400 | SF | Annex- Kitchen and storage rooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 69 | Terrazzo Floors | 500 | SF | Stairwells- Annex | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Bridge Schools Branch Unit 22321 Building ID 2380

Address 3800 North New England Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| |
|---|
| Reinspection Date 6/21/2022 |
| Inspector Name <u>Jeffin Chakkalake</u> |
| 100-20485 5/15/2023 |
| Inspector's IDPH License Number / Expiration Date |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 01 | |
| 02 | |
| 03 | |
| 04 | |
| 05 | |
| 06 | |
| 08 | |
| 18 | |
| 19 | |
| 20 | |
| 50 | |
| 51 | |
| 52 | |
| 53 | |
| 54 | |
| 54A | |
| 55 | |
| 55A | |
| 56 | |
| 57 | |
| 57A | |
| 58 | |
| 59 | |
| 59A | |

Chicago Public Schools

School Bridge Schools Branch **Unit** 22321 **Building ID** 2380

Address 3800 North New England Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 60 | |
| 60A | |
| 61 | |
| 62 | |
| 62A | |
| 63 | |
| 63A | |
| 64 | |
| 65 | |
| 66 | |
| 67 | |
| 67A | |
| 68 | |
| 68A | |
| 69 | |

Table II

Management Planner's Review

Chicago Public Schools

School Bridge Schools Branch
Address 3800 North New England Avenue

Unit 22321
 Chicago, IL, 60634

Building ID 2380
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|---|-----------------|
| 01 | MJP on Aircell | 1,040 | EA | Throughout building | Assumed | TSI | Yes | 30 | EA | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| 02 | Aircell | 2,067 | LF | Throughout building | Assumed | TSI | Yes | 40 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| 03 | MJP on Paperwrap | 627 | EA | Throughout Building | Assumed | TSI | Yes | 10 | EA | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| 04 | Paperwrap | 1,123 | LF | Throughout building | Assumed | TSI | Yes | 25 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| 05 | MJP on Paperwrap | 640 | EA | Throughout building | Assumed | TSI | Yes | 10 | EA | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| 06 | Paperwrap | 1,101 | LF | Throughout Building | Assumed | TSI | Yes | 25 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| 08 | 9x9 multicolored VFT | 2,760 | SF | Basement halls and rooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18 | 12x12 VFT (under carpet) | 9,217 | SF | 1st floor east wing | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 19 | 9x9 multicolored VFT MASTIC | 2,460 | SF | Bsmt halls and rooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 20 | 12x12 VFT MASTIC (under carpet) | 9,217 | SF | 1st floor; east wing | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 50 | Black Vinyl Baseboard | 350 | LF | Teacher's lounge, principal's office, computer room | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 51 | Black Vinyl Baseboard MASTIC | 350 | LF | Teacher's lounge, principal's office, computer room | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 52 | Terrazzo | 3,690 | SF | East wing hallway, stair landings, bathroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 53 | Plaster | 35,000 | SF | Throughout Main Bldg | Assumed | SURFACE | No | 0 | SF | | Follow O&M Plan |
| 54 | 9x9 Tan VFT | 75 | SF | 3rd fl. teacher's lounge and toilet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 54A | 9x9 Tan VFT MASTIC | 75 | SF | 3rd fl. teacher's lounge and toilet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 55 | 12x12 Beige w/ dark streaks VFT | 200 | SF | 3rd fl. teacher's lounge | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 55A | 12x12 Beige w/ dark streaks VFT MASTIC | 200 | SF | #rd fl. teacher's lounge | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 56 | Drywall | 1,200 | SF | 3rd floor boys' toilet; rooms 101, 102, 104, 107 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 57 | 12x12 light gray streaked VFT | 200 | SF | 2nd fl. Teachers' lounge | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 57A | 12x12 light gray streaked VFT MASTIC | 200 | SF | 2nd fl. teachers' lounge | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 58 | Carpet MASTIC | 250 | SF | 2nd fl. storage, 3rd fl. copy room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 59 | 12x12 Burnt orange VFT | 500 | SF | 1st fl center stair landing, 1st fl east stair landing, 1st fl corridor border | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 59A | 12x12 Burnt orange VFT MASTIC | 500 | SF | 1st fl center stair landing, 2st fl east stair landing, 1st fl corridor border | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Bridge Schools Branch
Address 3800 North New England Avenue

Unit 22321
 Chicago, IL, 60634

Building ID 2380
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 60 | 12x12 Light yellow VFT | 1,600 | SF | 1st floor corridor | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 60A | 12x12 light yellow VFT MASTIC | 1,600 | SF | 1st floor corridor | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 61 | 1x1 white w/ grooves ceiling tile | 4,000 | SF | Rooms 101, 103, 105, 102, 104 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 62 | 12x12 sand VFT | 744 | SF | Room 103 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 62A | 12x12 Sand VFT MASTIC | 744 | SF | Room 103 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 63 | 12x12 pink VFT | 600 | SF | 1st fl classroom- Annex | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 63A | 12x12 pink VFT MASTIC | 600 | SF | 1st fl classroom- Annex | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 64 | 2'x4' white grooved ceiling tile | 600 | SF | 1st fl classroom- Annex | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 65 | 1x1 white grooved ceiling tile | 7,000 | SF | 1st floor lunch room, kitchen, storage rooms, 2nd floor corridors- Annex Bldg | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 66 | Brown Vinyl Baseboard MASTIC | 800 | SF | Throughout Annex Bldg | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 67 | 9x9 brown w/ brown and white streaks VFT | 5,500 | SF | Annex- Lunchroom rooms 17, 18, 19, 20 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 67A | 9x9 brown w/ brown and white streaks VFT MASTIC | 5,500 | SF | Annex- Lunchroom rooms 17, 18, 19, 20 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 68 | 12x12 Sand VFT | 400 | SF | Annex- Kitchen and storage rooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 68A | 12x12 Sand VFT MASTIC | 400 | SF | Annex- Kitchen and storage rooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 69 | Terrazzo Floors | 500 | SF | Stairwells- Annex | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Bridge Schools Branch
Address 3800 North New England Avenue

Unit 22321
 Chicago, IL, 60634

Building ID 2380
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|--------------|
| Review Date | 7/13/2022 |
| Manager Planner Name | Arturo Saenz |
| 100-04019 | 5/15/2023 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|--|
| 01 | sample material, repair damaged ACM ASAP |
| 02 | sample material, repair damaged ACM ASAP |
| 03 | sample material, repair damaged ACM ASAP |
| 04 | sample material, repair damaged ACM ASAP |
| 05 | sample material, repair damaged ACM ASAP |
| 06 | sample material, repair damaged ACM ASAP |
| 08 | |
| 18 | |
| 19 | |
| 20 | |
| 50 | |
| 51 | |
| 52 | |
| 53 | |
| 54 | |
| 54A | |
| 55 | |
| 55A | |
| 56 | |
| 57 | |

Chicago Public Schools

School Bridge Schools Branch
Address 3800 North New England Avenue

Unit 22321
Chicago, IL, 60634

Building ID 2380
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 57A | |
| 58 | |
| 59 | |
| 59A | |
| 60 | |
| 60A | |
| 61 | |
| 62 | |
| 62A | |
| 63 | |
| 63A | |
| 64 | |
| 65 | |
| 66 | |
| 67 | |
| 67A | |
| 68 | |
| 68A | |
| 69 | |

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUILDING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **MJP on Aircell**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY: **1040**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **MJP on Aircell**
MATERIAL LOCATION: **Throughout building**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

sample material, repair damaged ACM ASAP

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Aircell**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Water**
DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Throughout building**
MATERIAL QUANTITY: **2067** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Aircell**
MATERIAL LOCATION: **Throughout building**
MATERIAL QUANTITY: **2067** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

sample material, repair damaged ACM ASAP

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **MJP on Paperwrap**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **627**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **MJP on Paperwrap**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **627** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

sample material, repair damaged ACM ASAP

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUILDING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **Paperwrap**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY: **1123**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **Paperwrap**
MATERIAL LOCATION: **Throughout building**
MATERIAL QUANTITY: **1123** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **25** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

sample material, repair damaged ACM ASAP

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **MJP on Paperwrap**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY: **640**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **MJP on Paperwrap**
MATERIAL LOCATION: **Throughout building**
MATERIAL QUANTITY: **640** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

sample material, repair damaged ACM ASAP

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Paperwrap**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **1101**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Paperwrap**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1101** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **25** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

sample material, repair damaged ACM ASAP

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9x9 multicolored VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement halls and rooms**
MATERIAL QUANTITY: **2760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9x9 multicolored VFT**
MATERIAL LOCATION: **Basement halls and rooms**
MATERIAL QUANTITY: **2760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12x12 VFT (under carpet)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **!st floor east wing**
MATERIAL QUANTITY: **9217** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12x12 VFT (under carpet)**
MATERIAL LOCATION: **1st floor east wing**
MATERIAL QUANTITY: **9217** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9x9 multicolored VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Bsmt halls and rooms**
MATERIAL QUANTITY: **2460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9x9 multicolored VFT MASTIC**
MATERIAL LOCATION: **Bsmt halls and rooms**
MATERIAL QUANTITY: **2460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12x12 VFT MASTIC (under carpet)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st floor; east wing**
MATERIAL QUANTITY: **9217** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12x12 VFT MASTIC (under carpet)**
MATERIAL LOCATION: **1st floor; east wing**
MATERIAL QUANTITY: **9217** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's lounge, principal's office, computer room**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**
MATERIAL LOCATION: **Teacher's lounge, principal's office, computer room**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's lounge, principal's office, computer room**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard MASTIC**
MATERIAL LOCATION: **Teacher's lounge, principal's office, computer room**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East wing hallway, stair landings, bathroom**
MATERIAL QUANTITY: **3690** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **East wing hallway, stair landings, bathroom**
MATERIAL QUANTITY: **3690** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Main Bldg**
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout Main Bldg**
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **9x9 Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd fl. teacher's lounge and toilet**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **9x9 Tan VFT**
MATERIAL LOCATION: **3rd fl. teacher's lounge and toilet**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54A**
MATERIAL DESCRIPTION: **9x9 Tan VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd fl. teacher's lounge and toilet**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **54A**
MATERIAL DESCRIPTION: **9x9 Tan VFT MASTIC**
MATERIAL LOCATION: **3rd fl. teacher's lounge and toilet**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12x12 Beige w/ dark streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd fl. teacher's lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12x12 Beige w/ dark streaks VFT**
MATERIAL LOCATION: **3rd fl. teacher's lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55A**
MATERIAL DESCRIPTION: **12x12 Beige w/ dark streaks VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **#rd fl. teacher's lounge**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **55A**
MATERIAL DESCRIPTION: **12x12 Beige w/ dark streaks VFT MASTIC**
MATERIAL LOCATION: **#rd fl. teacher's lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd floor boys' toilet; rooms 101, 102, 104, 107**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **3rd floor boys' toilet; rooms 101, 102, 104, 107**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12x12 light gray streaked VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd fl. Teachers' lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12x12 light gray streaked VFT**
MATERIAL LOCATION: **2nd fl. Teachers' lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57A**
MATERIAL DESCRIPTION: **12x12 light gray streaked VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd fl. teachers' lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **57A**
MATERIAL DESCRIPTION: **12x12 light gray streaked VFT MASTIC**
MATERIAL LOCATION: **2nd fl. teachers' lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Carpet MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd fl. storage, 3rd fl. copy room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Carpet MASTIC**
MATERIAL LOCATION: **2nd fl. storage, 3rd fl. copy room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **12x12 Burnt orange VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl center stair landing, 1st fl east stair landing, 1st fl corridor border**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **12x12 Burnt orange VFT**
MATERIAL LOCATION: **1st fl center stair landing, 1st fl east stair landing, 1st fl corridor border**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59A**
MATERIAL DESCRIPTION: **12x12 Burnt orange VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl center stair landing, 2st fl east stair landing, 1st fl corridor border**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **59A**
MATERIAL DESCRIPTION: **12x12 Burnt orange VFT MASTIC**
MATERIAL LOCATION: **1st fl center stair landing, 2st fl east stair landing, 1st fl corridor border**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12x12 Light yellow VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st floor corridor**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12x12 Light yellow VFT**
MATERIAL LOCATION: **1st floor corridor**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60A**
MATERIAL DESCRIPTION: **12x12 light yellow VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st floor corridor**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **60A**
MATERIAL DESCRIPTION: **12x12 light yellow VFT MASTIC**
MATERIAL LOCATION: **1st floor corridor**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **1x1 white w/ grooves ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101, 103, 105, 102, 104**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **1x1 white w/ grooves ceiling tile**
MATERIAL LOCATION: **Rooms 101, 103, 105, 102, 104**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12x12 sand VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **744** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12x12 sand VFT**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **744** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62A**
MATERIAL DESCRIPTION: **12x12 Sand VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **744** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **62A**
MATERIAL DESCRIPTION: **12x12 Sand VFT MASTIC**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **744** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12x12 pink VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl classroom- Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12x12 pink VFT**
MATERIAL LOCATION: **1st fl classroom- Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63A**
MATERIAL DESCRIPTION: **12x12 pink VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl classroom- Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **63A**
MATERIAL DESCRIPTION: **12x12 pink VFT MASTIC**
MATERIAL LOCATION: **1st fl classroom- Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **2'x4' white grooved ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st fl classroom- Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **2'x4' white grooved ceiling tile**
MATERIAL LOCATION: **1st fl classroom- Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **1x1 white grooved ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st floor lunch room, kitchen, storage rooms, 2nd floor corridors- Annex Bldg**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **1x1 white grooved ceiling tile**
MATERIAL LOCATION: **1st floor lunch room, kitchen, storage rooms, 2nd floor corridors- Annex Bldg**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Annex Bldg**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard MASTIC**
MATERIAL LOCATION: **Throughout Annex Bldg**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **9x9 brown w/ brown and white streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Lunchroom rooms 17, 18, 19, 20**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **9x9 brown w/ brown and white streaks VFT**
MATERIAL LOCATION: **Annex- Lunchroom rooms 17, 18, 19, 20**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67A**
MATERIAL DESCRIPTION: **9x9 brown w/ brown and white streaks VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Lunchroom rooms 17, 18, 19, 20**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **67A**
MATERIAL DESCRIPTION: **9x9 brown w/ brown and white streaks VFT MASTIC**
MATERIAL LOCATION: **Annex- Lunchroom rooms 17, 18, 19, 20**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12x12 Sand VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Kitchen and storage rooms**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12x12 Sand VFT**
MATERIAL LOCATION: **Annex- Kitchen and storage rooms**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68A**
MATERIAL DESCRIPTION: **12x12 Sand VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex- Kitchen and storage rooms**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/21/2022

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **68A**
MATERIAL DESCRIPTION: **12x12 Sand VFT MASTIC**
MATERIAL LOCATION: **Annex- Kitchen and storage rooms**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**
SCHOOL NAME: **Bridge Schools Branch** INSPECTION DATE: **6/21/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Terrazzo Floors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairwells- Annex**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/21/2022**

Chicago Public Schools

Specialty Consulting, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22321** BUIDLING ID: **2380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Bridge Schools Branch** REVIEW DATE: **7/13/2022**
ADDRESS: **3800 North New England Avenue** IDPH LICENSE NO: **100-20485**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Terrazzo Floors**
MATERIAL LOCATION: **Stairwells- Annex**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/13/2022**

Chicago Public Schools

Specialty Consulting, Inc.
2022 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER

100 - 20485

ISSUED

5/5/2021

EXPIRES

05/15/2022

JEFFIN J CHAKKALAKEL

1319 TOWER HILL DR

WOODRIDGE, IL 60517

Environmental Health



CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JEFFIN J. CHAKKALAKEL
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/15/2022

Course Dates:

01/15/2023

Expires:

2201BIR04

Certificate Number:

A handwritten signature in blue ink, appearing to read "N Peneff DPH". The signature is written over a light-colored rectangular background.

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JEFFIN J CHAKKALAKEL
1319 TOWER HILL DR
WOODRIDGE, IL 60517

5/20/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 20485

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| | | | | | |
|--|----------------------------|--------------------------------------|---|---|-------------------|
|  | | ASBESTOS PROFESSIONAL LICENSE | | ENDORSEMENTS | TC EXPIRES |
| ID NUMBER 100 - 20485 | ISSUED 5/20/2022 | EXPIRES 05/15/2023 |  | INSPECTOR | 1/15/2023 |
| JEFFIN J CHAKKALAKEL 1319 TOWER HILL DR WOODRIDGE, IL 60517 Environmental Health | | | | PROJECT MANAGER | 4/29/2023 |
| | | | | Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562


Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

2/28/2022



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 04019

ISSUED
2/28/2022

EXPIRES
05/15/2023

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612



Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| | | | | |
|---|---------------------|-----------------------|---------------------------|-------------------|
|  ASBESTOS PROFESSIONAL LICENSE | | | ENDORSEMENTS | TC EXPIRES |
| ID NUMBER 100 - 04019 | ISSUED 2/28/2022 | EXPIRES 05/15/2023 | INSPECTOR | 11/1/2022 |
| ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health | | | MANAGEMENT PLANNER | 11/1/2022 |
|  | | | AIR SAMPLING PROFESSIONAL | |
| Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | | | | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES

Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|-------------|--|
| MATERIAL | | |
| | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | | |
| | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | | |
| | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | | |
| | Loc | Localized |
| | Dist | Distributed |