

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2109
SCHOOL NAME: Burroughs School
ADDRESS OF SCHOOL: 3542 S. Washtenaw
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/22/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 7/12/2022 ENROLLMENT 330
IDPH INSPECTOR LICENSE NUMBER: 100-20411
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



7/14/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Burroughs School

3542 S. Washtenaw
Chicago, IL, 60632

Unit: 22481
Building ID: 2540

IDPH ID Number: 14-016-2990-2109

REPORT DATE:

Thursday, July 14, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

07/14/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22481 Region: 04 IDPH ID: 14-016-2990-2109

School: Burroughs School Building ID: 2540

Address: 3542 S. Washtenaw

Chicago, IL, 60632

Building Contact: Cermak, Blake

Contact Phone: 3126130863

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/12/2022

Review Date: 07/14/2022

Inspector: Benyamen Maradkel

Inspector IDPH License: 100-20411

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: July 14, 2022

RE: Burroughs School, Unit 22481
3542 S. Washtenaw
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Burroughs School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Burroughs School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Burroughs School Unit: 22481 Region: 04
Address: 3542 S. Washtenaw Chicago, IL, 60632
IDPH ID: 14-016-2990-2109 Building ID: 2540
Contact: Cermak, Blake Phone: 3126130863

2. Description of Facility

Original Construction: 1893 Additional Construction:
Total Square Footage: 49191 No of Floors: 4
Current Occupancy: 330

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Benyamen Maradkel


Inspector IDPH license # 100-20411
Reinspection Date: 7/12/2022

Signature: 
Date: 7/12/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature: 
Date: 07/14/2022

7. Review Date: 07/14/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 7/14/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Burroughs School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2540:

35	Incinerator flue liner
36	Brown stair tread
37	Brown stair tread mastic
38	12" x 12" White w/ Beige Specks Floor Tile
39	12" x 12" Lime Green w/ Green Specks Floor Tile
40	12" x 12" Blonde w/ White Specks Floor Tile
41	12" x 12" White w/ Beige Specks (HA 38) & 12" x 12" Lime Green w/ Green Specks (HA 39) & 12" x 12" Blonde w/ White Specks (HA 40) Floor Tile Mastic
42	12" x 12" Dark Blue Floor Tile

43	12" x 12" Dark Blue Floor Tile Mastic
44	9" x 9" Gray Floor Tile
45	9" x 9" Gray Floor Tile Mastic
F	Cardboard pipe insulation
K	Cementitious pipe fittings off city water line
L	Valve headers

B. The following new homogenous areas have been identified for Building 2540:

- 38 12" x 12" White w/ Beige Specks Floor Tile
- 39 12" x 12" Lime Green w/ Green Specks Floor Tile
- 40 12" x 12" Blonde w/ White Specks Floor Tile
- 41 12" x 12" White w/ Beige Specks (HA 38) & 12" x 12" Lime Green w/ Green Specks (HA 39) & 12" x 12" Blonde w/ White Specks (HA 40) Floor Tile Mastic
- 42 12" x 12" Dark Blue Floor Tile
- 43 12" x 12" Dark Blue Floor Tile Mastic
- 44 9" x 9" Gray Floor Tile
- 45 9" x 9" Gray Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

17	Green floor tile
21	Roof Flashing - non - AHERA
23	12" x 12" blue floor tile
24	12" x 12" blue floor tile mastic
25	Chalk boards
26	12" x 12" White Vinyl Floor Tile
27	12" x 12" White Vinyl Floor Tile Mastic
28	Beige baseboard
29	Beige baseboard mastic
30	2' x 2' Ceiling Tile
31	Blue linoleum
32	Blue linoleum mastic
33	Red linoleum
34	Red linoleum mastic
35	Incinerator flue liner
36	Brown stair tread
37	Brown stair tread mastic
38	12" x 12" White w/ Beige Specks Floor Tile
39	12" x 12" Lime Green w/ Green Specks Floor Tile
40	12" x 12" Blonde w/ White Specks Floor Tile
41	12" x 12" White w/ Beige Specks (HA 38) & 12" x 12" Lime Green w/ Green Specks (HA 39) & 12" x 12" Blonde w/ White Specks (HA 40) Floor Tile Mastic
42	12" x 12" Dark Blue Floor Tile
43	12" x 12" Dark Blue Floor Tile Mastic
44	9" x 9" Gray Floor Tile
45	9" x 9" Gray Floor Tile Mastic
5A	12" x 12" Speckled Brown Floor Tile
5B	12" x 12" Brown w/White Specks Floor Tile
5C	12" x 12" Beige w/White Specks Floor Tile
5D	12" x 12" Mottled Brown Floor Tile
5E	12" x 12" Brownish Gold Floor Tile
5F	12" x 12" Off-White w/Brown Specks Floor Tile
5G	12" x 12" Dark Gray Floor Tile
5H	12" x 12" Tan Floor Tile
5I	12" x 12" Off-White w/Brown Specks Floor Tile
5J	12" x 12" Off-White Floor Tile
7	Adhesive on 1' x 1' Ceiling Tile
9A	12" x 12" Brown Speckled Floor Tile Mastic
9B	12" x 12" Brown w/White Specks Floor Tile Mastic
9C	12" x 12" Beige w/White Specks Floor Tile Mastic

9D 12" x 12" Mottled Brown Floor Tile Mastic
9J 12" x 12" Off-White Floor Tile Mastic

The following areas were deemed to be inaccessible:

27 12" x 12" White Vinyl Floor Tile Mastic
29 Beige baseboard mastic
32 Blue linoleum mastic
34 Red linoleum mastic
37 Brown stair tread mastic
41 12" x 12" White w/ Beige Specks (HA 38) & 12" x
12" Lime Green w/ Green Specks (HA 39) & 12" x
12" Blonde w/ White Specks (HA 40) Floor Tile
Mastic
43 12" x 12" Dark Blue Floor Tile Mastic
45 9" x 9" Gray Floor Tile Mastic
9A 12" x 12" Brown Speckled Floor Tile Mastic
9B 12" x 12" Brown w/White Specks Floor Tile Mastic
9C 12" x 12" Beige w/White Specks Floor Tile Mastic
L Valve headers

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Burroughs School Building 2540 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Burroughs School Unit 22481 Building ID 2540

Address 3542 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Hard plaster			Throughout	NO_ACBM	SURFACE								
10A	Red linoleum mastic		SF	1st and 2nd Floor Plumbing Rooms	CHR	MISC				SF				
11	Carpet mastic			Principal's Office and Room 206	NO_ACBM	MISC								
12	Green linoleum			Room 101 and Basement	NO_ACBM	MISC								
13	Wall stucco			Basement	NO_ACBM	MISC								
14	Black baseboard			Room 006	NO_ACBM	MISC								
14A	Black baseboard adhesive			Room 006	NO_ACBM	MISC								
15	Green linoleum			Rooms 203, 206	NO_ACBM	MISC								
16	Brown linoleum			Principal's Office - Under 9" x 9" FT, 1st Floor Corridor	NO_ACBM	MISC								
17	Green floor tile		SF	Lunchroom	ASSUMED	MISC				SF				
17A	Yellow mastic under green floor tile			Lunchroom	NO_ACBM	MISC								
18	Brown brick - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
19	Brick mortar - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
2	1' x 1' Ceiling tile			Classrooms	NO_ACBM	MISC								
20	Exterior window glaze - Non-AHERA			Exterior of Field House	CHR	MISC								
21	Roof Flashing - non - AHERA				ASSUMED	MISC								
22	Roof field -Non-AHERA				NO_ACBM	MISC								
23	12" x 12" blue floor tile	1,200	SF	Lunchroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
24	12" x 12" blue floor tile mastic	1,200	SF	Lunchroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
25	Chalk boards	1,550	SF	301, 302, 306, Library, 201, 202, 203, 204, 205, 206, 104, 105, 106, 101	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
26	12" x 12" White Vinyl Floor Tile	486	SF	Module Corridor and Classes, 006	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
27	12" x 12" White Vinyl Floor Tile Mastic	486	SF	Module Corridor and Classes, 006	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
28	Beige baseboard	108	SF	Module Corridor	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
29	Beige baseboard mastic	108	SF	Module Corridor	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
3	2' x 4' Ceiling Tile			Classrooms	NO_ACBM	MISC								
30	2' x 2' Ceiling Tile	2,000	SF	Module Throughout	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
31	Blue linoleum	130	SF	Boys Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the		LOW

Chicago Public Schools

School Burroughs School Unit 22481 Building ID 2540

Address 3542 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				module								potential for damage		
32	Blue linoleum mastic	130	SF	Boys Bathroom module	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
33	Red linoleum	130	SF	Girls Bathroom module	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34	Red linoleum mastic	130	SF	Girls Bathroom module	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
35	Incinerator flue liner	50	LF	Boiler room, Tank room	ASSUMED	TSI	Y	NONE	0	LF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
36	Brown stair tread	500	SF	North and South Stairs	ASSUMED	MISC	N	LOC	10	SF	Yes	ACBM with the potential for damage	5	LOW
37	Brown stair tread mastic	500	SF	North and South Stairs	ASSUMED	MISC	N	LOC	10	SF	Yes	ACBM with the potential for damage	5	LOW
38	12" x 12" White w/ Beige Specks Floor Tile	200	SF	3rd floor south corridor, 002	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
39	12" x 12" Lime Green w/ Green Specks Floor Tile	200	SF	3rd floor south corridor, 002	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
40	12" x 12" Blonde w/ White Specks Floor Tile	200	SF	3rd floor south corridor, 002	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
41	12" x 12" White w/ Beige Specks (HA 38) & 12" x 12" Lime Green w/ Green Specks (HA 39) & 12" x 12" Blonde w/ White Specks (HA 40) Floor Tile Mastic	600	SF	3rd floor south corridor, 002	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
42	12" x 12" Dark Blue Floor Tile	100	SF	Lunchroom, lunchroom office, 3rd floor south corridor, 1st floor plumbing closet	ASSUMED	MISC	N	DIST	7	SF	Yes	ACBM with potential for significant damage	5	MODERATE
43	12" x 12" Dark Blue Floor Tile Mastic	100	SF	Lunchroom, lunchroom office, 3rd floor south corridor, 1st floor plumbing closet	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
44	9" x 9" Gray Floor Tile	100	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
45	9" x 9" Gray Floor Tile Mastic	100	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
4A	9" x 9" Tan Floor Tile	1,200	SF	Rooms 203 and 206	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
4B	9" x 9" Brownish/Pink Floor Tile		SF	Main Office	CHR	MISC				SF				
4C	9" x 9" Brown Floor Tile		SF	Basement Floor Room 004	CHR	MISC				SF				
4D	9" x 9" Green Floor Tile w/Black Specks		SF	Engineer's Office	CHR	MISC				SF				

Chicago Public Schools

School Burroughs School Unit 22481 Building ID 2540

Address 3542 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
5A	12" x 12" Speckled Brown Floor Tile	500	SF	3rd Floor Stage, 3rd floor north corridor	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
5B	12" x 12" Brown w/White Specks Floor Tile	300	SF	1st Floor Teacher's Lunchroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
5C	12" x 12" Beige w/White Specks Floor Tile	150	SF	1st Floor Teacher's Lunchroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
5D	12" x 12" Mottled Brown Floor Tile		SF	3rd Floor South Corridor	ASSUMED	MISC				SF				
5E	12" x 12" Brownish Gold Floor Tile	1,400	SF	1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
5F	12" x 12" Off-White w/Brown Specks Floor Tile	2,400	SF	1st and 2nd Fl Corridors and Room 205, 1st fl teachers lunch Room, Libuary store Rm (see Mgr comments), 005	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
5G	12" x 12" Dark Gray Floor Tile		SF	Lunchroom	ASSUMED	MISC				SF				
5H	12" x 12" Tan Floor Tile		SF	Library storage	ASSUMED	MISC				SF				
5I	12" x 12" Off-White w/Brown Specks Floor Tile	1,800	SF	1st and 2nd Floor Corridors, Rooms 006 and 205	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
5J	12" x 12" Off-White Floor Tile			Fieldhouse Bathrooms	ASSUMED	MISC								
6A	Red linoleum		SF	1st and 2nd Floor Plumbing Room	CHR	MISC				SF				
7	Adhesive on 1' x 1' Ceiling Tile	400	SF	Principal's Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
8A	9" x 9" Tan Floor Tile Mastic	1,200	SF	Rooms 203	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
8B	9" x 9" Brownish/Pink Floor Tile Mastic		SF	Principal's Office	CHR	MISC				SF				
8C	9" x 9" Brown Floor Tile Mastic		SF	Basement Room 004	CHR	MISC				SF				
8D	9" x 9" Green Floor Tile w/Black Specks Mastic		SF	Engineer's office	CHR	MISC				SF				
9A	12" x 12" Brown Speckled Floor Tile Mastic	500	SF	3rd Floor Stage, 3rd floor north corridor, 305 closet	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
9B	12" x 12" Brown w/White Specks Floor Tile Mastic	300	SF	1st Floor Teacher's Lunchroom, 005	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
9C	12" x 12" Beige w/White Specks Floor Tile Mastic	150	SF	1st Floor Teacher's Lunchroom, 005	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
9D	12" x 12" Mottled Brown Floor Tile Mastic		SF	3rd Floor South Corridor	ASSUMED	MISC				SF				
9E	12" x 12" Brownish Gold Floor Tile Mastic	1,400	SF	2nd Floor Corridors,	CHR	MISC	N	NONE	0	SF	No	ACBM with the		LOW

Chicago Public Schools

School Burroughs School Unit 22481 Building ID 2540

Address 3542 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date **7/12/2022**
Inspector Name **Benyamen Maradkel**
100-20411 **5/15/2023**
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10A	Not observed 2022
11	
12	
13	
14	
14A	
15	
16	Not observed 2022
17	Not observed 2022
17A	Not observed 2022
18	Not observed 2022
19	Not observed 2022
2	
20	
21	
22	Not observed 2022
23	
24	
25	
26	
27	
28	
29	

Chicago Public Schools

School Burroughs School Unit 22481 Building ID 2540

Address 3542 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
3	
30	
31	
32	
33	
34	
35	Inaccessible 2022
36	Damage located in the basement - south stairs
37	Damage located in the basement - south stairs
38	
39	
40	
41	
42	Damage in 3rd floor south corridor & lunchroom office
43	
44	
45	
4A	Not observed in Room 206 in 2022
4B	Not observed 2022
4C	Not observed 2022
4D	Not observed 2022
5A	
5B	
5C	
5D	Not observed 2022
5E	
5F	
5G	Not observed 2022
5H	Not observed 2022

Chicago Public Schools

School Burroughs School Unit 22481 Building ID 2540

Address 3542 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
5I	Not observed in Room 006 in 2022
5J	Demolished
6A	Not observed 2022
7	
8A	
8B	Not observed 2022
8C	Not observed 2022
8D	Not observed 2022
9A	
9B	
9C	
9D	Not observed 2022
9E	
9F	Damage in teacher's lunchroom
9G	Not observed 2022
9H	Not observed 2022
9I	
9J	Demolished - Not observed 2022
E	
F	Damage in basement hallway
G	
I	
J	
K	
L	
M	

Chicago Public Schools

School Burroughs School **Unit** 22481 **Building ID** 2540

Address 3542 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Burroughs School
Address 3542 S. Washtenaw

Unit 22481
Chicago, IL, 60632

Building ID 2540
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Hard plaster			Throughout	No ACBM	SURFACE					
10A	Red linoleum mastic		SF	1st and 2nd Floor Plumbing Rooms	Chrysotile	MISC			SF		Follow O&M Plan
11	Carpet mastic			Principal's Office and Room 206	No ACBM	MISC					
12	Green linoleum			Room 101 and Basement	No ACBM	MISC					
13	Wall stucco			Basement	No ACBM	MISC					
14	Black baseboard			Room 006	No ACBM	MISC					
14A	Black baseboard adhesive			Room 006	No ACBM	MISC					
15	Green linoleum			Rooms 203, 206	No ACBM	MISC					
16	Brown linoleum			Principal's Office - Under 9'"x9'" FT, 1st Floor Corridor	No ACBM	MISC					
17	Green floor tile		SF	Lunchroom	Assumed	MISC			SF		Follow O&M Plan
17A	Yellow mastic under green floor tile			Lunchroom	No ACBM	MISC					
18	Brown brick - Non-AHERA			Exterior of Building	No ACBM	MISC					
19	Brick mortar - Non-AHERA			Exterior of Building	No ACBM	MISC					
2	1' x 1' Ceiling tile			Classrooms	No ACBM	MISC					
20	Exterior window glaze - Non-AHERA			Exterior of Field House	Chrysotile	MISC					Follow O&M Plan
21	Roof Flashing - non - AHERA				Assumed	MISC					Follow O&M Plan
22	Roof field -Non-AHERA				No ACBM	MISC					
23	12" x 12" blue floor tile	1,200	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" blue floor tile mastic	1,200	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Chalk boards	1,550	SF	301, 302, 306, Library, 201, 202, 203, 204, 205, 206, 104, 105, 106, 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12" x 12" White Vinyl Floor Tile	486	SF	Module Corridor and Classes, 006	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" x 12" White Vinyl Floor Tile Mastic	486	SF	Module Corridor and Classes, 006	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Beige baseboard	108	SF	Module Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Beige baseboard mastic	108	SF	Module Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3	2' x 4' Ceiling Tile			Classrooms	No ACBM	MISC					
30	2' x 2' Ceiling Tile	2,000	SF	Module Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Blue linoleum	130	SF	Boys Bathroom module	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Blue linoleum mastic	130	SF	Boys Bathroom module	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Red linoleum	130	SF	Girls Bathroom module	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Red linoleum mastic	130	SF	Girls Bathroom module	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Incinerator flue liner	50	LF	Boiler room, Tank room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
36	Brown stair tread	500	SF	North and South Stairs	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair

Chicago Public Schools

School Burroughs School

Unit 22481

Building ID 2540

Address 3542 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37	Brown stair tread mastic	500	SF	North and South Stairs	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
38	12" x 12" White w/ Beige Specks Floor Tile	200	SF	3rd floor south corridor, 002	Assumed	SURFACE	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
39	12" x 12" Lime Green w/ Green Specks Floor Tile	200	SF	3rd floor south corridor, 002	Assumed	SURFACE	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
40	12" x 12" Blonde w/ White Specks Floor Tile	200	SF	3rd floor south corridor, 002	Assumed	SURFACE	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
41	12" x 12" White w/ Beige Specks (HA 38) & 12" x 12" Lime Green w/ Green Specks (HA 39) & 12" x 12" Blonde w/ White Specks (HA 40) Floor Tile Mastic	600	SF	3rd floor south corridor, 002	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" Dark Blue Floor Tile	100	SF	Lunchroom, lunchroom office, 3rd floor south corridor, 1st floor plumbing closet	Assumed	MISC	No	7	SF	5 ACBM with potential for significant damage	Repair
43	12" x 12" Dark Blue Floor Tile Mastic	100	SF	Lunchroom, lunchroom office, 3rd floor south corridor, 1st floor plumbing closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	9" x 9" Gray Floor Tile	100	SF	Engineer's Office	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
45	9" x 9" Gray Floor Tile Mastic	100	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4A	9" x 9" Tan Floor Tile	1,200	SF	Rooms 203 and 206	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4B	9" x 9" Brownish/Pink Floor Tile		SF	Main Office	Chrysotile	MISC			SF		Follow O&M Plan
4C	9" x 9" Brown Floor Tile		SF	Basement Floor Room 004	Chrysotile	MISC			SF		Follow O&M Plan
4D	9" x 9" Green Floor Tile w/Black Specks		SF	Engineer's Office	Chrysotile	MISC			SF		Follow O&M Plan
5A	12" x 12" Speckled Brown Floor Tile	500	SF	3rd Floor Stage, 3rd floor north corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5B	12" x 12" Brown w/White Specks Floor Tile	300	SF	1st Floor Teacher's Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5C	12" x 12" Beige w/White Specks Floor Tile	150	SF	1st Floor Teacher's Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5D	12" x 12" Mottled Brown Floor Tile		SF	3rd Floor South Corridor	Assumed	MISC			SF		Follow O&M Plan
5E	12" x 12" Brownish Gold Floor Tile	1,400	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5F	12" x 12" Off-White w/Brown Specks Floor Tile	2,400	SF	1st and 2nd FI Corridors and Room 205, 1st fl teachers lunch Room, Libuary store Rm (see Mgr comments), 005	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5G	12" x 12" Dark Gray Floor Tile		SF	Lunchroom	Assumed	MISC			SF		Follow O&M Plan
5H	12" x 12" Tan Floor Tile		SF	Library storage	Assumed	MISC			SF		Follow O&M Plan
5I	12" x 12" Off-White w/Brown Specks Floor Tile	1,800	SF	1st and 2nd Floor Corridors, Rooms 006 and 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5J	12" x 12" Off-White Floor Tile			Fieldhouse Bathrooms	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Burroughs School
Address 3542 S. Washtenaw

Unit 22481
 Chicago, IL, 60632

Building ID 2540
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
6A	Red linoleum		SF	1st and 2nd Floor Plumbing Room	Chrysotile	MISC			SF		Follow O&M Plan
7	Adhesive on 1' x 1' Ceiling Tile	400	SF	Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8A	9" x 9" Tan Floor Tile Mastic	1,200	SF	Rooms 203	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8B	9" x 9" Brownish/Pink Floor Tile Mastic		SF	Principal's Office	Chrysotile	MISC			SF		Follow O&M Plan
8C	9" x 9" Brown Floor Tile Mastic		SF	Basement Room 004	Chrysotile	MISC			SF		Follow O&M Plan
8D	9" x 9" Green Floor Tile w/Black Specks Mastic		SF	Engineer's office	Chrysotile	MISC			SF		Follow O&M Plan
9A	12" x 12" Brown Speckled Floor Tile Mastic	500	SF	3rd Floor Stage, 3rd floor north corridor, 305 closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9B	12" x 12" Brown w/White Specks Floor Tile Mastic	300	SF	1st Floor Teacher's Lunchroom, 005	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9C	12" x 12" Beige w/White Specks Floor Tile Mastic	150	SF	1st Floor Teacher's Lunchroom, 005	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9D	12" x 12" Mottled Brown Floor Tile Mastic		SF	3rd Floor South Corridor	Assumed	MISC			SF		Follow O&M Plan
9E	12" x 12" Brownish Gold Floor Tile Mastic	1,400	SF	2nd Floor Corridors, 1st Floor Teacher's Lunchroom, 2nd Floor Teacher's Rest Room,	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9F	12" x 12" Off-White w/Brown Specks Floor Tile Mastic	2,400	SF	2nd Floor Corridors and Room 205, 1st F Teacher's Lunch Room, 2nd Floor Teacher's Bathroom, (See Mgr comments), 305 closet	Chrysotile	MISC	No	6	SF	6 ACBM with the potential for damage	Repair
9G	12" x 12" Dark Gray Floor Tile Mastic		SF	Lunch room	Chrysotile	MISC			SF		Follow O&M Plan
9H	12" x 12" Tan Floor Tile Mastic		SF	Library Storage	Chrysotile	MISC			SF		Follow O&M Plan
9I	12" x 12" Off-White w/Brown Specks Floor Tile Mastic	1,800	SF	2nd Floor Corridors and Room 205	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9J	12" x 12" Off-White Floor Tile Mastic			Fieldhouse Bathroom	Assumed	MISC					Follow O&M Plan
E	Air cell duct insulation	400	SF	Basement, Corridor, Room 006,	Chrysotile	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Cardboard pipe insulation	220	SF	Basement Storage, Boiler Room, Basement Hallway	Chrysotile	TSI	Yes	2	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Encapsulate
G	Fittings off cardboard pipe insulation	30	LF	Basement Storage, Boiler Room, Basement Hallway	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Vibration collar	5	SF	Lunch room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	Boiler gaskets			Boiler Room	No ACBM	MISC					
K	Cementitious pipe fittings off city water line	10	FITTING	Basement Store Room	Chrysotile	TSI	Yes	0	FITTING	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Valve headers	25	LF	Tank Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Fittings on Fiberglass Pipe Insulation			Basement	No ACBM	MISC					

Chicago Public Schools

School Burroughs School
Address 3542 S. Washtenaw

Unit 22481
 Chicago, IL, 60632

Building ID 2540
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	7/14/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10A	
11	
12	
13	
14	
14A	

Chicago Public Schools

School Burroughs School
Address 3542 S. Washtenaw

Unit 22481
Chicago, IL, 60632

Building ID 2540
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
15	
16	
17	
17A	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	

Chicago Public Schools

School Burroughs School
Address 3542 S. Washtenaw

Unit 22481
 Chicago, IL, 60632

Building ID 2540
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
39	
40	
41	
42	Sample to determine ACM content.
43	
44	
45	
4A	
4B	
4C	
4D	
5A	
5B	
5C	
5D	
5E	
5F	
5G	
5H	
5I	
5J	
6A	
7	
8A	
8B	
8C	
8D	

Chicago Public Schools

School Burroughs School
Address 3542 S. Washtenaw

Unit 22481
Chicago, IL, 60632

Building ID 2540
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
9A	
9B	
9C	
9D	
9E	
9F	
9G	
9H	
9I	
9J	
E	
F	
G	
I	
J	
K	
L	
M	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Hard plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Hard plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **Red linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Plumbing Rooms**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **Red linoleum mastic**
MATERIAL LOCATION: **1st and 2nd Floor Plumbing Rooms**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principal's Office and Room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Carpet mastic**

MATERIAL LOCATION: **Principal's Office and Room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Green linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101 and Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Green linoleum**

MATERIAL LOCATION: **Room 101 and Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Wall stucco**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Wall stucco**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Black baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 006**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Black baseboard**

MATERIAL LOCATION: **Room 006**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **Black baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 006**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **14A**

MATERIAL DESCRIPTION: **Black baseboard adhesive**

MATERIAL LOCATION: **Room 006**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Green linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 203, 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Green linoleum**

MATERIAL LOCATION: **Rooms 203, 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Brown linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principal's Office - Under 9"x9" FT, 1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Brown linoleum**

MATERIAL LOCATION: **Principal's Office - Under 9'"x9'" FT, 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Green floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Green floor tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **Yellow mastic under green floor tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **17A**

MATERIAL DESCRIPTION: **Yellow mastic under green floor tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Brown brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Brown brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Brick mortar - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Brick mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **1' x 1' Ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **1' x 1' Ceiling tile**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Exterior window glaze - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Field House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Exterior window glaze - Non-AHERA**

MATERIAL LOCATION: **Exterior of Field House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Roof Flashing - non - AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Roof Flashing - non - AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Roof field -Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Roof field -Non-AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" blue floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" blue floor tile**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" blue floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" blue floor tile mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Chalk boards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **301, 302, 306, Library, 201, 202, 203, 204, 205, 206, 104, 105, 106, 101**
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Chalk boards**
MATERIAL LOCATION: **301, 302, 306, Library, 201, 202, 203, 204, 205, 206, 104, 105, 106, 101**
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Module Corridor and Classes, 006**

MATERIAL QUANTITY: **486**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile**

MATERIAL LOCATION: **Module Corridor and Classes, 006**

MATERIAL QUANTITY: **486**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Module Corridor and Classes, 006**
MATERIAL QUANTITY: **486** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Module Corridor and Classes, 006**
MATERIAL QUANTITY: **486** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Beige baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Module Corridor**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Beige baseboard**

MATERIAL LOCATION: **Module Corridor**

MATERIAL QUANTITY: **108**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Beige baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Module Corridor**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Beige baseboard mastic**

MATERIAL LOCATION: **Module Corridor**

MATERIAL QUANTITY: **108**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Module Throughout**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**
MATERIAL LOCATION: **Module Throughout**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Blue linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boys Bathroom module**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Blue linoleum**
MATERIAL LOCATION: **Boys Bathroom module**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Blue linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boys Bathroom module**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Blue linoleum mastic**
MATERIAL LOCATION: **Boys Bathroom module**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Red linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girls Bathroom module**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Red linoleum**

MATERIAL LOCATION: **Girls Bathroom module**

MATERIAL QUANTITY: **130**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Red linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girls Bathroom module**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Red linoleum mastic**

MATERIAL LOCATION: **Girls Bathroom module**

MATERIAL QUANTITY: **130**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Incinerator flue liner**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler room, Tank room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Inaccessible 2022**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Incinerator flue liner**

MATERIAL LOCATION: **Boiler room, Tank room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Brown stair tread**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North and South Stairs**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in the basement - south stairs**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Brown stair tread**

MATERIAL LOCATION: **North and South Stairs**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Brown stair tread mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North and South Stairs**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in the basement - south stairs**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Brown stair tread mastic**

MATERIAL LOCATION: **North and South Stairs**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4A**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 203 and 206**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in Room 206 in 2022**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4A**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**
MATERIAL LOCATION: **Rooms 203 and 206**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4B**
MATERIAL DESCRIPTION: **9" x 9" Brownish/Pink Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4B**

MATERIAL DESCRIPTION: **9" x 9" Brownish/Pink Floor Tile**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4C**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Floor Room 004**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4C**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **Basement Floor Room 004**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4D**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/Black Specks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4D**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/Black Specks**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A**
MATERIAL DESCRIPTION: **12" x 12" Speckled Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Stage, 3rd floor north corridor**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5A**
MATERIAL DESCRIPTION: **12" x 12" Speckled Brown Floor Tile**
MATERIAL LOCATION: **3rd Floor Stage, 3rd floor north corridor**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5B**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Teacher's Lunchroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5B**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Specks Floor Tile**
MATERIAL LOCATION: **1st Floor Teacher's Lunchroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5C**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Teacher's Lunchroom**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5C**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Specks Floor Tile**
MATERIAL LOCATION: **1st Floor Teacher's Lunchroom**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5D**
MATERIAL DESCRIPTION: **12" x 12" Mottled Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor South Corridor**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5D**

MATERIAL DESCRIPTION: **12" x 12" Mottled Brown Floor Tile**

MATERIAL LOCATION: **3rd Floor South Corridor**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5E**
MATERIAL DESCRIPTION: **12" x 12" Brownish Gold Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridors**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5E**
MATERIAL DESCRIPTION: **12" x 12" Brownish Gold Floor Tile**
MATERIAL LOCATION: **1st and 2nd Floor Corridors**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5F**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd FI Corridors and Room 205, 1st fl teachers lunch Room, Libuary store Rm (see Mgr comments), 005**

MATERIAL QUANTITY: **2400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5F**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile**
MATERIAL LOCATION: **1st and 2nd FI Corridors and Room 205, 1st fl teachers lunch Room, Libuary store Rm (see Mgr comments), 005**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5G**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5G**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5H**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library storage**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5H**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

MATERIAL LOCATION: **Library storage**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5I**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Corridors, Rooms 006 and 205**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 006 in 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5I**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile**
MATERIAL LOCATION: **1st and 2nd Floor Corridors, Rooms 006 and 205**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5J**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fieldhouse Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Demolished**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5J**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**

MATERIAL LOCATION: **Fieldhouse Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A**
MATERIAL DESCRIPTION: **Red linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Plumbing Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **6A**

MATERIAL DESCRIPTION: **Red linoleum**

MATERIAL LOCATION: **1st and 2nd Floor Plumbing Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Adhesive on 1' x 1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Adhesive on 1' x 1' Ceiling Tile**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8A**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 203**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUILDING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **8A**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 203**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**
MATERIAL DESCRIPTION: **9" x 9" Brownish/Pink Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **8B**

MATERIAL DESCRIPTION: **9" x 9" Brownish/Pink Floor Tile Mastic**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8C**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Room 004**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **8C**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Basement Room 004**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8D**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/Black Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **8D**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/Black Specks Mastic**

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9A**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Stage, 3rd floor north corridor, 305 closet**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9A**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**
MATERIAL LOCATION: **3rd Floor Stage, 3rd floor north corridor, 305 closet**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9B**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Teacher's Lunchroom, 005**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9B**

MATERIAL DESCRIPTION: **12" x 12" Brown w/White Specks Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Teacher's Lunchroom, 005**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9C**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Teacher's Lunchroom, 005**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9C**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Teacher's Lunchroom, 005**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9D**
MATERIAL DESCRIPTION: **12" x 12" Mottled Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor South Corridor**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9D**

MATERIAL DESCRIPTION: **12" x 12" Mottled Brown Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor South Corridor**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9E**
MATERIAL DESCRIPTION: **12" x 12" Brownish Gold Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridors, 1st Floor Teacher's Lunchroom, 2nd Floor Teacher's Rest Room,**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9E**
MATERIAL DESCRIPTION: **12" x 12" Brownish Gold Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Corridors, 1st Floor Teacher's Lunchroom, 2nd Floor Teacher's Rest Room,**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9F**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridors and Room 205, 1st F Teacher's Lunch Room, 2nd Floor Teacher's Bathroom, (See Mgr comments), 305 closet**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in teacher's lunchroom**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9F**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Corridors and Room 205, 1st F Teacher's Lunch Room, 2nd Floor Teacher's Bathroom, (See Mgr comments), 305 closet**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9G**
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9G**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile Mastic**

MATERIAL LOCATION: **Lunch room**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9H**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library Storage**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9H**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Library Storage**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9I**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridors and Room 205**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9I**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Corridors and Room 205**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9J**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fieldhouse Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Demolished - Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9J**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile Mastic**

MATERIAL LOCATION: **Fieldhouse Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Air cell duct insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement, Corridor, Room 006,**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Air cell duct insulation**
MATERIAL LOCATION: **Basement, Corridor, Room 006,**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACM or friable suspect ACM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Storage, Boiler Room, Basement Hallway**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in basement hallway**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
MATERIAL LOCATION: **Basement Storage, Boiler Room, Basement Hallway**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fittings off cardboard pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Storage, Boiler Room, Basement Hallway**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fittings off cardboard pipe insulation**
MATERIAL LOCATION: **Basement Storage, Boiler Room, Basement Hallway**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Vibration collar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch room**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Vibration collar**

MATERIAL LOCATION: **Lunch room**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Boiler gaskets**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Boiler gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Cementitious pipe fittings off city water line**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Store Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Cementitious pipe fittings off city water line**

MATERIAL LOCATION: **Basement Store Room**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Valve headers**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Valve headers**
MATERIAL LOCATION: **Tank Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUIDLING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUILDING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12" x 12" Blonde w/ White Specks Floor Tile**
MATERIAL LOCATION: **3rd floor south corridor, 002**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUILDING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Specks Floor Tile**
MATERIAL LOCATION: **3rd floor south corridor, 002**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUILDING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12" x 12" Lime Green w/ Green Specks Floor Tile**
MATERIAL LOCATION: **3rd floor south corridor, 002**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUILDING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Specks (HA 38) & 12" x 12" Lime Green w/ Green Specks (HA 39) & 12" x 12" Blonde w/ White Specks (HA 40) Floor Tile Mastic**

MATERIAL LOCATION: **3rd floor south corridor, 002**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUILDING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Floor Tile Mastic**
MATERIAL LOCATION: **Lunchroom, lunchroom office, 3rd floor south corridor, 1st floor plumbing closet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUILDING ID: **2540**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Burroughs School** INSPECTION DATE: **7/12/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Floor Tile**
MATERIAL LOCATION: **Lunchroom, lunchroom office, 3rd floor south corridor, 1st floor plumbing closet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **Significantly Damaged**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **7** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
Damage in 3rd floor south corridor & lunchroom office

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUILDING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Floor Tile**
MATERIAL LOCATION: **Lunchroom, lunchroom office, 3rd floor south corridor, 1st floor plumbing closet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **7** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content.

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22481** BUILDING ID: **2540**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Burroughs School** REVIEW DATE: **7/14/2022**
ADDRESS: **3542 S. Washtenaw** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/14/2022**

APPENDIX B

Inspector and Management Planner Licenses

Benyamen Maradkel

Illinois Licensed Building Inspector



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 20411

ISSUED
3/17/2022

EXPIRES
05/15/2023

BENYAMEN C MARADKEL
706 W HACKBERRY DR
ARLINGTON HEIGHTS, IL 6000
Environmental Health



ENDORSEMENTS

INSPECTOR

EXPIRES

5/9/2023

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Benyamen Maradkel

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090703

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed