# ILLINOIS DEPARTMENT OF PUBLIC HEALTH AHERA THREE YEAR REINSPECTION ASBESTOS ABATEMENT PROGRAM SCHOOL INFORMATION FORM

14-016-2990-2120

CHICAGO SCHOOL DIST 299

### **SECTION I**

IL-482-1026

NAME OF SCHOOL DISTRICT:

SCHOOL ID NUMBER:

**SCHOOL NAME:** Carnegie School ADDRESS OF SCHOOL: 1414 E. 61st Place CITY: Chicago, IL, 60637 DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 8/30/2019 If the address on this form is different than the address of the building, submit a written explanation. **SECTION II** (Please type or print) PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION: DATE REINSPECTION COMPLETED: 8/31/2022 ENROLLMENT 437 IDPH INSPECTOR LICENSE NUMBER: 100-20640 IDPH LICENSED INSPECTOR NAME (Please Print): Mike Di Canio IDPH MP LICENSE NUMBER: 100-01784 IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074 9/6/2022 Richard J. Schliger Signature of Designated Person Date **SECTION III** PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT. School building has been sold. Date of Sale: School has been closed. Date closed: School building has been demolished. Date: School building is <u>asbestos free</u> since last reinspection: Please explain in writing why the school building is now asbestos free and include the supporting documentation. If a new school building has been added to the district, submit either and exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building. Explain in writing if the address of the building is different than the address on this form:

Revised 10.03

#### THREE-YEAR REINSPECTION

#### **CHICAGO SCHOOL DIST 299**

### **Carnegie School**

1414 E. 61st Place Chicago, IL, 60637

Unit: 22551 Building ID: 2630

IDPH ID Number: 14-016-2990-2120

#### **REPORT DATE:**

Tuesday, September 06, 2022

Prepared for: Chicago Public Schools 42 W. Madison Street Chicago, IL 60602

Prepared by: TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

# DO NOT REMOVE FROM SCHOOL REQUIRED BY FEDERAL LAW

#### 09/02/2022

Mr.Eric Culbertson Asbestos Program Illinois Department of Public Health 525 West Jefferson Street Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr.Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22551 Region: 05 IDPH ID: 14-016-2990-2120

School: Carnegie School Building ID: 2630

Address: 1414 E. 61st Place

Chicago, IL, 60637

Building Contact: Ortiz, Alejandro Contact Phone: 7732168322

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/31/2022

Review Date: 09/02/2022

Inspector: Mike Di Canio Inspector IDPH License: 100-20640

Management Planner: Steven Geneser Management Planner IDPH License: 100-01784

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,

TEM Environmental, Inc.

Stoven B Genee

Steven Geneser 100-01784

### **Environmental Notification to Occupants**

To: Faculty, Staff and Parents From: Chicago Public Schools Date: September 06, 2022

RE: Carnegie School, Unit 22551

1414 E. 61st Place Chicago, IL, 60637

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Carnegie School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Carnegie School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

#### **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

#### **APPENDICES**:

Appendix A: Assessment Sheets, Drawings and Photos

Appendix B: Inspector and Management Planner Licenses

Appendix C: Laboratory Accreditations

Appendix D: Laboratory Results

Appendix E: Chain of Custody Forms

#### SCHOOL AND INSPECTION INFORMATION

#### 1. School Information

School: Carnegie School Unit: 22551 Region: 05

 Address:
 1414 E. 61st Place
 Chicago, IL, 60637

 IDPH ID:
 14-016-2990-2120
 Building ID: 2630

 Contact:
 Ortiz, Alejandro
 Phone: 7732168322

#### 2. Description of Facility

Original Construction: 2001 Additional Construction: 1957,1996

Total Square Footage: 17980 No of Floors: 2

Current Occupancy: 437

#### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074

Address: 42 West Madison Street

Chicago, IL 60602

#### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc. Contact: Steven Geneser Address 174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

#### 5. Inspector

Inspector Name: Mike Di Canio

Signature:

Michel Di Ca.

Inspector IDPH license # 100-20640 Date: 8/31/2022 Reinspection Date: 8/31/2022

#### 6. Management Planner

Management Planner Name: Steven Geneser

Signature:
Date: 09/02/2022

Management Planner IDPH license # 100-01784

Richard J. Schliger

#### 7. Review Date: 09/02/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:

Date: 9/6/2022

Name: Richard J.Schleyer

### **II. EXECUTIVE SUMMARY**

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Carnegie School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2630:

NEW Newly Installed Suspect ACM

Unit: 22551 Carnegie School Building: 2630

B. The following new homogenous areas have been identified for Building 2630:							
NEW	Newly Installed Suspect ACM						

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	1x1 Acoustical Tile
04A	12x12 Blue Floor Tile
04B	12x12 Gray Floor Tile
04D	12x12 Pink Floor Tile
04E	12x12 Red Floor Tile
09	Black Border Board Floor Tile Mastic
16	12x12 Beige w/Brown Specks
16A	12x12 Beige w/Brown Specks Mastic
17A	12x12 Red Floor Tile
17B	12x12 Red Floor Tile Mastic
18	12"x12" Blue Floor Tile
19	Mastic associated with 12"x12" Blue Floor Tile
20	Whiteboard Adhesive
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

05	9x9 Brown Floor Tile Black Mastic
07	12x12 Brown Floor Tile Mastic
07F	12x12 Light Pink Floor Tile Mastic
09	Black Border Board Floor Tile Mastic
10	9x9 Brown w/Speckles Floor Tile
10A	9x9 Brown w/Speckles Floor Tile Mastic
11	Gray Carpet Mastic
13	Brown Carpet Mastic
16A	12x12 Beige w/Brown Specks Mastic
17B	12x12 Red Floor Tile Mastic
19	Mastic associated with 12"x12" Blue Floor Tile
20	Whiteboard Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mike Di Canio, IDPH License # 100-20640. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

### III. METHODOLOGY

Tasks performed on-site included the following:

- 1. Review current management plan, identify HA(s) and extract appropriate information.
- 2. Examine and verify abatement records.
- 3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
- 4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
- 5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
- 6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
- 7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
- 8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

#### IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 6/30/2022 6/30/2022

#### V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### VI. CONCLUSIONS

The Carnegie School Building 2630 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

# **Table I Inspector's Reinspection Findings**

**School** Carnegie School **Unit** 22551 **Building ID** 2630 **Address** 1414 E. 61st Place **Region** 05

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	1x1 Acoustical Tile	4,000	SF	Gym, Assembly, Assembly Hall, Lobby	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
03	9x9 Brown Floor Tile	3,300	SF	Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	12x12 Brown Floor Tile	1,140	SF	1st & 2nd Floor Halls, Engineer's Office, and 2nd Floor Teachers' Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04A	12x12 Blue Floor Tile	200	SF	1st Floor Counselor's Office (Room 121)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04B	12x12 Gray Floor Tile	200	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04D	12x12 Pink Floor Tile	275	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04E	12x12 Red Floor Tile	100	SF	Room 128	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04F	12x12 Light Pink Floor Tile	800	SF	Lunchroom, Main Office, Principal's Office, Principal's Washroom	CHR	MISC	N	LOC	5		No	ACBM with the potential for damage		LOW
05	9x9 Brown Floor Tile Black Mastic	3,300	SF	Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	12x12 Brown Floor Tile Mastic	1,000	SF	1st & 2nd Floor Halls, and 2nd Floor Teachers' Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	12x12 Blue Floor Tile Mastic- No ACBM			1st Floor Counselor's Office (Room 121)	NO_ACBM	MISC								
07B	12x12 Gray Floor Tile Mastic- No ACBM			Room 108	NO_ACBM	MISC								
07D	12x12 Pink Floor Tile Mastic- No ACBM			Kitchen	NO_ACBM	MISC								
07E	12x12 Red Floor Tile Mastic- No ACBM			Room 128	NO_ACBM	MISC								
07F	12x12 Light Pink Floor Tile Mastic	800	SF	Lunchroom, Main Office, Principal's Office, Principal's Washroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Black Border Board Floor Tile	1,200	LF	1st & 2nd Floor Hallway, Throughout Classrooms	CHR	MISC	N	DIST	10		No	ACBM with the potential for damage		LOW
09	Black Border Board Floor Tile Mastic	1,200	LF	1st & 2nd Floor Hallway,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

**School** Carnegie School **Unit** 22551 **Building ID** 2630 **Address** 1414 E. 61st Place **Region** 05

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Throughout Classrooms										
10	9x9 Brown w/Speckles Floor Tile	75	SF	Principal's Washroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10A	9x9 Brown w/Speckles Floor Tile Mastic	75	SF	Principal's Washroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Gray Carpet Mastic	1,200	SF	Room 203	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Gray Carpet Mastic DUPLICATE HA			Room 203 DUPLICATE HA 11	CHR	MISC	N							
13	Brown Carpet Mastic	900	SF	2nd Floor Teachers' Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Red Carpet Mastic NOT OBSERVED			Room 120	CHR	MISC								
15	Red Carpet Mastic NOT OBSERVED			Main Office	CHR	MISC								
16	12x12 Beige w/Brown Specks	55	SF	2nd Floor Teachers' Lounge	ASSUMED	MISC	N	LOC			No	ACBM with the potential for damage		MODERATE
16A	12x12 Beige w/Brown Specks Mastic	55	SF	2nd Floor Teachers' Lounge Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	12x12 Red Floor Tile	340	SF	Room 120	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17B	12x12 Red Floor Tile Mastic	340	SF	Room 120	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"x12" Blue Floor Tile	350	SF	Room 203	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Mastic associated with 12"x12" Blue Floor Tile	350	SF	Room 203	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Whiteboard Adhesive	30	SF		ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

**School** Carnegie School **Unit** 22551 **Building ID** 2630 **Address** 1414 E. 61st Place **Region** 05

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/31/2022

Inspector Name Mike Di Canio

<u>100-20640</u> <u>5/15/2023</u>

Inspector's IDPH License Number / Expiration Date

### **Inspector's Comments**

HA Number:	Inspector Comments:
01	1
03	
04	2nd Floor Teachers' Lounge Sampled
04A	
04B	
04D	
04E	
04F	Main Office Completely Abated. Damage in Lunchroom.
05	
07	2nd Floor Teachers' Lounge Sampled
07A	
07B	
07D	
07E	
07F	Main Office Completely abated
08	
09	
10	Not Observed. Covered with 12"x12" Pink Tile
10A	Not Observed. Covered with 12"x12" Pink Tile
11	
12	Duplicate of HA 11
13	
14	Not Observed
15	Not Observed

**School** Carnegie School **Unit** 22551 **Building ID** 2630 **Address** 1414 E. 61st Place **Region** 05

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
16	Floor tiles chipped and cracked but intact
16A	
17A	
17B	
18	
19	
20	
NEW	

### Table II

### **Management Planner's Review**

SchoolCarnegie SchoolUnit22551Building ID2630

Address1414 E. 61st PlaceChicago, IL, 60637Region05

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

	Motorial Decaription				management Flaimer's Comments Summanzed at the Lind of the Report							
	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response	
Num		Quantity	Units		Type	Category		Quantity	Units			
01 1)	1x1 Acoustical Tile	4,000	SF	Gym, Assembly, Assembly Hall, Lobby	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
03 9x	9x9 Brown Floor Tile	3,300	SF	Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
04 12	12x12 Brown Floor Tile	1,140	SF	1st & 2nd Floor Halls, Engineer's	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
				Office, and 2nd Floor Teachers' Lounge	-							
04A 12	12x12 Blue Floor Tile	200	SF	1st Floor Counselor's Office (Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
				121)								
	12x12 Gray Floor Tile	200	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
	12x12 Pink Floor Tile	275	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
04E 12	12x12 Red Floor Tile	100	SF	Room 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
04F 12	12x12 Light Pink Floor Tile	800	SF	Lunchroom, Main Office, Principal's	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Repair	
				Office, Principal's Washroom								
05 9>	9x9 Brown Floor Tile Black Mastic	3,300	SF	Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
07 12	12x12 Brown Floor Tile Mastic	1,000	SF	1st & 2nd Floor Halls, and 2nd Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
				Teachers' Lounge								
07A 12	12x12 Blue Floor Tile Mastic- No ACBM			1st Floor Counselor's Office (Room	No ACBM	MISC						
				121)								
	12x12 Gray Floor Tile Mastic- No ACBM			Room 108	No ACBM	MISC						
	12x12 Pink Floor Tile Mastic- No ACBM			Kitchen	No ACBM	MISC						
07E 12	12x12 Red Floor Tile Mastic- No ACBM			Room 128	No ACBM	MISC						
07F 12	12x12 Light Pink Floor Tile Mastic	800	SF	Lunchroom, Main Office, Principal's	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
				Office, Principal's Washroom	-					•		
08 BI	Black Border Board Floor Tile	1,200	LF	1st & 2nd Floor Hallway, Throughout	Chrysotile	MISC	No	10	LF	6 ACBM with the potential for damage	Repair	
				Classrooms	-					•	· ·	
09 BI	Black Border Board Floor Tile Mastic	1,200	LF	1st & 2nd Floor Hallway, Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan	
				Classrooms								
10 9x	9x9 Brown w/Speckles Floor Tile	75	SF	Principal's Washroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
10A 9x	9x9 Brown w/Speckles Floor Tile Mastic	75	SF	Principal's Washroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
11 G	Gray Carpet Mastic	1,200	SF	Room 203	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
12 G	Gray Carpet Mastic DUPLICATE HA			Room 203 DUPLICATE HA 11	Chrysotile	MISC	No					
13 Br	Brown Carpet Mastic	900	SF	2nd Floor Teachers' Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
14 R	Red Carpet Mastic NOT OBSERVED			Room 120	Chrysotile	MISC				-		
15 R	Red Carpet Mastic NOT OBSERVED			Main Office	Chrysotile	MISC						
16 12	12x12 Beige w/Brown Specks	55	SF	2nd Floor Teachers' Lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan	
	12x12 Beige w/Brown Specks Mastic	55	SF	2nd Floor Teachers' Lounge Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	
	12x12 Red Floor Tile	340	SF	Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan	

SchoolCarnegie SchoolUnit22551Building ID2630

Address 1414 E. 61st Place Chicago, IL, 60637 Region 05

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	90111011		<b>-</b>	nonco Gannianizoa at tirt	
HA	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Num		Quantity	Units		Type	Category		Quantity	Units		
17B	12x12 Red Floor Tile Mastic	340	SF	Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Blue Floor Tile	350	SF	Room 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Mastic associated with 12"x12" Blue Floor Tile	350	SF	Room 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Whiteboard Adhesive	30	SF		Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
				Management Plan and After							
				Renovations							

SchoolCarnegie SchoolUnit22551Building ID2630

Chicago, IL, 60637

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

Region 05

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

Review Date	9/2/2022						
Manager Planner Name	Steven Geneser						
100-01784	5/15/2023						
Manager IDPH License N	o/Expiration						

Address 1414 E. 61st Place

HA Number	Management Comments
01	
03	
04	
04A	
04B	
04D	
04E	
04F	
05	
07	
07A	
07B	
07D	
07E	
07F	
08	
09	
10	
10A	
11	
12	
13	
14	
15	
16	
16A	

 School
 Carnegie School
 Unit
 22551
 Building ID
 2630

 Address
 1414 E. 61st Place
 Chicago, IL, 60637
 Region
 05

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
17A	
17B	
18	
19	
20	
NEW	

# APPENDIX A

# **Assessment Sheets, Drawings and Photos**

TEM Environmental, Inc. 2022 AHERA REINSPECTION

# TEM Environmental, Inc. 2022 AHERA REINSPECTION Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 01

MATERIAL DESCRIPTION: 1x1 Acoustical Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: Yes

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Gym, Assembly, Assembly Hall, Lobby

MATERIAL QUANTITY: 4000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID:	2630	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser		
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640		
HOMOGENEOUS A	REA:	01					
MATERIAL DESCRI	PTION:	1x1 Acoustical 1	Гile				
MATERIAL LOCATION	ON:	Gym, Assembly	, Assembly Hall, Lo	bby			
MATERIAL QUANTI	TY:	4000			MATERIAL UNIT	S:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	i:	SF
n accordance with Semanagement planner original inspection of the following recommon.  The RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	mmend appropria	ite respo	
Follow O&M Plan							
Comments:							
Management Plan	norlo Ciar	Stav	en B Genes	_	Data	00/02/24	22
wanayement Plan	ners sign	iaiuie.			Date:	09/02/20	JLL

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03

MATERIAL DESCRIPTION: 9x9 Brown Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Gym

MATERIAL QUANTITY: 3300 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	Date:	08/31/2022
		00.01,=0==

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640	
HOMOGENEOUS A	REA:	03				
MATERIAL DESCRI	PTION:	9x9 Brown Floor	Tile			
MATERIAL LOCATION	ON:	Gym				
MATERIAL QUANTI	TY:	3300			MATERIAL UNITS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS:	SF
management planner	to review t he above i	he results of the in	spection and assess	ment and reco	Response Act (AHERA) the ommend appropriate respondence with Sections 7	onse actions. The
The RESPONSE AC	TION reco	mmendation is:				
Follow O&M Plan						
Comments:						
Management Plan	ner's Siar	nature: Stave	n B Geree	_	Date: 09/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04

MATERIAL DESCRIPTION: 12x12 Brown Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1st & 2nd Floor Halls, Engineer's Office, and 2nd Floor Teachers' Lounge

MATERIAL QUANTITY: 1140 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: 2nd Floor Teachers' Lounge Sampled

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	
Inspector's Signature:	Mudel	Vilai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 26	630	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser		
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	<b>)</b> :	100-20640		
HOMOGENEOUS A	REA:	04					
MATERIAL DESCRI	PTION:	12x12 Brown Flo	oor Tile				
MATERIAL LOCATION	ON:	1st & 2nd Floor	Halls, Engineer's O	ffice, and 2nd	Floor Teachers' Lo	ounge	
MATERIAL QUANTI	TY:	1140			MATERIAL UNITS	: SF	
DAMAGE QUANTIT	Υ:	0			DAMAGE UNITS:	SF	
management planner	to review the above endations.	the results of the ir identified homoger	nspection and assess	sment and reco	ommend appropriate	RA) the LEA must select a response actions. The ions 763.88 and 763.90 wi	
Follow O&M Plan							
Comments:							
		<b>.</b>	en B Genee				
Management Plan	ner's Sig	nature:	en Vienea	-	Date: <b>0</b> 9	9/02/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04A

MATERIAL DESCRIPTION: 12x12 Blue Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1st Floor Counselor's Office (Room 121)

MATERIAL QUANTITY: 200 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	Michiel	di Cai	Date:	08/31/2022	
				·	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID:	2630	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser		
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640		
HOMOGENEOUS A	REA:	04A					
MATERIAL DESCRI	PTION:	12x12 Blue Floor	r Tile				
MATERIAL LOCATION	ON:	1st Floor Counse	elor's Office (Room	121)			
MATERIAL QUANTI	TY:	200			MATERIAL UNIT	S:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	3:	SF
n accordance with Semanagement planner original inspection of the following recommendation.  The RESPONSE AC	to review the above endations.	the results of the in identified homoger	spection and assess	ment and reco	ommend appropria	ite respo	
Follow O&M Plan							
Comments:							
		Ο.	in B Geree				
Management Plan	ner's Sigr	nature:	in Where		Date:	09/02/20	)22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04B

MATERIAL DESCRIPTION: 12x12 Gray Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 108

MATERIAL QUANTITY: 200 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	Mirle	di Cai	r	Date:	08/31/2022	
inspector's Signature.			I.	Date.	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		•	•			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	)
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NC	:	100-20640	
HOMOGENEOUS A	REA:	04B				
MATERIAL DESCRI	PTION:	12x12 Gray Floo	or Tile			
MATERIAL LOCATION	ON:	Room 108				
MATERIAL QUANTI	TY:	200			MATERIAL UNITS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS:	SF
management planner	to review the above indations.	the results of the ir identified homoger	nspection and assess	ment and reco	ommend appropriate re	a) the LEA must select a esponse actions. The ns 763.88 and 763.90 with
Follow O&M Plan						
Comments:						
Management Plani	ner's Siar	nature:	en B Geres	_	Date: <b>09/0</b>	2/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04D

MATERIAL DESCRIPTION: 12x12 Pink Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY: 275 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	Midul	di Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			9			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640	
HOMOGENEOUS A	REA:	04D				
MATERIAL DESCRI	PTION:	12x12 Pink Floo	r Tile			
MATERIAL LOCATION	ON:	Kitchen				
MATERIAL QUANTI	TY:	275			MATERIAL UNITS:	SF
DAMAGE QUANTIT	Υ:	0			DAMAGE UNITS:	SF
management planner original inspection of t the following recomme The RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	Response Act (AHERA) the commend appropriate respure ccordance with Sections	onse actions. The
Follow O&M Plan						
Comments:						
		04	en B Genes	_		
Management Plan	nor's Sign	nature: Day	in Olai	70 (00)	Data: 00/02/2	ນດວວ

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04E

MATERIAL DESCRIPTION: 12x12 Red Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 128

MATERIAL QUANTITY: 100 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	
inspector's Signature.			Date.	00/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		•	•				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630		
CITY/STATE:	Chicago, Illinois		MANAGEMENT PLANNER:		Steven Geneser		
SCHOOL NAME:	Carnegie School		REVIEW DATE:		9/2/2022		
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640		
HOMOGENEOUS A	REA:	04E					
MATERIAL DESCRI	PTION:	12x12 Red Floor	Tile				
MATERIAL LOCATION	ON:	Room 128					
MATERIAL QUANTI	TY:	100			MATERIAL UNITS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF	
management planner	to review the above lendations.	the results of the ir identified homoger	nspection and assess	ment and reco	Response Act (AHERA) to commend appropriate respectordance with Sections	onse actions. The	
Follow O&M Plan							
Comments:							
Management Plan	ner's Sigr	nature: Star	en B Geres	-	Date: <b>09/02/</b> 2	2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04F

MATERIAL DESCRIPTION: 12x12 Light Pink Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Lunchroom, Main Office, Principal's Office, Principal's Washroom

MATERIAL QUANTITY: 800 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Main Office Completely Abated. Damage in Lunchroom.

nspector's Signature:	di Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID:	2630		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser			
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640			
HOMOGENEOUS A	REA:	04F						
MATERIAL DESCRI		12x12 Light Pink	r Floor Tile					
MATERIAL LOCATION		_	n Office, Principal's	Office. Princ	inal's Washroom	1		
MATERIAL QUANTI		800		, ee	MATERIAL UNIT		SF	
DAMAGE QUANTIT		5			DAMAGE UNITS		SF	
DAMAGE QUARTIT	١.	J			DAMAGE ONTO	·•	JI .	
In accordance with Semanagement planner original inspection of the following recommendation of the RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ite respo	nse actions. The	
Follow O&M Plan								
Comments:								
Management Plan	ner's Sia	nature: Stav	en B Genes	-	Date:	09/02/20	)22	
J	- 3							

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05

MATERIAL DESCRIPTION: 9x9 Brown Floor Tile Black Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Gym

MATERIAL QUANTITY: 3300 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Midul	di Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		•				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640	
HOMOGENEOUS A	REA:	05				
MATERIAL DESCRI	PTION:	9x9 Brown Floor	Tile Black Mastic			
MATERIAL LOCATION	ON:	Gym				
MATERIAL QUANTI	TY:	3300			MATERIAL UNITS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF
management planner	to review he above endations.	the results of the ir identified homoger	spection and assess	ment and reco	Response Act (AHERA) ommend appropriate res ccordance with Sections	
Follow O&M Plan						
Comments:						
		Stan	en B Genes	_	_	
Management Plan	ner's Sigı	nature:			Date: <b>09/02</b> /	/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07

MATERIAL DESCRIPTION: 12x12 Brown Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1st & 2nd Floor Halls, and 2nd Floor Teachers' Lounge

MATERIAL QUANTITY: 1000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: 2nd Floor Teachers' Lounge Sampled

Inspector's Signature:	Midul	di Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 263	30
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640	
HOMOGENEOUS A	REA:	07				
MATERIAL DESCRI	PTION:	12x12 Brown Flo	oor Tile Mastic			
MATERIAL LOCATION	ON:	1st & 2nd Floor	Halls, and 2nd Floo	r Teachers' L	ounge	
MATERIAL QUANTI	TY:	1000			MATERIAL UNITS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF
management planner	to review t he above i	he results of the in	spection and assess	ment and reco	ommend appropriate	(A) the LEA must select a response actions. The ons 763.88 and 763.90 with
The RESPONSE AC	CTION reco	mmendation is:				
Follow O&M Plan						
Comments:						
Management Plan	ner's Sigr	nature:	en B Geres	-	Date: <b>09</b> /	/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07A

MATERIAL DESCRIPTION: 12x12 Blue Floor Tile Mastic- No ACBM

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Counselor's Office (Room 121)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

nspector's Signature:	volul di Cai	Date:	08/31/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630			
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PI	_ANNER:	Steven Geneser			
SCHOOL NAME:	Carnegi	ie School	REVIEW DATE:		9/2/2022			
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	<b>)</b> :	100-20640			
HOMOGENEOUS A	REA:	07A						
MATERIAL DESCRI	PTION:	12x12 Blue Floo	r Tile Mastic- No A	СВМ				
MATERIAL LOCATI	ON:	1st Floor Couns	1st Floor Counselor's Office (Room 121)					
MATERIAL QUANTI	TY:				MATERIAL UNITS:			
DAMAGE QUANTIT	Υ:				DAMAGE UNITS:			
management planner	to review the above	the results of the ir identified homoger	nspection and asses	sment and reco	Response Act (AHERA) the LEA must select a commend appropriate response actions. The ccordance with Sections 763.88 and 763.90 with			
The RESPONSE AC	CTION rec	ommendation is:						
Comments:								
		0.	en B Geree					
Management Plan	ner's Sig	nature:	en Vieres		Date: <b>09/02/2022</b>			

#### **TEM Environmental, Inc.** 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 22551 **BUIDLING ID:** 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: INSPECTION DATE: 8/31/2022 **Carnegie School** 

1414 E. 61st Place ADDRESS: IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

07B **HOMOGENEOUS AREA:** 

MATERIAL DESCRIPTION: 12x12 Gray Floor Tile Mastic- No ACBM

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

**ASBESTOS TYPE:** No ACBM FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DAMAGE QUANTITY:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: **Room 108** 

MATERIAL QUANTITY: MATERIAL UNITS: DAMAGE UNITS:

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 22551	BUIDLING ID: 2630
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser
SCHOOL NAME:	Carnegie School	REVIEW DATE:	9/2/2022
ADDRESS:	1414 E. 61st Place	IDPH LICENSE NO:	100-20640
HOMOGENEOUS A	REA: <b>07B</b>		
MATERIAL DESCR	IPTION: 12x12 Gray Floo	or Tile Mastic- No ACBM	
MATERIAL LOCATI	ON: <b>Room 108</b>		
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Υ:		DAMAGE UNITS:
management planner	to review the results of the in the above identified homoge	nspection and assessment and re	/ Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION recommendation is:		
Comments:			
Management Plan	ner's Signature:	en B Genee	Date: _ <b>09/02/2022</b>
			<u> </u>

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07D

MATERIAL DESCRIPTION: 12x12 Pink Floor Tile Mastic- No ACBM

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

22551

BUIDLING ID: 2630

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago,	Illinois	MANAGEMENT PLANNER:	Steven Geneser
SCHOOL NAME:	Carnegie	School	REVIEW DATE:	9/2/2022
ADDRESS:	1414 E. 61	1st Place	IDPH LICENSE NO:	100-20640
HOMOGENEOUS A	REA: C	)7D		
MATERIAL DESCR	IPTION: 1	12x12 Pink Floo	or Tile Mastic- No ACBM	
MATERIAL LOCATI	ON:	Kitchen		
MATERIAL QUANT	ITY:			MATERIAL UNITS:
DAMAGE QUANTIT	Y:			DAMAGE UNITS:
management planner original inspection of the following recomm	to review the above idendations.	e results of the i entified homoge	nspection and assessment and rec	Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION recon	nmendation is:		
Comments:				
		St	en B Genee	
Management Plan	ner's Signa	ature:		Date: <u>09/02/2022</u>

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07E

MATERIAL DESCRIPTION: 12x12 Red Floor Tile Mastic- No ACBM

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 128

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

Inspector's Signature:	Midul	di Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

22551

BUIDLING ID: 2630

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illin	ois	MANAGEMENT PLANNER:	Steven Geneser
SCHOOL NAME:	Carnegie Sch	ool	REVIEW DATE:	9/2/2022
ADDRESS:	1414 E. 61st	Place	IDPH LICENSE NO:	100-20640
HOMOGENEOUS A	REA: <b>07E</b>			
MATERIAL DESCRI	PTION: <b>12x</b> 1	2 Red Floo	r Tile Mastic- No ACBM	
MATERIAL LOCATION	ON: Roo	m 128		
MATERIAL QUANTI	TY:			MATERIAL UNITS:
DAMAGE QUANTIT	Y:			DAMAGE UNITS:
management planner	to review the re he above identi endations.	sults of the i fied homoge	nspection and assessment and rec	Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
Comments:  Management Plant	ner's Signatur	e: Stor	en B Gerea	Date: <u>09/02/2022</u>

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07F

MATERIAL DESCRIPTION: 12x12 Light Pink Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Lunchroom, Main Office, Principal's Office, Principal's Washroom

MATERIAL QUANTITY: 800 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Main Office Completely abated

Inspector's Signature:	Mirli	di Cai	Date:	08/31/2022	

#### **TEM Environmental, Inc.** 2022 AHERA REINSPECTION

#### **Management Planner Review Form**

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630 CITY/STATE: Chicago, Illinois MANAGEMENT PLANNER: Steven Geneser **Carnegie School** SCHOOL NAME: **REVIEW DATE:** 9/2/2022 ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640 HOMOGENEOUS AREA: 07F 12x12 Light Pink Floor Tile Mastic MATERIAL DESCRIPTION: MATERIAL LOCATION: Lunchroom, Main Office, Principal's Office, Principal's Washroom MATERIAL QUANTITY: 800 MATERIAL UNITS: SF DAMAGE QUANTITY: DAMAGE UNITS: 0 SF In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations. The RESPONSE ACTION recommendation is: Follow O&M Plan Comments: Stoven B Gener

Date: 09/02/2022

Management Planner's Signature:

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08

MATERIAL DESCRIPTION: Black Border Board Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1st & 2nd Floor Hallway, Throughout Classrooms

MATERIAL QUANTITY: 1200 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 263	30
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	):	100-20640	
HOMOGENEOUS A	REA:	08				
MATERIAL DESCRI	IPTION:	Black Border Bo	oard Floor Tile			
MATERIAL LOCATI	ON:	1st & 2nd Floor	Hallway, Throughou	ut Classroom	S	
MATERIAL QUANTI	ITY:	1200			MATERIAL UNITS:	LF
DAMAGE QUANTIT	Y:	10			DAMAGE UNITS:	LF
management planner	to review the above	the results of the ir identified homoger	spection and assess	sment and reco	ommend appropriate	(A) the LEA must select a response actions. The ons 763.88 and 763.90 with
The RESPONSE AC	CTION reco	ommendation is:				
Follow O&M Plan						
Comments:						
Management Plan	nar's Sia	nature: Stav	en B Geres	_	Date: <b>09</b> /	/02/2022
ivianayement rian	inei a oiyi	iatui 6.			שמוכ. <b>עש</b> ו	ULILULL

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 09

MATERIAL DESCRIPTION: Black Border Board Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1st & 2nd Floor Hallway, Throughout Classrooms

MATERIAL QUANTITY: 1200 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	
inspector's Signature.			Date.	00/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NC	):	100-20640	
HOMOGENEOUS A	REA:	09				
MATERIAL DESCRI	IPTION:	Black Border Bo	oard Floor Tile Mast	ic		
MATERIAL LOCATI	ON:	1st & 2nd Floor	Hallway, Throughou	ut Classroom	s	
MATERIAL QUANTI	ITY:	1200			MATERIAL UNITS:	LF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	LF
management planner	to review the above endations.	the results of the ir identified homoger	spection and assess	sment and reco	Response Act (AHERA) the commend appropriate respure coordance with Sections 7	onse actions. The
Follow O&M Plan						
Comments:						
Managagaga	navle O:	Star	en B Geres	-	Deta: 00/00/0	
Management Plan	ners sig	nature.	200-200		Date: 09/02/2	:UZZ

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 10

MATERIAL DESCRIPTION: 9x9 Brown w/Speckles Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Principal's Washroom

MATERIAL QUANTITY: 75 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Not Observed. Covered with 12"x12" Pink Tile

Inspector's Signature:	Mirle	di Cai	r	Date:	08/31/2022	
inspector's Signature.			I.	Date.	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME: Chicago, Illinois MANAGEMENT PLANNER: Steven Geneser  SCHOOL NAME: Carnegie School REVIEW DATE: 9/2/2022  ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640  HOMOGENEOUS AREA: 10  MATERIAL DESCRIPTION: 9x9 Brown w/Speckles Floor Tile  MATERIAL QUANTITY: 75  DAMAGE QUANTITY: 0 MATERIAL QUANTITY: 55  DAMAGE QUANTITY: 0 MATERIAL DESCRIPTION: 9x9 Brown w/Speckles Floor Tile  naccordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The following recommendations:  The RESPONSE ACTION recommendation is:  Follow O&M Plan  Management Planner's Signature: Date: 9/402/2022				_			
SCHOOL NAME: Carnegle School REVIEW DATE: 9/2/2022  ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640  HOMOGENEOUS AREA: 10 MATERIAL DESCRIPTION: 9x9 Brown w/Speckles Floor Tile MATERIAL COCATION: Principal's Washroom MATERIAL QUANTITY: 75 DAMAGE QUANTITY: 0 MATERIAL UNITS: SF  DAMAGE QUANTITY: 0 DAMAGE UNITS: SF  DAMAGE UNITS: SF  The RESPONSE ACTION recommendations.  The RESPONSE ACTION recommendation is:  Follow O&M Plan  Comments:	LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640  HOMOGENEOUS AREA: 10  MATERIAL DESCRIPTION: 9x9 Brown w/Speckles Floor Tile  MATERIAL QUANTITY: 75  DAMAGE QUANTITY: 0 MATERIAL QUANTITY: 5F  DAMAGE QUANTITY: 5F	CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
HOMOGENEOUS AREA: 10  MATERIAL DESCRIPTION: 9x9 Brown w/Speckles Floor Tile  MATERIAL LOCATION: Principal's Washroom  MATERIAL QUANTITY: 75  DAMAGE QUANTITY: 0 DAMAGE UNITS: SF  DAMAGE QUANTITY: 0 DAMAGE UNITS: SF  In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with he following recommendations.  The RESPONSE ACTION recommendation is:  Follow O&M Plan  Comments:	SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
MATERIAL DESCRIPTION: Principal's Washroom  MATERIAL QUANTITY: 75 MATERIAL UNITS: SF  DAMAGE QUANTITY: 0 DAMAGE UNITS: SF  In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The principal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.  The RESPONSE ACTION recommendation is:  Follow O&M Plan  Comments:	ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	):	100-20640	
MATERIAL LOCATION: Principal's Washroom  MATERIAL QUANTITY: 75 MATERIAL UNITS: SF  DAMAGE QUANTITY: 0 DAMAGE UNITS: SF  In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The priginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.  The RESPONSE ACTION recommendation is:  Follow O&M Plan  Comments:	HOMOGENEOUS A	REA:	10				
MATERIAL QUANTITY: 75  DAMAGE QUANTITY: 0  DAMAGE UNITS: SF  n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with he following recommendations.  The RESPONSE ACTION recommendation is:  Follow O&M Plan  Comments:	MATERIAL DESCRI	IPTION:	9x9 Brown w/Sp	eckles Floor Tile			
n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The priginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with he following recommendations.  The RESPONSE ACTION recommendation is:  Follow O&M Plan  Comments:	MATERIAL LOCATION	ON:	Principal's Was	hroom			
n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The ringinal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with he following recommendations.  The RESPONSE ACTION recommendation is:  Follow O&M Plan  Comments:	MATERIAL QUANTI	ITY:	75			MATERIAL UNITS:	SF
management planner to review the results of the inspection and assessment and recommend appropriate response actions. The priginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with he following recommendations.  The RESPONSE ACTION recommendation is:  Follow O&M Plan  Comments:	DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF
Comments:	management planner original inspection of t the following recommo	to review the above endations.	the results of the in identified homoge	nspection and assess	sment and reco	ommend appropriate resp	ponse actions. The
QA D. Serres	Follow O&M Plan						
QA D. Serres							
Management Planner's Signature: Store & June Date: 09/02/2022	Comments:						
Management Planner's Signature: Stown & Junes Date: 09/02/2022							
Management Planner's Signature: Store & Jense Date: 09/02/2022							
Management Planner's Signature: Steven & Junes Date: 09/02/2022							
Management Planner's Signature: Stown B Jeres Date: 09/02/2022							
Management Planner's Signature: Stown B Jense Date: 09/02/2022							
Management Planner's Signature: Stoven B Jense Date: 09/02/2022							
Management Planner's Signature: Steven & Jerres Date: 09/02/2022							
Management Planner's Signature: Date: 09/02/2022							
Management Planner's Signature: Steven B Jerse Date: 09/02/2022							
	Management Plan	ner's Sig	nature. Star	en B Geree	-	Date: no/no/	2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 10A

MATERIAL DESCRIPTION: 9x9 Brown w/Speckles Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Principal's Washroom

MATERIAL QUANTITY: 75 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Not Observed. Covered with 12"x12" Pink Tile

Inspector's Signature:	Mirle	di Cai	r	Date:	08/31/2022	
inspector's Signature.			I.	Date.	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 263	30
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640	
HOMOGENEOUS A	REA:	10A				
MATERIAL DESCRI	PTION:	9x9 Brown w/Sp	eckles Floor Tile Ma	astic		
MATERIAL LOCATION	ON:	Principal's Wash	nroom			
MATERIAL QUANTI	TY:	75			MATERIAL UNITS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF
management planner	to review the above i	the results of the in	spection and assess	ment and reco	mmend appropriate	A) the LEA must select a response actions. The ons 763.88 and 763.90 with
The RESPONSE AC	CTION reco	ommendation is:				
Follow O&M Plan						
Comments:						
Management Plan	ner's Sigr	nature:	en B Genes	-	Date: <b>09</b> /	02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: Gray Carpet Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 203

MATERIAL QUANTITY: 1200 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	
inspector's Signature.			Date.	00/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegie	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E. 6	61st Place	IDPH LICENSE NO	):	100-20640	
HOMOGENEOUS A	REA:	11				
MATERIAL DESCRI	PTION:	Gray Carpet Mas	stic			
MATERIAL LOCATION	ON:	Room 203				
MATERIAL QUANTI	TY:	1200			MATERIAL UNITS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF
management planner	to review the above in	he results of the ir	nspection and assess	sment and reco	Response Act (AHERA) to ommend appropriate resp ccordance with Sections	onse actions. The
The RESPONSE AC	TION reco	mmendation is:				
Follow O&M Plan						
Comments:						
Management Plan	ner's Sian	nature:	en B Geres	_	Date: <b>09/02/</b> ;	2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12

MATERIAL DESCRIPTION: Gray Carpet Mastic DUPLICATE HA

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: Room 203 DUPLICATE HA 11

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Duplicate of HA 11

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

22551

BUIDLING ID: 2630

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illinoi	s MANAGEMENT PL	ANNER: Steven	Geneser
SCHOOL NAME:	Carnegie School	ol REVIEW DATE:	9/2/202	2
ADDRESS:	1414 E. 61st Pla	ace IDPH LICENSE NO	): 100-206	640
HOMOGENEOUS A	REA: <b>12</b>			
MATERIAL DESCR	PTION: Gray C	Carpet Mastic DUPLICATE HA		
MATERIAL LOCATI	ON: Room	203 DUPLICATE HA 11		
MATERIAL QUANT	TY:		MATER	IAL UNITS:
DAMAGE QUANTIT	Y:		DAMAG	SE UNITS:
management planner original inspection of the following recomm	to review the resu the above identifie endations.	llts of the inspection and assess d homogeneous area has been	sment and recommend	e Act (AHERA) the LEA must select a appropriate response actions. The e with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION recommend	dation is:		
Comments:				
		0 2 4		
Management Plan	ner's Signature:	Stoven & Gener		Date: <b>09/02/2022</b>

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13

MATERIAL DESCRIPTION: Brown Carpet Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 2nd Floor Teachers' Lounge

MATERIAL QUANTITY: 900 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Date:	08/31/2022
		***************************************

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			9				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 26	30	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser		
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	1414 E. (	61st Place	IDPH LICENSE NO	:	100-20640		
HOMOGENEOUS A	REA:	13					
MATERIAL DESCRI	PTION:	Brown Carpet M	astic				
MATERIAL LOCATION	ON:	2nd Floor Teach	ers' Lounge				
MATERIAL QUANTI	TY:	900			MATERIAL UNITS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF	
management planner	to review the above indations.	he results of the in dentified homoger	spection and assess	ment and reco	ommend appropriate	RA) the LEA must select a response actions. The ons 763.88 and 763.90 wit	th
Follow O&M Plan							
Comments:							
		0	ο Λ.				
Management Plan	nor's Sign	Store Store	en B Genes	-	Doto: 00	/02/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14

MATERIAL DESCRIPTION: Red Carpet Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Chrysotile FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: Room 120

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:	Midul	Vi Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

22551

BUIDLING ID: 2630

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANN	NER: Steven Geneser
SCHOOL NAME:	Carnegie Schoo	REVIEW DATE:	9/2/2022
ADDRESS:	1414 E. 61st Pla	ce IDPH LICENSE NO:	100-20640
HOMOGENEOUS A	AREA: <b>14</b>		
MATERIAL DESCR	IPTION: Red Ca	rpet Mastic NOT OBSERVED	
MATERIAL LOCATI	ON: Room	120	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:
management planner	to review the resulthe above identified	ts of the inspection and assessmer	nergency Response Act (AHERA) the LEA must select a not and recommend appropriate response actions. The lewed in accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION recommend	ation is:	
Comments:			
		ο	
Marian	a a da <b>O</b> 'a a	Stoven B Gener	D. I. activities
Management Plan	iner's Signature:	, - • • • • • • • • • • • • • • • • • •	Date: <u>09/02/2022</u>

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15

MATERIAL DESCRIPTION: Red Carpet Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Chrysotile FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: Main Office

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:	Midul	Vi Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

22551

BUIDLING ID: 2630

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNE	R: Steven Geneser
SCHOOL NAME:	Carnegie School	REVIEW DATE:	9/2/2022
ADDRESS:	1414 E. 61st Plac	e IDPH LICENSE NO:	100-20640
HOMOGENEOUS A	REA: <b>15</b>		
MATERIAL DESCRI	PTION: Red Car	pet Mastic NOT OBSERVED	
MATERIAL LOCATION	ON: <b>Main O</b> f	fice	
MATERIAL QUANTI	TY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:
management planner	to review the result he above identified	s of the inspection and assessment	ergency Response Act (AHERA) the LEA must select a and recommend appropriate response actions. The wed in accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION recommenda	tion is:	
Comments:			
		C 2 Q	
Management Plan	ner's Signature:	Stoven B Genee	Date: <b>09/02/2022</b>
· ·	<u> </u>		

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 16

MATERIAL DESCRIPTION: 12x12 Beige w/Brown Specks

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON: Physical Damage

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: 2nd Floor Teachers' Lounge

MATERIAL QUANTITY: 55 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Floor tiles chipped and cracked but intact

Inspector's Signature: Murli Di Ca Date: 08/31/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640	
HOMOGENEOUS A	REA:	16				
MATERIAL DESCRI	PTION:	12x12 Beige w/B	rown Specks			
MATERIAL LOCATION	ON:	2nd Floor Teach	ers' Lounge			
MATERIAL QUANTI	TY:	55			MATERIAL UNITS:	SF
DAMAGE QUANTITY	Y:				DAMAGE UNITS:	SF
management planner	to review t he above i	he results of the in	spection and assess	ment and reco	Response Act (AHERA) the immend appropriate respondence with Sections 7	onse actions. The
The RESPONSE AC	TION reco	mmendation is:				
Follow O&M Plan						
Comments:						
Management Plan	ner's Siar	nature: Stave	n B Genea	-	Date: 09/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 16A

MATERIAL DESCRIPTION: 12x12 Beige w/Brown Specks Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 2nd Floor Teachers' Lounge Washroom

MATERIAL QUANTITY: 55 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	
inspector's Signature.			Date.	00/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID:	2630	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser		
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640		
HOMOGENEOUS A	REA:	16A					
MATERIAL DESCRI	PTION:	12x12 Beige w/B	rown Specks Masti	С			
MATERIAL LOCATION	ON:	2nd Floor Teach	ers' Lounge Washr	oom			
MATERIAL QUANTI	TY:	55			MATERIAL UNIT	S:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	3:	SF
n accordance with Semanagement planner original inspection of the following recommender The RESPONSE AC	to review the above indations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ite respo	
Follow O&M Plan							
Comments:							
		0.	n B Geree				
Management Plan	ner's Sigr	nature:	in Orania		Date:	09/02/20	)22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17A

MATERIAL DESCRIPTION: 12x12 Red Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 120

MATERIAL QUANTITY: 340 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		•	•			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640	
HOMOGENEOUS A	REA:	17A				
MATERIAL DESCRI	PTION:	12x12 Red Floor	Tile			
MATERIAL LOCATION	ON:	Room 120				
MATERIAL QUANTI	TY:	340			MATERIAL UNITS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS:	SF
management planner	to review the above lendations.	the results of the ir identified homoger	spection and assess	ment and reco	Response Act (AHERA) ommend appropriate res ccordance with Sections	
Follow O&M Plan						
Comments:						
Management Plani	ner's Siar	nature:	en B Geres	-	Date: <b>09/02</b> /	<b>/2022</b>

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17B

MATERIAL DESCRIPTION: 12x12 Red Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 120

MATERIAL QUANTITY: 340 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	
inspector's Signature.			Date.	00/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	):	100-20640	
HOMOGENEOUS A	REA:	17B				
MATERIAL DESCRI	IPTION:	12x12 Red Floor	Tile Mastic			
MATERIAL LOCATI	ON:	Room 120				
MATERIAL QUANTI	ITY:	340			MATERIAL UNITS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF
management planner	to review the above endations.	the results of the ir identified homoger	nspection and assess	sment and reco	Response Act (AHERA) tommend appropriate responder or control of the control of t	onse actions. The
Follow O&M Plan						
Comments:						
Management Plan	ner's Sig	nature: Star	en B Genee	-	Date: <b>09/02/</b> :	2022
managoment i lan	S Oly	ilatai o.			Date. <b>03/02/</b>	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18

MATERIAL DESCRIPTION: 12"x12" Blue Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 203

MATERIAL QUANTITY: 350 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	
inspector's Signature.			Date.	00/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		•	•			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2630	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640	
HOMOGENEOUS A	REA:	18				
MATERIAL DESCRI	PTION:	12"x12" Blue Flo	oor Tile			
MATERIAL LOCATION	ON:	Room 203				
MATERIAL QUANTI	TY:	350			MATERIAL UNITS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF
management planner	to review the above lendations.	the results of the ir identified homoger	nspection and assess	ment and reco	Response Act (AHERA) to commend appropriate respectordance with Sections	onse actions. The
Follow O&M Plan						
Comments:						
Management Plan	norle Sier	Staven Stave	en B Gener	_	Date: <b>09/02</b> /:	2022
ivianayement Flan	nei s sigi	iaiui <del>C</del> .			Date: <b>09/02/</b> 2	LULL

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 19

MATERIAL DESCRIPTION: Mastic associated with 12"x12" Blue Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 203

MATERIAL QUANTITY: 350 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	
inspector's Signature.			Date.	00/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 2	630
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser	
SCHOOL NAME:	Carnegi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	1414 E.	61st Place	IDPH LICENSE NO	:	100-20640	
HOMOGENEOUS A	REA:	19				
MATERIAL DESCRI	PTION:	Mastic associate	ed with 12"x12" Blue	e Floor Tile		
MATERIAL LOCATION	ON:	Room 203				
MATERIAL QUANTI	TY:	350			MATERIAL UNITS	S: <b>SF</b>
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF
management planner	to review he above endations.	the results of the ir identified homoger ommendation is:	spection and assess	ment and reco	ommend appropriaticcordance with Sec	ERA) the LEA must select a e response actions. The stions 763.88 and 763.90 with

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20

MATERIAL DESCRIPTION: Whiteboard Adhesive

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:

MATERIAL QUANTITY: 30 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Mirle	di Cai	Date:	08/31/2022	
Inspector's Signature:		0.00	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`	•				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	22551	BUIDLING ID: 20	630	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Steven Geneser		
SCHOOL NAME:	Carnegie	School	REVIEW DATE:		9/2/2022		
ADDRESS:	1414 E. 6	61st Place	IDPH LICENSE NC	):	100-20640		
HOMOGENEOUS A	REA:	20					
MATERIAL DESCRI	PTION:	Whiteboard Adh	esive				
MATERIAL LOCATION	ON:						
MATERIAL QUANTI	TY:	30			MATERIAL UNITS	: SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF	
n accordance with Se management planner original inspection of the he following recommo	to review the above in the abov	he results of the ir dentified homoger	nspection and assess	sment and reco	ommend appropriate	response actions	. The
The RESPONSE AC	CTION reco	mmendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Sian	nature:	en B Geree	_	Date: <b>0</b> 9	9/02/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Inspector Assessment Form (New Homogeneous Area)**

LEA NAME: Chicago Public Schools UNIT NUMBER: 22551 BUIDLING ID: 2630

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mike Di Canio

SCHOOL NAME: Carnegie School INSPECTION DATE: 8/31/2022

ADDRESS: 1414 E. 61st Place IDPH LICENSE NO: 100-20640

#### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW** 

MATERIAL DESCRIPTION: Newly Installed Suspect ACM

MATERIAL LOCATION: Installed After Implementation of Management Plan and After Renovations

MATERIAL QUANTITY: MATERIAL UNITS:

MATERIAL CATEGORY: MISC FRIABLE:

ASBESTOS TYPE: Assumed

DISTURBANCE POTENTIAL: CONDITION:

AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage

ACCESSIBILITY: Within Reach DAMAGE REASON:

DAMAGE REASON: DAMAGE REASON: DAMAGE UNITS:

DAMAGE QUANTITY:

	Mirle	di Ca			
Inspector's Signature:		0.	Date:	08/31/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

22551

BUIDLING ID: 2630

UNIT NUMBER:

**Chicago Public Schools** 

LEA NAME:

CITY/STATE:	Chicago, Illinois	s MAN	NAGEMENT PLANNE	R: <b>Steve</b> i	n Geneser		
SCHOOL NAME:	Carnegie Schoo	I REV	IEW DATE:	9/2/20	22		
ADDRESS:	1414 E. 61st Pla	ce IDPI	H LICENSE NO:	100-20	0640		
HOMOGENEOUS A	AREA:	NEW					
MATERIAL DESCRIPTION:		Newly Installed Suspect ACM					
MATERIAL LOCATI	ION:	Installed After I	mplementation of M	anagement Pl	an and After Renovations		
MATERIAL QUANT	TTY:	MATERIAL UNITS:					
DAMAGE QUANTITY: DAMAGE UNITS:							
management planne	er to review the res ove identified hom	sults of the inspec	tion and assessment	and recommer	nse Act (AHERA) the LEA must select a and appropriate response actions. The original and Sections 763.88 and 763.90 with the		
The RESPONSE AC	CTION recommen	dation is:					
COMMENTS:							
		Star ?	) Seres				
Management Plar	nner's Signature:				Date: <u>09/02/2022</u>		

### APPENDIX B

### **Inspector and Management Planner Licenses**



# OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

# Michael DiCanio

has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/1/2022 - 3/3/2022

Exam Date: 3/3/2022

Expiration Date: 3/3/2023

Certificate Number: ABI2203030655

Kathy DeSalvo, Director



525-535 West Jefferson Street + Springfield, Illinois 62761-0001 + www.dph.illinois.gov

MICHAEL R DI CANIO 2514 N 79TH AVE ELMWOOD PARK, IL 60707 4/7/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER:

20640

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

#### COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

**ASBESTOS** PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

ID NUMBER 100 - 20640

ISSUED 4/7/2022

EXPIRES 05/15/2023

INSPECTOR

3/3/2023

MICHAEL R DI CANIO 2514 N 79TH AVE ELMWOOD PARK, IL 60707

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid

training course certificate.

PRUFESSION LICENSE

If you have any questions or ID NUMBER (217)785-5897.

100 - 20640

ISSUED 4/7/2022

EXPIRES 05/15/2023 am at (217)782-3517 or fax

Our WEB address is: dph.il 2514 N 79TH AVE EMAIL Address: dph.asbes ELMWOOD PARK, IL 60707

MICHAEL R DI CANIO

Environmental Health

stection/asbestos

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



This is to certify that

### **Steve Geneser**

has on 4/6/22, in Springfield, Illinois, completed the requirements for asbestos accreditation under Section 206 of TSCA Title II

# **Asbestos Building Inspector Refresher Training**

as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA) and passed the associated examination with a score of 70% or higher.

Course Date: April 6, 2022	COURSE LENGTH: 4 HOURS
Examination Date: April 6, 2022	
Expiration Date: April 6, 2023	William S. William
Certificate Number: BIR/1044	Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  $\ \square$  217.787.9800  $\ \square$  www.ReliableEnv.com



This is to certify that

### **Steve Geneser**

has on 4/06/22, in Springfield, Illinois, completed the requirements for asbestos accreditation under Section 206 of TSCA Title II

### **Asbestos Management Planner Refresher Training**

as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA) and passed the associated examination with a score of 70% or higher

Course Date: April 6, 2022

Examination Date: April 6, 2022

Expiration Date: April 6, 2023

Certificate Number: MPR/0470

Course Length: 4 Hours

William S. Williams

2760 W. Jefferson Street, Springfield, Illinois □ 217.787.9800 □ www.ReliableEnv.com





#### **ASBESTOS PROFESSIONAL** LICENSE

**ID NUMBER** 100 - 01784 ISSUED 3/1/2022

**EXPIRES** 05/15/2023

STEVEN B GENESER 210 BARNSIDE CIRCLE GENEVA, IL 60134

Environmental Health



#### **ENDORSEMENTS**

#### TC EXPIRES

INSPECTOR 5/5/2022 MANAGEMENT PLANNER 5/5/2022 PROJECT MANAGER 8/4/2022 AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.

### APPENDIX C

### **Laboratory Accreditations**

# APPENDIX D

# **Laboratory Results**

# APPENDIX E

# Chain of Custody Forms

# **Three-Year Reinspection Key to Terms**

	CODE	KEY
MATERIAL CATEGORY	ACBM	Asbestos Containing Building Materials
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed