

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3770
SCHOOL NAME: Carver Primary School
ADDRESS OF SCHOOL: 901 E. 133rd Place
CITY: Chicago, IL, 60627

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/29/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 1/12/2023 ENROLLMENT 453
IDPH INSPECTOR LICENSE NUMBER: 100-18281
IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



1/13/2023

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Carver Primary School

901 E. 133rd Place
Chicago, IL, 60627

Unit: 22621
Building ID: 2690

IDPH ID Number: 14-016-2990-3770

REPORT DATE:

Friday, January 13, 2023

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

01/13/2023

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22621 Region: 06 IDPH ID: 14-016-2990-3770

School: Carver Primary School Building ID: 2690

Address: 901 E. 133rd Place

Chicago, IL, 60627

Building Contact: Brown, David

Contact Phone: 7736778815

Current Building Owners: Chicago Public Schools

Reinspection Date: 1/12/2023

Review Date: 01/13/2023

Inspector: Christopher Antonopoulos

Inspector IDPH License: 100-18281

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: January 13, 2023

RE: Carver Primary School, Unit 22621
901 E. 133rd Place
Chicago, IL, 60627

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Carver Primary School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Carver Primary School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Carver Primary School Unit: 22621 Region: 06
Address: 901 E. 133rd Place Chicago, IL, 60627
IDPH ID: 14-016-2990-3770 Building ID: 2690
Contact: Brown, David Phone: 7736778815

2. Description of Facility

Original Construction: 1945 Additional Construction:
Total Square Footage: 14725 No of Floors: 1
Current Occupancy: 453

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Christopher Antonopoulos



Inspector IDPH license # 100-18281
Reinspection Date: 1/12/2023

Signature:
Date: 1/12/2023

6. Management Planner

Management Planner Name: Todd Huffer



Management Planner IDPH license # 100-09870

Signature:
Date: 01/13/2023

7. Review Date: 01/13/2023

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 1/13/2023

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Carver Primary School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2690:

"Annex A"-05	12x12 Blue Floor Tile
"Annex A"-05A	12x12 Blue Floor Tile Mastic
"Annex A"-26	12x12 Green Vinyl Floor Tile
"Annex A"-32	12x12 Beige w/White Streaks Floor Tile
"Annex A"-32A	12x12 Beige w/White Streaks Floor Tile
"Annex A"-B	Aircell Pipe Joints
"Annex A"-C	Cardboard Pipe Insulation
"Annex A"-D	Cardboard Pipe Joints
"Annex A"-E	Aircell Duct Cover

"Annex A"-F	MJP E/F/V on Fiberglass Pipe Insulation
31	Chalkboards
NEW	Newly Installed Suspect ACM
Primary-32	Vault Liner
Primary-A	Aircell Pipe Insulation
Primary-B	Aircell Pipe Insulation Joints
Primary-C	Cardboard Pipe Insulation
Primary-D	Elbows on Cardboard Insulation

B. The following new homogenous areas have been identified for Building 2690:

"Annex A"-32	12x12 Beige w/White Streaks Floor Tile
"Annex A"-32A	12x12 Beige w/White Streaks Floor Tile
31	Chalkboards
NEW	Newly Installed Suspect ACM
Primary-32	Vault Liner

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

"Annex A"- FD-1	Insulation in Fire Rated Doors
"Annex A"-01	1x12 Tan w/Blue Specks Floor Tile
"Annex A"-01A	12x12 Tan w/Blue Specks Floor Tile Mastic
"Annex A"-02C	Tan Carpet Adhesive
"Annex A"-05	12x12 Blue Floor Tile
"Annex A"-05A	12x12 Blue Floor Tile Mastic
"Annex A"-06	12x12 Light Green Floor Tile
"Annex A"-06A	12x12 Light Green Floor Tile Mastic
"Annex A"-08	12x12 Off-White w/Blue Streaks Floor Tile
"Annex A"-08A	12x12 Off-White w/Blue Specks Mastic
"Annex A"-09	Brown Baseboard
"Annex A"-09A	Brown Baseboard Mastic
"Annex A"-10	Gray Carpet Mastic
"Annex A"-13	Ceramic Floor Tile Grout
"Annex A"-14	Hardcoat Plaster
"Annex A"-15	12x12 Tan w/Specks Floor Tile
"Annex A"-15A	12x12 Tan w/Specks Mastic
"Annex A"-16	12x12 Off-White w/Brown Specks Floor Tile
"Annex A"-16A	12x12 Off-White w/Brown Specks Floor Tile Mastic
"Annex A"-17	12x12 Green Floor Tile
"Annex A"-17A	12x12 Green Floor Tile Mastic
"Annex A"-18	12x12 Blue Floor Tile
"Annex A"-18A	12x12 Blue Floor Tile Mastic
"Annex A"-20	12x12 Orange Floor Tile
"Annex A"-20A	12x12 Orange Floor Tile Mastic
"Annex A"-21	12x12 Gray w/Multicolor Floor Tile
"Annex A"-21A	12x12 Gray w/Multicolor Floor Tile Mastic
"Annex A"-22	12x12 Lime Green Vinyl Floor Tile
"Annex A"-23	12x12 Lime Green Vinyl Floor Tile Mastic
"Annex A"-24	12x12 Light Tan Speckled Vinyl Floor Tile
"Annex A"-25	12x12 Light Tan Speckled Mastic
"Annex A"-26	12x12 Green Vinyl Floor Tile
"Annex A"-27	12x12 Green Vinyl Floor Tile Mastic
"Annex A"-32	12x12 Beige w/White Streaks Floor Tile
"Annex A"-32A	12x12 Beige w/White Streaks Floor Tile
"Annex A"-F	MJP E/F/V on Fiberglass Pipe Insulation
"Annex B "-26	12x12 Yellow Floor Tile
"Annex B"-26A	12x12 Yellow Vinyl Floor Tile Mastic
"Annex B"-27	12x12 Green Vinyl Floor Tile
"Annex B"-27A	12x12 Green Vinyl Floor Tile Mastic
"Annex B"-28	12x12 Beige Floor Tile
"Annex B"-28A	12x12 Beige Floor Tile Mastic

"Annex B"-29	12x12 White w/Brown Floor Tile
"Annex B"-29A	12x12 White w/Brown Floor Tile Mastic
"Annex B"-30	12x12 Grey w/Multicolor Floor Tile
"Annex B"-30A	12x12 Grey w/Multicolor Floor Tile Mastic
"Annex D"-31	12x12 Green Floor Tile
"Annex D"-32A	12x12 Yellow Floor Tile Mastic
31	Chalkboards
NEW	Newly Installed Suspect ACM
Primary 06A	Gray Baseboard
Primary 07A	Gray Baseboard Mastic
Primary 31	1x1 Off-White w/Black Specks Ceiling Tile
Primary-01	Hardcoat Plaster
Primary-05	12x12 Tan w/Brown Floor Tile Mastic
Primary-06	Black Baseboard
Primary-07	Black Baseboard Mastic
Primary-08	Firedoors
Primary-20	Textured Ceiling
Primary-21	Ceramic Tiles
Primary-22A	12x12 Yellow Floor Tile Mastic
Primary-24	Blue Carpet Adhesive
Primary-25	Purple Carpet Adhesive
Primary-26A	12x12 Gray Floor Tile Mastic
Primary-27A	12x12 White Floor Tile Mastic
Primary-28	Terrazzo
Primary-30	12x12 Green Floor Tile
Primary-30A	12x12 Green Floor Tile Mastic
Primary-32	Vault Liner

The following areas were deemed to be inaccessible:

"Annex A"- FD-1	Insulation in Fire Rated Doors
"Annex A"-01A	12x12 Tan w/Blue Specks Floor Tile Mastic
"Annex A"-02C	Tan Carpet Adhesive
"Annex A"-06A	12x12 Light Green Floor Tile Mastic
"Annex A"-08A	12x12 Off-White w/Blue Specks Mastic
"Annex A"-09A	Brown Baseboard Mastic
"Annex A"-10	Gray Carpet Mastic
"Annex A"-14	Hardcoat Plaster
"Annex A"-15A	12x12 Tan w/Specks Mastic
"Annex A"-16A	12x12 Off-White w/Brown Specks Floor Tile Mastic
"Annex A"-17A	12x12 Green Floor Tile Mastic
"Annex A"-18A	12x12 Blue Floor Tile Mastic
"Annex A"-20A	12x12 Orange Floor Tile Mastic
"Annex A"-21A	12x12 Gray w/Multicolor Floor Tile Mastic
"Annex A"-23	12x12 Lime Green Vinyl Floor Tile Mastic
"Annex A"-25	12x12 Light Tan Speckled Mastic

"Annex A"-27	12x12 Green Vinyl Floor Tile Mastic
"Annex A"-B	Aircell Pipe Joints
"Annex A"-E	Aircell Duct Cover
"Annex A"-F	MJP E/F/V on Fiberglass Pipe Insulation
"Annex B"-26A	12x12 Yellow Vinyl Floor Tile Mastic
"Annex B"-27A	12x12 Green Vinyl Floor Tile Mastic
"Annex B"-28A	12x12 Beige Floor Tile Mastic
"Annex B"-29A	12x12 White w/Brown Floor Tile Mastic
"Annex B"-30A	12x12 Grey w/Multicolor Floor Tile Mastic
"Annex D"-32A	12x12 Yellow Floor Tile Mastic
Primary 07A	Gray Baseboard Mastic
Primary-05	12x12 Tan w/Brown Floor Tile Mastic
Primary-07	Black Baseboard Mastic
Primary-08	Firedoors
Primary-20	Textured Ceiling
Primary-22A	12x12 Yellow Floor Tile Mastic
Primary-24	Blue Carpet Adhesive
Primary-25	Purple Carpet Adhesive
Primary-26A	12x12 Gray Floor Tile Mastic
Primary-27A	12x12 White Floor Tile Mastic
Primary-30A	12x12 Green Floor Tile Mastic
Primary-A	Aircell Pipe Insulation
Primary-B	Aircell Pipe Insulation Joints
Primary-C	Cardboard Pipe Insulation
Primary-D	Elbows on Cardboard Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	4/15/2022
	4/15/2022
	4/15/2022
	4/15/2022
	5/19/2022

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Carver Primary School Building 2690 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
"Annex A"- FD-1	Insulation in Fire Rated Doors	412	SF	Throughout Facility	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-01	1x12 Tan w/Blue Specks Floor Tile	5,580	SF	Halls, Rooms 400, 402, 414 & Paint Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-01A	12x12 Tan w/Blue Specks Floor Tile Mastic	5,580	SF	Rooms Halls, 400, 402, 414, & Paint Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-02	12x12 Gray Floor Tile NOT OBSERVED			Rooms 405 and 407		MISC								
"Annex A"-02A	12x12 Gray Floor Tile Mastic NOT OBSERVED			Annex "A"; Rooms 405 and 407		MISC								
"Annex A"-02C	Tan Carpet Adhesive	650	SF	Annex A- Room 411	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-03	12 x 12 Orange Floor Tile NOT OBSERVED			Annex "A"- Room 403		MISC								
"Annex A"-03A	12 x 12 Orange Floor Tile Mastic NOT OBSERVED			Annex "A"- Room 403		MISC								
"Annex A"-04	12x12 Red Floor Tile NOT OBSERVED			Annex "A"- Room 409		MISC								
"Annex A"-04A	12x12 Red Floor Tile Mastic NOT OBSERVED			Annex "A"- Room 409		MISC								
"Annex A"-05	12x12 Blue Floor Tile	600	SF	Annex "A"- Rooms 401 & 408	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
"Annex A"-05A	12x12 Blue Floor Tile Mastic	600	SF	Annex "A"- Rooms 401 & 408	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
"Annex A"-06	12x12 Light Green Floor Tile	400	SF	Annex "A"- Room 410 and 404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-06A	12x12 Light Green Floor Tile Mastic	400	SF	Annex "A"- Room 410 and 404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-07	12x12 Sand Floor Tile REMOVED 2010			Annex "A"- 413	ABATED	MISC								
"Annex A"-07A	12x12 Sand Floor Tile Mastic REMOVED 2010			Annex "A" 413	ABATED	MISC								
"Annex A"-08	12x12 Off-White w/Blue Streaks Floor Tile	1,275	SF	"Annex A"- N/S Corner Connections, Carpenter, Hallways Between Buildings, Main Office, Copy Room, Teachers' Lounge & Room 408	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-08A	12x12 Off-White w/Blue Specks Mastic	1,275	SF	"Annex A"- N/S	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
A*-08A				Corner Connections, Carpenter, Hallways Between Buildings, Main Office, Copy Room, Teachers' Lounge & Room 408								potential for damage		
"Annex A*-09	Brown Baseboard	230	LF	North & South Connecting Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-09A	Brown Baseboard Mastic	230	LF	"Annex A"- North and South Connecting Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-10	Gray Carpet Mastic	1,800	SF	"Annex A"- Main Office, Rooms 410, 413, 408, 412, 405, 407, 403	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-11	Green Carpet Mastic NOT OBSERVED			Rooms 405, 407, 411, 402, 401, 409		MISC								
"Annex A*-12	Firebrick ABATED			"Annex A"- Boiler Room Incinerator	ABATED	MISC								
"Annex A*-13	Ceramic Floor Tile Grout	682	SF	Annex "A"- Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-14	Hardcoat Plaster	54,000	SF	Annex "A"- Throughout Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-15	12x12 Tan w/Specks Floor Tile	325	SF	Annex "A"- Small Entry Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-15A	12x12 Tan w/Specks Mastic	325	SF	Annex "A"- Small Entry Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-16	12x12 Off-White w/Brown Specks Floor Tile	485	SF	Annex "A"- Entry Easy	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-16A	12x12 Off-White w/Brown Specks Floor Tile Mastic	485	SF	Annex "A"- Entry Easy	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-17	12x12 Green Floor Tile	1,100	SF	Rooms 405 & 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-17A	12x12 Green Floor Tile Mastic	1,100	SF	Rooms 405 & 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-18	12x12 Blue Floor Tile	1,800	SF	Rooms 404 & 408	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A*-18A	12x12 Blue Floor Tile Mastic	1,800	SF	Rooms 404 & 408	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
"Annex A"-19	12x12 Red Floor Tile NOT OBSERVED			Rooms 403 and 409		MISC								
"Annex A"-19A	12x12 Red Floor Tile Mastic NOT OBSERVED			Rooms 403 and 409		MISC								
"Annex A"-20	12x12 Orange Floor Tile	500	SF	Rooms 413	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-20A	12x12 Orange Floor Tile Mastic	500	SF	Room 413	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-21	12x12 Gray w/Multicolor Floor Tile	6,200	SF	Room 412, Copy Room, Office & Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-21A	12x12 Gray w/Multicolor Floor Tile Mastic	6,200	SF	Room 412, Copy Room, Office & Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-22	12x12 Lime Green Vinyl Floor Tile	50	SF	Room 409	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-23	12x12 Lime Green Vinyl Floor Tile Mastic	50	SF	Room 409	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-24	12x12 Light Tan Speckled Vinyl Floor Tile	800	SF	Rooms 401 & 409	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-25	12x12 Light Tan Speckled Mastic	800	SF	Rooms 401 & 409	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-26	12x12 Green Vinyl Floor Tile	600	SF	Room 401	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
"Annex A"-27	12x12 Green Vinyl Floor Tile Mastic	50	SF	Room 401	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex A"-32	12x12 Beige w/White Streaks Floor Tile	500	SF	Room 406	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
"Annex A"-32A	12x12 Beige w/White Streaks Floor Tile	500	SF	Room 406	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
"Annex A"-A	Aircell Pipe Insulation	550	LF	Annex "A"- Attic Pipe Chases	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
"Annex A"-B	Aircell Pipe Joints	70	LF	Annex "A"- Attic Pipe Chases	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
"Annex A"-C	Cardboard Pipe Insulation	370	LF	Annex "A"- Attic Pipe Chases	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
"Annex A"-D	Cardboard Pipe Joints	42	LF	Annex "A"- Attic	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
"Annex	Aircell Duct Cover	3,200	SF	Annex "A"- Attic	CHR	TSI	Y	NONE	0		Yes	Any remaining friable		LOW

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
"Annex C"-E	Aircell Duct Cover ABATED			Annex "C"- Boiler Room Attic	CHR	TSI								
"Annex C"-F	Fiberglass Joints ABATED			Annex "C"- Boiler Room	ABATED	TSI								
"Annex C"-G	Mag Tank Cover ABATED			Annex "C"- Boiler Room	ABATED	TSI								
"Annex D"-31	12x12 Green Floor Tile	1,400	SF	East and West Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
"Annex D"-31A	12x12 Green Floor Tile Mastic NOT OBSERVED			East and West Hallways		MISC								
"Annex D"-32	12x12 Yellow Floor Tile NOT OBSERVED			East and West Hallways		MISC								
"Annex D"-32A	12x12 Yellow Floor Tile Mastic	1,400	SF	East and West Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Chalkboards	30	EA	Primary, Annexes A & B- All Classrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		
Primary 06A	Gray Baseboard	200	LF	Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary 07A	Gray Baseboard Mastic	600	LF	Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary 31	1x1 Off-White w/Black Specks Ceiling Tile	1,250	SF	Gym and Library	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Primary-01	Hardcoat Plaster	29,952	SF	Ceilings & Half-Walls in Corridors	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-03	12x12 Tan w/Brown Floor Tile	15,094	SF	All Classrooms, Gym, Storage, Room 115 & Library	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-05	12x12 Tan w/Brown Floor Tile Mastic	15,094	SF	All Classrooms, Gym, Storage, Room 115 & Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-06	Black Baseboard	3,100	LF	Classrooms Only	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-07	Black Baseboard Mastic	3,100	LF	Classrooms Only	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
Primary-08	Firedoors	72	SF	Gymnasium	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-20	Textured Ceiling	832	SF	Switch Board Pump Room (Basement)	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Primary-21	Ceramic Tiles	1,160	SF	Vestibules and Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-22	12x12 Yellow Floor Tile	6,284	SF	Hallways 1st & 2nd Floor, Room 205, Teachers' Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-22A	12x12 Yellow Floor Tile Mastic	6,284	SF	Hallways 1st and 2nd floor, Room 205, Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-23	9x9 Beige Floor Tile NOT OBSERVED			In front of 2nd Floor Janitor's Closet		MISC								
Primary-23A	9x9 Beige Floor Tile Mastic NOT OBSERVED			In front of 2nd Floor Janitor's Closet		MISC								
Primary-24	Blue Carpet Adhesive	380	SF	Room 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-25	Purple Carpet Adhesive	600	SF	Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-26	12x12 Gray Floor Tile	304	SF	Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-26A	12x12 Gray Floor Tile Mastic	304	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-27	12x12 White Floor Tile	304	SF	Kitchen, Gym, Storage & Main Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-27A	12x12 White Floor Tile Mastic	304	SF	Kitchen, Gym, Storage & Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-28	Terrazzo	1,670	SF	Stairs & Stairway Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-29	9x9 Cream w/Black Streaks Floor Tile NOT OBSERVED			Rooms 021, 013, 012 (Patches in each Room)		MISC								
Primary-29A	9x9 Cream w/Black Streaks Floor Tile Mastic NOT OBSERVED			Rooms 021, 013, 012 (Patches in Each Room)		MISC								
Primary-30	12x12 Green Floor Tile	6,500	SF	Hallway Borders	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Primary-	12x12 Green Floor Tile Mastic	6,500	SF	Hallway Borders	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
30A												potential for damage		
Primary-32	Vault Liner	10	SF	Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
Primary-A	Aircell Pipe Insulation	610	LF	Crawlspace, Pipechases, Basement, Storage A & B	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
Primary-B	Aircell Pipe Insulation Joints	54	LF	Crawlspace, Pipechase, Basement, Storage A & B	AMO	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
Primary-C	Cardboard Pipe Insulation	2,113	LF	Pipechases, Crawlspace, Basement, Storage A & B	AMO	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
Primary-D	Elbows on Cardboard Insulation	45	LF	Crawlspace, Pipechase, Basement, Storage A & B	AMO	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 1/12/2023
Inspector Name Christopher Antonopoulos
100-18281 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
"Annex A"-FD-1	
"Annex A"-01	
"Annex A"-01A	
"Annex A"-02	Not Observed in 405 or 407- 2022
"Annex A"-02A	Not Observed in 405 or 407- 2022
"Annex A"-02C	
"Annex A"-03	Not Observed 2022
"Annex A"-03A	Not Observed 2022
"Annex A"-04	Not Observed 2022
"Annex A"-04A	Not Observed 2022
"Annex A"-05	Not Observed in Room 401. Present in 408
"Annex A"-05A	No Observed in Room 401. Present in 408
"Annex A"-06	Not Observed in Room 410
"Annex A"-06A	Not Observed in Room 410
"Annex A"-07	Removed 2010
"Annex A"-07A	Removed 2010
"Annex A"-08	
"Annex A"-08A	
"Annex A"-09	
"Annex A"-09A	
"Annex A"-10	
"Annex A"-11	Not Observed Multiple Years, including 2022
"Annex A"-12	

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
"Annex A"-13	
"Annex A"-14	
"Annex A"-15	
"Annex A"-15A	
"Annex A"-16	
"Annex A"-16A	
"Annex A"-17	
"Annex A"-17A	
"Annex A"-18	
"Annex A"-18A	
"Annex A"-19	Not Observed Multiple Years, including 2022
"Annex A"-19A	Not Observed Multiple Years, including 2022
"Annex A"-20	
"Annex A"-20A	
"Annex A"-21	
"Annex A"-21A	
"Annex A"-22	
"Annex A"-23	
"Annex A"-24	
"Annex A"-25	
"Annex A"-26	Status changed per Inspector's Notes
"Annex A"-27	
"Annex A"-32	
"Annex A"-32A	
"Annex A"-A	
"Annex A"-B	
"Annex A"-C	
"Annex A"-D	
"Annex A"-E	

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
"Annex A"-F	
"Annex B "-26	
"Annex B"-26A	
"Annex B"-27	
"Annex B"-27A	
"Annex B"-28	
"Annex B"-28A	
"Annex B"-29	
"Annex B"-29A	
"Annex B"-30	
"Annex B"-30A	
"Annex C"- 11	Building Decommissioned. Abated June 2021
"Annex C"-01	Building Decommissioned. Abated June 2021
"Annex C"-01A	Building Decommissioned. Abated June 2021
"Annex C"-02	Building Decommissioned. Abated June 2021
"Annex C"-02A	Building Decommissioned. Abated June 2021
"Annex C"-03	Building Decommissioned. Abated June 2021
"Annex C"-03A	Building Decommissioned. Abated June 2021
"Annex C"-04	Building Decommissioned. Abated June 2021
"Annex C"-04A	Building Decommissioned. Abated June 2021
"Annex C"-05	Building Decommissioned. Abated June 2021
"Annex C"-05A	Building Decommissioned. Abated June 2021
"Annex C"-06	Building Decommissioned. Abated June 2021
"Annex C"-06A	Building Decommissioned. Abated June 2021
"Annex C"-07	Building Decommissioned. Abated June 2021
"Annex C"-08	Building Decommissioned. Abated June 2021
"Annex C"-09	Building Decommissioned. Abated June 2021
"Annex C"-12	Building Decommissioned. Abated June 2021
"Annex C"-A	Building Decommissioned. Abated June 2021

Chicago Public Schools

School Carver Primary School Unit 22621 Building ID 2690

Address 901 E. 133rd Place Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
"Annex C"-B	Building Decommissioned. Abated June 2021
"Annex C"-C	Building Decommissioned. Abated June 2021
"Annex C"-D	Building Decommissioned. Abated June 2021
"Annex C"-E	Building Decommissioned. Abated June 2021
"Annex C"-F	Building Decommissioned. Abated June 2021
"Annex C"-G	Building Decommissioned. Abated June 2021
"Annex D"-31	
"Annex D"-31A	Not Observed 2022
"Annex D"-32	Not Observed 2022
"Annex D"-32A	
31	
NEW	
Primary 06A	
Primary 07A	
Primary 31	
Primary-01	
Primary-03	N
Primary-05	
Primary-06	
Primary-07	
Primary-08	
Primary-20	
Primary-21	
Primary-22	
Primary-22A	
Primary-23	Not Observed Multiple Years, including 2022
Primary-23A	Not Observed Multiple Years, including 2022
Primary-24	
Primary-25	

Chicago Public Schools

School Carver Primary School **Unit** 22621 **Building ID** 2690

Address 901 E. 133rd Place **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
Primary-26	
Primary-26A	
Primary-27	
Primary-27A	
Primary-28	
Primary-29	Not Observed 2019 & 2022
Primary-29A	Not Observed 2019 & 2022
Primary-30	
Primary-30A	
Primary-32	
Primary-A	
Primary-B	
Primary-C	
Primary-D	

Table II

Management Planner's Review

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
"Annex A"- FD-1	Insulation in Fire Rated Doors	412	SF	Throughout Facility	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-01	1x12 Tan w/Blue Specks Floor Tile	5,580	SF	Halls, Rooms 400, 402, 414 & Paint Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-01A	12x12 Tan w/Blue Specks Floor Tile Mastic	5,580	SF	Rooms Halls, 400, 402, 414, & Paint Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-02	12x12 Gray Floor Tile NOT OBSERVED			Rooms 405 and 407		MISC					
"Annex A"-02A	12x12 Gray Floor Tile Mastic NOT OBSERVED			Annex "A": Rooms 405 and 407		MISC					
"Annex A"-02C	Tan Carpet Adhesive	650	SF	Annex A- Room 411	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-03	12 x 12 Orange Floor Tile NOT OBSERVED			Annex "A"- Room 403		MISC					
"Annex A"-03A	12 x 12 Orange Floor Tile Mastic NOT OBSERVED			Annex "A"- Room 403		MISC					
"Annex A"-04	12x12 Red Floor Tile NOT OBSERVED			Annex "A"- Room 409		MISC					
"Annex A"-04A	12x12 Red Floor Tile Mastic NOT OBSERVED			Annex "A"- Room 409		MISC					
"Annex A"-05	12x12 Blue Floor Tile	600	SF	Annex "A"- Rooms 401 & 408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-05A	12x12 Blue Floor Tile Mastic	600	SF	Annex "A"- Rooms 401 & 408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-06	12x12 Light Green Floor Tile	400	SF	Annex "A"- Room 410 and 404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-06A	12x12 Light Green Floor Tile Mastic	400	SF	Annex "A"- Room 410 and 404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-07	12x12 Sand Floor Tile REMOVED 2010			Annex "A"- 413	Abated	MISC					
"Annex A"-07A	12x12 Sand Floor Tile Mastic REMOVED 2010			Annex "A" 413	Abated	MISC					
"Annex A"-08	12x12 Off-White w/Blue Streaks Floor Tile	1,275	SF	"Annex A"- N/S Corner Connections, Carpenter, Hallways Between Buildings, Main Office, Copy Room,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
A"-19											
"Annex A"-19A	12x12 Red Floor Tile Mastic NOT OBSERVED			Rooms 403 and 409		MISC					
"Annex A"-20	12x12 Orange Floor Tile	500	SF	Rooms 413	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-20A	12x12 Orange Floor Tile Mastic	500	SF	Room 413	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-21	12x12 Gray w/Multicolor Floor Tile	6,200	SF	Room 412, Copy Room, Office & Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-21A	12x12 Gray w/Multicolor Floor Tile Mastic	6,200	SF	Room 412, Copy Room, Office & Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-22	12x12 Lime Green Vinyl Floor Tile	50	SF	Room 409	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-23	12x12 Lime Green Vinyl Floor Tile Mastic	50	SF	Room 409	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-24	12x12 Light Tan Speckled Vinyl Floor Tile	800	SF	Rooms 401 & 409	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-25	12x12 Light Tan Speckled Mastic	800	SF	Rooms 401 & 409	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-26	12x12 Green Vinyl Floor Tile	600	SF	Room 401	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-27	12x12 Green Vinyl Floor Tile Mastic	50	SF	Room 401	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-32	12x12 Beige w/White Streaks Floor Tile	500	SF	Room 406	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-32A	12x12 Beige w/White Streaks Floor Tile	500	SF	Room 406	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex A"-A	Aircell Pipe Insulation	550	LF	Annex "A"- Attic Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
"Annex A"-B	Aircell Pipe Joints	70	LF	Annex "A" - Attic Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
"Annex A"-C	Cardboard Pipe Insulation	370	LF	Annex "A"- Attic Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
"Annex A"-D	Cardboard Pipe Joints	42	LF	Annex "A"- Attic	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
"Annex	Aircell Duct Cover	3,200	SF	Annex "A"- Attic	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
A"-E										suspect ACBM	
"Annex A"-F	MJP E/F/V on Fiberglass Pipe Insulation	50	LF	Annex "A"- Attic (Throughout)	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
"Annex B "-26	12x12 Yellow Floor Tile	10,000	SF	Gym, Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex B"-26A	12x12 Yellow Vinyl Floor Tile Mastic	10,000	SF	Gym, Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex B"-27	12x12 Green Vinyl Floor Tile	1,200	SF	Gym, Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex B"-27A	12x12 Green Vinyl Floor Tile Mastic	1,200	SF	Gym, Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex B"-28	12x12 Beige Floor Tile	3,000	SF	Platform, Coach's Office, Store Room, Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex B"-28A	12x12 Beige Floor Tile Mastic	3,000	SF	Platform, Coach's Office, Store Room, Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex B"-29	12x12 White w/Brown Floor Tile	550	SF	Kitchen, Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex B"-29A	12x12 White w/Brown Floor Tile Mastic	600	SF	Kitchen, Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex B"-30	12x12 Grey w/Multicolor Floor Tile	1,000	SF	Vestibules and Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex B"-30A	12x12 Grey w/Multicolor Floor Tile Mastic	1,000	SF	Vestibules and Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
"Annex C"- 11	Hard Coat Plaster ABATED			Throughout School, Ceilings and Walls		SURFACE					
"Annex C"-01	9x9 Beige w/Specks Floor Tile ABATED			Annex "C" Room 100, 102, 104	Abated	MISC					
"Annex C"-01A	9x9 Beige w/Specks Floor Tile Mastic ABATED			Annex "C" Room 100, 102, 104	Abated	MISC					
"Annex C"-02	9x9 Red w/White streaks Floor Tile ABATED			Annex "2"- Room 107 and Hall (Patches)	Abated	MISC					
"Annex C"-02A	9x9 Red w/White Streaks Floor Tile Mastic ABATED			Annex "C"- Room 107 and Hall (Patches)	Abated	MISC					
"Annex C"-03	9x9 Sand Floor Tile ABATED			Annex "C"- Room 107 and Hall (Patches)	Abated	MISC					
"Annex	9x9 Sand Floor Tile Mastic ABATED			Annex "C"- Room 107 and Hall	Abated	MISC					

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
C"-03A				(Patches)							
"Annex C"-04	12x12 Red w/White Streaks Floor Tile ABATED			Annex "C"- Entire School, except Rooms 100, 102 & 104	Abated	MISC					
"Annex C"-04A	12x12 Red with White Streaks Floor Tile Mastic ABATED			Annex "C"- Entire School, except for Rooms 100, 102 & 104	Abated	MISC					
"Annex C"-05	12x12 Brown w/Black Streaks Floor Tile ABATED			Annex "C"- Entire School, except Rooms 100, 102 & 104	Abated	MISC					
"Annex C"-05A	12x12 Brown w/Black Streaks Floor Tile Mastic ABATED			Annex "C"- Entire School, except Rooms 100, 102 & 104	Chrysotile	MISC					
"Annex C"-06	18x24 Brown Edging Floor Tile ABATED			Annex "C"- Perimeter of Classrooms and Halls	Abated	MISC					
"Annex C"-06A	18x24 Brown Edging Floor Tile Mastic ABATED			Annex "C"- Perimeter of Classrooms and Halls	Abated	MISC					
"Annex C"-07	Ceramic Tile Grout ABATED			Annex "C"- All Washrooms	Abated	MISC					
"Annex C"-08	Hardcoat Plaster ABATED			Annex "C"- Throughout School	Abated	SURFACE					
"Annex C"-09	Firebrick ABATED			Annex "C"- Boiler Room Incinerator	Abated	MISC					
"Annex C"-12	Friable Surfacing Material ABATED			Annex "C"- Boiler Room Inside Blower Room (Heat Exchange)	Abated	SURFACE					
"Annex C"-A	Aircell Pipe Cover ABATED			Annex C- Boiler Room Attic	Abated	TSI					
"Annex C"-B	Aircell Joints ABATED			Annex "C"- Boiler Room Attic	Abated	TSI					
"Annex C"-C	Cardboard Pipe Cover ABATED			Annex "C"- Boiler Room Attic	Abated	TSI					
"Annex C"-D	Cardboard Pipe Joints ABATED			Annex "C"- Boiler Room Attic	Abated	TSI					
"Annex C"-E	Aircell Duct Cover ABATED			Annex "C"- Boiler Room Attic	Chrysotile	TSI					
"Annex C"-F	Fiberglass Joints ABATED			Annex "C"- Boiler Room	Abated	TSI					
"Annex C"-G	Mag Tank Cover ABATED			Annex "C"- Boiler Room	Abated	TSI					
"Annex	12x12 Green Floor Tile	1,400	SF	East and West Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
D"-31											
"Annex D"-31A	12x12 Green Floor Tile Mastic NOT OBSERVED			East and West Hallways		MISC					
"Annex D"-32	12x12 Yellow Floor Tile NOT OBSERVED			East and West Hallways		MISC					
"Annex D"-32A	12x12 Yellow Floor Tile Mastic	1,400	SF	East and West Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Chalkboards	30	EA	Primary, Annexes A & B- All Classrooms	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
Primary 06A	Gray Baseboard	200	LF	Room 103	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Primary 07A	Gray Baseboard Mastic	600	LF	Room 103	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Primary 31	1x1 Off-White w/Black Specks Ceiling Tile	1,250	SF	Gym and Library	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Primary -01	Hardcoat Plaster	29,952	SF	Ceilings & Half-Walls in Corridors	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -03	12x12 Tan w/Brown Floor Tile	15,094	SF	All Classrooms, Gym, Storage, Room 115 & Library	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -05	12x12 Tan w/Brown Floor Tile Mastic	15,094	SF	All Classrooms, Gym, Storage, Room 115 & Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -06	Black Baseboard	3,100	LF	Classrooms Only	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -07	Black Baseboard Mastic	3,100	LF	Classrooms Only	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -08	Firedoors	72	SF	Gymnasium	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -20	Textured Ceiling	832	SF	Switch Board Pump Room (Basement)	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Primary -21	Ceramic Tiles	1,160	SF	Vestibules and Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -22	12x12 Yellow Floor Tile	6,284	SF	Hallways 1st & 2nd Floor, Room 205, Teachers' Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
Primary -22A	12x12 Yellow Floor Tile Mastic	6,284	SF	Hallways 1st and 2nd floor, Room 205, Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -23	9x9 Beige Floor Tile NOT OBSERVED			In front of 2nd Floor Janitor's Closet		MISC					
Primary -23A	9x9 Beige Floor Tile Mastic NOT OBSERVED			In front of 2nd Floor Janitor's Closet		MISC					
Primary -24	Blue Carpet Adhesive	380	SF	Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -25	Purple Carpet Adhesive	600	SF	Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -26	12x12 Gray Floor Tile	304	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -26A	12x12 Gray Floor Tile Mastic	304	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -27	12x12 White Floor Tile	304	SF	Kitchen, Gym, Storage & Main Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -27A	12x12 White Floor Tile Mastic	304	SF	Kitchen, Gym, Storage & Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -28	Terrazzo	1,670	SF	Stairs & Stairway Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -29	9x9 Cream w/Black Streaks Floor Tile NOT OBSERVED			Rooms 021, 013, 012 (Patches in each Room)		MISC					
Primary -29A	9x9 Cream w/Black Streaks Floor Tile Mastic NOT OBSERVED			Rooms 021, 013, 012 (Patches in Each Room)		MISC					
Primary -30	12x12 Green Floor Tile	6,500	SF	Hallway Borders	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -30A	12x12 Green Floor Tile Mastic	6,500	SF	Hallway Borders	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -32	Vault Liner	10	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Primary -A	Aircell Pipe Insulation	610	LF	Crawlspace, Pipechases, Basement, Storage A & B	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Primary -B	Aircell Pipe Insulation Joints	54	LF	Crawlspace, Pipechase, Basement, Storage A & B	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Primary -C	Cardboard Pipe Insulation	2,113	LF	Pipechases, Crawlspace, Basement, Storage A & B	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
Primary -D	Elbows on Cardboard Insulation	45	LF	Crawlspace, Pipechase, Basement, Storage A & B	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Review Date	1/13/2023
Manager Planner Name	Todd Huffer

HA Number	Management Comments
"Annex A"-FD-1	

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
"Annex A"-01	
"Annex A"-01 A	
"Annex A"-02	
"Annex A"-02 A	
"Annex A"-02 C	
"Annex A"-03	
"Annex A"-03 A	
"Annex A"-04	
"Annex A"-04 A	
"Annex A"-05	
"Annex A"-05 A	
"Annex A"-06	
"Annex A"-06 A	
"Annex A"-07	
"Annex A"-07 A	
"Annex A"-08	
"Annex A"-08 A	
"Annex A"-09	
"Annex A"-09	

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
A	
"Annex A"-10	
"Annex A"-11	
"Annex A"-12	
"Annex A"-13	
"Annex A"-14	
"Annex A"-15	
"Annex A"-15 A	
"Annex A"-16	
"Annex A"-16 A	
"Annex A"-17	
"Annex A"-17 A	
"Annex A"-18	
"Annex A"-18 A	
"Annex A"-19	
"Annex A"-19 A	
"Annex A"-20	
"Annex A"-20 A	
"Annex A"-21	
"Annex A"-21 A	
"Annex A"-22	

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
"Annex A"-23	
"Annex A"-24	
"Annex A"-25	
"Annex A"-26	
"Annex A"-27	
"Annex A"-32	
"Annex A"-32 A	
"Annex A"-A	
"Annex A"-B	
"Annex A"-C	
"Annex A"-D	
"Annex A"-E	
"Annex A"-F	
"Annex B "-26	
"Annex B"-26 A	
"Annex B"-27	
"Annex B"-27 A	
"Annex B"-28	
"Annex B"-28 A	
"Annex B"-29	
"Annex B"-29 A	
"Annex B"-30	

Chicago Public Schools

School Carver Primary School

Unit 22621

Building ID 2690

Address 901 E. 133rd Place

Chicago, IL, 60627

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
"Annex B"-30 A	
"Annex C"- 11	Building Decommissioned
"Annex C"-01	Building Decommissioned
"Annex C"-01 A	Building Decommissioned
"Annex C"-02	Building Decommissioned
"Annex C"-02 A	Building Decommissioned
"Annex C"-03	Building Decommissioned
"Annex C"-03 A	Building Decommissioned
"Annex C"-04	Building Decommissioned
"Annex C"-04 A	Building Decommissioned
"Annex C"-05	
"Annex C"-05 A	Building Decommissioned
"Annex C"-06	Building Decommissioned
"Annex C"-06 A	Building Decommissioned
"Annex C"-07	Building Decommissioned
"Annex C"-08	Building Decommissioned
"Annex C"-09	Building Decommissioned
"Annex C"-12	Building Decommissioned
"Annex C"-A	Building Decommissioned
"Annex C"-B	Building Decommissioned
"Annex C"-C	Building Decommissioned

Chicago Public Schools

School Carver Primary School
Address 901 E. 133rd Place

Unit 22621
 Chicago, IL, 60627

Building ID 2690
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
"Annex C"-D	Building Decommissioned
"Annex C"-E	Building Decommissioned
"Annex C"-F	Building Decommissioned
"Annex C"-G	Building Decommissioned
"Annex D"-31	
"Annex D"-31 A	
"Annex D"-32	
"Annex D"-32 A	
31	
NEW	
Primary 06A	
Primary 07A	
Primary 31	
Primary-01	
Primary-03	
Primary-05	
Primary-06	
Primary-07	
Primary-08	
Primary-20	
Primary-21	
Primary-22	
Primary-22A	
Primary-23	
Primary-23A	

Chicago Public Schools

School Carver Primary School
Address 901 E. 133rd Place

Unit 22621
Chicago, IL, 60627

Building ID 2690
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
Primary-24	
Primary-25	
Primary-26	
Primary-26A	
Primary-27	
Primary-27A	
Primary-28	
Primary-29	
Primary-29A	
Primary-30	
Primary-30A	
Primary-32	
Primary-A	
Primary-B	
Primary-C	
Primary-D	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"- FD-1**
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **412**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"- FD-1**
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **412** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-01
MATERIAL DESCRIPTION: 1x12 Tan w/Blue Specks Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Halls, Rooms 400, 402, 414 & Paint Room**
MATERIAL QUANTITY: **5580** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-01**
MATERIAL DESCRIPTION: **1x12 Tan w/Blue Specks Floor Tile**
MATERIAL LOCATION: **Halls, Rooms 400, 402, 414 & Paint Room**
MATERIAL QUANTITY: **5580** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-01A**
MATERIAL DESCRIPTION: **12x12 Tan w/Blue Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms Halls, 400, 402, 414, & Paint Room**

MATERIAL QUANTITY: **5580**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-01A**
MATERIAL DESCRIPTION: **12x12 Tan w/Blue Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms Halls, 400, 402, 414, & Paint Room**
MATERIAL QUANTITY: **5580** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-02**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 405 and 407**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed in 405 or 407- 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-02**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile NOT OBSERVED**
MATERIAL LOCATION: **Rooms 405 and 407**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-02A**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "A": Rooms 405 and 407**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed in 405 or 407- 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-02A**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic NOT OBSERVED**
MATERIAL LOCATION: **Annex "A": Rooms 405 and 407**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-02C**
MATERIAL DESCRIPTION: **Tan Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex A- Room 411**

MATERIAL QUANTITY: **650**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-02C**
MATERIAL DESCRIPTION: **Tan Carpet Adhesive**
MATERIAL LOCATION: **Annex A- Room 411**
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-03
MATERIAL DESCRIPTION: 12 x 12 Orange Floor Tile NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Annex "A"- Room 403

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-03**
MATERIAL DESCRIPTION: **12 x 12 Orange Floor Tile NOT OBSERVED**
MATERIAL LOCATION: **Annex "A" - Room 403**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-03A**
MATERIAL DESCRIPTION: **12 x 12 Orange Floor Tile Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "A"- Room 403**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-03A**

MATERIAL DESCRIPTION: **12 x 12 Orange Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Annex "A" - Room 403**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-04
MATERIAL DESCRIPTION: 12x12 Red Floor Tile NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Annex "A"- Room 409

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-04**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile NOT OBSERVED**
MATERIAL LOCATION: **Annex "A" - Room 409**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-04A**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "A"- Room 409**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-04A**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic NOT OBSERVED**
MATERIAL LOCATION: **Annex "A" - Room 409**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-05
MATERIAL DESCRIPTION: 12x12 Blue Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex "A"- Rooms 401 & 408**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Room 401. Present in 408**

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-05**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**
MATERIAL LOCATION: **Annex "A"- Rooms 401 & 408**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-05A
MATERIAL DESCRIPTION: 12x12 Blue Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Annex "A"- Rooms 401 & 408
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS: No Observed in Room 401. Present in 408

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-05A**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**
MATERIAL LOCATION: **Annex "A"- Rooms 401 & 408**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-06
MATERIAL DESCRIPTION: 12x12 Light Green Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex "A"- Room 410 and 404**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Room 410**

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-06**
MATERIAL DESCRIPTION: **12x12 Light Green Floor Tile**
MATERIAL LOCATION: **Annex "A" - Room 410 and 404**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-06A
MATERIAL DESCRIPTION: 12x12 Light Green Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex "A"- Room 410 and 404**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Room 410**

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-06A**
MATERIAL DESCRIPTION: **12x12 Light Green Floor Tile Mastic**
MATERIAL LOCATION: **Annex "A" - Room 410 and 404**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-07**
MATERIAL DESCRIPTION: **12x12 Sand Floor Tile REMOVED 2010**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "A"- 413**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Removed 2010**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-07**
MATERIAL DESCRIPTION: **12x12 Sand Floor Tile REMOVED 2010**
MATERIAL LOCATION: **Annex "A"- 413**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-07A**
MATERIAL DESCRIPTION: **12x12 Sand Floor Tile Mastic REMOVED 2010**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "A" 413**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Removed 2010**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-07A**

MATERIAL DESCRIPTION: **12x12 Sand Floor Tile Mastic REMOVED 2010**

MATERIAL LOCATION: **Annex "A" 413**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-08
MATERIAL DESCRIPTION: 12x12 Off-White w/Blue Streaks Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: "Annex A"- N/S Corner Connections, Carpenter, Hallways Between Buildings, Main Office, Copy Room, Teachers' Lounge & Room 408

MATERIAL QUANTITY: 1275 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-08**
MATERIAL DESCRIPTION: **12x12 Off-White w/Blue Streaks Floor Tile**
MATERIAL LOCATION: **"Annex A" - N/S Corner Connections, Carpenter, Hallways Between Buildings, Main Office, Copy Room, Teachers' Lounge & Room 408**
MATERIAL QUANTITY: **1275** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-08A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Blue Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **"Annex A"- N/S Corner Connections, Carpenter, Hallways Between Buildings, Main Office, Copy Room, Teachers' Lounge & Room 408**

MATERIAL QUANTITY: **1275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-08A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Blue Specks Mastic**
MATERIAL LOCATION: **"Annex A" - N/S Corner Connections, Carpenter, Hallways Between Buildings, Main Office, Copy Room, Teachers' Lounge & Room 408**
MATERIAL QUANTITY: **1275** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-09
MATERIAL DESCRIPTION: Brown Baseboard
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: North & South Connecting Hallways
MATERIAL QUANTITY: 230 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-09**
MATERIAL DESCRIPTION: **Brown Baseboard**
MATERIAL LOCATION: **North & South Connecting Hallways**
MATERIAL QUANTITY: **230** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-09A**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **"Annex A"- North and South Connecting Hallways**

MATERIAL QUANTITY: **230** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-09A**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
MATERIAL LOCATION: **"Annex A" - North and South Connecting Hallways**
MATERIAL QUANTITY: **230** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-10
MATERIAL DESCRIPTION: Gray Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: "Annex A"- Main Office, Rooms 410, 413, 408, 412, 405, 407, 403

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-10**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
MATERIAL LOCATION: **"Annex A" - Main Office, Rooms 410, 413, 408, 412, 405, 407, 403**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-11
MATERIAL DESCRIPTION: Green Carpet Mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 405, 407, 411, 402, 401, 409

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years, including 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-11**
MATERIAL DESCRIPTION: **Green Carpet Mastic NOT OBSERVED**
MATERIAL LOCATION: **Rooms 405, 407, 411, 402, 401, 409**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-12
MATERIAL DESCRIPTION: Firebrick ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: "Annex A"- Boiler Room Incinerator

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-12**
MATERIAL DESCRIPTION: **Firebrick ABATED**
MATERIAL LOCATION: **"Annex A" - Boiler Room Incinerator**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-13
MATERIAL DESCRIPTION: Ceramic Floor Tile Grout
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex "A"- Washrooms**

MATERIAL QUANTITY: **682**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-13**
MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**
MATERIAL LOCATION: **Annex "A" - Washrooms**
MATERIAL QUANTITY: **682** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-14**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex "A"- Throughout Building**
MATERIAL QUANTITY: **54000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-14**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **Annex "A" - Throughout Building**
MATERIAL QUANTITY: **54000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-15
MATERIAL DESCRIPTION: 12x12 Tan w/Specks Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex "A"- Small Entry Hallways**

MATERIAL QUANTITY: **325**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-15**
MATERIAL DESCRIPTION: **12x12 Tan w/Specks Floor Tile**
MATERIAL LOCATION: **Annex "A" - Small Entry Hallways**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-15A
MATERIAL DESCRIPTION: 12x12 Tan w/Specks Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex "A"- Small Entry Hallways**

MATERIAL QUANTITY: **325**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-15A**
MATERIAL DESCRIPTION: **12x12 Tan w/Specks Mastic**
MATERIAL LOCATION: **Annex "A" - Small Entry Hallways**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-16**
MATERIAL DESCRIPTION: **12x12 Off-White w/Brown Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex "A"- Entry Easy**

MATERIAL QUANTITY: **485**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-16**
MATERIAL DESCRIPTION: **12x12 Off-White w/Brown Specks Floor Tile**
MATERIAL LOCATION: **Annex "A" - Entry Easy**
MATERIAL QUANTITY: **485** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-16A
MATERIAL DESCRIPTION: 12x12 Off-White w/Brown Specks Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex "A"- Entry Easy**

MATERIAL QUANTITY: **485**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-16A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **Annex "A" - Entry Easy**
MATERIAL QUANTITY: **485** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-17**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 405 & 407**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-17**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
MATERIAL LOCATION: **Rooms 405 & 407**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-17A**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 405 & 407**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-17A**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 405 & 407**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-18**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 404 & 408**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-18**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**
MATERIAL LOCATION: **Rooms 404 & 408**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-18A**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 404 & 408**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-18A**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 404 & 408**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-19**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile NOT OBSERVED**
MATERIAL LOCATION: **Rooms 403 and 409**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-19A**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic NOT OBSERVED**
MATERIAL LOCATION: **Rooms 403 and 409**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-20
MATERIAL DESCRIPTION: 12x12 Orange Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Rooms 413
MATERIAL QUANTITY: 500 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-20**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**
MATERIAL LOCATION: **Rooms 413**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-20A
MATERIAL DESCRIPTION: 12x12 Orange Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 413**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-20A**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**
MATERIAL LOCATION: **Room 413**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-21
MATERIAL DESCRIPTION: 12x12 Gray w/Multicolor Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 412, Copy Room, Office & Hallway**

MATERIAL QUANTITY: **6200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-21**
MATERIAL DESCRIPTION: **12x12 Gray w/Multicolor Floor Tile**
MATERIAL LOCATION: **Room 412, Copy Room, Office & Hallway**
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-21A
MATERIAL DESCRIPTION: 12x12 Gray w/Multicolor Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 412, Copy Room, Office & Hallway**

MATERIAL QUANTITY: **6200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-21A**
MATERIAL DESCRIPTION: **12x12 Gray w/Multicolor Floor Tile Mastic**
MATERIAL LOCATION: **Room 412, Copy Room, Office & Hallway**
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-22
MATERIAL DESCRIPTION: 12x12 Lime Green Vinyl Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 409
MATERIAL QUANTITY: 50 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-22**
MATERIAL DESCRIPTION: **12x12 Lime Green Vinyl Floor Tile**
MATERIAL LOCATION: **Room 409**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-23
MATERIAL DESCRIPTION: 12x12 Lime Green Vinyl Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 409**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-23**
MATERIAL DESCRIPTION: **12x12 Lime Green Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 409**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-24
MATERIAL DESCRIPTION: 12x12 Light Tan Speckled Vinyl Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Rooms 401 & 409
MATERIAL QUANTITY: 800 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-24**
MATERIAL DESCRIPTION: **12x12 Light Tan Speckled Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 401 & 409**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-25**
MATERIAL DESCRIPTION: **12x12 Light Tan Speckled Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 401 & 409**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-25**
MATERIAL DESCRIPTION: **12x12 Light Tan Speckled Mastic**
MATERIAL LOCATION: **Rooms 401 & 409**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-26
MATERIAL DESCRIPTION: 12x12 Green Vinyl Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 401
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS: Status changed per Inspector's Notes

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-26**
MATERIAL DESCRIPTION: **12x12 Green Vinyl Floor Tile**
MATERIAL LOCATION: **Room 401**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-27
MATERIAL DESCRIPTION: 12x12 Green Vinyl Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 401
MATERIAL QUANTITY: 50 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-27**
MATERIAL DESCRIPTION: **12x12 Green Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 401**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex "A"- Attic Pipe Chases**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Annex "A" - Attic Pipe Chases**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-B**
MATERIAL DESCRIPTION: **Aircell Pipe Joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex "A" - Attic Pipe Chases**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-B**
MATERIAL DESCRIPTION: **Aircell Pipe Joints**
MATERIAL LOCATION: **Annex "A" - Attic Pipe Chases**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex "A"- Attic Pipe Chases**
MATERIAL QUANTITY: **370** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Annex "A" - Attic Pipe Chases**
MATERIAL QUANTITY: **370** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex A"-D
MATERIAL DESCRIPTION: Cardboard Pipe Joints
HISTORICAL AHERA DAMAGE CATEGORY 7 Any remaining friable ACBM or friable suspect ACBM
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Annex "A"- Attic
MATERIAL QUANTITY: 42 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-D**
MATERIAL DESCRIPTION: **Cardboard Pipe Joints**
MATERIAL LOCATION: **Annex "A"- Attic**
MATERIAL QUANTITY: **42** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-E**
MATERIAL DESCRIPTION: **Aircell Duct Cover**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex "A"- Attic**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-E**
MATERIAL DESCRIPTION: **Aircell Duct Cover**
MATERIAL LOCATION: **Annex "A" - Attic**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex A"-F**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex "A"- Attic (Throughout)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-F**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Annex "A" - Attic (Throughout)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex B "-26**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym, Corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B "-26**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**
MATERIAL LOCATION: **Gym, Corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex B"-26A
MATERIAL DESCRIPTION: 12x12 Yellow Vinyl Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Gym, Corridors
MATERIAL QUANTITY: 10000 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B"-26A**
MATERIAL DESCRIPTION: **12x12 Yellow Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Gym, Corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex B"-27
MATERIAL DESCRIPTION: 12x12 Green Vinyl Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Gym, Corridors
MATERIAL QUANTITY: 1200 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B"-27**
MATERIAL DESCRIPTION: **12x12 Green Vinyl Floor Tile**
MATERIAL LOCATION: **Gym, Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex B"-27A
MATERIAL DESCRIPTION: 12x12 Green Vinyl Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Gym, Corridors
MATERIAL QUANTITY: 1200 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B"-27A**
MATERIAL DESCRIPTION: **12x12 Green Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Gym, Corridors**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex B"-28
MATERIAL DESCRIPTION: 12x12 Beige Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Platform, Coach's Office, Store Room, Offices**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B"-28**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**
MATERIAL LOCATION: **Platform, Coach's Office, Store Room, Offices**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex B"-28A
MATERIAL DESCRIPTION: 12x12 Beige Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Platform, Coach's Office, Store Room, Offices
MATERIAL QUANTITY: 3000 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B"-28A**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**
MATERIAL LOCATION: **Platform, Coach's Office, Store Room, Offices**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex B"-29**
MATERIAL DESCRIPTION: **12x12 White w/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen, Lunchroom**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B"-29**
MATERIAL DESCRIPTION: **12x12 White w/Brown Floor Tile**
MATERIAL LOCATION: **Kitchen, Lunchroom**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex B"-29A**
MATERIAL DESCRIPTION: **12x12 White w/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen, Lunchroom**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B"-29A**
MATERIAL DESCRIPTION: **12x12 White w/Brown Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen, Lunchroom**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex B"-30
MATERIAL DESCRIPTION: 12x12 Grey w/Multicolor Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Vestibules and Lobby
MATERIAL QUANTITY: 1000 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B"-30**
MATERIAL DESCRIPTION: **12x12 Grey w/Multicolor Floor Tile**
MATERIAL LOCATION: **Vestibules and Lobby**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex B"-30A
MATERIAL DESCRIPTION: 12x12 Grey w/Multicolor Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Vestibules and Lobby**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex B"-30A**
MATERIAL DESCRIPTION: **12x12 Grey w/Multicolor Floor Tile Mastic**
MATERIAL LOCATION: **Vestibules and Lobby**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"- 11**
MATERIAL DESCRIPTION: **Hard Coat Plaster ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School, Ceilings and Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"- 11**
MATERIAL DESCRIPTION: **Hard Coat Plaster ABATED**
MATERIAL LOCATION: **Throughout School, Ceilings and Walls**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-01**
MATERIAL DESCRIPTION: **9x9 Beige w/Specks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C" Room 100, 102, 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-01**
MATERIAL DESCRIPTION: **9x9 Beige w/Specks Floor Tile ABATED**
MATERIAL LOCATION: **Annex "C" Room 100, 102, 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex C"-01A
MATERIAL DESCRIPTION: 9x9 Beige w/Specks Floor Tile Mastic ABATED
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Annex "C" Room 100, 102, 104

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Building Decommissioned. Abated June 2021

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-01A**
MATERIAL DESCRIPTION: **9x9 Beige w/Specks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Annex "C" Room 100, 102, 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:
Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-02**
MATERIAL DESCRIPTION: **9x9 Red w/White streaks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "2"- Room 107 and Hall (Patches)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-02**
MATERIAL DESCRIPTION: **9x9 Red w/White streaks Floor Tile ABATED**
MATERIAL LOCATION: **Annex "2"- Room 107 and Hall (Patches)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-02A**
MATERIAL DESCRIPTION: **9x9 Red w/White Streaks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Room 107 and Hall (Patches)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-02A**
MATERIAL DESCRIPTION: **9x9 Red w/White Streaks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Annex "C"- Room 107 and Hall (Patches)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-03**
MATERIAL DESCRIPTION: **9x9 Sand Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Room 107 and Hall (Patches)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-03**
MATERIAL DESCRIPTION: **9x9 Sand Floor Tile ABATED**
MATERIAL LOCATION: **Annex "C"- Room 107 and Hall (Patches)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-03A**
MATERIAL DESCRIPTION: **9x9 Sand Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Room 107 and Hall (Patches)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-03A**
MATERIAL DESCRIPTION: **9x9 Sand Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Annex "C"- Room 107 and Hall (Patches)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-04**
MATERIAL DESCRIPTION: **12x12 Red w/White Streaks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Entire School, except Rooms 100, 102 & 104**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-04**
MATERIAL DESCRIPTION: **12x12 Red w/White Streaks Floor Tile ABATED**
MATERIAL LOCATION: **Annex "C"- Entire School, except Rooms 100, 102 & 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-04A**
MATERIAL DESCRIPTION: **12x12 Red with White Streaks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Entire School, except for Rooms 100, 102 & 104**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-04A**
MATERIAL DESCRIPTION: **12x12 Red with White Streaks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Annex "C"- Entire School, except for Rooms 100, 102 & 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex C"-05
MATERIAL DESCRIPTION: 12x12 Brown w/Black Streaks Floor Tile ABATED
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Annex "C"- Entire School, except Rooms 100, 102 & 104

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Building Decommissioned. Abated June 2021

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-05**
MATERIAL DESCRIPTION: **12x12 Brown w/Black Streaks Floor Tile ABATED**
MATERIAL LOCATION: **Annex "C"- Entire School, except Rooms 100, 102 & 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-05A**
MATERIAL DESCRIPTION: **12x12 Brown w/Black Streaks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Entire School, except Rooms 100, 102 & 104**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-05A**
MATERIAL DESCRIPTION: **12x12 Brown w/Black Streaks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Annex "C"- Entire School, except Rooms 100, 102 & 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex C"-06
MATERIAL DESCRIPTION: 18x24 Brown Edging Floor Tile ABATED
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Annex "C"- Perimeter of Classrooms and Halls

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Building Decommissioned. Abated June 2021

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-06**
MATERIAL DESCRIPTION: **18x24 Brown Edging Floor Tile ABATED**
MATERIAL LOCATION: **Annex "C"- Perimeter of Classrooms and Halls**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-06A**
MATERIAL DESCRIPTION: **18x24 Brown Edging Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Perimeter of Classrooms and Halls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-06A**
MATERIAL DESCRIPTION: **18x24 Brown Edging Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Annex "C"- Perimeter of Classrooms and Halls**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: "Annex C"-07
MATERIAL DESCRIPTION: Ceramic Tile Grout ABATED
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Annex "C"- All Washrooms

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Building Decommissioned. Abated June 2021

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-07**
MATERIAL DESCRIPTION: **Ceramic Tile Grout ABATED**
MATERIAL LOCATION: **Annex "C"- All Washrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-08**
MATERIAL DESCRIPTION: **Hardcoat Plaster ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-08**
MATERIAL DESCRIPTION: **Hardcoat Plaster ABATED**
MATERIAL LOCATION: **Annex "C"- Throughout School**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: 01/13/2023

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-09**
MATERIAL DESCRIPTION: **Firebrick ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Boiler Room Incinerator**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-09**
MATERIAL DESCRIPTION: **Firebrick ABATED**
MATERIAL LOCATION: **Annex "C"- Boiler Room Incinerator**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-12**
MATERIAL DESCRIPTION: **Friable Surfacing Material ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Boiler Room Inside Blower Room (Heat Exchange)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-12**
MATERIAL DESCRIPTION: **Friable Surfacing Material ABATED**
MATERIAL LOCATION: **Annex "C"- Boiler Room Inside Blower Room (Heat Exchange)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-A**
MATERIAL DESCRIPTION: **Aircell Pipe Cover ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex C- Boiler Room Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-A**
MATERIAL DESCRIPTION: **Aircell Pipe Cover ABATED**
MATERIAL LOCATION: **Annex C- Boiler Room Attic**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-B**
MATERIAL DESCRIPTION: **Aircell Joints ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Boiler Room Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-B**
MATERIAL DESCRIPTION: **Aircell Joints ABATED**
MATERIAL LOCATION: **Annex "C"- Boiler Room Attic**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-C**
MATERIAL DESCRIPTION: **Cardboard Pipe Cover ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Boiler Room Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-C**
MATERIAL DESCRIPTION: **Cardboard Pipe Cover ABATED**
MATERIAL LOCATION: **Annex "C"- Boiler Room Attic**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-D**
MATERIAL DESCRIPTION: **Cardboard Pipe Joints ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Boiler Room Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-D**
MATERIAL DESCRIPTION: **Cardboard Pipe Joints ABATED**
MATERIAL LOCATION: **Annex "C"- Boiler Room Attic**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-E**
MATERIAL DESCRIPTION: **Aircell Duct Cover ABATED**
HISTORICAL AHERA DAMAGE CATEGORY: **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Boiler Room Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-E**
MATERIAL DESCRIPTION: **Aircell Duct Cover ABATED**
MATERIAL LOCATION: **Annex "C"- Boiler Room Attic**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-F**
MATERIAL DESCRIPTION: **Fiberglass Joints ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-F**
MATERIAL DESCRIPTION: **Fiberglass Joints ABATED**
MATERIAL LOCATION: **Annex "C"- Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex C"-G**
MATERIAL DESCRIPTION: **Mag Tank Cover ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex "C"- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Building Decommissioned. Abated June 2021**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex C"-G**
MATERIAL DESCRIPTION: **Mag Tank Cover ABATED**
MATERIAL LOCATION: **Annex "C"- Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Building Decommissioned

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex D"-31**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East and West Hallways**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex D"-31**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
MATERIAL LOCATION: **East and West Hallways**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex D"-31A**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East and West Hallways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex D"-31A**

MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **East and West Hallways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex D"-32**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East and West Hallways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex D"-32**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile NOT OBSERVED**
MATERIAL LOCATION: **East and West Hallways**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **"Annex D"-32A**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **East and West Hallways**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex D"-32A**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**
MATERIAL LOCATION: **East and West Hallways**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary 06A**
MATERIAL DESCRIPTION: **Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary 06A**
MATERIAL DESCRIPTION: **Gray Baseboard**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary 07A
MATERIAL DESCRIPTION: Gray Baseboard Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 103
MATERIAL QUANTITY: 600 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary 07A**
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary 31**
MATERIAL DESCRIPTION: **1x1 Off-White w/Black Specks Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym and Library**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary 31**
MATERIAL DESCRIPTION: **1x1 Off-White w/Black Specks Ceiling Tile**
MATERIAL LOCATION: **Gym and Library**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-01
MATERIAL DESCRIPTION: Hardcoat Plaster
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Ceilings & Half-Walls in Corridors
MATERIAL QUANTITY: 29952 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-01**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **Ceilings & Half-Walls in Corridors**
MATERIAL QUANTITY: **29952** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary-03**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Classrooms, Gym, Storage, Room 115 & Library**
MATERIAL QUANTITY: **15094** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **N**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-03**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Floor Tile**
MATERIAL LOCATION: **All Classrooms, Gym, Storage, Room 115 & Library**
MATERIAL QUANTITY: **15094** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary-05**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Classrooms, Gym, Storage, Room 115 & Library**
MATERIAL QUANTITY: **15094** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-05**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Floor Tile Mastic**
MATERIAL LOCATION: **All Classrooms, Gym, Storage, Room 115 & Library**
MATERIAL QUANTITY: **15094** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-06
MATERIAL DESCRIPTION: Black Baseboard
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Classrooms Only
MATERIAL QUANTITY: 3100 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-06**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Classrooms Only**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-07
MATERIAL DESCRIPTION: Black Baseboard Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Classrooms Only
MATERIAL QUANTITY: 3100 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-07**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Classrooms Only**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary-08**
MATERIAL DESCRIPTION: **Firedoors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **72**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-08**

MATERIAL DESCRIPTION: **Firedoors**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **72**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-20
MATERIAL DESCRIPTION: Textured Ceiling
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Switch Board Pump Room (Basement)
MATERIAL QUANTITY: 832 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-20**
MATERIAL DESCRIPTION: **Textured Ceiling**
MATERIAL LOCATION: **Switch Board Pump Room (Basement)**
MATERIAL QUANTITY: **832** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-21
MATERIAL DESCRIPTION: Ceramic Tiles
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Vestibules and Washrooms**

MATERIAL QUANTITY: **1160**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-21**
MATERIAL DESCRIPTION: **Ceramic Tiles**
MATERIAL LOCATION: **Vestibules and Washrooms**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-22
MATERIAL DESCRIPTION: 12x12 Yellow Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallways 1st & 2nd Floor, Room 205, Teachers' Lounge**

MATERIAL QUANTITY: **6284** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-22**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**
MATERIAL LOCATION: **Hallways 1st & 2nd Floor, Room 205, Teachers' Lounge**
MATERIAL QUANTITY: **6284** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-22A
MATERIAL DESCRIPTION: 12x12 Yellow Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallways 1st and 2nd floor, Room 205, Teachers' Lounge**

MATERIAL QUANTITY: **6284** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-22A**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Hallways 1st and 2nd floor, Room 205, Teachers' Lounge**
MATERIAL QUANTITY: **6284** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-23**
MATERIAL DESCRIPTION: **9x9 Beige Floor Tile NOT OBSERVED**
MATERIAL LOCATION: **In front of 2nd Floor Janitor's Closet**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-23A
MATERIAL DESCRIPTION: 9x9 Beige Floor Tile Mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: In front of 2nd Floor Janitor's Closet

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years, including 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-23A**
MATERIAL DESCRIPTION: **9x9 Beige Floor Tile Mastic NOT OBSERVED**
MATERIAL LOCATION: **In front of 2nd Floor Janitor's Closet**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023** _____

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary-24**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: **380**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-24**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-25
MATERIAL DESCRIPTION: Purple Carpet Adhesive
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 103
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-25**
MATERIAL DESCRIPTION: **Purple Carpet Adhesive**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-26
MATERIAL DESCRIPTION: 12x12 Gray Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Kitchen
MATERIAL QUANTITY: 304 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-26**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **304** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-26A
MATERIAL DESCRIPTION: 12x12 Gray Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Kitchen
MATERIAL QUANTITY: 304 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-26A**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **304** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-27
MATERIAL DESCRIPTION: 12x12 White Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, Gym, Storage & Main Office**

MATERIAL QUANTITY: **304**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-27**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
MATERIAL LOCATION: **Kitchen, Gym, Storage & Main Office**
MATERIAL QUANTITY: **304** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-27A
MATERIAL DESCRIPTION: 12x12 White Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, Gym, Storage & Main Office**

MATERIAL QUANTITY: **304**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-27A**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen, Gym, Storage & Main Office**
MATERIAL QUANTITY: **304** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-28
MATERIAL DESCRIPTION: Terrazzo
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Stairs & Stairway Landing
MATERIAL QUANTITY: 1670 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-28**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stairs & Stairway Landing**
MATERIAL QUANTITY: **1670** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary-29**
MATERIAL DESCRIPTION: **9x9 Cream w/Black Streaks Floor Tile NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 021, 013, 012 (Patches in each Room)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-29**

MATERIAL DESCRIPTION: **9x9 Cream w/Black Streaks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Rooms 021, 013, 012 (Patches in each Room)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-29A**
MATERIAL DESCRIPTION: **9x9 Cream w/Black Streaks Floor Tile Mastic NOT OBSERVED**
MATERIAL LOCATION: **Rooms 021, 013, 012 (Patches in Each Room)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUIDLING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-30
MATERIAL DESCRIPTION: 12x12 Green Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Hallway Borders
MATERIAL QUANTITY: 6500 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-30**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
MATERIAL LOCATION: **Hallway Borders**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary-30A**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallway Borders**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-30A**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**
MATERIAL LOCATION: **Hallway Borders**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22621 BUILDING ID: 2690
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Carver Primary School INSPECTION DATE: 1/12/2023
ADDRESS: 901 E. 133rd Place IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Primary-A
MATERIAL DESCRIPTION: Aircell Pipe Insulation
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Crawlspace, Pipechases, Basement, Storage A & B
MATERIAL QUANTITY: 610 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Crawlspace, Pipechases, Basement, Storage A & B**
MATERIAL QUANTITY: **610** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary-B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Crawlspace, Pipechase, Basement, Storage A & B**
MATERIAL QUANTITY: **54** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**
MATERIAL LOCATION: **Crawlspace, Pipechase, Basement, Storage A & B**
MATERIAL QUANTITY: **54** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary-C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pipechases, Crawlspace, Basement, Storage A & B**
MATERIAL QUANTITY: **2113** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Pipechases, Crawlspace, Basement, Storage A & B**
MATERIAL QUANTITY: **2113** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Primary-D**
MATERIAL DESCRIPTION: **Elbows on Cardboard Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Crawlspace, Pipechase, Basement, Storage A & B**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUIDLING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-D**
MATERIAL DESCRIPTION: **Elbows on Cardboard Insulation**
MATERIAL LOCATION: **Crawlspace, Pipechase, Basement, Storage A & B**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-32**
MATERIAL DESCRIPTION: **12x12 Beige w/White Streaks Floor Tile**
MATERIAL LOCATION: **Room 406**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Chalkboards**
MATERIAL LOCATION: **Primary, Annexes A & B- All Classrooms**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **EA**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature: *Christopher Antonopoulos* Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Chalkboards**
MATERIAL LOCATION: **Primary, Annexes A & B- All Classrooms**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 01/13/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS:
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **01/12/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **"Annex A"-32A**
MATERIAL DESCRIPTION: **12x12 Beige w/White Streaks Floor Tile**
MATERIAL LOCATION: **Room 406**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **01/13/2023**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Carver Primary School** INSPECTION DATE: **1/12/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **Primary-32**
MATERIAL DESCRIPTION: **Vault Liner**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 01/12/2023

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22621** BUILDING ID: **2690**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Carver Primary School** REVIEW DATE: **1/13/2023**
ADDRESS: **901 E. 133rd Place** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **Primary-32**
MATERIAL DESCRIPTION: **Vault Liner**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 01/13/2023

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N. Penneff".

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:




37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Penef". The signature is written in a cursive style and is positioned above the printed name of the Director of Training.

Director of Training
Nicholas J. Penef
Doctor of Public Health

Phone: 312-491-0081


FORM # A-010B

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 18281	2/10/2022	05/15/2023

CHRISTOPHER J ANTONOPO
1736 W 102nd ST
CHICAGO, IL 60643

Environmental Health



ENDORSEMENT	TC EXPIRES
INSPECTOR	6/1/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

TODD T HUFFER
315 HATLEN COURT
MT. PROSPECT, IL 60056

2/18/2022


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

			ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS		TC EXPIRES
ID NUMBER 100 - 09870	ISSUED 2/18/2022	EXPIRES 05/15/2023	INSPECTOR				11/1/2022
TODD T HUFFER 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health					MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL		11/19/2022 10/20/2022
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.							

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265


Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed