

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2133  
SCHOOL NAME: Cleveland School  
ADDRESS OF SCHOOL: 3121 W Byron Avenue  
CITY: Chicago, IL, 60618

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **6/7/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 5/10/2022 ENROLLMENT 484  
IDPH INSPECTOR LICENSE NUMBER: 100-20485  
IDPH LICENSED INSPECTOR NAME (Please Print): Jeffin Chakkalake  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



5/31/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Cleveland School**

3121 W Byron Avenue  
Chicago, IL, 60618

Unit: 22741  
Building ID: 2800

IDPH ID Number: 14-016-2990-2133

**REPORT DATE:**

Tuesday, May 31, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Specialty Consulting, Inc.**

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

05/31/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 22741            Region: 01            IDPH ID: 14-016-2990-2133

School: Cleveland School            Building ID: 2800

Address: 3121 W Byron Avenue

Chicago, IL, 60618

Building Contact: Michael, Pakan

Contact Phone: 7737106507

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/10/2022

Review Date: 05/31/2022

Inspector: Jeffin Chakkalake

Inspector IDPH License: 100-20485

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,  
Specialty Consulting, Inc.



Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 31, 2022

RE: Cleveland School, Unit 22741  
3121 W Byron Avenue  
Chicago, IL, 60618

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Cleveland School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Cleveland School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Cleveland School Unit: 22741 Region: 01  
Address: 3121 W Byron Avenue Chicago, IL, 60618  
IDPH ID: 14-016-2990-2133 Building ID: 2800  
Contact: Michael, Pakan Phone: 7737106507

### 2. Description of Facility

Original Construction: 1910 Additional Construction:  
Total Square Footage: 93450 No of Floors: 4  
Current Occupancy: 484

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren Street  
Phone: (312) 319-7575 Fax: (312) 319-7580

### 5. Inspector

Inspector Name: Jeffin Chakkalake

Inspector IDPH license # 100-20485  
Reinspection Date: 5/10/2022

  
Signature:  
Date: 5/10/2022

### 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

  
Signature:  
Date: 05/31/2022

### 7. Review Date: 05/31/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

  
Signature:

Date: 5/31/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Cleveland School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2800:

04

12"x12" Tan Spotted VFT

B. The following new homogenous areas have been identified for Building 2800:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05	Green Linoleum
08	Green Linoleum Mastic
09	Drywall Joint Compound
17	12"x12" Rust VFT Mastic
18	12"x12" White Streaked VFT
19	12"x12" White Streaked VFT Mastic
20	Exterior Window Caulk
21	12" x 12" White VFT
22	12" x 12" White VFT Mastic
23	12" x 12" Grey VFT
24	12" x 12" Grey VFT Mastic
25	Drywall
26	12 x 12 inch Brwn w/Wht Specks VFT
26 A	12 x 12 inch Brwn w/Wht Specks VFT Mastic
27	Fire Doors
28	12"x12" white & beige floor tile
28A	12"x12" white and beige floor tile (MASTIC)
29	2'x2' ceiling tile
30	vinyl baseboard mastic
31	dry wall, tape & compound
32	Textured ceiling plaster
33	Fire Door
34	decorative plaster
35	2'x4' ceiling tile
36	12"x12" Pink floor tile
36A	12"x12" pink floor tile & MASTIC
37	12"x12" sand VFT
37A	12"x12" sand VFT mastic
38	Vinyl Baseboard mastic
39	Skim Coat and Hard Plaster
40	Glazed Brick Mortar
41	Ceramic Floor Tile Mortar
L	Carpet Mastic
M	Fiber Glass pipes
N	MJP on E/F/V

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jeffin Chakkalake, IDPH License # 100-20485. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:       7/15/2021  
                                  7/28/2021  
                                  8/13/2021

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Cleveland School Building 2800 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Cleveland School Unit 22741 Building ID 2800

Address 3121 W Byron Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	9"x9" Brown VFT	4,300	SF	Rooms 101 and 210; 203A & 203B (under existing flooring).	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04	12"x12" Tan Spotted VFT	1,070	SF	Auditorium Balcony , 203A , 203B , 103, Engineers Office, Main Office, Associated Staff Offices.	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
05	Green Linoleum	5,000	SF	Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	9"x9" Brown VFT Mastic	4,300	SF	NOT OBSERVED in Rooms 101, 210 & Main Office; 203A & 203B (under existintg flooring).	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
07	12"x12" Tan Spotted VFT Mastic	1,070	SF	Auditorium Balcony, 203A, 203B, 103 & Engineers office, Main Office, Associated Staff Offices.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Green Linoleum Mastic	5,000	SF	Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Drywall Joint Compound	200	LF	Room's 100, 203B, 203 A, 301	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
12	9"x9" Gray VFT	875	SF	Room 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
13	9"x9" Gray VFT Mastic	875	SF	Room 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12"x12" Rust VFT	400	SF	Kitchen, Engineers Storage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
17	12"x12" Rust VFT Mastic	400	SF	Kitchen, Engineers Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"x12" White Streaked VFT	300	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

School Cleveland School Unit 22741 Building ID 2800

Address 3121 W Byron Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
19	12"x12" White Streaked VFT Mastic	300	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Exterior Window Caulk	9,000	LF	Exterior Windows	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12" x 12" White VFT	8,000	SF	1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitors closets (under ceramic floor).	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
22	12" x 12" White VFT Mastic	8,000	SF	1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitor's closets (under ceramic floor).	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12" x 12" Grey VFT	2,000	SF	1st thru 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
24	12" x 12" Grey VFT Mastic	2,000	SF	1st thru 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Drywall	1,500	SF	Room's 100, 203B, 203 A, 301	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
26	12 x 12 inch Brwn w/Wht Specks VFT	250	SF	Gym Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26 A	12 x 12 inch Brwn w/Wht Specks VFT Mastic	250	SF	Gym Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Fire Doors	3	EA	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12"x12" white & beige floor tile	2,000	SF	throughout mobile unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
28A	12"x12" white and beige floor tile (MASTIC)	2,000	SF	throughout mobile unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	2'x2' ceiling tile	1,800	SF	corridor and classrooms in mobile unit	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

School Cleveland School Unit 22741 Building ID 2800

Address 3121 W Byron Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
30	vinyl baseboard mastic	200	LF	throughout mobile unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	dry wall, tape & compound	3,000	SF	throughout mobile unit	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
32	Textured ceiling plaster	300	SF	men's/women's toilet & mechanical room in mobile unit	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
33	Fire Door	1	EA		ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	decorative plaster	2,000	SF	auditorium main bldg.	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
35	2'x4' ceiling tile	1,600	SF	Basement Room 500, 700, engineers office main bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
36	12"x12" Pink floor tile	200	SF	teachers toilets, slop sinks rooms, stair landing & room 700 closet in main bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
36A	12"x12" pink floor tile & MASTIC	200	SF	teachers toilets, slop sinks rooms, stair landings & room 700 closet in main bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12"x12" sand VFT	400	SF	Basement Room 350 main bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37A	12"x12" sand VFT mastic	400	SF	Basement Room 350 main bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Vinyl Baseboard mastic	800	LF	1st & 2nd floor corridors main bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Skim Coat and Hard Plaster	75,000	SF	Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Glazed Brick Mortar	5,000	SF	Toilet Rooms	ASSUMED	MISC	N	UNKNO WN	0		No	ACBM with the potential for damage		MODERATE
41	Ceramic Floor Tile Mortar	5,000	SF	Toilet Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
C	Cardboard Pipe Insulation	350	LF	Boiler, Pump, Engine, & Airhandling Rooms, Rm 100, Cold Deck, Rm 100, 005, 118, 120, 015	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	MJP E/F/V on Cardboard Pipe Insulation	15	LF	Kitchen, Boiler, Pump, Engine & room 100	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Cleveland School Unit 22741 Building ID 2800

Address 3121 W Byron Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
G	Aircell Duct Insulation	1,940	SF	Boy's Playroom, Main Electrical room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	Mag Block Insulation	80	SF	Feed Water Tank Pump Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Aircell Pipe Insulation	100	LF	Rooms 100, 200, 300, 350 & 500	CHR	TSI	Y	NONE	0		No	ACBM with potential for significant damage		MODERATE
K	MJP E/F/V on Aircell Pipe Insulation	4	LF	Rooms 100, 200, 300 & 500	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	Carpet Mastic	2,380	SF	MDF, Assembly Hall, Balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M	Fiber Glass pipes	150	EA	Boiler room, Janitor's closets, kitchen, water main room, room 500 toilet main bldg, 2nd fl girls & boys bathrooms	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
N	MJP on E/F/V	150	EA	Boiler Room, Janitors Closets, Kitchen, Water Main Room, Room #500 Toilet, 2nd FL Boys + Girls Bathrooms.	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Cleveland School Unit 22741 Building ID 2800

Address 3121 W Byron Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>5/10/2022</b>
Inspector Name <b><u>Jeffin Chakkalake</u></b>
<b>100-20485</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
03	
04	
05	
06	
07	
08	
09	
12	
13	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
26 A	
27	
28	
28A	

# Chicago Public Schools

School Cleveland School Unit 22741 Building ID 2800

Address 3121 W Byron Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
29	
30	
31	
32	
33	
34	
35	
36	
36A	
37	
37A	
38	
39	
40	
41	
C	
D	
G	
I	
J	
K	
L	
M	
N	

# Chicago Public Schools

**School** Cleveland School **Unit** 22741 **Building ID** 2800

**Address** 3121 W Byron Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Cleveland School  
Address 3121 W Byron Avenue

Unit 22741  
Chicago, IL, 60618

Building ID 2800  
Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	9"x9" Brown VFT	4,300	SF	Rooms 101 and 210; 203A & 203B (under existing flooring).	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" Tan Spotted VFT	1,070	SF	Auditorium Balcony, 203A, 203B, 103, Engineers Office, Main Office, Associated Staff Offices.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	Green Linoleum	5,000	SF	Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x9" Brown VFT Mastic	4,300	SF	NOT OBSERVED in Rooms 101, 210 & Main Office; 203A & 203B (under existing flooring).	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Tan Spotted VFT Mastic	1,070	SF	Auditorium Balcony, 203A, 203B, 103 & Engineers office, Main Office, Associated Staff Offices.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Green Linoleum Mastic	5,000	SF	Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Drywall Joint Compound	200	LF	Room's 100, 203B, 203 A, 301	Assumed	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	9"x9" Gray VFT	875	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	9"x9" Gray VFT Mastic	875	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" Rust VFT	400	SF	Kitchen, Engineers Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" Rust VFT Mastic	400	SF	Kitchen, Engineers Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" White Streaked VFT	300	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" White Streaked VFT Mastic	300	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Exterior Window Caulk	9,000	LF	Exterior Windows	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
21	12" x 12" White VFT	8,000	SF	1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitors closets (under ceramic floor).	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" White VFT Mastic	8,000	SF	1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitor's closets (under ceramic floor).	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Grey VFT	2,000	SF	1st thru 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Cleveland School  
Address 3121 W Byron Avenue

Unit 22741  
Chicago, IL, 60618

Building ID 2800  
Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
24	12" x 12" Grey VFT Mastic	2,000	SF	1st thru 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Drywall	1,500	SF	Room's 100, 203B, 203 A, 301	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12 x 12 inch Brwn w/Wht Specks VFT	250	SF	Gym Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26 A	12 x 12 inch Brwn w/Wht Specks VFT Mastic	250	SF	Gym Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Fire Doors	3	EA	Boiler Room	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
28	12"x12" white & beige floor tile	2,000	SF	throughout mobile unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28A	12"x12" white and beige floor tile (MASTIC)	2,000	SF	throughout mobile unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	2'x2' ceiling tile	1,800	SF	corridor and classrooms in mobile unit	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	vinyl baseboard mastic	200	LF	throughout mobile unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
31	dry wall, tape & compound	3,000	SF	throughout mobile unit	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Textured ceiling plaster	300	SF	men's/women's toilet & mechanical room in mobile unit	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Fire Door	1	EA		Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
34	decorative plaster	2,000	SF	auditorium main bldg.	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	2'x4' ceiling tile	1,600	SF	Basement Room 500, 700, engineers office main bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" Pink floor tile	200	SF	teachers toilets, slop sinks rooms, stair landing & room 700 closet in main bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36A	12"x12" pink floor tile & MASTIC	200	SF	teachers toilets, slop sinks rooms, stair landings & room 700 closet in main bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"x12" sand VFT	400	SF	Basement Room 350 main bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37A	12"x12" sand VFT mastic	400	SF	Basement Room 350 main bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Vinyl Baseboard mastic	800	LF	1st & 2nd floor corridors main bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
39	Skim Coat and Hard Plaster	75,000	SF	Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Glazed Brick Mortar	5,000	SF	Toilet Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Ceramic Floor Tile Mortar	5,000	SF	Toilet Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Cardboard Pipe Insulation	350	LF	Boiler, Pump, Engine, & Airhandling Rooms, Rm 100, Cold Deck, Rm 100, 005, 118, 120, 015	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Cardboard Pipe Insulation	15	LF	Kitchen, Boiler, Pump, Engine & room 100	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	Aircell Duct Insulation	1,940	SF	Boy's Playroom, Main Electrical room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	Mag Block Insulation	80	SF	Feed Water Tank Pump Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	Aircell Pipe Insulation	100	LF	Rooms 100, 200, 300, 350 & 500	Chrysotile	TSI	Yes	0	LF	5 ACBM with potential for significant	Follow O&M Plan

# Chicago Public Schools

**School** Cleveland School  
**Address** 3121 W Byron Avenue

**Unit** 22741  
 Chicago, IL, 60618

**Building ID** 2800  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										damage	
K	MJP E/F/V on Aircell Pipe Insulation	4	LF	Rooms 100, 200, 300 & 500	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	Carpet Mastic	2,380	SF	MDF, Assembly Hall, Balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	Fiber Glass pipes	150	EA	Boiler room, Janitor's closets, kitchen, water main room, room 500 toilet main bldg, 2nd fl girls & boys bathrooms	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
N	MJP on E/F/V	150	EA	Boiler Room, Janitors Closets, Kitchen, Water Main Room, Room #500 Toilet, 2nd FL Boys + Girls Bathrooms.	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Cleveland School  
**Address** 3121 W Byron Avenue

**Unit** 22741  
 Chicago, IL, 60618

**Building ID** 2800  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	5/31/2022
Manager Planner Name	Arturo Saenz
100-04019	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
04	
05	
06	
07	
08	
09	
12	
13	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
26 A	
27	
28	
28A	
29	
30	



# Chicago Public Schools

**School** Cleveland School  
**Address** 3121 W Byron Avenue

**Unit** 22741  
Chicago, IL, 60618

**Building ID** 2800  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
31	
32	
33	
34	
35	
36	
36A	
37	
37A	
38	
39	
40	
41	
C	
D	
G	
I	
J	
K	
L	
M	
N	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

Specialty Consulting, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9"x9" Brown VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 101 and 210; 203A & 203B (under existing flooring).**

MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9"x9" Brown VFT**  
MATERIAL LOCATION: **Rooms 101 and 210; 203A & 203B (under existing flooring).**  
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Tan Spotted VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Auditorium Balcony , 203A , 203B , 103, Engineers Office, Main Office, Associated Staff Offices.**

MATERIAL QUANTITY: **1070** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Tan Spotted VFT**  
MATERIAL LOCATION: **Auditorium Balcony , 203A , 203B , 103, Engineers Office, Main Office, Associated Staff Offices.**  
MATERIAL QUANTITY: **1070** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Green Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **05/10/2022**



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Green Linoleum**  
MATERIAL LOCATION: **Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **9"x9" Brown VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **NOT OBSERVED in Rooms 101, 210 & Main Office; 203A & 203B (under existng flooring).**

MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **9"x9" Brown VFT Mastic**

MATERIAL LOCATION: **NOT OBSERVED in Rooms 101, 210 & Main Office; 203A & 203B (under existing flooring).**

MATERIAL QUANTITY: **4300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12"x12" Tan Spotted VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium Balcony, 203A, 203B, 103 & Engineers office, Main Office, Associated Staff Offices.**

MATERIAL QUANTITY: **1070**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12"x12" Tan Spotted VFT Mastic**  
MATERIAL LOCATION: **Auditorium Balcony, 203A, 203B, 103 & Engineers office, Main Office, Associated Staff Offices.**  
MATERIAL QUANTITY: **1070** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
MATERIAL LOCATION: **Engineers Office; Room 311; NOT OBSERVED in Gymnasium (under wood floor).**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room's 100, 203B, 203 A, 301**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **Room's 100, 203B, 203 A, 301**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" Rust VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Kitchen, Engineers Storage**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" Rust VFT**  
MATERIAL LOCATION: **Kitchen, Engineers Storage**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12"x12" Rust VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen, Engineers Storage**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12"x12" Rust VFT Mastic**  
MATERIAL LOCATION: **Kitchen, Engineers Storage**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" White Streaked VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" White Streaked VFT**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12"x12" White Streaked VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12"x12" White Streaked VFT Mastic**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Exterior Windows**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
MATERIAL LOCATION: **Exterior Windows**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12" x 12" White VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitors closets (under ceramic floor).**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12" x 12" White VFT**  
MATERIAL LOCATION: **1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitors closets (under ceramic floor).**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12" x 12" White VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitor's closets (under ceramic floor).**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12" x 12" White VFT Mastic**  
MATERIAL LOCATION: **1st thru 3rd Floor & Basement Corridors, Room 600, 1st thru 3rd floor, Lunchroom Vestibule, South vestibule; NOT OBSERVED in Janitor's closets (under ceramic floor).**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12" x 12" Grey VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st thru 3rd Floor Corridors**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12" x 12" Grey VFT**  
MATERIAL LOCATION: **1st thru 3rd Floor Corridors**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12" x 12" Grey VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st thru 3rd Floor Corridors**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12" x 12" Grey VFT Mastic**  
MATERIAL LOCATION: **1st thru 3rd Floor Corridors**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room's 100, 203B, 203 A, 301**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Room's 100, 203B, 203 A, 301**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12 x 12 inch Brwn w/Wht Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12 x 12 inch Brwn w/Wht Specks VFT**  
MATERIAL LOCATION: **Gym Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26 A**  
MATERIAL DESCRIPTION: **12 x 12 inch Brwn w/Wht Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **26 A**  
MATERIAL DESCRIPTION: **12 x 12 inch Brwn w/Wht Specks VFT Mastic**  
MATERIAL LOCATION: **Gym Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12"x12" white & beige floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **throughout mobile unit**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12"x12" white & beige floor tile**  
MATERIAL LOCATION: **throughout mobile unit**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28A**  
MATERIAL DESCRIPTION: **12"x12" white and beige floor tile (MASTIC)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **throughout mobile unit**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **28A**  
MATERIAL DESCRIPTION: **12"x12" white and beige floor tile (MASTIC)**  
MATERIAL LOCATION: **throughout mobile unit**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **2'x2' ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **corridor and classrooms in mobile unit**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **2'x2' ceiling tile**  
MATERIAL LOCATION: **corridor and classrooms in mobile unit**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **vinyl baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **throughout mobile unit**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **vinyl baseboard mastic**  
MATERIAL LOCATION: **throughout mobile unit**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **dry wall, tape & compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **throughout mobile unit**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **dry wall, tape & compound**  
MATERIAL LOCATION: **throughout mobile unit**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Textured ceiling plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **men's/women's toilet & mechanical room in mobile unit**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Textured ceiling plaster**  
MATERIAL LOCATION: **men's/women's toilet & mechanical room in mobile unit**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Fire Door**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION:

MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Fire Door**

MATERIAL LOCATION:

MATERIAL QUANTITY: **1**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **decorative plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **auditorium main bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **decorative plaster**  
MATERIAL LOCATION: **auditorium main bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **2'x4' ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Room 500, 700, engineers office main bldg.**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **2'x4' ceiling tile**  
MATERIAL LOCATION: **Basement Room 500, 700, engineers office main bldg.**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"x12" Pink floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **teachers toilets, slop sinks rooms, stair landing & room 700 closet in main bldg.**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"x12" Pink floor tile**  
MATERIAL LOCATION: **teachers toilets, slop sinks rooms, stair landing & room 700 closet in main bldg.**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36A**  
MATERIAL DESCRIPTION: **12"x12" pink floor tile & MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **teachers toilets, slop sinks rooms, stair landings & room 700 closet in main bldg.**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **36A**  
MATERIAL DESCRIPTION: **12"x12" pink floor tile & MASTIC**  
MATERIAL LOCATION: **teachers toilets, slop sinks rooms, stair landings & room 700 closet in main bldg.**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12"x12" sand VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Room 350 main bldg.**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12"x12" sand VFT**  
MATERIAL LOCATION: **Basement Room 350 main bldg.**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37A**  
MATERIAL DESCRIPTION: **12"x12" sand VFT mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Room 350 main bldg.**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **37A**  
MATERIAL DESCRIPTION: **12"x12" sand VFT mastic**  
MATERIAL LOCATION: **Basement Room 350 main bldg.**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Vinyl Baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd floor corridors main bldg.**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Vinyl Baseboard mastic**  
MATERIAL LOCATION: **1st & 2nd floor corridors main bldg.**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Skim Coat and Hard Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **75000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Skim Coat and Hard Plaster**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **75000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Glazed Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Toilet Rooms**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Glazed Brick Mortar**  
MATERIAL LOCATION: **Toilet Rooms**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Ceramic Floor Tile Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Toilet Rooms**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Ceramic Floor Tile Mortar**  
MATERIAL LOCATION: **Toilet Rooms**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler, Pump, Engine, & Airhandling Rooms, Rm 100, Cold Deck, Rm 100, 005, 118, 120, 015**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Boiler, Pump, Engine, & Airhandling Rooms, Rm 100, Cold Deck, Rm 100, 005, 118, 120, 015**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen, Boiler, Pump, Engine & room 100**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Kitchen, Boiler, Pump, Engine & room 100**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boy's Playroom, Main Electrical room**  
MATERIAL QUANTITY: **1940** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
MATERIAL LOCATION: **Boy's Playroom, Main Electrical room**  
MATERIAL QUANTITY: **1940** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Mag Block Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Feed Water Tank Pump Room**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Mag Block Insulation**  
MATERIAL LOCATION: **Feed Water Tank Pump Room**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **5 Damaged or significantly damaged friable thermal system insulating ACM**  
HISTORICAL DAMAGE REASON: **Physical Damage  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 100, 200, 300. 350 & 500**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Rooms 100, 200, 300. 350 & 500**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 100, 200, 300 & 500**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Rooms 100, 200, 300 & 500**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **MDF, Assembly Hall, Balcony**  
MATERIAL QUANTITY: **2380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/10/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUILDING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **MDF, Assembly Hall, Balcony**  
MATERIAL QUANTITY: **2380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Fiber Glass pipes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler room, Janitor's closets, kitchen, water main room, room 500 toilet main bldg, 2nd fl girls & boys bathrooms**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**



# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Fiber Glass pipes**  
MATERIAL LOCATION: **Boiler room, Janitor's closets, kitchen, water main room, room 500 toilet main bldg, 2nd fl girls & boys bathrooms**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jeffin Chakkalake**  
SCHOOL NAME: **Cleveland School** INSPECTION DATE: **5/10/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **MJP on E/F/V**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room, Janitors Closets, Kitchen, Water Main Room, Room #500 Toilet, 2nd FL Boys + Girls Bathrooms.**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **05/10/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22741** BUIDLING ID: **2800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Cleveland School** REVIEW DATE: **5/31/2022**  
ADDRESS: **3121 W Byron Avenue** IDPH LICENSE NO: **100-20485**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **MJP on E/F/V**  
MATERIAL LOCATION: **Boiler Room, Janitors Closets, Kitchen, Water Main Room, Room #500 Toilet, 2nd FL Boys + Girls Bathrooms.**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/31/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
*2022 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER

100 - 20485

ISSUED

5/5/2021

EXPIRES

05/15/2022

JEFFIN J CHAKKALAKEL

1319 TOWER HILL DR

WOODRIDGE, IL 60517

Environmental Health



# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JEFFIN J. CHAKKALAKEL  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

01/15/2022

Course Dates:

01/15/2023

Expires:

2201BIR04

Certificate Number:

A handwritten signature in blue ink, appearing to read "N Peneff DPH". The signature is written over a light-colored rectangular background.

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JEFFIN J CHAKKALAKEL**  
1319 TOWER HILL DR  
WOODRIDGE, IL 60517

5/20/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 20485

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
			INSPECTOR	1/15/2023
ID NUMBER 100 - 20485	ISSUED 5/20/2022	EXPIRES 05/15/2023	PROJECT MANAGER	4/29/2023
JEFFIN J CHAKKALAKEL 1319 TOWER HILL DR WOODRIDGE, IL 60517 Environmental Health			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
Nationally Accredited by PHAB





# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

  
Kathy DeSalvo, Director



# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois

**ARTURO SAENZ**  
 2942 W VAN BUREN ST  
 CHICAGO, IL 60612

2/28/2022



**ASBESTOS  
 PROFESSIONAL  
 LICENSE**

ID NUMBER  
 100 - 04019

ISSUED  
 2/28/2022

EXPIRES  
 05/15/2023

**ARTURO SAENZ**  
 2942 W VAN BUREN ST  
 CHICAGO, IL 60612



Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <p><b>ASBESTOS          PROFESSIONAL          LICENSE</b></p>			<p><b>ENDORSEMENTS</b></p> <p>INSPECTOR</p> <p>MANAGEMENT PLANNER</p> <p>AIR SAMPLING PROFESSIONAL</p> <p><b>Alteration of this license shall result in legal action</b>          This license issued under authority of the State of Illinois          Department of Public Health          This license is valid only when accompanied by a valid          training course certificate.</p>	<p><b>TC EXPIRES</b></p> <p>11/1/2022</p> <p>11/1/2022</p>
<p>ID NUMBER          100 - 04019</p> <p><b>ARTURO SAENZ</b>          2942 W VAN BUREN ST          CHICAGO, IL 60612</p> <p>Environmental Health</p>	<p>ISSUED          2/28/2022</p>	<p>EXPIRES          05/15/2023</p> 		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH. IMPROVING LIVES**

Nationally Accredited by PHAB

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed