

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2704  
SCHOOL NAME: Copernicus School  
ADDRESS OF SCHOOL: 6010 S. Throop  
CITY: Chicago, IL, 60636

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/21/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** (Please type or print)

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 8/31/2022 ENROLLMENT 179  
IDPH INSPECTOR LICENSE NUMBER: 100-20640  
IDPH LICENSED INSPECTOR NAME (Please Print): Mike Di Canio  
IDPH MP LICENSE NUMBER: 100-03613  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



9/22/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Copernicus School**

6010 S. Throop  
Chicago, IL, 60636

Unit: 22841  
Building ID: 2900

IDPH ID Number: 14-016-2990-2704

**REPORT DATE:**

Thursday, September 22, 2022

**Prepared for:**

**Chicago Public Schools  
42 W. Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

09/22/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 22841            Region: 05            IDPH ID: 14-016-2990-2704

School: Copernicus School            Building ID: 2900

Address: 6010 S. Throop  
Chicago, IL, 60636

Building Contact: Johnson, Andre            Contact Phone: 7737096868

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/31/2022

Review Date: 09/22/2022

Inspector: Mike Di Canio            Inspector IDPH License: 100-20640  
Management Planner: Daniel Juneau            Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Daniel Juneau  
100-03613

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 22, 2022

RE: Copernicus School, Unit 22841  
6010 S. Throop  
Chicago, IL, 60636

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Copernicus School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Copernicus School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Copernicus School  
Address: 6010 S. Throop  
IDPH ID: 14-016-2990-2704  
Contact: Johnson, Andre

Unit: 22841  
Chicago, IL, 60636  
Building ID: 2900  
Phone: 7737096868

Region: 05

### 2. Description of Facility

Original Construction: 1905  
Total Square Footage: 78575  
Current Occupancy: 179

Additional Construction:  
No of Floors: 3

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant


MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Mike Di Canio

Inspector IDPH license # 100-20640  
Reinspection Date: 8/31/2022




Signature:  
Date: 8/31/2022

### 6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613




Signature:  
Date: 09/22/2022

### 7. Review Date: 09/22/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 9/22/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Copernicus School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2900:

02A	12x12 Cream Floor Tile ABATED
28	Plaster
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 2900:

NEW

Newly Installed Suspect ACM



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	12x12 Brown Specked Floor Tile
04A	Green Linoleum
05	12x12 Brown Specked Floor Tile Mastic
05C	12x12 Light Brown Floor Tile Mastic
08	Brown Vinyl Baseboard Mastic
08A	Black Vinyl Baseboard Mastic
09	Brown Vinyl Baseboard
09A	Black Vinyl Baseboard
10	Grey Carpet Mastic
14B	Black Linoleum NOT OBSERVED
15	9x9 White/Red-Brown Floor Tile
16	12x12 Brown Floor Tile
17	12x12 Brown Floor Tile Mastic
18	12x12 Blue Floor Tile
19	12x12 Blue Floor Tile Mastic
20	12x12 Brown Floor Tile Mastic
21	12x12 Aqua Floor Tile
22	12x12 Brown Mastic
23	12x12 Aqua Floor Tile Mastic
26	12x12 Dark Blue Floor Tile
27	12x12 Dark Blue Floor Tile Mastic
29	Gypsum Board
30	Joint Compound
E	Cardboard Pipe Insulation
F	Cardboard Pipe Joints
H	12x12 Floor Tile
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

05	12x12 Brown Specked Floor Tile Mastic
05A	12x12 Cream Floor Tile Mastic
05B	12x12 Green Floor Tile Mastic
05C	12x12 Light Brown Floor Tile Mastic
06	9x9 Brown w/Red Floor Tile Mastic
06A	9x9 Light Brown Floor Tile Mastic
06D	9x9 Dark Brown & Tan Floor Tile Mastic
07	Dark Brown w/Black Spots Linoleum Mastic
07A	Green Linoleum Mastic
08	Brown Vinyl Baseboard Mastic

08A	Black Vinyl Baseboard Mastic
10	Grey Carpet Mastic
17	12x12 Brown Floor Tile Mastic
19	12x12 Blue Floor Tile Mastic
22	12x12 Brown Mastic
23	12x12 Aqua Floor Tile Mastic
27	12x12 Dark Blue Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mike Di Canio, IDPH License # 100-20640. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	1/7/2021
	7/14/2021
	7/18/2022

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Copernicus School Building 2900 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Copernicus School Unit 22841 Building ID 2900

Address 6010 S. Throop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	12x12 Brown Specked Floor Tile	13,415	SF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02A	12x12 Cream Floor Tile ABATED			2nd Floor Women's Toilet, Lunchroom, Kitchen, Lunchroom Manager's Office, Room 205 1/2	ABATED	MISC					Yes			
02B	12x12 Green Floor Tile	1,316	SF	Main Office, Store Room, Principal's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02C	12x12 Light Brown Floor Tile	852	SF	Room 205 1/2, Lunchroom, Kitchen, Lunchroom Managers Office, 2nd Floor Teachers' Lounge, South Vestibule #2	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	9x9 Brown w/Red Floor Tile	1,361	SF	Ladies' Washroom, Basement Library Entrance, Room 009, EC Office Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03A	9x9 Light Brown Floor Tile	432	SF	Office Vault	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03B	9x9 Red Floor Tile NOT OBSERVED			South Vestibule #2	CHR	MISC								
03C	9x9 Green Floor Tile NOT OBSERVED			E. C. Office	CHR	MISC								
03D	9x9 Dark Brown & Tan Floor Tile	1,084	SF	Library Room 200	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	Dark Brown w/Black Spots Linoleum	1,098	SF	Stage Auditorium	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04A	Green Linoleum	1,168	SF	Room 307 and Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	12x12 Brown Specked Floor Tile Mastic	13,415	SF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	12x12 Cream Floor Tile Mastic	852	SF	2nd Floor Women's Toilet, Lunchroom, Kitchen, Lunchroom Manager's Office, Room 205 1/2	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	12x12 Green Floor Tile Mastic	1,316	SF	Main Office, Store Room, Principal's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05C	12x12 Light Brown Floor Tile Mastic	1,232	SF	Room 205 1/2, Lunchroom,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Copernicus School Unit 22841 Building ID 2900

Address 6010 S. Throop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Kitchen, Lunchroom Manager's Office, 2nd Floor Teachers' Lounge, South Vestibule #2										
06	9x9 Brown w/Red Floor Tile Mastic	1,361	SF	Ladies' Washroom, Basement Library Entrance, Room 009, EC Office Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	9x9 Light Brown Floor Tile Mastic	432	SF	Main Office, Main Office Vault & Washroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06B	9x9 Red Floor Tile Mastic NOT OBSERVED			South Vestibule #2	CHR	MISC								
06C	9x9 Green Floor Tile Mastic NOT OBSERVED			E. C. Office	CHR	MISC		None						Low
06D	9x9 Dark Brown & Tan Floor Tile Mastic	200	SF	Library	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	Dark Brown w/Black Spots Linoleum Mastic	1,098	SF	Stage Auditorium	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	Green Linoleum Mastic	1,168	SF	Room 307 and Closet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Brown Vinyl Baseboard Mastic	591	SF	Main Entrance, All Stair Landings, Stage, Gym, Room 108, Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	Black Vinyl Baseboard Mastic	500	LF	E. C. Washroom, Kitchen, Ladies Toilet (East Basement), 3rd Floor T. L., (Men's & Women's Washrooms)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Brown Vinyl Baseboard	591	LF	Main Entrance, All Stair Landings, Stage, Gym, Room 108, Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09A	Black Vinyl Baseboard	500	LF	E. C. Washroom, Kitchen, Ladies' Toilet (East Basement), 3rd Floor T. L., (Men's &	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Copernicus School Unit 22841 Building ID 2900

Address 6010 S. Throop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Women's Washrooms)										
10	Grey Carpet Mastic	1,074	SF	Auditorium, Computer Lab, 2nd Floor Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14B	Black Linoleum NOT OBSERVED			Room 130	ASSUMED	MISC								
15	9x9 White/Red-Brown Floor Tile	1,800	SF	2nd Floor Office (No Classrooms)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12x12 Brown Floor Tile	1,188	SF	Main Office, Clerk Space, Principal's Office & Library Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12x12 Brown Floor Tile Mastic	2,576	SF	Main Office, Clerk Space, Principal's Office & Library Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12x12 Blue Floor Tile	600	SF	Room 009	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12x12 Blue Floor Tile Mastic	600	SF	Room 009	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12x12 Brown Floor Tile Mastic	1,185	SF	Main Office, Clerk Space, Principal's Office & Library Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12x12 Aqua Floor Tile	227	SF	E.C. Office, Counselor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12x12 Brown Mastic	1,168	SF	Room 307 & Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12x12 Aqua Floor Tile Mastic	227	SF	E.C. Counselor's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12x12 Dark Blue Floor Tile	1,088	SF	Stage Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x12 Dark Blue Floor Tile Mastic	1,088	SF	Stage Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Plaster	143,000	SF	Throughout	CHR	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
29	Gypsum Board	7,350	SF	3rd Floor, 1st & 2nd Floor Corridors & Stairs, Basement & 2nd Floor Boys' & Girls' Restrooms, Partial Basement, Auditorium/Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Copernicus School Unit 22841 Building ID 2900

Address 6010 S. Throop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
30	Joint Compound	7,350	SF	3rd Floor, 1st & 2nd Floor Corridors & Stairs, Basement & 2nd Floor Boys' & Girls' Restrooms, Partial Basement, Auditorium/Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	Aircell Insulation	200	LF	Boiler Room, Fan Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Aircell Joints	30	LF	Basement	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Cardboard Pipe Insulation	50	LF	Basement	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Cardboard Pipe Joints	10	LF	Basement	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Preformed Tank Insulation	375	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	12x12 Floor Tile	1,600	SF	Rooms 113 & 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		



# Chicago Public Schools

School Copernicus School Unit 22841 Building ID 2900

Address 6010 S. Throop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>8/31/2022</b>
Inspector Name <b>Mike Di Canio</b>
<b>100-20640</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
02	
02A	Abated
02B	Main Office Abated
02C	
03	
03A	
03B	Not Observed Multiple Years
03C	Not Observed Multiple Years
03D	
04	
04A	
05	
05A	
05B	Main Office Abated 2022
05C	
06	
06A	Main Office Abated
06B	Not Observed Multiple Years
06C	Not Observed Multiple Years
06D	
07	
07A	
08	
08A	

# Chicago Public Schools

School Copernicus School Unit 22841 Building ID 2900

Address 6010 S. Throop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
09	
09A	
10	
14B	Not Observed Multiple Years
15	
16	
17	
18	
19	
20	
21	
22	
23	
26	
27	
28	Auditorium/Gym fully abated 2018; Abatement & Repair entire 3rd Floor; 1st & 2nd Floor Halls; Basement; 2nd Floor Boys' & Girls' Restrooms Abated 2022; Stairwells & Vestibules
29	2nd Floor Boys' & Girls' Restrooms Abated 2022
30	2nd Floor Boys' & Girls' Restrooms Abated 2022
C	
D	
E	
F	
G	
H	
NEW	

# Chicago Public Schools

**School** Copernicus School **Unit** 22841 **Building ID** 2900

**Address** 6010 S. Throop **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Copernicus School

Unit 22841

Building ID 2900

Address 6010 S. Throop

Chicago, IL, 60636

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	12x12 Brown Specked Floor Tile	13,415	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02A	12x12 Cream Floor Tile ABATED			2nd Floor Women's Toilet, Lunchroom, Kitchen, Lunchroom Manager's Office, Room 205 1/2	Abated	MISC					
02B	12x12 Green Floor Tile	1,316	SF	Main Office, Store Room, Principal's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02C	12x12 Light Brown Floor Tile	852	SF	Room 205 1/2, Lunchroom, Kitchen, Lunchroom Managers Office, 2nd Floor Teachers' Lounge, South Vestibule #2	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	9x9 Brown w/Red Floor Tile	1,361	SF	Ladies' Washroom, Basement Library Entrance, Room 009, EC Office Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03A	9x9 Light Brown Floor Tile	432	SF	Office Vault	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03B	9x9 Red Floor Tile NOT OBSERVED			South Vestibule #2	Chrysotile	MISC					
03C	9x9 Green Floor Tile NOT OBSERVED			E. C. Office	Chrysotile	MISC					
03D	9x9 Dark Brown & Tan Floor Tile	1,084	SF	Library Room 200	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	Dark Brown w/Black Spots Linoleum	1,098	SF	Stage Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04A	Green Linoleum	1,168	SF	Room 307 and Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12x12 Brown Specked Floor Tile Mastic	13,415	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05A	12x12 Cream Floor Tile Mastic	852	SF	2nd Floor Women's Toilet, Lunchroom, Kitchen, Lunchroom Manager's Office, Room 205 1/2	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05B	12x12 Green Floor Tile Mastic	1,316	SF	Main Office, Store Room, Principal's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05C	12x12 Light Brown Floor Tile Mastic	1,232	SF	Room 205 1/2, Lunchroom, Kitchen, Lunchroom Manager's Office, 2nd Floor Teachers' Lounge, South Vestibule #2	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9x9 Brown w/Red Floor Tile Mastic	1,361	SF	Ladies' Washroom, Basement Library Entrance, Room 009, EC Office Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	9x9 Light Brown Floor Tile Mastic	432	SF	Main Office, Main Office Vault & Washroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06B	9x9 Red Floor Tile Mastic NOT OBSERVED			South Vestibule #2	Chrysotile	MISC					
06C	9x9 Green Floor Tile Mastic NOT OBSERVED			E. C. Office	Chrysotile	MISC					
06D	9x9 Dark Brown & Tan Floor Tile Mastic	200	SF	Library	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	Dark Brown w/Black Spots Linoleum Mastic	1,098	SF	Stage Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	Green Linoleum Mastic	1,168	SF	Room 307 and Closet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Brown Vinyl Baseboard Mastic	591	SF	Main Entrance, All Stair Landings,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Copernicus School

Unit 22841

Building ID 2900

Address 6010 S. Throop

Chicago, IL, 60636

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Stage, Gym, Room 108, Teachers' Lounge							
08A	Black Vinyl Baseboard Mastic	500	LF	E. C. Washroom, Kitchen, Ladies Toilet (East Basement), 3rd Floor T. L. (Men's & Women's Washrooms)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
09	Brown Vinyl Baseboard	591	LF	Main Entrance, All Stair Landings, Stage, Gym, Room 108, Teachers' Lounge	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
09A	Black Vinyl Baseboard	500	LF	E. C. Washroom, Kitchen, Ladies' Toilet (East Basement), 3rd Floor T. L. (Men's & Women's Washrooms)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
10	Grey Carpet Mastic	1,074	SF	Auditorium, Computer Lab, 2nd Floor Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14B	Black Linoleum NOT OBSERVED			Room 130	Assumed	MISC					
15	9x9 White/Red-Brown Floor Tile	1,800	SF	2nd Floor Office (No Classrooms)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12x12 Brown Floor Tile	1,188	SF	Main Office, Clerk Space, Principal's Office & Library Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 Brown Floor Tile Mastic	2,576	SF	Main Office, Clerk Space, Principal's Office & Library Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12x12 Blue Floor Tile	600	SF	Room 009	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12x12 Blue Floor Tile Mastic	600	SF	Room 009	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12x12 Brown Floor Tile Mastic	1,185	SF	Main Office, Clerk Space, Principal's Office & Library Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 Aqua Floor Tile	227	SF	E.C. Office, Counselor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12x12 Brown Mastic	1,168	SF	Room 307 & Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12x12 Aqua Floor Tile Mastic	227	SF	E.C. Counselor's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Dark Blue Floor Tile	1,088	SF	Stage Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Dark Blue Floor Tile Mastic	1,088	SF	Stage Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Plaster	143,000	SF	Throughout	Chrysotile	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Gypsum Board	7,350	SF	3rd Floor, 1st & 2nd Floor Corridors & Stairs, Basement & 2nd Floor Boys' & Girls' Restrooms, Partial Basement, Auditorium/Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Joint Compound	7,350	SF	3rd Floor, 1st & 2nd Floor Corridors & Stairs, Basement & 2nd Floor Boys' & Girls' Restrooms, Partial Basement,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Copernicus School

Unit 22841

Building ID 2900

Address 6010 S. Throop

Chicago, IL, 60636

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Auditorium/Gym							
C	Aircell Insulation	200	LF	Boiler Room, Fan Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Aircell Joints	30	LF	Basement	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Cardboard Pipe Insulation	50	LF	Basement	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Cardboard Pipe Joints	10	LF	Basement	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Preformed Tank Insulation	375	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	12x12 Floor Tile	1,600	SF	Rooms 113 & 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Copernicus School  
**Address** 6010 S. Throop

**Unit** 22841  
 Chicago, IL, 60636

**Building ID** 2900  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	9/22/2022
Manager Planner Name	Daniel Juneau
100-03613	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
02A	
02B	
02C	
03	
03A	
03B	
03C	
03D	
04	
04A	
05	
05A	
05B	
05C	
06	
06A	
06B	
06C	
06D	
07	
07A	



# Chicago Public Schools

**School** Copernicus School  
**Address** 6010 S. Throop

**Unit** 22841  
 Chicago, IL, 60636

**Building ID** 2900  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
08	
08A	
09	
09A	
10	
14B	
15	
16	
17	
18	
19	
20	
21	
22	
23	
26	
27	
28	
29	
30	
C	
D	
E	
F	
G	
H	
NEW	

# Chicago Public Schools

**School** Copernicus School

**Unit** 22841

**Building ID** 2900

**Address** 6010 S. Throop

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

***Management Planner's Comments Summarized at the End of the Report***

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

## 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Brown Specked Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **13415** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Brown Specked Floor Tile**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **13415** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **2nd Floor Women's Toilet, Lunchroom, Kitchen, Lunchroom Manager's Office, Room 205 1/2**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile ABATED**  
MATERIAL LOCATION: **2nd Floor Women's Toilet, Lunchroom, Kitchen, Lunchroom Manager's Office, Room 205 1/2**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02B**  
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Store Room, Principal's Office**  
MATERIAL QUANTITY: **1316** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Main Office Abated**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **02B**  
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**  
MATERIAL LOCATION: **Main Office, Store Room, Principal's Office**  
MATERIAL QUANTITY: **1316** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02C**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Room 205 1/2, Lunchroom, Kitchen, Lunchroom Managers Office, 2nd Floor Teachers' Lounge, South Vestibule #2**

MATERIAL QUANTITY: **852** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **02C**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile**  
MATERIAL LOCATION: **Room 205 1/2, Lunchroom, Kitchen, Lunchroom Managers Office, 2nd Floor Teachers' Lounge, South Vestibule #2**  
MATERIAL QUANTITY: **852** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Ladies' Washroom, Basement Library Entrance, Room 009, EC Office Toilet**  
MATERIAL QUANTITY: **1361** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Floor Tile**  
MATERIAL LOCATION: **Ladies' Washroom, Basement Library Entrance, Room 009, EC Office Toilet**  
MATERIAL QUANTITY: **1361** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**  
MATERIAL DESCRIPTION: **9x9 Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office Vault**  
MATERIAL QUANTITY: **432** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **03A**  
MATERIAL DESCRIPTION: **9x9 Light Brown Floor Tile**  
MATERIAL LOCATION: **Office Vault**  
MATERIAL QUANTITY: **432** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03B**  
MATERIAL DESCRIPTION: **9x9 Red Floor Tile NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Vestibule #2**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **03B**  
MATERIAL DESCRIPTION: **9x9 Red Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **South Vestibule #2**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03C**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **E. C. Office**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **03C**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **E. C. Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03D**  
MATERIAL DESCRIPTION: **9x9 Dark Brown & Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library Room 200**  
MATERIAL QUANTITY: **1084** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **03D**  
MATERIAL DESCRIPTION: **9x9 Dark Brown & Tan Floor Tile**  
MATERIAL LOCATION: **Library Room 200**  
MATERIAL QUANTITY: **1084** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Dark Brown w/Black Spots Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage Auditorium**  
MATERIAL QUANTITY: **1098** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Dark Brown w/Black Spots Linoleum**  
MATERIAL LOCATION: **Stage Auditorium**  
MATERIAL QUANTITY: **1098** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **Green Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 307 and Closet**  
MATERIAL QUANTITY: **1168** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **Green Linoleum**  
MATERIAL LOCATION: **Room 307 and Closet**  
MATERIAL QUANTITY: **1168** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12x12 Brown Specked Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **13415** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12x12 Brown Specked Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **13415** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **2nd Floor Women's Toilet, Lunchroom, Kitchen, Lunchroom Manager's Office, Room 205 1/2**

MATERIAL QUANTITY: **852** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
MATERIAL LOCATION: **2nd Floor Women's Toilet, Lunchroom, Kitchen, Lunchroom Manager's Office, Room 205 1/2**  
MATERIAL QUANTITY: **852** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Store Room, Principal's Office**  
MATERIAL QUANTITY: **1316** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Main Office Abated 2022**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**  
MATERIAL LOCATION: **Main Office, Store Room, Principal's Office**  
MATERIAL QUANTITY: **1316** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05C**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 205 1/2, Lunchroom, Kitchen, Lunchroom Manager's Office, 2nd Floor Teachers' Lounge, South Vestibule #2**

MATERIAL QUANTITY: **1232** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **05C**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Room 205 1/2, Lunchroom, Kitchen, Lunchroom Manager's Office, 2nd Floor Teachers' Lounge, South Vestibule #2**  
MATERIAL QUANTITY: **1232** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Ladies' Washroom, Basement Library Entrance, Room 009, EC Office Toilet**  
MATERIAL QUANTITY: **1361** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **9x9 Brown w/Red Floor Tile Mastic**  
MATERIAL LOCATION: **Ladies' Washroom, Basement Library Entrance, Room 009, EC Office Toilet**  
MATERIAL QUANTITY: **1361** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **9x9 Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Main Office Vault & Washroom**  
MATERIAL QUANTITY: **432** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Main Office Abated**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **9x9 Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Main Office, Main Office Vault & Washroom**  
MATERIAL QUANTITY: **432** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**  
MATERIAL DESCRIPTION: **9x9 Red Floor Tile Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Vestibule #2**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **06B**  
MATERIAL DESCRIPTION: **9x9 Red Floor Tile Mastic NOT OBSERVED**  
MATERIAL LOCATION: **South Vestibule #2**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **E. C. Office**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **06C**

MATERIAL DESCRIPTION: **9x9 Green Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **E. C. Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06D**  
MATERIAL DESCRIPTION: **9x9 Dark Brown & Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **06D**  
MATERIAL DESCRIPTION: **9x9 Dark Brown & Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Dark Brown w/Black Spots Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage Auditorium**  
MATERIAL QUANTITY: **1098** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Dark Brown w/Black Spots Linoleum Mastic**  
MATERIAL LOCATION: **Stage Auditorium**  
MATERIAL QUANTITY: **1098** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 307 and Closet**  
MATERIAL QUANTITY: **1168** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
MATERIAL LOCATION: **Room 307 and Closet**  
MATERIAL QUANTITY: **1168** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Entrance, All Stair Landings, Stage, Gym, Room 108, Teachers' Lounge**  
MATERIAL QUANTITY: **591** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Main Entrance, All Stair Landings, Stage, Gym, Room 108, Teachers' Lounge**  
MATERIAL QUANTITY: **591** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **E. C. Washroom, Kitchen, Ladies Toilet (East Basement), 3rd Floor T. L, (Men's & Women's Washrooms)**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **E. C. Washroom, Kitchen, Ladies Toilet (East Basement), 3rd Floor T. L, (Men's & Women's Washrooms)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Entrance, All Stair Landings, Stage, Gym, Room 108, Teachers' Lounge**  
MATERIAL QUANTITY: **591** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**  
MATERIAL LOCATION: **Main Entrance, All Stair Landings, Stage, Gym, Room 108, Teachers' Lounge**  
MATERIAL QUANTITY: **591** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **E. C. Washroom, Kitchen, Ladies' Toilet (East Basement), 3rd Floor T. L, (Men's & Women's Washrooms)**

MATERIAL QUANTITY: **500**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
MATERIAL LOCATION: **E. C. Washroom, Kitchen, Ladies' Toilet (East Basement), 3rd Floor T. L, (Men's & Women's Washrooms)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Grey Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, Computer Lab, 2nd Floor Teachers' Lounge**  
MATERIAL QUANTITY: **1074** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Grey Carpet Mastic**  
MATERIAL LOCATION: **Auditorium, Computer Lab, 2nd Floor Teachers' Lounge**  
MATERIAL QUANTITY: **1074** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14B**  
MATERIAL DESCRIPTION: **Black Linoleum NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **14B**

MATERIAL DESCRIPTION: **Black Linoleum NOT OBSERVED**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 White/Red-Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Office (No Classrooms)**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 White/Red-Brown Floor Tile**  
MATERIAL LOCATION: **2nd Floor Office (No Classrooms)**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Clerk Space, Principal's Office & Library Entrance**  
MATERIAL QUANTITY: **1188** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
MATERIAL LOCATION: **Main Office, Clerk Space, Principal's Office & Library Entrance**  
MATERIAL QUANTITY: **1188** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Clerk Space, Principal's Office & Library Entrance**  
MATERIAL QUANTITY: **2576** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Main Office, Clerk Space, Principal's Office & Library Entrance**  
MATERIAL QUANTITY: **2576** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 009**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**  
MATERIAL LOCATION: **Room 009**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 009**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**  
MATERIAL LOCATION: **Room 009**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Clerk Space, Principal's Office & Library Entrance**  
MATERIAL QUANTITY: **1185** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Main Office, Clerk Space, Principal's Office & Library Entrance**  
MATERIAL QUANTITY: **1185** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **E.C. Office, Counselor**  
MATERIAL QUANTITY: **227** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile**  
MATERIAL LOCATION: **E.C. Office, Counselor**  
MATERIAL QUANTITY: **227** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12x12 Brown Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 307 & Closet**  
MATERIAL QUANTITY: **1168** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12x12 Brown Mastic**  
MATERIAL LOCATION: **Room 307 & Closet**  
MATERIAL QUANTITY: **1168** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **E.C. Counselor's Office**  
MATERIAL QUANTITY: **227** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile Mastic**  
MATERIAL LOCATION: **E.C. Counselor's Office**  
MATERIAL QUANTITY: **227** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage Auditorium**  
MATERIAL QUANTITY: **1088** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile**  
MATERIAL LOCATION: **Stage Auditorium**  
MATERIAL QUANTITY: **1088** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage Auditorium**  
MATERIAL QUANTITY: **1088** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile Mastic**  
MATERIAL LOCATION: **Stage Auditorium**  
MATERIAL QUANTITY: **1088** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **143000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Auditorium/Gym fully abated 2018; Abatement & Repair entire 3rd Floor; 1st & 2nd Floor Halls; Basement; 2nd Floor Boys' & Girls' Restrooms Abated 2022; Stairwells & Vestibules**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **143000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Gypsum Board**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **3rd Floor, 1st & 2nd Floor Corridors & Stairs, Basement & 2nd Floor Boys' & Girls' Restrooms, Partial Basement, Auditorium/Gym**

MATERIAL QUANTITY: **7350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **2nd Floor Boys' & Girls' Restrooms Abated 2022**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Gypsum Board**  
MATERIAL LOCATION: **3rd Floor, 1st & 2nd Floor Corridors & Stairs, Basement & 2nd Floor Boys' & Girls' Restrooms, Partial Basement, Auditorium/Gym**  
MATERIAL QUANTITY: **7350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **3rd Floor, 1st & 2nd Floor Corridors & Stairs, Basement & 2nd Floor Boys' & Girls' Restrooms, Partial Basement, Auditorium/Gym**

MATERIAL QUANTITY: **7350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **2nd Floor Boys' & Girls' Restrooms Abated 2022**

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Joint Compound**  
MATERIAL LOCATION: **3rd Floor, 1st & 2nd Floor Corridors & Stairs, Basement & 2nd Floor Boys' & Girls' Restrooms, Partial Basement, Auditorium/Gym**  
MATERIAL QUANTITY: **7350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Fan Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Insulation**  
MATERIAL LOCATION: **Boiler Room, Fan Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Joints**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Joints**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Cardboard Pipe Joints**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Cardboard Pipe Joints**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School** INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Preformed Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Preformed Tank Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22841**    BUIDLING ID: **2900**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mike Di Canio**  
SCHOOL NAME: **Copernicus School**    INSPECTION DATE: **8/31/2022**  
ADDRESS: **6010 S. Throop**    IDPH LICENSE NO: **100-20640**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **12x12 Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 113 & 220**  
MATERIAL QUANTITY: **1600**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/31/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22841** BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School** REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop** IDPH LICENSE NO: **100-20640**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **12x12 Floor Tile**  
MATERIAL LOCATION: **Rooms 113 & 220**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/22/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22841**      BUILDING ID: **2900**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Copernicus School**      REVIEW DATE: **9/22/2022**  
ADDRESS: **6010 S. Throop**      IDPH LICENSE NO: **100-20640**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  \_\_\_\_\_ Date: **09/22/2022**

# APPENDIX B

## Inspector and Management Planner Licenses

---



# Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

**Michael DiCanio**

has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/1/2022 - 3/3/2022

Exam Date: 3/3/2022

Expiration Date: 3/3/2023

Certificate Number: ABI2203030655

Kathy DeSalvo, Director





ILLINOIS DEPARTMENT OF PUBLIC HEALTH

525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MICHAEL R DI CANIO  
2514 N 79TH AVE  
ELMWOOD PARK, IL 60707

4/7/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 20640


Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<p><b>ENDORSEMENTS</b></p> <p>INSPECTOR</p>	<p><b>TC EXPIRES</b></p> <p>3/3/2023</p>
<p><b>ID NUMBER</b> 100 - 20640</p>	<p><b>ISSUED</b> 4/7/2022</p>	<p><b>EXPIRES</b> 05/15/2023</p>	<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	
<p>MICHAEL R DI CANIO 2514 N 79TH AVE ELMWOOD PARK, IL 60707 Environmental Health</p>				



If you have any questions or  
(217)785-5897.

Our WEB address is: dph.il  
EMAIL Address: dph.asbes


<p><b>ID NUMBER</b> 100 - 20640</p>	<p><b>ISSUED</b> 4/7/2022</p>	<p><b>EXPIRES</b> 05/15/2023</p>
<p>MICHAEL R DI CANIO 2514 N 79TH AVE ELMWOOD PARK, IL 60707 Environmental Health</p>		
		

am at (217)782-3517 or fax

tection/asbestos

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB




**ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 03613	3/1/2022	05/15/2023

DANIEL J JUNEAU  
 1408 OAKWOOD AVENUE  
 DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/19/2022
MANAGEMENT PLANNER	11/19/2022
PROJECT MANAGER	11/1/2022
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
 This license issued under authority of the State of Illinois  
 Department of Public Health  
 This license is valid only when accompanied by a valid  
 training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed