

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2149
SCHOOL NAME: Davis School
ADDRESS OF SCHOOL: 3015 W. 39th Pl.
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **7/26/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/29/2022 ENROLLMENT 521
IDPH INSPECTOR LICENSE NUMBER: 100-20411
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



7/14/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Davis School

3015 W. 39th Pl.
Chicago, IL, 60632

Unit: 22891
Building ID: 2970

IDPH ID Number: 14-016-2990-2149

REPORT DATE:

Thursday, July 14, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: July 14, 2022

RE: Davis School, Unit 22891
3015 W. 39th Pl.
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Davis School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Davis School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Davis School
Address: 3015 W. 39th Pl.
IDPH ID: 14-016-2990-2149
Contact:

Unit: 22891
Chicago, IL, 60632
Building ID: 2970
Phone:

Region: 04

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 521

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant


MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Benyamen Maradkel


Inspector IDPH license # 100-20411
Reinspection Date: 6/29/2022

Signature: 
Date: 6/29/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature: 
Date: 07/14/2022

7. Review Date: 07/14/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 7/14/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Davis School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2970:

17	12" x 12" Beige and Cream Vinyl Floor Tile
19	Black White and Beige spotted Terrazzo
20	12" x 12" White w/ Black and Gray Spots Floor Tile
21	12" x 12" White w/ Black and Gray Spots Floor Tile Mastic
4.3	12" x 12" Brown/Orange Floor Tile
C	Aircell pipe joints

B. The following new homogenous areas have been identified for Building 2970:

- | | |
|----|--|
| 19 | Black White and Beige spotted Terrazzo |
| 20 | 12" x 12" White w/ Black and Gray Spots Floor Tile |
| 21 | 12" x 12" White w/ Black and Gray Spots Floor Tile
Mastic |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	12" x 12" Beige Floor Tile
11	12" x 12" Beige Floor Tile Mastic
12	Transite Lab top
13	2' x 4' White ceiling tile
14	Chalk boards
15	Fire doors (4 doors)
16	Black Terrazzo flooring
17	12" x 12" Beige and Cream Vinyl Floor Tile
18	12" x 12" Beige and Cream Vinyl Floor Tile Mastic
19	Black White and Beige spotted Terrazzo
20	12" x 12" White w/ Black and Gray Spots Floor Tile
21	12" x 12" White w/ Black and Gray Spots Floor Tile Mastic
4	12" x 12" Dark Beige Floor Tile
4.1	12" x 12" Light Beige Floor Tile
4.3	12" x 12" Brown/Orange Floor Tile
4.4	12" x 12" Gray Floor Tile
7.1	12" x 12" Light Beige Floor Tile Mastic
7.4	12" x 12" Gray Floor Tile Mastic
9	Roofing material
A	12" x 12" Red/Brown w/ White Streaks Floor Tile and Mastic
B	12" x 12" Beige Checkered Pattern Floor Tile w Mastic
BB	Blackboard adhesive
N	Brick material (interior)
O	Exterior brick material non ahera
P	Interior mortar material
Q	Exterior mortar material non ahera
R	Cork flooring
S	Corkboard flooring mastic

The following areas were deemed to be inaccessible:

18	12" x 12" Beige and Cream Vinyl Floor Tile Mastic
7.1	12" x 12" Light Beige Floor Tile Mastic
7.3	12" x 12" Brown/Orange Floor Tile Mastic
7.4	12" x 12" Gray Floor Tile Mastic
BB	Blackboard adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Davis School Building 2970 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Davis School Unit 22891 Building ID 2970

Address 3015 W. 39th Pl. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
10	12" x 12" Beige Floor Tile	2,400	SF	Rooms 208, 211, 300	ASSUMED	MISC	N	LOC	4	SF	No	ACBM with potential for significant damage	3	LOW
11	12" x 12" Beige Floor Tile Mastic	2,400	SF	Rooms 208, 211, 300	ASSUMED	MISC	N	LOC	1	SF	No	ACBM with potential for significant damage	3	LOW
12	Transite Lab top	80	SF	Rooms 304, 302	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
13	2' x 4' White ceiling tile	3,000	SF	Room 103, 105, 200, 311	ASSUMED	MISC	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
14	Chalk boards	3,645	SF	Room 301-310, Rooms 201-210, Rooms 102-110	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
15	Fire doors (4 doors)	84	SF	Auditorium	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
16	Black Terrazzo flooring		SF	Kitchen Storage Room	ASSUMED	MISC				SF				
17	12" x 12" Beige and Cream Vinyl Floor Tile	16,374	SF	Corridors, Rooms 200, 208, 300, Basement East and West, Lunchrooms,	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
18	12" x 12" Beige and Cream Vinyl Floor Tile Mastic	16,374	SF	Corridors, Rooms 200, 208, Basement East and West, Lunchrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
19	Black White and Beige spotted Terrazzo	400	SF	2nd Flr girls restroom , 3rd Flr girls restroom	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		MODERATE
20	12" x 12" White w/ Black and Gray Spots Floor Tile	400	SF	Room 211	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with potential for significant damage	5	MODERATE
21	12" x 12" White w/ Black and Gray Spots Floor Tile Mastic	400	SF	Room 211	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with potential for significant damage	5	MODERATE
4	12" x 12" Dark Beige Floor Tile	9	SF	Room 211	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
4.1	12" x 12" Light Beige Floor Tile	1,500	SF	Assembly Hall, Room 102	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
4.2	12" x 12" Off-White Floor Tile			Rooms 200	ABATED	MISC								
4.3	12" x 12" Brown/Orange Floor Tile	2,100	SF	All Faculty Bathrooms, 1st and 3rd Floor Girl's Bathroom, Room 103, Main Office	ASSUMED	MISC	N	LOC	21	SF	Yes	ACBM with potential for significant damage	3	LOW
4.4	12" x 12" Gray Floor Tile	2,200	SF	Assembly Hall, Assembly Dressing Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Davis School Unit 22891 Building ID 2970

Address 3015 W. 39th Pl. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
4.5	12" x 12" Reddish Brown Floor Tile Removed 2001			Room 210	ABATED	MISC								
5	12" x 12" Light Beige Floor Tile	2,600	SF	Faculty Lounge and Lunchrooms 1 & 2	CHR	MISC	N	LOC	1	SF	No	ACBM with potential for significant damage	3	LOW
5.1	9" x 9" Beige Floor Tile abated May 14 2002			Room 208	ABATED	MISC								
5.2	9" x 9" Gray Floor Tile abated May 14, 2002			Room 311	ABATED	MISC								
5.3	9" x 9" Olive Green Floor Tile abated May 14, 2002			Room 211	ABATED	MISC								
7	12" x 12" Dark Beige Floor Tile Mastic			Room 300	ABATED	MISC								
7.1	12" x 12" Light Beige Floor Tile Mastic	1,500	SF	Room 300, 102, Assembly hall, Assembly dressing room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
7.2	12" x 12" Off-White Floor Tile Mastic		SF	Rooms 200	CHR	MISC				SF				
7.3	12" x 12" Brown/Orange Floor Tile Mastic	1,600	SF	All Faculty Bathrooms, Room 103	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
7.4	12" x 12" Gray Floor Tile Mastic	3,500	SF	Assembly Hall, Assembly Dressing Room, Room 102	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
7.5	12" x 12" Reddish Brown Floor Tile Mastic abated 2/2001			Room 210	ABATED	MISC								
8	12" x 12" Light Beige Floor Tile Mastic	2,600	SF	Faculty Lounge and Lunchrooms 1 & 2, faculty main office restroom	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
8.1	9" x 9" Beige Floor Tile Mastic abated May 14, 2002			Room 208	ABATED	MISC								
8.2	9" x 9" Gray Floor Tile Mastic			Room 311	ABATED	MISC								
8.3	9" x 9" Olive Green Floor Tile Mastic			Room 211	ABATED	MISC								
9	Roofing material			Building Exterior NOT AHERA	ASSUMED	MISC								
A	12" x 12" Red/Brown w/ White Streaks Floor Tile and Mastic	900	SF	Room 050	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
B	12" x 12" Beige Checkered Pattern Floor Tile w Mastic	1,200	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
BB	Blackboard adhesive	552	SF	Rooms 106, 104, 206, 204, 202, 201, 301, 302	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
C	Aircell pipe joints	50	LF	Office, Faculty Bathroom, Boiler Room, Rooms 30,	CHR	TSI	Y	DIST	9	LF	Yes	Damaged or significantly damaged friable thermal system	5	MODERATE

Chicago Public Schools

School Davis School Unit 22891 Building ID 2970

Address 3015 W. 39th Pl. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 6/29/2022
Inspector Name Benyamen Maradkel
100-20411 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
10	Damage in Room 211
11	Damage in Room 211
12	
13	
14	
15	
16	Not observed 2022
17	
18	
19	
20	Damage in Center of Room 211
21	Damage in Center of Room 211
4	
4.1	
4.2	Not observed 2022
4.3	Damage in 2nd floor faculty bathroom
4.4	
4.5	
5	Damage outside of faculty lounge
5.1	
5.2	
5.3	
7	
7.1	Room 102 had construction and was inaccessible

Chicago Public Schools

School Davis School Unit 22891 Building ID 2970

Address 3015 W. 39th Pl. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
7.2	Not observed 2022
7.3	
7.4	Room 102 had construction and was inaccessible
7.5	
8	
8.1	
8.2	abated may 14 2002
8.3	abated may 14 2002
9	
A	
B	
BB	
C	Damage in Rooms 206A (3 SF), 103 (3 SF), Main Office (3 SF)
D	Damage in Room 103, 101 area under construction couldn't access
E	Not observed couldn't access principals office
F	Not observed 2022
H	By Engineers Office
I	
K	
L	
N	
O	
P	
Q	
R	Not observed 2022
S	Not observed 2022

Chicago Public Schools

School Davis School **Unit** 22891 **Building ID** 2970

Address 3015 W. 39th Pl. **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Davis School
Address 3015 W. 39th Pl.

Unit 22891
Chicago, IL, 60632

Building ID 2970
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
10	12" x 12" Beige Floor Tile	2,400	SF	Rooms 208, 211, 300	Assumed	MISC	No	4	SF	5 ACBM with potential for significant damage	Repair
11	12" x 12" Beige Floor Tile Mastic	2,400	SF	Rooms 208, 211, 300	Assumed	MISC	No	1	SF	5 ACBM with potential for significant damage	Repair
12	Transite Lab top	80	SF	Rooms 304, 302	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	2' x 4' White ceiling tile	3,000	SF	Room 103, 105, 200, 311	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	Chalk boards	3,645	SF	Room 301-310, Rooms 201-210, Rooms 102-110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Fire doors (4 doors)	84	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Black Terrazzo flooring		SF	Kitchen Storage Room	Assumed	MISC			SF		Follow O&M Plan
17	12" x 12" Beige and Cream Vinyl Floor Tile	16,374	SF	Corridors, Rooms 200, 208, 300, Basement East and West, Lunchrooms,	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
18	12" x 12" Beige and Cream Vinyl Floor Tile Mastic	16,374	SF	Corridors, Rooms 200, 208, Basement East and West, Lunchrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Black White and Beige spotted Terrazzo	400	SF	2nd Flr girls restroom , 3rd Flr girls restroom	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Repair
20	12" x 12" White w/ Black and Gray Spots Floor Tile	400	SF	Room 211	Assumed	MISC	No	3	SF	5 ACBM with potential for significant damage	Repair
21	12" x 12" White w/ Black and Gray Spots Floor Tile Mastic	400	SF	Room 211	Assumed	MISC	No	3	SF	5 ACBM with potential for significant damage	Repair
4	12" x 12" Dark Beige Floor Tile	9	SF	Room 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4.1	12" x 12" Light Beige Floor Tile	1,500	SF	Assembly Hall, Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4.2	12" x 12" Off-White Floor Tile			Rooms 200	Abated	MISC					
4.3	12" x 12" Brown/Orange Floor Tile	2,100	SF	All Faculty Bathrooms, 1st and 3rd Floor Girl's Bathroom, Room 103, Main Office	Assumed	MISC	No	21	SF	5 ACBM with potential for significant damage	Repair
4.4	12" x 12" Gray Floor Tile	2,200	SF	Assembly Hall, Assembly Dressing Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4.5	12" x 12" Reddish Brown Floor Tile Removed 2001			Room 210	Abated	MISC					
5	12" x 12" Light Beige Floor Tile	2,600	SF	Faculty Lounge and Lunchrooms 1 & 2	Chrysotile	MISC	No	1	SF	5 ACBM with potential for significant damage	Repair
5.1	9" x 9" Beige Floor Tile abated May 14 2002			Room 208	Abated	MISC					
5.2	9" x 9" Gray Floor Tile abated May 14, 2002			Room 311	Abated	MISC					
5.3	9" x 9" Olive Green Floor Tile abated May 14, 2002			Room 211	Abated	MISC					
7	12" x 12" Dark Beige Floor Tile Mastic			Room 300	Abated	MISC					Follow O&M Plan

Chicago Public Schools

School Davis School
Address 3015 W. 39th Pl.

Unit 22891
Chicago, IL, 60632

Building ID 2970
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
7.1	12" x 12" Light Beige Floor Tile Mastic	1,500	SF	Room 300, 102, Assembly hall, Assembly dressing room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.2	12" x 12" Off-White Floor Tile Mastic		SF	Rooms 200	Chrysotile	MISC			SF		Follow O&M Plan
7.3	12" x 12" Brown/Orange Floor Tile Mastic	1,600	SF	All Faculty Bathrooms, Room 103	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.4	12" x 12" Gray Floor Tile Mastic	3,500	SF	Assembly Hall, Assembly Dressing Room, Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.5	12" x 12" Reddish Brown Floor Tile Mastic abated 2/2001			Room 210	Abated	MISC					
8	12" x 12" Light Beige Floor Tile Mastic	2,600	SF	Faculty Lounge and Lunchrooms 1 & 2, faculty main office restroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8.1	9" x 9" Beige Floor Tile Mastic abated May 14, 2002			Room 208	Abated	MISC					
8.2	9" x 9" Gray Floor Tile Mastic			Room 311	Abated	MISC					
8.3	9" x 9" Olive Green Floor Tile Mastic			Room 211	Abated	MISC					
9	Roofing material			Building Exterior NOT AHERA	Assumed	MISC					Follow O&M Plan
A	12" x 12" Red/Brown w/ White Streaks Floor Tile and Mastic	900	SF	Room 050	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	12" x 12" Beige Checkered Pattern Floor Tile w Mastic	1,200	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BB	Blackboard adhesive	552	SF	Rooms 106, 104, 206, 204, 202, 201, 301, 302	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Aircell pipe joints	50	LF	Office, Faculty Bathroom, Boiler Room, Rooms 30, 105, 103, 101, and 206A	Chrysotile	TSI	Yes	9	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
D	Aircell pipe covering	900	LF	Rooms 101,103,104, nurse office, 1st Floor faculty restroom	Chrysotile	TSI	Yes	2	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
E	Cardboard pipe covering			Principal Storage Room, Kitchen Storage Room and Room 050	Chrysotile	TSI					Follow O&M Plan
F	Joints on Cardboard Pipe Covering			Kitchen Storage, Room 50	Chrysotile	TSI					Follow O&M Plan
H	Joints on Fiberglass Insulation	620	LF	Basement by engineer's office and in hallway outside kids' lunchroom	Chrysotile	TSI	Yes	9	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
I	Aircell Duct Covering abated in 1989			Basement Storage Room, Boy's Bathroom	Abated	TSI					
K	Cardboard Pipe Insulation (Abated before 1998)			Field House	Abated	TSI					
L	Joints on Cardboard Pipe Insulation			Field House (Abated Before 1998)	Abated	TSI					
N	Brick material (interior)	15,000	SF	Basement Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
O	Exterior brick material non ahera			Main Building	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Davis School
Address 3015 W. 39th Pl.

Unit 22891
 Chicago, IL, 60632

Building ID 2970
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
P	Interior mortar material	15,000	LF	Basement Area Hallway and Stairwell	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Q	Exterior mortar material non ahera			Main Building	Assumed	MISC					Follow O&M Plan
R	Cork flooring			Dental Room	Assumed	MISC					Follow O&M Plan
S	Corkboard flooring mastic			Dental Room	Assumed	MISC					Follow O&M Plan

Review Date 7/14/2022

HA Number	Management Comments
-----------	---------------------

Chicago Public Schools

School Davis School
Address 3015 W. 39th Pl.

Unit 22891
 Chicago, IL, 60632

Building ID 2970
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
4	
4.1	
4.2	
4.3	
4.4	
4.5	
5	
5.1	
5.2	
5.3	
7	
7.1	
7.2	
7.3	
7.4	

Chicago Public Schools

School Davis School
Address 3015 W. 39th Pl.

Unit 22891
Chicago, IL, 60632

Building ID 2970
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
7.5	
8	
8.1	
8.2	
8.3	
9	
A	
B	
BB	
C	
D	
E	
F	
H	
I	
K	
L	
N	
O	
P	
Q	
R	
S	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 208, 211, 300**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 211**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **Rooms 208, 211, 300**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage
Previous Repair**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 208, 211, 300**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 211**

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 208, 211, 300**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Transite Lab top**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 304, 302**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Transite Lab top**

MATERIAL LOCATION: **Rooms 304, 302**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **2' x 4' White ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 103, 105, 200, 311**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **2' x 4' White ceiling tile**
MATERIAL LOCATION: **Room 103, 105, 200, 311**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Chalk boards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 301-310, Rooms 201-210, Rooms 102-110**
MATERIAL QUANTITY: **3645** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Chalk boards**
MATERIAL LOCATION: **Room 301-310, Rooms 201-210, Rooms 102-110**
MATERIAL QUANTITY: **3645** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Fire doors (4 doors)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **84**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Fire doors (4 doors)**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **84**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Black Terrazzo flooring**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Black Terrazzo flooring**

MATERIAL LOCATION: **Kitchen Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" Beige and Cream Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridors, Rooms 200, 208, 300, Basement East and West, Lunchrooms,**

MATERIAL QUANTITY: **16374** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" Beige and Cream Vinyl Floor Tile**
MATERIAL LOCATION: **Corridors, Rooms 200, 208, 300, Basement East and West, Lunchrooms,**
MATERIAL QUANTITY: **16374** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" Beige and Cream Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridors, Rooms 200, 208, Basement East and West, Lunchrooms**
MATERIAL QUANTITY: **16374** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" Beige and Cream Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Corridors, Rooms 200, 208, Basement East and West, Lunchrooms**
MATERIAL QUANTITY: **16374** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 211**
MATERIAL QUANTITY: **9** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige Floor Tile**
MATERIAL LOCATION: **Room 211**
MATERIAL QUANTITY: **9** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4.1**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Assembly Hall, Room 102**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4.1**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile**
MATERIAL LOCATION: **Assembly Hall, Room 102**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4.2**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4.2**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**

MATERIAL LOCATION: **Rooms 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4.3**
MATERIAL DESCRIPTION: **12" x 12" Brown/Orange Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Faculty Bathrooms, 1st and 3rd Floor Girl's Bathroom, Room 103, Main Office**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2100** DAMAGE UNITS: **SF**
COMMENTS: **Damage in 2nd floor faculty bathroom**

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4.3**
MATERIAL DESCRIPTION: **12" x 12" Brown/Orange Floor Tile**
MATERIAL LOCATION: **All Faculty Bathrooms, 1st and 3rd Floor Girl's Bathroom, Room 103, Main Office**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **21** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4.4**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall, Assembly Dressing Room**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4.4**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
MATERIAL LOCATION: **Assembly Hall, Assembly Dressing Room**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4.5**
MATERIAL DESCRIPTION: **12" x 12" Reddish Brown Floor Tile Removed 2001**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 210**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4.5**

MATERIAL DESCRIPTION: **12" x 12" Reddish Brown Floor Tile Removed 2001**

MATERIAL LOCATION: **Room 210**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Lounge and Lunchrooms 1 & 2**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage outside of faculty lounge**

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile**
MATERIAL LOCATION: **Faculty Lounge and Lunchrooms 1 & 2**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5.1**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile abated May 14 2002**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5.1**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile abated May 14 2002**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5.2**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile abated May 14, 2002**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5.2**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile abated May 14, 2002**

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5.3**
MATERIAL DESCRIPTION: **9" x 9" Olive Green Floor Tile abated May 14, 2002**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **5.3**

MATERIAL DESCRIPTION: **9" x 9" Olive Green Floor Tile abated May 14, 2002**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Dark Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **12" x 12" Dark Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.1**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 300, 102, Assembly hall, Assembly dressing room**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Room 102 had construction and was inaccessible**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **7.1**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile Mastic**
MATERIAL LOCATION: **Room 300, 102, Assembly hall, Assembly dressing room**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.2**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 200**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **7.2**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 200**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.3**
MATERIAL DESCRIPTION: **12" x 12" Brown/Orange Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Faculty Bathrooms, Room 103**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **7.3**
MATERIAL DESCRIPTION: **12" x 12" Brown/Orange Floor Tile Mastic**
MATERIAL LOCATION: **All Faculty Bathrooms, Room 103**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.4**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall, Assembly Dressing Room, Room 102**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Room 102 had construction and was inaccessible**

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **7.4**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
MATERIAL LOCATION: **Assembly Hall, Assembly Dressing Room, Room 102**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.5**
MATERIAL DESCRIPTION: **12" x 12" Reddish Brown Floor Tile Mastic abated 2/2001**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 210**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **7.5**

MATERIAL DESCRIPTION: **12" x 12" Reddish Brown Floor Tile Mastic abated 2/2001**

MATERIAL LOCATION: **Room 210**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Lounge and Lunchrooms 1 & 2, faculty main office restroom**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUILDING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile Mastic**
MATERIAL LOCATION: **Faculty Lounge and Lunchrooms 1 & 2, faculty main office restroom**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8.1**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic abated May 14, 2002**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **8.1**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic abated May 14, 2002**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8.2**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **abated may 14 2002**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **8.2**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8.3**
MATERIAL DESCRIPTION: **9" x 9" Olive Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **abated may 14 2002**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **8.3**

MATERIAL DESCRIPTION: **9" x 9" Olive Green Floor Tile Mastic**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Roofing material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior NOT AHERA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Roofing material**

MATERIAL LOCATION: **Building Exterior NOT AHERA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **12" x 12" Red/Brown w/ White Streaks Floor Tile and Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 050**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **12" x 12" Red/Brown w/ White Streaks Floor Tile and Mastic**
MATERIAL LOCATION: **Room 050**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **12" x 12" Beige Checkered Pattern Floor Tile w Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **12" x 12" Beige Checkered Pattern Floor Tile w Mastic**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **Blackboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 106, 104, 206, 204, 202, 201, 301, 302**
MATERIAL QUANTITY: **552** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **Blackboard adhesive**
MATERIAL LOCATION: **Rooms 106, 104, 206, 204, 202, 201, 301, 302**
MATERIAL QUANTITY: **552** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell pipe joints**
HISTORICAL AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Office, Faculty Bathroom, Boiler Room, Rooms 30, 105, 103, 101, and 206A**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **LF**
COMMENTS: **Damage in Rooms 206A (3 SF), 103 (3 SF), Main Office (3 SF)**

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell pipe joints**
MATERIAL LOCATION: **Office, Faculty Bathroom, Boiler Room, Rooms 30, 105, 103, 101, and 206A**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **9** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22891 BUIDLING ID: 2970
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Benyamen Maradkel
SCHOOL NAME: Davis School INSPECTION DATE: 6/29/2022
ADDRESS: 3015 W. 39th Pl. IDPH LICENSE NO: 100-20411

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: D
MATERIAL DESCRIPTION: Aircell pipe covering
HISTORICAL AHERA DAMAGE CATEGORY 1 Damaged or significantly damaged friable thermal system insulating ACBM
HISTORICAL DAMAGE REASON: Physical Damage
HISTORICAL RESPONSE ACTION: Repair
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 1. **Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: Physical Damage
DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Rooms 101,103,104, nurse office, 1st Floor faculty restroom
MATERIAL QUANTITY: 900 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF
COMMENTS: Damage in Room 103, 101 area under construction couldn't access

Inspector's Signature:



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Aircell pipe covering**
MATERIAL LOCATION: **Rooms 101,103,104, nurse office, 1st Floor faculty restroom**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard pipe covering**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principal Storage Room, Kitchen Storage Room and Room 050**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed couldn't access principals office**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Cardboard pipe covering**

MATERIAL LOCATION: **Principal Storage Room, Kitchen Storage Room and Room 050**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Joints on Cardboard Pipe Covering**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen Storage, Room 50**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Joints on Cardboard Pipe Covering**

MATERIAL LOCATION: **Kitchen Storage, Room 50**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Joints on Fiberglass Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement by engineer's office and in hallway outside kids' lunchroom**
MATERIAL QUANTITY: **620** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **620** DAMAGE UNITS: **LF**
COMMENTS: **By Engineers Office**

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Joints on Fiberglass Insulation**
MATERIAL LOCATION: **Basement by engineer's office and in hallway outside kids' lunchroom**
MATERIAL QUANTITY: **620** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **9** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Aircell Duct Covering abated in 1989**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Storage Room, Boy's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Aircell Duct Covering abated in 1989**

MATERIAL LOCATION: **Basement Storage Room, Boy's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (Abated before 1998)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Field House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUILDING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (Abated before 1998)**

MATERIAL LOCATION: **Field House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Joints on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Field House (Abated Before 1998)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Joints on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Field House (Abated Before 1998)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Brick material (interior)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Area**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Brick material (interior)**
MATERIAL LOCATION: **Basement Area**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Exterior brick material non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Exterior brick material non ahera**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Interior mortar material**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Area Hallway and Stairwell**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Interior mortar material**
MATERIAL LOCATION: **Basement Area Hallway and Stairwell**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Exterior mortar material non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Exterior mortar material non ahera**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **Cork flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Dental Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Cork flooring**

MATERIAL LOCATION: **Dental Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Corkboard flooring mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Dental Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUIDLING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **S**

MATERIAL DESCRIPTION: **Corkboard flooring mastic**

MATERIAL LOCATION: **Dental Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUILDING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black and Gray Spots Floor Tile Mastic**
MATERIAL LOCATION: **Room 211**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **3** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in Center of Room 211

Inspector's Signature: _____



Date: **06/29/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUILDING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" White w/ Black and Gray Spots Floor Tile Mastic**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUILDING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black and Gray Spots Floor Tile**
MATERIAL LOCATION: **Room 211**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **3** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in Center of Room 211

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUILDING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black and Gray Spots Floor Tile**
MATERIAL LOCATION: **Room 211**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUILDING ID: **2970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Davis School** INSPECTION DATE: **6/29/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Black White and Beige spotted Terrazzo**
MATERIAL LOCATION: **2nd Flr girls restroom , 3rd Flr girls restroom**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 06/29/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22891** BUILDING ID: **2970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Davis School** REVIEW DATE: **7/14/2022**
ADDRESS: **3015 W. 39th Pl.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Black White and Beige spotted Terrazzo**

MATERIAL LOCATION: **2nd Flr girls restroom , 3rd Flr girls restroom**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 07/14/2022

APPENDIX B

Inspector and Management Planner Licenses

Benyamen Maradkel

Illinois Licensed Building Inspector



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 20411

ISSUED
3/17/2022

EXPIRES
05/15/2023

BENYAMEN C MARADKEL
706 W HACKBERRY DR
ARLINGTON HEIGHTS, IL 6000
Environmental Health



ENDORSEMENTS

INSPECTOR

EXPIRES

3/9/2023

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Benyamen Maradkel

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090703

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed