

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2150
SCHOOL NAME: Dawes School
ADDRESS OF SCHOOL: 3810 W. 81st St.
CITY: Chicago, IL, 60652

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/29/2019**


If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 8/17/2022 ENROLLMENT 981
IDPH INSPECTOR LICENSE NUMBER: 100-11070
IDPH LICENSED INSPECTOR NAME (Please Print): Mallory Jones
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



9/21/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Dawes School

3810 W. 81st St.
Chicago, IL, 60652

Unit: 22901
Building ID: 2980

IDPH ID Number: 14-016-2990-2150

REPORT DATE:

Wednesday, September 21, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

09/21/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22901 Region: 05 IDPH ID: 14-016-2990-2150

School: Dawes School Building ID: 2980

Address: 3810 W. 81st St.

Chicago, IL, 60652

Building Contact: Czerwinski, Thomas

Contact Phone: 7735741297

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/17/2022

Review Date: 09/21/2022

Inspector: Mallory Jones

Inspector IDPH License: 100-11070

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Daniel Juneau
100-03613

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 21, 2022

RE: Dawes School, Unit 22901
3810 W. 81st St.
Chicago, IL, 60652

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Dawes School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Dawes School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Dawes School Unit: 22901 Region: 05
Address: 3810 W. 81st St. Chicago, IL, 60652
IDPH ID: 14-016-2990-2150 Building ID: 2980
Contact: Czerwinski, Thomas Phone: 7735741297

2. Description of Facility

Original Construction: 2017 Additional Construction:
Total Square Footage: 9800 No of Floors: 1
Current Occupancy: 981

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Mallory Jones

Inspector IDPH license # 100-11070
Reinspection Date: 8/17/2022




Signature:
Date: 8/17/2022

6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613




Signature:
Date: 09/21/2022

7. Review Date: 09/21/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 9/21/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Dawes School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2980:

A	Mag Block Insulation ABATED
C	Aircell Pipe Insulation ABATED
D	Cloth Wrap Aircell Duct Insulation ABATED
E	Cardboard Pipe Insulation ABATED
H	Aircell MJP ABATED
I	Breeching Insulation ABATED
J	Aircell Pipe Insulation ABATED
K	Cardboard Pipe Insulation ABATED
L	Fiberglass Fittings & Runs ABATED

M Cementitious Pipe Insulation (Mag) ABATED

NEW Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 2980:

NEW

Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

06A	12x12 Gray w/Dark Streaks Floor Tile
06C	12x12 White w/Specks Floor Tile
06D	12x12 White w/Tan Specks Floor Tile
07A	Gray Swirl Multicolor Linoleum NOT OBSERVED
14A	9x9 Tan w/Rust Streaks Floor Tile Mastic
14B	9x9 Rust w/Black & White Streaks Floor Tile Mastic
15C	12x12 White w/Specks Floor Tile Mastic
15D	12x12 White w/Tan Specks Floor Tile Mastic
18A	Gray Swirl Multicolor Linoleum Mastic
21A	Brown Baseboard (some painted Yellow)
21B	Green Baseboard
21C	Black Baseboard
21D	Cream Baseboard
21E	Light Brown Baseboard
22B	Green Baseboard Mastic
22C	Black Baseboard Mastic
22D	Cream Baseboard Mastic
22E	Light Brown Baseboard Mastic
23	12x12 Beige Floor Tile
24	12x12 Beige Floor Tile Mastic
CM-1	Brown Carpet Mastic
CM-2	Brown Carpet Mastic
CM-3	Blue Carpet Mastic
FT-1	12x12 Light Blue Tile
FT-2	12x12 Yellow Floor Tile
FTM-1	12x12 Light Blue Tile Mastic
FTM-2	12x12 Yellow Floor Tile Mastic
N	Plaster
NEW	Newly Installed Suspect ACM
O	Transite Type Boards
P	Brown Carpet Square Mastic

The following areas were deemed to be inaccessible:

15D	12x12 White w/Tan Specks Floor Tile Mastic
22B	Green Baseboard Mastic
22C	Black Baseboard Mastic
22D	Cream Baseboard Mastic
22E	Light Brown Baseboard Mastic

24	12x12 Beige Floor Tile Mastic
CM-2	Brown Carpet Mastic
FTM-1	12x12 Light Blue Tile Mastic
FTM-2	12x12 Yellow Floor Tile Mastic
P	Brown Carpet Square Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mallory Jones, IDPH License # 100-11070. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/26/2021

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Dawes School Building 2980 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Dawes School Unit 22901 Building ID 2980

Address 3810 W. 81st St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
05A	9x9 Tan w/Rust Streaks Floor Tile	16,950	SF	Original Building- 1/2 of Rooms: 100, 101, 103, 106, 107, 108, 202-208 & 210	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	9x9 Rust w/Black & White Streaks Floor Tile	16,950	SF	Original Building- Half of Rooms: 100, 101, 103, 106, 107, 108, 202-208 & 210	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05C	9x9 Green Vinyl Floor Tile ABATED			2nd Floor Corridor between Both Additions & Women Teachers' Lounge	ABATED	MISC								Low
05D	9x9 Rust w/Streaks Floor Tile ABATED			2nd Floor Corridor between Both Addition & Women Teachers' Lounge	ABATED	MISC								Low
05E	9x9 Brown Floor Tile ABATED			1952 Building- 1st & 2nd Floor Corridor Patches	ABATED	MISC								Low
05F	9x9 Tan w/Brown Floor Tile ABATED			1954 & 1958 Buildings- Patches in Hallways	ABATED	MISC								Low
06A	12x12 Gray w/Dark Streaks Floor Tile	400	SF	Section of Room 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06B	12x12 Tan w/Black Streaks Floor Tile	9,750	SF	Rooms: 109, 113, 116, 118, 120, 122, 211, 213, 121, 216, 218, 224, 226	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06C	12x12 White w/Specks Floor Tile	6,000	SF	Basement Passage, Teachers' Lunchroom, Kitchen Lunchroom, Modular Classroom, Book Store Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06D	12x12 White w/Tan Specks Floor Tile	6,048	SF	Modular Buildings- 220, Carpet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	Gray Swirl Multicolor Linoleum NOT OBSERVED	840	SF	Room 200, Room 200-4	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12A	9x9 Tan w/Black Streaks Floor Tile Mastic ABATED			1st & 2nd Floor Corridors	ABATED	MISC								Low
13A	9x9 Tan w/Black Streaks Floor Tile Mastic ABATED			1st & 2nd Floor Corridors	ABATED	MISC					No			Low
14A	9x9 Tan w/Rust Streaks Floor Tile Mastic	16,950	SF	Original Building- 1/2 of Room: 100 -	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Dawes School Unit 22901 Building ID 2980

Address 3810 W. 81st St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				108, 202 - 208, 210, Public part of Office										
14B	9x9 Rust w/Black & White Streaks Floor Tile Mastic	13,750	SF	Original Building- 1/2 of Rooms 100-108, 202-208, 210, Public Part of Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14C	9x9 Green Vinyl Floor Tile Mastic ABATED			2nd Floor Corridor between Both Additions & Women Teachers' Lounge	ABATED	MISC								Low
14D	9x9 Rust w/Streaks Floor Tile Mastic ABATED			2nd Floor Corridor between Both Addition & Women Teachers' Lounge	ABATED	MISC								Low
14E	9x9 Brown Floor Tile Mastic ABATED			1952 Building- 1st & 2nd Floor Corridor Patches	ABATED	MISC								Low
14F	9x9 Tan w/Brown Floor Tile Mastic ABATED			1954 & 1958 Buildings- Patches in Hallways	ABATED	MISC								Low
15A	12x12 Gray w/Dark Streaks Floor Tile Mastic	400	SF	Section of Room 201	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15B	12x12 Tan w/Black Streaks Floor Tile Mastic	9,750	SF	Rooms 109, 113, 116, 118, 120, 122, 211, 213, 121, 216, 218, 224, 226	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15C	12x12 White w/Specks Floor Tile Mastic	6,000	SF	Basement Passage, Teachers' Lunchroom, Kitchen Lunchroom, Modular Classroom, Book Store Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15D	12x12 White w/Tan Specks Floor Tile Mastic	6,048	SF	Modular Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18A	Gray Swirl Multicolor Linoleum Mastic	840	SF	Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21A	Brown Baseboard (some painted Yellow)	1,370	LF	Rooms 114, 118, 120, 122, Restroom, Teachers' Lounge, 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21B	Green Baseboard	119	LF	1958 Building- Room 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21C	Black Baseboard	419	LF	Rooms 109, 113, 122, 201 & 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Dawes School Unit 22901 Building ID 2980

Address 3810 W. 81st St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
21D	Cream Baseboard	1,000	LF	Modular Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21E	Light Brown Baseboard	200	LF	Basement, Lunchroom, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22A	Brown Baseboard Mastic	1,370	LF	Rooms 114, 116, 118, 120, 122, Restroom & Teachers' Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22B	Green Baseboard Mastic	119	LF	Room 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22C	Black Baseboard Mastic	300	LF	Rooms 109, 113, 122 & 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22D	Cream Baseboard Mastic	1,000	LF	Modular Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22E	Light Brown Baseboard Mastic	200	LF	Basement, Lunchroom, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12x12 Beige Floor Tile	4,000	SF	1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12x12 Beige Floor Tile Mastic	4,000	SF	1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Mag Block Insulation ABATED			Boiler Room- Boiler	ABATED	TSI					Yes			
C	Aircell Pipe Insulation ABATED			Original Building- Basement, 1st & 2nd Floors	ABATED	TSI					Yes			
CM-1	Brown Carpet Mastic	60	SF	1954 Building- Room 102 Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-2	Brown Carpet Mastic	3,300	SF	1958 Building- 112, 114 & 222	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-3	Blue Carpet Mastic	3,000	SF	Principal's Office, Rooms 111, 209, 212, 221, and Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-4	Green Carpet Mastic	1,200	SF	Room 220, Main Office	CHR	MISC	N	UNKNOWN			No	ACBM with the potential for damage		LOW
D	Cloth Wrap Aircell Duct Insulation ABATED			1958 Building- Crawlspace North and South Sections, South Wing, North & South Areas	ABATED	TSI					Yes			
E	Cardboard Pipe Insulation ABATED			1958 Building- Basement, 1st & 2nd Floor	ABATED	TSI					Yes			
FT-1	12x12 Light Blue Tile	1,125	SF	Room 102, 114, 222	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Dawes School Unit 22901 Building ID 2980

Address 3810 W. 81st St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
FT-2	12x12 Yellow Floor Tile	950	SF	Room 112, 1st Floor Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	12x12 Light Blue Tile Mastic	1,125	SF	Room 102, 114, 222	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-2	12x12 Yellow Floor Tile Mastic	950	SF	Room 112, 1st Floor Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G	Fiberglass Fittings	150	LF	1954 Building-Basement	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	Aircell MJP ABATED			Basement, 1st & 2nd Floors, Boiler Room, Locker Room, Engineer's Office, Fan Rooms, Crawlspace, Air Tunnels	ABATED	TSI					Yes			
I	Breeching Insulation ABATED			Basement Boiler Room	ABATED	TSI					Yes			
J	Aircell Pipe Insulation ABATED			1958 Building-Basement, 1st & 2nd Floors, Fan Rooms, Crawlspace, South Wing Air Tunnels	ABATED	TSI					Yes			
K	Cardboard Pipe Insulation ABATED			1958 Building-Basement, 1st & 2nd Floors	ABATED	TSI					Yes			
L	Fiberglass Fittings & Runs ABATED			1st & 2nd Floor Boys' & Girls' Toilet, Fan Room*	ABATED	TSI					Yes			
M	Cementitious Pipe Insulation (Mag) ABATED			Basement, 1st & 2nd Floors	ABATED	TSI					Yes			
N	Plaster	1,000	SF	Boiler Room	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		
O	Transite Type Boards	250	SF	Ramps of Modular Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
P	Brown Carpet Square Mastic	500	SF	Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Dawes School Unit 22901 Building ID 2980

Address 3810 W. 81st St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/17/2022
Inspector Name Mallory Jones
100-11070 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
05A	Rooms 116, 118, 120 & 122 are included in HA 06B & 15B
05B	Rooms 116, 118, 120 & 122 are included in HA 06B & 15B
05C	
05D	
05E	
05F	
06A	
06B	
06C	
06D	
07A	Not Observed 2022
12A	
13A	
14A	
14B	
14C	
14D	
14E	
14F	
15A	
15B	Rooms 116, 118, 120 & 122 have different Material. New HA Assigned
15C	
15D	
18A	

Chicago Public Schools

School Dawes School Unit 22901 Building ID 2980

Address 3810 W. 81st St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
21A	
21B	
21C	
21D	
21E	
22A	
22B	
22C	
22D	
22E	
23	
24	
A	Abated 2022
C	Abated 2022
CM-1	
CM-2	
CM-3	
CM-4	
D	Abated 2022
E	Abated 2022
FT-1	
FT-2	
FTM-1	
FTM-2	
G	
H	Abated 2022
I	Abated 2022
J	Abated 2022
K	Abated 2022

Chicago Public Schools

School Dawes School Unit 22901 Building ID 2980

Address 3810 W. 81st St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
L	Abated 2022
M	Abated 2022
N	
NEW	
O	
P	

Table II

Management Planner's Review

Chicago Public Schools

School Dawes School
Address 3810 W. 81st St.

Unit 22901
Chicago, IL, 60652

Building ID 2980
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
05A	9x9 Tan w/Rust Streaks Floor Tile	16,950	SF	Original Building- 1/2 of Rooms: 100, 101, 103, 106, 107, 108, 202-208 & 210	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05B	9x9 Rust w/Black & White Streaks Floor Tile	16,950	SF	Original Building- Half of Rooms: 100, 101, 103, 106, 107, 108, 202-208 & 210	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05C	9x9 Green Vinyl Floor Tile ABATED			2nd Floor Corridor between Both Additions & Women Teachers' Lounge	Abated	MISC					
05D	9x9 Rust w/Streaks Floor Tile ABATED			2nd Floor Corridor between Both Addition & Women Teachers' Lounge	Abated	MISC					
05E	9x9 Brown Floor Tile ABATED			1952 Building- 1st & 2nd Floor Corridor Patches	Abated	MISC					
05F	9x9 Tan w/Brown Floor Tile ABATED			1954 & 1958 Buildings- Patches in Hallways	Abated	MISC					
06A	12x12 Gray w/Dark Streaks Floor Tile	400	SF	Section of Room 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06B	12x12 Tan w/Black Streaks Floor Tile	9,750	SF	Rooms: 109, 113, 116, 118, 120, 122, 211, 213, 121, 216, 218, 224, 226	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06C	12x12 White w/Specks Floor Tile	6,000	SF	Basement Passage, Teachers' Lunchroom, Kitchen Lunchroom, Modular Classroom, Book Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06D	12x12 White w/Tan Specks Floor Tile	6,048	SF	Modular Buildings- 220, Carpet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	Gray Swirl Multicolor Linoleum NOT OBSERVED	840	SF	Room 200, Room 200-4	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
12A	9x9 Tan w/Black Streaks Floor Tile Mastic ABATED			1st & 2nd Floor Corridors	Abated	MISC					
13A	9x9 Tan w/Black Streaks Floor Tile Mastic ABATED			1st & 2nd Floor Corridors	Abated	MISC					
14A	9x9 Tan w/Rust Streaks Floor Tile Mastic	16,950	SF	Original Building- 1/2 of Room: 100 - 108, 202 - 208, 210, Public part of Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14B	9x9 Rust w/Black & White Streaks Floor Tile Mastic	13,750	SF	Original Building- 1/2 of Rooms 100-108, 202-208, 210, Public Part of Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14C	9x9 Green Vinyl Floor Tile Mastic ABATED			2nd Floor Corridor between Both Additions & Women Teachers' Lounge	Abated	MISC					
14D	9x9 Rust w/Streaks Floor Tile Mastic ABATED			2nd Floor Corridor between Both Addition & Women Teachers' Lounge	Abated	MISC					
14E	9x9 Brown Floor Tile Mastic ABATED			1952 Building- 1st & 2nd Floor Corridor Patches	Abated	MISC					
14F	9x9 Tan w/Brown Floor Tile Mastic ABATED			1954 & 1958 Buildings- Patches in	Abated	MISC					

Chicago Public Schools

School Dawes School
Address 3810 W. 81st St.

Unit 22901
Chicago, IL, 60652

Building ID 2980
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Hallways							
15A	12x12 Gray w/Dark Streaks Floor Tile Mastic	400	SF	Section of Room 201	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15B	12x12 Tan w/Black Streaks Floor Tile Mastic	9,750	SF	Rooms 109, 113, 116, 118, 120, 122, 211, 213, 121, 216, 218, 224, 226	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15C	12x12 White w/Specks Floor Tile Mastic	6,000	SF	Basement Passage, Teachers' Lunchroom, Kitchen Lunchroom, Modular Classroom, Book Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15D	12x12 White w/Tan Specks Floor Tile Mastic	6,048	SF	Modular Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	Gray Swirl Multicolor Linoleum Mastic	840	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21A	Brown Baseboard (some painted Yellow)	1,370	LF	Rooms 114, 118, 120, 122, Restroom, Teachers' Lounge, 116	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
21B	Green Baseboard	119	LF	1958 Building- Room 220	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
21C	Black Baseboard	419	LF	Rooms 109, 113, 122, 201 & 220	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
21D	Cream Baseboard	1,000	LF	Modular Buildings	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
21E	Light Brown Baseboard	200	LF	Basement, Lunchroom, Kitchen	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22A	Brown Baseboard Mastic	1,370	LF	Rooms 114, 116, 118, 120, 122, Restroom & Teachers' Lounge	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22B	Green Baseboard Mastic	119	LF	Room 220	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22C	Black Baseboard Mastic	300	LF	Rooms 109, 113, 122 & 201	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22D	Cream Baseboard Mastic	1,000	LF	Modular Buildings	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22E	Light Brown Baseboard Mastic	200	LF	Basement, Lunchroom, Kitchen	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
23	12x12 Beige Floor Tile	4,000	SF	1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12x12 Beige Floor Tile Mastic	4,000	SF	1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Mag Block Insulation ABATED			Boiler Room- Boiler	Abated	TSI					
C	Aircell Pipe Insulation ABATED			Original Building- Basement, 1st & 2nd Floors	Abated	TSI					
CM-1	Brown Carpet Mastic	60	SF	1954 Building- Room 102 Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-2	Brown Carpet Mastic	3,300	SF	1958 Building- 112, 114 & 222	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-3	Blue Carpet Mastic	3,000	SF	Principal's Office, Rooms 111, 209, 212, 221, and Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-4	Green Carpet Mastic	1,200	SF	Room 220, Main Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
D	Cloth Wrap Aircell Duct Insulation ABATED			1958 Building- Crawlspace North and South Sections, South Wing, North & South Areas	Abated	TSI					
E	Cardboard Pipe Insulation ABATED			1958 Building- Basement, 1st & 2nd	Abated	TSI					

Chicago Public Schools

School Dawes School
Address 3810 W. 81st St.

Unit 22901
Chicago, IL, 60652

Building ID 2980
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Floor							
FT-1	12x12 Light Blue Tile	1,125	SF	Room 102, 114, 222	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-2	12x12 Yellow Floor Tile	950	SF	Room 112, 1st Floor Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 Light Blue Tile Mastic	1,125	SF	Room 102, 114, 222	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	12x12 Yellow Floor Tile Mastic	950	SF	Room 112, 1st Floor Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Fiberglass Fittings	150	LF	1954 Building- Basement	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	Aircell MJP ABATED			Basement, 1st & 2nd Floors, Boiler Room, Locker Room, Engineer's Office, Fan Rooms, Crawlspace, Air Tunnels	Abated	TSI					
I	Breeching Insulation ABATED			Basement Boiler Room	Abated	TSI					
J	Aircell Pipe Insulation ABATED			1958 Building- Basement, 1st & 2nd Floors, Fan Rooms, Crawlspace, South Wing Air Tunnels	Abated	TSI					
K	Cardboard Pipe Insulation ABATED			1958 Building- Basement, 1st & 2nd Floors	Abated	TSI					
L	Fiberglass Fittings & Runs ABATED			1st & 2nd Floor Boys' & Girls' Toilet, Fan Room*	Abated	TSI					
M	Cementitious Pipe Insulation (Mag) ABATED			Basement, 1st & 2nd Floors	Abated	TSI					
N	Plaster	1,000	SF	Boiler Room	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
O	Transite Type Boards	250	SF	Ramps of Modular Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
P	Brown Carpet Square Mastic	500	SF	Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Dawes School
Address 3810 W. 81st St.

Unit 22901
 Chicago, IL, 60652

Building ID 2980
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	9/21/2022
Manager Planner Name	Daniel Juneau
100-03613	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
05A	
05B	
05C	
05D	
05E	
05F	
06A	
06B	
06C	
06D	
07A	
12A	
13A	
14A	
14B	
14C	

Chicago Public Schools

School Dawes School
Address 3810 W. 81st St.

Unit 22901
 Chicago, IL, 60652

Building ID 2980
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
14D	
14E	
14F	
15A	
15B	
15C	
15D	
18A	
21A	
21B	
21C	
21D	
21E	
22A	
22B	
22C	
22D	
22E	
23	
24	
A	
C	
CM-1	
CM-2	
CM-3	
CM-4	
D	

Chicago Public Schools

School Dawes School
Address 3810 W. 81st St.

Unit 22901
Chicago, IL, 60652

Building ID 2980
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
E	
FT-1	
FT-2	
FTM-1	
FTM-2	
G	
H	
I	
J	
K	
L	
M	
N	
NEW	
O	
P	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **9x9 Tan w/Rust Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Original Building- 1/2 of Rooms: 100, 101, 103, 106, 107, 108, 202-208 & 210**

MATERIAL QUANTITY: **16950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Rooms 116, 118, 120 & 122 are included in HA 06B & 15B**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **9x9 Tan w/Rust Streaks Floor Tile**
MATERIAL LOCATION: **Original Building- 1/2 of Rooms: 100, 101, 103, 106, 107, 108, 202-208 & 210**
MATERIAL QUANTITY: **16950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **9x9 Rust w/Black & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Original Building- Half of Rooms: 100, 101, 103, 106, 107, 108, 202-208 & 210**
MATERIAL QUANTITY: **16950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Rooms 116, 118, 120 & 122 are included in HA 06B & 15B**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **9x9 Rust w/Black & White Streaks Floor Tile**
MATERIAL LOCATION: **Original Building- Half of Rooms: 100, 101, 103, 106, 107, 108, 202-208 & 210**
MATERIAL QUANTITY: **16950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05C**
MATERIAL DESCRIPTION: **9x9 Green Vinyl Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **2nd Floor Corridor between Both Additions & Women Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **05C**
MATERIAL DESCRIPTION: **9x9 Green Vinyl Floor Tile ABATED**
MATERIAL LOCATION: **2nd Floor Corridor between Both Additions & Women Teachers' Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05D**
MATERIAL DESCRIPTION: **9x9 Rust w/Streaks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **2nd Floor Corridor between Both Addition & Women Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **05D**
MATERIAL DESCRIPTION: **9x9 Rust w/Streaks Floor Tile ABATED**
MATERIAL LOCATION: **2nd Floor Corridor between Both Addition & Women Teachers' Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05E**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **1952 Building- 1st & 2nd Floor Corridor Patches**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **05E**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile ABATED**
MATERIAL LOCATION: **1952 Building- 1st & 2nd Floor Corridor Patches**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05F**
MATERIAL DESCRIPTION: **9x9 Tan w/Brown Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **1954 & 1958 Buildings- Patches in Hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **05F**
MATERIAL DESCRIPTION: **9x9 Tan w/Brown Floor Tile ABATED**
MATERIAL LOCATION: **1954 & 1958 Buildings- Patches in Hallways**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12x12 Gray w/Dark Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Section of Room 210**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12x12 Gray w/Dark Streaks Floor Tile**
MATERIAL LOCATION: **Section of Room 210**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **12x12 Tan w/Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms: 109, 113, 116, 118, 120, 122, 211, 213, 121, 216, 218, 224, 226**
MATERIAL QUANTITY: **9750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **12x12 Tan w/Black Streaks Floor Tile**
MATERIAL LOCATION: **Rooms: 109, 113, 116, 118, 120, 122, 211, 213, 121, 216, 218, 224, 226**
MATERIAL QUANTITY: **9750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **12x12 White w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Basement Passage, Teachers' Lunchroom, Kitchen Lunchroom, Modular Classroom, Book Store Room**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **12x12 White w/Specks Floor Tile**
MATERIAL LOCATION: **Basement Passage, Teachers' Lunchroom, Kitchen Lunchroom, Modular Classroom, Book Store Room**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06D**
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Buildings- 220, Carpet**
MATERIAL QUANTITY: **6048** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **06D**
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile**
MATERIAL LOCATION: **Modular Buildings- 220, Carpet**
MATERIAL QUANTITY: **6048** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **Gray Swirl Multicolor Linoleum NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 200, Room 200-4**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed 2022**

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **Gray Swirl Multicolor Linoleum NOT OBSERVED**
MATERIAL LOCATION: **Room 200, Room 200-4**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **9x9 Tan w/Black Streaks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **9x9 Tan w/Black Streaks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **9x9 Tan w/Black Streaks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **9x9 Tan w/Black Streaks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **9x9 Tan w/Rust Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Original Building- 1/2 of Room: 100 - 108, 202 - 208, 210, Public part of Office**
MATERIAL QUANTITY: **16950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **9x9 Tan w/Rust Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Original Building- 1/2 of Room: 100 - 108, 202 - 208, 210, Public part of Office**
MATERIAL QUANTITY: **16950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14B**
MATERIAL DESCRIPTION: **9x9 Rust w/Black & White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Original Building- 1/2 of Rooms 100-108, 202-208, 210, Public Part of Office**
MATERIAL QUANTITY: **13750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **14B**
MATERIAL DESCRIPTION: **9x9 Rust w/Black & White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Original Building- 1/2 of Rooms 100-108, 202-208, 210, Public Part of Office**
MATERIAL QUANTITY: **13750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14C**
MATERIAL DESCRIPTION: **9x9 Green Vinyl Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **2nd Floor Corridor between Both Additions & Women Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **14C**
MATERIAL DESCRIPTION: **9x9 Green Vinyl Floor Tile Mastic ABATED**
MATERIAL LOCATION: **2nd Floor Corridor between Both Additions & Women Teachers' Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14D**
MATERIAL DESCRIPTION: **9x9 Rust w/Streaks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **2nd Floor Corridor between Both Addition & Women Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **14D**
MATERIAL DESCRIPTION: **9x9 Rust w/Streaks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **2nd Floor Corridor between Both Addition & Women Teachers' Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14E**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **1952 Building- 1st & 2nd Floor Corridor Patches**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **14E**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1952 Building- 1st & 2nd Floor Corridor Patches**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14F**
MATERIAL DESCRIPTION: **9x9 Tan w/Brown Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **1954 & 1958 Buildings- Patches in Hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **14F**
MATERIAL DESCRIPTION: **9x9 Tan w/Brown Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1954 & 1958 Buildings- Patches in Hallways**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12x12 Gray w/Dark Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Section of Room 201**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12x12 Gray w/Dark Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Section of Room 201**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **12x12 Tan w/Black Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 109, 113, 116, 118, 120, 122, 211, 213, 121, 216, 218, 224, 226**
MATERIAL QUANTITY: **9750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Rooms 116, 118, 120 & 122 have different Material. New HA Assigned**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **12x12 Tan w/Black Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 109, 113, 116, 118, 120, 122, 211, 213, 121, 216, 218, 224, 226**
MATERIAL QUANTITY: **9750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15C**
MATERIAL DESCRIPTION: **12x12 White w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Basement Passage, Teachers' Lunchroom, Kitchen Lunchroom, Modular Classroom, Book Store Room**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **15C**
MATERIAL DESCRIPTION: **12x12 White w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Basement Passage, Teachers' Lunchroom, Kitchen Lunchroom, Modular Classroom, Book Store Room**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15D**
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Buildings**
MATERIAL QUANTITY: **6048** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **15D**
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile Mastic**
MATERIAL LOCATION: **Modular Buildings**
MATERIAL QUANTITY: **6048** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **Gray Swirl Multicolor Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **Gray Swirl Multicolor Linoleum Mastic**
MATERIAL LOCATION: **Room 200**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21A**
MATERIAL DESCRIPTION: **Brown Baseboard (some painted Yellow)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114, 118, 120, 122, Restroom, Teachers' Lounge, 116**
MATERIAL QUANTITY: **1370** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **21A**
MATERIAL DESCRIPTION: **Brown Baseboard (some painted Yellow)**
MATERIAL LOCATION: **Rooms 114, 118, 120, 122, Restroom, Teachers' Lounge, 116**
MATERIAL QUANTITY: **1370** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21B**
MATERIAL DESCRIPTION: **Green Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building- Room 220**
MATERIAL QUANTITY: **119** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **21B**
MATERIAL DESCRIPTION: **Green Baseboard**
MATERIAL LOCATION: **1958 Building- Room 220**
MATERIAL QUANTITY: **119** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21C**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 109, 113, 122, 201 & 220**
MATERIAL QUANTITY: **419** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **21C**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Rooms 109, 113, 122, 201 & 220**
MATERIAL QUANTITY: **419** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21D**
MATERIAL DESCRIPTION: **Cream Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Buildings**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **21D**
MATERIAL DESCRIPTION: **Cream Baseboard**
MATERIAL LOCATION: **Modular Buildings**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21E**
MATERIAL DESCRIPTION: **Light Brown Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement, Lunchroom, Kitchen**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **21E**
MATERIAL DESCRIPTION: **Light Brown Baseboard**
MATERIAL LOCATION: **Basement, Lunchroom, Kitchen**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22A**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114, 116, 118, 120, 122, Restroom & Teachers' Lounge**
MATERIAL QUANTITY: **1370** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **22A**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
MATERIAL LOCATION: **Rooms 114, 116, 118, 120, 122, Restroom & Teachers' Lounge**
MATERIAL QUANTITY: **1370** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22B**
MATERIAL DESCRIPTION: **Green Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 220**
MATERIAL QUANTITY: **119** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **22B**
MATERIAL DESCRIPTION: **Green Baseboard Mastic**
MATERIAL LOCATION: **Room 220**
MATERIAL QUANTITY: **119** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22C**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 109, 113, 122 & 201**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **22C**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Rooms 109, 113, 122 & 201**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22D**
MATERIAL DESCRIPTION: **Cream Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Modular Buildings**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **22D**
MATERIAL DESCRIPTION: **Cream Baseboard Mastic**
MATERIAL LOCATION: **Modular Buildings**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22E**
MATERIAL DESCRIPTION: **Light Brown Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement, Lunchroom, Kitchen**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **22E**
MATERIAL DESCRIPTION: **Light Brown Baseboard Mastic**
MATERIAL LOCATION: **Basement, Lunchroom, Kitchen**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Mag Block Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room- Boiler**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Mag Block Insulation ABATED**

MATERIAL LOCATION: **Boiler Room- Boiler**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building- Basement, 1st & 2nd Floors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature: 

Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**

MATERIAL LOCATION: **Original Building- Basement, 1st & 2nd Floors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1954 Building- Room 102 Closet**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **1954 Building- Room 102 Closet**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building- 112, 114 & 222**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **1958 Building- 112, 114 & 222**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-3**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office, Rooms 111, 209, 212, 221, and Library**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **CM-3**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Principal's Office, Rooms 111, 209, 212, 221, and Library**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-4**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 220, Main Office**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **CM-4**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
MATERIAL LOCATION: **Room 220, Main Office**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cloth Wrap Aircell Duct Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Building- Crawlspace North and South Sections, South Wing, North & South Areas**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature: 

Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cloth Wrap Aircell Duct Insulation ABATED**
MATERIAL LOCATION: **1958 Building- Crawlspace North and South Sections, South Wing, North & South Areas**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Building- Basement, 1st & 2nd Floor**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**
MATERIAL LOCATION: **1958 Building- Basement, 1st & 2nd Floor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **12x12 Light Blue Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102, 114, 222**
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **12x12 Light Blue Tile**
MATERIAL LOCATION: **Room 102, 114, 222**
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112, 1st Floor Storage**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **FT-2**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**
MATERIAL LOCATION: **Room 112, 1st Floor Storage**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **12x12 Light Blue Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102, 114, 222**
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **12x12 Light Blue Tile Mastic**
MATERIAL LOCATION: **Room 102, 114, 222**
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-2**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112, 1st Floor Storage**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **FTM-2**
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Room 112, 1st Floor Storage**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fiberglass Fittings**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1954 Building- Basement**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fiberglass Fittings**
MATERIAL LOCATION: **1954 Building- Basement**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell MJP ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Basement, 1st & 2nd Floors, Boiler Room, Locker Room, Engineer's Office, Fan Rooms, Crawlspace, Air Tunnels**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Aircell MJP ABATED**

MATERIAL LOCATION: **Basement, 1st & 2nd Floors, Boiler Room, Locker Room, Engineer's Office, Fan Rooms, Crawlspace, Air Tunnels**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Breeching Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Boiler Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Breeching Insulation ABATED**

MATERIAL LOCATION: **Basement Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Building- Basement, 1st & 2nd Floors, Fan Rooms, Crawlspace, South Wing Air Tunnels**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature: 

Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**
MATERIAL LOCATION: **1958 Building- Basement, 1st & 2nd Floors, Fan Rooms, Crawlspace, South Wing Air Tunnels**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1958 Building- Basement, 1st & 2nd Floors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**
MATERIAL LOCATION: **1958 Building- Basement, 1st & 2nd Floors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Fiberglass Fittings & Runs ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st & 2nd Floor Boys' & Girls' Toilet, Fan Room***

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Fiberglass Fittings & Runs ABATED**
MATERIAL LOCATION: **1st & 2nd Floor Boys' & Girls' Toilet, Fan Room***
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Cementitious Pipe Insulation (Mag) ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, 1st & 2nd Floors**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated 2022**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Cementitious Pipe Insulation (Mag) ABATED**
MATERIAL LOCATION: **Basement, 1st & 2nd Floors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Transite Type Boards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Ramps of Modular Classrooms**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Transite Type Boards**
MATERIAL LOCATION: **Ramps of Modular Classrooms**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Dawes School** INSPECTION DATE: **8/17/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Brown Carpet Square Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUIDLING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Brown Carpet Square Mastic**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/21/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22901** BUILDING ID: **2980**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Dawes School** REVIEW DATE: **9/21/2022**
ADDRESS: **3810 W. 81st St.** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/21/2022**

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MALLORY JONES
 524 HOMELAND ROAD
 MATTESON, IL 60443

3/16/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11070

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS SUPERVISOR/WORKER INSPECTOR		TC EXPIRES 6/5/2022 3/9/2023
ID NUMBER 100 - 11070	ISSUED 3/16/2022	EXPIRES 05/15/2023				
MALLORY JONES 524 HOMELAND ROAD MATTESON, IL 60443 Environmental Health						
				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	6/5/2022	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.						

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MALLORY JONES
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/09/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/09/2022

Course Dates:

03/09/2023

Expires:

2203BIR06

Certificate Number:

PHS Environmental &
Occupational Services


37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com



Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/19/2022
MANAGEMENT PLANNER	11/19/2022
PROJECT MANAGER	11/1/2022
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645

Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed