

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2166  
SCHOOL NAME: Doolittle East  
ADDRESS OF SCHOOL: 535 E. 35th Street  
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/10/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**


---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 11/2/2022 ENROLLMENT 267  
IDPH INSPECTOR LICENSE NUMBER: 100-19554  
IDPH LICENSED INSPECTOR NAME (Please Print): Carol Ashman  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



11/17/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Doolittle East**

535 E. 35th Street  
Chicago, IL, 60616

Unit: 22991  
Building ID: 3070

IDPH ID Number: 14-016-2990-2166

**REPORT DATE:**

Thursday, November 17, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

11/17/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 66442                      Region: 04                      IDPH ID: 14-016-2990-2166

School: Doolittle East                      Building ID: 3070

Address: 535 E. 35th Street  
Chicago, IL, 60616

Building Contact:                      Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 11/2/2022

Review Date: 11/17/2022

Inspector: Carol Ashman                      Inspector IDPH License: 100-19554  
Management Planner: Evan Christian                      Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: November 17, 2022

RE: Doolittle East, Unit 22991  
535 E. 35th Street  
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Doolittle East , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Doolittle East, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Doolittle East Unit: 66442 Region: 04  
Address: 535 E. 35th Street Chicago, IL, 60616  
IDPH ID: 14-016-2990-2166 Building ID: 3070  
Contact: Phone:

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: No of Floors:  
Current Occupancy: 267

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Carol Ashman


Inspector IDPH license # 100-19554  
Reinspection Date: 11/2/2022

Signature:  
Date: 11/2/2022

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature:   
Date: 11/17/2022

### 7. Review Date: 11/17/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 11/17/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Doolittle East. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3070:

1	Plaster
26	Blue patterned carpet mastic
3	12" x 12" Gray Floor Tile w/Multi-Color Streaks
41	12" x 12" Tan Mottle Floor Tile over existing HA 13/14
49	Wood laminate
50	12" x 12" Beige Floor Tile
51	12" x 12 Beige Floor Tile Mastic
52	12" x 12" Yellow Floor Tile
53	12" x 12" Yellow Floor Tile Mastic

54	12" x 12" Light Beige Floor Tile
55	12" x 12" Light Beige Floor Tile Mastic
56	12" x 12 " Tan Floor Tile
57	12" x 12 " Tan Floor Tile Mastic
58	12" x 12" Black Floor Tile
59	12" x 12" Black Floor Tile Mastic
60	12" x 12" Light Green Floor Tile
61	12" x 12" Light Green Floor Tile Mastic
62	12" x 12" Orange Floor Tile
63	12" x 12" Orange Floor Tile Mastic
64	12" x 12" Light Blue Floor Tile
65	12" x 12" Light Blue Floor Tile Mastic
G	Air cell pipe insulation



B. The following new homogenous areas have been identified for Building 3070:

49	Wood laminate
50	12" x 12" Beige Floor Tile
51	12" x 12 Beige Floor Tile Mastic
52	12" x 12" Yellow Floor Tile
53	12" x 12" Yellow Floor Tile Mastic
54	12" x 12" Light Beige Floor Tile
55	12" x 12" Light Beige Floor Tile Mastic
56	12" x 12 " Tan Floor Tile
57	12" x 12 " Tan Floor Tile Mastic
58	12" x 12" Black Floor Tile
59	12" x 12" Black Floor Tile Mastic
60	12" x 12" Light Green Floor Tile
61	12" x 12" Light Green Floor Tile Mastic
62	12" x 12" Orange Floor Tile
63	12" x 12" Orange Floor Tile Mastic
64	12" x 12" Light Blue Floor Tile
65	12" x 12" Light Blue Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	Plaster
20	Brown carpet mastic
21	Gray carpet mastic
23	Brown mix carpet
25	Orange carpet mastic
26	Blue patterned carpet mastic
27	Vault door liner
36	Free standing lab tables - Non-AHERA
37	12" x 12" Gray w/White & Black Specks Floor Tile
38	12" x 12" Gray w/White & Black Specks Floor Tile Mastic
39	Red carpet mastic
40	Blue/gray/whitet multi color ceramic floor tile grout
41	12" x 12" Tan Mottle Floor Tile over existing HA 13/14
42	Mastic for 12" x 12" tan Floor Tile
43	12" x 12" Black w/ White Specks Floor Tile
44	Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile
45	12" x 12" Tan w/ White Specks Floor Tile
46	Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile
47	12" x 12" Cream w/ White Specks Floor Tile
48	Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile
49	Wood laminate
50	12" x 12" Beige Floor Tile
51	12" x 12 Beige Floor Tile Mastic
52	12" x 12" Yellow Floor Tile
53	12" x 12" Yellow Floor Tile Mastic
54	12" x 12" Light Beige Floor Tile
55	12" x 12" Light Beige Floor Tile Mastic
56	12" x 12 " Tan Floor Tile
57	12" x 12 " Tan Floor Tile Mastic
58	12" x 12" Black Floor Tile
59	12" x 12" Black Floor Tile Mastic
60	12" x 12" Light Green Floor Tile
61	12" x 12" Light Green Floor Tile Mastic
62	12" x 12" Orange Floor Tile
63	12" x 12" Orange Floor Tile Mastic
64	12" x 12" Light Blue Floor Tile
65	12" x 12" Light Blue Floor Tile Mastic

AA	12" x 12" Floor tile tan w/ Green Specks
AA-1	12" x 12" Floor tile tan w/ Green Specks Mastic
AB	Baseboard
AB-1	Baseboard mastic
AC	Carpet mastic
AD	Terrazo flooring
AE	12" x 12" Floor tile tan/Green
AE-1	12" x 12" Floor Tile Tan/Green Mastic
AF	Gerth flooring mastic
AG	Drywall
AH	Fire doors
AI	Window caulk

The following areas were deemed to be inaccessible:

11	12" x 12" Dark Brown Floor Tile Mastic
20	Brown carpet mastic
26	Blue patterned carpet mastic
39	Red carpet mastic
42	Mastic for 12" x 12" tan Floor Tile
46	Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile
48	Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile
9	12" x 12" Gray Floor Tile w/Multi-Color Streaks Mastic
AB-1	Baseboard mastic
AC	Carpet mastic
AE-1	12" x 12" Floor Tile Tan/Green Mastic
AI	Window caulk

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Carol Ashman, IDPH License # 100-19554. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Doolittle East Building 3070 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---



# Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
33	12" x 12" White Floor Tile w/Gray Specks Mastic			Rooms 112, 310, 316, 110 - ABATED	ABATED	MISC								
34	90 Degree Black Metal Baseboard			Large Gym	NOT_TESTED	MISC								
35	90 Degree Black Metal Base			Large Gym	NOT_TESTED	MISC								
36	Free standing lab tables - Non-AHERA			Room 317 - Removed	ASSUMED	MISC								
37	12" x 12" Gray w/White & Black Specks Floor Tile	750	SF	Rooms 309	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
38	12" x 12" Gray w/White & Black Specks Floor Tile Mastic			Room 309	ASSUMED	MISC								
39	Red carpet mastic	2,250	SF	Main Office and Principal's Office and Room 106	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
4	9" x 9" Multi-Colored Floor Tile			Room 110 - ABATED	ABATED	MISC								
40	Blue/gray/whitet multi color ceramic floor tile grout	4,050	SF	Boys' and Girls' Bathrooms on 1st, 2nd,3rd Floors and Basement	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
41	12" x 12" Tan Mottle Floor Tile over existing HA 13/14	500	SF	Engineer's office	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with potential for significant damage	4	LOW
42	Mastic for 12" x 12" tan Floor Tile	500	SF	Engineer's office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
43	12" x 12" Black w/ White Specks Floor Tile		SF	Room 306	ASSUMED	MISC				SF				
44	Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile		SF	Room 306	ASSUMED	MISC				SF				
45	12" x 12" Tan w/ White Specks Floor Tile	3,422	SF	Rooms 200 and 310 Pre-K Cafeteria	ASSUMED	MISC	N	LOC	5	SF	No	ACBM with the potential for damage	5	LOW
46	Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile	3,422	SF	Rooms 200 and 310, Pre-K Cafeteria	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
47	12" x 12" Cream w/ White Specks Floor Tile	1,140	SF	Dance Hall/Small Gym	ASSUMED	MISC	N	LOC	10	SF	No	ACBM with the potential for damage	5	LOW
48	Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile	1,140	SF	Dance Hall/Small Gym	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
49	Wood laminate	3,000	SF	Rooms 301, 303, 302, 305, 312, 316, main office	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
50	12" x 12" Beige Floor Tile	900	SF	Room 100	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with potential for significant damage	4	HIGH
51	12" x 12 Beige Floor Tile Mastic	900	SF	Room 100	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with potential for significant damage	4	HIGH

# Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
52	12" x 12" Yellow Floor Tile	5,400	SF	Rooms 110, 116, 118, 218, 216, 212	ASSUMED	MISC	N	DIST	15	SF	Yes	ACBM with potential for significant damage	4	HIGH
53	12" x 12" Yellow Floor Tile Mastic	5,400	SF	Rooms 110, 116, 118, 218, 216, 212	ASSUMED	MISC	N	DIST	15	SF	Yes	ACBM with potential for significant damage	4	HIGH
54	12" x 12" Light Beige Floor Tile	4,500	SF	Rooms 310, 319, elevator hallway, 317, 318, 319, 200, 210	ASSUMED	MISC	N	DIST	6	SF	Yes	ACBM with potential for significant damage	4	HIGH
55	12" x 12" Light Beige Floor Tile Mastic	4,500	SF	Rooms 310, 319, elevator hallway, 317, 318, 319, 200, 210	ASSUMED	MISC	N	DIST	6	SF	Yes	ACBM with potential for significant damage	4	HIGH
56	12" x 12" Tan Floor Tile	600	SF	Dance room, gym	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		HIGH
57	12" x 12" Tan Floor Tile Mastic	600	SF	Dance room, gym	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		HIGH
58	12" x 12" Black Floor Tile	900	SF	Room 306	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
59	12" x 12" Black Floor Tile Mastic	900	SF	Room 306	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
60	12" x 12" Light Green Floor Tile	100	SF	Rooms 310, 317, 216, 218, 118, elevator hallway	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
61	12" x 12" Light Green Floor Tile Mastic	100	SF	Rooms 310, 317, 216, 218, 118, elevator hallway	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
62	12" x 12" Orange Floor Tile	60	SF	Elevator hallway on each floor	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
63	12" x 12" Orange Floor Tile Mastic	60	SF	Elevator hallway on each floor	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
64	12" x 12" Light Blue Floor Tile	20	SF	2nd floor elevator area	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
65	12" x 12" Light Blue Floor Tile Mastic	20	SF	2nd floor elevator area	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with potential for significant damage		LOW
7	12" x 12" Dark Brown Floor Tile	2,250	SF	First, Second & Third Floor Corridors	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
8	9" x 9" Tan Floor Tile - ABATED 1			Lunchroom & Small Gym	ABATED	MISC								
9	12" x 12" Gray Floor Tile w/Multi-Color Streaks Mastic	29,000	SF	See HA 3 - Abated	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
A	Insulation Jacketing & Wrap on Water Tank			Boiler Room	NO_ACBM	MISC								
AA	12" x 12" Floor tile tan w/ Green Specks		SF	Room 312	ASSUMED	MISC				SF				







# Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>11/2/2022</b>
Inspector Name <b>Carol Ashman</b>
<b>100-19554</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
1	Damaged room 212 (on wall), assembly hall (wall) , 318(ceiling)
10	
11	
12	
13	Not observed 2022
14	Not observed 2022
15	
16	
17	
18	
2	
20	
21	Not observed - Replaced with red carpet 2022
22	Not observed 2022
23	Not observed 2022
24	
25	Not observed 2022
26	Damaged in main office
27	Not observed 2022
28	
29	
3	Damage in 205
30	
31	

# Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
32	
33	
34	Not Suspect
35	Not Suspect
36	
37	
38	Not observed 2022 - Same as HA 3
39	
4	
40	
41	Damaged in engineer's office
42	
43	Not observed 2022
44	Not observed 2022
45	Damage in Room 310
46	
47	Damage located in small gym
48	
49	
50	Damage in Room 100
51	Damage in Room 100
52	Damaged in 216, 212, 218 , 116,110
53	Damaged in 216, 212, 218 , 116,110
54	Damage in rooms 310, 319
55	Damage in rooms 310, 319
56	
57	
58	
59	

# Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
60	
61	
62	
63	
64	
65	
7	
8	
9	
A	
AA	Not observed 2022
AA-1	Not observed 2022
AB	
AB-1	
AC	
AD	
AE	
AE-1	
AF	Not observed 2022
AG	
AH	
AI	
B	
F	
G	Damaged in boiler room
L	
M	
N	

# Chicago Public Schools

**School** Doolittle East **Unit** 66442 **Building ID** 3070

**Address** 535 E. 35th Street **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Doolittle East  
**Address** 535 E. 35th Street

**Unit** 66442  
Chicago, IL, 60616

**Building ID** 3070  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Plaster	60,000	SF	Throughout Facility	Assumed	SURFACE	Yes	65	SF	2 Damaged friable surfacing ACBM	Encapsulate
10	9" x 9" Multi-Colored Floor Tile Mastic			Room 110 - ABATED	Abated	MISC					
11	12" x 12" Dark Brown Floor Tile Mastic	2,250	SF	First, Second & Third Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9" x 9" Tan Floor Tile Mastic - ABATED			Lunchroom & Small Gym	Abated	MISC					
13	9" x 9" Wine Colored Floor Tile		SF	Engineer's Office	Chrysotile	MISC			SF		Follow O&M Plan
14	9" x 9" Wine Colored Floor Tile Mastic			Engineer's Office	No ACBM	MISC					
15	Red floor tile - abated 1999			Lunchroom	Abated	MISC					
16	Red floor tile mastic - abated 1999			Lunchroom	Abated	MISC					
17	Brick Mortar - Non-AHERA			Exterior of Building	No ACBM	MISC					
18	Window sash caulking	22	LF	1928 and 1944 Additions	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
2	2' x 4' (Off) White Ceiling Panels			Office	No ACBM	MISC					
20	Brown carpet mastic	450	SF	Rooms 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Gray carpet mastic			Room 106	Assumed	MISC					Follow O&M Plan
22	Green patterned carpet mastic - abated			Library	Abated	MISC					
23	Brown mix carpet			Office	Assumed	MISC					Follow O&M Plan
24	Purple carpet mastic - abated			Auditorium	Abated	MISC					
25	Orange carpet mastic			Rooms B-1 & B-2	Assumed	MISC					Follow O&M Plan
26	Blue patterned carpet mastic	1,800	SF	Principal's Office, library, Main office	Assumed	MISC	No	10	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
27	Vault door liner		SF	Office	Assumed	TSI			SF		Follow O&M Plan
28	12" x 12" White Floor Tile w/Blue Specks			Lunchroom & Small Gym - ABATED	Abated	MISC					
29	12" x 12" White Floor Tile w/Blue Specks Mastic			Lunchroom & Small Gym - ABATED	Abated	MISC					
3	12" x 12" Gray Floor Tile w/Multi-Color Streaks	29,000	SF	Corridors, rooms B19,100-103,105,107,109,112, 116,201, 203, 202, 205, 204, 206, 207,209,300, 304, 307,309	Chrysotile	MISC	No	1	SF	5 ACBM with potential for significant damage	Repair
30	4" Black vinyl baseboard - abated 2006			Lunchroom	Abated	MISC					
31	4" Black vinyl baseboard adhesive - abated			Lunchroom	Abated	MISC					
32	12" x 12" White Floor Tile w/ Gray Specks			Rooms 112, 310, 316, 110 - ABATED	Abated	MISC					
33	12" x 12" White Floor Tile w/Gray Specks Mastic			Rooms 112, 310, 316, 110 - ABATED	Abated	MISC					
34	90 Degree Black Metal Baseboard			Large Gym	Not Tested	MISC					Follow O&M Plan
35	90 Degree Black Metal Base			Large Gym	Not Tested	MISC					Follow O&M Plan
36	Free standing lab tables - Non-AHERA			Room 317 - Removed	Assumed	MISC					Follow O&M Plan
37	12" x 12" Gray w/White & Black Specks Floor Tile	750	SF	Rooms 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12" x 12" Gray w/White & Black Specks Floor Tile			Room 309	Assumed	MISC					Follow O&M Plan



# Chicago Public Schools

School Doolittle East  
Address 535 E. 35th Street

Unit 66442  
Chicago, IL, 60616

Building ID 3070  
Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic										
39	Red carpet mastic	2,250	SF	Main Office and Principal's Office and Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	9" x 9" Multi-Colored Floor Tile			Room 110 - ABATED	Abated	MISC					
40	Blue/gray/whitet multi color ceramic floor tile grout	4,050	SF	Boys' and Girls' Bathrooms on 1st,2nd, 3rd Floors and Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12" x 12" Tan Mottle Floor Tile over existing HA 13/14	500	SF	Engineer's office	Assumed	MISC	No	3	SF	5 ACBM with potential for significant damage	Repair
42	Mastic for 12" x 12" tan Floor Tile	500	SF	Engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" x 12" Black w/ White Specks Floor Tile		SF	Room 306	Assumed	MISC			SF		Follow O&M Plan
44	Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile		SF	Room 306	Assumed	MISC			SF		Follow O&M Plan
45	12" x 12" Tan w/ White Specks Floor Tile	3,422	SF	Rooms 200 and 310 Pre-K Cafeteria	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Remove
46	Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile	3,422	SF	Rooms 200 and 310, Pre-K Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Cream w/ White Specks Floor Tile	1,140	SF	Dance Hall/Small Gym	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Remove
48	Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile	1,140	SF	Dance Hall/Small Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Wood laminate	3,000	SF	Rooms 301, 303, 302, 305, 312, 316, main office	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
50	12" x 12" Beige Floor Tile	900	SF	Room 100	Assumed	MISC	No	3	SF	5 ACBM with potential for significant damage	Repair
51	12" x 12 Beige Floor Tile Mastic	900	SF	Room 100	Assumed	MISC	No	3	SF	5 ACBM with potential for significant damage	Repair
52	12" x 12" Yellow Floor Tile	5,400	SF	Rooms 110, 116, 118, 218,216, 212	Assumed	MISC	No	15	SF	5 ACBM with potential for significant damage	Repair
53	12" x 12" Yellow Floor Tile Mastic	5,400	SF	Rooms 110, 116, 118, 218,216, 212	Assumed	MISC	No	15	SF	5 ACBM with potential for significant damage	Repair
54	12" x 12" Light Beige Floor Tile	4,500	SF	Rooms 310, 319, elevator hallway, 317, 318, 319, 200, 210	Assumed	MISC	No	6	SF	5 ACBM with potential for significant damage	Repair
55	12" x 12" Light Beige Floor Tile Mastic	4,500	SF	Rooms 310, 319, elevator hallway, 317, 318, 319, 200, 210	Assumed	MISC	No	6	SF	5 ACBM with potential for significant damage	Repair
56	12" x 12 " Tan Floor Tile	600	SF	Dance room, gym	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
57	12" x 12 " Tan Floor Tile Mastic	600	SF	Dance room, gym	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan

# Chicago Public Schools

School Doolittle East  
Address 535 E. 35th Street

Unit 66442  
Chicago, IL, 60616

Building ID 3070  
Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
58	12" x 12" Black Floor Tile	900	SF	Room 306	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
59	12" x 12" Black Floor Tile Mastic	900	SF	Room 306	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
60	12" x 12" Light Green Floor Tile	100	SF	Rooms 310, 317, 216, 218, 118, elevator hallway	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
61	12" x 12" Light Green Floor Tile Mastic	100	SF	Rooms 310, 317, 216, 218, 118, elevator hallway	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
62	12" x 12" Orange Floor Tile	60	SF	Elevator hallway on each floor	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
63	12" x 12" Orange Floor Tile Mastic	60	SF	Elevator hallway on each floor	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
64	12" x 12" Light Blue Floor Tile	20	SF	2nd floor elevator area	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
65	12" x 12" Light Blue Floor Tile Mastic	20	SF	2nd floor elevator area	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
7	12" x 12" Dark Brown Floor Tile	2,250	SF	First, Second & Third Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	9" x 9" Tan Floor Tile - ABATED 1			Lunchroom & Small Gym	Abated	MISC					
9	12" x 12" Gray Floor Tile w/Multi-Color Streaks Mastic	29,000	SF	See HA 3 - Abated	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Insulation Jacketing & Wrap on Water Tank			Boiler Room	No ACBM	MISC					
AA	12" x 12" Floor tile tan w/ Green Specks		SF	Room 312	Assumed	MISC			SF		Follow O&M Plan
AA-1	12" x 12" Floor tile tan w/ Green Specks Mastic		SF	Lunchroom, Room 112,116,118,210,212,216,218,301, 310, 312,317-319	Assumed	MISC			SF		Follow O&M Plan
AB	Baseboard	300	LF	Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
AB-1	Baseboard mastic	300	LF	Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
AC	Carpet mastic	3,200	SF	Library, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AD	Terrazzo flooring	1,500	SF	Elevator, Ground Floor, middle corridor on all floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AE	12" x 12" Floor tile tan/Green	1,300	SF	Elevator Area, 1st - 3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AE-1	12" x 12" Floor Tile Tan/Green Mastic	1,300	SF	Elevator, 1st-3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AF	Gerth flooring mastic		SF	Rooms 205, 302, 303, 305, 310, 316	Assumed	MISC			SF		Follow O&M Plan
AG	Drywall	2,100	SF	Elevator Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AH	Fire doors	8	EA	Elevator Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
AI	Window caulk	15,000	LF	Elevator Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Doolittle East  
**Address** 535 E. 35th Street

**Unit** 66442  
 Chicago, IL, 60616

**Building ID** 3070  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
B	Insulation Jacketing & Wrap on Water Tank			Boiler Room	No ACBM	MISC					
F	Cementitious Insulation on Small Joints	100	LF	Wet Walls in Boy's Bathrooms, Boiler Room, Janitor's Closets, Classroom 209	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Air cell pipe insulation	350	LF	Bathrooms, Boiler Room, Auditorium, Room 209	Chrysotile	TSI	Yes	5	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Encapsulate
L	Cementitious joint insulation- large gray fittings	48	LF	Boiler Room, Janitor Closet, Basement	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
M	Gray mud packing	10	SF	Engineer's Bathroom- Surrounding Duct	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Cementitious valve insulation- large gray fittings			Boiler Room - ABATED 1999	Abated	MISC					

# Chicago Public Schools

**School** Doolittle East  
**Address** 535 E. 35th Street

**Unit** 66442  
 Chicago, IL, 60616

**Building ID** 3070  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	11/17/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	

# Chicago Public Schools

**School** Doolittle East  
**Address** 535 E. 35th Street

**Unit** 66442  
 Chicago, IL, 60616

**Building ID** 3070  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	Sample to Determine ACM Content
46	
47	Sample to determine ACM Content
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	

# Chicago Public Schools

**School** Doolittle East  
**Address** 535 E. 35th Street

**Unit** 66442  
 Chicago, IL, 60616

**Building ID** 3070  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
58	
59	
60	
61	
62	
63	
64	
65	
7	
8	
9	
A	
AA	
AA-1	
AB	
AB-1	
AC	
AD	
AE	
AE-1	
AF	
AG	
AH	
AI	
B	
F	
G	

# Chicago Public Schools

**School** Doolittle East  
**Address** 535 E. 35th Street

**Unit** 66442  
Chicago, IL, 60616

**Building ID** 3070  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
L	
M	
N	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---



# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2022 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **2 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **2. Damaged friable surfacing ACBM**

DAMAGE REASON: **Other**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damaged room 212 (on wall), assembly hall (wall) , 318(ceiling)**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **65** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9" x 9" Multi-Colored Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 110 - ABATED**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9" x 9" Multi-Colored Floor Tile Mastic**

MATERIAL LOCATION: **Room 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First, Second & Third Floor Corridors**

MATERIAL QUANTITY: **2250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile Mastic**  
MATERIAL LOCATION: **First, Second & Third Floor Corridors**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom & Small Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **Lunchroom & Small Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9" x 9" Wine Colored Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9" x 9" Wine Colored Floor Tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9" x 9" Wine Colored Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **9" x 9" Wine Colored Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Red floor tile - abated 1999**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **11/02/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Red floor tile - abated 1999**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Red floor tile mastic - abated 1999**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Red floor tile mastic - abated 1999**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Brick Mortar - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Window sash caulking**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1928 and 1944 Additions**  
MATERIAL QUANTITY: **22**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Window sash caulking**

MATERIAL LOCATION: **1928 and 1944 Additions**

MATERIAL QUANTITY: **22**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **2' x 4' (Off) White Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **2' x 4' (Off) White Ceiling Panels**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Brown carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 104**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Brown carpet mastic**  
MATERIAL LOCATION: **Rooms 104**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Gray carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed - Replaced with red carpet 2022**

Inspector's Signature: \_\_\_\_\_ Date: **11/02/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Gray carpet mastic**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Green patterned carpet mastic - abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: **11/02/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Green patterned carpet mastic - abated**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Brown mix carpet**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Brown mix carpet**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Purple carpet mastic - abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Purple carpet mastic - abated**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Orange carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms B-1 & B-2**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Orange carpet mastic**

MATERIAL LOCATION: **Rooms B-1 & B-2**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Blue patterned carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Other**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office, library, Main office**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damaged in main office**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Blue patterned carpet mastic**  
MATERIAL LOCATION: **Principal's Office, library, Main office**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Vault door liner**  
HISTORICAL AHERA DAMAGE CATEGORY: **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Vault door liner**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Blue Specks**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom & Small Gym - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Blue Specks**

MATERIAL LOCATION: **Lunchroom & Small Gym - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Blue Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom & Small Gym - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Blue Specks Mastic**

MATERIAL LOCATION: **Lunchroom & Small Gym - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Multi-Color Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Other**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors, rooms B19,100-103,105,107,109,112, 116,201, 203 202, 205, 204, 206, 207,209,300, 304, 307,309**  
MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in 205**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Multi-Color Streaks**  
MATERIAL LOCATION: **Corridors, rooms B19,100-103,105,107,109,112, 116,201, 203 202, 205, 204, 206, 207,209,300, 304, 307,309**  
MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **4" Black vinyl baseboard - abated 2006**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **4" Black vinyl baseboard - abated 2006**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **4" Black vinyl baseboard adhesive - abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **4" Black vinyl baseboard adhesive - abated**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Specks**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112, 310, 316, 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Specks**

MATERIAL LOCATION: **Rooms 112, 310, 316, 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112, 310, 316, 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Specks Mastic**

MATERIAL LOCATION: **Rooms 112, 310, 316, 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **90 Degree Black Metal Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Large Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Suspect**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **90 Degree Black Metal Baseboard**

MATERIAL LOCATION: **Large Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **90 Degree Black Metal Base**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Large Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Suspect**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **90 Degree Black Metal Base**

MATERIAL LOCATION: **Large Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Free standing lab tables - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 317 - Removed**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Free standing lab tables - Non-AHERA**

MATERIAL LOCATION: **Room 317 - Removed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/White & Black Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 309**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12" x 12" Gray w/White & Black Specks Floor Tile**

MATERIAL LOCATION: **Rooms 309**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/White & Black Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022 - Same as HA 3**

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12" x 12" Gray w/White & Black Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Red carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office and Principal's Office and Room 106**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Red carpet mastic**  
MATERIAL LOCATION: **Main Office and Principal's Office and Room 106**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **9" x 9" Multi-Colored Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **9" x 9" Multi-Colored Floor Tile**

MATERIAL LOCATION: **Room 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Blue/gray/whitet multi color ceramic floor tile grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boys' and Girls' Bathrooms on 1st,2nd,3rd Floors and Basement**  
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Blue/gray/whitet multi color ceramic floor tile grout**  
MATERIAL LOCATION: **Boys' and Girls' Bathrooms on 1st,2nd,3rd Floors and Basement**  
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" x 12" Tan Mottle Floor Tile over existing HA 13/14**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Other**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's office**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damaged in engineer's office**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" x 12" Tan Mottle Floor Tile over existing HA 13/14**  
MATERIAL LOCATION: **Engineer's office**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" tan Floor Tile**  
MATERIAL LOCATION: **Engineer's office**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 306**

MATERIAL QUANTITY:    MATERIAL UNITS: **SF**

DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" x 12" Black w/ White Specks Floor Tile**

MATERIAL LOCATION: **Room 306**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 306**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile**

MATERIAL LOCATION: **Room 306**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 200 and 310 Pre-K Cafeteria**  
MATERIAL QUANTITY: **3422** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Room 310**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ White Specks Floor Tile**  
MATERIAL LOCATION: **Rooms 200 and 310 Pre-K Cafeteria**  
MATERIAL QUANTITY: **3422** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Sample to Determine ACM Content

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 200 and 310, Pre-K Cafeteria**

MATERIAL QUANTITY: **3422**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile**  
MATERIAL LOCATION: **Rooms 200 and 310, Pre-K Cafeteria**  
MATERIAL QUANTITY: **3422** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Cream w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Dance Hall/Small Gym**  
MATERIAL QUANTITY: **1140** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage located in small gym**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **12" x 12" Cream w/ White Specks Floor Tile**

MATERIAL LOCATION: **Dance Hall/Small Gym**

MATERIAL QUANTITY: **1140**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Sample to determine ACM Content

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Dance Hall/Small Gym**

MATERIAL QUANTITY: **1140**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile**  
MATERIAL LOCATION: **Dance Hall/Small Gym**  
MATERIAL QUANTITY: **1140** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First, Second & Third Floor Corridors**

MATERIAL QUANTITY: **2250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile**  
MATERIAL LOCATION: **First, Second & Third Floor Corridors**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile - ABATED 1**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom & Small Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile - ABATED 1**

MATERIAL LOCATION: **Lunchroom & Small Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Multi-Color Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **See HA 3 - Abated**  
MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Multi-Color Streaks Mastic**  
MATERIAL LOCATION: **See HA 3 - Abated**  
MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Insulation Jacketing & Wrap on Water Tank**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Insulation Jacketing & Wrap on Water Tank**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **12" x 12" Floor tile tan w/ Green Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 312**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AA**

MATERIAL DESCRIPTION: **12" x 12" Floor tile tan w/ Green Specks**

MATERIAL LOCATION: **Room 312**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA-1**  
MATERIAL DESCRIPTION: **12" x 12" Floor tile tan w/ Green Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Room 112,116,118,210,212,216,218,301, 310, 312,317-319**

MATERIAL QUANTITY:    MATERIAL UNITS: **SF**

DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AA-1**  
MATERIAL DESCRIPTION: **12" x 12" Floor tile tan w/ Green Specks Mastic**  
MATERIAL LOCATION: **Lunchroom, Room 112,116,118,210,212,216,218,301, 310, 312,317-319**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AB**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AB**  
MATERIAL DESCRIPTION: **Baseboard**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AB-1**  
MATERIAL DESCRIPTION: **Baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AB-1**

MATERIAL DESCRIPTION: **Baseboard mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AC**  
MATERIAL DESCRIPTION: **Carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library, Auditorium**  
MATERIAL QUANTITY: **3200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AC**  
MATERIAL DESCRIPTION: **Carpet mastic**  
MATERIAL LOCATION: **Library, Auditorium**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AD**  
MATERIAL DESCRIPTION: **Terrazo flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator, Ground Floor, middle corridor on all floors**  
MATERIAL QUANTITY: **1500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AD**  
MATERIAL DESCRIPTION: **Terrazo flooring**  
MATERIAL LOCATION: **Elevator, Ground Floor, middle corridor on all floors**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AE**  
MATERIAL DESCRIPTION: **12" x 12" Floor tile tan/Green**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Elevator Area, 1st - 3rd Floor**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AE**  
MATERIAL DESCRIPTION: **12" x 12" Floor tile tan/Green**  
MATERIAL LOCATION: **Elevator Area, 1st - 3rd Floor**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AE-1**  
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Tan/Green Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator, 1st-3rd Floor**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AE-1**  
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Tan/Green Mastic**  
MATERIAL LOCATION: **Elevator, 1st-3rd Floor**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AF**  
MATERIAL DESCRIPTION: **Gerth flooring mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 205, 302, 303, 305, 310, 316**

MATERIAL QUANTITY:    MATERIAL UNITS: **SF**

DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AF**

MATERIAL DESCRIPTION: **Gerth flooring mastic**

MATERIAL LOCATION: **Rooms 205, 302, 303, 305, 310, 316**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AG**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator Building**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AG**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Elevator Building**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AH**  
MATERIAL DESCRIPTION: **Fire doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Elevator Building**

MATERIAL QUANTITY: **8**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AH**  
MATERIAL DESCRIPTION: **Fire doors**  
MATERIAL LOCATION: **Elevator Building**  
MATERIAL QUANTITY: **8** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AI**  
MATERIAL DESCRIPTION: **Window caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator Building**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **AI**  
MATERIAL DESCRIPTION: **Window caulk**  
MATERIAL LOCATION: **Elevator Building**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Insulation Jacketing & Wrap on Water Tank**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Insulation Jacketing & Wrap on Water Tank**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Cementitious Insulation on Small Joints**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Wet Walls in Boy's Bathrooms, Boiler Room, Janitor's Closets, Classroom 209**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Cementitious Insulation on Small Joints**  
MATERIAL LOCATION: **Wet Walls in Boy's Bathrooms, Boiler Room, Janitor's Closets, Classroom 209**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Air cell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Other**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Bathrooms, Boiler Room, Auditorium, Room 209**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS: **Damaged in boiler room**

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Air cell pipe insulation**  
MATERIAL LOCATION: **Bathrooms, Boiler Room, Auditorium, Room 209**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Cementitious joint insulation- large gray fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler Room, Janitor Closet, Basement**

MATERIAL QUANTITY: **48** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Cementitious joint insulation- large gray fittings**  
MATERIAL LOCATION: **Boiler Room, Janitor Closet, Basement**  
MATERIAL QUANTITY: **48** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Gray mud packing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Bathroom- Surrounding Duct**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Gray mud packing**  
MATERIAL LOCATION: **Engineer's Bathroom- Surrounding Duct**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Cementitious valve insulation- large gray fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - ABATED 1999**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cementitious valve insulation- large gray fittings**

MATERIAL LOCATION: **Boiler Room - ABATED 1999**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**  
MATERIAL LOCATION: **Elevator hallway on each floor**  
MATERIAL QUANTITY: **60**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **11/17/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12" x 12 " Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Dance room, gym**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**  
MATERIAL LOCATION: **Rooms 110, 116, 118, 218,216, 212**  
MATERIAL QUANTITY: **5400**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **15**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022





# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12" x 12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **900**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12" x 12 " Tan Floor Tile**  
MATERIAL LOCATION: **Dance room, gym**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East** REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile**  
MATERIAL LOCATION: **2nd floor elevator area**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile**  
MATERIAL LOCATION: **Elevator hallway on each floor**  
MATERIAL QUANTITY: **60**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022





# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**  
MATERIAL LOCATION: **Room 306**  
MATERIAL QUANTITY: **900**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 310, 317, 216, 218, 118, elevator hallway**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 310, 317, 216, 218, 118, elevator hallway**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 110, 116, 118, 218,216, 212**  
MATERIAL QUANTITY: **5400**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **15**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Wood laminate**  
MATERIAL LOCATION: **Rooms 301, 303, 302, 305, 312, 316, main office**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Wood laminate**  
MATERIAL LOCATION: **Rooms 301, 303, 302, 305, 312, 316, main office**  
MATERIAL QUANTITY: **3000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 310, 319, elevator hallway, 317, 318, 319, 200, 210**  
MATERIAL QUANTITY: **4500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **HIGH**    CONDITION: **Damaged**  
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **6**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Damage in rooms 310, 319

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 310, 319, elevator hallway, 317, 318, 319, 200, 210**  
MATERIAL QUANTITY: **4500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **6**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige Floor Tile**  
MATERIAL LOCATION: **Rooms 310, 319, elevator hallway, 317, 318, 319, 200, 210**  
MATERIAL QUANTITY: **4500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **6**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile Mastic**  
MATERIAL LOCATION: **2nd floor elevator area**  
MATERIAL QUANTITY: **20**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **11/17/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66442**    BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Carol Ashman**  
SCHOOL NAME: **Doolittle East**    INSPECTION DATE: **11/2/2022**  
ADDRESS: **535 E. 35th Street**    IDPH LICENSE NO: **100-19554**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile**  
MATERIAL LOCATION: **Rooms 310, 317, 216, 218, 118, elevator hallway**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 11/02/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile**  
MATERIAL LOCATION: **Rooms 310, 317, 216, 218, 118, elevator hallway**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022





# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Room 100**

MATERIAL QUANTITY: **900**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **11/17/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66442**      BUILDING ID: **3070**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Doolittle East**      REVIEW DATE: **11/17/2022**  
ADDRESS: **535 E. 35th Street**      IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**  
MATERIAL LOCATION: **Room 306**  
MATERIAL QUANTITY: **900**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 11/17/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otsafety.com](http://www.otsafety.com)

2022

OCCUPATIONAL TRAINING & SUPPLY, INC.



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Carol Ashman**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 5/16/2022

Exam Date: 5/16/2022




Expiration Date: 5/16/2023

Certificate Number: BIR2205161413

  
Kathy Desalvo, Director

# Carol Ashman

Illinois Licensed Building Inspector

 ILLINOIS DEPARTMENT OF PUBLIC HEALTH <b>IDPH</b> INTEGRATING SCIENCE. EMPOWERING COMMUNITY.	<b>ASBESTOS PROFESSIONAL LICENSE</b>	
ID NUMBER 100 - 19554	ISSUED 4/19/2022	EXPIRES 05/15/2023
<b>CAROL L ASHMAN</b> 1633 Mc KAY ST WAUKEGAN, IL 60087 Environmental Health		

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/7/2022
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/28/2023

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519

  
Kathy DeSalvo, Director





# ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

**100 - 19466**

ISSUED

**4/22/2022**

EXPIRES

**05/15/2023**

**EVAN I CHRISTIAN**  
**1119 N HOYNE AVE, APT 1**  
**CHICAGO, IL 60622**

Environmental Health



## ENDORSEMENTS

## TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed