

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2618
SCHOOL NAME: Foster Park School Annex
ADDRESS OF SCHOOL: 1819 W 85th Street
CITY: Chicago, IL, 60620

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/6/2019

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 8/17/2022 ENROLLMENT 296
IDPH INSPECTOR LICENSE NUMBER: 100-19782
IDPH LICENSED INSPECTOR NAME (Please Print): Roxana Ordonez
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



9/10/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Foster Park School Annex

1819 W 85th Street
Chicago, IL, 60620

Unit: 23261
Building ID: 3430/Annex

IDPH ID Number: 14-016-2990-2618

REPORT DATE:

Saturday, September 10, 2022

Prepared for:

**Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

09/10/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23261 Region: 06 IDPH ID: 14-016-2990-2618

School: Foster Park School Annex Building ID: 3430/Annex

Address: 1819 W 85th Street
Chicago, IL, 60620

Building Contact: Mclver, Justin Contact Phone: 7737103201

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/17/2022

Review Date: 09/10/2022

Inspector: Roxana Ordonez Inspector IDPH License: 100-19782
Management Planner: Todd Huffer Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 10, 2022

RE: Foster Park School Annex, Unit 23261
1819 W 85th Street
Chicago, IL, 60620

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Foster Park School Annex , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Foster Park School Annex, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Foster Park School Annex Unit: 23261 Region: 06
Address: 1819 W 85th Street Chicago, IL, 60620
IDPH ID: 14-016-2990-2618 Building ID: 3430/Annex
Contact: Mclver, Justin Phone: 7737103201

2. Description of Facility

Original Construction: 1937 Additional Construction: 1952
Total Square Footage: 17910 No of Floors: 2
Current Occupancy: 296

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Roxana Ordonez



Inspector IDPH license # 100-19782
Reinspection Date: 8/17/2022

Signature:
Date: 8/17/2022

6. Management Planner

Management Planner Name: Todd Huffer



Management Planner IDPH license # 100-09870

Signature:
Date: 09/10/2022

7. Review Date: 09/10/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 9/10/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Foster Park School Annex. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3430/Annex:

Annex-CT-2	2'x4' Dot & Pin-Dot Lay-In Ceiling Tile
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 3430/Annex:

Annex-CT-2	2'x4' Dot & Pin-Dot Lay-In Ceiling Tile
NEW	Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

18	Tan Terrazzo
19	Green Mosaic Ceramic Tile
20	Green Mosaic Ceramic Adhesive
21	12"x12" Green Floor Tile
21M	12"x12" Green Floor Tile Mastic
22	2'x4' White Smooth Ceiling Tile
23	2'x4' White Deep Fissure Ceiling Tile
24	Black Sink Undercoating
25	Maroon Carpet Mastic
Annex-04	12"x12" Brown w/White Floor Tile NOT OBSERVED
Annex-05	12"x 12" Off-White Floor Tile
Annex-08	Black Baseboard Mastic
Annex-09	Black Baseboard
Annex-CM-1	Aqua Carpet Mastic NOT OBSERVED
Annex-CT-1	2'x4' Pin Dot Fissured Ceiling Tile
Annex-CT-2	2'x4' Dot & Pin-Dot Lay-In Ceiling Tile
Annex-FT-3	12"x12" Blue Floor Tile
Annex-FTM-3	12"x12" Blue Floor Tile Mastic
Annex-WG-1	Interior Window Glazing
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

20	Green Mosaic Ceramic Adhesive
21M	12"x12" Green Floor Tile Mastic
25	Maroon Carpet Mastic
Annex-06	12"x12" Off-White Floor Tile Mastic
Annex-07	12"x12" Brown w/White Floor Tile Mastic NOT OBSERVED
Annex-CM-1	Aqua Carpet Mastic NOT OBSERVED
Annex-FTM-3	12"x12" Blue Floor Tile Mastic
Annex-TSI-1	Fittings on Fiberglass

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Roxana Ordonez, IDPH License # 100-19782. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and

Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/6/2021

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Foster Park School Annex Building 3430/Annex Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Foster Park School Annex Unit 23261 Building ID 3430/Annex
Address 1819 W 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
18	Tan Terrazzo	800	SF	2nd & 3rd Floors, East and West Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Green Mosaic Ceramic Tile	1,800	SF	1st, 2nd and 3rd Floor Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Green Mosaic Ceramic Adhesive	1,800	SF	1st, 2nd and 3rd Floor Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12"x12" Green Floor Tile	21,000	SF	1st, 2nd and 3rd Floor Classrooms and Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21M	12"x12" Green Floor Tile Mastic	21,000	SF	1st, 2nd and 3rd Floor Classrooms and Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	2'x4' White Smooth Ceiling Tile	800	SF	Kitchen	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
23	2'x4' White Deep Fissure Ceiling Tile	19,500	SF	Library, Teachers' Lounge, Office, Rooms 113, 114 Storage Room & Toilet, 115, 117, 118 Storage Room & Toilet, 119, 120, 210, 211, 212, 213, 215, 217, 219, 310, 311, 312, 313, 314, 315, 316, 317, 319 & 320	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
24	Black Sink Undercoating	20	SF	Rooms 113, 114, 118, 210 & 316	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Maroon Carpet Mastic	300	SF	Room 120 (Auxiliary Office)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-04	12"x12" Brown w/White Floor Tile NOT OBSERVED	1,513	SF	N/S Multipurpose Room, 2nd Floor Landing, East 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-05	12"x 12" Off-White Floor Tile	3,200	SF	Center Multipurpose Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-06	12"x12" Off-White Floor Tile Mastic	3,200	SF	Center Multipurpose Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-07	12"x12" Brown w/White Floor Tile Mastic NOT OBSERVED	1,513	SF	N/S Multipurpose Room, 2nd Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Foster Park School Annex Unit 23261 Building ID 3430/Annex
Address 1819 W 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Landing (Patch), East 1st Floor Corridor										
Annex-08	Black Baseboard Mastic	16,000	LF	Throughout- Except Stairwells & Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-09	Black Baseboard	16,000	LF	Throughout- Except Stairwells & Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-CM-1	Aqua Carpet Mastic NOT OBSERVED	17,160	SF	Rooms 113-115, 117, 119, 211, 212, 213, 215, 217, 219, 311-315, 317, 319, Library & Adjustment Offices, 1st/3rd Teach NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-CT-1	2'x4' Pin Dot Fissured Ceiling Tile	36,000	SF	1st, 2nd & 3rd Floor Corridors	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Annex-CT-2	2'x4' Dot & Pin-Dot Lay-In Ceiling Tile	1,100	SF	Rooms 114, 118 & 119	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
Annex-FT-1	12"x12" Olive Green Floor Tile	1,350	SF	Kitchen Office, Kitchen Locker Room, Janitor's Closet 1st Floor, Rooms 210 & 310	CHR	MISC	N	NONE	0		No	ACBM with potential for significant damage		MODERATE
Annex-FT-2	12"x12" Gray w/Olive Green Floor Tile	10,560	SF	2nd & 3rd Floor Corridors, Rooms 211 Storeroom, 311 Storeroom & Library Workroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-FT-3	12"x12" Blue Floor Tile	2,100	SF	1st Floor Corridor & Kitchen Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-FTM-1	12"x12" Olive Green Floor Tile Mastic	1,350	SF	Kitchen Office, Kitchen Locker Room, Janitor's Closet 1st Floor, Rooms 210 & 310	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-FTM-2	Gray w/Olive Green Floor Tile Mastic	10,560	SF	2nd and 3rd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-FTM-3	12"x12" Blue Floor Tile Mastic	2,100	SF	1st Floor Corridor & Kitchen Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Foster Park School Annex Unit 23261 Building ID 3430/Annex
 Address 1819 W 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room										
Annex-TSI-1	Fittings on Fiberglass	14	EA	Kitchen, Janitor's Closet, Kitchen Storage	CHR	TSI	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		LOW
Annex-WC-1	Interior Window Caulk	9,000	LF	Windows 1st, 2nd & 3rd Floors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Annex-WG-1	Interior Window Glazing	18,000	LF	Windows 1st, 2nd & 3rd floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

Chicago Public Schools

School Foster Park School Annex Unit 23261 Building ID 3430/Annex
Address 1819 W 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/17/2022
Inspector Name Roxana Ordonez
100-19782 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
18	
19	
20	
21	
21M	
22	
23	
24	
25	
Annex-04	Not Observed 2022. May be Under Existing Floor
Annex-05	
Annex-06	
Annex-07	Not Observed 2022. May be Under Existing Floor
Annex-08	
Annex-09	
Annex-CM-1	Not Observed 2022. May be Under Existing Floor
Annex-CT-1	
Annex-CT-2	
Annex-FT-1	
Annex-FT-2	
Annex-FT-3	
Annex-FTM-1	
Annex-FTM-2	
Annex-FTM-3	

Chicago Public Schools

School Foster Park School Annex **Unit** 23261 **Building ID** 3430/Annex
Address 1819 W 85th Street **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
Annex-TSI-1	
Annex-WC-1	
Annex-WG-1	
NEW	

Table II

Management Planner's Review

Chicago Public Schools

School Foster Park School Annex

Unit 23261

Building ID 3430/Annex

Address 1819 W 85th Street

Chicago, IL, 60620

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
18	Tan Terrazzo	800	SF	2nd & 3rd Floors, East and West Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Green Mosaic Ceramic Tile	1,800	SF	1st, 2nd and 3rd Floor Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Green Mosaic Ceramic Adhesive	1,800	SF	1st, 2nd and 3rd Floor Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x12" Green Floor Tile	21,000	SF	1st, 2nd and 3rd Floor Classrooms and Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21M	12"x12" Green Floor Tile Mastic	21,000	SF	1st, 2nd and 3rd Floor Classrooms and Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	2'x4' White Smooth Ceiling Tile	800	SF	Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
23	2'x4' White Deep Fissure Ceiling Tile	19,500	SF	Library, Teachers' Lounge, Office, Rooms 113, 114 Storage Room & Toilet, 115, 117, 118 Storage Room & Toilet, 119, 120, 210, 211, 212, 213, 215, 217, 219, 310, 311, 312, 313, 314, 315, 316, 317, 319 & 320	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
24	Black Sink Undercoating	20	SF	Rooms 113, 114, 118, 210 & 316	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Maroon Carpet Mastic	300	SF	Room 120 (Auxiliary Office)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-04	12"x12" Brown w/White Floor Tile NOT OBSERVED	1,513	SF	N/S Multipurpose Room, 2nd Floor Landing, East 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-05	12"x 12" Off-White Floor Tile	3,200	SF	Center Multipurpose Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-06	12"x12" Off-White Floor Tile Mastic	3,200	SF	Center Multipurpose Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-07	12"x12" Brown w/White Floor Tile Mastic NOT OBSERVED	1,513	SF	N/S Multipurpose Room, 2nd Floor Landing (Patch), East 1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-08	Black Baseboard Mastic	16,000	LF	Throughout- Except Stairwells & Restroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-09	Black Baseboard	16,000	LF	Throughout- Except Stairwells & Restroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-CM-1	Aqua Carpet Mastic NOT OBSERVED	17,160	SF	Rooms 113-115, 117, 119, 211, 212, 213, 215, 217, 219, 311-315, 317, 319, Library & Adjustment Offices, 1st/3rd	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Foster Park School Annex
Address 1819 W 85th Street

Unit 23261
 Chicago, IL, 60620

Building ID 3430/Annex
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Teach NOT OBSERVED							
Annex-CT-1	2'x4' Pin Dot Fissured Ceiling Tile	36,000	SF	1st, 2nd & 3rd Floor Corridors	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Annex-CT-2	2'x4' Dot & Pin-Dot Lay-In Ceiling Tile	1,100	SF	Rooms 114, 118 & 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-FT-1	12"x12" Olive Green Floor Tile	1,350	SF	Kitchen Office, Kitchen Locker Room, Janitor's Closet 1st Floor, Rooms 210 & 310	Chrysotile	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
Annex-FT-2	12"x12" Gray w/Olive Green Floor Tile	10,560	SF	2nd & 3rd Floor Corridors, Rooms 211 Storeroom, 311 Storeroom & Library Workroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-FT-3	12"x12" Blue Floor Tile	2,100	SF	1st Floor Corridor & Kitchen Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-FTM-1	12"x12" Olive Green Floor Tile Mastic	1,350	SF	Kitchen Office, Kitchen Locker Room, Janitor's Closet 1st Floor, Rooms 210 & 310	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-FTM-2	Gray w/Olive Green Floor Tile Mastic	10,560	SF	2nd and 3rd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-FTM-3	12"x12" Blue Floor Tile Mastic	2,100	SF	1st Floor Corridor & Kitchen Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-TSI-1	Fittings on Fiberglass	14	EA	Kitchen, Janitor's Closet, Kitchen Storage	Chrysotile	TSI	Yes	0	EA	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Annex-WC-1	Interior Window Caulk	9,000	LF	Windows 1st, 2nd & 3rd Floors	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Annex-WG-1	Interior Window Glazing	18,000	LF	Windows 1st, 2nd & 3rd floors	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Foster Park School Annex
Address 1819 W 85th Street

Unit 23261
 Chicago, IL, 60620

Building ID 3430/Annex
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	9/10/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
18	
19	
20	
21	
21M	
22	
23	
24	
25	
Annex-04	
Annex-05	

Chicago Public Schools

School Foster Park School Annex
Address 1819 W 85th Street

Unit 23261
 Chicago, IL, 60620

Building ID 3430/Annex
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
Annex-06	
Annex-07	
Annex-08	
Annex-09	
Annex-CM-1	
Annex-CT-1	
Annex-CT-2	
Annex-FT-1	
Annex-FT-2	
Annex-FT-3	
Annex-FTM-1	
Annex-FTM-2	
Annex-FTM-3	
Annex-TSI-1	
Annex-WC-1	
Annex-WG-1	
NEW	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Tan Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd & 3rd Floors, East and West Stairways**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Tan Terrazzo**
MATERIAL LOCATION: **2nd & 3rd Floors, East and West Stairways**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Tile**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Adhesive**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Classrooms and Offices**
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Classrooms and Offices**
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21M**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Classrooms and Offices**
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **21M**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Classrooms and Offices**
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **2'x4' White Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **2'x4' White Smooth Ceiling Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **2'x4' White Deep Fissure Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, Teachers' Lounge, Office, Rooms 113, 114 Storage Room & Toilet, 115, 117, 118 Storage Room & Toilet, 119, 120, 210, 211, 212, 213, 215, 217, 219, 310, 311, 312, 313, 314, 315, 316, 317, 319 & 320**

MATERIAL QUANTITY: **19500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **2'x4' White Deep Fissure Ceiling Tile**
MATERIAL LOCATION: **Library, Teachers' Lounge, Office, Rooms 113, 114 Storage Room & Toilet, 115, 117, 118 Storage Room & Toilet, 119, 120, 210, 211, 212, 213, 215, 217, 219, 310, 311, 312, 313, 314, 315, 316, 317, 319 & 320**
MATERIAL QUANTITY: **19500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Black Sink Undercoating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 113, 114, 118, 210 & 316**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Black Sink Undercoating**
MATERIAL LOCATION: **Rooms 113, 114, 118, 210 & 316**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Maroon Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 120 (Auxiliary Office)**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Maroon Carpet Mastic**
MATERIAL LOCATION: **Room 120 (Auxiliary Office)**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23261 BUIDLING ID: 3430/Annex
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Roxana Ordonez
SCHOOL NAME: Foster Park School Annex INSPECTION DATE: 8/17/2022
ADDRESS: 1819 W 85th Street IDPH LICENSE NO: 100-19782

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Annex-04
MATERIAL DESCRIPTION: 12"x12" Brown w/White Floor Tile NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: N/S Multipurpose Room, 2nd Floor Landing, East 1st Floor Corridor
MATERIAL QUANTITY: 1513 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS: Not Observed 2022. May be Under Existing Floor

Inspector's Signature:



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-04**
MATERIAL DESCRIPTION: **12"x12" Brown w/White Floor Tile NOT OBSERVED**
MATERIAL LOCATION: **N/S Multipurpose Room, 2nd Floor Landing, East 1st Floor Corridor**
MATERIAL QUANTITY: **1513** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-05**
MATERIAL DESCRIPTION: **12"x 12" Off-White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Center Multipurpose Room**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-05**
MATERIAL DESCRIPTION: **12"x 12" Off-White Floor Tile**
MATERIAL LOCATION: **Center Multipurpose Room**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-06**
MATERIAL DESCRIPTION: **12"x12" Off-White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Center Multipurpose Room**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-06**
MATERIAL DESCRIPTION: **12"x12" Off-White Floor Tile Mastic**
MATERIAL LOCATION: **Center Multipurpose Room**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-07**
MATERIAL DESCRIPTION: **12"x12" Brown w/White Floor Tile Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **N/S Multipurpose Room, 2nd Floor Landing (Patch), East 1st Floor Corridor**
MATERIAL QUANTITY: **1513** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2022. May be Under Existing Floor**

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUILDING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-07**
MATERIAL DESCRIPTION: **12"x12" Brown w/White Floor Tile Mastic NOT OBSERVED**
MATERIAL LOCATION: **N/S Multipurpose Room, 2nd Floor Landing (Patch), East 1st Floor Corridor**
MATERIAL QUANTITY: **1513** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-08**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout- Except Stairwells & Restroom**

MATERIAL QUANTITY: **16000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-08**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Throughout- Except Stairwells & Restroom**
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-09**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout- Except Stairwells & Restroom**
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-09**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Throughout- Except Stairwells & Restroom**
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-CM-1**
MATERIAL DESCRIPTION: **Aqua Carpet Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 113-115, 117, 119, 211, 212, 213, 215, 217, 219, 311-315, 317, 319, Library & Adjustment Offices, 1st/3rd Teach NOT OBSERVED**

MATERIAL QUANTITY: **17160** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2022. May be Under Existing Floor**

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-CM-1**
MATERIAL DESCRIPTION: **Aqua Carpet Mastic NOT OBSERVED**
MATERIAL LOCATION: **Rooms 113-115, 117, 119, 211, 212, 213, 215, 217, 219, 311-315, 317, 319, Library & Adjustment Offices, 1st/3rd Teach NOT OBSERVED**
MATERIAL QUANTITY: **17160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-CT-1**
MATERIAL DESCRIPTION: **2'x4' Pin Dot Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **36000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/17/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-CT-1**
MATERIAL DESCRIPTION: **2'x4' Pin Dot Fissured Ceiling Tile**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **36000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-FT-1**
MATERIAL DESCRIPTION: **12"x12" Olive Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Kitchen Office, Kitchen Locker Room, Janitor's Closet 1st Floor, Rooms 210 & 310**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-FT-1**
MATERIAL DESCRIPTION: **12"x12" Olive Green Floor Tile**
MATERIAL LOCATION: **Kitchen Office, Kitchen Locker Room, Janitor's Closet 1st Floor, Rooms 210 & 310**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-FT-2**
MATERIAL DESCRIPTION: **12"x12" Gray w/Olive Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors, Rooms 211 Storeroom, 311 Storeroom & Library Workroom**
MATERIAL QUANTITY: **10560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-FT-2**
MATERIAL DESCRIPTION: **12"x12" Gray w/Olive Green Floor Tile**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors, Rooms 211 Storeroom, 311 Storeroom & Library Workroom**
MATERIAL QUANTITY: **10560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-FT-3**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor & Kitchen Storage Room**

MATERIAL QUANTITY: **2100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-FT-3**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
MATERIAL LOCATION: **1st Floor Corridor & Kitchen Storage Room**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-FTM-1**
MATERIAL DESCRIPTION: **12"x12" Olive Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen Office, Kitchen Locker Room, Janitor's Closet 1st Floor, Rooms 210 & 310**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-FTM-1**
MATERIAL DESCRIPTION: **12"x12" Olive Green Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen Office, Kitchen Locker Room, Janitor's Closet 1st Floor, Rooms 210 & 310**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-FTM-2**
MATERIAL DESCRIPTION: **Gray w/Olive Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **10560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-FTM-2**
MATERIAL DESCRIPTION: **Gray w/Olive Green Floor Tile Mastic**
MATERIAL LOCATION: **2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **10560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-FTM-3**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor & Kitchen Storage Room**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-FTM-3**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor & Kitchen Storage Room**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-TSI-1**
MATERIAL DESCRIPTION: **Fittings on Fiberglass**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, Janitor's Closet, Kitchen Storage**

MATERIAL QUANTITY: **14**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-TSI-1**
MATERIAL DESCRIPTION: **Fittings on Fiberglass**
MATERIAL LOCATION: **Kitchen, Janitor's Closet, Kitchen Storage**
MATERIAL QUANTITY: **14** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-WC-1**
MATERIAL DESCRIPTION: **Interior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Windows 1st, 2nd & 3rd Floors**

MATERIAL QUANTITY: **9000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-WC-1**
MATERIAL DESCRIPTION: **Interior Window Caulk**
MATERIAL LOCATION: **Windows 1st, 2nd & 3rd Floors**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Annex-WG-1**
MATERIAL DESCRIPTION: **Interior Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Windows 1st, 2nd & 3rd floors**

MATERIAL QUANTITY: **18000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUIDLING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-WG-1**
MATERIAL DESCRIPTION: **Interior Window Glazing**
MATERIAL LOCATION: **Windows 1st, 2nd & 3rd floors**
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUILDING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan**
MATERIAL QUANTITY: MATERIAL UNITS:
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUILDING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **09/10/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUILDING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roxana Ordonez**
SCHOOL NAME: **Foster Park School Annex** INSPECTION DATE: **8/17/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **Annex-CT-2**
MATERIAL DESCRIPTION: **2'x4' Dot & Pin-Dot Lay-In Ceiling Tile**
MATERIAL LOCATION: **Rooms 114, 118 & 119**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/17/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23261** BUILDING ID: **3430/Annex**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Foster Park School Annex** REVIEW DATE: **9/10/2022**
ADDRESS: **1819 W 85th Street** IDPH LICENSE NO: **100-19782**

HOMOGENEOUS AREA: **Annex-CT-2**
MATERIAL DESCRIPTION: **2'x4' Dot & Pin-Dot Lay-In Ceiling Tile**
MATERIAL LOCATION: **Rooms 114, 118 & 119**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/10/2022

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ROXANA I ORDONEZ
10834 WELLINGTON STREET
MELROSE PARK, IL 60164

3/15/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 19782

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	ID NUMBER 100 - 19782	ISSUED 3/15/2022	INSPECTOR	2/9/2023
ROXANA I ORDONEZ 10834 WELLINGTON STREET MELROSE PARK, IL 60164 Environmental Health		EXPIRES 05/15/2023	PROJECT MANAGER AIR SAMPLING PROFESSIONAL	10/20/2022
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Roxana Ordonez

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/9/2022

Exam Date: 2/9/2022

Expiration Date: 2/9/2023

Certificate Number: BIR2202090439

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

TODD T HUFFER
315 HATLEN COURT
MT. PROSPECT, IL 60056

2/18/2022


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

			ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 09870	ISSUED 2/18/2022	EXPIRES 05/15/2023			INSPECTOR	11/1/2022
TODD T HUFFER 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health					MANAGEMENT PLANNER	11/19/2022
					PROJECT MANAGER	10/20/2022
					AIR SAMPLING PROFESSIONAL	
					Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265


Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed