# ILLINOIS DEPARTMENT OF PUBLIC HEALTH AHERA THREE YEAR REINSPECTION ASBESTOS ABATEMENT PROGRAM SCHOOL INFORMATION FORM

14-016-2990-2236

CHICAGO SCHOOL DIST 299

#### **SECTION I**

IL-482-1026

NAME OF SCHOOL DISTRICT:

SCHOOL ID NUMBER:

**SCHOOL NAME:** Gillespie School ADDRESS OF SCHOOL: 9301 S State Street CITY: Chicago, IL, 60619 DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 10/3/2019 If the address on this form is different than the address of the building, submit a written explanation. **SECTION II** (Please type or print) PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION: DATE REINSPECTION COMPLETED: 8/9/2022 ENROLLMENT 383 IDPH INSPECTOR LICENSE NUMBER: 100-20327 IDPH LICENSED INSPECTOR NAME (Please Print): Drake Ottley IDPH MP LICENSE NUMBER: 100-03613 IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074 9/2/2022 Richard J. Schliger Signature of Designated Person Date **SECTION III** PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT. School building has been sold. Date of Sale: School has been closed. Date closed: School building has been demolished. Date: School building is <u>asbestos free</u> since last reinspection: Please explain in writing why the school building is now asbestos free and include the supporting documentation. If a new school building has been added to the district, submit either and exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building. Explain in writing if the address of the building is different than the address on this form:

Revised 10.03

#### THREE-YEAR REINSPECTION

#### **CHICAGO SCHOOL DIST 299**

#### **Gillespie School**

9301 S State Street Chicago, IL, 60619

Unit: 23321 Building ID: 3530

IDPH ID Number: 14-016-2990-2236

#### **REPORT DATE:**

Friday, September 02, 2022

Prepared for: Chicago Public Schools 42 W. Madison Street Chicago, IL 60602

Prepared by: TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

## DO NOT REMOVE FROM SCHOOL REQUIRED BY FEDERAL LAW

#### 09/02/2022

Mr.Eric Culbertson Asbestos Program Illinois Department of Public Health 525 West Jefferson Street Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr.Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23321 Region: 06 IDPH ID: 14-016-2990-2236

School: Gillespie School Building ID: 3530

Address: 9301 S State Street

Chicago, IL, 60619

Building Contact: Palmer, Chris Contact Phone: 7736306543

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/9/2022

Review Date: 09/02/2022

Inspector: Drake Ottley Inspector IDPH License: 100-20327

Management Planner: Daniel Juneau Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,

TEM Environmental, Inc.

Daniel Juneau 100-03613

### **Environmental Notification to Occupants**

To: Faculty, Staff and Parents From: Chicago Public Schools Date: September 02, 2022

RE: Gillespie School, Unit 23321

9301 S State Street Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Gillespie School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Gillespie School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

#### **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

#### **APPENDICES**:

Appendix A: Assessment Sheets, Drawings and Photos

Appendix B: Inspector and Management Planner Licenses

Appendix C: Laboratory Accreditations

Appendix D: Laboratory Results

Appendix E: Chain of Custody Forms

#### SCHOOL AND INSPECTION INFORMATION

#### 1. School Information

School: Gillespie School Unit: 23321 Region: 06

 Address:
 9301 S State Street
 Chicago, IL, 60619

 IDPH ID:
 14-016-2990-2236
 Building ID: 3530

 Contact:
 Palmer, Chris
 Phone: 7736306543

#### 2. Description of Facility

Original Construction: 1961 Additional Construction: 1937

Total Square Footage: 30600 No of Floors: 2

Current Occupancy: 383

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074

Address: 42 West Madison Street

Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc. Contact: Steven Geneser Address 174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Dakeretty

1000cle

5. Inspector

Inspector Name: Drake Ottley

Signature:

Date: 8/9/2022

Inspector IDPH license # 100-20327 Reinspection Date: 8/9/2022

6. Management Planner

Management Planner Name: Daniel Juneau

Signature:

Management Planner IDPH license # 100-03613

Richard J. Schliger

Date: 09/02/2022

7. Review Date: 09/02/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:

Date: 9/2/2022

Name: Richard J.Schleyer

#### **II. EXECUTIVE SUMMARY**

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Gillespie School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3530:

NEW Newly Installed Suspect ACM

B. The following new homogen	ous areas have been identified for Building 3530:
NEW	Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Green Linoleum
10	9"x9" Beige Floor Tile Mastic
13	Smooth Plaster
14	Insulation in Fire Rated Doors
15	Black Vinyl Baseboard
16	Black Vinyl Baseboard Mastic
17	Smooth Plaster
18	Smooth Plaster
20	9"x9" Orange Floor Tile Mastic
21	Transite Desktops
22	Counter Tops
23	12"x12" Ceiling Tile
30	12"x12" Light Grey Floor Tile
32	12"x12" Light Brown Floor Tile
33	12"x12" Light Brown Floor Tile Mastic
41	Brown Carpet Mastic
42	Black Vinyl Baseboard
43	Black Vinyl Baseboard Mastic
44	9"x9" Tan w/Brown & White Streaks Floor Tile
45	9"x9" Tan w/Brown & White Streaks Floor Tile
	Mastic
46	9"x9" Cream Floor Tile
47	9"x9" Cream Floor Tile Mastic
48	9"x9" Brown w/White Streaks Floor Tile
49	9"x9" Brown w/White Streaks Floor Tile Mastic
50	12"x12" White w/Gray Specks Floor Tile
51	12"x12" White w/Gray Specks Floor Tile Mastic
52	12"x12" Tan w/Brown Specks Floor Tile
53	12"x12" Tan w/Brown Specks Floor Tile Mastic
56	12"x12" Peach Floor Tile
57	12"x12" Peach Floor Tile Mastic
62	12x12 Cream w/Brown Specks Floor Tile
63	12x12 Cream w/Brown Specks Floor Tile Mastic
72	12"x12" Red w/Black Specks Floor Tile
73	12"x12" Red w/Black Specks Floor Tile Mastic
78	12 X 12 Beige w/Light Red and Light Blue Streaks
	Floor Tile
78M	12"x12" Beige w/Light Red and Light Blue Streaks
	Floor Tile Mastic
79	Brown with Black Streaks Terrazzo
80	Grey, White and Black Speckled Terrazzo
81	Brown and Tan Mosaic Ceramic Tile Grout

81M	Brown and Tan Mosaic Ceramic Tile Mastic
_	
82	4"x4" Red Ceramic Tile Grout
82M	4"x4" Red Ceramic Tile Grout
83	Light and Dark Orange Speckled Terrazzo
84	Beige with Yellow Specks Terrazzo
85	Blue Carpet Mastic
86	Acoustical Ceiling Plaster
87	Tan Mosaic Ceramic Tile Grout
87M	Tan Mosaic Ceramic Tile Mastic
88	Multicolor Mosaic Floor Tile Grout
89	Multicolor Mosaic Floor Tile Mastic
90	12"x12" Light Grey w/Dark Grey Streaks Floor Tile
90M	12"x12" Light Grey w/Dark Grey Streaks Floor Tile
	Mastic
91	12"x12" Royal Blue Vinyl Floor Tile
91A	12"x12" Royal Blue Vinyl Floor Tile Mastic
92	12"x12" Red Vinyl Floor Tile
92A	12"x12" Red Vinyl Floor Tile Mastic
93	12"x12" Blue Streaked Vinyl Floor Tile
93A	12"x12" Blue Streaked Vinyl Floor Tile Mastic
94	12"x12" Blue Streaked Vinyl Floor Tile
94A	12"x12" Blue Streaked Vinyl Floor Tile Mastic
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

08	12"x12" Red Floor Tile Mastic
10	9"x9" Beige Floor Tile Mastic
14	Insulation in Fire Rated Doors
16	Black Vinyl Baseboard Mastic
19	Green Linoleum Mastic
20	9"x9" Orange Floor Tile Mastic
31	12"x12" Light Grey Floor Tile Mastic
33	12"x12" Light Brown Floor Tile Mastic
35	12"x12" Tan Floor Tile Mastic
36	12"x12" Tan Floor Tile Mastic
38	12"x12" Dark Brown Floor Tile Mastic
40	Brown Border Floor Tile Mastic
41	Brown Carpet Mastic
43	Black Vinyl Baseboard Mastic
45	9"x9" Tan w/Brown & White Streaks Floor Tile
	Mastic
47	9"x9" Cream Floor Tile Mastic
49	9"x9" Brown w/White Streaks Floor Tile Mastic
51	12"x12" White w/Gray Specks Floor Tile Mastic
53	12"x12" Tan w/Brown Specks Floor Tile Mastic

57	12"x12" Peach Floor Tile Mastic
63	12x12 Cream w/Brown Specks Floor Tile Mastic
73	12"x12" Red w/Black Specks Floor Tile Mastic
78M	12"x12" Beige w/Light Red and Light Blue Streaks
	Floor Tile Mastic
81M	Brown and Tan Mosaic Ceramic Tile Mastic
82M	4"x4" Red Ceramic Tile Grout
85	Blue Carpet Mastic
87M	Tan Mosaic Ceramic Tile Mastic
89	Multicolor Mosaic Floor Tile Mastic
90M	12"x12" Light Grey w/Dark Grey Streaks Floor Tile
	Mastic
92A	12"x12" Red Vinyl Floor Tile Mastic
93A	12"x12" Blue Streaked Vinyl Floor Tile Mastic
94A	12"x12" Blue Streaked Vinyl Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Drake Ottley, IDPH License # 100-20327. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

#### III. METHODOLOGY

Tasks performed on-site included the following:

- 1. Review current management plan, identify HA(s) and extract appropriate information.
- 2. Examine and verify abatement records.
- 3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
- 4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
- 5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
- 6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
- 7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
- 8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

#### IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/22/2021

#### V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

#### VI. CONCLUSIONS

The Gillespie School Building 3530 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

# **Table I Inspector's Reinspection Findings**

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Green Linoleum	700	SF	1936 Building- Room 250	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	9"x9" Orange Floor Tile	775	SF	1944 Building- Room 256, Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	12"x12" Tan Floor Tile	4,700	SF	1944 Building- Room 107, Corridor/Gym Rooms 155-157 & Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	9"x9" Brown Floor Tile NOT OBSERVED			1936 Building- 1st & 2nd Floor Corridors		MISC								
06	9"x9" Brown Floor Tile Mastic NOT OBSERVED			1936 Building- 1st & 2nd Floor Corridor		MISC								
07	12"x12" Red Floor Tile	7,000	SF	1944 Building- Rooms 153, 155- 157, 252, 254, 255, 257, Gym, Assembly Hall, Book Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	12"x12" Red Floor Tile Mastic	7,000	SF	1944 Building- Rooms 153, 155- 157, 252, 254, 255, 257, Gym, Assembly Hall, Book Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	9"x9" Beige Floor Tile	3,950	SF	1961 Building- Lunchroom, Boys' Toilet, Room 118 & 120, and 1st Floor Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9"x9" Beige Floor Tile Mastic	3,950	SF	1961 Building- 1st Floor Gym, Lunchroom, Boys' Toilet, Rooms 118 & 120	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	9"x9" Tan Floor Tile	20,000	SF	1961 Building- Rooms 114-120, 200, 209, 210, 212, 214, 216-220, 1st & 2nd Floor Corridors, Teachers Restroom & Lunchroom,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Storeroom, W Teachers Room, and Vault										
12	9"x9" Tan Floor Tile Mastic	20,000	SF	1961 Building- Rooms 114-120, 200, 209, 210, 212, 214, 216-220, 1st & 2nd Floor Corridors, Teachers' Restroom & Lunchroom, Storeroom, W Teachers' Room, and Vault	CHR	MISC	N	NONE	5		No	ACBM with the potential for damage		LOW
13	Smooth Plaster	96,000	SF	1944 Building- Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Insulation in Fire Rated Doors	2	EA	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
15	Black Vinyl Baseboard	210	LF	1961 Building- Boom 118, 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Black Vinyl Baseboard Mastic	210	LF	1961 Building- Room 118, 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Smooth Plaster	120,000	SF	1936 Building- Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Smooth Plaster	27,500	SF	1961 Building- Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Green Linoleum Mastic	700	SF	1944 Building- Room 250	CHR	MISC	N		0		No	ACBM with the potential for damage		LOW
20	9"x9" Orange Floor Tile Mastic	775	SF	1944 Building- Room 256, Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Transite Desktops	30	SF	Room 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Counter Tops	20	SF	1961 Building- Room 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12"x12" Ceiling Tile	2,000	SF	1961 Building- 1st Floor Lobby, Room 220, Lunchroom	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
24	9"x9" Brown Floor Tile NOT OBSERVED			1961 Building- 1st & 2nd Floor Corridor		MISC								
25	9"x9" Brown Floor Tile Mastic NOT OBSERVED			1961 Building- 1st & 2nd Floor Corridor		MISC								
26	9"x9" Black Floor Tile NOT OBSERVED			1936 Building- 1st		MISC								

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				& 2nd Floor Corridor										
27	9"x9" Black Floor Tile Mastic NOT OBSERVED			1936 Building-1st & 2nd Floor Corridor		MISC								
28	12"x12" Light Grey Floor Tile NOT OBSERVED			1936 Building- Room 102		MISC								
29	12"x12" Light Grey Floor Tile Mastic NOT OBSERVED			1936 Building- Room 102		MISC								
30	12"x12" Light Grey Floor Tile	680	SF	1936 Building- Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12"x12" Light Grey Floor Tile Mastic	680	SF	1936 Building- Room 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12"x12" Light Brown Floor Tile	200	SF	1961 Building- Teachers' Lunchroom & Corridor, and Room 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	12"x12" Light Brown Floor Tile Mastic	200	SF	1961 Building- Teachers Lunchroom & Corridor, and Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12"x12" Tan Floor Tile	170	SF	1961 Building- 1st Floor Storeroom, Patch in Room 118	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12"x12" Tan Floor Tile Mastic	170	SF	1961 Building- 1st Floor Storeroom, Patch in Room 118	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12"x12" Tan Floor Tile Mastic	4,700	SF	1944 Building- Room 107, Corridor/Gym, Rooms 155-157 & Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12"x12" Dark Brown Floor Tile	1,150	SF	1944 Building- Room 152, Principal's Office & Room 253	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12"x12" Dark Brown Floor Tile Mastic	1,150	SF	1944 Building- Room 152, Principal's Office, Room 253	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Brown Border Floor Tile	800	SF	1944 Building- Rooms 153, 155- 157, 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridor, Rooms 252, 254-257, 2nd Floor Corridor & Teachers' Restroom										
40	Brown Border Floor Tile Mastic	800	SF	1944 Building- Rooms 153, 155- 157, 1st Floor Corridor, Rooms 252, 254-257, 2nd Floor Corridor & Teachers' Restroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Brown Carpet Mastic	650	SF	1944 Building- Principal's Office, Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Black Vinyl Baseboard	80		1944 Building- Room 250	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Black Vinyl Baseboard Mastic	80		1944 Building- Room 250	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	9"x9" Tan w/Brown & White Streaks Floor Tile	100	SF	Patch in Room 256	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	9"x9" Tan w/Brown & White Streaks Floor Tile Mastic	100	SF	Patch in Room 256	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	9"x9" Cream Floor Tile	25	SF	Patch in Room 256	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	9"x9" Cream Floor Tile Mastic	25	SF	Patch in Room 256	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	9"x9" Brown w/White Streaks Floor Tile	500	SF	Room 215, Patch in Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	9"x9" Brown w/White Streaks Floor Tile Mastic	500	SF	Room 215, Patch in Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12"x12" White w/Gray Specks Floor Tile	4,000	SF	Lunchroom, Patches in Room 116, Room 219, Under Water Fountain	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	12"x12" White w/Gray Specks Floor Tile Mastic	4,000	SF	Lunchroom, Patches in Room 116, Room 219, Under Water Fountain	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12"x12" Tan w/Brown Specks Floor Tile	900	SF	1944 Building- Room 154	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12"x12" Tan w/Brown Specks Floor Tile Mastic	900	SF	1944 Building- Room 154	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12"x12" Light Red Floor Tile ABATED			1944 Building- Patch in Room 154	ABATED	MISC								

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
55	12"x12" Light Red Floor Tile Mastic ABATED			1944 Building- Patch in Room 154	ABATED	MISC								
56	12"x12" Peach Floor Tile	50	SF	1944 Building- Patches in Room 155, Room 156	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12"x12" Peach Floor Tile Mastic	50	SF	1944 Building- Patches in Room 155, Room 156	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12"x12" Light Brown Floor Tile NOT OBSERVED			Patch in 1961 Corridor		MISC								
59	12x12 Light Brown Floor Tile Mastic NOT OBSERVED			Patch in 1961 Corridor		MISC								
60	9x9 Pinkish Red w/White Streaks NOT OBSERVED			1961 Building- Entrance to 1st Floor Girls' Bathroom		MISC								
61	9x9 Pinkish Red w/White Streaks Mastic NOT OBSERVED			1961 Building- Entrance to 1st Floor Girls' Bathroom		MISC		None	0					
62	12x12 Cream w/Brown Specks Floor Tile	10	SF	1961 Building- Patch in Room 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	12x12 Cream w/Brown Specks Floor Tile Mastic	10	SF	1961 Building- Patch in Room 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12x12 Light Brown w/White Specks Floor Tile NOT OBSERVED			Patch in 1936 Corridor		MISC								
65	12x12 Light Brown w/White Specks Floor Tile Mastic NOT OBSERVED			Patch in 1936 Corridor		MISC								
66	9x9 Cream Floor Tile NOT OBSERVED			1961 Building- Patch at Entrance to Room 208		MISC								
67	9x9 Cream Floor Tile Mastic NOT OBSERVED			1961 Building- Patch at Entrance to Room 208		MISC								
68	12x12 Red Floor Tile NOT OBSERVED			1936 Building- Part of Corridor, Room 207, Room 107, Main Office		MISC								
69	12x12 Red floor Tile Mastic NOT OBSERVED			1936 Building- Part of Corridor, Room 207, Room 107, Main Office		MISC								
70	9x9 Black w/White Streaks Floor Tile NOT OBSERVED			Room 252, Patches in 1936 Corridor, Patches in Room 219, Patches in		MISC								

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Teachers' Lunchroom										
71	9"x9" Black w/White Streaks Floor Tile Mastic NOT OBSERVED			Room 252, Patches in 1936 Corridor, Patches in Room 219, Patches in Teachers' Lunchroom		MISC								
72	12"x12" Red w/Black Specks Floor Tile	60	SF	1944 Building- Patches in Rooms 252, 155, 156	ASSUMED	MISC	N	DIST	0		No	ACBM with the potential for damage		LOW
73	12"x12" Red w/Black Specks Floor Tile Mastic	60	SF	1944 Building- Patches in Rooms 155, 156 & 252	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	Black Tile Border NOT OBSERVED			1936 Corridor- 1st & 2nd floors		MISC								
75	Black Tile Border Mastic NOT OBSERVED			1936 Corridor- 1st & 2nd Floors		MISC								
76	12"x12" Beige Floor Tile NOT OBSERVED			1st and 2nd Floor Hallways		MISC								
77	12"x12" Beige Floor Tile Mastic NOT OBSERVED			1st and 2nd Floor Hallways		MISC								
78	12 X 12 Beige w/Light Red and Light Blue Streaks Floor Tile	35,000	SF	1936, 1944 & 1961 Buildings- 1st Floor Corridors /1961 Building- 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78M	12"x12" Beige w/Light Red and Light Blue Streaks Floor Tile Mastic	35,000	SF	1936, 1944 & 1961 Buildings- 1st Floor Corridors /1961 Building- 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	Brown with Black Streaks Terrazzo	3,500	SF	1944 Building- Stairwells	ASSUMED	MISC	N	None	0		No	ACBM with the potential for damage		LOW
80	Grey, White and Black Speckled Terrazzo	2,300	SF	1936 Building- Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	Brown and Tan Mosaic Ceramic Tile Grout	1,800	SF	1936 Building- Boys and Girls Toilets and Vestibules	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
81M	Brown and Tan Mosaic Ceramic Tile Mastic	1,800	SF	1936 Building- Boys and Girls Toilets and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	4"x4" Red Ceramic Tile Grout	600	SF	1961 Building- Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
82M	4"x4" Red Ceramic Tile Grout	600	SF	1961 Building- Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	Light and Dark Orange Speckled Terrazzo	3,600	SF	1961 Building - Stairs and Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	Beige with Yellow Specks Terrazzo	2,200	SF	1961 Building- Stairs and Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	Blue Carpet Mastic	2,200	SF	1961 Building- Library and Room 118	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	Acoustical Ceiling Plaster	14,500	SF	1961 Building- Throughout Ceilings	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
87	Tan Mosaic Ceramic Tile Grout	2,600	SF	1944 Building- Boys and Girls Washrooms and Vestibules	ASSUMED	MISC	N	None	0		No	ACBM with the potential for damage		LOW
87M	Tan Mosaic Ceramic Tile Mastic	2,600	SF	1944 Building- Boys' & Girls' Washrooms and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	Multicolor Mosaic Floor Tile Grout	1,600	SF	1961 Building- Boys' & Girls' Washrooms and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	Multicolor Mosaic Floor Tile Mastic	1,600	SF	1961 Building- Boys' & Girls' Washrooms and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12"x12" Light Grey w/Dark Grey Streaks Floor Tile	7,400	SF	1936 & 1944 Buildings- 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90M	12"x12" Light Grey w/Dark Grey Streaks Floor Tile Mastic	7,400	SF	1936 & 1944 Buildings- 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	12"x12" Royal Blue Vinyl Floor Tile	60	SF	1961 Building- 1st Floor Men's Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91A	12"x12" Royal Blue Vinyl Floor Tile Mastic	60	SF	1961 Building- 1st Floor Men's Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	12"x12" Red Vinyl Floor Tile	60	SF	1961 Building- 1st Floor Women's Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92A	12"x12" Red Vinyl Floor Tile Mastic	60	SF	1961 Building- 1st Floor Women's	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Restroom										
93	12"x12" Blue Streaked Vinyl Floor Tile	2,400	SF	1944 Building- Gym/Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93A	12"x12" Blue Streaked Vinyl Floor Tile Mastic	2,400	SF	1944 Building- Gym/Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
94	12"x12" Blue Streaked Vinyl Floor Tile	3,000	SF	1961 Building- Gym/Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
94A	12"x12" Blue Streaked Vinyl Floor Tile Mastic	3,000	SF	1961 Building- Gym/Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Α	Boiler Insulation NOT OBSERVED			Boiler Room		TSI						,		
В	Boiler Breaching NOT OBSERVED			Boiler Room		TSI								
С	Aircell Pipe Insulation	2,500	LF	1944 Building- Coal Room, Boiler Room & Unfinished Pipe Space	CHR	TSI	Y	DIST	50		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
D	Aircell Pipe Joint Insulation	175	LF	1944 Building- Coal Room & Unfinished Pipe Space	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Е	Tank Insulation NOT OBSERVED			Pump Room		TSI								
F	Paper-Wrap Pipe Insulation	700	LF	1944 Building- Boys and Girls Toilet, Chases and Crawlspace	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Paper-Wrap Pipe Joint Insulation	80	LF	1944 Building- Boys and Girls Toilet, Chases and Crawlspace	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Н	Duct Insulation	1,000	SF	1944 Building- Unfinished Pipe Space	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	Duct Insulation	1,200	SF	1936 Building- Unfinished Pipe Space	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	Fiberglass Joint Insulation	345	LF	1961 Building- Unfinished Pipe Space	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	Tank Insulation NOT OBSERVED			Boiler Room		TSI								
N	Fiberglass Joint Insulation	170	LF	Unfinished Pipe Space	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and Afte Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
P	Aircell Pipe Insulation	100	LF	1961 Building- Unfinished Pipe Space & Outside Engineer's Office	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
R	Fiberglass Joint Insulation	60	LF	1944 Building- Coal Room & Unfinished Pipe Space	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Т	Incinerator Insulation NOT OBSERVED			1944 Building- Boiler Room		TSI			0					

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/9/2022

<u>100-20327</u> <u>5/15/2023</u>

Inspector's IDPH License Number / Expiration Date

#### **Inspector's Comments**

HA Number:	Inspector Comments:
01	•
02	
03	
05	Not Observed
06	Not Observed
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	Not Observed
25	Not Observed

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA Number:	Inspector Comments:
26	Not Observed
27	Not Observed
28	Not Observed
29	Not Observed
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	Abated from Teachers' Restroom
41	Abated from Main Office
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA Number:	Inspector Comments:
55	
56	
57	
58	Not Observed
59	Not Observed
60	Not Observed
61	Not Observed
62	
63	
64	Not Observed
65	Not Observed
66	Not Observed
67	Not Observed
68	Not Observed
69	Not Observed
70	Not Observed
71	Not Observed
72	
73	
74	Not Observed
75	Not Observed
76	Not Observed
77	Not Observed
78	
78M	
79	
80	
81	
81M	

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA Number:	Inspector Comments:
82	
82M	
83	
84	
85	
86	
87	
87M	
88	
89	
90	
90M	
91	
91A	
92	
92A	
93	
93A	
94	
94A	
Α	Not Observed. New Boilers
В	Not Observed. New Boilers
C D	50 LF of Damage in Boiler Room
D	
E	Not Observed. No Tank
F	
G	
Н	
1	

**School** Gillespie School **Unit** 23321 **Building ID** 3530 **Address** 9301 S State Street **Region** 06

### ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

**Inspector's Reinspection Findings Table 1** 

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA Number:	Inspector Comments:
K	
L	Not Observed. No Tank
Ν	
NEW	
Р	
R	
Т	Not Observed

### Table II

### **Management Planner's Review**

SchoolGillespie SchoolUnit23321Building ID3530

Address 9301 S State Street Chicago, IL, 60619 Region 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

						iviaiia	gemeni	Piailie	S COIII	's Comments Summarized at the End of the Report				
HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response			
01	Green Linoleum	700	SF	1936 Building- Room 250	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			
02	9"x9" Orange Floor Tile	775	SF	1944 Building- Room 256, Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			
03	12"x12" Tan Floor Tile	4,700	SF	1944 Building- Room 107, Corridor/Gym Rooms 155-157 & Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			
05	9"x9" Brown Floor Tile NOT OBSERVED			1936 Building- 1st & 2nd Floor Corridors		MISC								
06	9"x9" Brown Floor Tile Mastic NOT OBSERVED			1936 Building- 1st & 2nd Floor Corridor		MISC								
07	12"x12" Red Floor Tile	7,000	SF	1944 Building- Rooms 153, 155-157, 252, 254, 255, 257, Gym, Assembly Hall, Book Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			
08	12"x12" Red Floor Tile Mastic	7,000	SF	1944 Building- Rooms 153, 155-157, 252, 254, 255, 257, Gym, Assembly Hall, Book Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			
09	9"x9" Beige Floor Tile	3,950	SF	1961 Building- Lunchroom, Boys' Toilet, Room 118 & 120, and 1st Floor Gvm	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			
10	9"x9" Beige Floor Tile Mastic	3,950	SF	1961 Building- 1st Floor Gym, Lunchroom, Boys' Toilet, Rooms 118 & 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			
11	9"x9" Tan Floor Tile	20,000	SF	1961 Building- Rooms 114-120, 200, 209, 210, 212, 214, 216-220, 1st & 2nd Floor Corridors, Teachers Restroom & Lunchroom, Storeroom, W Teachers Room, and Vault	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			
12	9"x9" Tan Floor Tile Mastic	20,000	SF	1961 Building- Rooms 114-120, 200, 209, 210, 212, 214, 216-220, 1st & 2nd Floor Corridors, Teachers' Restroom & Lunchroom, Storeroom, W Teachers' Room, and Vault	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Follow O&M Plan			
13	Smooth Plaster	96,000	SF	1944 Building- Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			
14	Insulation in Fire Rated Doors	2	EA	Boiler Room	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan			
15	Black Vinyl Baseboard	210	LF	1961 Building- Boom 118, 209	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan			
16	Black Vinyl Baseboard Mastic	210	LF	1961 Building- Room 118, 209	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan			
17	Smooth Plaster	120,000	SF	1936 Building- Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan			

SchoolGillespie SchoolUnit23321Building ID3530

Address 9301 S State Street Chicago, IL, 60619 Region 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

						1	<u> </u>		1	ments Summarized at th	
HA	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Num		Quantity	Units		Type	Category		Quantity	Units		
18	Smooth Plaster	27,500	SF	1961 Building- Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Green Linoleum Mastic	700	SF	1944 Building- Room 250	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9"x9" Orange Floor Tile Mastic	775	SF	1944 Building- Room 256, Engineer's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Office							
21	Transite Desktops	30	SF	Room 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Counter Tops	20	SF	1961 Building- Room 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Ceiling Tile	2,000	SF	1961 Building- 1st Floor Lobby, Room	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				220, Lunchroom							
24	9"x9" Brown Floor Tile NOT OBSERVED			1961 Building- 1st & 2nd Floor Corridor		MISC					
25	9"x9" Brown Floor Tile Mastic NOT OBSERVED			1961 Building- 1st & 2nd Floor Corridor		MISC					
26	9"x9" Black Floor Tile NOT OBSERVED			1936 Building- 1st & 2nd Floor Corridor		MISC					
27	9"x9" Black Floor Tile Mastic NOT OBSERVED			1936 Building-1st & 2nd Floor Corridor		MISC					
28	12"x12" Light Grey Floor Tile NOT OBSERVED			1936 Building- Room 102		MISC					
29	12"x12" Light Grey Floor Tile Mastic NOT OBSERVED			1936 Building- Room 102		MISC					
30	12"x12" Light Grey Floor Tile	680	SF	1936 Building- Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" Light Grey Floor Tile Mastic	680	SF	1936 Building- Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Light Brown Floor Tile	200	SF	1961 Building- Teachers' Lunchroom & Corridor, and Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12"x12" Light Brown Floor Tile Mastic	200	SF	1961 Building- Teachers Lunchroom & Corridor, and Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12"x12" Tan Floor Tile	170	SF	1961 Building- 1st Floor Storeroom, Patch in Room 118	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12"x12" Tan Floor Tile Mastic	170	SF	1961 Building- 1st Floor Storeroom, Patch in Room 118	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" Tan Floor Tile Mastic	4,700	SF	1944 Building- Room 107, Corridor/Gym, Rooms 155-157 & Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"x12" Dark Brown Floor Tile	1,150	SF	1944 Building- Room 152, Principal's Office & Room 253	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12"x12" Dark Brown Floor Tile Mastic	1,150	SF	1944 Building- Room 152, Principal's Office, Room 253	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Brown Border Floor Tile	800	SF	1944 Building- Rooms 153, 155-157, 1st Floor Corridor, Rooms 252, 254- 257, 2nd Floor Corridor & Teachers' Restroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

SchoolGillespie SchoolUnit23321Building ID3530

Address 9301 S State Street Chicago, IL, 60619 Region 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

							<u> </u>		-		1 -
HA	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Num		Quantity	Units		Type	Category		Quantity	Units		
40	Brown Border Floor Tile Mastic	800	SF	1944 Building- Rooms 153, 155-157,	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				1st Floor Corridor, Rooms 252, 254-							
				257, 2nd Floor Corridor & Teachers'							
				Restroom	<u> </u>						- "
41	Brown Carpet Mastic	650	SF	1944 Building- Principal's Office, Main	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Disabilities d Deserbased	00	LF	Office	A = == = = = =	MICO	NI-		LF	C A CDAA with the area to a till for all areas are	Follow O&M Plan
42	Black Vinyl Baseboard Black Vinyl Baseboard Mastic	80		1944 Building- Room 250	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
43	,	80	LF	1944 Building- Room 250	Assumed		No	0		6 ACBM with the potential for damage	
44	9"x9" Tan w/Brown & White Streaks Floor Tile	100	SF	Patch in Room 256	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	9"x9" Tan w/Brown & White Streaks Floor Tile Mastic	100	SF	Patch in Room 256	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	9"x9" Cream Floor Tile	25	SF	Patch in Room 256	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	9"x9" Cream Floor Tile Mastic	25	SF	Patch in Room 256	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	9"x9" Brown w/White Streaks Floor Tile	500	SF	Room 215. Patch in Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	9"x9" Brown w/White Streaks Floor Tile Mastic	500	SF	Room 215, Patch in Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12"x12" White w/Gray Specks Floor Tile	4,000	SF	Lunchroom. Patches in Room 116.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
	12 A12 Trime in Gray opeans Tiest Ties	.,000	0.	Room 219, Under Water Fountain	7.00000				0.	o / to 2 m mar and poterman for damage	. 6.16.11 64.111 14.11
51	12"x12" White w/Gray Specks Floor Tile Mastic	4,000	SF	Lunchroom, Patches in Room 116,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Room 219, Under Water Fountain							
52	12"x12" Tan w/Brown Specks Floor Tile	900	SF	1944 Building- Room 154	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"x12" Tan w/Brown Specks Floor Tile Mastic	900	SF	1944 Building- Room 154	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12"x12" Light Red Floor Tile ABATED			1944 Building- Patch in Room 154	Abated	MISC					
55	12"x12" Light Red Floor Tile Mastic ABATED			1944 Building- Patch in Room 154	Abated	MISC					
56	12"x12" Peach Floor Tile	50	SF	1944 Building- Patches in Room 155,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Room 156							
57	12"x12" Peach Floor Tile Mastic	50	SF	1944 Building- Patches in Room 155, Room 156	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12"x12" Light Brown Floor Tile NOT OBSERVED			Patch in 1961 Corridor		MISC					
59	12x12 Light Brown Floor Tile Mastic NOT			Patch in 1961 Corridor	+	MISC					
00	OBSERVED			Tatorini 1301 Comdoi		WIIGO					
60	9x9 Pinkish Red w/White Streaks NOT			1961 Building- Entrance to 1st Floor		MISC					
	OBSERVED			Girls' Bathroom							
61	9x9 Pinkish Red w/White Streaks Mastic NOT			1961 Building- Entrance to 1st Floor		MISC		0			
	OBSERVED			Girls' Bathroom							
62	12x12 Cream w/Brown Specks Floor Tile	10	SF	1961 Building- Patch in Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12x12 Cream w/Brown Specks Floor Tile Mastic	10	SF	1961 Building- Patch in Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

SchoolGillespie SchoolUnit23321Building ID3530

Address 9301 S State Street Chicago, IL, 60619 Region 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

							<u> </u>				,
HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
64	12x12 Light Brown w/White Specks Floor Tile NOT OBSERVED			Patch in 1936 Corridor		MISC					
65	12x12 Light Brown w/White Specks Floor Tile Mastic NOT OBSERVED			Patch in 1936 Corridor		MISC					
66	9x9 Cream Floor Tile NOT OBSERVED			1961 Building- Patch at Entrance to Room 208		MISC					
67	9x9 Cream Floor Tile Mastic NOT OBSERVED			1961 Building- Patch at Entrance to Room 208		MISC					
68	12x12 Red Floor Tile NOT OBSERVED			1936 Building- Part of Corridor, Room 207, Room 107, Main Office		MISC					
69	12x12 Red floor Tile Mastic NOT OBSERVED			1936 Building- Part of Corridor, Room 207, Room 107, Main Office		MISC					
70	9x9 Black w/White Streaks Floor Tile NOT OBSERVED			Room 252, Patches in 1936 Corridor, Patches in Room 219, Patches in Teachers' Lunchroom		MISC					
71	9"x9" Black w/White Streaks Floor Tile Mastic NOT OBSERVED			Room 252, Patches in 1936 Corridor, Patches in Room 219, Patches in Teachers' Lunchroom		MISC					
72	12"x12" Red w/Black Specks Floor Tile	60	SF	1944 Building- Patches in Rooms 252, 155, 156	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12"x12" Red w/Black Specks Floor Tile Mastic	60	SF	1944 Building- Patches in Rooms 155, 156 & 252	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	Black Tile Border NOT OBSERVED			1936 Corridor- 1st & 2nd floors		MISC					
75	Black Tile Border Mastic NOT OBSERVED			1936 Corridor- 1st & 2nd Floors		MISC					
76	12"x12" Beige Floor Tile NOT OBSERVED			1st and 2nd Floor Hallways		MISC					
77	12"x12" Beige Floor Tile Mastic NOT OBSERVED			1st and 2nd Floor Hallways		MISC					
78	12 X 12 Beige w/Light Red and Light Blue Streaks Floor Tile	35,000	SF	1936, 1944 & 1961 Buildings- 1st Floor Corridors /1961 Building- 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78M	12"x12" Beige w/Light Red and Light Blue Streaks Floor Tile Mastic	35,000	SF	1936, 1944 & 1961 Buildings- 1st Floor Corridors /1961 Building- 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	Brown with Black Streaks Terrazzo	3,500	SF	1944 Building- Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Grey, White and Black Speckled Terrazzo	2,300	SF	1936 Building- Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Brown and Tan Mosaic Ceramic Tile Grout	1,800	SF	1936 Building- Boys and Girls Toilets and Vestibules	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

SchoolGillespie SchoolUnit23321Building ID3530

Address 9301 S State Street Chicago, IL, 60619 Region 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

						1	<u> </u>	riaiiie	i s com	nents Summarized at th	e Liiu oi iiie Neport
HA	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Num		Quantity	Units		Туре	Category		Quantity	Units		
81M	Brown and Tan Mosaic Ceramic Tile Mastic	1,800	SF	1936 Building- Boys and Girls Toilets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				and Vestibules						-	
82	4"x4" Red Ceramic Tile Grout	600	SF	1961 Building- Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82M	4"x4" Red Ceramic Tile Grout	600	SF	1961 Building- Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	Light and Dark Orange Speckled Terrazzo	3,600	SF	1961 Building - Stairs and Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Beige with Yellow Specks Terrazzo	2,200	SF	1961 Building- Stairs and Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Blue Carpet Mastic	2,200	SF	1961 Building- Library and Room 118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	Acoustical Ceiling Plaster	14,500	SF	1961 Building- Throughout Ceilings	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Tan Mosaic Ceramic Tile Grout	2,600	SF	1944 Building- Boys and Girls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Washrooms and Vestibules							
87M	Tan Mosaic Ceramic Tile Mastic	2,600	SF	1944 Building- Boys' & Girls'	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Washrooms and Vestibules							
88	Multicolor Mosaic Floor Tile Grout	1,600	SF	1961 Building- Boys' & Girls'	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Washrooms and Vestibules							
89	Multicolor Mosaic Floor Tile Mastic	1,600	SF	1961 Building- Boys' & Girls'	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Washrooms and Vestibules							
90	12"x12" Light Grey w/Dark Grey Streaks Floor Tile	7,400	SF	1936 & 1944 Buildings- 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Corridors							
90M	12"x12" Light Grey w/Dark Grey Streaks Floor Tile	7,400	SF	1936 & 1944 Buildings- 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
	Mastic			Corridors							
91	12"x12" Royal Blue Vinyl Floor Tile	60	SF	1961 Building- 1st Floor Men's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Restroom							
91A	12"x12" Royal Blue Vinyl Floor Tile Mastic	60	SF	1961 Building- 1st Floor Men's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Restroom				_			- "
92	12"x12" Red Vinyl Floor Tile	60	SF	1961 Building- 1st Floor Women's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Restroom				_			- "
92A	12"x12" Red Vinyl Floor Tile Mastic	60	SF	1961 Building- 1st Floor Women's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
	1011 1011 PL 01 1 1 1 1 1 1 1 1 1 1 1	0.400	0=	Restroom			l		0-	2.40214 19 19 19 19 19	5 II 00MBI
93	12"x12" Blue Streaked Vinyl Floor Tile	2,400	SF	1944 Building- Gym/Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93A	12"x12" Blue Streaked Vinyl Floor Tile Mastic	2,400	SF	1944 Building- Gym/Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12"x12" Blue Streaked Vinyl Floor Tile	3,000	SF	1961 Building- Gym/Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94A	12"x12" Blue Streaked Vinyl Floor Tile Mastic	3,000	SF	1961 Building- Gym/Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Α	Boiler Insulation NOT OBSERVED			Boiler Room		TSI					
В	Boiler Breaching NOT OBSERVED			Boiler Room		TSI					
С	Aircell Pipe Insulation	2,500	LF	1944 Building- Coal Room, Boiler	Chrysotile	TSI	Yes	50	LF	1 Damaged or significantly damaged	Repair
				Room & Unfinished Pipe Space						friable thermal system insulating ACBM	

SchoolGillespie SchoolUnit23321Building ID3530

Address 9301 S State Street Chicago, IL, 60619 Region 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Num	·	Quantity	Units		Туре	Category		Quantity	Units		·
D	Aircell Pipe Joint Insulation	175	LF	1944 Building- Coal Room & Unfinished Pipe Space	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	Tank Insulation NOT OBSERVED			Pump Room		TSI					
F	Paper-Wrap Pipe Insulation	700	LF	1944 Building- Boys and Girls Toilet, Chases and Crawlspace	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	Paper-Wrap Pipe Joint Insulation	80	LF	1944 Building- Boys and Girls Toilet, Chases and Crawlspace	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Н	Duct Insulation	1,000	SF	1944 Building- Unfinished Pipe Space	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	Duct Insulation	1,200	SF	1936 Building- Unfinished Pipe Space	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	Fiberglass Joint Insulation	345	LF	1961 Building- Unfinished Pipe Space	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	Tank Insulation NOT OBSERVED			Boiler Room		TSI					
N	Fiberglass Joint Insulation	170	LF	Unfinished Pipe Space	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and Afte Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
Р	Aircell Pipe Insulation	100	LF	1961 Building- Unfinished Pipe Space & Outside Engineer's Office	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
R	Fiberglass Joint Insulation	60	LF	1944 Building- Coal Room & Unfinished Pipe Space	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Τ	Incinerator Insulation NOT OBSERVED	·		1944 Building- Boiler Room		TSI		0			

 School
 Gillespie School
 Unit
 23321
 Building ID
 3530

 Address
 9301 S State Street
 Chicago, IL, 60619
 Region
 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Review Date	9/2/2022				
Manager Planner Name	Daniel Juneau				
100-03613	5/15/2023				
Manager IDPH License No/Expiration					

Management Comments

 School
 Gillespie School
 Unit
 23321
 Building ID
 3530

 Address
 9301 S State Street
 Chicago, IL, 60619
 Region
 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

HA Number	Management Comments  Management Comments
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	

SchoolGillespie SchoolUnit23321Building ID3530Address9301 S State StreetChicago, IL, 60619Region06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
47	
48	
49	
50	
51	
52	
53	
54	
54 55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	

 School
 Gillespie School
 Unit
 23321
 Building ID
 3530

 Address
 9301 S State Street
 Chicago, IL, 60619
 Region
 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments  Management Comments
74	
75	
76	
77	
78	
78M	
79	
80	
81	
81M	
82	
82M	
83	
84	
85	
86	
87	
87M	
88	
89	
90	
90M	
91	
91A	
92	
92A	
93	

 School
 Gillespie School
 Unit
 23321
 Building ID
 3530

 Address
 9301 S State Street
 Chicago, IL, 60619
 Region
 06

### **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
93A	
94	
94A	
Α	
В	
С	Replace or Repair Damaged Insulation
D	
E	
F	
G	
Н	
1	
K	
L	
N	
NEW	
Р	
R	
T	

## APPENDIX A

## **Assessment Sheets, Drawings and Photos**

TEM Environmental, Inc. 2022 AHERA REINSPECTION

# TEM Environmental, Inc. 2022 AHERA REINSPECTION Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 01

MATERIAL DESCRIPTION: Green Linoleum

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 Building- Room 250

MATERIAL QUANTITY: 700 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Varke & College	Date:	08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	01						
MATERIAL DESCRI	PTION:	Green Linoleum						
MATERIAL LOCATI	ON:	1936 Building- R	toom 250					
MATERIAL QUANTI	TY:	700			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Υ:	0			DAMAGE UNITS	3:	SF	
n accordance with Semanagement planner original inspection of the following recommend	to review the above	the results of the ir	spection and assess	ment and reco	mmend appropria	ate respo	nse actions.	The
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Sig	pature.	Jule Cl	-	Date:	09/02/20	122	
managomoni i lan	noi o oigi	iaturo.			Daic.	JJ1 JZ1 Z	<i>,</i>	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02

MATERIAL DESCRIPTION: 9"x9" Orange Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 256, Engineer's Office

MATERIAL QUANTITY: 775 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Value & Cottes	Date:	08/09/2022	
•				

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO:	:	100-20327		
HOMOGENEOUS A	REA:	02					
MATERIAL DESCRI	PTION:	9"x9" Orange Flo	oor Tile				
MATERIAL LOCATION	ON:	1944 Building- R	oom 256, Engineer'	s Office			
MATERIAL QUANTI	TY:	775			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with ne following recommendations.						nse actions. The	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Siar	pature:	succe	-	Date:	00/02/20	122

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03

MATERIAL DESCRIPTION: 12"x12" Tan Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 107, Corridor/Gym Rooms 155-157 & Corridor

MATERIAL QUANTITY: 4700 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Ethis			
Inspector's Signature:	Vac	Date:	08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

LEA NAME:	Chicago	Public Schools	UNII NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	):	100-20327			
HOMOGENEOUS A	REA:	03						
MATERIAL DESCRI	PTION:	12"x12" Tan Flo	or Tile					
MATERIAL LOCATION	ON:	1944 Building- R	Room 107, Corridor/	Gym Rooms	155-157 & Corrid	or		
MATERIAL QUANTI	TY:	4700			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
In accordance with Semanagement planner original inspection of the following recommendation of the RESPONSE ACCORDANCE FOLLOW O&M Plan  Comments:	to review the above endations.	the results of the ir identified homoger	nspection and assess	sment and reco	ommend appropria	ate respo		

Date: 09/02/2022

Management Planner's Signature:

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05

MATERIAL DESCRIPTION: 9"x9" Brown Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1936 Building- 1st & 2nd Floor Corridors

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

	Jake E Editis		
Inspector's Signature:	Voc	Date: 08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	_ANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S State Street		IDPH LICENSE NO	):	100-20327	
HOMOGENEOUS A	REA:	05				
MATERIAL DESCRI	PTION:	9"x9" Brown Flo	oor Tile NOT OBSE	RVED		
MATERIAL LOCATION	ON:	1936 Building- 1	st & 2nd Floor Cor	ridors		
MATERIAL QUANTI	TY:				MATERIAL UNIT	S:
DAMAGE QUANTIT	Y:				DAMAGE UNITS	:
management planner	to review he above	the results of the ir identified homoger	nspection and asses	sment and reco	ommend appropria	ERA) the LEA must select a teresponse actions. The ections 763.88 and 763.90 with
The RESPONSE AC	CTION rec	ommendation is:				
Comments:						
Management Plan	norle Cier	noturo:	Jucce	-	Doto	00/02/2022
wanayement rian	rici s sigi	nature.			Date: _	09/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 06

MATERIAL DESCRIPTION: 9"x9" Brown Floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1936 Building- 1st & 2nd Floor Corridor

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

D/ Cottus

COMMENTS: Not Observed

Inspector's Signature:	Vaire S	Date:	08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S \$	State Street	IDPH LICENSE NC	):	100-20327	
HOMOGENEOUS A	REA:	06				
MATERIAL DESCRI	PTION:	9"x9" Brown Flo	oor Tile Mastic NOT	OBSERVED		
MATERIAL LOCATION	ON:	1936 Building- 1	st & 2nd Floor Corr	idor		
MATERIAL QUANTI	TY:				MATERIAL UNIT	rs:
DAMAGE QUANTIT	Y:				DAMAGE UNITS	5:
management planner original inspection of t he following recomme	n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with ne following recommendations.					
The RESPONSE AC	CTION reco	ommendation is:				
Comments:						
Management Plan	ner's Sigi	nature:	Jucces	-	Date:	09/02/2022
<u> </u>	3					

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07

MATERIAL DESCRIPTION: 12"x12" Red Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Rooms 153, 155-157, 252, 254, 255, 257, Gym, Assembly Hall, Book

Room

MATERIAL QUANTITY: 7000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

DI ATI

Inspector's Signature:	Varke & Estas	Date:	08/09/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	_ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillesp	ie School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327		
HOMOGENEOUS A	AREA:	07					
MATERIAL DESCRIPTION: 12"x12" Red Fig		oor Tile					
MATERIAL LOCATION: 1944 Building- Ro			Rooms 153, 155-157	, 252, 254, 25	5, 257, Gym, Ass	sembly H	-lall, Book Room
MATERIAL QUANT	ITY:	7000			MATERIAL UNI	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNIT	S:	SF
In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.							
The RESPONSE AC	CTION red	commendation is:					
Follow O&M Plan							

Date: 09/02/2022

Comments:

Management Planner's Signature:

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08

MATERIAL DESCRIPTION: 12"x12" Red Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Rooms 153, 155-157, 252, 254, 255, 257, Gym, Assembly Hall, Book

Room

MATERIAL QUANTITY: 7000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

DI ATI

Inspector's Signature:	Varke & Estas	Date:	08/09/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530 CITY/STATE: Chicago, Illinois MANAGEMENT PLANNER: **Daniel Juneau** Gillespie School SCHOOL NAME: **REVIEW DATE:** 9/2/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 HOMOGENEOUS AREA: 80 12"x12" Red Floor Tile Mastic MATERIAL DESCRIPTION: MATERIAL LOCATION: 1944 Building- Rooms 153, 155-157, 252, 254, 255, 257, Gym, Assembly Hall, Book Room MATERIAL QUANTITY: 7000 MATERIAL UNITS: SF DAMAGE QUANTITY: DAMAGE UNITS: 0 SF In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations. The RESPONSE ACTION recommendation is: Follow O&M Plan Comments: Allele

Date: 09/02/2022

Management Planner's Signature:

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 09

MATERIAL DESCRIPTION: 9"x9" Beige Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Lunchroom, Boys' Toilet, Room 118 & 120, and 1st Floor Gym

MATERIAL QUANTITY: 3950 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Daker Estis			
Inspector's Signature:	Vacate	Date:	08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 353	0
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	_ANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	):	100-20327	
HOMOGENEOUS A	REA:	09				
MATERIAL DESCRI	PTION:	9"x9" Beige Floo	or Tile			
MATERIAL LOCATION	ON:	1961 Building- L	unchroom, Boys' T	oilet, Room 1	18 & 120, and 1st Flo	or Gym
MATERIAL QUANTI	TY:	3950			MATERIAL UNITS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF
management planner original inspection of t the following recomme The RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	sment and reco	ommend appropriate re	A) the LEA must select a esponse actions. The ns 763.88 and 763.90 with
Follow O&M Plan						
Comments:						
Management Plan	ner's Sigi	nature:	succe	-	Date: <b>09/</b> 0	02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 10

MATERIAL DESCRIPTION: 9"x9" Beige Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- 1st Floor Gym, Lunchroom, Boys' Toilet, Rooms 118 & 120

MATERIAL QUANTITY: 3950 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Dake & Estis			
Inspector's Signature:	Voire C	Date:	08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO:	:	100-20327		
HOMOGENEOUS A	REA:	10					
MATERIAL DESCRI	PTION:	9"x9" Beige Floo	or Tile Mastic				
MATERIAL LOCATION	ON:	1961 Building- 1	st Floor Gym, Luncl	nroom, Boys'	Toilet, Rooms 1	18 & 120	
MATERIAL QUANTI	TY:	3950			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner original inspection of the he following recomme	to review t he above i	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	oorlo Sigr	The state of the s	Jucce	-	Data	00/02/20	22

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: 9"x9" Tan Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Rooms 114-120, 200, 209, 210, 212, 214, 216-220, 1st & 2nd Floor

Corridors, Teachers Restroom & Lunchroom, Storeroom, W Teachers Room, and

Vault

MATERIAL QUANTITY: 20000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Estis	Date:	08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois MANAGEMENT PLANNER: Daniel Juneau

SCHOOL NAME: Gillespie School REVIEW DATE: 9/2/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: 9"x9" Tan Floor Tile

MATERIAL LOCATION: 1961 Building- Rooms 114-120, 200, 209, 210, 212, 214, 216-220, 1st & 2nd Floor Corridors,

Teachers Restroom & Lunchroom, Storeroom, W Teachers Room, and Vault

MATERIAL QUANTITY: 20000 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow	O&M	Plan
--------	-----	------

Comments:

	Aucel			
Management Planner's Signature:	140	Date:	09/02/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12

MATERIAL DESCRIPTION: 9"x9" Tan Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Rooms 114-120, 200, 209, 210, 212, 214, 216-220, 1st & 2nd Floor

Corridors, Teachers' Restroom & Lunchroom, Storeroom, W Teachers' Room, and

Vault

MATERIAL QUANTITY: 20000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

D/ Ative

Inspector's Signature:	Vale 2 cours	Date:	08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530
CITY/STATE: Chicago, Illinois MANAGEMENT PLANNER: Daniel Juneau

SCHOOL NAME: Gillespie School REVIEW DATE: 9/2/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

HOMOGENEOUS AREA: 12

MATERIAL DESCRIPTION: 9"x9" Tan Floor Tile Mastic

MATERIAL LOCATION: 1961 Building- Rooms 114-120, 200, 209, 210, 212, 214, 216-220, 1st & 2nd Floor Corridors,

Teachers' Restroom & Lunchroom, Storeroom, W Teachers' Room, and Vault

MATERIAL QUANTITY: 20000 MATERIAL UNITS: SF

DAMAGE QUANTITY: 5 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow	O&M	Plan
--------	-----	------

Comments:

	Aucel			
Management Planner's Signature:	160	Date:	09/02/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13

MATERIAL DESCRIPTION: Smooth Plaster

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Throughout

MATERIAL QUANTITY: 96000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Edition			
Inspector's Signature:	Vot	Date:	08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	13						
MATERIAL DESCRI	PTION:	Smooth Plaster						
MATERIAL LOCATION	ON:	1944 Building- T	hroughout					
MATERIAL QUANTI	TY:	96000			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Semanagement planner original inspection of the following recommendations and the following recommendations are according to the following recommendations and the following recommendations are according to the following to the fo	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	mmend appropria	ate respo	nse actions. 1	Γhe
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	norlo Cia-	noturo:	Julle	_	Data	00/00/0	222	
ivianayement Pian	1151 2 2101	ialuit.			Date:	09/02/20	144	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14

MATERIAL DESCRIPTION: Insulation in Fire Rated Doors

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: 2 MATERIAL UNITS: EA

DAMAGE QUANTITY: DAMAGE UNITS: **EA** 

	Darke & Cotty			
Inspector's Signature:	Voc	Date:	08/09/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

			9					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327			
HOMOGENEOUS A	REA:	14						
MATERIAL DESCRI	PTION:	Insulation in Fire	Rated Doors					
MATERIAL LOCATION	ON:	Boiler Room						
MATERIAL QUANTI	TY:	2			MATERIAL UNIT	S:	EA	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	:	EA	
In accordance with Semanagement planner original inspection of the following recommender.  The RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	sment and reco	ommend appropria	ite respo	nse actions. T	he
Follow O&M Plan								
Comments:								
Management Plan	ner's Sig	nature:	Juli Cl	<del>.</del>	Date:	09/02/20	122	
	9						-	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15

MATERIAL DESCRIPTION: Black Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Boom 118, 209

MATERIAL QUANTITY: 210 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

Inspector's Signature:	Docke & Estres	Date:	08/09/2022	
,				

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	15						
MATERIAL DESCRI	PTION:	Black Vinyl Base	eboard					
MATERIAL LOCATION	ON:	1961 Building- B	soom 118, 209					
MATERIAL QUANTI	TY:	210			MATERIAL UNI	ΓS:	LF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	LF	
n accordance with Semanagement planner original inspection of the following recommendation of the following recommendation.	to review the above	the results of the ir identified homoger	spection and assess	ment and reco	mmend appropri	ate respo	onse actions. 7	Γhe
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
			Julce	-				
Management Plan	ner's Siai	nature:			Date:	09/02/20	022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 16

MATERIAL DESCRIPTION: Black Vinyl Baseboard Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Room 118, 209

MATERIAL QUANTITY: 210 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

Inspector's Signature:	Docke & Estis	Date:	08/09/2022	
. 5				

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

			<del>-</del>					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	16						
MATERIAL DESCRI	PTION:	Black Vinyl Base	eboard Mastic					
MATERIAL LOCATION	ON:	1961 Building- R	oom 118, 209					
MATERIAL QUANTI	TY:	210			MATERIAL UNI	TS:	LF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	<b>S</b> :	LF	
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the in	spection and assess	ment and reco	mmend appropri	ate respo	nse actions. 1	he
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Siar	nature:	Succes	-	Date:	09/02/20	022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17

MATERIAL DESCRIPTION: Smooth Plaster

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 Building- Throughout

MATERIAL QUANTITY: 120000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docke & Estis	Date:	08/09/2022	
. 5				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	17						
MATERIAL DESCRI	PTION:	Smooth Plaster						
MATERIAL LOCATION	ON:	1936 Building- T	hroughout					
MATERIAL QUANTI	TY:	120000			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Semanagement planner original inspection of the following recommend	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	mmend appropria	ate respo	nse actions. T	he
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
		The state of the s	Jucce co	-				
Management Plan	ner's Sigi	nature:			Date:	09/02/20	)22	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18

MATERIAL DESCRIPTION: Smooth Plaster

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Throughout

MATERIAL QUANTITY: 27500 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Ethis	Date:	08/09/2022	
. 5				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 3	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NC	):	100-20327		
HOMOGENEOUS A	REA:	18					
MATERIAL DESCRI	PTION:	Smooth Plaster					
MATERIAL LOCATION	ON:	1961 Building- T	hroughout				
MATERIAL QUANTI	TY:	27500			MATERIAL UNITS	S:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	:	SF
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the ir identified homoger	spection and assess	sment and reco	ommend appropriat	te respoi	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Siar	nature:	Jucces	-	Date: (	09/02/20	22

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 19

MATERIAL DESCRIPTION: Green Linoleum Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 250

MATERIAL QUANTITY: 700 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Ething			
Inspector's Signature:	Vot	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	19					
MATERIAL DESCRI	PTION:	Green Linoleum	Mastic				
MATERIAL LOCATION	ON:	1944 Building- R	toom 250				
MATERIAL QUANTI	TY:	700			MATERIAL UNIT	S: <b>\$</b>	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	: 8	SF
n accordance with Semanagement planner original inspection of the following recommendations are as a second control of the following recommendations.	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	te respon	se actions. The
The RESPONSE AC	CTION reco	ommendation is:					
Follow O&M Plan							
Comments:							
			Jucce co	-			
Management Plan	ner's Sigi	nature:			Date: 0	09/02/202	22

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20

MATERIAL DESCRIPTION: 9"x9" Orange Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 256, Engineer's Office

MATERIAL QUANTITY: 775 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docke & Ething	Date:	08/09/2022	
, ,				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS AI	REA:	20					
MATERIAL DESCRI	PTION:	9"x9" Orange Flo	oor Tile Mastic				
MATERIAL LOCATION	ON:	1944 Building- R	toom 256, Engineer'	s Office			
MATERIAL QUANTI	ΓY:	775			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner to priginal inspection of the he following recomme	to review t ne above i	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plans	oorlo Sicr	natura:	JULCEL	-	Date:	00/02/20	122

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21

MATERIAL DESCRIPTION: Transite Desktops

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 209

MATERIAL QUANTITY: 30 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Dake & Ethis		
Inspector's Signature:	Varie C 3	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespie	School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	21						
MATERIAL DESCRI	PTION:	Transite Desktop	os					
MATERIAL LOCATION	ON:	Room 209						
MATERIAL QUANTI	TY:	30			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Semanagement planner original inspection of the following recommend	to review the above in the abov	he results of the ir dentified homoger	spection and assess	ment and reco	mmend appropria	ate respo	nse actions. T	he
The RESPONSE AC	CTION reco	mmendation is:						
Follow O&M Plan								
Comments:								
		(A)	Mecco.	-				
Management Plan	ner's Sigr	nature:			Date:	09/02/20	)22	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22

MATERIAL DESCRIPTION: Counter Tops

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Room 209

MATERIAL QUANTITY: 20 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Edition	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	22						
MATERIAL DESCRI	PTION:	Counter Tops						
MATERIAL LOCATION	ON:	1961 Building- R	loom 209					
MATERIAL QUANTI	TY:	20			MATERIAL UNIT	S:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	:	SF	
In accordance with Semanagement planner original inspection of the following recomments of the RESPONSE AC	to review the above lendations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ite respo	nse actions. T	he
Follow O&M Plan								
Comments:								
Management Plan	ner's Sigr	nature:	succe	-	Date:	09/02/20	)22	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23

MATERIAL DESCRIPTION: 12"x12" Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- 1st Floor Lobby, Room 220, Lunchroom

MATERIAL QUANTITY: 2000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Dake & Cotty			
Inspector's Signature:	Villa de Company	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	23					
MATERIAL DESCRI	PTION:	12"x12" Ceiling	Tile				
MATERIAL LOCATION	ON:	1961 Building- 1	st Floor Lobby, Roc	m 220, Lunch	nroom		
MATERIAL QUANTI	TY:	2000			MATERIAL UNIT	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
management planner original inspection of t	n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with ne following recommendations.						
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Sigr	nature:	Jule Cle	-	Date:	00/02/20	122

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24

MATERIAL DESCRIPTION: 9"x9" Brown Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1961 Building- 1st & 2nd Floor Corridor

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

D/ Cottus

COMMENTS: Not Observed

Inspector's Signature:	Vaine C	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNII NUMBER:	23321	BUIDLING ID: 3530					
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PI	_ANNER:	Daniel Juneau					
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022					
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327					
HOMOGENEOUS A	REA:	24								
MATERIAL DESCRI	PTION:	9"x9" Brown Flo	oor Tile NOT OBSEI	RVED						
MATERIAL LOCATION	:NC	1961 Building- 1	31 Building- 1st & 2nd Floor Corridor							
MATERIAL QUANTI	TY:				MATERIAL UNITS:					
DAMAGE QUANTIT	Y:				DAMAGE UNITS:					
management planner original inspection of t he following recomme	a accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.  The RESPONSE ACTION recommendation is:									
Comments:										
Management Plan	ner's Sig	nature:	Jucce e le	-	Date: <u>09/02/2022</u>					

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25

MATERIAL DESCRIPTION: 9"x9" Brown Floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1961 Building- 1st & 2nd Floor Corridor

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

D/ Cottus

COMMENTS: Not Observed

Inspector's Signature:	Vaine C	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespie	School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	):	100-20327	
HOMOGENEOUS AF	REA:	25				
MATERIAL DESCRIP	PTION:	9"x9" Brown Flo	or Tile Mastic NOT	OBSERVED		
MATERIAL LOCATIO	N:	1961 Building- 1	st & 2nd Floor Corr	idor		
MATERIAL QUANTIT	ΓΥ:				MATERIAL UNIT	S:
DAMAGE QUANTITY	<b>/</b> :				DAMAGE UNITS	3:
nanagement planner to riginal inspection of th	accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a anagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The iginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with e following recommendations.					
THE REST SINGE AS	TIOIV ICCO	minendation is.				
Comments:						
Management Plann	ner's Sigr	nature:	succe	-	Date: _	09/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26

MATERIAL DESCRIPTION: 9"x9" Black Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1936 Building- 1st & 2nd Floor Corridor

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:	Dake Ethis	Date	e:	08/09/2022	
	-				 

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT P	LANNER:	Daniel Juneau
SCHOOL NAME:	Gillespi	ie School	REVIEW DATE:		9/2/2022
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327
HOMOGENEOUS A	REA:	26			
MATERIAL DESCRIPTION: 9"x9" Black Flo		or Tile NOT OBSER	VED		
MATERIAL LOCATI	ON:	1936 Building- 1	st & 2nd Floor Cor	ridor	
MATERIAL QUANTI	ITY:				MATERIAL UNITS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS:
nanagement planner	to review the above	the results of the inidentified homoger	nspection and asses	sment and rec	Response Act (AHERA) the LEA must select a ommend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION rec	ommendation is:			
Comments:					
			Ducces		
Management Plan	ner's Sig	nature:	Share S		Date: <u>09/02/2022</u>

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27

MATERIAL DESCRIPTION: 9"x9" Black Floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1936 Building-1st & 2nd Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:	Daker Ethy	Date:	08/09/2022	
1 0				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S \$	State Street	IDPH LICENSE NC	):	100-20327		
HOMOGENEOUS A	REA:	27					
MATERIAL DESCRI	PTION:	9"x9" Black Floo	or Tile Mastic NOT (	DBSERVED			
MATERIAL LOCATION	ON:	1936 Building-1s	st & 2nd Floor Corri	dor			
MATERIAL QUANTI	TY:				MATERIAL UNIT	ΓS:	
DAMAGE QUANTIT	Y:				DAMAGE UNITS	S:	
management planner original inspection of the following recommender he following recommender in the following recommender	a accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a panagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.						
The RESPONSE AC	TION reco	ommendation is:					
Commenter							
Comments:							
Management Plan	ner's Sig	nature:	Jucce co	~	Date: _	09/02/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Inspector Assessment Form (REASSESSMENT)**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28

MATERIAL DESCRIPTION: 12"x12" Light Grey Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1936 Building- Room 102

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:	Daker Ethy	Date:	08/09/2022	
1 0				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327	
HOMOGENEOUS A	REA:	28				
MATERIAL DESCRI	PTION:	12"x12" Light G	rey Floor Tile NOT 0	BSERVED		
MATERIAL LOCATION	ON:	1936 Building- R	Room 102			
MATERIAL QUANTI	TY:				MATERIAL UNI	TS:
DAMAGE QUANTITY	Y:				DAMAGE UNITS	S:
management planner or priginal inspection of the he following recomment	a accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a transparent planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.					
The RESPONSE AC	TION reco	ommendation is:				
Comments:						
M		A	Jucce e	-	5.	
Management Plani	ner's Sigi	nature:			Date: _	09/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Inspector Assessment Form (REASSESSMENT)**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29

MATERIAL DESCRIPTION: 12"x12" Light Grey Floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1936 Building- Room 102

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:	Dake Ethis	Date	e:	08/09/2022	
	-				 

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327
HOMOGENEOUS A	AREA:	29			
MATERIAL DESCR	IPTION:	12"x12" Light G	rey Floor Tile Masti	c NOT OBSE	RVED
MATERIAL LOCATI	ON:	1936 Building- F	Room 102		
MATERIAL QUANT	ITY:				MATERIAL UNITS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS:
nanagement planner	to review the above	the results of the initial identified homogerates	nspection and assess	sment and reco	Response Act (AHERA) the LEA must select a ommend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION rec	ommendation is:			
Comments:					
			ducce		
Management Plan	ner's Sig	nature:			Date: 09/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30

MATERIAL DESCRIPTION: 12"x12" Light Grey Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 Building- Room 106

MATERIAL QUANTITY: 680 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Ethis	Date:	08/09/2022	
. 5				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO:	:	100-20327		
HOMOGENEOUS A	REA:	30					
MATERIAL DESCRI	PTION:	12"x12" Light Gr	ey Floor Tile				
MATERIAL LOCATION	ON:	1936 Building- R	oom 106				
MATERIAL QUANTI	TY:	680			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with ne following recommendations.							
The RESPONSE AC	TION reco	mmendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Siar	nature:	succe	-	Date:	00/02/20	122

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31

MATERIAL DESCRIPTION: 12"x12" Light Grey Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 Building- Room 106

MATERIAL QUANTITY: 680 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Edition	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	31						
MATERIAL DESCRI	PTION:	12"x12" Light G	rey Floor Tile Mastic					
MATERIAL LOCATION	ON:	1936 Building- R	oom 106					
MATERIAL QUANTI	TY:	680			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Semanagement planner original inspection of the following recomme	to review the above	the results of the ir identified homoger	spection and assess	ment and reco	mmend appropri	ate respo	onse actions. T	he
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
			Julce					
Management Plan	ner's Siai	nature:	5		Date:	09/02/20	022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32

MATERIAL DESCRIPTION: 12"x12" Light Brown Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Teachers' Lunchroom & Corridor, and Room 102

MATERIAL QUANTITY: 200 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Ething			
Inspector's Signature:	Vaire 5	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO:	:	100-20327		
HOMOGENEOUS A	REA:	32					
MATERIAL DESCRI	PTION:	12"x12" Light Br	own Floor Tile				
MATERIAL LOCATION	ON:	1961 Building- T	eachers' Lunchroor	n & Corridor,	and Room 102		
MATERIAL QUANTI	TY:	200			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with ne following recommendations.							
The RESPONSE AC	TION reco	mmendation is:					
Follow O&M Plan							
Comments:							
Management Plan	oor's Sign	noture:	Juccel	-	Data	00/02/20	122

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33

MATERIAL DESCRIPTION: 12"x12" Light Brown Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Teachers Lunchroom & Corridor, and Room 102

MATERIAL QUANTITY: 200 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Ething			
Inspector's Signature:	Vaire 5	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S	State Street	IDPH LICENSE NC	):	100-20327		
HOMOGENEOUS A	REA:	33					
MATERIAL DESCRI	PTION:	12"x12" Light B	rown Floor Tile Mas	tic			
MATERIAL LOCATION	ON:	1961 Building- T	eachers Lunchroor	n & Corridor,	and Room 102		
MATERIAL QUANTI	TY:	200			MATERIAL UNI	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	<b>S</b> :	SF
In accordance with Semanagement planner original inspection of the following recommendation of the RESPONSE ACFOLLOW O&M Plan	to review he above endations.	the results of the ir identified homoger	nspection and assess	sment and reco	ommend appropri	ate respo	
Comments:							
Management Plan	ner's Sig	nature:	Julece	-	Date: _	09/02/20	022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34

MATERIAL DESCRIPTION: 12"x12" Tan Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- 1st Floor Storeroom, Patch in Room 118

MATERIAL QUANTITY: 170 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Daker Cottes			
Inspector's Signature:	Vac per s	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			•					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespie	School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NC	:	100-20327			
HOMOGENEOUS A	REA:	34						
MATERIAL DESCRI	PTION:	12"x12" Tan Flo	or Tile					
MATERIAL LOCATION	ON:	1961 Building- 1	st Floor Storeroom	, Patch in Roo	om 118			
MATERIAL QUANTI	TY:	170			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
In accordance with Se management planner original inspection of t the following recomme	to review t he above i endations.	he results of the ir dentified homoger	spection and assess	ment and reco	ommend appropri	ate respo	nse actions.	The
The RESPONSE AC	TION reco	mmendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Sigr	nature:	Jucce Ce	-	Date:	09/02/20	)22	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35

MATERIAL DESCRIPTION: 12"x12" Tan Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- 1st Floor Storeroom, Patch in Room 118

MATERIAL QUANTITY: 170 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docke & Ething	Date:	08/09/2022	
, ,				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 3	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	35					
MATERIAL DESCRI	PTION:	12"x12" Tan Flo	or Tile Mastic				
MATERIAL LOCATION	ON:	1961 Building- 1	st Floor Storeroom	Patch in Roc	om 118		
MATERIAL QUANTI	TY:	170			MATERIAL UNITS	S: <b>S</b>	SF.
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	S	6F
In accordance with Semanagement planner original inspection of the following recommender The RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropriat	e respons	se actions. The
Follow O&M Plan							
Comments:							
Management Plan	ner's Sig	nature:	succe	-	Date: 0	9/02/202	2
, J <b></b>	9						

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 36

MATERIAL DESCRIPTION: 12"x12" Tan Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 107, Corridor/Gym, Rooms 155-157 & Corridor

MATERIAL QUANTITY: 4700 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Cotty			
Inspector's Signature:	Vaire C	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	36					
MATERIAL DESCRI	PTION:	12"x12" Tan Flo	or Tile Mastic				
MATERIAL LOCATION	ON:	1944 Building- R	oom 107, Corridor/	Gym, Rooms	155-157 & Corric	dor	
MATERIAL QUANTI	TY:	4700			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Semanagement planner original inspection of the following recomment of the RESPONSE ACTION O&M Plan	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	
Comments:							
Management Plan	ner's Sigi	nature:	Jule Cle	-	Date:	09/02/20	022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37

MATERIAL DESCRIPTION: 12"x12" Dark Brown Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 152, Principal's Office & Room 253

MATERIAL QUANTITY: 1150 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Edition	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	37						
MATERIAL DESCRI	PTION:	12"x12" Dark Br	own Floor Tile					
MATERIAL LOCATION	ON:	1944 Building- R	oom 152, Principal'	s Office & Ro	om 253			
MATERIAL QUANTI	TY:	1150			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Se management planner original inspection of t he following recomme	to review t he above	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	onse actions. The	
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
			\					
Management Plan	ner's Sigr	nature:	succe.	-	Date:	09/02/20	)22	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 38

MATERIAL DESCRIPTION: 12"x12" Dark Brown Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 152, Principal's Office, Room 253

MATERIAL QUANTITY: 1150 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Darke & Cottes	Date:	08/09/2022	
		_		

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	38					
MATERIAL DESCRI	PTION:	12"x12" Dark Br	own Floor Tile Mast	ic			
MATERIAL LOCATION	ON:	1944 Building- R	loom 152, Principal'	s Office, Roo	m 253		
MATERIAL QUANTI	TY:	1150			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	3:	SF
n accordance with Semanagement planner original inspection of the following recomment.  The RESPONSE ACTION O&M Plan	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	
Comments:							
Management Plan	ner's Sigr	nature:	Jucce Co	-	Date:	09/02/20	)22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39

MATERIAL DESCRIPTION: Brown Border Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Rooms 153, 155-157, 1st Floor Corridor, Rooms 252, 254-257, 2nd Floor

**Corridor & Teachers' Restroom** 

MATERIAL QUANTITY: 800 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

DI ATI

Inspector's Signature:	Voeke & Estes	Date:	08/09/2022
mopecion o orginalure.		Date.	00/03/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Management Planner Review Form**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois MANAGEMENT PLANNER: Daniel Juneau

SCHOOL NAME: Gillespie School REVIEW DATE: 9/2/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

HOMOGENEOUS AREA: 39

MATERIAL DESCRIPTION: Brown Border Floor Tile

MATERIAL LOCATION: 1944 Building- Rooms 153, 155-157, 1st Floor Corridor, Rooms 252, 254-257, 2nd Floor Corridor &

**Teachers' Restroom** 

MATERIAL QUANTITY: 800 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Folle	ow O	&M	Plan
-------	------	----	------

Comments:

	Allele			
Management Planner's Signature:		Date:	09/02/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40

MATERIAL DESCRIPTION: Brown Border Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Rooms 153, 155-157, 1st Floor Corridor, Rooms 252, 254-257, 2nd Floor

Corridor & Teachers' Restroom

MATERIAL QUANTITY: 800 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

DI ATI

COMMENTS: Abated from Teachers' Restroom

	Jacke & Every		
Inspector's Signature:		Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Management Planner Review Form**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530 CITY/STATE: Chicago, Illinois MANAGEMENT PLANNER: **Daniel Juneau** Gillespie School SCHOOL NAME: **REVIEW DATE:** 9/2/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 HOMOGENEOUS AREA: 40

MATERIAL DESCRIPTION: Brown Border Floor Tile Mastic

MATERIAL LOCATION: 1944 Building- Rooms 153, 155-157, 1st Floor Corridor, Rooms 252, 254-257, 2nd Floor Corridor &

**Teachers' Restroom** 

MATERIAL QUANTITY: 800 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan		
Comments:		

	( Allelle			
Management Planner's Signature:		Date:	09/02/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 41

MATERIAL DESCRIPTION: Brown Carpet Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Principal's Office, Main Office

MATERIAL QUANTITY: 650 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Abated from Main Office

Inspector's Signature:	Dake & Ethis	Date:	08/09/2022	
. 5				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	41					
MATERIAL DESCRI	PTION:	Brown Carpet M	astic				
MATERIAL LOCATION	ON:	1944 Building- P	rincipal's Office, Ma	ain Office			
MATERIAL QUANTI	TY:	650			MATERIAL UNIT	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner original inspection of t he following recomme	to review t he above i	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
			2,000,000				
Management Plan	ner's Siar	nature:	Julee	-	Date:	00/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 42

MATERIAL DESCRIPTION: Black Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 250

MATERIAL QUANTITY: 80 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

Inspector's Signature:	Docker College	Date:	08/09/2022
		_	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	42						
MATERIAL DESCRI	PTION:	Black Vinyl Base	eboard					
MATERIAL LOCATION	ON:	1944 Building- R	toom 250					
MATERIAL QUANTI	TY:	80			MATERIAL UNIT	ΓS:	LF	
DAMAGE QUANTIT	Υ:	0			DAMAGE UNITS	S:	LF	
n accordance with Semanagement planner original inspection of the following recommend	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	mmend appropri	ate respo	nse actions. 7	Γhe
The RESPONSE AC	CTION rec	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	norlo Si-	noturo:	Julle	_	Date:	00/00/00	22	
ivianayement Fidh	1101 5 31Y	natur <del>c</del> .			Dale.	09/02/20	144	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 43

MATERIAL DESCRIPTION: Black Vinyl Baseboard Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 250

MATERIAL QUANTITY: 80 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

Inspector's Signature:	Dake & College	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 353	30
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	):	100-20327	
HOMOGENEOUS A	REA:	43				
MATERIAL DESCRI	PTION:	Black Vinyl Base	eboard Mastic			
MATERIAL LOCATI	ON:	1944 Building- R	Room 250			
MATERIAL QUANTI	TY:	80			MATERIAL UNITS:	LF
DAMAGE QUANTIT	Υ:	0			DAMAGE UNITS:	LF
management planner	to review the above	the results of the ir identified homoger	nspection and assess	sment and reco	ommend appropriate	A) the LEA must select a response actions. The ons 763.88 and 763.90 with
The RESPONSE AC	CTION reco	ommendation is:				
Follow O&M Plan						
Comments:						
Management Plan	ner's Sia	nature:	Jucces	_	Date: <b>09</b> /	/02/2022
ivialiaaciliciili lall	TICL 3 CIUI	naturo.			Date. <b>U3</b> 1	V616V66

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 44

MATERIAL DESCRIPTION: 9"x9" Tan w/Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Patch in Room 256

MATERIAL QUANTITY: 100 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Estres	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	44					
MATERIAL DESCRI	PTION:	9"x9" Tan w/Bro	wn & White Streaks	Floor Tile			
MATERIAL LOCATION	ON:	Patch in Room 2	56				
MATERIAL QUANTI	TY:	100			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner original inspection of t he following recomme	to review t he above i	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Siar	nature:	Julee	-	Date:	ng/n2/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 45

MATERIAL DESCRIPTION: 9"x9" Tan w/Brown & White Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Patch in Room 256

MATERIAL QUANTITY: 100 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Edition	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	45					
MATERIAL DESCRI			wn & White Streaks	Floor Tile Ma	astic		
MATERIAL LOCATION		Patch in Room 2					
MATERIAL QUANTI		100			MATERIAL UNIT	·s·	SF
DAMAGE QUANTIT		0			DAMAGE UNITS		SF
DAMAGE QUANTIT	1.	U			DAMAGE ONLY	).	<b>S</b> F
In accordance with Semanagement planner original inspection of the following recomments	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	
Follow O&M Plan							
Comments:							
		(A)	Juleel	-			
Management Plan	ner's Sig	nature:			Date:	09/02/20	N22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46

MATERIAL DESCRIPTION: 9"x9" Cream Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Patch in Room 256

MATERIAL QUANTITY: 25 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Ethis	Date:	08/09/2022	
. 5				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	46						
MATERIAL DESCRI	PTION:	9"x9" Cream Flo	or Tile					
MATERIAL LOCATION	ON:	Patch in Room 2	256					
MATERIAL QUANTI	TY:	25			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Semanagement planner original inspection of the following recommender.	to review the above	the results of the ir identified homoger	spection and assess	ment and reco	mmend appropria	ate respo	nse actions. 7	Γhe
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
			ducce					
Management Plan	ner's Sigi	nature:		-	Date:	09/02/20	)22	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 47

MATERIAL DESCRIPTION: 9"x9" Cream Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Patch in Room 256

MATERIAL QUANTITY: 25 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Ething			
Inspector's Signature:	Vot	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S \$	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	47						
MATERIAL DESCRI	PTION:	9"x9" Cream Flo	or Tile Mastic					
MATERIAL LOCATION	ON:	Patch in Room 2	256					
MATERIAL QUANTI	TY:	25			MATERIAL UNIT	S:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	3:	SF	
n accordance with Semanagement planner original inspection of the following recommend	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	nse actions. Th	ne
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Managament Disc	norlo C:	The state of the s	dece ce	-	Data	00/00/00	22	
Management Plan	nei s oigi	nature.			Date:	09/02/20	<b>44</b>	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 48

MATERIAL DESCRIPTION: 9"x9" Brown w/White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 215, Patch in Room 115

MATERIAL QUANTITY: 500 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Ethis	Date:	08/09/2022	
. 5				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 3	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	48						
MATERIAL DESCRI	PTION:	9"x9" Brown w/\	White Streaks Floor	Tile				
MATERIAL LOCATION	ON:	Room 215, Patcl	h in Room 115					
MATERIAL QUANTI	TY:	500			MATERIAL UNITS	S:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:		SF	
In accordance with Semanagement planner original inspection of the following recommendation of the RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropriat	te respoi	nse actions. The	е
Follow O&M Plan								
Comments:								
		(A)	Jule Ce	-				
Management Plan	ner's Sia	nature:			Date: 0	09/02/20	22	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 49

MATERIAL DESCRIPTION: 9"x9" Brown w/White Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 215, Patch in Room 115

MATERIAL QUANTITY: 500 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Ething			
Inspector's Signature:	Vot	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			9				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	49					
MATERIAL DESCRI	PTION:	9"x9" Brown w/\	Vhite Streaks Floor	Tile Mastic			
MATERIAL LOCATION	ON:	Room 215, Patch	n in Room 115				
MATERIAL QUANTI	TY:	500			MATERIAL UNIT	S:	SF
DAMAGE QUANTIT	Υ:	0			DAMAGE UNITS	:	SF
n accordance with Semanagement planner original inspection of the following recommon.  The RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	mmend appropria	te respo	
Follow O&M Plan							
Comments:							
		(A)	Luce co	_			
Management Plan	nor's Sign	noturo:			Data:	00/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 50

MATERIAL DESCRIPTION: 12"x12" White w/Gray Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Lunchroom, Patches in Room 116, Room 219, Under Water Fountain

MATERIAL QUANTITY: 4000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & College	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS AREA: 50							
MATERIAL DESCRI	PTION:	12"x12" White w	/Gray Specks Floor	Tile			
MATERIAL LOCATION	ON:	Lunchroom, Pate	ches in Room 116, I	Room 219, Un	nder Water Fount	ain	
MATERIAL QUANTI	TY:	4000			MATERIAL UNIT	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the in	spection and assess	ment and reco	ommend appropria	ate respo	
The RESPONSE AC	CTION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Siar	pature.	Julice	-	Date:	09/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 51

MATERIAL DESCRIPTION: 12"x12" White w/Gray Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Lunchroom, Patches in Room 116, Room 219, Under Water Fountain

MATERIAL QUANTITY: 4000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Cotty	Date <sup>.</sup>	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	51					
MATERIAL DESCRI	PTION:	12"x12" White w	/Gray Specks Floor	Tile Mastic			
MATERIAL LOCATION	ON:	Lunchroom, Pate	ches in Room 116, F	Room 219, Ur	nder Water Foun	tain	
MATERIAL QUANTI	TY:	4000			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	3:	SF
n accordance with Semanagement planner original inspection of the following recomment of the RESPONSE ACTION O&M Plan	to review the above indations.	the results of the in identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	
Comments:			7100000				
Management Plan	ner's Sigr	nature:	Jule Cl	-	Date:	09/02/20	)22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 52

MATERIAL DESCRIPTION: 12"x12" Tan w/Brown Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 154

MATERIAL QUANTITY: 900 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Estres	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530			
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau				
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022				
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327				
HOMOGENEOUS A	REA:	52							
MATERIAL DESCRIPTION:		12"x12" Tan w/Brown Specks Floor Tile							
MATERIAL LOCATION	ON:	1944 Building- Room 154							
MATERIAL QUANTI	ITY:	900			MATERIAL UNIT	ΓS:	SF		
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF		
In accordance with Semanagement planner original inspection of the following recommend.  The RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	onse actions.	The	
Follow O&M Plan									
Comments:									
Management Plan	nor's Sign	naturo:	Jucce e	-	Date:	00/02/24	122		
ivialiaucilielii Flall	110 0 010	lialuic.			Dale.	UJIUZIZL	J <b>LL</b>		

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 53

MATERIAL DESCRIPTION: 12"x12" Tan w/Brown Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Room 154

MATERIAL QUANTITY: 900 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Estres	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	53						
MATERIAL DESCRI	PTION:	12"x12" Tan w/B	rown Specks Floor	Tile Mastic				
MATERIAL LOCATION	ON:	1944 Building- R	oom 154					
MATERIAL QUANTI	TY:	900			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the in	spection and assess	ment and reco	ommend appropri	ate respo	onse actions. T	he
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Sigr	nature:	Jule Cle	-	Date:	09/02/20	022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 23321 **BUIDLING ID:** 3530 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 9301 S State Street ADDRESS: IDPH LICENSE NO: 100-20327 INFORMATION FROM PREVIOUS INSPECTION 54 **HOMOGENEOUS AREA:** MATERIAL DESCRIPTION: 12"x12" Light Red Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1944 Building- Patch in Room 154

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

DI Ative

COMMENTS:

Inspector's Signature:	Vacke & Color	Date:	08/09/2022
· ·		-	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	-ANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespie	School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S S	state Street	IDPH LICENSE NO	<b>)</b> :	100-20327	
HOMOGENEOUS A	REA:	54				
MATERIAL DESCRI	IPTION:	12"x12" Light R	ed Floor Tile ABAT	ED		
MATERIAL LOCATION	ON:	1944 Building- F	Patch in Room 154			
MATERIAL QUANTI	ITY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS	S:
nanagement planner	to review the above in	he results of the ir	nspection and assess	sment and reco	ommend appropri	HERA) the LEA must select a ate response actions. The ections 763.88 and 763.90 with
The RESPONSE AC	CTION reco	mmendation is:				
Comments:						
			Jucce			
Management Plan	ner's Sign	nature:	Buch		Date:	09/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 55

MATERIAL DESCRIPTION: 12"x12" Light Red Floor Tile Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1944 Building- Patch in Room 154

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

D/ cottes

COMMENTS:

Inspector's Signature:	Voixe Co	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	55					
MATERIAL DESCRI	PTION:	12"x12" Light Re	ed Floor Tile Mastic	ABATED			
MATERIAL LOCATION	ON:	1944 Building- P	atch in Room 154				
MATERIAL QUANTI	TY:				MATERIAL UNIT	S:	
DAMAGE QUANTIT	Y:				DAMAGE UNITS	3:	
nanagement planner original inspection of the he following recomme	accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a anagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The iginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with e following recommendations.  The RESPONSE ACTION recommendation is:						
Comments:							
Management Plan	ner's Sigr	nature:	Julle	-	Date: _	09/02/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 56

MATERIAL DESCRIPTION: 12"x12" Peach Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Patches in Room 155, Room 156

MATERIAL QUANTITY: 50 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

	Dake & Estres			
Inspector's Signature:	Vaire 5	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO:	:	100-20327		
HOMOGENEOUS A	REA:	56					
MATERIAL DESCRI	PTION:	12"x12" Peach F	loor Tile				
MATERIAL LOCATION	ON:	1944 Building- P	atches in Room 155	5, Room 156			
MATERIAL QUANTI	TY:	50			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	3:	SF
n accordance with Semanagement planner original inspection of the following recommendate The RESPONSE ACTION O&M Plan	to review the above indations.	the results of the in identified homoger	spection and assess	ment and reco	mmend appropri	ate respo	
Comments:							
Management Plani	ner's Sigr	nature:	Jule Cle	-	Date:	09/02/20	)22

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 57

MATERIAL DESCRIPTION: 12"x12" Peach Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Patches in Room 155, Room 156

MATERIAL QUANTITY: 50 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

	- / 14			
	Dake & College			
nspector's Signature:	Vou	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillesp	ie School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	):	100-20327		
HOMOGENEOUS A	AREA:	57					
MATERIAL DESCR	IPTION:	12"x12" Peach l	Floor Tile Mastic				
MATERIAL LOCATION: 1944 Building-		Patches in Room 15	5, Room 156				
MATERIAL QUANT	TTY:	50			MATERIAL UNI	ΓS:	SF
DAMAGE QUANTIT	ГΥ:	0			DAMAGE UNITS	3:	SF
In accordance with S management planner original inspection of the following recomm	to review the above endations	the results of the i identified homoge .	nspection and assess	sment and rec	ommend appropri	ate respo	

Date: 09/02/2022

Follow O&M Plan

Management Planner's Signature:

Comments:

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 23321 **BUIDLING ID:** 3530 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 58

MATERIAL DESCRIPTION: 12"x12" Light Brown Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: Patch in 1961 Corridor

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

D/ cottes

Inspector's Signature:	Valle	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNII NUMBER:	23321	BUIDLING ID: 3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	-ANNER:	Daniel Juneau
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	):	100-20327
HOMOGENEOUS A	REA:	58			
MATERIAL DESCRI	PTION:	12"x12" Light B	rown Floor Tile NO	Γ OBSERVED	
MATERIAL LOCATION	:NC	Patch in 1961 C	orridor		
MATERIAL QUANTI	TY:				MATERIAL UNITS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS:
management planner	to review he above endations.	the results of the in identified homoger	nspection and asses	sment and reco	Response Act (AHERA) the LEA must select a ommend appropriate response actions. The ecordance with Sections 763.88 and 763.90 with
Comments:					
Management Plan	ner's Sig	nature:	Succe	-	Date: <u>09/02/2022</u>

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 23321 **BUIDLING ID:** 3530 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 INFORMATION FROM PREVIOUS INSPECTION 59 **HOMOGENEOUS AREA:** MATERIAL DESCRIPTION: 12x12 Light Brown Floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Patch in 1961 Corridor

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

DI Ation

Inspector's Signature:	Voile & Early	Date:	08/09/2022	
-				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	):	100-20327		
HOMOGENEOUS A	REA:	59					
MATERIAL DESCRI	PTION:	12x12 Light Brow	wn Floor Tile Masti	c NOT OBSER	RVED		
MATERIAL LOCATION	ON:	Patch in 1961 Co	orridor				
MATERIAL QUANTI	TY:				MATERIAL UNIT	ΓS:	
DAMAGE QUANTIT	Y:				DAMAGE UNITS	S:	
n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with ne following recommendations.							
The RESPONSE AC	TION reco	ommendation is:					
Comments:							
Management Plan	ner's Sigr	nature:	Jule Cle	-	Date: _	09/02/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 60

MATERIAL DESCRIPTION: 9x9 Pinkish Red w/White Streaks NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1961 Building- Entrance to 1st Floor Girls' Bathroom

D/ cottes

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

Inspector's Signature:	Valleter	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PI	LANNER:	Daniel Juneau
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327
HOMOGENEOUS A	AREA:	60			
MATERIAL DESCR	IPTION:	9x9 Pinkish Red	l w/White Streaks N	OT OBSERVI	ED
MATERIAL LOCATI	ON:	1961 Building- E	Entrance to 1st Floo	or Girls' Bathr	room
MATERIAL QUANT	ITY:				MATERIAL UNITS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS:
nanagement planner	to review the above	the results of the initial identified homogerates	nspection and asses	sment and rec	Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION rec	ommendation is:			
Comments:					
			Diecel		
Management Plan	ner's Sig	nature:			Date: <u>09/02/2022</u>

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 61

MATERIAL DESCRIPTION: 9x9 Pinkish Red w/White Streaks Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1961 Building- Entrance to 1st Floor Girls' Bathroom

D/ cottes

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

Inspector's Signature:	Valette	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago Public Schools	S UNIT NUMBER: 23321	BUIDLING ID: 3530
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau
SCHOOL NAME:	Gillespie School	REVIEW DATE:	9/2/2022
ADDRESS:	9301 S State Street	IDPH LICENSE NO:	100-20327
HOMOGENEOUS AI	REA: <b>61</b>		
MATERIAL DESCRI	PTION: 9x9 Pinkish R	ed w/White Streaks Mastic NOT O	BSERVED
MATERIAL LOCATION	ON: 1961 Building	- Entrance to 1st Floor Girls' Bath	room
MATERIAL QUANTI	ΓY:		MATERIAL UNITS:
DAMAGE QUANTITY	Y: <b>0</b>		DAMAGE UNITS:
management planner to priginal inspection of the he following recomme	to review the results of the ne above identified homog	e inspection and assessment and re- geneous area has been reviewed in	Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
Comments:			
Management Plani	ner's Signature:	Ducce	Date: <u>09/02/2022</u>

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 62

MATERIAL DESCRIPTION: 12x12 Cream w/Brown Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Patch in Room 116

MATERIAL QUANTITY: 10 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	Docke & Esting	Date:	08/09/2022	
-1				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	62					
MATERIAL DESCRI	PTION:	12x12 Cream w/l	Brown Specks Flooi	r Tile			
MATERIAL LOCATION	ON:	1961 Building- P	atch in Room 116				
MATERIAL QUANTI	TY:	10			MATERIAL UNIT	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Semanagement planner original inspection of the following recommend	to review the above	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	CTION reco	ommendation is:					
Follow O&M Plan							
Comments:							
		(Fle	Julle	-	_		
Management Plan	ner's Siar	nature.			Date:	na/n2/20	122

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 63

MATERIAL DESCRIPTION: 12x12 Cream w/Brown Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Patch in Room 116

MATERIAL QUANTITY: 10 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	Docker Edition	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			9						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 353	0			
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau				
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022				
ADDRESS:	9301 S \$	State Street	IDPH LICENSE NO	:	100-20327				
HOMOGENEOUS A	REA:	63							
MATERIAL DESCRI	PTION:	12x12 Cream w/l	Brown Specks Floo	r Tile Mastic					
MATERIAL LOCATION	ON:	1961 Building- P	atch in Room 116						
MATERIAL QUANTI	TY:	10			MATERIAL UNITS:	SF			
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS:	SF			
management planner original inspection of t the following recomme	n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.  The RESPONSE ACTION recommendation is:								
FOIIOW O&M Plan									
Comments:									
Management Plan	nor's Sig	natura:	Jucce	-	Data: 00/	02/2022			

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

23321

**BUIDLING ID:** 

3530

UNIT NUMBER:

LEA NAME:

COMMENTS: Not Observed

**Chicago Public Schools** 

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 INFORMATION FROM PREVIOUS INSPECTION 64 **HOMOGENEOUS AREA:** MATERIAL DESCRIPTION: 12x12 Light Brown w/White Specks Floor Tile NOT OBSERVED HISTORICAL AHERA DAMAGE CATEGORY HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION: **ASBESTOS TYPE:** FRIABLE: RESULTS OF REINSPECTION AND REASSESSMENT This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection. The current AHERA DAMAGE CATEGORY is determined to be . DAMAGE REASON: **DISTURBANCE POTENTIAL:** MATERIAL LOCATION: Patch in 1936 Corridor MATERIAL QUANTITY: MATERIAL UNITS: DAMAGE QUANTITY: DAMAGE UNITS:

Inspector's Signature:

Date: 08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAIVIE.	Cnicago	Public Schools	UNIT NUMBER.	23321	BUIDLING ID. 3530			
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT P	LANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327			
HOMOGENEOUS A	REA:	64						
MATERIAL DESCRI	PTION:	12x12 Light Bro	wn w/White Speck	s Floor Tile NC	OT OBSERVED			
MATERIAL LOCATION	ON:	Patch in 1936 C	Patch in 1936 Corridor					
MATERIAL QUANTI	TY:				MATERIAL UNITS:			
DAMAGE QUANTIT	Y:				DAMAGE UNITS:			
management planner	to review he above	the results of the in identified homoger	nspection and asses	sment and reco	Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with			
The RESPONSE AC	CTION rec	ommendation is:						
Comments:								
Management Plan	ner's Sig	nature:	Jucce	_	Date: <u>09/02/2022</u>			

#### **TEM Environmental, Inc.** 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 23321 **BUIDLING ID:** 3530 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 INFORMATION FROM PREVIOUS INSPECTION 65 **HOMOGENEOUS AREA:** MATERIAL DESCRIPTION: 12x12 Light Brown w/White Specks Floor Tile Mastic NOT OBSERVED HISTORICAL AHERA DAMAGE CATEGORY HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION: **ASBESTOS TYPE:** FRIABLE: RESULTS OF REINSPECTION AND REASSESSMENT This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection. The current AHERA DAMAGE CATEGORY is determined to be . DAMAGE REASON: **DISTURBANCE POTENTIAL:** MATERIAL LOCATION: Patch in 1936 Corridor MATERIAL QUANTITY: MATERIAL UNITS: DAMAGE QUANTITY: DAMAGE UNITS: COMMENTS: Not Observed Daker Estis

Date:

08/09/2022

Inspector's Signature:

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNII NUMBER:	23321	BUIDLING ID: 3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	-ANNER:	Daniel Juneau
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327
HOMOGENEOUS A	REA:	65			
MATERIAL DESCRI	PTION:	12x12 Light Bro	wn w/White Specks	Floor Tile Ma	stic NOT OBSERVED
MATERIAL LOCATION	ON:	Patch in 1936 C	orridor		
MATERIAL QUANTI	TY:				MATERIAL UNITS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS:
management planner	to review he above endations.	the results of the in identified homoge	nspection and asses	sment and reco	Response Act (AHERA) the LEA must select a immend appropriate response actions. The ecordance with Sections 763.88 and 763.90 with
Management Plan	ner's Sig	nature:	Juce e le		Date: <b>09/02/2022</b>
wanagement Plan	ner's Sigi	nature:			Date: 09/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 66

MATERIAL DESCRIPTION: 9x9 Cream Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1961 Building- Patch at Entrance to Room 208

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

Inspector's Signature:	Docke & Estres	Date:	08/09/2022	
1 0				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327	
HOMOGENEOUS A	REA:	66				
MATERIAL DESCRI	PTION:	9x9 Cream Floor	Tile NOT OBSERV	ED		
MATERIAL LOCATION	ON:	1961 Building- P	atch at Entrance to	Room 208		
MATERIAL QUANTI	TY:				MATERIAL UNIT	ΓS:
DAMAGE QUANTITY	Y:				DAMAGE UNITS	S:
management planner original inspection of the he following recomme	accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a anagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The iginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with e following recommendations.  The RESPONSE ACTION recommendation is:					
Comments:						
Management Plan	ner's Sigr	nature:	Jule	<del></del>	Date: _	09/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 67

MATERIAL DESCRIPTION: 9x9 Cream Floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1961 Building- Patch at Entrance to Room 208

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

Inspector's Signature:	Docke & Estres	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT P	LANNER:	Daniel Juneau
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327
HOMOGENEOUS A	REA:	67			
MATERIAL DESCRI	IPTION:	9x9 Cream Floo	r Tile Mastic NOT C	BSERVED	
MATERIAL LOCATI	ON:	1961 Building- F	Patch at Entrance to	Room 208	
MATERIAL QUANTI	ITY:				MATERIAL UNITS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS:
nanagement planner	to review the above	the results of the initial identified homogerates	nspection and asses	sment and rec	Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION rec	ommendation is:			
Comments:					
			Duccel		
Management Plan	ner's Sig	nature:	Dice -	-	Date:09/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 68

MATERIAL DESCRIPTION: 12x12 Red Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1936 Building- Part of Corridor, Room 207, Room 107, Main Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

D/ cottes

Inspector's Signature:	Valette	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespie	School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	68						
MATERIAL DESCRI	PTION:	12x12 Red Floor	Tile NOT OBSERVE	ĒD				
MATERIAL LOCATION	ON:	1936 Building- P	art of Corridor, Room 207, Room 107, Main Office					
MATERIAL QUANTI	TY:				MATERIAL UNIT	ΓS:		
DAMAGE QUANTITY	<b>Y</b> :				DAMAGE UNITS	3:		
nanagement planner	to review the above iendations.	he results of the in dentified homogen	spection and assess	ment and reco	mmend appropria	IERA) the LEA must select a ate response actions. The ections 763.88 and 763.90 with		
Comments:								
Management Plani	ner's Sigr	nature:	Weece.	-	Date: _	09/02/2022		

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 69

MATERIAL DESCRIPTION: 12x12 Red floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1936 Building- Part of Corridor, Room 207, Room 107, Main Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

D/ cottes

Inspector's Signature:	Valle Control	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PI	_ANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327	
HOMOGENEOUS AI	REA:	69				
MATERIAL DESCRIPTION: 12x12 Red floor		Tile Mastic NOT O	BSERVED			
MATERIAL LOCATION	ON:	1936 Building- P	art of Corridor, Ro	om 207, Room	n 107, Main Offic	е
MATERIAL QUANTI	TY:				MATERIAL UNI	ΓS:
DAMAGE QUANTITY	Y:				DAMAGE UNITS	S:
nanagement planner	to review the above indations.	the results of the in identified homoger	spection and asses	sment and reco	ommend appropris	HERA) the LEA must select a ate response actions. The ections 763.88 and 763.90 with
Comments:						
Management Plani	ner's Sigr	nature:	JULCE C C.	-	Date: _	09/02/2022

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 70

MATERIAL DESCRIPTION: 9x9 Black w/White Streaks Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: Room 252, Patches in 1936 Corridor, Patches in Room 219, Patches in Teachers'

Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

D/ Atus

Inspector's Signature:	Voile	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	70					
MATERIAL DESCRI	PTION:	9x9 Black w/Whi	te Streaks Floor Til	e NOT OBSEF	RVED		
MATERIAL LOCATION	ON:	Room 252, Patch	nes in 1936 Corridor, Patches in Room 219, Patches in Teachers' Lunchroom				
MATERIAL QUANTI	TY:				MATERIAL UNIT	ΓS:	
DAMAGE QUANTITY	<b>Y</b> :				DAMAGE UNITS	3:	
nanagement planner	to review the above iendations.	he results of the in dentified homogen	spection and assess	ment and reco	mmend appropria	IERA) the LEA must select a ate response actions. The ections 763.88 and 763.90 with	
Comments:							
Management Plani	ner's Sigr	nature:	Weece.	-	Date: _	09/02/2022	

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 71

MATERIAL DESCRIPTION: 9"x9" Black w/White Streaks Floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: Room 252, Patches in 1936 Corridor, Patches in Room 219, Patches in Teachers'

Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

D/ Atus

Inspector's Signature:	Vacke 2 200	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 23321	BUIDLING ID: 3530
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau
SCHOOL NAME:	Gillespie School	REVIEW DATE:	9/2/2022
ADDRESS:	9301 S State Street	IDPH LICENSE NO:	100-20327
HOMOGENEOUS A	.REA: <b>71</b>		
MATERIAL DESCRI	PTION: 9"x9" Black w/\	White Streaks Floor Tile Mastic N	NOT OBSERVED
MATERIAL LOCATION	ON: Room 252, Pato	hes in 1936 Corridor, Patches in	n Room 219, Patches in Teachers' Lunchroom
MATERIAL QUANTI	TY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:
nanagement planner	to review the results of the the above identified homoge	nspection and assessment and re	y Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION recommendation is:		
Comments:			
		JULICE CO	
Management Plan	ner's Signature:	Durice -	Date: 09/02/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 72

MATERIAL DESCRIPTION: 12"x12" Red w/Black Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Patches in Rooms 252, 155, 156

MATERIAL QUANTITY: 60 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	D / Atua			
Inspector's Signature:	Docker cottes	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Management Planner Review Form**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530 CITY/STATE: Chicago, Illinois MANAGEMENT PLANNER: **Daniel Juneau** Gillespie School SCHOOL NAME: **REVIEW DATE:** 9/2/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 HOMOGENEOUS AREA: 72 12"x12" Red w/Black Specks Floor Tile MATERIAL DESCRIPTION: MATERIAL LOCATION: 1944 Building- Patches in Rooms 252, 155, 156 MATERIAL QUANTITY: MATERIAL UNITS: 60 SF DAMAGE QUANTITY: DAMAGE UNITS: 0 SF In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations. The RESPONSE ACTION recommendation is: Follow O&M Plan Comments: Allele Management Planner's Signature: Date: 09/02/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 73

MATERIAL DESCRIPTION: 12"x12" Red w/Black Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Patches in Rooms 155, 156 & 252

MATERIAL QUANTITY: 60 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Daker Eding			
Inspector's Signature:	Variation of the second	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	73						
MATERIAL DESCRI	PTION:	12"x12" Red w/B	Black Specks Floor	Tile Mastic				
MATERIAL LOCATION	ON:	1944 Building- P	atches in Rooms 1	55, 156 & 252				
MATERIAL QUANTI	TY:	60			MATERIAL UNI	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the in	spection and assess	ment and reco	ommend appropri	ate respo	onse actions. The	
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Sigi	nature:	Jul Cle	-	Date:	09/02/20	022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 74

MATERIAL DESCRIPTION: Black Tile Border NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1936 Corridor- 1st & 2nd floors

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:	Dake Ethis	Date	e:	08/09/2022	
	-				 

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID: 3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PI	LANNER:	Daniel Juneau	
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022	
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	):	100-20327	
HOMOGENEOUS A	REA:	74				
MATERIAL DESCRI	PTION:	Black Tile Borde	er NOT OBSERVED	ı		
MATERIAL LOCATION	ON:	1936 Corridor- 1	st & 2nd floors			
MATERIAL QUANTI	TY:				MATERIAL UNITS:	
DAMAGE QUANTIT	Y:				DAMAGE UNITS:	
management planner	to review the above	the results of the in identified homoger	nspection and asses	sment and reco	Response Act (AHERA) the LEA must select a ommend appropriate response actions. The accordance with Sections 763.88 and 763.90 with	า
The RESPONSE AC	CTION rec	ommendation is:				
Comments:						
			21000000			
Management Plan	ner's Sig	nature:	Jule Cl	-	Date: <u>09/02/2022</u>	_

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 75

MATERIAL DESCRIPTION: Black Tile Border Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1936 Corridor- 1st & 2nd Floors

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:	Dake Ethis	Date	e:	08/09/2022	
	-				 

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

## **Management Planner Review Form**

23321

BUIDLING ID: 3530

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau
SCHOOL NAME:	Gillespie School	REVIEW DATE:	9/2/2022
ADDRESS:	9301 S State Street	IDPH LICENSE NO:	100-20327
HOMOGENEOUS A	NREA: <b>75</b>		
MATERIAL DESCR	IPTION: Black Tile Boi	rder Mastic NOT OBSERVED	
MATERIAL LOCATI	ON: 1936 Corridor	- 1st & 2nd Floors	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	<b>"</b> Y:		DAMAGE UNITS:
management planner	to review the results of the the above identified homogeneous	e inspection and assessment and r	by Response Act (AHERA) the LEA must select a ecommend appropriate response actions. The n accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION recommendation is	:	
Comments:			
		21000000	
Management Plan	ner's Signature:	Ducce	Date: <u>09/02/2022</u>

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Inspector Assessment Form (REASSESSMENT)**

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 23321 **BUIDLING ID:** 3530 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 INFORMATION FROM PREVIOUS INSPECTION 76 **HOMOGENEOUS AREA:** 

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION:

MATERIAL DESCRIPTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

12"x12" Beige Floor Tile NOT OBSERVED

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1st and 2nd Floor Hallways

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

DI CATUS

COMMENTS: Not Observed

Inspector's Signature:	Valle & Color	Date:	08/09/2022
		_	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAIVIE.	Cnicago	Public Schools	UNIT NUMBER.	23321	BUIDLING ID. 3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT P	LANNER:	Daniel Juneau
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327
HOMOGENEOUS A	REA:	76			
MATERIAL DESCRI	PTION:	12"x12" Beige F	loor Tile NOT OBS	ERVED	
MATERIAL LOCATION	ON:	1st and 2nd Floo	or Hallways		
MATERIAL QUANTI	TY:				MATERIAL UNITS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS:
management planner	to review he above	the results of the ir identified homoger	nspection and asses	ssment and reco	Response Act (AHERA) the LEA must select a commend appropriate response actions. The ccordance with Sections 763.88 and 763.90 with
The RESPONSE AC	TION reco	ommendation is:			
Comments:					
Management Plan	ner's Sia	nature:	Juccel	_	Date: <b>09/02/2022</b>
	5 <b>5</b> 191				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Inspector Assessment Form (REASSESSMENT)**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 77

MATERIAL DESCRIPTION: 12"x12" Beige Floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: 1st and 2nd Floor Hallways

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:	Dake Ethis	Date	e:	08/09/2022	
	-				 

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

## **Management Planner Review Form**

23321

BUIDLING ID: 3530

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau
SCHOOL NAME:	Gillespie School	REVIEW DATE:	9/2/2022
ADDRESS:	9301 S State Street	IDPH LICENSE NO:	100-20327
HOMOGENEOUS A	.REA: <b>77</b>		
MATERIAL DESCR		e Floor Tile Mastic NOT OBSERVE	ED.
MATERIAL LOCATI	_	Floor Hallways	
MATERIAL QUANT		·	MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:
management planner	to review the results of the above identified home	ne inspection and assessment and re	y Response Act (AHERA) the LEA must select a ecommend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION recommendation is	S:	
Comments:			
		Allee el	
Management Plan	ner's Signature:		Date: <u>09/02/2022</u>

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 78

MATERIAL DESCRIPTION: 12 X 12 Beige w/Light Red and Light Blue Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936, 1944 & 1961 Buildings- 1st Floor Corridors /1961 Building- 2nd Floor Corridor

MATERIAL QUANTITY: 35000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Vacker College	Date:	08/09/2022
-		•	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	78					
MATERIAL DESCRI	PTION:	12 X 12 Beige w/	Light Red and Light	t Blue Streaks	s Floor Tile		
MATERIAL LOCATION	ON:	1936, 1944 & 196	31 Buildings- 1st Flo	or Corridors	/1961 Building- 2	2nd Floo	r Corridor
MATERIAL QUANTI	TY:	35000			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Semanagement planner original inspection of the following recommender The RESPONSE ACTION O&M Plan	to review the above indations.	the results of the in identified homoger	spection and assess	ment and reco	mmend appropria	ate respo	
Comments:							
Management Plani	ner's Sigr	nature:	Jule Cl	-	Date:	09/02/20	<b>122</b>

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 78M

MATERIAL DESCRIPTION: 12"x12" Beige w/Light Red and Light Blue Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936, 1944 & 1961 Buildings- 1st Floor Corridors /1961 Building- 2nd Floor Corridor

MATERIAL QUANTITY: 35000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Edities	Date:	08/09/2022
_			

#### **TEM Environmental, Inc.** 2022 AHERA REINSPECTION

#### **Management Planner Review Form**

LEA NAME:	Chicago Public Schools	UNII NUMBER: 233	321	BUIDLING ID:	3530
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNE	ER:	Daniel Juneau	
SCHOOL NAME:	Gillespie School	REVIEW DATE:		9/2/2022	

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

HOMOGENEOUS AREA: 78M

12"x12" Beige w/Light Red and Light Blue Streaks Floor Tile Mastic MATERIAL DESCRIPTION:

MATERIAL LOCATION: 1936, 1944 & 1961 Buildings- 1st Floor Corridors /1961 Building- 2nd Floor Corridor

MATERIAL QUANTITY: 35000 MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS: 0 SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:			

Allelle Management Planner's Signature:

Date: 09/02/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 79

MATERIAL DESCRIPTION: Brown with Black Streaks Terrazzo

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Stairwells

MATERIAL QUANTITY: 3500 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Ething			
Inspector's Signature:	Vot	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	79						
MATERIAL DESCRI	PTION:	Brown with Blac	k Streaks Terrazzo					
MATERIAL LOCATION	ON:	1944 Building- S	tairwells					
MATERIAL QUANTI	TY:	3500			MATERIAL UNI	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the ir	spection and assess	ment and reco	ommend appropri	ate respo	onse actions. Th	ie
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Siar	nature:	succe	-	Date:	09/02/20	022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 80

MATERIAL DESCRIPTION: Grey, White and Black Speckled Terrazzo

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 Building- Stairs

MATERIAL QUANTITY: 2300 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Ethis	Date:	08/09/2022	
. 5				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS AI	REA:	80					
MATERIAL DESCRI	PTION:	Grey, White and	Black Speckled Ter	razzo			
MATERIAL LOCATION	ON:	1936 Building- S	tairs				
MATERIAL QUANTI	TY:	2300			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner to priginal inspection of the he following recomme	to review t he above i	he results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	mmendation is:					
Follow O&M Plan							
Comments:							
Management Plans	oorlo Cica	The state of the s	Jucce	-	Date:	00/00/00	200

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 81

MATERIAL DESCRIPTION: Brown and Tan Mosaic Ceramic Tile Grout

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 Building- Boys and Girls Toilets and Vestibules

MATERIAL QUANTITY: 1800 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Dake & Coty			
Inspector's Signature:	Vacr	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	RFA:	81					
MATERIAL DESCRI			Mosaic Ceramic Tile	Grout			
MATERIAL LOCATION			Boys and Girls Toile		ulos		
		_	oys and Giris Tolle	is allu vestib		FO.	05
MATERIAL QUANTI		1800			MATERIAL UNIT		SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
In accordance with Semanagement planner original inspection of the following recomments	to review he above	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	
The RESPONSE AC	TION rec	ommendation is:					
Follow O&M Plan							
Commentar							
Comments:							
			Jucce				
Management Plan	ner's Sig	nature:	Succession	-	Date:	09/02/20	N22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 81M

MATERIAL DESCRIPTION: Brown and Tan Mosaic Ceramic Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 Building- Boys and Girls Toilets and Vestibules

MATERIAL QUANTITY: 1800 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Daker Cottes			
Inspector's Signature:	Vac per s	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	81M					
MATERIAL DESCRI	PTION:	Brown and Tan	Mosaic Ceramic Tile	e Mastic			
MATERIAL LOCATION	ON:	1936 Building- B	Boys and Girls Toile	ts and Vestib	ules		
MATERIAL QUANTI	TY:	1800			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
he following recomme The RESPONSE AC Follow O&M Plan	he above endations.	identified homoger					onse actions. The 63.88 and 763.90 with
Comments:	nada Çin	R	Jule Cl		Detai		
Management Plan	ner's Sigı	nature:			Date:	09/02/20	)22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 82

MATERIAL DESCRIPTION: 4"x4" Red Ceramic Tile Grout

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Kitchen

MATERIAL QUANTITY: 600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Ething			
Inspector's Signature:	Vot	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	82					
MATERIAL DESCRI	PTION:	4"x4" Red Ceran	nic Tile Grout				
MATERIAL LOCATION	ON:	1961 Building- K	itchen				
MATERIAL QUANTI	TY:	600			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
In accordance with Semanagement planner original inspection of the following recommendates The RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	
Follow O&M Plan							
Comments:							
			Jule Cle	-			
Management Plan	ner's Sia	nature.			Date:	09/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 82M

MATERIAL DESCRIPTION: 4"x4" Red Ceramic Tile Grout

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Kitchen

MATERIAL QUANTITY: 600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Vocker College	Date:	08/09/2022
· -		•	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	82M						
MATERIAL DESCRI	PTION:	4"x4" Red Ceran	nic Tile Grout					
MATERIAL LOCATION	ON:	1961 Building- K	litchen					
MATERIAL QUANTI	TY:	600			MATERIAL UNI	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	<b>S</b> :	SF	
n accordance with Se management planner original inspection of t he following recomme	to review t he above	the results of the ir	spection and assess	ment and reco	ommend appropri	ate respo	nse actions. T	he
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Sigr	nature:	succe	-	Date:	09/02/20	022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 83

MATERIAL DESCRIPTION: Light and Dark Orange Speckled Terrazzo

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building - Stairs and Entrance

MATERIAL QUANTITY: 3600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Edition	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS AF	REA:	83					
MATERIAL DESCRI	PTION:	Light and Dark C	Orange Speckled Te	rrazzo			
MATERIAL LOCATION	ON:	1961 Building - S	Stairs and Entrance				
MATERIAL QUANTI	ΓY:	3600			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner to original inspection of the he following recomme	to review t ne above i	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plans	nor's Sign	nature:	Juccel	-	Date:	00/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 84

MATERIAL DESCRIPTION: Beige with Yellow Specks Terrazzo

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Stairs and Entrance

MATERIAL QUANTITY: 2200 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Estres	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	84						
MATERIAL DESCRI	PTION:	Beige with Yello	w Specks Terrazzo					
MATERIAL LOCATION	ON:	1961 Building- S	tairs and Entrance					
MATERIAL QUANTI	TY:	2200			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Semanagement planner original inspection of the following recomme	to review the above	the results of the ir	spection and assess	ment and reco	mmend appropri	ate respo	nse actions. T	The .
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
			Julce					
Management Plan	ner's Siar	nature:			Date:	09/02/20	)22	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 85

MATERIAL DESCRIPTION: Blue Carpet Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Library and Room 118

MATERIAL QUANTITY: 2200 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Vale & Cours	Date:	08/09/2022
		-	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	85					
MATERIAL DESCRI	PTION:	Blue Carpet Mas	stic				
MATERIAL LOCATION	ON:	1961 Building- L	ibrary and Room 11	8			
MATERIAL QUANTI	TY:	2200			MATERIAL UNIT	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner original inspection of t he following recomme	to review t he above i	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Siar	nature:	Jucce co	-	Date:	00/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 86

MATERIAL DESCRIPTION: Acoustical Ceiling Plaster

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Throughout Ceilings

MATERIAL QUANTITY: 14500 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Stus	Date	e:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO:	:	100-20327		
HOMOGENEOUS AF	REA:	86					
MATERIAL DESCRI	PTION:	Acoustical Ceilin	ng Plaster				
MATERIAL LOCATION	ON:	1961 Building- T	hroughout Ceilings				
MATERIAL QUANTI	ΓY:	14500			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se nanagement planner to original inspection of the he following recomme	to review t ne above i	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plans	orlo Sicr	noturo:	Julce	-	Date:	00/02/24	222

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 87

MATERIAL DESCRIPTION: Tan Mosaic Ceramic Tile Grout

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Boys and Girls Washrooms and Vestibules

MATERIAL QUANTITY: 2600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Vocker Colles	Date:	08/09/2022
- · · · · · · · · · · · · · · · · · · ·		_	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	87					
MATERIAL DESCRI	PTION:	Tan Mosaic Cera	mic Tile Grout				
MATERIAL LOCATION	ON:	1944 Building- B	oys and Girls Wash	rooms and V	estibules		
MATERIAL QUANTI	TY:	2600			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner original inspection of t he following recomme	to review t he above i	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Siar	nature:	Jule Co	-	Date:	00/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 87M

MATERIAL DESCRIPTION: Tan Mosaic Ceramic Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Boys' & Girls' Washrooms and Vestibules

MATERIAL QUANTITY: 2600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Dale & Estis			
Inspector's Signature:	Vaires	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327		
HOMOGENEOUS A	REA:	87M					_
MATERIAL DESCRI		Tan Mosaic Cera	amic Tile Mastic				
MATERIAL LOCATION			Boys' & Girls' Wash	rooms and Va	etihulas		
		_	ooys & Onis Wasiii	ioonis and ve		TC.	ee.
MATERIAL QUANTI		2600			MATERIAL UNIT		SF
DAMAGE QUANTIT	Υ:	0			DAMAGE UNITS	5:	SF
In accordance with Semanagement planner original inspection of the following recommendation of the RESPONSE ACCORDIGION O&M Plan  Comments:	to review he above endations.	the results of the ir identified homoger ommendation is:	nspection and assess	sment and reco	ommend appropri	ate respo	e LEA must select a conse actions. The 63.88 and 763.90 with
Management Plan	ner's Sigi	nature:			Date:	09/02/20	022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 88

MATERIAL DESCRIPTION: Multicolor Mosaic Floor Tile Grout

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Boys' & Girls' Washrooms and Vestibules

MATERIAL QUANTITY: 1600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Dake & Cotty			
Inspector's Signature:	Volume -	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	88					
MATERIAL DESCRI	PTION:	Multicolor Mosa	ic Floor Tile Grout				
MATERIAL LOCATION	ON:	1961 Building- B	oys' & Girls' Washr	ooms and Ve	stibules		
MATERIAL QUANTI	TY:	1600			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
In accordance with Semanagement planner original inspection of the following recommendation of the RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	
Follow O&M Plan							
Comments:							
			\				
Management Plan	ner's Sign	nature:	Jucce	-	Date:	09/02/20	n22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 89

MATERIAL DESCRIPTION: Multicolor Mosaic Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Boys' & Girls' Washrooms and Vestibules

MATERIAL QUANTITY: 1600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & Cottus			
Inspector's Signature:	Vice to S	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		•						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S \$	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	89						
MATERIAL DESCRI	PTION:	Multicolor Mosa	ic Floor Tile Mastic					
MATERIAL LOCATION	ON:	1961 Building- B	loys' & Girls' Washi	ooms and Ve	estibules			
MATERIAL QUANTI	TY:	1600			MATERIAL UNI	TS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
In accordance with Semanagement planner original inspection of the following recommend.	to review he above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropri	ate respo	onse actions. The	th
Follow O&M Plan								
Comments:								
			ducce					
Management Plan	ner's Sigi	nature:	Succession	-	Date:	09/02/20	022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 90

MATERIAL DESCRIPTION: 12"x12" Light Grey w/Dark Grey Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 & 1944 Buildings- 2nd Floor Corridors

MATERIAL QUANTITY: 7400 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Darke & College			
Inspector's Signature:	Voct	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S \$	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	90						
MATERIAL DESCRI	PTION:	12"x12" Light G	rey w/Dark Grey Str	eaks Floor Ti	le			
MATERIAL LOCATION	ON:	1936 & 1944 Bui	ldings- 2nd Floor C	orridors				
MATERIAL QUANTI	TY:	7400			MATERIAL UNIT	S:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	:	SF	
In accordance with Semanagement planner original inspection of the following recommendate RESPONSE AC	to review he above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	te respo	nse actions. T	he
Follow O&M Plan								
Comments:								
			21000000					
Management Plan	ner's Sigi	nature:	succe	-	Date:	09/02/20	)22	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 90M

MATERIAL DESCRIPTION: 12"x12" Light Grey w/Dark Grey Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 & 1944 Buildings- 2nd Floor Corridors

MATERIAL QUANTITY: 7400 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Daker Ethis		
Inspector's Signature:	Vac	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	_	o, Illinois	MANAGEMENT PL		Daniel Juneau		
	_			JANULIA.			
SCHOOL NAME:	-	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NC	):	100-20327		
HOMOGENEOUS A	REA:	90M					
MATERIAL DESCRI	PTION:	12"x12" Light G	rey w/Dark Grey Str	eaks Floor Ti	le Mastic		
MATERIAL LOCATION	ON:	1936 & 1944 Bui	ldings- 2nd Floor C	orridors			
MATERIAL QUANTI	TY:	7400			MATERIAL UNI	ΓS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
In accordance with Semanagement planner original inspection of the following recomments of the RESPONSE AC	to review he above endations.	the results of the ir identified homoger	spection and assess	sment and reco	ommend appropri	ate respo	e LEA must select a onse actions. The 63.88 and 763.90 with
Follow O&M Plan							
Comments:							
			Jule Cle				
Management Plan	ner's Sig	nature:	Buch	-	Date:	09/02/20	)22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 91

MATERIAL DESCRIPTION: 12"x12" Royal Blue Vinyl Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- 1st Floor Men's Restroom

MATERIAL QUANTITY: 60 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docke & Ething	Date:	08/09/2022	
, ,				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO:	:	100-20327		
HOMOGENEOUS A	REA:	91					
MATERIAL DESCRI	PTION:	12"x12" Royal B	lue Vinyl Floor Tile				
MATERIAL LOCATION	ON:	1961 Building- 1	st Floor Men's Resti	room			
MATERIAL QUANTI	TY:	60			MATERIAL UNIT	TS:	SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner original inspection of the he following recomme	to review t he above i	he results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	mmendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Siar	nature:	succe	-	Date:	00/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 91A

MATERIAL DESCRIPTION: 12"x12" Royal Blue Vinyl Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- 1st Floor Men's Restroom

MATERIAL QUANTITY: 60 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Vale & Cours	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	91A					
MATERIAL DESCRI	PTION:	12"x12" Royal B	lue Vinyl Floor Tile	Mastic			
MATERIAL LOCATION	ON:	1961 Building- 1	st Floor Men's Rest	room			
MATERIAL QUANTI	TY:	60			MATERIAL UNIT	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
n accordance with Se management planner original inspection of t he following recomme	to review t he above i	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Sigr	nature:	Julice	-	Date:	09/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 92

MATERIAL DESCRIPTION: 12"x12" Red Vinyl Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- 1st Floor Women's Restroom

MATERIAL QUANTITY: 60 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Dake & Estres			
Inspector's Signature:	Vaire 5	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	92						
MATERIAL DESCRI	PTION:	12"x12" Red Vin	yl Floor Tile					
MATERIAL LOCATION	ON:	1961 Building- 1	st Floor Women's R	estroom				
MATERIAL QUANTI	TY:	60			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the ir	spection and assess	ment and reco	mmend appropri	ate respo	onse actions. Th	ne
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Sigi	nature:	Juecce -	-	Date:	09/02/20	022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 92A

MATERIAL DESCRIPTION: 12"x12" Red Vinyl Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- 1st Floor Women's Restroom

MATERIAL QUANTITY: 60 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Edition	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	92A					
MATERIAL DESCRI	PTION:	12"x12" Red Vin	yl Floor Tile Mastic				
MATERIAL LOCATION	ON:	1961 Building- 1	st Floor Women's R	Restroom			
MATERIAL QUANTI	TY:	60			MATERIAL UNI	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	<b>3</b> :	SF
management planner original inspection of the following recomment of the RESPONSE ACTION O&M Plan	he above endations.	identified homoger					63.88 and 763.90 with
Comments:							
Management Plan	ner's Sig	nature:	succe.	-	Date:	09/02/20	022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 93

MATERIAL DESCRIPTION: 12"x12" Blue Streaked Vinyl Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Gym/Assembly Hall

MATERIAL QUANTITY: 2400 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docke & Ething	Date:	08/09/2022	
, ,				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S \$	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	93						
MATERIAL DESCRI	PTION:	12"x12" Blue Sti	eaked Vinyl Floor T	ile				
MATERIAL LOCATION	ON:	1944 Building- G	ym/Assembly Hall					
MATERIAL QUANTI	TY:	2400			MATERIAL UNIT	S:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	:	SF	
In accordance with Semanagement planner original inspection of the following recomments of the RESPONSE AC	to review he above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	te respo	nse actions. 7	Γhe
Follow O&M Plan								
Comments:								
			2100000					
Management Plan	ner's Sigi	nature:	Jule Cle	-	Date:	09/02/20	)22	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 93A

MATERIAL DESCRIPTION: 12"x12" Blue Streaked Vinyl Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Gym/Assembly Hall

MATERIAL QUANTITY: 2400 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Vocke E Edit	Date:	08/09/2022
·		=	· ·

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	_	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	_	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	-	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	93A					
MATERIAL DESCRI	PTION:	12"x12" Blue Str	eaked Vinyl Floor T	ile Mastic			
MATERIAL LOCATION	ON:	1944 Building- G	ym/Assembly Hall				
MATERIAL QUANTI	TY:	2400			MATERIAL UNIT	ΓS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF
management planner original inspection of t	n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with ne following recommendations.						
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Tollow Odivi Tiali							
Comments:							
			Juccel				
Management Plan	ner's Sigr		Butter	-	Date:	09/02/20	)22

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 94

MATERIAL DESCRIPTION: 12"x12" Blue Streaked Vinyl Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Gym/Lunchroom

MATERIAL QUANTITY: 3000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Dake & Estres	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	94						
MATERIAL DESCRI	PTION:	12"x12" Blue Str	reaked Vinyl Floor T	ile				
MATERIAL LOCATION	ON:	1961 Building- G	sym/Lunchroom					
MATERIAL QUANTI	TY:	3000			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the in	spection and assess	ment and reco	mmend appropri	ate respo	nse actions.	The
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Sigr	nature:	Jule Co	-	Date:	09/02/20	022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 94A

MATERIAL DESCRIPTION: 12"x12" Blue Streaked Vinyl Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Gym/Lunchroom

MATERIAL QUANTITY: 3000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Estis	Date:	08/09/2022	
		_		

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	94A					
MATERIAL DESCRI	PTION:	12"x12" Blue St	reaked Vinyl Floor 1	ile Mastic			
MATERIAL LOCATION	ON:	1961 Building- G	Sym/Lunchroom				
MATERIAL QUANTI	TY:	3000			MATERIAL UNI	TS:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	<b>3</b> :	SF
management planner original inspection of the following recomment.  The RESPONSE ACT Follow O&M Plan  Comments:	he above endations.	identified homoger					63.88 and 763.90 with
Management Plan	ner's Sigi	nature:	JULC CLO	-	Date:	09/02/20	022

### **TEM Environmental, Inc.** 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 23321 **BUIDLING ID:** 3530 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 INFORMATION FROM PREVIOUS INSPECTION **HOMOGENEOUS AREA:** Α MATERIAL DESCRIPTION: **Boiler Insulation NOT OBSERVED** HISTORICAL AHERA DAMAGE CATEGORY HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION: **ASBESTOS TYPE:** FRIABLE: RESULTS OF REINSPECTION AND REASSESSMENT This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection. The current AHERA DAMAGE CATEGORY is determined to be . DAMAGE REASON: **DISTURBANCE POTENTIAL:** MATERIAL LOCATION: **Boiler Room** MATERIAL QUANTITY: MATERIAL UNITS: DAMAGE QUANTITY: DAMAGE UNITS: COMMENTS: Not Observed, New Boilers Daker Ettis

Date:

08/09/2022

Inspector's Signature:

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

## **Management Planner Review Form**

23321

BUIDLING ID: 3530

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau				
SCHOOL NAME:	Gillespie School	REVIEW DATE:	9/2/2022				
ADDRESS:	9301 S State Street	IDPH LICENSE NO:	100-20327				
HOMOGENEOUS A	REA: A						
MATERIAL DESCRI	PTION: Boiler Insulati	on NOT OBSERVED					
MATERIAL LOCATION	ON: Boiler Room						
MATERIAL QUANTI	TY:		MATERIAL UNITS:				
DAMAGE QUANTIT	Y:		DAMAGE UNITS:				
management planner original inspection of t	In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.						
The RESPONSE AC	TION recommendation is:						
Comments:							
		210000000					
Management Plan	ner's Signature:	Duccel	Date: <b>09/02/2022</b>				
			<u>-</u>				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Inspector Assessment Form (REASSESSMENT)**

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 23321 **BUIDLING ID:** 3530 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: B

MATERIAL DESCRIPTION: Boiler Breaching NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

**DISTURBANCE POTENTIAL:** 

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

D/ cottes

COMMENTS: Not Observed. New Boilers

Inspector's Signature:	Valle Colo	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

## **Management Planner Review Form**

23321

BUIDLING ID: 3530

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau				
SCHOOL NAME:	Gillespie School	REVIEW DATE:	9/2/2022				
ADDRESS:	9301 S State Street	IDPH LICENSE NO:	100-20327				
HOMOGENEOUS A	REA: <b>B</b>						
MATERIAL DESCRI	PTION: Boiler Breach	ing NOT OBSERVED					
MATERIAL LOCATI	ON: Boiler Room						
MATERIAL QUANTI	TY:		MATERIAL UNITS:				
DAMAGE QUANTIT	Y:		DAMAGE UNITS:				
In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.							
The RESPONSE AC	CTION recommendation is:						
Comments:							
Management Plan	ner's Signature:	Ducce	Date: <b>09/02/2022</b>				
a.iagomont i lun							

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: C

MATERIAL DESCRIPTION: Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY 1 Damaged or significantly damaged friable thermal system insulating

**ACBM** 

HISTORICAL DAMAGE REASON: Deterioration

HISTORICAL RESPONSE ACTION: Repair

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 1. Damaged or significantly damaged friable thermal system insulating ACBM

DAMAGE REASON: Deterioration

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: 1944 Building- Coal Room, Boiler Room & Unfinished Pipe Space

DI Ati

MATERIAL QUANTITY: 2500 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS: 50 LF of Damage in Boiler Room

Inspector's Signature:	Vale & Edit	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### **Management Planner Review Form**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois MANAGEMENT PLANNER: Daniel Juneau

SCHOOL NAME: Gillespie School REVIEW DATE: 9/2/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

HOMOGENEOUS AREA: C

MATERIAL DESCRIPTION: Aircell Pipe Insulation

MATERIAL LOCATION: 1944 Building- Coal Room, Boiler Room & Unfinished Pipe Space

MATERIAL QUANTITY: 2500 MATERIAL UNITS: LF

DAMAGE QUANTITY: 50 DAMAGE UNITS: LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:
Replace or Repair Damaged Insulation

Repair

Management Planner's Signature:	Johnson	Date:	09/02/2022	

( 21000000

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: D

MATERIAL DESCRIPTION: Aircell Pipe Joint Insulation

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Coal Room & Unfinished Pipe Space

MATERIAL QUANTITY: 175 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

	Dakeretus			
Inspector's Signature:	Volume	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`	•					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S \$	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	D						
MATERIAL DESCRI	PTION:	Aircell Pipe Join	t Insulation					
MATERIAL LOCATION	ON:	1944 Building- C	coal Room & Unfinis	shed Pipe Spa	ace			
MATERIAL QUANTI	TY:	175			MATERIAL UNIT	ΓS:	LF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	LF	
n accordance with Se management planner original inspection of t he following recomme	to review he above	the results of the ir identified homoger	nspection and assess	ment and reco	ommend appropri	ate respo	nse actions.	The
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Sig	nature:	Jucc Cl	_	Date:	09/02/20	122	

#### **TEM Environmental, Inc.** 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 23321 **BUIDLING ID:** 3530 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 INFORMATION FROM PREVIOUS INSPECTION Ε **HOMOGENEOUS AREA:** MATERIAL DESCRIPTION: Tank Insulation NOT OBSERVED HISTORICAL AHERA DAMAGE CATEGORY HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION: **ASBESTOS TYPE:** FRIABLE: RESULTS OF REINSPECTION AND REASSESSMENT This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection. The current AHERA DAMAGE CATEGORY is determined to be . DAMAGE REASON: **DISTURBANCE POTENTIAL:** MATERIAL LOCATION: **Pump Room** MATERIAL QUANTITY: MATERIAL UNITS: DAMAGE QUANTITY: DAMAGE UNITS: COMMENTS: Not Observed, No Tank Daker Estis

Date:

08/09/2022

Inspector's Signature:

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Management Planner Review Form**

23321

BUIDLING ID: 3530

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau
SCHOOL NAME:	Gillespie School	REVIEW DATE:	9/2/2022
ADDRESS:	9301 S State Street	IDPH LICENSE NO:	100-20327
HOMOGENEOUS A	REA: <b>E</b>		
MATERIAL DESCRI	PTION: Tank Insulation	on NOT OBSERVED	
MATERIAL LOCATION	ON: Pump Room		
MATERIAL QUANTI	TY:		MATERIAL UNITS:
DAMAGE QUANTITY	Y:		DAMAGE UNITS:
management planner	to review the results of the he above identified homogeneous	e inspection and assessment and re	y Response Act (AHERA) the LEA must select a ecommend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
The RESPONSE AC	CTION recommendation is:	:	
Comments:			
		21220 2 22	
Management Plani	ner's Signature:	Ducce Co	Date: <b>09/02/2022</b>

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F** 

MATERIAL DESCRIPTION: Paper-Wrap Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Boys and Girls Toilet, Chases and Crawlspace

MATERIAL QUANTITY: 700 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

Inspector's Signature:	Docker Cotty	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	F						
MATERIAL DESCRI	PTION:	Paper-Wrap Pipe	e Insulation					
MATERIAL LOCATION	ON:	1944 Building- B	oys and Girls Toile	t, Chases and	l Crawlspace			
MATERIAL QUANTI	TY:	700			MATERIAL UNI	ΓS:	LF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	<b>S</b> :	LF	
n accordance with Semanagement planner original inspection of the following recomme	to review the above	the results of the ir	spection and assess	ment and reco	mmend appropri	ate respo	nse actions. T	The The
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
			Julce	_				
Management Plan	ner's Siai	nature:	5		Date:	09/02/20	022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: G

MATERIAL DESCRIPTION: Paper-Wrap Pipe Joint Insulation

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Boys and Girls Toilet, Chases and Crawlspace

MATERIAL QUANTITY: 80 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

	Dale & Estis			
Inspector's Signature:	Vaires	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLA	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS AREA: G							
MATERIAL DESCRI	PTION:	Paper-Wrap Pipe	Joint Insulation				
MATERIAL LOCATION	ON:	1944 Building- B	oys and Girls Toilet	, Chases and	l Crawlspace		
MATERIAL QUANTI	TY:	80			MATERIAL UNIT	TS:	LF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	LF
n accordance with Se management planner original inspection of t he following recomme	to review t he above	the results of the in	spection and assess	ment and reco	mmend appropria	ate respo	
The RESPONSE AC	TION reco	ommendation is:					
Follow O&M Plan							
Comments:							
Management Plan	ner's Sia	nature:	Julee	-	Date:	ng/n2/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: H

MATERIAL DESCRIPTION: Duct Insulation

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Unfinished Pipe Space

MATERIAL QUANTITY: 1000 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

Inspector's Signature:	Docker Edition	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			,				
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau		
SCHOOL NAME:	Gillespie	e School	REVIEW DATE:		9/2/2022		
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327		
HOMOGENEOUS A	REA:	н					
MATERIAL DESCRI	PTION:	<b>Duct Insulation</b>					
MATERIAL LOCATION	ON:	1944 Building- U	nfinished Pipe Spa	ce			
MATERIAL QUANTI	TY:	1000			MATERIAL UNIT	S:	SF
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	:	SF
n accordance with Semanagement planner original inspection of the following recommendates.	to review the above indations.	the results of the in identified homoger	spection and assess	ment and reco	mmend appropria	te respo	
Follow O&M Plan							
Comments:							
Management Plan	nor's Sign	natura:	Juccel	-	Data:	00/02/20	122

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:

MATERIAL DESCRIPTION: Duct Insulation

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1936 Building- Unfinished Pipe Space

MATERIAL QUANTITY: 1200 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

	Dake & Ethis		
Inspector's Signature:	Varie C 3	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	ı						
MATERIAL DESCRI	IPTION:	Duct Insulation						
MATERIAL LOCATI	ON:	1936 Building- U	Infinished Pipe Spa	ce				
MATERIAL QUANTI	ITY:	1200			MATERIAL UNIT	ΓS:	SF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	SF	
In accordance with Semanagement planner original inspection of the following recommend.  The RESPONSE AC	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	nse actions. T	he
Follow O&M Plan								
Comments:								
Management Plan	ner'e Sia	nature:	Jucce co	-	Date:	00/02/20	122	
ivialiauciliciil i lali		naturo.			Date.	<i><b>JULIA</b></i>	<i>1 = -</i>	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: K

MATERIAL DESCRIPTION: Fiberglass Joint Insulation

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Unfinished Pipe Space

MATERIAL QUANTITY: 345 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

Inspector's Signature:	Dake & Ethis	Date:	08/09/2022	
. 5				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	К						
MATERIAL DESCRI	PTION:	Fiberglass Joint	Insulation					
MATERIAL LOCATION	ON:	1961 Building- U	Infinished Pipe Spa	ce				
MATERIAL QUANTI	TY:	345			MATERIAL UNI	ΓS:	LF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	LF	
n accordance with Semanagement planner original inspection of the following recomme	to review the above	the results of the ir identified homoger	spection and assess	ment and reco	mmend appropri	ate respo	onse actions.	The
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
			Jule	_				
Management Plan	ner's Siai	nature:	5		Date:	09/02/20	022	

#### **TEM Environmental, Inc.** 2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530				
CITY/STATE:	Chicago, Illinois		AHERA INSPECTOR:	Drake Ottley					
SCHOOL NAME:	Gillespie School		INSPECTION DATE:	8/9/2022					
ADDRESS:	9301 S State Street		IDPH LICENSE NO:	100-20327					
	INFORMATION FROM PREVIOUS INSPECTION								
HOMOGENEOUS	AREA:	L							
MATERIAL DESCR	IPTION:	Tank Insula	ation NOT OBSERVED						
HISTORICAL AHER	RA DAMAGE CATEGORY								
HISTORICAL DAM	AGE REASON:								
HISTORICAL RESI	PONSE ACTION:								
ASBESTOS TYPE:				FRIABLE:					
	RESULTS OF REINSPECTION AND REASSESSMENT								
This homogeneous condition HAS NOT	area was reinspected and re CHANGED when compared	eassessed in acco I to the conditions	rdance with Section 763. of the last AHERA reinsp	85 and 763.88 of a pection.	AHERA and it's				
The current AHERA	A DAMAGE CATEGORY is de	etermined to be .							
DAMAGE REASON	l:								
DISTURBANCE PO	DTENTIAL:								
MATERIAL LOCAT	ION: Boiler Ro	oom							
MATERIAL QUANT	TITY:		MA	ATERIAL UNITS:					
DAMAGE QUANTI	ΓY:		DA	AMAGE UNITS:					
COMMENTS: No	t Observed. No Tank								
	T /	At.							
Inspector's Signa	Docke E.	Aug	Da	ate: 08/00/202	<b>)</b>				

Date: **08/09/2022** 

Inspector's Signature:

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Management Planner Review Form**

23321

BUIDLING ID: 3530

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau				
SCHOOL NAME:	Gillespie School	REVIEW DATE:	9/2/2022				
ADDRESS:	9301 S State Street	IDPH LICENSE NO:	100-20327				
HOMOGENEOUS A	REA: L						
MATERIAL DESCR	IPTION: Tank Insulation	on NOT OBSERVED					
MATERIAL LOCATI	ON: Boiler Room						
MATERIAL QUANT	ITY:		MATERIAL UNITS:				
DAMAGE QUANTIT	Y:		DAMAGE UNITS:				
management planner original inspection of the following recomm	In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.						
The RESPONSE AC	CTION recommendation is	:					
Comments:							
Management Plan	ner's Signature	Jule ce	Date: <b>09/02/2022</b>				
anagomont i lan			DGGG. VOIVELEVEE				

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: N

MATERIAL DESCRIPTION: Fiberglass Joint Insulation

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Unfinished Pipe Space

MATERIAL QUANTITY: 170 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

	Dake & Cotty		
Inspector's Signature:	Voct	Date:	08/09/2022

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

		`						
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S \$	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	N						
MATERIAL DESCRI	PTION:	Fiberglass Joint	Insulation					
MATERIAL LOCATION	ON:	Unfinished Pipe	Space					
MATERIAL QUANTI	TY:	170			MATERIAL UNIT	S:	LF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	LF	
n accordance with Semanagement planner original inspection of the following recommendation of the following recommendation of the following recommendation or	to review the above endations.	the results of the ir identified homoger	spection and assess	ment and reco	ommend appropria	ate respo	nse actions. T	he
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
		(A)	Luce co					
Management Plan	ner's Sigi	nature:			Date:	09/02/20	)22	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: P

MATERIAL DESCRIPTION: Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1961 Building- Unfinished Pipe Space & Outside Engineer's Office

MATERIAL QUANTITY: 100 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

Inspector's Signature:	Dake & College	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	P						
MATERIAL DESCRI	PTION:	Aircell Pipe Insu	ılation					
MATERIAL LOCATION	ON:	1961 Building- U	Infinished Pipe Spa	ce & Outside	Engineer's Offic	е		
MATERIAL QUANTI	TY:	100			MATERIAL UNIT	ΓS:	LF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	LF	
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the ir	nspection and assess	ment and reco	mmend appropri	ate respo	nse actions. The	
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Siar	nature:	Juccel	-	Date:	09/02/20	)22	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: R

MATERIAL DESCRIPTION: Fiberglass Joint Insulation

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

#### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1944 Building- Coal Room & Unfinished Pipe Space

MATERIAL QUANTITY: 60 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

Inspector's Signature:	Daker Ethy	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

			_					
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	23321	BUIDLING ID:	3530		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	Daniel Juneau			
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022			
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	:	100-20327			
HOMOGENEOUS A	REA:	R						
MATERIAL DESCRI	PTION:	Fiberglass Joint	Insulation					
MATERIAL LOCATION	ON:	1944 Building- C	Coal Room & Unfinis	shed Pipe Spa	ace			
MATERIAL QUANTI	TY:	60			MATERIAL UNI	TS:	LF	
DAMAGE QUANTIT	Y:	0			DAMAGE UNITS	S:	LF	
n accordance with Se management planner original inspection of t he following recomme	to review the above	the results of the ir	nspection and assess	ment and reco	ommend appropri	ate respo	onse actions. Th	ne
The RESPONSE AC	CTION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Plan	ner's Siai	nature:	Jule Cle	_	Date:	09/02/20	022	

#### **TEM Environmental, Inc.** 2022 AHERA REINSPECTION

#### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 23321 **BUIDLING ID:** 3530 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Drake Ottley** SCHOOL NAME: INSPECTION DATE: Gillespie School 8/9/2022 ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327 INFORMATION FROM PREVIOUS INSPECTION Т **HOMOGENEOUS AREA:** MATERIAL DESCRIPTION: Incinerator Insulation NOT OBSERVED HISTORICAL AHERA DAMAGE CATEGORY HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION: **ASBESTOS TYPE:** FRIABLE: RESULTS OF REINSPECTION AND REASSESSMENT This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection. The current AHERA DAMAGE CATEGORY is determined to be . DAMAGE REASON: **DISTURBANCE POTENTIAL:** MATERIAL LOCATION: 1944 Building- Boiler Room MATERIAL QUANTITY: MATERIAL UNITS: DAMAGE QUANTITY: DAMAGE UNITS: COMMENTS: Not Observed Daker Estis

Date:

08/09/2022

Inspector's Signature:

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

LEA NAIVIE.	Cnicago	Public Schools	UNIT NUMBER.	23321	BUIDLING ID. 3530
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT P	LANNER:	Daniel Juneau
SCHOOL NAME:	Gillespi	e School	REVIEW DATE:		9/2/2022
ADDRESS:	9301 S S	State Street	IDPH LICENSE NO	<b>)</b> :	100-20327
HOMOGENEOUS A	REA:	т			
MATERIAL DESCRI	PTION:	Incinerator Insu	lation NOT OBSER	VED	
MATERIAL LOCATION	ON:	1944 Building- B	Boiler Room		
MATERIAL QUANTI	TY:				MATERIAL UNITS:
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS:
management planner	to review the above endations.	the results of the ir identified homoger	nspection and asses	sment and reco	Response Act (AHERA) the LEA must select a commend appropriate response actions. The eccordance with Sections 763.88 and 763.90 with
Comments:					
Management Plani	ner's Sigi	nature:	Jucce Co		Date: <b>09/02/2022</b>

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Inspector Assessment Form (New Homogeneous Area)**

LEA NAME: Chicago Public Schools UNIT NUMBER: 23321 BUIDLING ID: 3530

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Drake Ottley

SCHOOL NAME: Gillespie School INSPECTION DATE: 8/9/2022

ADDRESS: 9301 S State Street IDPH LICENSE NO: 100-20327

#### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW** 

MATERIAL DESCRIPTION: Newly Installed Suspect ACM

MATERIAL LOCATION: Installed After Implementation of Management Plan and Afte Renovations

MATERIAL QUANTITY: MATERIAL UNITS:

MATERIAL CATEGORY: MISC FRIABLE:

ASBESTOS TYPE: Assumed

DISTURBANCE POTENTIAL: CONDITION:

AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage

ACCESSIBILITY: Within Reach DAMAGE REASON:

DAMAGE REASON: DAMAGE REASON: DAMAGE UNITS:

COMMENTS:

DAMAGE QUANTITY:

	Darke & Cottes			
Inspector's Signature:	Vote	Date:	08/09/2022	

# TEM Environmental, Inc. 2022 AHERA REINSPECTION

#### **Management Planner Review Form**

23321

BUIDLING ID: 3530

UNIT NUMBER:

**Chicago Public Schools** 

LEA NAME:

CITY/STATE:	Chicago, Illinois	MANAGEMENT PL	ANNER: <b>Danie</b>	l Juneau
SCHOOL NAME:	Gillespie School	REVIEW DATE:	9/2/20	22
ADDRESS:	9301 S State Str	eet IDPH LICENSE NO	: 100-20	0327
HOMOGENEOUS A	AREA:	NEW		
MATERIAL DESCR	IPTION:	Newly Installed Suspect ACM		
MATERIAL LOCATI	ON:	Installed After Implementation	of Management P	an and Afte Renovations
MATERIAL QUANT	ITY:		MATERIAL UNITS:	
DAMAGE QUANTIT	Y:		DAMAGE UNITS:	
management planne	er to review the resove identified home	sults of the inspection and assess	sment and recomme	onse Act (AHERA) the LEA must select a nd appropriate response actions. The original h Sections 763.88 and 763.90 with the
The RESPONSE AC	CTION recommend	dation is:		
COMMENTS:				
		Aucel		
Management Plan	ner's Signature:	The state of the s	1	Date: <u>09/02/2022</u>

## APPENDIX B

## **Inspector and Management Planner Licenses**



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

# Drake Ottley

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/1/2021

Exam Date: 12/1/2021

Expiration Date: 12/1/2022

Certificate Number: BIR2112012887

Kathy DeSalvo Director





#### **ASBESTOS** PROFESSIONAL LICENSE

ID NUMBER 100 - 20327 ISSUED 3/1/2022

**EXPIRES** 05/15/2023

DRAKE E OTTLEY 693 LEXINGTON DR GENEVA, IL 60134

Environmental Health



**ENDORSEMENTS** TC EXPIRES

INSPECTOR 12/1/2022

PROJECT MANAGER 12/2/2022

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



# EarthTech, Inc.

435 Shadow Wood Drive, Yorkville, IL 60560

# Asbestos Building Inspector Refresher

# THIS CERTIFIES THAT Drake Ottley

Has successfully completed the IL and IN Approved Asbestos Training Course and passed the Examination for purposes of accreditation under section 206 of Title II, 15 USC 2646 of the Toxic Substances Control Act (TSCA) and 326 IAC 18-2. Conducted by EarthTech, Inc 630-417-6951

CLASS DATES: 11/16/2022

LOCATION: Amerisafe

EXAMINATION:

11/16/2022

EXPIRATION:

11/16/2023

CERTIFICATE NUMBER: 110173X19S103885





#### **ASBESTOS PROFESSIONAL** LICENSE

ID NUMBER 100 - 03613 ISSUED 3/1/2022

**EXPIRES** 05/15/2023

DANIEL J JUNEAU 1408 OAKWOOD AVENUE DES PLAINES, IL 60016

Environmental Health



#### **ENDORSEMENTS**

#### TC EXPIRES

INSPECTOR

11/19/2022

MANAGEMENT PLANNER

11/19/2022 11/1/2022

PROJECT MANAGER AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action This license issued under authority of the State of Illinois

Department of Public Health This license is valid only when accompanied by a valid training course certificate.



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

Kathy DeSalvo, Director



# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

## Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

Kathy DeSalvo Director



# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

## Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo Director



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645

Kathy DeSalvo, Director

## APPENDIX C

## **Laboratory Accreditations**

## APPENDIX D

## **Laboratory Results**

## APPENDIX E

## Chain of Custody Forms

## **Three-Year Reinspection Key to Terms**

	CODE	KEY
MATERIAL CATEGORY	ACBM	Asbestos Containing Building Materials
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed