

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2622
SCHOOL NAME: Grissom School
ADDRESS OF SCHOOL: 12810 Escanaba
CITY: Chicago, IL, 60633

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **10/2/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 8/12/2022 ENROLLMENT 307
IDPH INSPECTOR LICENSE NUMBER: 100-18281
IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

9/8/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Grissom School

12810 Escanaba
Chicago, IL, 60633

Unit: 23361
Building ID: 3580

IDPH ID Number: 14-016-2990-2622

REPORT DATE:

Thursday, September 08, 2022

Prepared for:

**Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

09/08/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23361 Region: 06 IDPH ID: 14-016-2990-2622

School: Grissom School Building ID: 3580

Address: 12810 Escanaba
Chicago, IL, 60633

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/12/2022

Review Date: 09/08/2022

Inspector: Christopher Antonopoulos
Management Planner: Todd Huffer

Inspector IDPH License: 100-18281
Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 08, 2022

RE: Grissom School, Unit 23361
12810 Escanaba
Chicago, IL, 60633

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Grissom School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Grissom School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Grissom School
Address: 12810 Escanaba
IDPH ID: 14-016-2990-2622
Contact:

Unit: 23361
Chicago, IL, 60633
Building ID: 3580
Phone:

Region: 06

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 307

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Christopher Antonopoulos



Inspector IDPH license # 100-18281
Reinspection Date: 8/12/2022

Signature:
Date: 8/12/2022

6. Management Planner

Management Planner Name: Todd Huffer



Management Planner IDPH license # 100-09870

Signature:
Date: 09/08/2022

7. Review Date: 09/08/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 9/8/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Grissom School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3580:

34	Terrazzo Flooring
C	Incinerator Brick ABATED
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 3580:

34	Terrazzo Flooring
NEW	Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

07	Insulation in Fire Rated Doors
08	Black Vinyl Baseboard
09	Black Vinyl Baseboard Mastic
10	Dark Gray Vinyl Baseboard
11	Dark Gray Vinyl Baseboard Mastic
12	Interior Window Glazing
13	Interior Window Glazing
14	Carpet Mastic
15	2' x 4' Acoustical Ceiling Tile
16	Spray-On Insulation
17	Off-White Baseboard
18	Off-White Baseboard Mastic
19	12"x12" Red Floor Tile
20	12"x12" Red Floor Tile Mastic
21	Red and Cream Speckled Terrazzo
22	Pink, Tan and White Ceramic Tile Grout
23	Pink, Tan and White Ceramic Tile Adhesive
24	Light Green Speckled Green Ceramic Tile Grout
25	Light Green Speckled Green Ceramic Tile Adhesive
26	White and Grey Ceramic Tile Grout
27	White and Grey Ceramic Tile Adhesive
28	Yellow and White Ceramic Tile Grout
29	Yellow and White Ceramic Tile Adhesive
30	12x12 Cream w/White Specks Vinyl Floor Tile
31	12x12 Cream w/White Specks Vinyl Floor Tile Mastic
32	Gray Carpet Mastic
33	MJP on Fiberglass
34	Terrazzo Flooring
E	Gasket on Air Handling Unit
F	Vibration Dampener Gasket
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

02D	12x12 Off White w/Specks Floor Tile Mastic
05A	12x12 Light Brown w/Specks Floor Tile Mastic
05B	12x12 Tan w/ Brown Specks Floor Tile Mastic
05C	12x12 Dark Brown Floor Tile Mastic
05D	12x12 Off White w/Specks Floor Tile Mastic

05E	12x12 Off White Floor Tile Mastic
05F	12x12 Medium Brown w/Specks Floor Tile Mastic
05G	12x12 Light Green Floor Tile Mastic
05H	12x12 Blue w/White Specks Floor Tile Mastic
07	Insulation in Fire Rated Doors
09	Black Vinyl Baseboard Mastic
11	Dark Gray Vinyl Baseboard Mastic
14	Carpet Mastic
15	2' x 4' Acoustical Ceiling Tile
16	Spray-On Insulation
18	Off-White Baseboard Mastic
20	12"x12" Red Floor Tile Mastic
23	Pink, Tan and White Ceramic Tile Adhesive
25	Light Green Speckled Green Ceramic Tile Adhesive
27	White and Grey Ceramic Tile Adhesive
29	Yellow and White Ceramic Tile Adhesive
31	12x12 Cream w/White Specks Vinyl Floor Tile Mastic
32	Gray Carpet Mastic
A	Cementitious Pipe Joint Insulation
D	Insulation in Vault Door

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Grissom School Building 3580 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Grissom School Unit 23361 Building ID 3580

Address 12810 Escanaba Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02A	12x12 Light Brown w/Specks Floor Tile	460	SF	Room 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02B	12x12 Tan w/Brown Specks Floor Tile	10,000	SF	Rooms 103, 104, 201, 203, Nurse's Office, 1st & 2nd Floor Corridors, MDF Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02C	12x12 Dark Brown Floor Tile	830	SF	1st and 2nd Floor Corridor Edgings	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02D	12x12 Off White w/Specks Floor Tile Mastic	1,460	SF	Room 106, Mobile Unit	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02E	12x12 Off White Floor Tile	6,680	SF	Rooms 102, 208, 206, 204, Counselor's Room, Main Office & Principal's Office, Teacher's Room, Storage Room, Room 108	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02F	12x12 Medium Brown w/Specks Floor Tile	510	SF	Kitchen, Main Office Vault and Supply Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02G	12x12 Light Green Floor Tile	708	SF	Engineer's Office and Closets, and Rooms 202, 205	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02H	12x12 Blue w/White Specks Floor Tile	500	SF	Room 108	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	12x12 Light Brown w/Specks Floor Tile Mastic	460	SF	Room 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	12x12 Tan w/ Brown Specks Floor Tile Mastic	10,000	SF	Rooms 103, 104, 201, 203, Nurse's Office, 1st & 2nd Floor Corridors, MDF Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05C	12x12 Dark Brown Floor Tile Mastic	830	SF	1st and 2nd Floor Corridor Edgings	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05D	12x12 Off White w/Specks Floor Tile Mastic	460	SF	Room 106, Mobile Unit	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05E	12x12 Off White Floor Tile Mastic	6,680	SF	Rooms 102, 108, 208, 206, 204, Counselor's Room, Main Office & Principal's Office, Teacher's Room, Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Grissom School Unit 23361 Building ID 3580

Address 12810 Escanaba Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
05F	12x12 Medium Brown w/Specks Floor Tile Mastic	510	SF	Kitchen, Main Office Vault and Supply Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05G	12x12 Light Green Floor Tile Mastic	708	SF	Engineer's Office and Closets, and Rooms 202, 205	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05H	12x12 Blue w/White Specks Floor Tile Mastic	500	SF	Room 108	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	Insulation in Fire Rated Doors	400	SF	Boiler Room, All Purpose Room, Utility Room Near Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Black Vinyl Baseboard	900	LF	Rooms 103, 104, 106, 205, 206, 207, and Teachers' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Black Vinyl Baseboard Mastic	900	LF	Rooms 103, 104, 106, 205, 206, 207, and Teachers Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Dark Gray Vinyl Baseboard	200	LF	Rooms 102, 106, 108, 208 (Counter Footings)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Dark Gray Vinyl Baseboard Mastic	200	LF	Rooms 102, 106, 108, 208 (Counter Footings)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Interior Window Glazing	1,420	LF	Throughout First Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Interior Window Glazing	1,420	SF	Throughout Second Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Carpet Mastic	900	SF	Room 207, Principal's Office, Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	2' x 4' Acoustical Ceiling Tile	20,000	SF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
16	Spray-On Insulation	20,000	SF	Troughout Building, Above Ceiling Tile	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
17	Off-White Baseboard	500	LF	Throughout Mobile Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Off-White Baseboard Mastic	500	LF	Throughout Mobile Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Red Floor Tile	1,500	SF	1st Floor Main Entry	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Grissom School Unit 23361 Building ID 3580

Address 12810 Escanaba Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lobby & South Entrance								potential for damage		
20	12"x12" Red Floor Tile Mastic	1,500	SF	1st Floor Main Entry Lobby & South Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Red and Cream Speckled Terrazzo	1,152	SF	Northeast and Southeast Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Pink, Tan and White Ceramic Tile Grout	824	SF	1st and 2nd Floor Girls' Restrooms and 1st Floor Women's Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Pink, Tan and White Ceramic Tile Adhesive	824	SF	1st and 2nd Floor Girls' Restrooms and 1st Floor Women's Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Light Green Speckled Green Ceramic Tile Grout	724	SF	1st and 2nd Floor Boys' Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Light Green Speckled Green Ceramic Tile Adhesive	724	SF	1st and 2nd Floor Boys' Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	White and Grey Ceramic Tile Grout	200	SF	1st and 2nd Floor Janitor's Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	White and Grey Ceramic Tile Adhesive	200	SF	1st and 2nd Floor Janitor's Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Yellow and White Ceramic Tile Grout	324	SF	1st and 2nd Floor Men's and Women's Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Yellow and White Ceramic Tile Adhesive	324	SF	1st and 2nd Floor Men's and Women's Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12x12 Cream w/White Specks Vinyl Floor Tile	2,500	SF	All Purpose Room and Stage Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
31	12x12 Cream w/White Specks Vinyl Floor Tile Mastic	2,500	SF	All Purpose Room and Stage Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Gray Carpet Mastic	500	SF	Main Office and Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	MJP on Fiberglass	100	SF	Kitchen, 2nd Floor Janitor's Closet	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
34	Terrazzo Flooring	500	SF	Stairs & Landings	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Cementitious Pipe Joint Insulation	950	LF	Chases above the Ceiling and Fan Room, Kitchen and 2nd Floor Janitor's	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Grissom School Unit 23361 Building ID 3580

Address 12810 Escanaba Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Closet Chase										
C	Incinerator Brick ABATED			Boiler Room	ABATED	TSI					Yes			
D	Insulation in Vault Door	18	SF	1st Floor Office Vault	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
E	Gasket on Air Handling Unit	14	LF	Fan Room near Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
F	Vibration Dampener Gasket	18	LF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

Chicago Public Schools

School Grissom School Unit 23361 Building ID 3580

Address 12810 Escanaba Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/12/2022
Inspector Name Christopher Antonopoulos
100-18281 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
02A	
02B	
02C	
02D	
02E	
02F	
02G	
02H	
05A	
05B	
05C	
05D	
05E	
05F	
05G	
05H	
07	
08	
09	
10	
11	
12	
13	
14	

Chicago Public Schools

School Grissom School Unit 23361 Building ID 3580

Address 12810 Escanaba Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
A	
C	Abated
D	
E	
F	
NEW	

Chicago Public Schools

School Grissom School **Unit** 23361 **Building ID** 3580

Address 12810 Escanaba **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Grissom School
Address 12810 Escanaba

Unit 23361
Chicago, IL, 60633

Building ID 3580
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02A	12x12 Light Brown w/Specks Floor Tile	460	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02B	12x12 Tan w/Brown Specks Floor Tile	10,000	SF	Rooms 103, 104, 201, 203, Nurse's Office, 1st & 2nd Floor Corridors, MDF Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02C	12x12 Dark Brown Floor Tile	830	SF	1st and 2nd Floor Corridor Edgings	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02D	12x12 Off White w/Specks Floor Tile Mastic	1,460	SF	Room 106, Mobile Unit	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02E	12x12 Off White Floor Tile	6,680	SF	Rooms 102, 208, 206, 204, Counselor's Room, Main Office & Principal's Office, Teacher's Room, Storage Room, Room 108	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02F	12x12 Medium Brown w/Specks Floor Tile	510	SF	Kitchen, Main Office Vault and Supply Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02G	12x12 Light Green Floor Tile	708	SF	Engineer's Office and Closets, and Rooms 202, 205	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02H	12x12 Blue w/White Specks Floor Tile	500	SF	Room 108	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05A	12x12 Light Brown w/Specks Floor Tile Mastic	460	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05B	12x12 Tan w/ Brown Specks Floor Tile Mastic	10,000	SF	Rooms 103, 104, 201, 203, Nurse's Office, 1st & 2nd Floor Corridors, MDF Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05C	12x12 Dark Brown Floor Tile Mastic	830	SF	1st and 2nd Floor Corridor Edgings	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05D	12x12 Off White w/Specks Floor Tile Mastic	460	SF	Room 106, Mobile Unit	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05E	12x12 Off White Floor Tile Mastic	6,680	SF	Rooms 102, 108, 208, 206, 204, Counselor's Room, Main Office & Principal's Office, Teacher's Room, Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05F	12x12 Medium Brown w/Specks Floor Tile Mastic	510	SF	Kitchen, Main Office Vault and Supply Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05G	12x12 Light Green Floor Tile Mastic	708	SF	Engineer's Office and Closets, and Rooms 202, 205	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05H	12x12 Blue w/White Specks Floor Tile Mastic	500	SF	Room 108	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	Insulation in Fire Rated Doors	400	SF	Boiler Room, All Purpose Room, Utility Room Near Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Black Vinyl Baseboard	900	LF	Rooms 103, 104, 106, 205, 206, 207, and Teachers' Restroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
09	Black Vinyl Baseboard Mastic	900	LF	Rooms 103, 104, 106, 205, 206, 207, and Teachers Restroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Grissom School
Address 12810 Escanaba

Unit 23361
Chicago, IL, 60633

Building ID 3580
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
10	Dark Gray Vinyl Baseboard	200	LF	Rooms 102, 106, 108, 208 (Counter Footings)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
11	Dark Gray Vinyl Baseboard Mastic	200	LF	Rooms 102, 106, 108, 208 (Counter Footings)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Interior Window Glazing	1,420	LF	Throughout First Floor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13	Interior Window Glazing	1,420	SF	Throughout Second Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Carpet Mastic	900	SF	Room 207, Principal's Office, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	2' x 4' Acoustical Ceiling Tile	20,000	SF	Throughout Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
16	Spray-On Insulation	20,000	SF	Troughout Building, Above Ceiling Tile	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
17	Off-White Baseboard	500	LF	Throughout Mobile Unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
18	Off-White Baseboard Mastic	500	LF	Throughout Mobile Unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Red Floor Tile	1,500	SF	1st Floor Main Entry Lobby & South Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Red Floor Tile Mastic	1,500	SF	1st Floor Main Entry Lobby & South Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Red and Cream Speckled Terrazzo	1,152	SF	Northeast and Southeast Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Pink, Tan and White Ceramic Tile Grout	824	SF	1st and 2nd Floor Girls' Restrooms and 1st Floor Women's Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Pink, Tan and White Ceramic Tile Adhesive	824	SF	1st and 2nd Floor Girls' Restrooms and 1st Floor Women's Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Light Green Speckled Green Ceramic Tile Grout	724	SF	1st and 2nd Floor Boys' Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Light Green Speckled Green Ceramic Tile Adhesive	724	SF	1st and 2nd Floor Boys' Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	White and Grey Ceramic Tile Grout	200	SF	1st and 2nd Floor Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	White and Grey Ceramic Tile Adhesive	200	SF	1st and 2nd Floor Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Yellow and White Ceramic Tile Grout	324	SF	1st and 2nd Floor Men's and Women's Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Yellow and White Ceramic Tile Adhesive	324	SF	1st and 2nd Floor Men's and Women's Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12x12 Cream w/White Specks Vinyl Floor Tile	2,500	SF	All Purpose Room and Stage Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12x12 Cream w/White Specks Vinyl Floor Tile Mastic	2,500	SF	All Purpose Room and Stage Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Grissom School
Address 12810 Escanaba

Unit 23361
 Chicago, IL, 60633

Building ID 3580
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	Gray Carpet Mastic	500	SF	Main Office and Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	MJP on Fiberglass	100	SF	Kitchen, 2nd Floor Janitor's Closet	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
34	Terrazzo Flooring	500	SF	Stairs & Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Cementitious Pipe Joint Insulation	950	LF	Chases above the Ceiling and Fan Room, Kitchen and 2nd Floor Janitor's Closet Chase	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Incinerator Brick ABATED			Boiler Room	Abated	TSI					
D	Insulation in Vault Door	18	SF	1st Floor Office Vault	Chrysotile	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
E	Gasket on Air Handling Unit	14	LF	Fan Room near Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	Vibration Dampener Gasket	18	LF	Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Grissom School
Address 12810 Escanaba

Unit 23361
 Chicago, IL, 60633

Building ID 3580
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	9/8/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
02A	
02B	
02C	
02D	
02E	
02F	
02G	
02H	
05A	
05B	
05C	
05D	
05E	
05F	
05G	
05H	
07	
08	
09	
10	
11	
12	

Chicago Public Schools

School Grissom School
Address 12810 Escanaba

Unit 23361
 Chicago, IL, 60633

Building ID 3580
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
A	
C	
D	
E	
F	

Chicago Public Schools

School Grissom School
Address 12810 Escanaba

Unit 23361
Chicago, IL, 60633

Building ID 3580
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
NEW	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**
MATERIAL DESCRIPTION: **12x12 Light Brown w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02A**
MATERIAL DESCRIPTION: **12x12 Light Brown w/Specks Floor Tile**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02B**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 103, 104, 201, 203, Nurse's Office, 1st & 2nd Floor Corridors, MDF Room**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02B**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Specks Floor Tile**
MATERIAL LOCATION: **Rooms 103, 104, 201, 203, Nurse's Office, 1st & 2nd Floor Corridors, MDF Room**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02C**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridor Edgings**
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02C**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile**
MATERIAL LOCATION: **1st and 2nd Floor Corridor Edgings**
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02D**
MATERIAL DESCRIPTION: **12x12 Off White w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106, Mobile Unit**
MATERIAL QUANTITY: **1460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02D**
MATERIAL DESCRIPTION: **12x12 Off White w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Room 106, Mobile Unit**
MATERIAL QUANTITY: **1460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02E**
MATERIAL DESCRIPTION: **12x12 Off White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 208, 206, 204, Counselor's Room, Main Office & Principal's Office, Teacher's Room, Storage Room, Room 108**

MATERIAL QUANTITY: **6680** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02E**
MATERIAL DESCRIPTION: **12x12 Off White Floor Tile**
MATERIAL LOCATION: **Rooms 102, 208, 206, 204, Counselor's Room, Main Office & Principal's Office, Teacher's Room, Storage Room, Room 108**
MATERIAL QUANTITY: **6680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02F**
MATERIAL DESCRIPTION: **12x12 Medium Brown w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen, Main Office Vault and Supply Room**
MATERIAL QUANTITY: **510** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02F**
MATERIAL DESCRIPTION: **12x12 Medium Brown w/Specks Floor Tile**
MATERIAL LOCATION: **Kitchen, Main Office Vault and Supply Room**
MATERIAL QUANTITY: **510** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23361 BUILDING ID: 3580
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Grissom School INSPECTION DATE: 8/12/2022
ADDRESS: 12810 Escanaba IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02G
MATERIAL DESCRIPTION: 12x12 Light Green Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Engineer's Office and Closets, and Rooms 202, 205
MATERIAL QUANTITY: 708 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02G**
MATERIAL DESCRIPTION: **12x12 Light Green Floor Tile**
MATERIAL LOCATION: **Engineer's Office and Closets, and Rooms 202, 205**
MATERIAL QUANTITY: **708** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02H**
MATERIAL DESCRIPTION: **12x12 Blue w/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02H**
MATERIAL DESCRIPTION: **12x12 Blue w/White Specks Floor Tile**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12x12 Light Brown w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12x12 Light Brown w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **12x12 Tan w/ Brown Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 103, 104, 201, 203, Nurse's Office, 1st & 2nd Floor Corridors, MDF Room**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **12x12 Tan w/ Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 103, 104, 201, 203, Nurse's Office, 1st & 2nd Floor Corridors, MDF Room**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05C**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridor Edgings**
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05C**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**
MATERIAL LOCATION: **1st and 2nd Floor Corridor Edgings**
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05D**
MATERIAL DESCRIPTION: **12x12 Off White w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106, Mobile Unit**
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05D**
MATERIAL DESCRIPTION: **12x12 Off White w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Room 106, Mobile Unit**
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05E**
MATERIAL DESCRIPTION: **12x12 Off White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 108, 208, 206, 204, Counselor's Room, Main Office & Principal's Office, Teacher's Room, Storage Room**

MATERIAL QUANTITY: **6680** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05E**
MATERIAL DESCRIPTION: **12x12 Off White Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 102, 108, 208, 206, 204, Counselor's Room, Main Office & Principal's Office, Teacher's Room, Storage Room**
MATERIAL QUANTITY: **6680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23361 BUILDING ID: 3580
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Grissom School INSPECTION DATE: 8/12/2022
ADDRESS: 12810 Escanaba IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05F
MATERIAL DESCRIPTION: 12x12 Medium Brown w/Specks Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Kitchen, Main Office Vault and Supply Room
MATERIAL QUANTITY: 510 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUILDING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05F**
MATERIAL DESCRIPTION: **12x12 Medium Brown w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen, Main Office Vault and Supply Room**
MATERIAL QUANTITY: **510** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05G**
MATERIAL DESCRIPTION: **12x12 Light Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office and Closets, and Rooms 202, 205**
MATERIAL QUANTITY: **708** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05G**
MATERIAL DESCRIPTION: **12x12 Light Green Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office and Closets, and Rooms 202, 205**
MATERIAL QUANTITY: **708** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05H**
MATERIAL DESCRIPTION: **12x12 Blue w/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **05H**
MATERIAL DESCRIPTION: **12x12 Blue w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room, All Purpose Room, Utility Room Near Gym**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**
MATERIAL LOCATION: **Boiler Room, All Purpose Room, Utility Room Near Gym**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23361 BUILDING ID: 3580
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Grissom School INSPECTION DATE: 8/12/2022
ADDRESS: 12810 Escanaba IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08
MATERIAL DESCRIPTION: Black Vinyl Baseboard
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Rooms 103, 104, 106, 205, 206, 207, and Teachers' Restroom
MATERIAL QUANTITY: 900 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**
MATERIAL LOCATION: **Rooms 103, 104, 106, 205, 206, 207, and Teachers' Restroom**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 103, 104, 106, 205, 206, 207, and Teachers Restroom**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Rooms 103, 104, 106, 205, 206, 207, and Teachers Restroom**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Dark Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102, 106, 108, 208 (Counter Footings)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Dark Gray Vinyl Baseboard**
MATERIAL LOCATION: **Rooms 102, 106, 108, 208 (Counter Footings)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Dark Gray Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102, 106, 108, 208 (Counter Footings)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Dark Gray Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Rooms 102, 106, 108, 208 (Counter Footings)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23361 BUIDLING ID: 3580
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Grissom School INSPECTION DATE: 8/12/2022
ADDRESS: 12810 Escanaba IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12
MATERIAL DESCRIPTION: Interior Window Glazing
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Throughout First Floor
MATERIAL QUANTITY: 1420 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Interior Window Glazing**
MATERIAL LOCATION: **Throughout First Floor**
MATERIAL QUANTITY: **1420** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Interior Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Second Floor**
MATERIAL QUANTITY: **1420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Interior Window Glazing**
MATERIAL LOCATION: **Throughout Second Floor**
MATERIAL QUANTITY: **1420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 207, Principal's Office, Main Office**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Room 207, Principal's Office, Main Office**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tile**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Spray-On Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Troughout Building, Above Ceiling Tile**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Spray-On Insulation**
MATERIAL LOCATION: **Troughout Building, Above Ceiling Tile**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Off-White Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Mobile Unit**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Off-White Baseboard**
MATERIAL LOCATION: **Throughout Mobile Unit**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Off-White Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Mobile Unit**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Off-White Baseboard Mastic**
MATERIAL LOCATION: **Throughout Mobile Unit**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Red Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Main Entry Lobby & South Entrance**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Red Floor Tile**
MATERIAL LOCATION: **1st Floor Main Entry Lobby & South Entrance**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Red Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Main Entry Lobby & South Entrance**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Red Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Main Entry Lobby & South Entrance**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Red and Cream Speckled Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Northeast and Southeast Stairwells**
MATERIAL QUANTITY: **1152** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Red and Cream Speckled Terrazzo**
MATERIAL LOCATION: **Northeast and Southeast Stairwells**
MATERIAL QUANTITY: **1152** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23361 BUILDING ID: 3580
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Grissom School INSPECTION DATE: 8/12/2022
ADDRESS: 12810 Escanaba IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22
MATERIAL DESCRIPTION: Pink, Tan and White Ceramic Tile Grout
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1st and 2nd Floor Girls' Restrooms and 1st Floor Women's Restroom
MATERIAL QUANTITY: 824 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Pink, Tan and White Ceramic Tile Grout**
MATERIAL LOCATION: **1st and 2nd Floor Girls' Restrooms and 1st Floor Women's Restroom**
MATERIAL QUANTITY: **824** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Pink, Tan and White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Girls' Restrooms and 1st Floor Women's Restroom**
MATERIAL QUANTITY: **824** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Pink, Tan and White Ceramic Tile Adhesive**
MATERIAL LOCATION: **1st and 2nd Floor Girls' Restrooms and 1st Floor Women's Restroom**
MATERIAL QUANTITY: **824** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Light Green Speckled Green Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Boys' Restrooms**
MATERIAL QUANTITY: **724** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Light Green Speckled Green Ceramic Tile Grout**
MATERIAL LOCATION: **1st and 2nd Floor Boys' Restrooms**
MATERIAL QUANTITY: **724** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Light Green Speckled Green Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Boys' Restrooms**
MATERIAL QUANTITY: **724** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Light Green Speckled Green Ceramic Tile Adhesive**
MATERIAL LOCATION: **1st and 2nd Floor Boys' Restrooms**
MATERIAL QUANTITY: **724** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **White and Grey Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Janitor's Closet**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **White and Grey Ceramic Tile Grout**
MATERIAL LOCATION: **1st and 2nd Floor Janitor's Closet**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23361 BUIDLING ID: 3580
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Grissom School INSPECTION DATE: 8/12/2022
ADDRESS: 12810 Escanaba IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27
MATERIAL DESCRIPTION: White and Grey Ceramic Tile Adhesive
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1st and 2nd Floor Janitor's Closet

MATERIAL QUANTITY: 200

MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **White and Grey Ceramic Tile Adhesive**
MATERIAL LOCATION: **1st and 2nd Floor Janitor's Closet**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Yellow and White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Men's and Women's Restrooms**
MATERIAL QUANTITY: **324** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Yellow and White Ceramic Tile Grout**
MATERIAL LOCATION: **1st and 2nd Floor Men's and Women's Restrooms**
MATERIAL QUANTITY: **324** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Yellow and White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Men's and Women's Restrooms**
MATERIAL QUANTITY: **324** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Yellow and White Ceramic Tile Adhesive**
MATERIAL LOCATION: **1st and 2nd Floor Men's and Women's Restrooms**
MATERIAL QUANTITY: **324** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12x12 Cream w/White Specks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **All Purpose Room and Stage Vestibules**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12x12 Cream w/White Specks Vinyl Floor Tile**
MATERIAL LOCATION: **All Purpose Room and Stage Vestibules**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12x12 Cream w/White Specks Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Purpose Room and Stage Vestibule**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12x12 Cream w/White Specks Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **All Purpose Room and Stage Vestibule**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office and Principal's Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
MATERIAL LOCATION: **Main Office and Principal's Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **MJP on Fiberglass**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen, 2nd Floor Janitor's Closet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **MJP on Fiberglass**
MATERIAL LOCATION: **Kitchen, 2nd Floor Janitor's Closet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACM or friable suspect ACM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACM or friable suspect ACM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Chases above the Ceiling and Fan Room, Kitchen and 2nd Floor Janitor's Closet Chase**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation**
MATERIAL LOCATION: **Chases above the Ceiling and Fan Room, Kitchen and 2nd Floor Janitor's Closet Chase**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Incinerator Brick ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS: **Abated**

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Incinerator Brick ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Insulation in Vault Door**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Office Vault**
MATERIAL QUANTITY: **18** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Insulation in Vault Door**
MATERIAL LOCATION: **1st Floor Office Vault**
MATERIAL QUANTITY: **18** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Gasket on Air Handling Unit**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Room near Gym**
MATERIAL QUANTITY: **14** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Gasket on Air Handling Unit**
MATERIAL LOCATION: **Fan Room near Gym**
MATERIAL QUANTITY: **14** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23361 BUILDING ID: 3580
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Grissom School INSPECTION DATE: 8/12/2022
ADDRESS: 12810 Escanaba IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F
MATERIAL DESCRIPTION: Vibration Dampener Gasket
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Boiler Room
MATERIAL QUANTITY: 18 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUIDLING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Vibration Dampener Gasket**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **18** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/08/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUILDING ID: **3580**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Grissom School** INSPECTION DATE: **8/12/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Terrazzo Flooring**
MATERIAL LOCATION: **Stairs & Landings**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **08/12/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUILDING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**


HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Terrazzo Flooring**
MATERIAL LOCATION: **Stairs & Landings**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/08/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23361	BUILDING ID:	3580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Christopher Antonopoulos		
SCHOOL NAME:	Grissom School	INSPECTION DATE:	8/12/2022		
ADDRESS:	12810 Escanaba	IDPH LICENSE NO:	100-18281		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	NEW	
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM	
MATERIAL LOCATION:	Installed After Implementation of Management Plan and After Renovations	
MATERIAL QUANTITY:		MATERIAL UNITS:
MATERIAL CATEGORY:	MISC	FRIABLE:
ASBESTOS TYPE:	Assumed	
DISTURBANCE POTENTIAL:		CONDITION:
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage	
ACCESSIBILITY:	Within Reach	DAMAGE REASON:
		DAMAGE REASON:
DAMAGE QUANTITY:		DAMAGE REASON:
		DAMAGE UNITS:
COMMENTS:		

Inspector's Signature:

Christopher Antonopoulos

Date: 08/12/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23361** BUILDING ID: **3580**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Grissom School** REVIEW DATE: **9/8/2022**
ADDRESS: **12810 Escanaba** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 09/08/2022

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N Penneff".

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:




37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Peneff". The signature is written in a cursive, somewhat stylized script.

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081


FORM # A-010B

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 18281	2/10/2022	05/15/2023

CHRISTOPHER J ANTONOPO
1736 W 102nd ST
CHICAGO, IL 60643

Environmental Health



ENDORSEMENT	TC EXPIRES
INSPECTOR	6/1/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

TODD T HUFFER
315 HATLEN COURT
MT. PROSPECT, IL 60056

2/18/2022


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

			ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 09870	ISSUED 2/18/2022	EXPIRES 05/15/2023			INSPECTOR	11/1/2022
TODD T HUFFER 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health					MANAGEMENT PLANNER	11/19/2022
					PROJECT MANAGER	10/20/2022
					AIR SAMPLING PROFESSIONAL	
					Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265


Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed