

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2239  
SCHOOL NAME: Hale School  
ADDRESS OF SCHOOL: 6140 S. Melvina  
CITY: Chicago, IL, 60638

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/16/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/1/2022 ENROLLMENT 783  
IDPH INSPECTOR LICENSE NUMBER: 100-11167  
IDPH LICENSED INSPECTOR NAME (Please Print): Brian Barry  
IDPH MP LICENSE NUMBER: 100-03613  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



9/15/2022

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Hale School**

6140 S. Melvina  
Chicago, IL, 60638

Unit: 23491  
Building ID: 3710

IDPH ID Number: 14-016-2990-2239

**REPORT DATE:**

Thursday, September 15, 2022

**Prepared for:**

**Chicago Public Schools  
42 W. Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

09/14/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 23491            Region: 05            IDPH ID: 14-016-2990-2239

School: Hale School            Building ID: 3710

Address: 6140 S. Melvina

Chicago, IL, 60638

Building Contact: Doyle, Robert

Contact Phone: 7737107548

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/1/2022

Review Date: 09/14/2022

Inspector: Brian Barry

Inspector IDPH License: 100-11167

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

A handwritten signature in black ink, appearing to read "Daniel Juneau", with a circular flourish at the end.

Daniel Juneau  
100-03613

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 15, 2022

RE: Hale School, Unit 23491  
6140 S. Melvina  
Chicago, IL, 60638

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Hale School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Hale School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Hale School Unit: 23491 Region: 05  
Address: 6140 S. Melvina Chicago, IL, 60638  
IDPH ID: 14-016-2990-2239 Building ID: 3710  
Contact: Doyle, Robert Phone: 7737107548

### 2. Description of Facility

Original Construction: 1953 Additional Construction: 2013  
Total Square Footage: 63323 No of Floors: 3  
Current Occupancy: 783

### 3. LEA Designated Person


Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880 Fax: 630-790-0882

### 5. Inspector

Inspector Name: Brian Barry



Signature:  
Date: 9/1/2022

Inspector IDPH license # 100-11167  
Reinspection Date: 9/1/2022

### 6. Management Planner

Management Planner Name: Daniel Juneau



Signature:  
Date: 09/14/2022

Management Planner IDPH license # 100-03613

### 7. Review Date: 09/14/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 9/15/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hale School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3710:

48	12x12 Beige w/Tan Streaks Floor Tile
48A	12x12 Beige w/Tan Streaks Floor Tile Mastic
49	12x12 Tan w/Brown Streaks Floor Tile
49A	12x12 Tan w/Brown Streaks Floor Tile Mastic
50	12x12 Grey Floor Tile
50A	12x12 Grey Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 3710:

48	12x12 Beige w/Tan Streaks Floor Tile
48A	12x12 Beige w/Tan Streaks Floor Tile Mastic
49	12x12 Tan w/Brown Streaks Floor Tile
49A	12x12 Tan w/Brown Streaks Floor Tile Mastic
50	12x12 Grey Floor Tile
50A	12x12 Grey Floor Tile Mastic



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

33A	12x12 Off-White Speckled Floor Tile Mastic
33E	12x12 Beige Floor Tile Mastic
35A	12x12 Off-White Speckled Floor Tile
35E	12x12 Beige Floor Tile
39A	Brown Mopboard
39B	Black Mopboard
40A	Brown Mopboard Mastic
40B	Black Mopboard Mastic
43	12x12 Vinyl Floor Tile Red w/Streaks
43A	12x12 Vinyl Floor Tile Red w/Streaks Mastic
44	12x12 Light Brown w/Streaks Floor Tile
44A	12x12 Light Brown w/Streaks Floor Tile Mastic
45	2'x2' Blue Carpet Squares Adhesive
46	12x12 Brown w/Streaks Floor Tile
46A	12x12 Brown w/Streaks Floor Tile Mastic
47	9x9 Bluish Green w/Black Specks Floor Tile
47A	9x9 Bluish Green w/Black Specks Floor Tile Mastic
48	12x12 Beige w/Tan Streaks Floor Tile
48A	12x12 Beige w/Tan Streaks Floor Tile Mastic
49	12x12 Tan w/Brown Streaks Floor Tile
49A	12x12 Tan w/Brown Streaks Floor Tile Mastic
50	12x12 Grey Floor Tile
50A	12x12 Grey Floor Tile Mastic
FT-1	12x12 White w/Grey Specks Floor Tile
FTM-1	12x12 White w/Grey Specks Floor Tile Mastic

The following areas were deemed to be inaccessible:

32A	9x9 Gray w/Black & White Floor Tile Mastic
33A	12x12 Off-White Speckled Floor Tile Mastic
33B	12x12 Gray w/Black & White Floor Tile Mastic
33C	12x12 Tan w/Brown and White Floor Tile Mastic
33E	12x12 Beige Floor Tile Mastic
34	12x12 Green w/Black Floor Tile Mastic
40A	Brown Mopboard Mastic
40B	Black Mopboard Mastic
43A	12x12 Vinyl Floor Tile Red w/Streaks Mastic
44A	12x12 Light Brown w/Streaks Floor Tile Mastic
45	2'x2' Blue Carpet Squares Adhesive
46A	12x12 Brown w/Streaks Floor Tile Mastic

FTM-1

12x12 White w/Grey Specks Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Brian Barry, IDPH License # 100-11167. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/16/2021

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Hale School Building 3710 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---



# Chicago Public Schools

School Hale School Unit 23491 Building ID 3710

Address 6140 S. Melvina Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				and at North End										
35E	12x12 Beige Floor Tile	130	SF	Patches in Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36A	9x9 Gray w/Black/White Floor Tile	515	SF	Rooms 202 & 204	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36B	9x9 Tan w/Brown and White Floor Tile NOT OBSERVED			Rooms 202 and 204	CHR	MISC		None						Low
36C	9x9 Tan Floor Tile	1,700	SF	Auditorium Aisles, Engineer's Office	CHR	MISC	N	DIST	50		No	ACBM with the potential for damage	5	LOW
37	12x12 Green w/Black Floor Tile	600	SF	Storeroom, Storage Closet, Janitor's Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39A	Brown Mopboard	450	LF	Room 202, 204, Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39B	Black Mopboard	1,200	LF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40A	Brown Mopboard Mastic	450	LF	Room 202 & 204, Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40B	Black Mopboard Mastic	1,200	LF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Window Glaze Throughout 1st & 2nd Floor Windows- Exterior Non AHERA			Throughout	CHR	MISC		None			No			Low
42	Fire Brick ABATED			Boiler Room	ABATED	MISC								
43	12x12 Vinyl Floor Tile Red w/Streaks	3,000	SF	1st and 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43A	12x12 Vinyl Floor Tile Red w/Streaks Mastic	3,000	SF	1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	12x12 Light Brown w/Streaks Floor Tile	1,500	SF	1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44A	12x12 Light Brown w/Streaks Floor Tile Mastic	1,500	SF	1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	2x2' Blue Carpet Squares Adhesive	600	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12x12 Brown w/Streaks Floor Tile	55	SF	Rooms 202 & 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46A	12x12 Brown w/Streaks Floor Tile Mastic	55	SF	Rooms 202 & 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	9x9 Bluish Green w/Black Specks Floor Tile	10	SF	Rooms 202 & 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47A	9x9 Bluish Green w/Black Specks Floor Tile Mastic	10	SF	Rooms 202 & 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12x12 Beige w/Tan Streaks Floor Tile	2,400	SF	Basement Lunchroom & Library	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Hale School Unit 23491 Building ID 3710

Address 6140 S. Melvina Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
48A	12x12 Beige w/Tan Streaks Floor Tile Mastic	2,400	SF	Basement Lunchroom & Library	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
49	12x12 Tan w/Brown Streaks Floor Tile	600	SF	Room 019	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
49A	12x12 Tan w/Brown Streaks Floor Tile Mastic	600	SF	Room 019	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
50	12x12 Grey Floor Tile	600	SF	Room 109	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
50A	12x12 Grey Floor Tile Mastic	600	SF	Room 109	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Aircell Pipe Covering	4,292	LF	Fan Room, Driving Room, Throughout Basement, Air Tunnels, Art Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
B	Aircell Pipe Joints	310	LF	Unfinished Pipe Space, Fan Room, Art Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
C	Felt Covering	2,580	LF	Fan Rooms, Unfinished Pipe Space, Gym	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	Felt Pipe Packing ABATED			Boiler Room	ABATED	TSI								
E	Fiberglass Pipe Packing ABATED			Boiler Room	ABATED	TSI								
F	Tank Insulation	180	SF	Boiler Room	AMO	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
FT-1	12x12 White w/Grey Specks Floor Tile	3,500	SF	Modular Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	12x12 White w/Grey Specks Floor Tile Mastic	3,500	SF	Modular Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G	Tank Packing ABATED			Boiler Room	ABATED	TSI								
H	Boiler Insulation ABATED			Boiler Room	ABATED	TSI								
I	Boiler Packing ABATED			Boiler Room	ABATED	TSI								
J	Mag Block Elbows ABATED			Boiler Room	ABATED	TSI								
K	Mag Pipe Insulation ABATED			Boiler Room	ABATED	TSI								
L	Trowel Applied Plaster Material	3,200	SF	Auditorium Ceiling	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
O	Boiler Gasket ABATED			Boiler Room	ABATED	TSI								
P	Mag Block Elbows ABATED			Assistant Principal's Washroom	ABATED	TSI		None						Low

# Chicago Public Schools

School Hale School Unit 23491 Building ID 3710

Address 6140 S. Melvina Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/1/2022</b>
Inspector Name <b>Brian Barry</b>
<b>100-11167</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
32A	
32B	Not Observed 2019 & 2022
32C	20 SF of Damage in Auditorium Aisles & 10 SF of Damage in the Engineer's Office
33A	
33B	
33C	
33D	
33E	
34	
35A	
35B	
35C	
35D	
35E	
36A	
36B	Not Observed 20109 & 2022
36C	45 SF of Damage in Auditorium Aisles & 10 SF of Damage in the Engineer's Office
37	
39A	
39B	
40A	
40B	
41	
42	



# Chicago Public Schools

School Hale School Unit 23491 Building ID 3710

Address 6140 S. Melvina Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
43	
43A	
44	
44A	
45	
46	
46A	
47	
47A	
48	
48A	
49	
49A	
50	
50A	
A	
B	
C	
D	
E	
F	
FT-1	
FTM-1	
G	
H	
I	
J	
K	
L	

# Chicago Public Schools

School Hale School Unit 23491 Building ID 3710

Address 6140 S. Melvina Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
O	
P	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Hale School  
**Address** 6140 S. Melvina

**Unit** 23491  
Chicago, IL, 60638

**Building ID** 3710  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32A	9x9 Gray w/Black & White Floor Tile Mastic	515	SF	Rooms 33C & 200	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32B	9x9 Tan w/Brown and White Floor Tile Mastic NOT OBSERVED			Rooms 202 & 204	Chrysotile	MISC					
32C	9x9 Tan Floor Tile Mastic	1,700	SF	Auditorium Aisles, Engineer's Office	Chrysotile	MISC	No	30	SF	6 ACBM with the potential for damage	Follow O&M Plan
33A	12x12 Off-White Speckled Floor Tile Mastic	3,500	SF	Lunchroom, Basement Classroom, Coat Check Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33B	12x12 Gray w/Black & White Floor Tile Mastic	10,300	SF	Main and Principal's Office, Rooms 200-213, 102-113	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33C	12x12 Tan w/Brown and White Floor Tile Mastic	12,000	SF	Library, 2nd Floor Teachers' Restroom, Rooms 019, 100, 102-106, 108, 110-113, 200, 201, 203, 205-213, Principal	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33D	12x12 Beige Speckled Floor Tile Mastic ABATED			1st Floor Corridor in front of Fountains and at North End	Abated	MISC					
33E	12x12 Beige Floor Tile Mastic	130	SF	Patches in Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12x12 Green w/Black Floor Tile Mastic	1,620	SF	Stockroom, Storage Closet, Janitor's Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35A	12x12 Off-White Speckled Floor Tile	3,500	SF	Basement Classroom, Auditorium Coat Check	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35B	12x12 Gray w/Black & White Floor Tile	10,300	SF	1st & 2nd Floor Corridors, Library, Main and Principal's Office, Rooms 200, 201, 203-213, 102-113	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35C	12x12 Tan w/Brown & White Floor Tile	12,000	SF	Library, 2nd Floor Teachers' Restroom, Rooms 100, 102-106, 108, 110-113, 200, 201, 203, 205-213, Principal	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35D	12x12 Beige Speckled Floor Tile ABATED			1st Floor Corridor in front of Fountains and at North End	Abated	MISC					
35E	12x12 Beige Floor Tile	130	SF	Patches in Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36A	9x9 Gray w/Black/White Floor Tile	515	SF	Rooms 202 & 204	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36B	9x9 Tan w/Brown and White Floor Tile NOT OBSERVED			Rooms 202 and 204	Chrysotile	MISC					
36C	9x9 Tan Floor Tile	1,700	SF	Auditorium Aisles, Engineer's Office	Chrysotile	MISC	No	50	SF	6 ACBM with the potential for damage	Repair
37	12x12 Green w/Black Floor Tile	600	SF	Storeroom, Storage Closet, Janitor's Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39A	Brown Mopboard	450	LF	Room 202, 204, Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
39B	Black Mopboard	1,200	LF	Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
40A	Brown Mopboard Mastic	450	LF	Room 202 & 204, Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Hale School  
**Address** 6140 S. Melvina

**Unit** 23491  
Chicago, IL, 60638

**Building ID** 3710  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
40B	Black Mopboard Mastic	1,200	LF	Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
41	Window Glaze Throughout 1st & 2nd Floor Windows- Exterior Non AHERA			Throughout	Chrysotile	MISC					
42	Fire Brick ABATED			Boiler Room	Abated	MISC					
43	12x12 Vinyl Floor Tile Red w/Streaks	3,000	SF	1st and 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43A	12x12 Vinyl Floor Tile Red w/Streaks Mastic	3,000	SF	1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12x12 Light Brown w/Streaks Floor Tile	1,500	SF	1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44A	12x12 Light Brown w/Streaks Floor Tile Mastic	1,500	SF	1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	2'x2' Blue Carpet Squares Adhesive	600	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12x12 Brown w/Streaks Floor Tile	55	SF	Rooms 202 & 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46A	12x12 Brown w/Streaks Floor Tile Mastic	55	SF	Rooms 202 & 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	9x9 Bluish Green w/Black Specks Floor Tile	10	SF	Rooms 202 & 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47A	9x9 Bluish Green w/Black Specks Floor Tile Mastic	10	SF	Rooms 202 & 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12x12 Beige w/Tan Streaks Floor Tile	2,400	SF	Basement Lunchroom & Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48A	12x12 Beige w/Tan Streaks Floor Tile Mastic	2,400	SF	Basement Lunchroom & Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12x12 Tan w/Brown Streaks Floor Tile	600	SF	Room 019	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49A	12x12 Tan w/Brown Streaks Floor Tile Mastic	600	SF	Room 019	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12x12 Grey Floor Tile	600	SF	Room 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50A	12x12 Grey Floor Tile Mastic	600	SF	Room 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Covering	4,292	LF	Fan Room, Driving Room, Throughout Basement, Air Tunnels, Art Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Aircell Pipe Joints	310	LF	Unfinished Pipe Space, Fan Room, Art Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
C	Felt Covering	2,580	LF	Fan Rooms, Unfinished Pipe Space, Gym	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	Felt Pipe Packing ABATED			Boiler Room	Abated	TSI					
E	Fiberglass Pipe Packing ABATED			Boiler Room	Abated	TSI					
F	Tank Insulation	180	SF	Boiler Room	Amosite	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-1	12x12 White w/Grey Specks Floor Tile	3,500	SF	Modular Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 White w/Grey Specks Floor Tile Mastic	3,500	SF	Modular Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Tank Packing ABATED			Boiler Room	Abated	TSI					
H	Boiler Insulation ABATED			Boiler Room	Abated	TSI					
I	Boiler Packing ABATED			Boiler Room	Abated	TSI					
J	Mag Block Elbows ABATED			Boiler Room	Abated	TSI					
K	Mag Pipe Insulation ABATED			Boiler Room	Abated	TSI					

# Chicago Public Schools

**School** Hale School  
**Address** 6140 S. Melvina

**Unit** 23491  
 Chicago, IL, 60638

**Building ID** 3710  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
L	Trowel Applied Plaster Material	3,200	SF	Auditorium Ceiling	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
O	Boiler Gasket ABATED			Boiler Room	Abated	TSI					
P	Mag Block Elbows ABATED			Assistant Principal's Washroom	Abated	TSI					

Review Date	9/14/2022
Manager Planner Name	Daniel Juneau

HA Number	Management Comments
32A	

# Chicago Public Schools

**School** Hale School  
**Address** 6140 S. Melvina

**Unit** 23491  
 Chicago, IL, 60638

**Building ID** 3710  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

100-03613	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
32B	
32C	Replace Damaged Tiles
33A	
33B	
33C	
33D	
33E	
34	
35A	
35B	
35C	
35D	
35E	
36A	
36B	
36C	Repair or removed as needed per conditions
37	
39A	
39B	
40A	
40B	
41	
42	
43	
43A	
44	
44A	

# Chicago Public Schools

**School** Hale School  
**Address** 6140 S. Melvina

**Unit** 23491  
 Chicago, IL, 60638

**Building ID** 3710  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
45	
46	
46A	
47	
47A	
48	
48A	
49	
49A	
50	
50A	
A	
B	
C	
D	
E	
F	
FT-1	
FTM-1	
G	
H	
I	
J	
K	
L	
O	
P	



# Chicago Public Schools

**School** Hale School  
**Address** 6140 S. Melvina

**Unit** 23491  
Chicago, IL, 60638

**Building ID** 3710  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

***Management Planner's Comments Summarized at the End of the Report***

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32A**  
MATERIAL DESCRIPTION: **9x9 Gray w/Black & White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 33C & 200**

MATERIAL QUANTITY: **515**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **32A**  
MATERIAL DESCRIPTION: **9x9 Gray w/Black & White Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 33C & 200**  
MATERIAL QUANTITY: **515** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32B**  
MATERIAL DESCRIPTION: **9x9 Tan w/Brown and White Floor Tile Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 202 & 204**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **32B**  
MATERIAL DESCRIPTION: **9x9 Tan w/Brown and White Floor Tile Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32C**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium Aisles, Engineer's Office**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1700** DAMAGE UNITS: **SF**  
COMMENTS: **20 SF of Damage in Auditorium Aisles & 10 SF of Damage in the Engineer's Office**

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **32C**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Auditorium Aisles, Engineer's Office**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Replace Damaged Tiles

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33A**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom, Basement Classroom, Coat Check Room**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **33A**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom, Basement Classroom, Coat Check Room**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33B**  
MATERIAL DESCRIPTION: **12x12 Gray w/Black & White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main and Principal's Office, Rooms 200-213, 102-113**  
MATERIAL QUANTITY: **10300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **33B**  
MATERIAL DESCRIPTION: **12x12 Gray w/Black & White Floor Tile Mastic**  
MATERIAL LOCATION: **Main and Principal's Office, Rooms 200-213, 102-113**  
MATERIAL QUANTITY: **10300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33C**  
MATERIAL DESCRIPTION: **12x12 Tan w/Brown and White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, 2nd Floor Teachers' Restroom, Rooms 019, 100, 102-106, 108, 110-113, 200, 201, 203, 205-213, Principal**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **33C**  
MATERIAL DESCRIPTION: **12x12 Tan w/Brown and White Floor Tile Mastic**  
MATERIAL LOCATION: **Library, 2nd Floor Teachers' Restroom, Rooms 019, 100, 102-106, 108, 110-113, 200, 201, 203, 205-213, Principal**  
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33D**  
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor Corridor in front of Fountains and at North End**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **33D**  
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1st Floor Corridor in front of Fountains and at North End**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33E**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Patches in Auditorum**  
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **33E**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Patches in Auditorum**  
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23491**    BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School**    INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina**    IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12x12 Green w/Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stockroom, Storage Closet, Janitor's Room**  
MATERIAL QUANTITY: **1620**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12x12 Green w/Black Floor Tile Mastic**  
MATERIAL LOCATION: **Stockroom, Storage Closet, Janitor's Room**  
MATERIAL QUANTITY: **1620** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35A**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Classroom, Auditorium Coat Check**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **35A**  
MATERIAL DESCRIPTION: **12x12 Off-White Speckled Floor Tile**  
MATERIAL LOCATION: **Basement Classroom, Auditorium Coat Check**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35B**  
MATERIAL DESCRIPTION: **12x12 Gray w/Black & White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Library, Main and Principal's Office, Rooms 200, 201, 203-213, 102-113**

MATERIAL QUANTITY: **10300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **35B**  
MATERIAL DESCRIPTION: **12x12 Gray w/Black & White Floor Tile**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Library, Main and Principal's Office, Rooms 200, 201, 203-213, 102-113**  
MATERIAL QUANTITY: **10300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35C**  
MATERIAL DESCRIPTION: **12x12 Tan w/Brown & White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, 2nd Floor Teachers' Restroom, Rooms 100, 102-106, 108, 110-113, 200, 201, 203, 205-213, Principal**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **35C**  
MATERIAL DESCRIPTION: **12x12 Tan w/Brown & White Floor Tile**  
MATERIAL LOCATION: **Library, 2nd Floor Teachers' Restroom, Rooms 100, 102-106, 108, 110-113, 200, 201, 203, 205-213, Principal**  
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23491 BUIDLING ID: 3710  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Brian Barry  
SCHOOL NAME: Hale School INSPECTION DATE: 9/1/2022  
ADDRESS: 6140 S. Melvina IDPH LICENSE NO: 100-11167

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35D  
MATERIAL DESCRIPTION: 12x12 Beige Speckled Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Corridor in front of Fountains and at North End

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/01/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **35D**  
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile ABATED**  
MATERIAL LOCATION: **1st Floor Corridor in front of Fountains and at North End**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35E**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Patches in Auditorium**  
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **35E**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **Patches in Auditorium**  
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36A**  
MATERIAL DESCRIPTION: **9x9 Gray w/Black/White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **515** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **36A**  
MATERIAL DESCRIPTION: **9x9 Gray w/Black/White Floor Tile**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **515** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36B**  
MATERIAL DESCRIPTION: **9x9 Tan w/Brown and White Floor Tile NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 202 and 204**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 20109 & 2022**

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **36B**  
MATERIAL DESCRIPTION: **9x9 Tan w/Brown and White Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 202 and 204**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36C**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium Aisles, Engineer's Office**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1700** DAMAGE UNITS: **SF**  
COMMENTS: **45 SF of Damage in Auditorium Aisles & 10 SF of Damage in the Engineer's Office**

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **36C**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**  
MATERIAL LOCATION: **Auditorium Aisles, Engineer's Office**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair or removed as needed per conditions

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Green w/Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Storeroom, Storage Closet, Janitor's Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Green w/Black Floor Tile**  
MATERIAL LOCATION: **Storeroom, Storage Closet, Janitor's Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39A**  
MATERIAL DESCRIPTION: **Brown Mopboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 202, 204, Lunchroom**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **39A**  
MATERIAL DESCRIPTION: **Brown Mopboard**  
MATERIAL LOCATION: **Room 202, 204, Lunchroom**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39B**  
MATERIAL DESCRIPTION: **Black Mopboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **39B**  
MATERIAL DESCRIPTION: **Black Mopboard**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40A**  
MATERIAL DESCRIPTION: **Brown Mopboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 202 & 204, Lunchroom**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **40A**  
MATERIAL DESCRIPTION: **Brown Mopboard Mastic**  
MATERIAL LOCATION: **Room 202 & 204, Lunchroom**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40B**  
MATERIAL DESCRIPTION: **Black Mopboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **40B**  
MATERIAL DESCRIPTION: **Black Mopboard Mastic**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Window Glaze Throughout 1st & 2nd Floor Windows- Exterior Non AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Window Glaze Throughout 1st & 2nd Floor Windows- Exterior Non AHERA**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Fire Brick ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Fire Brick ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile Red w/Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile Red w/Streaks**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile Red w/Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile Red w/Streaks Mastic**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Streaks Floor Tile**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44A**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **44A**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **2'x2' Blue Carpet Squares Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **2'x2' Blue Carpet Squares Adhesive**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **55** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **55** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46A**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **55** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **46A**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **55** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9x9 Bluish Green w/Black Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9x9 Bluish Green w/Black Specks Floor Tile**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **9x9 Bluish Green w/Black Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **9x9 Bluish Green w/Black Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 202 & 204**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Covering**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Fan Room, Driving Room, Throughout Basement, Air Tunnels, Art Room**  
MATERIAL QUANTITY: **4292** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Covering**  
MATERIAL LOCATION: **Fan Room, Driving Room, Throughout Basement, Air Tunnels, Art Room**  
MATERIAL QUANTITY: **4292** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Aircell Pipe Joints**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unfinished Pipe Space, Fan Room, Art Room**  
MATERIAL QUANTITY: **310** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Aircell Pipe Joints**  
MATERIAL LOCATION: **Unfinished Pipe Space, Fan Room, Art Room**  
MATERIAL QUANTITY: **310** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Felt Covering**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Fan Rooms, Unfinished Pipe Space, Gym**  
MATERIAL QUANTITY: **2580** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Felt Covering**  
MATERIAL LOCATION: **Fan Rooms, Unfinished Pipe Space, Gym**  
MATERIAL QUANTITY: **2580** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Felt Pipe Packing ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Felt Pipe Packing ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Fiberglass Pipe Packing ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Fiberglass Pipe Packing ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 White w/Grey Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular Classrooms**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 White w/Grey Specks Floor Tile**  
MATERIAL LOCATION: **Modular Classrooms**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 White w/Grey Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular Classrooms**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 White w/Grey Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Modular Classrooms**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Tank Packing ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Tank Packing ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Boiler Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Boiler Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Boiler Packing ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Boiler Packing ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Mag Block Elbows ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Mag Block Elbows ABATED**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Mag Pipe Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Mag Pipe Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Trowel Applied Plaster Material**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium Ceiling**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

---



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Trowel Applied Plaster Material**  
MATERIAL LOCATION: **Auditorium Ceiling**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Boiler Gasket ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **O**  
MATERIAL DESCRIPTION: **Boiler Gasket ABATED**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Mag Block Elbows ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Assistant Principal's Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUIDLING ID: **3710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School** REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Mag Block Elbows ABATED**

MATERIAL LOCATION: **Assistant Principal's Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23491** BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School** INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 09/01/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23491**      BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School**      REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina**      IDPH LICENSE NO: **100-11167**

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **09/14/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23491**    BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School**    INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina**    IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile**  
MATERIAL LOCATION: **Basement Lunchroom & Library**  
MATERIAL QUANTITY: **2400**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23491**      BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School**      REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina**      IDPH LICENSE NO: **100-11167**

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile**  
MATERIAL LOCATION: **Basement Lunchroom & Library**  
MATERIAL QUANTITY: **2400**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 09/14/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23491**    BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School**    INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina**    IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 019**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23491**      BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School**      REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina**      IDPH LICENSE NO: **100-11167**

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 019**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  \_\_\_\_\_ Date: **09/14/2022** \_\_\_\_\_

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23491**    BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School**    INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina**    IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **50A**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23491**      BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School**      REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina**      IDPH LICENSE NO: **100-11167**

HOMOGENEOUS AREA: **50A**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 09/14/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23491**    BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School**    INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina**    IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Basement Lunchroom & Library**  
MATERIAL QUANTITY: **2400**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **09/01/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23491**      BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School**      REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina**      IDPH LICENSE NO: **100-11167**

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Basement Lunchroom & Library**  
MATERIAL QUANTITY: **2400**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  \_\_\_\_\_ Date: **09/14/2022** \_\_\_\_\_

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23491**    BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Hale School**    INSPECTION DATE: **9/1/2022**  
ADDRESS: **6140 S. Melvina**    IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Room 019**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **09/01/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23491**      BUILDING ID: **3710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Hale School**      REVIEW DATE: **9/14/2022**  
ADDRESS: **6140 S. Melvina**      IDPH LICENSE NO: **100-11167**

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Room 019**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 09/14/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---



**ASBESTOS  
 PROFESSIONAL  
 LICENSE**

ID NUMBER      ISSUED      EXPIRES  
**100 - 11167**      **3/1/2022**      **05/15/2023**

**BRIAN J BARRY**  
 174 N BRANDON DR  
 GLENDALE HEIGHTS, IL 60139  
 Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR	12/17/2022
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/16/2022

**Alteration of this license shall result in legal action**  
 This license issued under authority of the State of Illinois  
 Department of Public Health  
 This license is valid only when accompanied by a valid  
 training course certificate.



**EarthTech, Inc.**

435 Shadow Wood Drive, Yorkville, IL 60560

## Asbestos Building Inspector Refresher

THIS CERTIFIES THAT

**Brian Barry**

Has successfully completed the IL and IN Approved Asbestos Training Course and passed the Examination for purposes of accreditation under section 206 of Title II, 15 USC 2646 of the Toxic Substances Control Act (TSCA) and 326 IAC 18-2. Conducted by EarthTech, Inc  
630-417-6951

CLASS DATES: 12/16/2022

EXAMINATION: 12/16/2022

LOCATION: Amerisafe

EXPIRATION: 12/16/2023

CERTIFICATE NUMBER: 110175X19S103884

A handwritten signature in blue ink, appearing to read 'R. Barry', is written over a horizontal line.



**EarthTech, Inc.**

435 Shadow Wood Drive, Yorkville, IL 60560

## Asbestos Building Inspector Refresher

THIS CERTIFIES THAT

**Brian Barry**

Has successfully completed the IL and IN Approved Asbestos Training Course and passed the Examination for purposes of accreditation under section 206 of Title II, 15 USC 2646 of the Toxic Substances Control Act (TSCA) and 326 IAC 18-2. Conducted by EarthTech, Inc  
630-417-6951

CLASS DATES: 12/17/2021


EXAMINATION: 12/17/2021

LOCATION: Amerisafe

EXPIRATION: 12/17/2022

A handwritten signature in blue ink, appearing to read 'Brian Barry', written over a horizontal line.


CERTIFICATE NUMBER: 109937X19S103884



**ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 03613	3/1/2022	05/15/2023

DANIEL J JUNEAU  
 1408 OAKWOOD AVENUE  
 DES PLAINES, IL 60016  
 Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/19/2022
MANAGEMENT PLANNER	11/19/2022
PROJECT MANAGER	11/1/2022
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
 This license issued under authority of the State of Illinois  
 Department of Public Health  
 This license is valid only when accompanied by a valid  
 training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

Kathy DeSalvo, Director





OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed