

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2254
SCHOOL NAME: Healy School
ADDRESS OF SCHOOL: 3010 S. Parnell
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **6/17/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 8/9/2022 ENROLLMENT 1219
IDPH INSPECTOR LICENSE NUMBER: 100-20411
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): _____ PHONE: _____

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Healy School

3010 S. Parnell
Chicago, IL, 60616

Unit: 23651
Building ID: 3880

IDPH ID Number: 14-016-2990-2254

REPORT DATE:

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23651 Region: 04 IDPH ID: 14-016-2990-2254

School: Healy School Building ID: 3880

Address: 3010 S. Parnell

Chicago, IL, 60616

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/9/2022

Review Date:

Inspector: Benyamen Maradkel

Inspector IDPH License: 100-20411

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date:

RE: Healy School, Unit 23651
3010 S. Parnell
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Healy School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Healy School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact , the designated Local Education Authority's Designated Person at .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Healy School
Address: 3010 S. Parnell
IDPH ID: 14-016-2990-2254
Contact:

Unit: 23651
Chicago, IL, 60616
Building ID: 3880
Phone:

Region: 04

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 1219

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact:
Address: 42 West Madison Street
Chicago, IL 60602

Phone:

4. Managing Environmental Consultant


MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Benyamen Maradkel


Inspector IDPH license # 100-20411
Reinspection Date: 8/9/2022


Signature:
Date: 8/9/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature:
Date:

7. Review Date:

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Name:

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Healy School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3880:

81	Vibration damper
82	Duct cornering
83	12" x 12" Dark Blue Vinyl Floor Tile
84	12" x 12" Dark Blue Vinyl Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 3880:

1	12" x 12" Brown Vinyl Floor Tile w/Brown & White Streaks
4	9" x 9" Tan Floor Tile w/White & Brown Streaks
48	Transite ceiling panels
63	12" x 12" White w/Gray Floor Tile
64	12" x 12" White w/Gray Floor Tile Mastic
83	12" x 12" Dark Blue Vinyl Floor Tile
84	12" x 12" Dark Blue Vinyl Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

035	Mastic associated with carpeting
036	Brown mop board
036 A	Brown mop board mastic
037	Black mop board
037 A	Black mop board mastic
038	Exterior window caulk - non ahera
039	Exterior expansion joint - non ahera
040	Dark brown exterior brick - Non-AHERA
041	Brown exterior brick - Non-AHERA
042	Tan exterior brick - Non-AHERA
043	Cream Brick w/Black Speckles - Non-AHERA
044	Brick mortar - Non-AHERA
045	Chimney flashing - Non-AHERA
046	Exterior window glaze - Non-AHERA
049	12" x 12" White w/Gray Specks Floor Tile
050	12" x 12" White w/Gray Specks Floor Tile Mastic
051	12" x 12" Burnt Orange Floor Tile
052	12" x 12" Burnt Orange Floor Tile Mastic
053	Dark gray carpet adhesive
054	12" x 12" Blue Floor Tile
055	12" x 12" Blue Floor Tile Mastic
056	12" x 12" Yellow Floor Tile
057	12" x 12" Yellow Floor Tile Mastic
059	12" x 12" Gray Mablign Mix Floor Tile
060	12" x 12" Gray Mablign Mix Floor Tile Mastic
061	12" x 12" Peach Floor Tile
062	12" x 12" Peach Floor Tile Mastic
063	12"x12" White w/Gray Floor Tile
064	12"x12" White w/Gray Floor Tile Mastic
065	12" x 12" Gray w/Gray Speckles Floor Tile
066	12" x 12" Gray w/Gray Speckles Floor Tile Mastic
067	12" x 12" Brown w/White Floor Tile
068	12" x 12" Brown w/White Floor Tile Mastic
069	Gray baseboard
070	Gray baseboard adhesive
071	Brown baseboard
072	Brown baseboard adhesive
073	9" x 9" White w/Brown Floor Tile
074	9" x 9" White w/Brown Floor Tile Mastic
58	Insulation inside of Vault Door
63	12" x 12" White w/Gray Floor Tile
64	12" x 12" White w/Gray Floor Tile Mastic

75	12" x 12" Light Brown Vinyl Floor Tile
76	12" x 12" Light Brown Vinyl Floor Tile Mastic
77	12" x 12" White w/Multicolored Speckle Vinyl Floor Tile
78	12" x 12" White w/Multicolored Speckle Vinyl Floor Tile Mastic
79	12" x 12" White w/Blue Speckles Vinyl Floor Tile
80	12" x 12" White w/Blue Speckles Vinyl Floor Tile Mastic
81	Vibration damper
82	Duct cornering
83	12" x 12" Dark Blue Vinyl Floor Tile
84	12" x 12" Dark Blue Vinyl Floor Tile Mastic

The following areas were deemed to be inaccessible:

001 A	12" x 12" Brown Vinyl Floor Tile w/Brown & White Streaks Mastic
002 A	9" x 9" Gray Floor Tile w/ White Streaks Mastic
003 A	9" x 9" Beige Floor Tile w/White & Blue Streaks Mastic
004 A	9" x 9" Tan Floor Tile w/White & Brown Streaks Mastic
006A	12" x 12" Light Brown Vinyl Floor Tile w/Dark Brown & Whitet. Marble mastic
007 A	12" x 12" Cream Vinyl Floor Tile w/Tan & Brown Marbling Mastic
008 A	9" x 9" White Vinyl Floor Tile w/Black & Gray Streaks Mastic
009 A	9" x 9" Red Floor Tile w/White Streaks Mastic
010 A	12" x 12" White Vinyl Floor Tile w/Black & Gray Streaks Mastic
012 A	9" x 9" Cream Floor Tile w/Red & Black Streaks Mastic
036 A	Brown mop board mastic
037 A	Black mop board mastic
050	12" x 12" White w/Gray Specks Floor Tile Mastic
052	12" x 12" Burnt Orange Floor Tile Mastic
053	Dark gray carpet adhesive
055	12" x 12" Blue Floor Tile Mastic
057	12" x 12" Yellow Floor Tile Mastic
060	12" x 12" Gray Mablign Mix Floor Tile Mastic
062	12" x 12" Peach Floor Tile Mastic
064	12"x12" White w/Gray Floor Tile Mastic
066	12" x 12" Gray w/Gray Speckles Floor Tile Mastic
068	12" x 12" Brown w/White Floor Tile Mastic

070	Gray baseboard adhesive
072	Brown baseboard adhesive
074	9" x 9" White w/Brown Floor Tile Mastic
64	12" x 12" White w/Gray Floor Tile Mastic
76	12" x 12" Light Brown Vinyl Floor Tile Mastic
78	12" x 12" White w/Multicolored Speckle Vinyl Floor Tile Mastic
80	12" x 12" White w/Blue Speckles Vinyl Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Healy School Building 3880 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	12"x12" Brown VFT w/Brown & White Streaks	1,475	SF	Engineer's Office, Room 101,209B	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
001 A	12" x 12" Brown Vinyl Floor Tile w/Brown & White Streaks Mastic	2,000	SF	Engineer's Office, Room 101,209B, 211A, Women's 2nd Floor Staff restroom, auditorium	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
002	9" x 9" Gray Floor Tile w/ White Streaks	445	SF	Room 103, Engineer's Corridor, 1st & 2nd Flr Teacher's Bathrooms, 1st Floor Men's Room & Computer Room	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
002 A	9" x 9" Gray Floor Tile w/ White Streaks Mastic	445	SF	Room 103, Engineer's Corridor, 1st & 2nd Flr Teacher's Bathrooms, 1st Floor Men's Room & Computer Room	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
003	9" x 9" Beige Floor Tile w/White & Blue Streaks	200	SF	Security Office	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
003 A	9" x 9" Beige Floor Tile w/White & Blue Streaks Mastic	200	SF	Security Office	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
004	9"x9" Tan Floor Tile w/White & Brown Streaks	8,000	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
004 A	9" x 9" Tan Floor Tile w/White & Brown Streaks Mastic	8,400	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off., 214	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
005	9"x9" Green Floor Tile w/White & Black Streaks			1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall	CHR	MISC								
005 A	9"x9" Green Floor Tile w/White & Blk Streaks Mastic			1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall	CHR	MISC								
006	12" x 12" Light Brown Vinyl Floor Tile w/ Dark Brown & White Marbling	3,300	SF	Kitchen and Rooms 101, 204, and 218	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
006A	12" x 12" Light Brown Vinyl Floor Tile w/Dark Brown & Whitet. Marble mastic	4,100	SF	Kitchen and Rooms 101,204, and 218	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
007	12" x 12" Cream Floor Tile w/Tan & Brown Marbling	4,100	SF	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
007 A	12" x 12" Cream Vinyl Floor Tile w/Tan & Brown Marbling Mastic	4,100	SF	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
008	9" x 9" White Floor Tile w/Black & Gray Streaks	2,500	SF	North Gym	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
008 A	9" x 9" White Vinyl Floor Tile w/Black & Gray Streaks Mastic	2,500	SF	North Gym	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
009	9" x 9" Red Floor Tile w/White Streaks	200	SF	North & South Gym Storage Areas and South Gym Office	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
009 A	9" x 9" Red Floor Tile w/White Streaks Mastic	200	SF	North & South Gym Storage Areas and South Gym Office	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
010	12" x 12" White Vinyl Floor Tile w/Black & Gray Streaks	2,500	SF	South Gym	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
010 A	12" x 12" White Vinyl Floor Tile w/Black & Gray Streaks Mastic	2,500	SF	South Gym	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
011	9" x 9" Blue Vinyl Floor Tile w/White & Black Streaks			Auditorium	CHR	MISC								
011 A	9" x 9" Blue Vinyl Floor Tile w/White & Black Streaks Mastic			Auditorium	CHR	MISC								
012	9" x 9" Cream Floor Tile w/Red & Black Streaks	4,150	SF	Rooms 103, 105, 106, 209A	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
012 A	9" x 9" Cream Floor Tile w/Red & Black Streaks Mastic	4,150	SF	Rooms 103, 105, 106, 209A	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
035	Mastic associated with carpeting			Engineer's Office, Main Office, Teachers Lounge, & Various areas Throughout	ASSUMED	MISC								
036	Brown mop board	100	SF	Throughout Building, Rooms 001, 003, 005, 116 & 208	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
036 A	Brown mop board mastic	100	SF	Throughout	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the		LOW

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building, Rooms 001, 003, 005, 116 & 208								potential for damage		
037	Black mop board	100	SF	Rooms 007 through 102 Auditorium & Room 100	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
037 A	Black mop board mastic	100	SF	Rooms 007 through 102 Auditorium & Room 100	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
038	Exterior window caulk - non ahera			Exterior of Building	ASSUMED	MISC								
039	Exterior expansion joint - non ahera			Exterior of Building	ASSUMED	MISC								
040	Dark brown exterior brick - Non-AHERA			Exterior of Building	ASSUMED	MISC								
041	Brown exterior brick - Non-AHERA			Exterior of Building	ASSUMED	MISC								
042	Tan exterior brick - Non-AHERA			Exterior of Building	ASSUMED	MISC								
043	Cream Brick w/Black Speckles - Non-AHERA			Exterior of Building	ASSUMED	MISC								
044	Brick mortar - Non-AHERA			Exterior of Building	ASSUMED	MISC								
045	Chimney flashing - Non-AHERA			Exterior of Building	ASSUMED	MISC								
046	Exterior window glaze - Non-AHERA			Exterior of Building	ASSUMED	MISC								
047	Plaster	3,000	SF	Gym and Auditorium	CHR	SURFACE	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
048	Transite Ceiling Panels			North Doors, West Doors by Main Office, Engineer's Corridor Door	CHR	MISC								
049	12" x 12" White w/Gray Specks Floor Tile	3,150	SF	Teacher's Lounge, Lunchroom, Rooms 207,210,213,107A, 107B, 204, 214, 218	ASSUMED	MISC	N	DIST	20	SF	No	ACBM with the potential for damage	5	LOW
050	12" x 12" White w/Gray Specks Floor Tile Mastic	3,150	SF	Teacher's Lounge, Lunchroom, Rooms 207,210,213,107A, 107B, 204, 214, 218	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
051	12" x 12" Burnt Orange Floor Tile	900	SF	North & South 2nd flr Stairwell, custodian closet 1st floor	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
052	12" x 12" Burnt Orange Floor Tile Mastic	900	SF	North & South 2nd flr Stairwell, custodian closet 1st floor	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
053	Dark gray carpet adhesive	120	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
054	12" x 12" Blue Floor Tile	5,400	SF	109 A and 1st Floor Hallway	ASSUMED	MISC	N	LOC	20	SF	No	ACBM with the potential for damage	5	LOW
055	12" x 12" Blue Floor Tile Mastic	5,400	SF	109 A and 1st Floor Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
056	12" x 12" Yellow Floor Tile	5,000	SF	2nd Floor Hallway and Janitor's Utility Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
057	12" x 12" Yellow Floor Tile Mastic	5,000	SF	2nd Floor Hallway and Janitor's Utility Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
059	12" x 12" Gray Marble Mix Floor Tile	1,150	SF	Room 107 (Library)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
060	12" x 12" Gray Marble Mix Floor Tile Mastic	1,150	SF	Room 107 (Library)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
061	12" x 12" Peach Floor Tile	300	SF	As Patches in Rooms 101, 103, 105 Bathroom, 110 & 112	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
062	12" x 12" Peach Floor Tile Mastic	300	SF	As Patches in Rooms 101, 103, 105 Bathroom, 110 & 112	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
063	12"x12" White w/Gray Floor Tile	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A, 107B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
064	12"x12" White w/Gray Floor Tile Mastic	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A, 107B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
065	12" x 12" Gray w/Gray Speckles Floor Tile	1,100	SF	First Floor Men's Room, Bathroom and Room 211	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
066	12" x 12" Gray w/Gray Speckles Floor Tile Mastic	1,100	SF	First Floor Men's Room, Bathroom and Room 211	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
067	12" x 12" Brown w/White Floor Tile	270	SF	Family Room and Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
068	12" x 12" Brown w/White Floor Tile Mastic	270	SF	Family Room and Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
069	Gray baseboard	1,500	LF	First Floor Hall and Main Office	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
070	Gray baseboard adhesive	1,500	LF	First Floor Hall and Main Office	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
071	Brown baseboard	6,500	LF	First & Second Floor Classrooms and Second Floor Hall	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
072	Brown baseboard adhesive	6,500	LF	First & Second Floor Classrooms and Second Floor Hall	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
073	9" x 9" White w/Brown Floor Tile	8	SF	Room 203 (Patch)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
074	9" x 9" White w/Brown Floor Tile Mastic	8	SF	Room 203 (Patch)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
1	12" x 12" Brown Vinyl Floor Tile w/Brown & White Streaks	2,000	SF	Engineer's Office, Room 101,209B, 211A, Women's 2nd Floor Staff restroom, auditorium	CHR	MISC	N	DIST	5	SF	No	ACBM with the potential for damage	5	LOW
4	9" x 9" Tan Floor Tile w/White & Brown Streaks	8,400	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off., 214	CHR	MISC	N	DIST	62	SF	No	ACBM with the potential for damage	5	LOW
48	Transite ceiling panels			North Doors, West Doors by Main Office, Engineer's Corridor Door, throughout facility	CHR	MISC								
58	Insulation inside of Vault Door			Main Office	ASSUMED	TSI								
63	12" x 12" White w/Gray Floor Tile	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	ASSUMED	MISC	N	DIST	37	SF	No	ACBM with the potential for damage	5	LOW
64	12" x 12" White w/Gray Floor Tile Mastic	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
75	12" x 12" Light Brown Vinyl Floor Tile	7,300	SF	Room 200,201,202,206,208,214,216,217	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
76	12" x 12" Light Brown Vinyl Floor Tile Mastic	7,300	SF	Room 200,201,202,206,208,214,216, 217	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
77	12" x 12" White w/Multicolored Speckle Vinyl Floor Tile	500	SF	Auditorium Rows	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/9/2022
Inspector Name <u>Benyamen Maradkel</u>
100-20411 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	
001 A	Not observed in Engineer's office 2022
002	
002 A	
003	
003 A	
004	
004 A	Not observed in Rms 210, 215, 218, 102, kitchen and Engineer's Office, could be under 12" floor tile, 207, 213, 205 abated - 2022
005	Not observed 2022
005 A	Not observed 2022
006	Not observed in Kitchen, Rm 204
006A	Not observed in Kitchen, Rm 204 2022
007	
007 A	
008	
008 A	
009	
009 A	
010	
010 A	
011	Not observed 2022
011 A	Not observed 2022
012	

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
012 A	
035	Not observed carpet in engineer 2022
036	
036 A	
037	
037 A	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	Damage in Rm 210, 107
050	
051	
052	Most removed
053	
054	Not observed in Rm 109A, some damage in hallway - 2022
055	Not observed in Rm 109A
056	
057	
059	
060	
061	

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	
073	
074	
1	Damage in east exit behind auditorium stage and not observed in Engineer's office - 2022
4	Damaged in room 111, 104, not observed in Rms 210, 215, 218, 206, 204, 202, 201, 208, 200, 102, kitchen and Engineer's Office, could be under 12" floor tile, 207, 213, 205 - 2022 - 2022
48	Not Observed 2022
58	Not observed 2022
63	Damage in 210, 107A
64	
75	Not observed in Rm 214
76	Not observed in Rm 214
77	Aisles still have tiles - Not observed in Rows of Seats
78	Aisles still have tiles - Not observed in Rows of Seats
79	
80	
81	

Chicago Public Schools

School Healy School Unit 23651 Building ID 3880

Address 3010 S. Parnell Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
82	
83	
84	
H	Abated 2021 all new non-asbestos
I	Not observed 2022

Table II

Management Planner's Review

Chicago Public Schools

School Healy School

Unit 23651

Building ID 3880

Address 3010 S. Parnell

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	12"x12" Brown VFT w/Brown & White Streaks	1,475	SF	Engineer's Office, Room 101,209B	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
001 A	12" x 12" Brown Vinyl Floor Tile w/Brown & White Streaks Mastic	2,000	SF	Engineer's Office, Room 101,209B, 211A, Women's 2nd Floor Staff restroom, auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
002	9" x 9" Gray Filor Tile w/ White Streaks	445	SF	Room 103, Engineer's Corridor, 1st & 2nd Flr Teacher's Bathrooms, 1st Floor Men's Room & Computer Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
002 A	9" x 9" Gray Filor Tile w/ White Streaks Mastic	445	SF	Room 103, Engineer's Corridor, 1st & 2nd Flr Teacher's Bathrooms, 1st Floor Men's Room & Computer Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003	9" x 9" Beige Floor Tile w/White & Blue Streaks	200	SF	Security Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003 A	9" x 9" Beige Floor Tile w/White & Blue Streaks Mastic	200	SF	Security Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
004	9"x9" Tan Floor Tile w/White & Brown Streaks	8,000	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
004 A	9" x 9" Tan Floor Tile w/White & Brown Streaks Mastic	8,400	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off., 214	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
005	9"x9" Green Floor Tile w/White & Black Streaks			1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall	Chrysotile	MISC					Follow O&M Plan
005 A	9"x9" Green Floor Tile w/White & Blk Streaks Mastic			1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall	Chrysotile	MISC					Follow O&M Plan
006	12" x 12" Light Brown Vinyl Floor Tile w/ Dark Brown & White Marbling	3,300	SF	Kitchen and Rooms 101, 204, and 218	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006A	12" x 12" Light Brown Vinyl Floor Tile w/Dark Brown & Whitet. Marble mastic	4,100	SF	Kitchen and Rooms 101,204, and 218	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007	12" x 12" Cream Floor Tile w/Tan & Brown Marbling	4,100	SF	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007 A	12" x 12" Cream Vinyl Floor Tile w/Tan & Brown Marbling Mastic	4,100	SF	Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008	9" x 9" White Floor Tile w/Black & Gray Streaks	2,500	SF	North Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008 A	9" x 9" White Vinyl Floor Tile w/Black & Gray Streaks Mastic	2,500	SF	North Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Healy School
Address 3010 S. Parnell

Unit 23651
Chicago, IL, 60616

Building ID 3880
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
009	9" x 9" Red Floor Tile w/White Streaks	200	SF	North & South Gym Storage Areas and South Gym Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
009 A	9" x 9" Red Floor Tile w/White Streaks Mastic	200	SF	North & South Gym Storage Areas and South Gym Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
010	12" x 12" White Vinyl Floor Tile w/Black & Gray Streaks	2,500	SF	South Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
010 A	12" x 12" White Vinyl Floor Tile w/Black & Gray Streaks Mastic	2,500	SF	South Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
011	9" x 9" Blue Vinyl Floor Tile w/White & Black Streaks			Auditorium	Chrysotile	MISC					Follow O&M Plan
011 A	9" x 9" Blue Vinyl Floor Tile w/White & Black Streaks Mastic			Auditorium	Chrysotile	MISC					Follow O&M Plan
012	9" x 9" Cream Floor Tile w/Red & Black Streaks	4,150	SF	Rooms 103, 105, 106, 209A	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
012 A	9" x 9" Cream Floor Tile w/Red & Black Streaks Mastic	4,150	SF	Rooms 103, 105, 106, 209A	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
035	Mastic associated with carpeting			Engineer's Office, Main Office, Teachers Lounge, & Various areas Throughout	Assumed	MISC					Follow O&M Plan
036	Brown mop board	100	SF	Throughout Building, Rooms 001, 003, 005, 116 & 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
036 A	Brown mop board mastic	100	SF	Throughout Building, Rooms 001, 003, 005, 116 & 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
037	Black mop board	100	SF	Rooms 007 through 102 Auditorium & Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
037 A	Black mop board mastic	100	SF	Rooms 007 through 102 Auditorium & Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
038	Exterior window caulk - non ahera			Exterior of Building	Assumed	MISC					Follow O&M Plan
039	Exterior expansion joint - non ahera			Exterior of Building	Assumed	MISC					Follow O&M Plan
040	Dark brown exterior brick - Non-AHERA			Exterior of Building	Assumed	MISC					Follow O&M Plan
041	Brown exterior brick - Non-AHERA			Exterior of Building	Assumed	MISC					Follow O&M Plan
042	Tan exterior brick - Non-AHERA			Exterior of Building	Assumed	MISC					Follow O&M Plan
043	Cream Brick w/Black Speckles - Non-AHERA			Exterior of Building	Assumed	MISC					Follow O&M Plan
044	Brick mortar - Non-AHERA			Exterior of Building	Assumed	MISC					Follow O&M Plan
045	Chimney flashing - Non-AHERA			Exterior of Building	Assumed	MISC					Follow O&M Plan
046	Exterior window glaze - Non-AHERA			Exterior of Building	Assumed	MISC					Follow O&M Plan
047	Plaster	3,000	SF	Gym and Auditorium	Chrysotile	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

Chicago Public Schools

School Healy School

Unit 23651

Building ID 3880

Address 3010 S. Parnell

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
048	Transite Ceiling Panels			North Doors, West Doors by Main Office, Engineer's Corridor Door	Chrysotile	MISC				suspect ACBM	
049	12" x 12" White w/Gray Specks Floor Tile	3,150	SF	Teacher's Lounge, Lunchroom, Rooms 207,210,213,107A,107B, 204, 214, 218	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
050	12" x 12" White w/Gray Specks Floor Tile Mastic	3,150	SF	Teacher's Lounge, Lunchroom, Rooms 207,210,213,107A,107B, 204, 214, 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
051	12" x 12" Burnt Orange Floor Tile	900	SF	North & South 2nd flr Stairwell, custodian closet 1st floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
052	12" x 12" Burnt Orange Floor Tile Mastic	900	SF	North & South 2nd flr Stairwell, custodian closet 1st floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
053	Dark gray carpet adhesive	120	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
054	12" x 12" Blue Floor Tile	5,400	SF	109 A and 1st Floor Hallway	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
055	12" x 12" Blue Floor Tile Mastic	5,400	SF	109 A and 1st Floor Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
056	12" x 12" Yellow Floor Tile	5,000	SF	2nd Floor Hallway and Janitor's Utility Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
057	12" x 12" Yellow Floor Tile Mastic	5,000	SF	2nd Floor Hallway and Janitor's Utility Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
059	12" x 12" Gray Mablign Mix Floor Tile	1,150	SF	Room 107 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
060	12" x 12" Gray Mablign Mix Floor Tile Mastic	1,150	SF	Room 107 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
061	12" x 12" Peach Floor Tile	300	SF	As Patches in Rooms 101, 103, 105 Bathroom, 110 & 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
062	12" x 12" Peach Floor Tile Mastic	300	SF	As Patches in Rooms 101, 103, 105 Bathroom, 110 & 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
063	12"x12" White w/Gray Floor Tile	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
064	12"x12" White w/Gray Floor Tile Mastic	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
065	12" x 12" Gray w/Gray Speckles Floor Tile	1,100	SF	First Floor Men's Room, Bathroom and Room 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
066	12" x 12" Gray w/Gray Speckles Floor Tile Mastic	1,100	SF	First Floor Men's Room,Bathroom and Room 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
067	12" x 12" Brown w/White Floor Tile	270	SF	Family Room and Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
068	12" x 12" Brown w/White Floor Tile Mastic	270	SF	Family Room and Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
069	Gray baseboard	1,500	LF	First Floor Hall and Main Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
070	Gray baseboard adhesive	1,500	LF	First Floor Hall and Main Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Healy School
Address 3010 S. Parnell

Unit 23651
Chicago, IL, 60616

Building ID 3880
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
071	Brown baseboard	6,500	LF	First & Second Floor Classrooms and Second Floor Hall	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
072	Brown baseboard adhesive	6,500	LF	First & Second Floor Classrooms and Second Floor Hall	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
073	9" x 9" White w/Brown Floor Tile	8	SF	Room 203 (Patch)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
074	9" x 9" White w/Brown Floor Tile Mastic	8	SF	Room 203 (Patch)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1	12" x 12" Brown Vinyl Floor Tile w/Brown & White Streaks	2,000	SF	Engineer's Office, Room 101,209B, 211A, Women's 2nd Floor Staff restroom, auditorium	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Remove
4	9" x 9" Tan Floor Tile w/White & Brown Streaks	8,400	SF	100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off., 214	Chrysotile	MISC	No	62	SF	6 ACBM with the potential for damage	Remove
48	Transite ceiling panels			North Doors, West Doors by Main Office, Engineer's Corridor Door, throughout facility	Chrysotile	MISC					Follow O&M Plan
58	Insulation inside of Vault Door			Main Office	Assumed	TSI					Follow O&M Plan
63	12" x 12" White w/Gray Floor Tile	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	Assumed	MISC	No	37	SF	6 ACBM with the potential for damage	Remove
64	12" x 12" White w/Gray Floor Tile Mastic	3,050	SF	Main Office, Principal's Office, and Rooms 210, 213, 107A,107B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12" x 12" Light Brown Vinyl Floor Tile	7,300	SF	Room 200,201,202,206,208,214,216,217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12" x 12" Light Brown Vinyl Floor Tile Mastic	7,300	SF	Room 200,201,202,206,208,214,216, 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	12" x 12" White w/Multicolored Speckle Vinyl Floor Tile	500	SF	Auditorium Rows	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" White w/Multicolored Speckle Vinyl Floor Tile Mastic	500	SF	Auditorium Rows	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12" x 12" White w/Blue Speckles Vinyl Floor Tile	1,400	SF	Room 212, asst. principal's office (120D)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12" x 12" White w/Blue Speckles Vinyl Floor Tile Mastic	900	SF	Room 212, asst. principal's office (120D)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Vibration damper	10	SF	2nd Floor Fan Room Above Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	Duct cornering	25	SF	2nd Floor Fan Room Above Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" Dark Blue Vinyl Floor Tile	250	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" Dark Blue Vinyl Floor Tile Mastic	250	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Healy School
Address 3010 S. Parnell

Unit 23651
 Chicago, IL, 60616

Building ID 3880
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
H	Pipe insulation		LF	101 and Bathroom, Crawl Space - Heating System	Abated	TSI			LF		
I	Pipe insulation assoc. Elbows			Crawl Space	Chrysotile	TSI					Follow O&M Plan

Review Date	
Manager Planner Name	Evan Christian

HA Number	Management Comments
001	

Chicago Public Schools

School Healy School
Address 3010 S. Parnell

Unit 23651
 Chicago, IL, 60616

Building ID 3880
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
001 A	
002	
002 A	
003	
003 A	
004	
004 A	
005	
005 A	
006	
006A	
007	
007 A	
008	
008 A	
009	
009 A	
010	
010 A	
011	
011 A	
012	
012 A	
035	
036	
036 A	
037	

Chicago Public Schools

School Healy School
Address 3010 S. Parnell

Unit 23651
Chicago, IL, 60616

Building ID 3880
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
037 A	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	
057	
059	
060	
061	
062	
063	
064	

Chicago Public Schools

School Healy School
Address 3010 S. Parnell

Unit 23651
 Chicago, IL, 60616

Building ID 3880
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
065	
066	
067	
068	
069	
070	
071	
072	
073	
074	
1	remove damaged
4	remove damaged materials, rep[lace an
48	
58	
63	Sample to determine ACM content.
64	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
H	

Chicago Public Schools

School Healy School
Address 3010 S. Parnell

Unit 23651
Chicago, IL, 60616

Building ID 3880
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
1	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **12"x12" Brown VFT w/Brown & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Room 101,209B**

MATERIAL QUANTITY: **1475**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **12"x12" Brown VFT w/Brown & White Streaks**
MATERIAL LOCATION: **Engineer's Office, Room 101,209B**
MATERIAL QUANTITY: **1475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001 A**
MATERIAL DESCRIPTION: **12" x 12" Brown Vinyl Floor Tile w/Brown & White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Room 101,209B, 211A, Women's 2nd Floor Staff restroom, auditorium**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Engineer's office 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **001 A**
MATERIAL DESCRIPTION: **12" x 12" Brown Vinyl Floor Tile w/Brown & White Streaks Mastic**
MATERIAL LOCATION: **Engineer's Office, Room 101,209B, 211A, Women's 2nd Floor Staff restroom, auditorium**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **9" x 9" Gray Fillor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 103, Engineer's Corridor, 1st & 2nd Flr Teacher's Bathrooms, 1st Floor Men's Room & Computer Room**

MATERIAL QUANTITY: **445** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **9" x 9" Gray Fillor Tile w/ White Streaks**
MATERIAL LOCATION: **Room 103, Engineer's Corridor, 1st & 2nd Flr Teacher's Bathrooms, 1st Floor Men's Room & Computer Room**
MATERIAL QUANTITY: **445** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002 A**
MATERIAL DESCRIPTION: **9" x 9" Gray Fillor Tile w/ White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 103, Engineer's Corridor, 1st & 2nd Flr Teacher's Bathrooms, 1st Floor Men's Room & Computer Room**

MATERIAL QUANTITY: **445** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **002 A**
MATERIAL DESCRIPTION: **9" x 9" Gray Fillor Tile w/ White Streaks Mastic**
MATERIAL LOCATION: **Room 103, Engineer's Corridor, 1st & 2nd Flr Teacher's Bathrooms, 1st Floor Men's Room & Computer Room**
MATERIAL QUANTITY: **445** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/White & Blue Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Security Office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/White & Blue Streaks**
MATERIAL LOCATION: **Security Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 A**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/White & Blue Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Security Office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **003 A**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/White & Blue Streaks Mastic**
MATERIAL LOCATION: **Security Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile w/White & Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile w/White & Brown Streaks**
MATERIAL LOCATION: **100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off.**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 23651 BUIDLING ID: 3880
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Benyamen Maradkel
SCHOOL NAME: Healy School INSPECTION DATE: 8/9/2022
ADDRESS: 3010 S. Parnell IDPH LICENSE NO: 100-20411

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 004 A
MATERIAL DESCRIPTION: 9" x 9" Tan Floor Tile w/White & Brown Streaks Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Chrysotile FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off., 214**

MATERIAL QUANTITY: **8400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rms 210, 215, 218, 102, kitchen and Engineer's Office, could be under 12" floor tile, 207, 213, 205 abated - 2022**

Inspector's Signature:



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **004 A**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/White & Brown Streaks Mastic**
MATERIAL LOCATION: **100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off., 214**
MATERIAL QUANTITY: **8400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile w/White & Black Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile w/White & Black Streaks**
MATERIAL LOCATION: **1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005 A**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile w/White & Blk Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **005 A**

MATERIAL DESCRIPTION: **9"x9" Green Floor Tile w/White & Blk Streaks Mastic**

MATERIAL LOCATION: **1st Floor E/W Corridor, Rooms 103 & 106, and Kitchen Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Vinyl Floor Tile w/ Dark Brown & White Marbling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen and Rooms 101, 204, and 218**

MATERIAL QUANTITY: **3300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Kitchen, Rm 204**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Vinyl Floor Tile w/ Dark Brown & White Marbling**
MATERIAL LOCATION: **Kitchen and Rooms 101, 204, and 218**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006A**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Vinyl Floor Tile w/Dark Brown & Whitet. Marble mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen and Rooms 101,204, and 218**

MATERIAL QUANTITY: **4100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Kitchen, Rm 204 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **006A**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Vinyl Floor Tile w/Dark Brown & Whitet. Marble mastic**
MATERIAL LOCATION: **Kitchen and Rooms 101,204, and 218**
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **12" x 12" Cream Floor Tile w/Tan & Brown Marbling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor**

MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **12" x 12" Cream Floor Tile w/Tan & Brown Marbling**
MATERIAL LOCATION: **Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor**
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 A**
MATERIAL DESCRIPTION: **12" x 12" Cream Vinyl Floor Tile w/Tan & Brown Marbling Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor**

MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **007 A**
MATERIAL DESCRIPTION: **12" x 12" Cream Vinyl Floor Tile w/Tan & Brown Marbling Mastic**
MATERIAL LOCATION: **Kitchen, Teacher's Lounge, Rooms 209, 215, 218 and the Far Room on the 1st Floor**
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Black & Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Black & Gray Streaks**
MATERIAL LOCATION: **North Gym**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008 A**
MATERIAL DESCRIPTION: **9" x 9" White Vinyl Floor Tile w/Black & Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **008 A**
MATERIAL DESCRIPTION: **9" x 9" White Vinyl Floor Tile w/Black & Gray Streaks Mastic**
MATERIAL LOCATION: **North Gym**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North & South Gym Storage Areas and South Gym Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/White Streaks**
MATERIAL LOCATION: **North & South Gym Storage Areas and South Gym Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009 A**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North & South Gym Storage Areas and South Gym Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **009 A**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/White Streaks Mastic**
MATERIAL LOCATION: **North & South Gym Storage Areas and South Gym Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile w/Black & Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile w/Black & Gray Streaks**
MATERIAL LOCATION: **South Gym**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010 A**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile w/Black & Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South Gym**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **010 A**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile w/Black & Gray Streaks Mastic**
MATERIAL LOCATION: **South Gym**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **9" x 9" Blue Vinyl Floor Tile w/White & Black Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **011**

MATERIAL DESCRIPTION: **9" x 9" Blue Vinyl Floor Tile w/White & Black Streaks**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011 A**
MATERIAL DESCRIPTION: **9" x 9" Blue Vinyl Floor Tile w/White & Black Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **011 A**

MATERIAL DESCRIPTION: **9" x 9" Blue Vinyl Floor Tile w/White & Black Streaks Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/Red & Black Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 103, 105, 106, 209A**

MATERIAL QUANTITY: **4150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/Red & Black Streaks**
MATERIAL LOCATION: **Rooms 103, 105, 106, 209A**
MATERIAL QUANTITY: **4150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012 A**
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/Red & Black Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 103, 105, 106, 209A**

MATERIAL QUANTITY: **4150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **012 A**
MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/Red & Black Streaks Mastic**
MATERIAL LOCATION: **Rooms 103, 105, 106, 209A**
MATERIAL QUANTITY: **4150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **Mastic associated with carpeting**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office, Main Office, Teachers Lounge, & Various areas Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed carpet in engineer 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **Mastic associated with carpeting**
MATERIAL LOCATION: **Engineer's Office, Main Office, Teachers Lounge, & Various areas Throughout**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **Brown mop board**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building, Rooms 001, 003, 005, 116 & 208**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **Brown mop board**
MATERIAL LOCATION: **Throughout Building, Rooms 001, 003, 005, 116 & 208**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036 A**
MATERIAL DESCRIPTION: **Brown mop board mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building, Rooms 001, 003, 005, 116 & 208**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **036 A**
MATERIAL DESCRIPTION: **Brown mop board mastic**
MATERIAL LOCATION: **Throughout Building, Rooms 001, 003, 005, 116 & 208**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **Black mop board**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 007 through 102 Auditorium & Room 100**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **Black mop board**
MATERIAL LOCATION: **Rooms 007 through 102 Auditorium & Room 100**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037 A**
MATERIAL DESCRIPTION: **Black mop board mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 007 through 102 Auditorium & Room 100**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **037 A**
MATERIAL DESCRIPTION: **Black mop board mastic**
MATERIAL LOCATION: **Rooms 007 through 102 Auditorium & Room 100**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **Exterior window caulk - non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **Exterior window caulk - non ahera**
MATERIAL LOCATION: **Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **Exterior expansion joint - non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **Exterior expansion joint - non ahera**
MATERIAL LOCATION: **Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **Dark brown exterior brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **040**

MATERIAL DESCRIPTION: **Dark brown exterior brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **Brown exterior brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **041**

MATERIAL DESCRIPTION: **Brown exterior brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **Tan exterior brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **042**

MATERIAL DESCRIPTION: **Tan exterior brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **Cream Brick w/Black Speckles - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **Cream Brick w/Black Speckles - Non-AHERA**
MATERIAL LOCATION: **Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **Brick mortar - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **044**

MATERIAL DESCRIPTION: **Brick mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Chimney flashing - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Chimney flashing - Non-AHERA**
MATERIAL LOCATION: **Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Exterior window glaze - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Exterior window glaze - Non-AHERA**
MATERIAL LOCATION: **Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym and Auditorium**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Gym and Auditorium**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **Transite Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Doors, West Doors by Main Office, Engineer's Corridor Door**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **Transite Ceiling Panels**
MATERIAL LOCATION: **North Doors, West Doors by Main Office, Engineer's Corridor Door**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's Lounge, Lunchroom, Rooms 207,210,213,107A,107B, 204, 214, 218**
MATERIAL QUANTITY: **3150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Rm 210, 107**

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile**
MATERIAL LOCATION: **Teacher's Lounge, Lunchroom, Rooms 207,210,213,107A,107B, 204, 214, 218**
MATERIAL QUANTITY: **3150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's Lounge, Lunchroom, Rooms 207,210,213,107A,107B, 204, 214, 218**
MATERIAL QUANTITY: **3150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Teacher's Lounge, Lunchroom, Rooms 207,210,213,107A,107B, 204, 214, 218**
MATERIAL QUANTITY: **3150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **12" x 12" Burnt Orange Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North & South 2nd flr Stairwell, custodian closet 1st floor**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **12" x 12" Burnt Orange Floor Tile**
MATERIAL LOCATION: **North & South 2nd flr Stairwell, custodian closet 1st floor**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **12" x 12" Burnt Orange Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North & South 2nd flr Stairwell, custodian closet 1st floor**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Most removed**

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **12" x 12" Burnt Orange Floor Tile Mastic**
MATERIAL LOCATION: **North & South 2nd flr Stairwell, custodian closet 1st floor**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Dark gray carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Dark gray carpet adhesive**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **109 A and 1st Floor Hallway**
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in Rm 109A, some damage in hallway - 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **109 A and 1st Floor Hallway**
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **109 A and 1st Floor Hallway**

MATERIAL QUANTITY: **5400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rm 109A**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **109 A and 1st Floor Hallway**
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Hallway and Janitor's Utility Room**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**
MATERIAL LOCATION: **2nd Floor Hallway and Janitor's Utility Room**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Hallway and Janitor's Utility Room**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Hallway and Janitor's Utility Room**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **12" x 12" Gray Mablign Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 107 (Library)**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **12" x 12" Gray Mablign Mix Floor Tile**
MATERIAL LOCATION: **Room 107 (Library)**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **12" x 12" Gray Mablign Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 107 (Library)**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **12" x 12" Gray Mablign Mix Floor Tile Mastic**
MATERIAL LOCATION: **Room 107 (Library)**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **12" x 12" Peach Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **As Patches in Rooms 101, 103, 105 Bathroom, 110 & 112**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **12" x 12" Peach Floor Tile**
MATERIAL LOCATION: **As Patches in Rooms 101, 103, 105 Bathroom, 110 & 112**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **062**
MATERIAL DESCRIPTION: **12" x 12" Peach Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **As Patches in Rooms 101, 103, 105 Bathroom, 110 & 112**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **062**
MATERIAL DESCRIPTION: **12" x 12" Peach Floor Tile Mastic**
MATERIAL LOCATION: **As Patches in Rooms 101, 103, 105 Bathroom, 110 & 112**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **063**
MATERIAL DESCRIPTION: **12"x12" White w/Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, Principal's Office, and Rooms 210, 213, 107A,107B**
MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **063**
MATERIAL DESCRIPTION: **12"x12" White w/Gray Floor Tile**
MATERIAL LOCATION: **Main Office, Principal's Office, and Rooms 210, 213, 107A,107B**
MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **064**
MATERIAL DESCRIPTION: **12"x12" White w/Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Principal's Office, and Rooms 210, 213, 107A,107B**

MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **064**
MATERIAL DESCRIPTION: **12"x12" White w/Gray Floor Tile Mastic**
MATERIAL LOCATION: **Main Office, Principal's Office, and Rooms 210, 213, 107A,107B**
MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **065**
MATERIAL DESCRIPTION: **12" x 12" Gray w/Gray Speckles Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First Floor Men's Room, Bathroom and Room 211**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **065**
MATERIAL DESCRIPTION: **12" x 12" Gray w/Gray Speckles Floor Tile**
MATERIAL LOCATION: **First Floor Men's Room, Bathroom and Room 211**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **066**
MATERIAL DESCRIPTION: **12" x 12" Gray w/Gray Speckles Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **First Floor Men's Room,Bathroom and Room 211**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **066**
MATERIAL DESCRIPTION: **12" x 12" Gray w/Gray Speckles Floor Tile Mastic**
MATERIAL LOCATION: **First Floor Men's Room,Bathroom and Room 211**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **067**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Family Room and Bathroom**

MATERIAL QUANTITY: **270**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **067**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Floor Tile**
MATERIAL LOCATION: **Family Room and Bathroom**
MATERIAL QUANTITY: **270** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Family Room and Bathroom**

MATERIAL QUANTITY: **270**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Floor Tile Mastic**
MATERIAL LOCATION: **Family Room and Bathroom**
MATERIAL QUANTITY: **270** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **069**
MATERIAL DESCRIPTION: **Gray baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **First Floor Hall and Main Office**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **069**
MATERIAL DESCRIPTION: **Gray baseboard**
MATERIAL LOCATION: **First Floor Hall and Main Office**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070**
MATERIAL DESCRIPTION: **Gray baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **First Floor Hall and Main Office**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **070**
MATERIAL DESCRIPTION: **Gray baseboard adhesive**
MATERIAL LOCATION: **First Floor Hall and Main Office**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date:

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **071**
MATERIAL DESCRIPTION: **Brown baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **First & Second Floor Classrooms and Second Floor Hall**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **071**
MATERIAL DESCRIPTION: **Brown baseboard**
MATERIAL LOCATION: **First & Second Floor Classrooms and Second Floor Hall**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **Brown baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First & Second Floor Classrooms and Second Floor Hall**

MATERIAL QUANTITY: **6500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **Brown baseboard adhesive**
MATERIAL LOCATION: **First & Second Floor Classrooms and Second Floor Hall**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **073**
MATERIAL DESCRIPTION: **9" x 9" White w/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 203 (Patch)**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **073**
MATERIAL DESCRIPTION: **9" x 9" White w/Brown Floor Tile**
MATERIAL LOCATION: **Room 203 (Patch)**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **074**
MATERIAL DESCRIPTION: **9" x 9" White w/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 203 (Patch)**

MATERIAL QUANTITY: **8**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **074**
MATERIAL DESCRIPTION: **9" x 9" White w/Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 203 (Patch)**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Insulation inside of Vault Door**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Insulation inside of Vault Door**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 200,201,202,206,208,214,216,217**
MATERIAL QUANTITY: **7300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **7300** DAMAGE UNITS: **SF**
COMMENTS: **Not observed in Rm 214**

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Vinyl Floor Tile**
MATERIAL LOCATION: **Room 200,201,202,206,208,214,216,217**
MATERIAL QUANTITY: **7300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 200,201,202,206,208,214,216, 217**

MATERIAL QUANTITY: **7300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rm 214**

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 200,201,202,206,208,214,216, 217**
MATERIAL QUANTITY: **7300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12" x 12" White w/Multicolored Speckle Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium Rows**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Aisles still have tiles - Not observed in Rows of Seats**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12" x 12" White w/Multicolored Speckle Vinyl Floor Tile**
MATERIAL LOCATION: **Auditorium Rows**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" White w/Multicolored Speckle Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium Rows**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Aisles still have tiles - Not observed in Rows of Seats**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" White w/Multicolored Speckle Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Auditorium Rows**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Speckles Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 212, asst. principal's office (120D)**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" White w/Blue Speckles Vinyl Floor Tile**

MATERIAL LOCATION: **Room 212, asst. principal's office (120D)**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Speckles Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 212, asst. principal's office (120D)**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Speckles Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 212, asst. principal's office (120D)**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **Vibration damper**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Fan Room Above Auditorium**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Vibration damper**

MATERIAL LOCATION: **2nd Floor Fan Room Above Auditorium**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **Duct cornering**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Fan Room Above Auditorium**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **Duct cornering**
MATERIAL LOCATION: **2nd Floor Fan Room Above Auditorium**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Water Physical Damage**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **101 and Bathroom, Crawl Space - Heating System**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Abated 2021 all new non-asbestos**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Pipe insulation**

MATERIAL LOCATION: **101 and Bathroom, Crawl Space - Heating System**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Pipe insulation assoc. Elbows**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Crawl Space**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **08/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUIDLING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Pipe insulation assoc. Elbows**

MATERIAL LOCATION: **Crawl Space**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date:

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Vinyl Floor Tile**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Healy School** REVIEW DATE:

ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12" x 12" Dark Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Healy School** REVIEW DATE:

ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/White & Brown Streaks**

MATERIAL LOCATION: **100, 102, 104, 108-115, 203, 205, 207, 210-212, 215, 218, Kitchen WR, Eng. Off., 214**

MATERIAL QUANTITY: **8400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **62** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

remove damaged materials, replace an

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Healy School** INSPECTION DATE: **8/9/2022**
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Floor Tile**
MATERIAL LOCATION: **Main Office, Principal's Office, and Rooms 210, 213, 107A,107B**
MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **37** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in 210, 107A

Inspector's Signature:



Date: 08/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Healy School** REVIEW DATE:

ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" White w/Gray Floor Tile**

MATERIAL LOCATION: **Main Office, Principal's Office, and Rooms 210, 213, 107A,107B**

MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **37** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content.

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Floor Tile Mastic**
MATERIAL LOCATION: **Main Office, Principal's Office, and Rooms 210, 213, 107A,107B**
MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Healy School** REVIEW DATE:

ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **12" x 12" Brown Vinyl Floor Tile w/Brown & White Streaks**

MATERIAL LOCATION: **Engineer's Office, Room 101,209B, 211A, Women's 2nd Floor Staff restroom, auditorium**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:
remove damaged

Management Planner's Signature: _____



Date: _____

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23651** BUILDING ID: **3880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Healy School** REVIEW DATE:
ADDRESS: **3010 S. Parnell** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Transite ceiling panels**

MATERIAL LOCATION: **North Doors, West Doors by Main Office, Engineer's Corridor Door, throughout facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: _____

APPENDIX B

Inspector and Management Planner Licenses

Benyamen Maradkel

Illinois Licensed Building Inspector



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 20411

ISSUED
3/17/2022

EXPIRES
05/15/2023

BENYAMEN C MARADKEL
706 W HACKBERRY DR
ARLINGTON HEIGHTS, IL 6000
Environmental Health



ENDORSEMENTS

INSPECTOR

EXPIRES

5/9/2023

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Benyamen Maradkel

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090703

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed