

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2285  
SCHOOL NAME: Jamieson School  
ADDRESS OF SCHOOL: 5650 N Mozart Street  
CITY: Chicago, IL, 60659

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **9/20/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 8/25/2022 ENROLLMENT 799  
IDPH INSPECTOR LICENSE NUMBER: 100-19036  
IDPH LICENSED INSPECTOR NAME (Please Print): Ismael Hernandez  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer*

9/16/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Jamieson School**

5650 N Mozart Street  
Chicago, IL, 60659

Unit: 23931  
Building ID: 4180

IDPH ID Number: 14-016-2990-2285

**REPORT DATE:**

Friday, September 16, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Specialty Consulting, Inc.**

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

09/16/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 23931            Region: 01            IDPH ID: 14-016-2990-2285

School: Jamieson School            Building ID: 4180

Address: 5650 N Mozart Street

Chicago, IL, 60659

Building Contact:            Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 8/25/2022

Review Date: 09/16/2022

Inspector: Ismael Hernandez

Inspector IDPH License: 100-19036

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,  
Specialty Consulting, Inc.



Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 16, 2022

RE: Jamieson School, Unit 23931  
5650 N Mozart Street  
Chicago, IL, 60659

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Jamieson School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Jamieson School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Jamieson School Unit: 23931 Region: 01  
Address: 5650 N Mozart Street Chicago, IL, 60659  
IDPH ID: 14-016-2990-2285 Building ID: 4180  
Contact: Phone:

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: 3956 No of Floors: 1  
Current Occupancy: 799

### 3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant


MEC: Specialty Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren Street  
Phone: (312) 319-7575 Fax: (312) 319-7580

### 5. Inspector

Inspector Name: Ismael Hernandez

Inspector IDPH license # 100-19036  
Reinspection Date: 8/25/2022

Signature:  
Date: 8/25/2022



### 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

Signature:  
Date: 09/16/2022




### 7. Review Date: 09/16/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 9/16/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Jamieson School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4180:

B. The following new homogenous areas have been identified for Building 4180:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

|     |   |
|-----|---|
| 03  | Brown Linoleum  |
| 04  | 9"x9" Red VFT Mastic                                    |
| 06  | Brown Linoleum Mastic                                   |
| 21  | Tan Linoleum  |
| 22  | 12"x12" Beige w/ White & Black Streaks VFT Mastic       |
| 25  | 12"x12" Gray w/ White Streaks VFT Mastic                |
| 28  | 12"x12" Light Brown w/ White & Brown Streaks VFT Mastic |
| 29  | 9"x9" Black VFT Mastic                                  |
| 30  | 6"x18" Black VFT Mastic                                 |
| 34  | Tan Linoleum Mastic                                     |
| 35  | 12"x12" White w/ Beige Spots VFT                        |
| 36  | 12"x12" White w/ Beige Spots VFT Mastic                 |
| 37  | 2' x 2' White w/ Grooves Ceiling Tile                   |
| 38  | 12"x12" Blue VFT  |
| 39  | 12"x12" Blue VFT Mastic                                 |
| 40  | 12"x12" Light Gray w/ Gray Specks VFT - NOT OBSERVED    |
| 41  | 12"x12" Light Gray w/ Gray Specks VFT Mastic            |
| 42  | 12"x12" Light Blue w/ White Specks VFT                  |
| 43  | 12"x12" Light Blue w/ White Specks VFT Mastic           |
| 44  | Carpet Mastic   |
| 45  | Terrazzo  |
| 46  | 12"x12" Blue Streaked VFT                               |
| 46A | 12"x12" Blue Streaked VFT Mastic                        |
| 47  | Decorative Plaster                                      |
| 48  | 2'x4' Ceiling Tiles                                     |
| 49  | Fire Doors  |
| 50  | Textured Ceiling Paint                                  |
| 51  | Vinyl Baseboard Mastic                                  |
| 52  | Terrazzo  |
| 53  | Fire Doors  |
| 54  | 2'x4' Ceiling Tiles                                     |
| 55  | Drywall, Tape, and Compound                             |
| 56  | Fire Doors  |
| 57  | 1'x1' Ceiling Tile with Grooves                         |
| 58  | Decorative Plaster Trim                                 |
| 59  | Pyrobar - NOT OBSERVED                                  |
| 60  | 12"x12" Light Gray w/ White and Gray Streaks VFT        |
| 60M | 12"x12" Light Gray w/ White and Gray Streaks VFT Mastic |

|    |  |
|----|--|
| 61 | Drywall System                           |
| 62 | 12"x12" Black w/ White Specs VFT         |
| 63 | 12"x12" Black w/ White Specks VFT Mastic |
| 64 | 20"x20" Yellow w/ Streaks VFT            |
| 65 | 20"x20" Yellow w/ Streaks VFT Mastic     |
| 66 | 20"x20" Blue w/ Streaks VFT              |
| 67 | 20"x20" Blue w/ Streaks VFT Mastic       |
| 68 | 20"x20" Off White w/ Streaks VFT         |
| 69 | 20"x20" Off White w/ Streaks VFT Mastic  |
| 70 | 2'x2' Ceiling Tile                       |
| 71 | 12"x12" Black w/ White Specks VFT        |
| 72 | 12"x12" Black w/ White Specks VFT Mastic |
| 73 | Carpet Mastic                            |
| Z  | Boiler Gasket                            |

The following areas were deemed to be inaccessible:

|    |                                    |
|----|------------------------------------|
| 13 | 12"x12" Green w/ White Streaks VFT |
|----|------------------------------------|

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Ismael Hernandez, IDPH License # 100-19036. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 12/8/2021

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Jamieson School Building 4180 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Jamieson School Unit 23931 Building ID 4180

Address 5650 N Mozart Street Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 01    | 9"x9" Red VFT  | 2,100             | SF             | 2nd & 3rd Floor Hall - 1937 Building                           | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 03    | Brown Linoleum   | 500               | SF             | Room 307 - 1937 Building                                       | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 04    | 9"x9" Red VFT Mastic                                   | 1,490             | SF             | 2nd & 3rd Floor Hall - 1937 Building                           | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 06    | Brown Linoleum Mastic                                  | 500               | SF             | Room 307 - 1937 Building                                       | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 07    | 12"x12" Gray w/ Pink, White, & Black Streaks VFT       | 2,500             | SF             | 1st & 2nd Floor Hall - 1954 Building                           | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 09    | 12"x12" Gray w/ Pink, White & Black Streaks VFT Mastic | 2,500             | SF             | 1st & 2nd Floor Hall - 1954 Building                           | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 11    | 12"x12" Beige w/ White & Black Streaks VFT             | 4,000             | SF             | Rooms 112, 114, 116, 216, & 212 - 1954 Building - NOT OBSERVED | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 12    | 12"x12" Gray w/ White Streaks VFT                      | 2,400             | SF             | Rooms 111, 213, & 211 - 1954 Building - NOT OBSERVED           | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 13    | 12"x12" Green w/ White Streaks VFT                     | 1,200             | SF             | Room 215 - 1954 Building                                       | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 15    | 12"x12" Light Brown w/ White & Brown Streaks VFT       | 2,430             | SF             | Rooms 305, & 1st Floor Hall - 1937 Building                    | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 16    | 9"x9" Black VFT  | 1,490             | SF             | 2nd & 3rd Floor Halls - 1937 Building                          | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 17    | 6"x18" Black VFT                                       | 400               | SF             | 2nd & 3rd Floor Halls - 1937 Building                          | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 18    | 12"x12" Beige w/ White Spots VFT                       | 750               | SF             | Lunchroom - 1937 Building                                      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 19    | 9"x9" Gray VFT   | 300               | SF             | Main Office (Under HA # 46) - 1937 Building                    | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 21    | Tan Linoleum   | 1,500             | SF             | Room 115 (Under Carpet) - 1954 Building                        | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 22    | 12"x12" Beige w/ White & Black Streaks VFT Mastic      | 4,500             | SF             | Rooms 112, 114, 116, 214, & 212 - 1954 Building                | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 23    | 9"x9" Beige w/ Black Streaks VFT                       | 235               | SF             | Engineer's Office & Bathroom - 1937 Building                   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Jamieson School Unit 23931 Building ID 4180

Address 5650 N Mozart Street Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                     | Material Quantity | Material Units | Material Location                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 24    | 9"x9" Beige w/ Black Streaks VFT Mastic                  | 235               | SF             | Engineer's Office & Bathroom - 1937 Building  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 25    | 12"x12" Gray w/ White Streaks VFT Mastic                 | 800               | SF             | Room 111 - 1954 Building                      | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 26    | 12"x12" Green w/ White Streaks VFT Mastic - NOT OBSERVED | 1,200             | SF             | Room 215 - 1954 Building - NOT OBSERVED       | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | Low                   |
| 28    | 12"x12" Light Brown w/ White & Brown Streaks VFT Mastic  | 2,430             | SF             | Room 305, & 1st Floor Hall - 1937 Building    | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 29    | 9"x9" Black VFT Mastic                                   | 1,490             | SF             | 2nd & 3rd Floor Halls - 1937 Building         | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 30    | 6"x18" Black VFT Mastic                                  | 1,490             | SF             | 2nd & 3rd Floor Halls - 1937 Building         | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 31    | 12"x12" Beige w/ White Spots VFT Mastic                  | 750               | SF             | Lunchroom - 1937 Building                     | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 32    | 9"x9" Gray VFT Mastic                                    | 300               | SF             | Main Office (Under HA # 46) - 1937 Building   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 34    | Tan Linoleum Mastic                                      | 800               | SF             | Room 115 (under carpet) - 1954 Building       | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 35    | 12"x12" White w/ Beige Spots VFT                         | 5,000             | SF             | Throughout - 1999 Modular (No Longer on Site) | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 36    | 12"x12" White w/ Beige Spots VFT Mastic                  | 5,000             | SF             | Throughout - 1999 Modular (No Longer on Site) | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 37    | 2' x 2' White w/ Grooves Ceiling Tile                    | 5,000             | SF             | Throughout - 1999 Modular (No Longer on Site) | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 38    | 12"x12" Blue VFT   | 2,200             | SF             | Auditorium - 1937 Building                    | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 39    | 12"x12" Blue VFT Mastic                                  | 2,200             | SF             | Auditorium - 1937 Building                    | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 40    | 12"x12" Light Gray w/ Gray Specks VFT - NOT OBSERVED     | 800               | SF             | Room 211 - 1954 Building - NOT OBSERVED       | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 41    | 12"x12" Light Gray w/ Gray Specks VFT Mastic             | 800               | SF             | Room 211 - 1954 Building - NOT OBSERVED       | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Jamieson School Unit 23931 Building ID 4180

Address 5650 N Mozart Street Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                          | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 42    | 12"x12" Light Blue w/ White Specks VFT        | 800               | SF             | Basement Teacher's Lounge                                    | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 43    | 12"x12" Light Blue w/ White Specks VFT Mastic | 800               | SF             | Basement Teacher's Lounge                                    | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 44    | Carpet Mastic                                 | 2,100             | SF             | Rooms 214, 113, and 115 - 1954 Building                      | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 45    | Terrazzo                                      | 500               | SF             | Stairs - 1954 Building                                       | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 46    | 12"x12" Blue Streaked VFT                     | 800               | SF             | Main Office - 1937 Building                                  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 46A   | 12"x12" Blue Streaked VFT Mastic              | 800               | SF             | Main Office - 1937 Building                                  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 47    | Decorative Plaster                            | 500               | SF             | Auditorium - 1937 Building                                   | ASSUMED       | SURFACE           | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 48    | 2'x4' Ceiling Tiles                           | 0                 | SF             | Gym - 1937 Building  | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 49    | Fire Doors                                    | 2                 | EA             | Mechanical Room - 1999 Mobile (No Longer on Site)            | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 50    | Textured Ceiling Paint                        | 300               | SF             | Restrooms - 1999 Mobile (No Longer on Site)                  | ASSUMED       | SURFACE           | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 51    | Vinyl Baseboard Mastic                        | 600               | LF             | Throughout - 1999 Mobile (No Longer on Site)                 | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 52    | Terrazzo                                      | 12,000            | SF             | 1st, 2nd, and 3rd Floor Hallways, Stairwells - 2004 Addition | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 53    | Fire Doors                                    | 3                 | EA             | Stairwells - 2004 Addition                                   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 54    | 2'x4' Ceiling Tiles                           | 30,000            | SF             | Throughout - 2004 Addition                                   | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 55    | Drywall, Tape, and Compound                   | 500               | SF             | Columns - 2004 Addition                                      | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 56    | Fire Doors                                    | 6                 | EA             | Auditorium, Balcony, Projector Room - 1937 Building          | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 57    | 1'x1' Ceiling Tile with Grooves               | 3,000             | SF             | Auditorium and Auditorium Balcony - 1937 Building            | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 58    | Decorative Plaster Trim                       | 1,500             | SF             | Auditorium and   | ASSUMED       | SURFACE           | N       | NONE        | 0               |              | No                            | ACBM with the                      |               | LOW                   |

# Chicago Public Schools

School Jamieson School Unit 23931 Building ID 4180

Address 5650 N Mozart Street Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |   |                   |                | Auditorium Balcony - 1937 Building                               |               |                   |         |             |                 |              |                               | potential for damage               |               |                       |
| 59    | Pyrobar - NOT OBSERVED                                  | 900               | SF             | East Wall between Buildings - 1954 Addition                      | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 60    | 12"x12" Light Gray w/ White and Gray Streaks VFT        | 4,500             | SF             | Rooms 216, 215, 213, 211, 114, 112, 111 - 1954 Addition          | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 60M   | 12"x12" Light Gray w/ White and Gray Streaks VFT Mastic | 4,500             | SF             | Rooms 216, 215, 213, 211, 114, 112, 111 - 1954 Addition          | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 61    | Drywall System  | 2,400             | SF             | Gym Ceiling - 1937 Building                                      | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 62    | 12"x12" Black w/ White Specs VFT                        | 1,000             | SF             | 2nd Floor Corridor, Room 217A Vestibule and Ramp - 1937 Building | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 63    | 12"x12" Black w/ White Specks VFT Mastic                | 1,000             | SF             | 2nd Floor Corridor, Room 217A Vestibule and Ramp - 1937 Building | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 64    | 20"x20" Yellow w/ Streaks VFT                           | 100               | SF             | Room 210 - 1937 Building   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 65    | 20"x20" Yellow w/ Streaks VFT Mastic                    | 100               | SF             | Room 210 - 1937 Building   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 66    | 20"x20" Blue w/ Streaks VFT                             | 100               | SF             | Room 210 - 1937 Building   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 67    | 20"x20" Blue w/ Streaks VFT Mastic                      | 100               | SF             | Room 210 - 1937 Building   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 68    | 20"x20" Off White w/ Streaks VFT                        | 600               | SF             | Room 210 - 1937 Building   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 69    | 20"x20" Off White w/ Streaks VFT Mastic                 | 600               | SF             | Room 210 - 1937 Building   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 70    | 2'x2' Ceiling Tile                                      | 800               | SF             | Room 210 - 1937 Building   | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 71    | 12"x12" Black w/ White Specks VFT                       | 600               | SF             | 2nd Floor Corridor - 1954 Building                               | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 72    | 12"x12" Black w/ White Specks VFT Mastic                | 600               | SF             | 2nd Floor Corridor - 1954 Building                               | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 73    | Carpet Mastic   | 600               | SF             | Principal's Office - 1937 Building                               | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| C     | Boiler Rope #1 - NOT OBSERVED                           | 12                | LF             | Boiler Room - 1937 Building                                      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| CC    | MJP E/F/V on Aircell Pipe Insulation                    | 40                | EA             | Unexcavated Area -   | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the                      |               | LOW                   |



# Chicago Public Schools

School Jamieson School Unit 23931 Building ID 4180

Address 5650 N Mozart Street Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                    | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |   |                   |                | 1954 Building                                  |               |                   |         |             |                 |              |                               | potential for damage               |               |                       |
| D     | Boiler Rope #2 - NOT OBSERVED           | 12                | LF             | Boiler Room - 1937 Building                    | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| DD    | Cardboard Pipe Insulation               | 250               | LF             | Unexcavated Area - 1954 Building               | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| EE    | Aircell Pipe Insulation                 | 325               | LF             | Unexcavated Area - 1954 Building               | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| F     | Aircell Pipe Insulation                 | 150               | LF             | Boiler Room - 1937 Building                    | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| FF    | Wicking Pipe Wrap on Coils              | 40                | LF             | Coil Area - 1937 Building                      | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| GG    | MJP E/F/V on Fiberglass Pipe Insulation | 60                | EA             | Unexcavated Area - 1954 Building               | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| H     | MJP E/F/V on Cardboard Pipe Insulation  | 80                | EA             | Throughout (See Hatching Maps) - 1937 Building | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| HH    | MJP E/F/V on Cardboard Pipe Insulation  | 30                | EA             | Unexcavated Area - 1954 Building               | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| I     | MJP E/F/V on Aircell Pipe Insulation    | 110               | EA             | Throughout (See Hatching Maps) - 1937 Building | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| K     | Tank Insulation                         | 80                | SF             | Boiler Room & Store Room - 1937 Building       | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| R     | MJP E/F/V on Fiberglass Pipe Insulation | 40                | EA             | Boiler Room - 1937 Building                    | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| S     | Aircell Pipe Insulation                 | 1,200             | LF             | Throughout (See Hatching Maps) - 1937 Building | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| T     | Cardboard Pipe Insulation               | 900               | LF             | Throughout (See Hatching Maps) - 1937 Building | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| W     | Aircell Duct Insulation                 | 400               | SF             | Unexcavated Area - 1937 Building               | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| Z     | Boiler Gasket                           | 20                | LF             | Boiler Room - 1937 Building                    | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Jamieson School Unit 23931 Building ID 4180

Address 5650 N Mozart Street Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date **8/25/2022**  
Inspector Name **Ismael Hernandez**  
**100-19036** **5/15/2023**  
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 01         |                     |
| 03         |                     |
| 04         |                     |
| 06         |                     |
| 07         |                     |
| 09         |                     |
| 11         |                     |
| 12         |                     |
| 13         |                     |
| 15         |                     |
| 16         |                     |
| 17         |                     |
| 18         |                     |
| 19         |                     |
| 21         |                     |
| 22         |                     |
| 23         |                     |
| 24         |                     |
| 25         |                     |
| 26         |                     |
| 28         |                     |
| 29         |                     |
| 30         |                     |
| 31         |                     |

# Chicago Public Schools

School Jamieson School Unit 23931 Building ID 4180

Address 5650 N Mozart Street Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 32         |                     |
| 34         |                     |
| 35         |                     |
| 36         |                     |
| 37         |                     |
| 38         |                     |
| 39         |                     |
| 40         |                     |
| 41         |                     |
| 42         |                     |
| 43         |                     |
| 44         |                     |
| 45         |                     |
| 46         |                     |
| 46A        |                     |
| 47         |                     |
| 48         |                     |
| 49         |                     |
| 50         |                     |
| 51         |                     |
| 52         |                     |
| 53         |                     |
| 54         |                     |
| 55         |                     |
| 56         |                     |
| 57         |                     |
| 58         |                     |
| 59         |                     |
| 60         |                     |

# Chicago Public Schools

School Jamieson School Unit 23931 Building ID 4180

Address 5650 N Mozart Street Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 60M        |                     |
| 61         |                     |
| 62         |                     |
| 63         |                     |
| 64         |                     |
| 65         |                     |
| 66         |                     |
| 67         |                     |
| 68         |                     |
| 69         |                     |
| 70         |                     |
| 71         |                     |
| 72         |                     |
| 73         |                     |
| C          |                     |
| CC         |                     |
| D          |                     |
| DD         |                     |
| EE         |                     |
| F          | 50 If removed       |
| FF         |                     |
| GG         |                     |
| H          |                     |
| HH         |                     |
| I          |                     |
| K          |                     |
| R          |                     |
| S          |                     |
| T          |                     |

# Chicago Public Schools

**School** Jamieson School **Unit** 23931 **Building ID** 4180

**Address** 5650 N Mozart Street **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| W          |                     |
| Z          |                     |

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Jamieson School  
**Address** 5650 N Mozart Street

**Unit** 23931  
Chicago, IL, 60659

**Building ID** 4180  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description                                     | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 01     | 9"x9" Red VFT  | 2,100             | SF             | 2nd & 3rd Floor Hall - 1937 Building                           | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 03     | Brown Linoleum   | 500               | SF             | Room 307 - 1937 Building                                       | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 04     | 9"x9" Red VFT Mastic                                     | 1,490             | SF             | 2nd & 3rd Floor Hall - 1937 Building                           | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 06     | Brown Linoleum Mastic                                    | 500               | SF             | Room 307 - 1937 Building                                       | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 07     | 12"x12" Gray w/ Pink, White, & Black Streaks VFT         | 2,500             | SF             | 1st & 2nd Floor Hall - 1954 Building                           | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 09     | 12"x12" Gray w/ Pink, White & Black Streaks VFT Mastic   | 2,500             | SF             | 1st & 2nd Floor Hall - 1954 Building                           | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 11     | 12"x12" Beige w/ White & Black Streaks VFT               | 4,000             | SF             | Rooms 112, 114, 116, 216, & 212 - 1954 Building - NOT OBSERVED | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 12     | 12"x12" Gray w/ White Streaks VFT                        | 2,400             | SF             | Rooms 111, 213, & 211 - 1954 Building - NOT OBSERVED           | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 13     | 12"x12" Green w/ White Streaks VFT                       | 1,200             | SF             | Room 215 - 1954 Building                                       | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 15     | 12"x12" Light Brown w/ White & Brown Streaks VFT         | 2,430             | SF             | Rooms 305, & 1st Floor Hall - 1937 Building                    | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 16     | 9"x9" Black VFT  | 1,490             | SF             | 2nd & 3rd Floor Halls - 1937 Building                          | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 17     | 6"x18" Black VFT   | 400               | SF             | 2nd & 3rd Floor Halls - 1937 Building                          | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18     | 12"x12" Beige w/ White Spots VFT                         | 750               | SF             | Lunchroom - 1937 Building                                      | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 19     | 9"x9" Gray VFT   | 300               | SF             | Main Office (Under HA # 46) - 1937 Building                    | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 21     | Tan Linoleum   | 1,500             | SF             | Room 115 (Under Carpet) - 1954 Building                        | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 22     | 12"x12" Beige w/ White & Black Streaks VFT Mastic        | 4,500             | SF             | Rooms 112, 114, 116, 214, & 212 - 1954 Building                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 23     | 9"x9" Beige w/ Black Streaks VFT                         | 235               | SF             | Engineer's Office & Bathroom - 1937 Building                   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 24     | 9"x9" Beige w/ Black Streaks VFT Mastic                  | 235               | SF             | Engineer's Office & Bathroom - 1937 Building                   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 25     | 12"x12" Gray w/ White Streaks VFT Mastic                 | 800               | SF             | Room 111 - 1954 Building                                       | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 26     | 12"x12" Green w/ White Streaks VFT Mastic - NOT OBSERVED | 1,200             | SF             | Room 215 - 1954 Building - NOT OBSERVED                        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 28     | 12"x12" Light Brown w/ White & Brown Streaks VFT Mastic  | 2,430             | SF             | Room 305, & 1st Floor Hall - 1937 Building                     | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 29     | 9"x9" Black VFT Mastic                                   | 1,490             | SF             | 2nd & 3rd Floor Halls - 1937 Building                          | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 30     | 6"x18" Black VFT Mastic                                  | 1,490             | SF             | 2nd & 3rd Floor Halls - 1937 Building                          | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 31     | 12"x12" Beige w/ White Spots VFT Mastic                  | 750               | SF             | Lunchroom - 1937 Building                                      | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 32     | 9"x9" Gray VFT Mastic                                    | 300               | SF             | Main Office (Under HA # 46) - 1937 Building                    | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Jamieson School  
**Address** 5650 N Mozart Street

**Unit** 23931  
 Chicago, IL, 60659

**Building ID** 4180  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description                                 | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|        |  |                   |                | Building   |               |                   |         |                 |              |                                      |                 |
| 34     | Tan Linoleum Mastic                                  | 800               | SF             | Room 115 (under carpet) - 1954 Building                      | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 35     | 12"x12" White w/ Beige Spots VFT                     | 5,000             | SF             | Throughout - 1999 Modular (No Longer on Site)                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 36     | 12"x12" White w/ Beige Spots VFT Mastic              | 5,000             | SF             | Throughout - 1999 Modular (No Longer on Site)                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 37     | 2' x 2' White w/ Grooves Ceiling Tile                | 5,000             | SF             | Throughout - 1999 Modular (No Longer on Site)                | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 38     | 12"x12" Blue VFT                                     | 2,200             | SF             | Auditorium - 1937 Building                                   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 39     | 12"x12" Blue VFT Mastic                              | 2,200             | SF             | Auditorium - 1937 Building                                   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 40     | 12"x12" Light Gray w/ Gray Specks VFT - NOT OBSERVED | 800               | SF             | Room 211 - 1954 Building - NOT OBSERVED                      | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 41     | 12"x12" Light Gray w/ Gray Specks VFT Mastic         | 800               | SF             | Room 211 - 1954 Building - NOT OBSERVED                      | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 42     | 12"x12" Light Blue w/ White Specks VFT               | 800               | SF             | Basement Teacher's Lounge                                    | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 43     | 12"x12" Light Blue w/ White Specks VFT Mastic        | 800               | SF             | Basement Teacher's Lounge                                    | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 44     | Carpet Mastic  | 2,100             | SF             | Rooms 214, 113, and 115 - 1954 Building                      | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 45     | Terrazzo   | 500               | SF             | Stairs - 1954 Building                                       | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 46     | 12"x12" Blue Streaked VFT                            | 800               | SF             | Main Office - 1937 Building                                  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 46A    | 12"x12" Blue Streaked VFT Mastic                     | 800               | SF             | Main Office - 1937 Building                                  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 47     | Decorative Plaster                                   | 500               | SF             | Auditorium - 1937 Building                                   | Assumed       | SURFACE           | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 48     | 2'x4' Ceiling Tiles                                  | 0                 | SF             | Gym - 1937 Building  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 49     | Fire Doors   | 2                 | EA             | Mechanical Room - 1999 Mobile (No Longer on Site)            | Assumed       | MISC              | No      | 0               | EA           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 50     | Textured Ceiling Paint                               | 300               | SF             | Restrooms - 1999 Mobile (No Longer on Site)                  | Assumed       | SURFACE           | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 51     | Vinyl Baseboard Mastic                               | 600               | LF             | Throughout - 1999 Mobile (No Longer on Site)                 | Assumed       | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 52     | Terrazzo   | 12,000            | SF             | 1st, 2nd, and 3rd Floor Hallways, Stairwells - 2004 Addition | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 53     | Fire Doors   | 3                 | EA             | Stairwells - 2004 Addition                                   | Assumed       | MISC              | No      | 0               | EA           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 54     | 2'x4' Ceiling Tiles                                  | 30,000            | SF             | Throughout - 2004 Addition                                   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 55     | Drywall, Tape, and Compound                          | 500               | SF             | Columns - 2004 Addition                                      | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 56     | Fire Doors   | 6                 | EA             | Auditorium, Balcony, Projector Room -                        | Assumed       | MISC              | No      | 0               | EA           | 6 ACBM with the potential for damage | Follow O&M Plan |



# Chicago Public Schools

**School** Jamieson School  
**Address** 5650 N Mozart Street

**Unit** 23931  
Chicago, IL, 60659

**Building ID** 4180  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description                                    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|        |   |                   |                | 1937 Building  |               |                   |         |                 |              |                                      |                 |
| 57     | 1'x1' Ceiling Tile with Grooves                         | 3,000             | SF             | Auditorium and Auditorium Balcony - 1937 Building                | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 58     | Decorative Plaster Trim                                 | 1,500             | SF             | Auditorium and Auditorium Balcony - 1937 Building                | Assumed       | SURFACE           | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 59     | Pyrobar - NOT OBSERVED                                  | 900               | SF             | East Wall between Buildings - 1954 Addition                      | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 60     | 12"x12" Light Gray w/ White and Gray Streaks VFT        | 4,500             | SF             | Rooms 216, 215, 213, 211, 114, 112, 111 - 1954 Addition          | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 60M    | 12"x12" Light Gray w/ White and Gray Streaks VFT Mastic | 4,500             | SF             | Rooms 216, 215, 213, 211, 114, 112, 111 - 1954 Addition          | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 61     | Drywall System  | 2,400             | SF             | Gym Ceiling - 1937 Building                                      | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 62     | 12"x12" Black w/ White Specs VFT                        | 1,000             | SF             | 2nd Floor Corridor, Room 217A Vestibule and Ramp - 1937 Building | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 63     | 12"x12" Black w/ White Specks VFT Mastic                | 1,000             | SF             | 2nd Floor Corridor, Room 217A Vestibule and Ramp - 1937 Building | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 64     | 20"x20" Yellow w/ Streaks VFT                           | 100               | SF             | Room 210 - 1937 Building   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 65     | 20"x20" Yellow w/ Streaks VFT Mastic                    | 100               | SF             | Room 210 - 1937 Building   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 66     | 20"x20" Blue w/ Streaks VFT                             | 100               | SF             | Room 210 - 1937 Building   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 67     | 20"x20" Blue w/ Streaks VFT Mastic                      | 100               | SF             | Room 210 - 1937 Building   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 68     | 20"x20" Off White w/ Streaks VFT                        | 600               | SF             | Room 210 - 1937 Building   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 69     | 20"x20" Off White w/ Streaks VFT Mastic                 | 600               | SF             | Room 210 - 1937 Building   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 70     | 2'x2' Ceiling Tile                                      | 800               | SF             | Room 210 - 1937 Building   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 71     | 12"x12" Black w/ White Specks VFT                       | 600               | SF             | 2nd Floor Corridor - 1954 Building                               | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 72     | 12"x12" Black w/ White Specks VFT Mastic                | 600               | SF             | 2nd Floor Corridor - 1954 Building                               | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 73     | Carpet Mastic   | 600               | SF             | Principal's Office - 1937 Building                               | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| C      | Boiler Rope #1 - NOT OBSERVED                           | 12                | LF             | Boiler Room - 1937 Building                                      | Chrysotile    | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| CC     | MJP E/F/V on Aircell Pipe Insulation                    | 40                | EA             | Unexcavated Area - 1954 Building                                 | Chrysotile    | TSI               | Yes     | 0               | EA           | 6 ACBM with the potential for damage | Follow O&M Plan |
| D      | Boiler Rope #2 - NOT OBSERVED                           | 12                | LF             | Boiler Room - 1937 Building                                      | Chrysotile    | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| DD     | Cardboard Pipe Insulation                               | 250               | LF             | Unexcavated Area - 1954 Building                                 | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| EE     | Aircell Pipe Insulation                                 | 325               | LF             | Unexcavated Area - 1954 Building                                 | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| F      | Aircell Pipe Insulation                                 | 150               | LF             | Boiler Room - 1937 Building                                      | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| FF     | Wicking Pipe Wrap on Coils                              | 40                | LF             | Coil Area - 1937 Building  | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| GG     | MJP E/F/V on Fiberglass Pipe Insulation                 | 60                | EA             | Unexcavated Area - 1954 Building                                 | Chrysotile    | TSI               | Yes     | 0               | EA           | 6 ACBM with the potential for damage | Follow O&M Plan |
| H      | MJP E/F/V on Cardboard Pipe Insulation                  | 80                | EA             | Throughout (See Hatching Maps) -                                 | Chrysotile    | TSI               | Yes     | 0               | EA           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Jamieson School  
**Address** 5650 N Mozart Street

**Unit** 23931  
 Chicago, IL, 60659

**Building ID** 4180  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description                    | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|        |   |                   |                | 1937 Building                                  |               |                   |         |                 |              |                                      |                 |
| HH     | MJP E/F/V on Cardboard Pipe Insulation  | 30                | EA             | Unexcavated Area - 1954 Building               | Chrysotile    | TSI               | Yes     | 0               | EA           | 6 ACBM with the potential for damage | Follow O&M Plan |
| I      | MJP E/F/V on Aircell Pipe Insulation    | 110               | EA             | Throughout (See Hatching Maps) - 1937 Building | Chrysotile    | TSI               | Yes     | 0               | EA           | 6 ACBM with the potential for damage | Follow O&M Plan |
| K      | Tank Insulation                         | 80                | SF             | Boiler Room & Store Room - 1937 Building       | Chrysotile    | TSI               | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| R      | MJP E/F/V on Fiberglass Pipe Insulation | 40                | EA             | Boiler Room - 1937 Building                    | Chrysotile    | TSI               | Yes     | 0               | EA           | 6 ACBM with the potential for damage | Follow O&M Plan |
| S      | Aircell Pipe Insulation                 | 1,200             | LF             | Throughout (See Hatching Maps) - 1937 Building | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| T      | Cardboard Pipe Insulation               | 900               | LF             | Throughout (See Hatching Maps) - 1937 Building | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| W      | Aircell Duct Insulation                 | 400               | SF             | Unexcavated Area - 1937 Building               | Chrysotile    | TSI               | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| Z      | Boiler Gasket                           | 20                | LF             | Boiler Room - 1937 Building                    | Assumed       | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Jamieson School  
**Address** 5650 N Mozart Street

**Unit** 23931  
 Chicago, IL, 60659

**Building ID** 4180  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

|                                    |              |
|------------------------------------|--------------|
| Review Date                        | 9/16/2022    |
| Manager Planner Name               | Arturo Saenz |
| 100-04019                          | 5/15/2023    |
| Manager IDPH License No/Expiration |              |

| HA Number | Management Comments |
|-----------|---------------------|
| 01        |                     |
| 03        |                     |
| 04        |                     |
| 06        |                     |
| 07        |                     |
| 09        |                     |
| 11        |                     |
| 12        |                     |
| 13        |                     |
| 15        |                     |
| 16        |                     |
| 17        |                     |
| 18        |                     |
| 19        |                     |
| 21        |                     |
| 22        |                     |
| 23        |                     |
| 24        |                     |
| 25        |                     |
| 26        |                     |
| 28        |                     |
| 29        |                     |
| 30        |                     |
| 31        |                     |

# Chicago Public Schools

**School** Jamieson School  
**Address** 5650 N Mozart Street

**Unit** 23931  
Chicago, IL, 60659

**Building ID** 4180  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 32        |                     |
| 34        |                     |
| 35        |                     |
| 36        |                     |
| 37        |                     |
| 38        |                     |
| 39        |                     |
| 40        |                     |
| 41        |                     |
| 42        |                     |
| 43        |                     |
| 44        |                     |
| 45        |                     |
| 46        |                     |
| 46A       |                     |
| 47        |                     |
| 48        |                     |
| 49        |                     |
| 50        |                     |
| 51        |                     |
| 52        |                     |
| 53        |                     |
| 54        |                     |
| 55        |                     |
| 56        |                     |
| 57        |                     |
| 58        |                     |

# Chicago Public Schools

**School** Jamieson School  
**Address** 5650 N Mozart Street

**Unit** 23931  
 Chicago, IL, 60659

**Building ID** 4180  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 59        |                     |
| 60        |                     |
| 60M       |                     |
| 61        |                     |
| 62        |                     |
| 63        |                     |
| 64        |                     |
| 65        |                     |
| 66        |                     |
| 67        |                     |
| 68        |                     |
| 69        |                     |
| 70        |                     |
| 71        |                     |
| 72        |                     |
| 73        |                     |
| C         |                     |
| CC        |                     |
| D         |                     |
| DD        |                     |
| EE        |                     |
| F         |                     |
| FF        |                     |
| GG        |                     |
| H         |                     |
| HH        |                     |
| I         |                     |

# Chicago Public Schools

**School** Jamieson School  
**Address** 5650 N Mozart Street

**Unit** 23931  
Chicago, IL, 60659

**Building ID** 4180  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| K         |                     |
| R         |                     |
| S         |                     |
| T         |                     |
| W         |                     |
| Z         |                     |

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

Specialty Consulting, Inc.  
*2022 AHERA REINSPECTION*



# Chicago Public Schools

Specialty Consulting, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **9"x9" Red VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd & 3rd Floor Hall - 1937 Building**

MATERIAL QUANTITY: **2100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **08/25/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **9"x9" Red VFT**  
MATERIAL LOCATION: **2nd & 3rd Floor Hall - 1937 Building**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 307 - 1937 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
MATERIAL LOCATION: **Room 307 - 1937 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **9"x9" Red VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Hall - 1937 Building**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **9"x9" Red VFT Mastic**  
MATERIAL LOCATION: **2nd & 3rd Floor Hall - 1937 Building**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 307 - 1937 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**  
MATERIAL LOCATION: **Room 307 - 1937 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Pink, White, & Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Hall - 1954 Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Pink, White, & Black Streaks VFT**  
MATERIAL LOCATION: **1st & 2nd Floor Hall - 1954 Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Pink, White & Black Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Hall - 1954 Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Pink, White & Black Streaks VFT Mastic**  
MATERIAL LOCATION: **1st & 2nd Floor Hall - 1954 Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White & Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 112, 114, 116, 216, & 212 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White & Black Streaks VFT**  
MATERIAL LOCATION: **Rooms 112, 114, 116, 216, & 212 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 111, 213, & 211 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks VFT**  
MATERIAL LOCATION: **Rooms 111, 213, & 211 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 215 - 1954 Building**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 215 - 1954 Building**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White & Brown Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 305, & 1st Floor Hall - 1937 Building**  
MATERIAL QUANTITY: **2430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White & Brown Streaks VFT**  
MATERIAL LOCATION: **Rooms 305, & 1st Floor Hall - 1937 Building**  
MATERIAL QUANTITY: **2430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9"x9" Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls - 1937 Building**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9"x9" Black VFT**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls - 1937 Building**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **6"x18" Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls - 1937 Building**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **6"x18" Black VFT**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls - 1937 Building**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White Spots VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom - 1937 Building**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White Spots VFT**  
MATERIAL LOCATION: **Lunchroom - 1937 Building**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office (Under HA # 46) - 1937 Building**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT**  
MATERIAL LOCATION: **Main Office (Under HA # 46) - 1937 Building**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 115 (Under Carpet) - 1954 Building**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
MATERIAL LOCATION: **Room 115 (Under Carpet) - 1954 Building**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White & Black Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 112, 114, 116, 214, & 212 - 1954 Building**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White & Black Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 112, 114, 116, 214, & 212 - 1954 Building**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **9"x9" Beige w/ Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Engineer's Office & Bathroom - 1937 Building**

MATERIAL QUANTITY: **235** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **9"x9" Beige w/ Black Streaks VFT**  
MATERIAL LOCATION: **Engineer's Office & Bathroom - 1937 Building**  
MATERIAL QUANTITY: **235** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **9"x9" Beige w/ Black Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Engineer's Office & Bathroom - 1937 Building**

MATERIAL QUANTITY: **235** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **9"x9" Beige w/ Black Streaks VFT Mastic**  
MATERIAL LOCATION: **Engineer's Office & Bathroom - 1937 Building**  
MATERIAL QUANTITY: **235** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 111 - 1954 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 111 - 1954 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks VFT Mastic - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**  
MATERIAL LOCATION: **Room 215 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks VFT Mastic - NOT OBSERVED**  
MATERIAL LOCATION: **Room 215 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White & Brown Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 305, & 1st Floor Hall - 1937 Building**  
MATERIAL QUANTITY: **2430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White & Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 305, & 1st Floor Hall - 1937 Building**  
MATERIAL QUANTITY: **2430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls - 1937 Building**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls - 1937 Building**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **6"x18" Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls - 1937 Building**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **6"x18" Black VFT Mastic**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls - 1937 Building**  
MATERIAL QUANTITY: **1490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White Spots VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom - 1937 Building**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White Spots VFT Mastic**  
MATERIAL LOCATION: **Lunchroom - 1937 Building**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office (Under HA # 46) - 1937 Building**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**  
MATERIAL LOCATION: **Main Office (Under HA # 46) - 1937 Building**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 115 (under carpet) - 1954 Building**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
MATERIAL LOCATION: **Room 115 (under carpet) - 1954 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Spots VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 1999 Modular (No Longer on Site)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Spots VFT**  
MATERIAL LOCATION: **Throughout - 1999 Modular (No Longer on Site)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Spots VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 1999 Modular (No Longer on Site)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Spots VFT Mastic**  
MATERIAL LOCATION: **Throughout - 1999 Modular (No Longer on Site)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **2' x 2' White w/ Grooves Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 1999 Modular (No Longer on Site)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **2' x 2' White w/ Grooves Ceiling Tile**  
MATERIAL LOCATION: **Throughout - 1999 Modular (No Longer on Site)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12"x12" Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium - 1937 Building**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12"x12" Blue VFT**  
MATERIAL LOCATION: **Auditorium - 1937 Building**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium - 1937 Building**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic**  
MATERIAL LOCATION: **Auditorium - 1937 Building**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Specks VFT - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 211 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Specks VFT - NOT OBSERVED**  
MATERIAL LOCATION: **Room 211 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 211 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Room 211 - 1954 Building - NOT OBSERVED**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Teacher's Lounge**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Specks VFT**  
MATERIAL LOCATION: **Basement Teacher's Lounge**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Teacher's Lounge**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Basement Teacher's Lounge**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 214, 113, and 115 - 1954 Building**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Rooms 214, 113, and 115 - 1954 Building**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairs - 1954 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Stairs - 1954 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12"x12" Blue Streaked VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office - 1937 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12"x12" Blue Streaked VFT**  
MATERIAL LOCATION: **Main Office - 1937 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46A**  
MATERIAL DESCRIPTION: **12"x12" Blue Streaked VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office - 1937 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **46A**  
MATERIAL DESCRIPTION: **12"x12" Blue Streaked VFT Mastic**  
MATERIAL LOCATION: **Main Office - 1937 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium - 1937 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
MATERIAL LOCATION: **Auditorium - 1937 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym - 1937 Building**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tiles**  
MATERIAL LOCATION: **Gym - 1937 Building**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mechanical Room - 1999 Mobile (No Longer on Site)**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **Mechanical Room - 1999 Mobile (No Longer on Site)**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Textured Ceiling Paint**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Restrooms - 1999 Mobile (No Longer on Site)**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Textured Ceiling Paint**  
MATERIAL LOCATION: **Restrooms - 1999 Mobile (No Longer on Site)**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Throughout - 1999 Mobile (No Longer on Site)**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Throughout - 1999 Mobile (No Longer on Site)**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Hallways, Stairwells - 2004 Addition**  
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Hallways, Stairwells - 2004 Addition**  
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwells - 2004 Addition**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **Stairwells - 2004 Addition**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 2004 Addition**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tiles**  
MATERIAL LOCATION: **Throughout - 2004 Addition**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Drywall, Tape, and Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Columns - 2004 Addition**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Drywall, Tape, and Compound**  
MATERIAL LOCATION: **Columns - 2004 Addition**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, Balcony, Projector Room - 1937 Building**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **Auditorium, Balcony, Projector Room - 1937 Building**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile with Grooves**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium and Auditorium Balcony - 1937 Building**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile with Grooves**  
MATERIAL LOCATION: **Auditorium and Auditorium Balcony - 1937 Building**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Decorative Plaster Trim**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium and Auditorium Balcony - 1937 Building**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Decorative Plaster Trim**  
MATERIAL LOCATION: **Auditorium and Auditorium Balcony - 1937 Building**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Pyrobar - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **East Wall between Buildings - 1954 Addition**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **08/25/2022**

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Pyrobar - NOT OBSERVED**  
MATERIAL LOCATION: **East Wall between Buildings - 1954 Addition**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ White and Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 216, 215, 213, 211, 114, 112, 111 - 1954 Addition**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ White and Gray Streaks VFT**  
MATERIAL LOCATION: **Rooms 216, 215, 213, 211, 114, 112, 111 - 1954 Addition**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60M**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ White and Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 216, 215, 213, 211, 114, 112, 111 - 1954 Addition**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **60M**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ White and Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 216, 215, 213, 211, 114, 112, 111 - 1954 Addition**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Drywall System**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Ceiling - 1937 Building**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **Gym Ceiling - 1937 Building**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specs VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Corridor, Room 217A Vestibule and Ramp - 1937 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specs VFT**  
MATERIAL LOCATION: **2nd Floor Corridor, Room 217A Vestibule and Ramp - 1937 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Corridor, Room 217A Vestibule and Ramp - 1937 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **2nd Floor Corridor, Room 217A Vestibule and Ramp - 1937 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**  
MATERIAL LOCATION: **Room 210 - 1937 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Corridor - 1954 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT**  
MATERIAL LOCATION: **2nd Floor Corridor - 1954 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Corridor - 1954 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **2nd Floor Corridor - 1954 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office - 1937 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Principal's Office - 1937 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Boiler Rope #1 - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1937 Building**  
MATERIAL QUANTITY: **12** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Boiler Rope #1 - NOT OBSERVED**  
MATERIAL LOCATION: **Boiler Room - 1937 Building**  
MATERIAL QUANTITY: **12** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CC**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Unexcavated Area - 1954 Building**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **CC**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Area - 1954 Building**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Boiler Rope #2 - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room - 1937 Building**

MATERIAL QUANTITY: **12**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Boiler Rope #2 - NOT OBSERVED**  
MATERIAL LOCATION: **Boiler Room - 1937 Building**  
MATERIAL QUANTITY: **12** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Unexcavated Area - 1954 Building**

MATERIAL QUANTITY: **250**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Area - 1954 Building**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EE**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unexcavated Area - 1954 Building**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **EE**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Area - 1954 Building**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1937 Building**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS: **50 lf removed**

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room - 1937 Building**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FF**  
MATERIAL DESCRIPTION: **Wicking Pipe Wrap on Coils**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Coil Area - 1937 Building**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUILDING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **FF**  
MATERIAL DESCRIPTION: **Wicking Pipe Wrap on Coils**  
MATERIAL LOCATION: **Coil Area - 1937 Building**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **GG**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unexcavated Area - 1954 Building**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **GG**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Area - 1954 Building**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1937 Building**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1937 Building**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HH**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unexcavated Area - 1954 Building**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **HH**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Area - 1954 Building**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1937 Building**  
MATERIAL QUANTITY: **110** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1937 Building**  
MATERIAL QUANTITY: **110** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room & Store Room - 1937 Building**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Boiler Room & Store Room - 1937 Building**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1937 Building**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room - 1937 Building**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1937 Building**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1937 Building**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1937 Building**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1937 Building**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unexcavated Area - 1937 Building**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
MATERIAL LOCATION: **Unexcavated Area - 1937 Building**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**

# Chicago Public Schools

Specialty Consulting, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**  
SCHOOL NAME: **Jamieson School** INSPECTION DATE: **8/25/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1937 Building**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 08/25/2022

# Chicago Public Schools

## Specialty Consulting, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23931** BUIDLING ID: **4180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Jamieson School** REVIEW DATE: **9/16/2022**  
ADDRESS: **5650 N Mozart Street** IDPH LICENSE NO: **100-19036**

---

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
MATERIAL LOCATION: **Boiler Room - 1937 Building**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **09/16/2022**



# Chicago Public Schools

Specialty Consulting, Inc.  
*2022 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ISMAEL HERNANDEZ  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/15/2022

Course Dates:

01/15/2023

Expires:

2201BIR12

Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Peneff". The signature is written in a cursive style and is placed over a light-colored rectangular background.

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
**100 - 19036**

ISSUED  
**2/28/2022**

EXPIRES  
**05/15/2023**

**ISMAEL HERNANDEZ**  
2942 W VAN BUREN ST, STE 2  
CHICAGO, IL 60612  
Environmental Health



**ISMAEL HERNANDEZ**  
2942 W VAN BUREN ST, STE 200  
CHICAGO, IL 60612

2/28/2022



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 19036

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

|  |                                    |  |  |   |
|--|------------------------------------|--|--|---|
|  <p><b>ASBESTOS<br/>PROFESSIONAL<br/>LICENSE</b></p>                |                                    |  | <p><b>ENDORSEMENTS</b></p> <p>INSPECTOR</p> <p>PROJECT MANAGER</p> <p>AIR SAMPLING PROFESSIONAL</p> <p><b>Alteration of this license shall result in legal action</b><br/>This license Issued under authority of the State of Illinois<br/>Department of Public Health<br/>This license is valid only when accompanied by a valid<br/>training course certificate.</p> | <p><b>TC EXPIRES</b></p> <p>1/15/2023</p> <p>2/6/2022</p> |
| <p>ID NUMBER<br/><b>100 - 19036</b></p> <p><b>ISMAEL HERNANDEZ</b><br/>2942 W VAN BUREN ST, STE 2<br/>CHICAGO, IL 60612<br/>Environmental Health</p> | <p>ISSUED<br/><b>2/28/2022</b></p> | <p>EXPIRES<br/><b>05/15/2023</b></p>  |  |   |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
Nationally Accredited by PHAB



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

A handwritten signature in cursive script that reads 'Kathy DeSalvo'.

Kathy DeSalvo, Director



# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

A handwritten signature in cursive script that reads 'Kathy DeSalvo'.

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois

**ARTURO SAENZ**  
 2942 W VAN BUREN ST  
 CHICAGO, IL 60612

2/28/2022



**ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER  
 100 - 04019

ISSUED  
 2/28/2022

EXPIRES  
 05/15/2023

ARTURO SAENZ  
 2942 W VAN BUREN ST  
 CHICAGO, IL 60612



Environmental Health

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

|   |                     |                       |   |                   |
|---|---------------------|-----------------------|---|-------------------|
| <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>   |                     |                       | <b>ENDORSEMENTS</b>   | <b>TC EXPIRES</b> |
| ID NUMBER<br>100 - 04019  | ISSUED<br>2/28/2022 | EXPIRES<br>05/15/2023 | INSPECTOR   | 11/1/2022         |
| <b>ARTURO SAENZ</b><br>2942 W VAN BUREN ST<br>CHICAGO, IL 60612<br>Environmental Health |                     |                       | MANAGEMENT PLANNER  | 11/1/2022         |
|   |                     |                       | <b>AIR SAMPLING PROFESSIONAL</b><br><b>Alteration of this license shall result in legal action</b><br>This license issued under authority of the State of Illinois<br>Department of Public Health<br>This license is valid only when accompanied by a valid<br>training course certificate. |                   |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH. IMPROVING LIVES**  
 Nationally Accredited by PHAB

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

|                          | <b>CODE</b> | <b>KEY</b>                             |
|--------------------------|-------------|--|
| <b>MATERIAL</b>          |             |  |
|                          | ACBM        | Asbestos Containing Building Materials |
| <b>MATERIAL CATEGORY</b> |             |  |
|                          | MISC        | Miscellaneous                          |
|                          | SURF        | Surfacing                              |
|                          | TSI         | Thermal System Insulation              |
| <b>MATERIAL UNITS</b>    |             |  |
|                          | LF          | Linear Feet                            |
|                          | SF          | Square Feet                            |
|                          | CF          | Cubic Feet                             |
| <b>DAMAGE TYPE</b>       |             |  |
|                          | Loc         | Localized                              |
|                          | Dist        | Distributed                            |