

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2292
SCHOOL NAME: Jungman School
ADDRESS OF SCHOOL: 1746 S. Miller
CITY: Chicago, IL, 60608

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/29/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 12/7/2022 ENROLLMENT 298
IDPH INSPECTOR LICENSE NUMBER: 100-07278
IDPH LICENSED INSPECTOR NAME (Please Print): Kenneth Karuhn
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



12/10/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Jungman School

1746 S. Miller
Chicago, IL, 60608

Unit: 23961
Building ID: 4230

IDPH ID Number: 14-016-2990-2292

REPORT DATE:

Saturday, December 10, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

12/10/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23961 Region: 03 IDPH ID: 14-016-2990-2292

School: Jungman School Building ID: 4230

Address: 1746 S. Miller

Chicago, IL, 60608

Building Contact: Guhr, Thomas

Contact Phone: 7734900569

Current Building Owners: Chicago Public Schools

Reinspection Date: 12/7/2022

Review Date: 12/10/2022

Inspector: Kenneth Karuhn

Inspector IDPH License: 100-07278

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: December 10, 2022

RE: Jungman School, Unit 23961
1746 S. Miller
Chicago, IL, 60608

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Jungman School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Jungman School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Jungman School Unit: 23961 Region: 03
Address: 1746 S. Miller Chicago, IL, 60608
IDPH ID: 14-016-2990-2292 Building ID: 4230
Contact: Guhr, Thomas Phone: 7734900569

2. Description of Facility

Original Construction: 1913 Additional Construction: 1902
Total Square Footage: 7750 No of Floors: 2
Current Occupancy: 298

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Kenneth Karuhn


Inspector IDPH license # 100-07278
Reinspection Date: 12/7/2022

Signature: 
Date: 12/7/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature: 
Date: 12/10/2022

7. Review Date: 12/10/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 12/10/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Jungman School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4230:

15	12" x 12" Brown Speckled Floor Tile
20	12" x 12" Light Tan Floor Tile w/ White Specks
22	9" x 9" Orange w/Red Floor Tile
26	12" x 12" Cream Colored Floor Tile
4	9" x 9" Green Floor Tile
5	9" x 9" Gray Floor Tile
55	12" x 12" Brown Speckles w/ White Specks Floor Tile
56	12" x 12" Brown Speckles w/ White Specks Floor Tile Mastic

67	Tan ceramic fl grout
69	12" x 12" Multi Spec Floor Tile
7	12" x 12" Tan Floor Tile
74	12" x 12" Light Green Mottled Floor Tile Mastic
75	12" x 12" Light Green Mottled Floor Tile
76	2' x 2' Ceiling Tile w/ pinholes
9	12" x 12" Brown Floor Tile
D	Cardboard pipe insulation

B. The following new homogenous areas have been identified for Building 4230:

- | | |
|----|---|
| 74 | 12" x 12" Light Green Mottled Floor Tile Mastic |
| 75 | 12" x 12" Light Green Mottled Floor Tile |
| 76 | 2' x 2' Ceiling Tile w/ pinholes |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

24	12" x 12" Brown Floor Tile w/Gray
36	Blue carpet mastic
37	Brown carpet mastic
38	Linoleum
39	Linoleum mastic
40	Insulation under incinerator shell
41	Fire Brick in Incinerator
42	Boiler gaskets
43	Drywall
44	Drywall tape
45	Drywall compound
46	4" Light brown vinyl baseboard
47	4" Pink vinyl baseboard adhesive
48	12" x 12" Green Self Stick Floor Tile
49	4" Green vinyl baseboard
50	4" Green vinyl baseboard adhesive
51	Green stage fire curtain
52	Beige stage fire curtain
53	4" Blue vinyl baseboard
54	4" Blue vinyl baseboard adhesive
55	12" x 12" Brown Speckles w/ White Specks Floor Tile
56	12" x 12" Brown Speckles w/ White Specks Floor Tile Mastic
57	12" x 12" Blue Speckled Floor Tile
58	12" x 12" Blue Speckled Floor Tile Mastic
59	New drywall - wall
60	New drywall - ceiling
61	New drywall - tape
62	New drywall - compound
63	Spray-on fire proofing
64	Terrazo flooring
66	Blue ceramic fl grout
67	Tan ceramic fl grout
68	Pink ceramic grout
69	12" x 12" Multi Spec Floor Tile
69M	12" x 12" Multi Spec Floor Tile Mastic
70	4" Blue vinyl baseboard
71	4" Blue vinyl baseboard adhesive
72	4" Gray vinyl baseboard
73	4" Gray vinyl baseboard adhesive
74	12" x 12" Light Green Mottled Floor Tile Mastic

75	12" x 12" Light Green Mottled Floor Tile
76	2' x 2' Ceiling Tile w/ pinholes
M	Boiler ins. Cloth jacketing

The following areas were deemed to be inaccessible:

10	12" x 12" Brown Floor Tile Mastic
11	9"x 9" green floor tile mastic
21	12" x 12" Light Tan Floor Tile w/ White Specks Mastic
23	9" x 9" Orange w/Red Floor Tile Mastic
27	12" x 12" Cream Colored Floor Tile Mastic
36	Blue carpet mastic
47	4" Pink vinyl baseboard adhesive
50	4" Green vinyl baseboard adhesive
54	4" Blue vinyl baseboard adhesive
56	12" x 12" Brown Speckles w/ White Specks Floor Tile Mastic
58	12" x 12" Blue Speckled Floor Tile Mastic
6	9" x 9" Gray Floor Tile Mastic
71	4" Blue vinyl baseboard adhesive
73	4" Gray vinyl baseboard adhesive
76	2' x 2' Ceiling Tile w/ pinholes
8	12" x 12" Tan Floor Tile Mastic
9	12" x 12" Brown Floor Tile

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Kenneth Karuhn, IDPH License # 100-07278. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Jungman School Building 4230 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Jungman School Unit 23961 Building ID 4230

Address 1746 S. Miller Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Ceiling plaster			Throughout Facility	NO_ACBM	SURFACE								
10	12" x 12" Brown Floor Tile Mastic	3,376	SF	Assembly Hall and Principal's Office/Room 204	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
11	9" x 9" green floor tile mastic	1,010	SF	Room 208	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
13	4" Black vinyl baseboard mastic			Kitchen and Teacher's Lunchroom, Room 006, Room 100A	NO_ACBM	MISC								
14	4" Black vinyl baseboards			Teacher's Lunchroom, Kitchen, Room 006, Room 100A	NO_ACBM	MISC								
15	12" x 12" Brown Speckled Floor Tile	1,000	SF	Room 302	CHR	MISC	N	LOC	20	SF	Yes	ACBM with the potential for damage	5	LOW
16	12" x 12" Brown Speckled Floor Tile Mastic		SF	Room 302	CHR	MISC				SF				
17	Poured asphalt			Hallways	NO_ACBM	MISC								
18	12" x 12" Brown Floor Tile w/ Gray Specks			Room 206	CHR	MISC								
19	12" x 12" Brown Floor Tile w/ Gray Specks. Mastic			Room 206	CHR	MISC								
2	2' x 4' Lay In Ceiling Panels			Classrooms	NO_ACBM	MISC								
20	12" x 12" Light Tan Floor Tile w/ White Specks	1,030	SF	Room 100, As Patch in Room 208	CHR	MISC	N	LOC	5	SF	Yes	ACBM with the potential for damage	5	LOW
21	12" x 12" Light Tan Floor Tile w/ White Specks Mastic	1,030	SF	Room 100, As Patch in Room 208	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22	9" x 9" Orange w/Red Floor Tile	1,000	SF	Room 101	CHR	MISC	N	LOC	4	SF	Yes	ACBM with the potential for damage	5	LOW
23	9" x 9" Orange w/Red Floor Tile Mastic	1,000	SF	Room 101	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
24	12" x 12" Brown Floor Tile w/Gray		SF	Room 102	ASSUMED	MISC				SF				
25	12" x 12" Brown Floor Tile w/Gray Mastic			Room 102	NO_ACBM	MISC								
26	12" x 12" Cream Colored Floor Tile	1,000	SF	Room 105	CHR	MISC	N	LOC	10	SF	Yes	ACBM with the potential for damage	5	LOW
27	12" x 12" Cream Colored Floor Tile Mastic	1,000	SF	Room 105	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
28	Exterior brick mortar			1902 Construction	NO_ACBM	MISC								
29	Exterior brick mortar			1913 Building	NO_ACBM	MISC								
3	Wall plaster			Basement Areas	NO_ACBM	SURFACE								
30	Exterior lime stone mortar			Building Exterior	NO_ACBM	MISC								
31	Gray floor tile		SF	Principle's Office (Underneath Carpet)	CHR	MISC				SF				

Chicago Public Schools

School Jungman School Unit 23961 Building ID 4230

Address 1746 S. Miller Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
32	Gray floor tile mastic		SF	Principle's Office (Underneath Carpet)	CHR	MISC				SF				
33	Exterior window sash caulk (Non-AHERA)			Throughout Building	CHR	MISC								
34	Roof flashing (Non-AHERA)			West Roof	CHR	MISC								
35	Roof decking			Exterior Roof	NO_ACBM	MISC								
36	Blue carpet mastic	200	SF	Principal's Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
37	Brown carpet mastic		SF	Professional Office Across From 012, Room 009A	ASSUMED	MISC				SF				
38	Linoleum			Professional Center	ASSUMED	MISC								
39	Linoleum mastic			Professional Center	ASSUMED	MISC								
4	9" x 9" Green Floor Tile	1,010	SF	Room 208	CHR	MISC	N	LOC	12	SF	Yes	ACBM with the potential for damage	5	LOW
40	Insulation under incinerator shell	200	SF	Boiler Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
41	Fire Brick in Incinerator	100	SF	Boiler Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
42	Boiler gaskets	50	LF	Boiler Room	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
43	Drywall	540	SF	Basement Northwest Side Near Room 005, Basement Girl's Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
44	Drywall tape	220	SF	Basement Northwest Side Near Room 005, Basement Girl's Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
45	Drywall compound	220	SF	Basement Northwest Side Near Room 005, Basement Girl's Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
46	4" Light brown vinyl baseboard	60	LF	Basement Girl's Bathroom	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
47	4" Pink vinyl baseboard adhesive	60	LF	Basement Girl's Bathroom	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
48	12" x 12" Green Self Stick Floor Tile	30	SF	Room 009A Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
49	4" Green vinyl baseboard	22	LF	Room 009A Bathroom	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
5	9" x 9" Gray Floor Tile	150	SF	Teacher's Lunch Room Between Rooms 206 and 208	CHR	MISC	N	LOC	5	SF	Yes	ACBM with the potential for damage	5	LOW

Chicago Public Schools

School Jungman School Unit 23961 Building ID 4230

Address 1746 S. Miller Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
50	4" Green vinyl baseboard adhesive	22	LF	Room 009A Bathroom	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
51	Green stage fire curtain	800	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
52	Beige stage fire curtain	800	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
53	4" Blue vinyl baseboard	60	LF	Basement Men's Bathroom	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
54	4" Blue vinyl baseboard adhesive	60	LF	Basement Men's Bathroom	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
55	12" x 12" Brown Speckles w/ White Specks Floor Tile	162	SF	Room 100A Bathroom, 1st Floor Women's Bathroom	ASSUMED	MISC	N	LOC	6	SF	Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
56	12" x 12" Brown Speckles w/ White Specks Floor Tile Mastic	162	SF	Room 100A Bathroom, 1st Floor Women's Bathroom	ASSUMED	MISC	N	LOC	6	SF	Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
57	12" x 12" Blue Speckled Floor Tile	276	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement, patch in 208	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
58	12" x 12" Blue Speckled Floor Tile Mastic	276	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
59	New drywall - wall	3,160	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement and Elecator Rooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
6	9" x 9" Gray Floor Tile Mastic	450	SF	Teacher's Lunch Room (Room 207) Between Rooms 206 and 208	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
60	New drywall - ceiling	1,200	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
61	New drywall - tape	300	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
62	New drywall - compound	300	SF	Elevator Area on 1st, 2nd, 3rd Floors	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Jungman School Unit 23961 Building ID 4230

Address 1746 S. Miller Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				and area between 1st Floor and Basement										
63	Spray-on fire proofing	160	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement and Elevator Room	ASSUMED	SURFACE	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
64	Terrazo flooring			2nd Floor Girl's Bathroom	ASSUMED	SURFACE								
66	Blue ceramic fl grout			Basement Boy's Bathroom	ASSUMED	MISC								
67	Tan ceramic fl grout	450	SF	Kitchen	ASSUMED	MISC	N	LOC	6	SF	Yes	ACBM with the potential for damage	5	LOW
68	Pink ceramic grout		SF	Basement Girl's Bathroom	ASSUMED	MISC				SF				
69	12" x 12" Multi Spec Floor Tile	200	SF	Room 102	ASSUMED	MISC	N	LOC	12	SF	Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
69M	12" x 12" Multi Spec Floor Tile Mastic		SF	Room 102	ASSUMED	MISC				SF				
7	12" x 12" Tan Floor Tile	5,000	SF	Kitchen Office, Rooms 102 and 2nd floor men's bathroom, patch in 208	CHR	MISC	N	LOC	20	SF	Yes	ACBM with the potential for damage	5	LOW
70	4" Blue vinyl baseboard	23	SF	2nd Floor Boy's Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
71	4" Blue vinyl baseboard adhesive	23	SF	2nd Floor Boy's Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
72	4" Gray vinyl baseboard	35	SF	2nd Floor Girl's Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
73	4" Gray vinyl baseboard adhesive	35	SF	2nd Floor Girl's Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
74	12" x 12" Light Green Mottled Floor Tile Mastic	30	SF	Room 208	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
75	12" x 12" Light Green Mottled Floor Tile	30	SF	Room 208	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
76	2' x 2' Ceiling Tile w/ pinholes	800	SF	Room 206	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
8	12" x 12" Tan Floor Tile Mastic	5,000	SF	Kitchen Office, Rooms 102 and 2nd floor men's bathroom, patch in 208	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
9	12" x 12" Brown Floor Tile	3,375	SF	Assembly Hall and	CHR	MISC	N	LOC	30	SF	Yes	ACBM with the	5	LOW

Chicago Public Schools

School Jungman School Unit 23961 Building ID 4230

Address 1746 S. Miller Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Principal's Office and Room 204								potential for damage		
A	Boiler #1 west insulation jacketing			Boiler Room	ABATED	TSI								
B	Boiler #2 east insulation jacketing			Boiler Room	ABATED	TSI								
C	Make up tank (sellers) insulation jacketing			Tank Room	NO_ACBM	TSI								
D	Cardboard pipe insulation	700	LF	Throughout Basement, Mechanical Room, Basement Halls, Boiler Room	CHR	TSI	Y	LOC	5	LF	Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
E	Cementitious Pipe Fittings off Cardboard Pipe Runs	175	FITTING	Throughout Basement, Mechanical Room, Basement Halls	CHR	TSI	Y	LOC	5	FITTING	No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
G	Cementitious Pipe Fitting on Old Fiberglass			Boiler Room	NO_ACBM	TSI								
H	Aircell pipe insulation		LF	Throughout Basement, Mechanical Rooms, Halls, 1st Floor Room 106 and 108	CHR	TSI				LF				
I	Cementitious Pipe Fittings on Aircell Pipe Runs	45	LF	Basement, Mechanical Rooms, Halls, and 1st Floor Rooms 106 and 108	CHR	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
J	Mag Block Pipe Insulation off Steam Line			Lunch Room	AMO	TSI								
K	Fire Brick from Boiler #1			Inside Boiler	NO_ACBM	MISC								
L	Mortar from fire brick			Boiler #1 Interior	NO_ACBM	MISC								
M	Boiler ins. Cloth jacketing	1,000	SF	Boiler Room	ASSUMED	TSI	Y	LOC	160	SF	No	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW

Chicago Public Schools

School Jungman School Unit 23961 Building ID 4230

Address 1746 S. Miller Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 12/7/2022
Inspector Name <u>Kenneth Karuhn</u>
100-07278 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
13	
14	
15	Damage in Room 302 20 SF missing or cracked, not observed
16	Not observed 2022
17	Not asphalt, concrete
18	Not observed 2022
19	Not observed 2022
2	
20	Damage in Room 100 5 ft crack
21	
22	Damage in Room 101 4 ft cracked
23	
24	Not observed 2022
25	
26	Damage in Room 105 3 ft cracked
27	
28	
29	
3	
30	
31	Not observed 2022

Chicago Public Schools

School Jungman School Unit 23961 Building ID 4230

Address 1746 S. Miller Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
32	Not observed 2022
33	
34	
35	
36	
37	Not observed 2022
38	Not observed 2022
39	Not observed 2022
4	Damage in Room 208 - 12 ft cracked
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	Damage in Room 207 5 ft cracked
50	
51	
52	
53	
54	
55	Damage in 1st floor woman's restroom 6 SF cracked, not observed
56	Damage in 1st floor woman's restroom 6 SF, not observed
57	
58	

Chicago Public Schools

School Jungman School Unit 23961 Building ID 4230

Address 1746 S. Miller Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
59	
6	
60	
61	
62	
63	
64	Not observed 2022
66	Not observed 2022
67	Kitchen tan ceramic grout. Both front room and back room have damage 6 ft cracked or loose tile
68	Not observed 2022
69	Damage in Room 102 -12 ft cracked
69M	Not observed 2022
7	Damage in 2nd floor men's room 20 ft cracked or missing
70	
71	
72	
73	
74	
75	
76	
8	
9	Damage in Auditorium 25 ft cracked; main office 5 ft cracked
A	
B	
C	
D	Damage in Boiler Room
E	Damage in Boiler room cement joint fittings top layer is cracking
G	

Chicago Public Schools

School Jungman School Unit 23961 Building ID 4230

Address 1746 S. Miller Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
H	Not observed 2022
I	
J	Not observed 2022
K	
L	
M	Damage in Boiler Room - Boiler 1 and boiler 2 cloth jacketing loose 160 sq ft. Abated? Boiler covered in fiberglass

Table II

Management Planner's Review

Chicago Public Schools

School Jungman School
Address 1746 S. Miller

Unit 23961
Chicago, IL, 60608

Building ID 4230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Ceiling plaster			Throughout Facility	No ACBM	SURFACE					
10	12" x 12" Brown Floor Tile Mastic	3,376	SF	Assembly Hall and Principal's Office/Room 204	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9"x 9" green floor tile mastic	1,010	SF	Room 208	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	4" Black vinyl baseboard mastic			Kitchen and Teacher's Lunchroom, Room 006, Room 100A	No ACBM	MISC					
14	4" Black vinyl baseboards			Teacher's Lunchroom, Kitchen, Room 006, Room 100A	No ACBM	MISC					
15	12" x 12" Brown Speckled Floor Tile	1,000	SF	Room 302	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
16	12" x 12" Brown Speckled Floor Tile Mastic		SF	Room 302	Chrysotile	MISC			SF		Follow O&M Plan
17	Poured asphalt			Hallways	No ACBM	MISC					
18	12" x 12" Brown Floor Tile w/ Gray Specks			Room 206	Chrysotile	MISC					Follow O&M Plan
19	12" x 12" Brown Floor Tile w/ Gray Specks. Mastic			Room 206	Chrysotile	MISC					Follow O&M Plan
2	2' x 4' Lay In Ceiling Panels			Classrooms	No ACBM	MISC					
20	12" x 12" Light Tan Floor Tile w/ White Specks	1,030	SF	Room 100, As Patch in Room 208	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Repair
21	12" x 12" Light Tan Floor Tile w/ White Specks Mastic	1,030	SF	Room 100, As Patch in Room 208	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	9" x 9" Orange w/Red Floor Tile	1,000	SF	Room 101	Chrysotile	MISC	No	4	SF	6 ACBM with the potential for damage	Repair
23	9" x 9" Orange w/Red Floor Tile Mastic	1,000	SF	Room 101	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" Brown Floor Tile w/Gray		SF	Room 102	Assumed	MISC			SF		Follow O&M Plan
25	12" x 12" Brown Floor Tile w/Gray Mastic			Room 102	No ACBM	MISC					
26	12" x 12" Cream Colored Floor Tile	1,000	SF	Room 105	Chrysotile	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
27	12" x 12" Cream Colored Floor Tile Mastic	1,000	SF	Room 105	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Exterior brick mortar			1902 Construction	No ACBM	MISC					
29	Exterior brick mortar			1913 Building	No ACBM	MISC					
3	Wall plaster			Basement Areas	No ACBM	SURFACE					
30	Exterior lime stone mortar			Building Exterior	No ACBM	MISC					
31	Gray floor tile		SF	Principle's Office (Underneath Carpet)	Chrysotile	MISC			SF		Follow O&M Plan
32	Gray floor tile mastic		SF	Principle's Office (Underneath Carpet)	Chrysotile	MISC			SF		Follow O&M Plan
33	Exterior window sash caulk (Non-AHERA)			Throughout Building	Chrysotile	MISC					Follow O&M Plan
34	Roof flashing (Non-AHERA)			West Roof	Chrysotile	MISC					Follow O&M Plan
35	Roof decking			Exterior Roof	No ACBM	MISC					
36	Blue carpet mastic	200	SF	Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Brown carpet mastic		SF	Professional Office Across From 012, Room 009A	Assumed	MISC			SF		Follow O&M Plan

Chicago Public Schools

School Jungman School

Unit 23961

Building ID 4230

Address 1746 S. Miller

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
38	Linoleum			Professional Center	Assumed	MISC					Follow O&M Plan
39	Linoleum mastic			Professional Center	Assumed	MISC					Follow O&M Plan
4	9" x 9" Green Floor Tile	1,010	SF	Room 208	Chrysotile	MISC	No	12	SF	6 ACBM with the potential for damage	Repair
40	Insulation under incinerator shell	200	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Fire Brick in Incinerator	100	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Boiler gaskets	50	LF	Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
43	Drywall	540	SF	Basement Northwest Side Near Room 005, Basement Girl's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Drywall tape	220	SF	Basement Northwest Side Near Room 005, Basement Girl's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Drywall compound	220	SF	Basement Northwest Side Near Room 005, Basement Girl's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	4" Light brown vinyl baseboard	60	LF	Basement Girl's Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
47	4" Pink vinyl baseboard adhesive	60	LF	Basement Girl's Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Green Self Stick Floor Tile	30	SF	Room 009A Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	4" Green vinyl baseboard	22	LF	Room 009A Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
5	9" x 9" Gray Floor Tile	150	SF	Teacher's Lunch Room Between Rooms 206 and 208	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Repair
50	4" Green vinyl baseboard adhesive	22	LF	Room 009A Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
51	Green stage fire curtain	800	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Beige stage fire curtain	800	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	4" Blue vinyl baseboard	60	LF	Basement Men's Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
54	4" Blue vinyl baseboard adhesive	60	LF	Basement Men's Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" Brown Speckles w/ White Specks Floor Tile	162	SF	Room 100A Bathroom, 1st Floor Women's Bathroom	Assumed	MISC	No	6	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
56	12" x 12" Brown Speckles w/ White Specks Floor Tile Mastic	162	SF	Room 100A Bathroom, 1st Floor Women's Bathroom	Assumed	MISC	No	6	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
57	12" x 12" Blue Speckled Floor Tile	276	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement, patch in 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12" x 12" Blue Speckled Floor Tile Mastic	276	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	New drywall - wall	3,160	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement and Elecator Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Jungman School

Unit 23961

Building ID 4230

Address 1746 S. Miller

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
6	9" x 9" Gray Floor Tile Mastic	450	SF	Teacher's Lunch Room (Room 207) Between Rooms 206 and 208	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	New drywall - ceiling	1,200	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	New drywall - tape	300	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	New drywall - compound	300	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Spray-on fire proofing	160	SF	Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement and Elevator Room	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
64	Terrazo flooring			2nd Floor Girl's Bathroom	Assumed	SURFACE					Follow O&M Plan
66	Blue ceramic fl grout			Basement Boy's Bathroom	Assumed	MISC					Follow O&M Plan
67	Tan ceramic fl grout	450	SF	Kitchen	Assumed	MISC	No	6	SF	6 ACBM with the potential for damage	Repair
68	Pink ceramic grout		SF	Basement Girl's Bathroom	Assumed	MISC			SF		Follow O&M Plan
69	12" x 12" Multi Spec Floor Tile	200	SF	Room 102	Assumed	MISC	No	12	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
69M	12" x 12" Multi Spec Floor Tile Mastic		SF	Room 102	Assumed	MISC			SF		Follow O&M Plan
7	12" x 12" Tan Floor Tile	5,000	SF	Kitchen Office, Rooms 102 and 2nd floor men's bathroom, patch in 208	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
70	4" Blue vinyl baseboard	23	SF	2nd Floor Boy's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	4" Blue vinyl baseboard adhesive	23	SF	2nd Floor Boy's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	4" Gray vinyl baseboard	35	SF	2nd Floor Girl's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	4" Gray vinyl baseboard adhesive	35	SF	2nd Floor Girl's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" x 12" Light Green Mottled Floor Tile Mastic	30	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12" x 12" Light Green Mottled Floor Tile	30	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	2' x 2' Ceiling Tile w/ pinholes	800	SF	Room 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	12" x 12" Tan Floor Tile Mastic	5,000	SF	Kitchen Office, Rooms 102 and 2nd floor men's bathroom, patch in 208	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	12" x 12" Brown Floor Tile	3,375	SF	Assembly Hall and Principal's Office and Room 204	Chrysotile	MISC	No	30	SF	6 ACBM with the potential for damage	Repair
A	Boiler #1 west insulation jacketing			Boiler Room	Abated	TSI					
B	Boiler #2 east insulation jacketing			Boiler Room	Abated	TSI					

Chicago Public Schools

School Jungman School
Address 1746 S. Miller

Unit 23961
 Chicago, IL, 60608

Building ID 4230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
C	Make up tank (sellers) insulation jacketing			Tank Room	No ACBM	TSI					
D	Cardboard pipe insulation	700	LF	Throughout Basement, Mechanical Room, Basement Halls, Boiler Room	Chrysotile	TSI	Yes	5	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
E	Cementitious Pipe Fittings off Cardboard Pipe Runs	175	FITTING	Throughout Basement, Mechanical Room, Basement Halls	Chrysotile	TSI	Yes	5	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
G	Cementitious Pipe Fitting on Old Fiberglass			Boiler Room	No ACBM	TSI					
H	Aircell pipe insulation		LF	Throughout Basement, Mechanical Rooms, Halls, 1st Floor Room 106 and 108	Chrysotile	TSI			LF		Follow O&M Plan
I	Cementitious Pipe Fittings on Aircell Pipe Runs	45	LF	Basement, Mechanical Rooms, Halls, and 1st Floor Rooms 106 and 108	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
J	Mag Block Pipe Insulation off Steam Line			Lunch Room	Amosite	TSI					Follow O&M Plan
K	Fire Brick from Boiler #1			Inside Boiler	No ACBM	MISC					
L	Mortar from fire brick			Boiler #1 Interior	No ACBM	MISC					
M	Boiler ins. Cloth jacketing	1,000	SF	Boiler Room	Assumed	TSI	Yes	160	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove

Chicago Public Schools

School Jungman School
Address 1746 S. Miller

Unit 23961
 Chicago, IL, 60608

Building ID 4230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	12/10/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	

Chicago Public Schools

School Jungman School
Address 1746 S. Miller

Unit 23961
Chicago, IL, 60608

Building ID 4230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	

Chicago Public Schools

School Jungman School
Address 1746 S. Miller

Unit 23961
 Chicago, IL, 60608

Building ID 4230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
66	
67	
68	
69	
69M	
7	
70	
71	
72	
73	
74	
75	
76	
8	
9	
A	

Chicago Public Schools

School Jungman School
Address 1746 S. Miller

Unit 23961
Chicago, IL, 60608

Building ID 4230
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
B	
C	
D	
E	
G	
H	
I	
J	
K	
L	
M	Sample to determine ACM content

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Ceiling plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Ceiling plaster**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall and Principal's Office/Room 204**
MATERIAL QUANTITY: **3376** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Assembly Hall and Principal's Office/Room 204**
MATERIAL QUANTITY: **3376** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x 9" green floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **1010** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9"x 9" green floor tile mastic**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **1010**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen and Teacher's Lunchroom, Room 006, Room 100A**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **4" Black vinyl baseboard mastic**

MATERIAL LOCATION: **Kitchen and Teacher's Lunchroom, Room 006, Room 100A**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **4" Black vinyl baseboards**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lunchroom, Kitchen, Room 006, Room 100A**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **4" Black vinyl baseboards**

MATERIAL LOCATION: **Teacher's Lunchroom, Kitchen, Room 006, Room 100A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 302**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1000** DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 302 20 SF missing or cracked, not observed**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**
MATERIAL LOCATION: **Room 302**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Poured asphalt**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not asphalt, concrete**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Poured asphalt**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ Gray Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ Gray Specks**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ Gray Specks. Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ Gray Specks. Mastic**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile w/ White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100, As Patch in Room 208**
MATERIAL QUANTITY: **1030** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 100 5 ft crack**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile w/ White Specks**

MATERIAL LOCATION: **Room 100, As Patch in Room 208**

MATERIAL QUANTITY: **1030**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile w/ White Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 100, As Patch in Room 208**

MATERIAL QUANTITY: **1030**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile w/ White Specks Mastic**
MATERIAL LOCATION: **Room 100, As Patch in Room 208**
MATERIAL QUANTITY: **1030** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **9" x 9" Orange w/Red Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1000** DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 101 4 ft cracked**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **9" x 9" Orange w/Red Floor Tile**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **4**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9" x 9" Orange w/Red Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9" x 9" Orange w/Red Floor Tile Mastic**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Gray**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Gray**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Gray Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/Gray Mastic**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12" x 12" Cream Colored Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 105 3 ft cracked**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12" x 12" Cream Colored Floor Tile**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" Cream Colored Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" Cream Colored Floor Tile Mastic**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Exterior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Exterior brick mortar**

MATERIAL LOCATION: **1902 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Exterior brick mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1913 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Exterior brick mortar**

MATERIAL LOCATION: **1913 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **Wall plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Areas**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Wall plaster**

MATERIAL LOCATION: **Basement Areas**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Exterior lime stone mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Exterior lime stone mortar**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Gray floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principle's Office (Underneath Carpet)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Gray floor tile**

MATERIAL LOCATION: **Principle's Office (Underneath Carpet)**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Gray floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principle's Office (Underneath Carpet)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Gray floor tile mastic**

MATERIAL LOCATION: **Principle's Office (Underneath Carpet)**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Exterior window sash caulk (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Exterior window sash caulk (Non-AHERA)**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Roof flashing (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Roof flashing (Non-AHERA)**

MATERIAL LOCATION: **West Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Roof decking**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Roof decking**

MATERIAL LOCATION: **Exterior Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Blue carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Blue carpet mastic**
MATERIAL LOCATION: **Principal's Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Brown carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Professional Office Across From 012, Room 009A**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Brown carpet mastic**

MATERIAL LOCATION: **Professional Office Across From 012, Room 009A**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Professional Center**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Linoleum**

MATERIAL LOCATION: **Professional Center**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Professional Center**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Linoleum mastic**

MATERIAL LOCATION: **Professional Center**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **1010** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 208 - 12 ft cracked**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **1010** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **12** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Insulation under incinerator shell**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Insulation under incinerator shell**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Fire Brick in Incinerator**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Fire Brick in Incinerator**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Boiler gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Enclose**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Boiler gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Enclose

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Northwest Side Near Room 005, Basement Girl's Bathroom**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Basement Northwest Side Near Room 005, Basement Girl's Bathroom**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Drywall tape**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Northwest Side Near Room 005, Basement Girl's Bathroom**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Drywall tape**
MATERIAL LOCATION: **Basement Northwest Side Near Room 005, Basement Girl's Bathroom**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Drywall compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Northwest Side Near Room 005, Basement Girl's Bathroom**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Drywall compound**
MATERIAL LOCATION: **Basement Northwest Side Near Room 005, Basement Girl's Bathroom**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **4" Light brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Girl's Bathroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **4" Light brown vinyl baseboard**

MATERIAL LOCATION: **Basement Girl's Bathroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **4" Pink vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Girl's Bathroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **4" Pink vinyl baseboard adhesive**

MATERIAL LOCATION: **Basement Girl's Bathroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" x 12" Green Self Stick Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 009A Bathroom**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12" x 12" Green Self Stick Floor Tile**

MATERIAL LOCATION: **Room 009A Bathroom**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **4" Green vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 009A Bathroom**
MATERIAL QUANTITY: **22** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **4" Green vinyl baseboard**

MATERIAL LOCATION: **Room 009A Bathroom**

MATERIAL QUANTITY: **22**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's Lunch Room Between Rooms 206 and 208**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 207 5 ft cracked**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**
MATERIAL LOCATION: **Teacher's Lunch Room Between Rooms 206 and 208**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **4" Green vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 009A Bathroom**
MATERIAL QUANTITY: **22** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **4" Green vinyl baseboard adhesive**

MATERIAL LOCATION: **Room 009A Bathroom**

MATERIAL QUANTITY: **22**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Green stage fire curtain**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Green stage fire curtain**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Beige stage fire curtain**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Beige stage fire curtain**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Men's Bathroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**

MATERIAL LOCATION: **Basement Men's Bathroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Men's Bathroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **4" Blue vinyl baseboard adhesive**

MATERIAL LOCATION: **Basement Men's Bathroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckles w/ White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100A Bathroom, 1st Floor Women's Bathroom**
MATERIAL QUANTITY: **162** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**
COMMENTS: **Damage in 1st floor woman's restroom 6 SF cracked, not observed**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckles w/ White Specks Floor Tile**
MATERIAL LOCATION: **Room 100A Bathroom, 1st Floor Women's Bathroom**
MATERIAL QUANTITY: **162** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckles w/ White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **4 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100A Bathroom, 1st Floor Women's Bathroom**
MATERIAL QUANTITY: **162** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **162** DAMAGE UNITS: **SF**
COMMENTS: **Damage in 1st floor woman's restroom 6 SF, not observed**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckles w/ White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Room 100A Bathroom, 1st Floor Women's Bathroom**
MATERIAL QUANTITY: **162** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement, patch in 208**

MATERIAL QUANTITY: **276** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement, patch in 208**
MATERIAL QUANTITY: **276** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement**
MATERIAL QUANTITY: **276** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile Mastic**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement**
MATERIAL QUANTITY: **276** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **New drywall - wall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement and Elecator Rooms**

MATERIAL QUANTITY: **3160**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **New drywall - wall**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement and Elecator Rooms**
MATERIAL QUANTITY: **3160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's Lunch Room (Room 207) Between Rooms 206 and 208**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**
MATERIAL LOCATION: **Teacher's Lunch Room (Room 207) Between Rooms 206 and 208**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **New drywall - ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **New drywall - ceiling**

MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **New drywall - tape**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **New drywall - tape**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **New drywall - compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **New drywall - compound**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Spray-on fire proofing**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement and Elevator Room**

MATERIAL QUANTITY: **160**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Spray-on fire proofing**
MATERIAL LOCATION: **Elevator Area on 1st, 2nd, 3rd Floors and area between 1st Floor and Basement and Elevator Room**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Terrazo flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Girl's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Terrazo flooring**

MATERIAL LOCATION: **2nd Floor Girl's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Blue ceramic fl grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Boy's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUILDING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Blue ceramic fl grout**

MATERIAL LOCATION: **Basement Boy's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Tan ceramic fl grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **450** DAMAGE UNITS: **SF**
COMMENTS: **Kitchen tan ceramic grout. Both front room and back room have damage 6 ft cracked or loose tile**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Tan ceramic fl grout**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **450**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **6**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Pink ceramic grout**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Girl's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Pink ceramic grout**

MATERIAL LOCATION: **Basement Girl's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" x 12" Multi Spec Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 102 -12 ft cracked**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" x 12" Multi Spec Floor Tile**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **12** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69M**
MATERIAL DESCRIPTION: **12" x 12" Multi Spec Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **69M**

MATERIAL DESCRIPTION: **12" x 12" Multi Spec Floor Tile Mastic**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen Office, Rooms 102 and 2nd floor men's bathroom, patch in 208**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5000** DAMAGE UNITS: **SF**
COMMENTS: **Damage in 2nd floor men's room 20 ft cracked or missing**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**
MATERIAL LOCATION: **Kitchen Office, Rooms 102 and 2nd floor men's bathroom, patch in 208**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Boy's Bathroom**
MATERIAL QUANTITY: **23** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**

MATERIAL LOCATION: **2nd Floor Boy's Bathroom**

MATERIAL QUANTITY: **23**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Boy's Bathroom**

MATERIAL QUANTITY: **23**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **4" Blue vinyl baseboard adhesive**

MATERIAL LOCATION: **2nd Floor Boy's Bathroom**

MATERIAL QUANTITY: **23**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Girl's Bathroom**
MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
MATERIAL LOCATION: **2nd Floor Girl's Bathroom**
MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Girl's Bathroom**

MATERIAL QUANTITY: **35**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**

MATERIAL LOCATION: **2nd Floor Girl's Bathroom**

MATERIAL QUANTITY: **35**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen Office, Rooms 102 and 2nd floor men's bathroom, patch in 208**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen Office, Rooms 102 and 2nd floor men's bathroom, patch in 208**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall and Principal's Office and Room 204**
MATERIAL QUANTITY: **3375** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in Auditorium 25 ft cracked; main office 5 ft cracked**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
MATERIAL LOCATION: **Assembly Hall and Principal's Office and Room 204**
MATERIAL QUANTITY: **3375** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Boiler #1 west insulation jacketing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler #1 west insulation jacketing**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Boiler #2 east insulation jacketing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Boiler #2 east insulation jacketing**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Make up tank (sellers) insulation jacketing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Make up tank (sellers) insulation jacketing**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Basement, Mechanical Room, Basement Halls, Boiler Room**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **700** DAMAGE UNITS: **LF**
COMMENTS: **Damage in Boiler Room**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
MATERIAL LOCATION: **Throughout Basement, Mechanical Room, Basement Halls, Boiler Room**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings off Cardboard Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Basement, Mechanical Room, Basement Halls**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **175** DAMAGE UNITS: **FITTING**
COMMENTS: **Damage in Boiler room cement joint fittings top layer is cracking**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings off Cardboard Pipe Runs**
MATERIAL LOCATION: **Throughout Basement, Mechanical Room, Basement Halls**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Cementitious Pipe Fitting on Old Fiberglass**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Cementitious Pipe Fitting on Old Fiberglass**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Basement , Mechanical Rooms, Halls, 1st Floor Room 106 and 108**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **Throughout Basement , Mechanical Rooms, Halls, 1st Floor Room 106 and 108**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings on Aircell Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement, Mechanical Rooms, Halls, and 1st Floor Rooms 106 and 108**

MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings on Aircell Pipe Runs**
MATERIAL LOCATION: **Basement, Mechanical Rooms, Halls, and 1st Floor Rooms 106 and 108**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation off Steam Line**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation off Steam Line**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Fire Brick from Boiler #1**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Inside Boiler**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Fire Brick from Boiler #1**

MATERIAL LOCATION: **Inside Boiler**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Mortar from fire brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler #1 Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Mortar from fire brick**

MATERIAL LOCATION: **Boiler #1 Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Boiler ins. Cloth jacketing**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1000** DAMAGE UNITS: **SF**
COMMENTS: **Damage in Boiler Room - Boiler 1 and boiler 2 cloth jacketing loose 160 sq ft. Abated? Boiler covered in fiberglass**

Inspector's Signature: _____



Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Boiler ins. Cloth jacketing**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **160** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content

Management Planner's Signature: _____



Date: **12/10/2022**

Chicago Public Schools

Carnow, Conibear and Associates 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUILDING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile w/ pinholes**
MATERIAL LOCATION: **Room 206**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Kenneth Karuhn

Date: 12/07/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUILDING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile w/ pinholes**
MATERIAL LOCATION: **Room 206**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUIDLING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12" x 12" Light Green Mottled Floor Tile**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Kenneth Karuhn

Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUILDING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12" x 12" Light Green Mottled Floor Tile**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUILDING ID: **4230**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Jungman School** INSPECTION DATE: **12/7/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12" x 12" Light Green Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **12/07/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23961** BUILDING ID: **4230**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Jungman School** REVIEW DATE: **12/10/2022**
ADDRESS: **1746 S. Miller** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12" x 12" Light Green Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 12/10/2022

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Kenneth Karuhn

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092154

Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 07278

ISSUED
4/15/2022

EXPIRES
05/15/2023

KENNETH A KARUHN
600 W VAN BUREN ST., STE 5
CHICAGO, IL 60607

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

10/9/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Kenneth Karuhn

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082269

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed